

## TECHNICAL APPENDICES November 2020



Prepared by:

Prepared for:



SPC SPC

### Appendices

- A. Steering Committee Meeting Minutes
- B. Public Comments Received
- C. Online Mapping Survey Questions
- D. Public Concern Map
- E. Stakeholder Meeting Minutes
- F. Existing Conditions Report
- G. Intersection Level of Service 2019 AM/PM and 2045 AM/PM
- H. Route 28 Design Criteria
- I. SPC Funding Program

# APPENDIX A Steering Committee Meeting Minutes



Steering Committee Kick-off Meeting DRAFT

Meeting:	Steering Committee Kickoff Meeting	Date:	December 5, 2019
Location:	Armstrong County Planning and Development Office	Time:	12:30pm to 2:30pm
Attendees:	See attached sign-in sheet		
Purpose:	The purpose of the meeting was to kick-off the Route 28 Corridor Study	Project.	

**Discussion:** The project kick-off meeting was held to discuss the Route 28 Corridor Study development, community outreach, initial goals and concern areas, and project schedule. John Petulla, consultant Project Manager began the meeting by welcoming the meeting attendees. Each Steering Committee member introduced themselves and provided the organization they represent. Each member was provided a packet with project related materials.

1) Mr. Petulla continued the presentation by reviewing the study area map. The study area includes Route 28 from Kittanning to Interstate 80 near Brookville. An overall study area map was provided in the packet and shown on a large format board at the front of the room for review. The attendees were asked to provide feedback or comments on the map. The map will be used throughout the study as the basis for displaying technical and non-technical information and the results displayed within the final report. Amy Kessler commented that the insets should be labeled, and the orange leader lines blend in with the yellow background. McCormick Taylor will adjust the map for subsequent versions. Additional feedback regarding the study area map was encouraged to be provided after the meeting via email.

The meeting continued with a small group exercise to discuss the draft project goals. Based upon initial study observations by the project team, the study team developed and presented the following draft goals:

- Increase Safety
- Support Economic Development
- Accommodate Mulitimodal Use

- Reduce Congestion
- Facilitate Freight Movement
- Improve Quality of Life

The attendees were split into the following three groups:

Group 1: Josh Spano, Lillian Gabreski, Kristi Amato, Dave Tomaswick, John Petulla

Group 2: Tim Jablunovsky, Domenic D'Andrea, Jamie Lefever, Travis Siegel, Melissa Thomas

Group 3: Ryan Gordon, Darren Alviano, Amy Kessler, Ashley Tracy

The Steering Committee was asked to provide input on the draft goals and/or add to the list as needed. Discussion related to the draft goals included the following:

- Improve Safety for all modes of transportation (trucks, cars, trail, pedestrians and cyclists). General safety and specific safety improvements related to the roadway is a high priority throughout the corridor.
- Support Regional Economic Development freight and trade along the Route 28 corridor is likely a key part of economic importance of the corridor. The value of the cargo moving along the Route 28 Corridor should be compared to the overall gross domestic product (GDP) for Pennsylvania as a potential economic performance measure of cargo moving through the corridor. Wayfinding signage for Route 28 from I-80 and from Pittsburgh is limited, and that affects tourism as well. Consider the larger businesses currently in the corridor and how improvements may impact them.
- Accommodate Multimodal Use there are needs at existing trail crossings. There are potential pedestrian improvements needed in New Bethlehem. Consider potential new trail opportunities along the corridor.

- Reduce Congestion / Improve Operations congestion is a lower priority as the corridor is not traditionally congested. Recommendations may include climbing lanes, passing lanes, signals, which would improve general operation of the corridor. Crashes on I-80 resulting in traffic using Route 28 as a detour route can result in secondary roads being gridlocked for hours as traffic diverts around I-80. Due to the frequency of crashes on I-80, consideration should be given to better notify drivers of congested secondary routes and potential choices before roadways become over saturated with vehicles. During an incident on I-80 resulting in a detour on Route 28, common congestion points and temporary or permanent solutions to reduce bottlenecks and improve emergency response times should be considered. In addition, the potential impact along the Route 28 corridor if I-80 becomes a toll road in the future was discussed. Providing reliable travel times for current businesses and residents, regional travel, and emergency response times was noted as being an important consideration.
- Facilitate Freight Movement / Regional Connectivity it was noted freight movement is directly correlated to economic development. Consideration should be given to inadequate turning radii and making the first and last mile connections for delivery of freight. For instance, in New Bethlehem trucks park along Route 28 and block lanes of traffic to service the businesses. There are also areas where trucks park on the corridor overnight, which points to a need for truck parking in the corridor.
- Environmental / Quality of Life the term "quality of life" needs to be better qualified. Environmental considerations may
  include improved stormwater infrastructure, identifying food deserts, and improving access for trail connections and access to
  public resources. Quality of life will be influenced by the ability to achieve the other goals such as safety, reliability, and
  supporting accessibility for all modes.
- **Resiliency / Reliability** the corridor needs to consistently support roadway users to provide reliable travel times for typical traffic and to better accommodate road closures and emergency detour routes.
- Tourism this was added as it is a federal planning factor. Route 28 corridor serves traffic to the south to Pittsburgh, as well
  as traffic to the north to Allegheny National Forest, Punxsutawney, trails and rivers outside the study area, and the Oil
  Heritage region. Armstrong County and Kittanning have a lot of historical sites, which could be better marketed.
- Security this was added as it is a federal planning factor. This may include emergency vehicle travel times, and the status of critical assets such as bridges and highways. The hospital location on the corridor and service area access should be considered. There are not many appropriate helicopter landing spots on the corridor. The Pennsylvania State Police Barracks is in Kittanning and coverage area expands into several communities along the corridor. It was noted Volunteer Fire Departments are struggling to recruit members and keep up their funding, and reluctant to combine services with other departments. The fire department coverage along the corridor is not ideal.
- Asset Preservation we need to consider asset management of key roadway features along the corridor and planning to maintain a good state of repair.
- Community Buy-in/Satisfaction community support of the study and proposed improvements is important. We need to
  balance community needs with regional needs. This may include reducing impacts to communities during construction.
  Communities may not want to attract additional regional traffic, though some may not want traffic diverted away from the
  corridor that potentially could take away business. The study should consider the community support behind each project.
  Community outreach will also be key for the public to understand and be able to provide input on the study as well as
  proposed future projects along the corridor.
- 2) Melissa Thomas, consultant Assistant Project Manager reviewed the project team's approach to public involvement. A project logo was developed for the corridor study with SPC's input and presented to the Steering Committee. The proposed website address is <u>www.Route28CorridorStudy.com</u>. The official project email address to send out correspondence and provide responses to feedback and questions is <u>Route28CorridorStudy@mccormicktaylor.com</u>.

The website is anticipated to include 4 main pages consisting of:

- About the Study
- Corridor Details
- Public Outreach
- Study Outcomes

The Route 28 Corridor Study website will host the Wiki-Map under the Public Outreach section. The Public Outreach section will allow users to comment on the study as well as pinpoint areas of concern along the corridor. Website display options are currently in the development process. Similar to the Route 28 Corridor Study logo, the draft website options will be sent to the Steering Committee for comment prior to implementation. The draft questions for the public on the Wiki-Map will be customized to the corridor. A sample of the draft user questions are attached to this summary for review and comments. It was discussed to make the website more public friendly, the project team may want to consider a story map imbedded on the website to better display study results.

McCormick Taylor anticipates collaborating with the Stakeholders to help inform the public of the Route 28 Study and ask for public input on the Wiki-Map section of the website. Members of the Steering committee suggested contacting the various active Chambers of Commerce located along the corridor including but not limited to Armstrong County, New Bethlehem, and Brookville. It was advised that the Chambers of Commerce could provide specific input on the website and the help distribute information obtain additional public input from their communities. McCormick Taylor will provide hard copies of the final questions for users who may not wish to complete the survey online. McCormick Taylor will discuss this option with the stakeholders further after the website is developed.

Domenic D'Andrea asked if McCormick Taylor has a social media plan for the study like Twitter, Facebook, etc. Ms. Tracy stated it was not scoped as part of the outreach, but that a social media platform could be considered for public outreach. Mr. D'Andrea mentioned they successfully used Streetlight data for the Second Avenue Study to get a list of zip codes of people who traverse the corridor, and sent targeted advertisements to those people on Facebook. Ms. Tracy asked if Mr. D'Andrea knew what the cost of the targeted ads was, and Mr. D'Andrea said that it was about \$50. Mr. Petulla agreed the application this collection of information may work well to gain information and target users to gain input on the Route 28 Corridor.

Interviews of key stakeholders along the corridor to obtain a better understanding of the corridor needs and potential areas of improvements were discussed. The project team requested the Steering Committee provide feedback on potential stakeholders to be interviewed. A request will be made via email by the project team for this information after the meeting.

Ms. Kessler stated that the North Central's Public Participation Plan (PPP) does not allow meetings past 5pm as there is no transit available to the public after that time. McCormick Taylor will review the PPP for each MPO/ RPO to determine the required outreach time frames and tailor the outreach to fit that. Ms. Lefever suggested that we should look at when the Chambers of Commerce have their meetings and try to do this as part of a regularly scheduled meeting, or back-to-back with one.

3) Ashley Tracy, consultant Traffic Lead, discussed traffic data collected to date. Data collection includes turning movement counts (TMC) and twenty-four hour automated traffic recorder (ATR) counts at key locations provided by SPC in the scope of services. Mr. Spano and Mr. Gordon mentioned that it would be possible to supplement the count data with Streetlight data. A comparison will be made between the TMC data obtained and the Streetlight data to verify the reliability of Streetlight count information before being incorporated into the study. Mr. D'Andrea mentioned the study team should review the Regional Operations Plans (ROP) to ensure the analysis is consistent with the respective plans.

INRIX data has been transferred from SPC to McCormick Taylor, which should give us a sense of travel times during the off-peak and peak directions. McCormick Taylor performed a preliminary crash history analysis and showed how the fatal and hit fixed object crash analysis may highlight areas for further consideration during field views. There was discussion of whether these crash maps would be shown on the study website. PennDOT indicated that have to be careful about the specifics of crash data and the language we use that will be displayed on the Route 28 website. Mr. D'Andrea stated it should be permitted to show a general crash area map with the specific crash information removed.

Signal permit plans were provided from PennDOT District 10 to McCormick Taylor to be used in the Synchro analysis of the existing and future conditions which will be completed in the next few months. Upcoming work on the data collection includes developing the data collection plan, analyzing the Streetlight data, and performing existing and future traffic analyses. SPC and Western PA Regional Operations Plans will be incorporated as well.

4) Mr. Petulla directed the Steering Committee back into their working groups for the second group activity of the meeting. This activity asked the participants to mark up the provided corridor map with initial areas of concern. The initial areas of concern discussed during the meeting were not prioritized:

- Route 422 at Rt 28 interchange upgrade for additional capacity, potential for economic development.
- Route 85 at Rt 28 economic development opportunity nearby, there is a 60-acre site for sale by the county.
- Route 66 and Route 28 turning radii difficult to navigate.
- Route 28 and SR 1018 intersection with sight distance issues.
- Selker Curve sharp horizontal curve that may be a safety concern.
- Mayport Curve sharp horizontal curve that may be a safety concern.
- Baxter Curve sharp horizontal curve that may be a safety concern.
- Fish Basket trail crossing, pedestrian & bicycle safety area that improvement options should be considered.
- Hays Run structure replacement and widening project currently programmed. May need additional upgrades adjacent to the project area in the future.
- **Sight Distance** potential for coordination with utilities through the corridor for tree trimming where warranted to improve sight distance.
- **General** truck climbing lanes and passing lanes where warranted. Slow trucks can delay travel time through the corridor by at least 30 minutes.
- **General** guiderail applications, centerline and shoulder rumble strip applications, and shoulder width should be applied consistently per PennDOT design criteria through the corridor.
- General deer crossings or accidents involving deer through the corridor.
- **General** intermittent roadway flooding. Mr. Gordon and Ms. Kessler have dates of flooding events when Route 28 has been closed. Ms. Lefever mentioned a few flooded locations between New Bethlehem and Brookville. McCormick Taylor will attempt to obtain photos of the mentioned locations and consult PennDOT Maintenance for additional information on areas of flooding concern.
- General emergency access and service times, especially related to the various volunteer fire department access along the corridor.
- General applications of Streetlight data to support analysis and decisions for the Route 28 Corridor Study. Streetlight data
  may provide an avenue for innovative uses i.e. target Facebook ads to the survey and public meetings, gain insight on
  travel patterns on specific days of incidents when I-80 is detoured, or if Route 28 is detoured. Streetlight has the potential to
  capture car and truck travel times, travel time reliability, limited multimodal travel, the estimated value of commercial goods
  traveling on the road. SPC expanded their license to have access to obtain Streetlight data along the Route 28 Corridor
  within Clarion and Jefferson Counties within the study area. This will enable the study team to be able to provide a consistent
  analysis of Streetlight data throughout the study area.
- **General** potential to evaluate practicality of high friction pavement along sharp curves, microsurfacing, shoulder width in the corridor.

Additionally, Mr. Tomaswick provided a list of potential improvement recommendation locations from District 10 Safety Coordinator William Rankin, PennDOT District 10 (see attached list).

5) The following is a list of next steps discussed during the meeting:

	Follo	w-Ups	
Follow-up item	Responsible party	Anticipated completion	Actual Completion
Provide Draft Wiki-Map survey	McCormick Taylor	December 2019	
questions for Steering			
Committee review.			
Develop pilot webpages	McCormick Taylor	January 2020	
Streetlight Data provided to	SPC	January 2020	
McCormick Taylor			
Analyze collected Traffic Data	McCormick Taylor	January 2020	
obtained from French			
Engineering			
Obtain Public Participation	McCormick Taylor.	January 2020	
Plan (PPP) for each			
MPO/RPO involved to			
determine required outreach.			
Determine active Chambers of			
Commerce along the corridor			
and dates of next upcoming			
meetings.			
Provide list of Stakeholder to	Steering Committee	January 2020	
be interviewed.			
Conference Call to discuss	McCormick Taylor/ Steering	January 2020	
Pilot Website and Stakeholder	Committee		
Interviews to be scheduled.			

The meeting was adjourned at approximately 2:25 p.m. by thanking the committee for their feedback during this meeting and throughout the study.

Prepared by:

McCORMICK TAYLOR, INC.

<u>Copies:</u> Attendees MT Project File

<u>Attachments:</u> Meeting Sign-in Sheet PennDOT District 10 - Corridor Safety Concerns List Draft Wiki Map Survey Questions



## **Steering Committee Meeting #1**

December 5, 2019

Name	Organization	Address	Phone	E-Mail
1. Josh Spano	SPL	Two charnom center	412-391-5580	j'spande secretur ory
2. Dom D'Andrea	SC	Two Chathan Ctr. 112 Washingh Pl., Suitesto, Poh 15219.	412-391-JJG0 -3451 X-341	dandre c speregin.on
3. Rycin Gordon	SPC	4	// ×333	Tgordon@spcregion.org
4. Kristi Amato	Clarion County	320 Main St; Koom IC Clarion, PA 16214	814-226-4000 Ext. 2800	Kamatoeco. Clarion pa.us
5. Sunclefacer	Saffasal	155 MAINIST Brockville PA 15825	8148491517	Vatora Jattorailugita
6. Darin Alviana	Armstrong Con-y	402 market Street Kitter	721-518-3223	ddalvanopco.amstronper.
7. Lillian Gabreshi	SPC	Two Chatham Center	412-391-5590 X327	Igabreshi@spcregion.org
8. RAVIS SECEL	NW RPD	395 Seneca Street Oll City, PA 16301	814.677.4800 X123	traviss@northwestpg.org
9. Any KESSLER	NC RPC	49 Ridgmand DR Ridgmand DR	814.773. 31ce2	Any ONCENTIAL. CUL
10. DAVE TOMASWICK	PENNDOT TRAFFIC	2550 OAKLAND AVENUE INDIANA PA	724 357 2645	PROMASWICK @ PA. GOV
11. Tim JABLUNOVSKY	PENNOUT DESIGN	2550 OAKLAND AJI INDIANA PA 15701	724-357-2874	TJABLUNOVS @ PA. GOV
12.				

#### Tomaswick, David P

From: Sent: To: Subject: Rankin, William Wednesday, December 4, 2019 10:02 AM Tomaswick, David P SR28

Sight distance at:

- 10-1 Sloan Hill Rd.
- 10-1 Oscar Rd. (SR1035)
- 10-1 Calhoun School Rd. (SR1016)
- 10-1 Tipple Rd.
- 10-3 Oak Ridge Rd. (SR2019)
- 10-5 Mendenhall Rd. (SR3035

The approach off of:

- 10-1 Oscar Rd. (SR1035)
- 10-1 Putneyville Rd. (SR839)
- 10-5 Seldom Seen Rd.
- 10-5 Snyder Rd.

Turning lane needed at:

• 10-1 SR1018 SB

The curves at:

- 10-1 SR1018
- 10-1 hogback area
- 10-1 South Bethlehem (kohlersburg Rd)
- 10-3 Alcola (TR-921)
- 10-5 Snyder Rd.

Speeding areas:

• Shannondale

#### Route 28 Corridor Study Wiki-map Survey Questions Draft 12.30.19

#### ADD A POINT

- 1. Select a point type\* and then place on map.
  - Travelling via a car
  - Travelling via bike
  - Travelling via walking
  - Travelling via truck/freight vehicle
- 2. I use this area for: (Select all that apply)
  - Local commuting (Less than 40 miles each way)
  - Regional commuting (More than 40 miles each way)
  - Business travel (Deliveries, moving freight, etc.)
  - Accessing government services
  - Accessing Redbank Valley Trail
  - Accessing local schools
  - Accessing stores, services, goods, healthcare
  - Accessing recreational opportunities
- 3. How frequently do you use this facility?
  - Daily
  - Weekly
  - Monthly
- 4. What about this location causes you concerns? [CARS]
  - Pedestrians in the roadway
  - Cyclists in the roadway
  - Excessive vehicle speed
  - Slow trucks cause delays
  - General congestion
  - Stopping or turning vehicles
  - Lack of connectivity
  - Other (open-ended)
- 5. What about this location causes you concerns? [BIKES]
  - No shoulder
  - Shoulder is too narrow
  - Poor shoulder condition
  - Travel lanes need to be swept
  - Lack of bike lane
  - Lack of protected bike lane
  - Travel lanes are too narrow
  - Drainage grates make facility unusable or hazardous

#### Route 28 Corridor Study Wiki-map Survey Questions Draft 12.30.19

- Vehicles are going too fast
- Too many large trucks
- Lack of enforcement
- Lack of connectivity to transit facilities
- Other (open-ended)
- 6. What about this location causes you concerns? [FREIGHT]
  - Pedestrians in the roadway
  - Cyclists in the roadway
  - Excessive vehicle speed
  - Grades are too steep
  - No climbing lane on steep grade
  - Travel lanes are too narrow
  - Intersection too narrow to safely turn
  - General congestion
  - Stopping or turning vehicles
  - Lack of connectivity
  - Other (open-ended)
- 7. What about this location causes you concerns? [WALKING]
  - Sidewalk ends/no sidewalk
  - Sidewalk condition
  - No shoulder
  - Shoulder is too narrow
  - Poor shoulder condition
  - Drainage grates make facility unusable or hazardous
  - Excessive vehicle speed
  - No crosswalk
  - Vehicles don't stop for pedestrians in crosswalks
  - Sidewalk not Americans with Disabilities Act (ADA) compliant
  - Lack of enforcement
  - Other (open-ended)
- 8. What improvements would you suggest for this location? (open-ended)
- 9. Do you have a photo of this area of concern for us to consider? Please upload it here.
- 10. Is there any other information you would like us to know about the Route 28 corridor? (openended)



Subject: Steering Committee Coordination Call

**Date**: Friday 1/24/2020; 1:00 pm to 2 pm

Location: Conference Call

John Petulla, McCormick Taylor, began the meeting by welcoming all those who called in and asking for each to introduce themselves. The list of all in attendance can be found at the end of this summary.

#### Study Goal Review & Discussion

Mr. Petulla then reviewed the Study Goals which were refined after the Steering Committee Kick-off Meeting held in December 2019. No additional changes or additions were discussed, and the refined Study Goals and associated guiding principles are:

- ✓ Improve Safety Improve safety for all modes of transportation
  - Improve Security Improve security by maintaining critical assets like bridges and reducing emergency response times
- Support Regional Economic Development Improve access to existing business and attract new businesses with an improved and efficient regional trade route between I-80 and Pittsburgh
  - Promote Tourism Facilitate access to historic locations, trails, and outdoors activities
- Facilitate Regional Connectivity Facilitate connections to other regional transportation facilities and systems
  - Accommodate Multimodal Use Improve existing and plan for new multimodal connections to non-motorized facilities
  - Accommodate Freight Movement Facilitate and improve access for freight and trucks
- ✓ Improve Operations Improve operations and reduce congestion
  - Improve Resiliency/Reliability Provide reliable travel times for all users
  - Focus on Asset Preservation Maintain a good state of repair of bridges, guide rail, signs, drainage, slopes, lighting, and pavement
- Minimize Impacts Minimize impacts to the environment and community
  - Improve Quality of Life Improve quality of life by providing access to a safe and efficient transportation system and public resources
  - Gain Community Buy-in/Satisfaction promote projects that have broad community support and meet the study's goals, and minimize impacts to the traveling public during construction

#### Website and Wikimap Survey Draft

Jennifer Threats, McCormick Taylor, then discussed the public outreach efforts that will be used to promote the Study in the region.

The McCormick Taylor team developed a Wikimap online mapping survey to collect input from the general public about specific areas of concern along the corridor. The team anticipates that the mapping survey will be ready to launch during the week of February 3 and remain open through the week of March 2. The survey is available for review at: https://wikimapping.com/Route-28-Corridor-Study-Kittanning-to-I-80.html A few comments and suggestions for the Wikimap survey were discussed:

- The map is mobile friendly and the survey feature is also functional on mobile devices.
- The current draft of the survey only allows for comments within the study boundary, but all in attendance agreed that viewers should be able to place points on all areas of the map. This will be adjusted before the map is circulated for further Steering Committee review.
- There is no character limit in the paragraph survey fields, so there should not be a risk of cutting off a response due to lack of space.

The other web-based public outreach tool is a study website, currently in development. The website will be launched at the same time as the Wikimap survey and will be available at: <a href="http://www.Route28CorridorStudy.com">www.Route28CorridorStudy.com</a>. The link to the test website will be shared with the Steering Committee members on January 27 or 28 for testing and review.

A press release and email blast will announce the launch of the website and Wikimap survey. The McCormick Taylor team will distribute the email blast to the Steering Committee who are encouraged to share it with their own connections. Social media graphics and text will also be developed for use by Steering Committee members on their organizations' social media accounts. Mr. Petulla asked the representatives from PennDOT District 10 if they would ask the Community Relations Coordinator to distribute the press release to their usual media contacts as well. He will send the draft press release to Tim Jablunovsky and Dave Tomaswick who will discuss with the Community Relations Coordinator.

#### Stakeholder Outreach

The study team will also conduct interviews with key stakeholders along the corridor. The Steering Committee provided names and contact information for several organizations and individuals who will be invited to participate. The current list of stakeholders will be shared with the committee to fill in any missing information or add additional contacts. Jamie Lefever, Jefferson County, mentioned that she will also reach out to any stakeholders within her contact network to encourage them to participate in the interviews. All agreed that this was a good approach for others on the committee to take.

Ms. Threats reviewed the draft Stakeholder Interview Plan with the committee, including potential locations for the interviews. The committee suggested additional locations, and the team will investigate the availability. The interviews will be tentatively held during the week of February 17 or 24, pending availability of the locations and the team members and committee members who will be attending.

A draft interview form was drafted to guide the discussion at the interviews. Ryan Gordon, Southwestern Pennsylvania Commission (SPC), suggested beginning with a short discussion of the locations with known safety or similar concerns to spark the discussion.

#### **Other Study Updates**

The McCormick Taylor team is continuing to review previous studies and plans related to the Route 28 Corridor for consideration during the study.

Traffic data collection is complete, including Synchro software analysis at all of the intersections. Highway Capacity Software (HCS) analysis will be completed next, and it may show more congestion that the Synchro analysis has so far. The McCormick Taylor team is coordinating with SPC to secure data from the Streetlight transportation analytics platform. All field work is also completed.

The next steps in traffic data analysis will include Synchro and HCS data for the future year, and the study team will need additional information from the Steering Committee regarding known planned development to come to an estimated growth rate to make those projections.

#### Next Steps

The Study Team will work toward the following milestones in the coming months:

- Public survey and website launch early February early March 2020
- Stakeholder interviews late February 2020
- Existing conditions memo March 2020
- Steering Committee call/meeting mid-March 2020

#### **Resulting Action Items**

- John Petulla will send the draft press release to Dave Tomaswick and Tim Jablunovsky to share with the Community Relations Coordinator.
- Ryan Gordon, SPC, will distribute all materials discussed at the meeting for review and feedback from the committee:
  - o Draft press release
  - o Draft announcement email blast
  - o Draft Stakeholder Interview plan
  - Draft Stakeholder Interview form
  - o Potential Stakeholder Interview invitation list
  - o Website
  - o Wikimap survey

#### Attendee List:

Darin Alviano	Armstrong County
Kristi Amato	Clarion County
Jamie Lefever	Jefferson County
Amy Kessler	North Central PA Regional Planning and Development Commission
Tim Jablunovsky	PennDOT District 10
Dave Tomaswick	PennDOT District 10
Dom D'Andrea	SPC
Ryan Gordon	SPC
Josh Spano	SPC
Andy Waple	SPC
Carrie Machuga	McCormick Taylor
John Petulla	McCormick Taylor
Melissa Thomas	McCormick Taylor
Jennifer Threats	McCormick Taylor
Ashley Tracy	McCormick Taylor



Meeting:	Steering Committee Me	eeting #3	Date:	April 28, 2020
Location:	Conference Call		Time:	10:00am – 12:00pm
Attendees:	Steering Committee: Darin Alviano Kristi Amato Jamie Lefever Amy Kessler Travis Siegel Dave Tomaswick Tim Jablunovsky Lillian Gabreski Josh Spano Domenic D'Andrea Ryan Gordon	Armstrong County Clarion County Jefferson County Northcentral RPO Northwest RPO PennDOT District 10 PennDOT District 10 Southwestern Pennsylvania Commission Southwestern Pennsylvania Commission Southwestern Pennsylvania Commission	<i>McCormick</i> John Petulla Ashley Trac <u>y</u> Melissa Tho Jennifer Thr Carrie Mach	<i>Taylor Study Team:</i> y mas eats uga

#### Purpose:

The purpose of the meeting was to review the initial draft Existing Conditions Report and related findings.

#### Discussion:

The third Steering Committee meeting was held to discuss the Route 28 Corridor Study work completed to date and related findings which are documented in the draft Existing Conditions Report. John Petulla, consultant Study Project Manager began the meeting by welcoming the meeting attendees. Each Steering Committee member introduced themselves and provided the organization they represent. In advance of the meeting, the Committee received the meeting agenda, the draft Existing Conditions Report and the draft Concerns Evaluation Matrix.

#### Progress to Date – Existing Conditions Report Overview

Ashley Tracy, Study Traffic Lead, reviewed the Existing Conditions Report and related data collection. She reviewed the conditions identified in the field analysis, which was conducted in January 2020. The examined areas were identified by the Steering Committee or through desktop research prior to field work, including locations with limited sight distance due to the horizontal and vertical curvature of the roadway or locations of tight geometry that are difficult for large vehicles to navigate. Speed differentials were noticeable, with a spectrum ranging from speeding in excess of the 55mph posted speed limit, aggressive passing behavior, and vehicles traveling 10-15mph below the speed limit.

Ms. Tracy also reviewed the information collected during Stakeholder Interviews in late February. The Steering Committee identified key stakeholders including county commissioners, municipal leaders, business owners, freight haulers, school district staff, emergency service providers, and state police. Seventeen (17) organizations participated in the interviews and provided valuable local insight and input to the study.

She then reviewed the data received from the Streetlight "big-data" platform. Streetlight provides roadway analytics from anonymized Bluetooth and cellular device information which can be analyzed to examine travel behavior and traveler demographics. Access to the Streetlight data service was provided by the Southwestern Pennsylvania Commission's subscription in support of the Route 28 Corridor Study.

The data was analyzed to understand existing travel conditions on the Route 28 corridor, such as the lengths of trips. More than half of the trips on the corridor are over 60 minutes in duration, with a large number of trips over 150 minutes. This trip duration includes commercial vehicle traffic, which may have hauling routes along the corridor or destined northward to Forest, Elk or

Venango counties. Trip lengths correspond with the trip duration, with a majority of trips longer than 30 miles. More than half of the travel speeds are between 30 and 50mph, with approximately 15% traveling 50 to 70mph.

The study team reviewed the distribution of trips passing a point near the intersection of Route 28 and South Main Street in Brookville. It showed traffic coming from approximately Williamsport and Brookville in the east, from areas slightly north of the I-80 interchange such as Sigel and Brockway south through Kittanning and Pittsburgh. Approximately 15% of trips passing this point are destined to Kittanning, and approximately 4% of trips passing this intersection are destined to Pittsburgh. This finding shows that the corridor primarily serves demand to Kittanning and communities along the Route 28 corridor, rather than functioning currently as a regional through route.

Examining a Top Route from Pittsburgh to a point east of Brookville, Streetlight highlighted two main routes: the Route 28 corridor, and the I-79 to I-80 corridor. The Streetlight Index is a proportional approximation of traffic along the route. The Streetlight Index for the Route 28 corridor (80.6 miles, 1h 31m) is 65 versus an index of 26 for I-79 to I-80 (118 miles, 1h 50m). This means that Route 28 is approximately three times more popular than I-79 to I-80 for this trip. However, the team did not observe a significant amount of through traffic on this route because there is not significant demand between these two points (as outlined above).

Streetlight data was also used to identify additional characteristics of the corridor users:

- Who does the Route 28 corridor serve? Travelers on this 40-mile section of the Route 28 corridor primarily live and work in areas adjacent to the corridor to the east and west. The cluster of home locations stretches as far southwest as Pittsburgh, with a few isolated clusters focused primarily in places that are accessible via Route 28, I-80, I-79, US 422, and US 322 such as Youngstown, Erie, Altoona, and State College.
- Where are people going on the Route 28 corridor, and at what levels of frequency? The team used a point in the middle
  of the corridor to show all personal trips passing through this point on a weekday and their origins and destinations. The
  data showed a distinct diagonal pattern of trips that follows the corridor, with a large geographic catchment area in the
  northeast counties (Forest, Elk, Warren, McKean, Clearfield, Cameron) for Route 28 traffic destined to Kittanning and
  Pittsburgh, as well as hauling or tourist-related traffic for outdoors activities to the northeast counties.
- How are people using the multimodal facilities on the corridor? The Open Street Map alignment data for the Redbank Valley Trail and Armstrong County Trail were imported to understand bicycle and pedestrian usage of the trail system, including trail user demographics and trip characteristics. The largest proportion of trips on the corridor are 45-60 minutes in length, which reveals a tremendous benefit to public health in the communities that it serves.

Ms. Tracy also reviewed the information gleaned from INRIX data. INRIX is a data repository for historical congested travel speeds and travel times. SPC provided observed speed and travel time data for the corridor from INRIX. Speeding is a noted concern throughout the corridor. In areas like New Bethlehem, maximum speeds range from 35 to 40 mph in the posted 25 mph zone. Most segments in the corridor have maximum observed speeds trending above 55 mph, and on average, the maximum speeds for cars on the corridor is 57 mph. The average maximum speed for trucks on the corridor is 51 mph. This 6 mph speed differential is exacerbated on areas where there are significant grades. The longest segment of speed differential between cars and trucks is from approximately Goheenville to Distant (5 to 10 mph difference) over the area known locally as Hogback Hill. Field observations and GIS data noted areas of significant grade change in this area. Another segment with a high-speed differential between cars and trucks is coming into South Bethlehem around the 15 mph curve through New Bethlehem (10 to 15 mph difference).

INRIX historical speed data was also used to understand the range of influence and operational impact of I-80 detour traffic on the corridor. The team studied data related to an incident on August 8th, 2016 where I-80 was closed from around 2pm through the afternoon peak hours. Average observed speeds dropped at various points along the corridor during the closure, first and most noticeably at the intersection with Route 322 close to the interchange and later and to a lesser extent as far south as Kittanning. This analysis supports that interstate closures can have widespread impacts on the corridor traffic operations. This in conjunction with detour route choice and signage, and travelers using personal devices to navigate off of I-80 create bottleneck conditions that are challenging for emergency responders, residents, and the traveling public.

Melissa Thomas, Study Highway Lead, discussed the team's review of previous and related studies. Seven (7) related documents were reviewed, including the most recent corridor feasibility study, <u>State Route 28 Feasibility Study Kittanning to I-80 Armstrong</u>, Clarion & Jefferson Counties, Pennsylvania, conducted by Michael Baker, International in June 1994.

This feasibility study examined Route 28 between Kittanning, PA and Interstate 80. The initial recommendation based on a Preliminary Location Study for State Route 28 completed by The Pennsylvania Department of Transportation in the 1960's was to

extend a 4 lane, limited access facility from Aspinwall to I-80. A portion of this was built in the 1970s and 1980s terminating in Kittanning, PA. This study examined the feasibility of continuing the 4-lane template from Kittanning to I-80. Ms. Thomas discussed the review of Michael Baker's cost estimate and how the estimate was escalated to 2020 dollars. While this estimate accounts for the construction cost, it does not take into account more stringent modern environmental regulations. In particular, regulations related to stormwater management, water quality treatment and the mitigation of protected environmental features. Accounting of this design, permitting, environmental and community impacts, construction, and future maintenance, presents potentially hidden costs which would place a further strain on initial design and construction costs and future PennDOT maintenance of the permitted stormwater and mitigation features.

Tim Jablunovsky, PennDOT District 10, asked about the construction engineering cost comparison. The team used the same 5% construction engineering cost that was cited in the 1994 study for the 2020 estimate. Mr. Jablunovsky requested the estimate to be updated using the current standard of 10%.

County and regional comprehensive plans were also reviewed for recommendations and future goals. Amy Kessler, Northcentral RPO, noted that the Northcentral and Northwest RPO Long Range Transportation Plans were not listed with the other related studies. The team will review both of those documents and add any findings to the Existing Conditions Report.

Ms. Thomas also reviewed the corridor geometric conditions. The team developed Design Criteria charts considering new construction following guidance found in PennDOT Publication 13M Design Manual Part 2 Highway Design. The design criteria data was used as a basis for comparison to the existing Route 28 Study Corridor roadway geometry and widths.

Existing horizontal radii through the corridor were weighted against the current design criteria. In examining the corridor, there are currently 18 notable areas with horizontal radii less than that current recommended design values. Speeds up to 40 MPH were limited to a maximum super elevation rate of 6%. For the higher speed limits 45 MPH & 55 MPH a slightly higher maximum super elevation rate of 8% is permitted with shoulder rounding.

Existing vertical grades vary throughout the corridor. Many sections have grades exceeding the desired current design maximum vertical grades of 5% (55 MPH) or 6% (up to 45 MPH). Excessive vertical grades not only make maintaining speeds difficult for larger truck traffic but also can limit sight distance for passing or entering roadways at intersections. In examining the corridor, there are 10 notable areas with vertical grades exceeding the current maximum design grade.

Jennifer Threats and Carrie Machuga, Study Public Involvement staff, reviewed the outreach conducted to collect feedback from the general public. In order to collect broad public input on the current conditions of the Route 28 Corridor from Kittanning to I-80, the study team utilized an online WikiMap survey. The survey was available at <a href="https://wikimapping.com/Route-28-Corridor-Study-Kittanning-to-I-80.html">https://wikimapping.com/Route-28-Corridor-Study-Kittanning-to-I-80.html</a> from Friday, February 7 through Friday, March 6, 2020. The Steering Committee member organizations promoted the survey through a press release, emails, and social media. Direct links to the mapping survey were also available on the study website (<a href="https://www.Route28CorridorStudy.com">www.Route28CorridorStudy.com</a>).

The interactive map allowed users to place points on a map of the corridor to identify areas of concern or opportunities for improvement related to vehicular, freight, bicycle, and pedestrian traffic. Each mode included targeted survey questions to collect specific details about the concern or opportunity.

During the course of the survey period, 305 total points were placed by 151 unique users. A majority (269) of points were related to vehicular traffic. Nineteen (19) were related to freight; ten (10) related to pedestrians; and seven (7) related to bicycles.

The survey points revealed common areas of concern, some of which were corridor-wide. Areas of concern were summarized into 31 unique locations. In each survey by travel mode, the public was prompted to select from several options for "What about this location causes you concern?" While each mode varied slightly in the options, the most common concerns were roadway safety; vehicle speeds, slow moving vehicles, intersection sight distance, and visibility of pedestrians and bicycles on the roadway.

Mr. Petulla then reviewed the Study Concern Matrix, which collected the concern locations that were documented in all aspects of data collection and studies. Thirty-eight (38) locations were listed in the matrix, and the Study Team indicated in columns across the matrix how the location was identified as a concern. These included previous studies, stakeholder interviews, public surveys, field observations, horizontal curvature, vertical grade, crash history, and existing operations. The team then noted the number of

times the location was found to prioritize these concern areas. Locations that were found in five or more data collection points were listed as High Priority. All others were listed as Moderate.

The team requested feedback from the Steering Committee within two weeks regarding the methodology for identifying these locations, whether they agree with the draft prioritization as presented, or if there are additional locations that should be considered higher priority.

Mr. Petulla then opened the meeting for discussion. The following questions or comments were discussed:

- The Committee requested a map of all locations on the Study Concern Matrix to provide a more visual context of each concern location.
- The Committee asked whether public input from other surveys and studies had been included. To this point, that input had not been considered, but the team will review the following for public concerns related to the corridor:
  - o State Transportation Commission Twelve Year Program Updates in 2017 and 2019
  - North Central and Northwest RPOs' recent Long Range Transportation Plan updates
  - o North Central RPO Safety Plan
- The Committee also noted that PennDOT Central Office has recently updated the Highway Safety Manual and associated Highway Safety Network Screening which provides predicted crash data (not only observed) for various roadway types. This information may be helpful to identify potential or predicted safety concern locations in addition to the observed safety concern locations. SPC offered to provide access to this tool and data.
- The Committee asked what methodology was used to warrant a check in the crash % column of the matrix. Ashley indicated that anything that was higher than the statewide average was included.
- Dominic D'Andrea asked if the team reviewed the Highway Safety Predictive Model. Ashley indicated the model had not been considered, but the team will review moving forward.
- Amy Kessler mentioned the Freight Plan Survey noted a comment related to potential truck turning issues at the intersection of Main Street and Route 28 in Brookville and a curve on Route 28 between Seldom Seen Road and Coder Road that is very dangerous.

The following is a list of next steps discussed during the meeting:

Follow-Ups			
Follow-up item	Responsible Party	Anticipated Completion	Actual Completion
Map all concern locations listed in matrix and provide to	McCormick Taylor	4/28	4/28
the Steering Committee			
Review additional public input from previous	McCormick Taylor	5/1	4/29
surveys/studies			
Review relevant corridor information from Northwest	McCormick Taylor	5/8	
and Northcentral RPO LRTPs, Northcentral Safety Plan			
Review Highway Safety Predictive Model	McCormick Taylor	5/11	5/11
Update the construction engineering cost assumption	McCormick Taylor	5/11	5/11
from 5% to 10% per Tim Jablunovsky			
Provide feedback on methodology and prioritization of	Steering Committee	5/12	
concern areas	-		

The meeting was adjourned at approximately 12:00 p.m. by thanking the committee for their feedback during this meeting and throughout the study.

Prepared by: McCORMICK TAYLOR, INC. <u>Copies:</u> Attendees MT Project File

<u>Attachments:</u> Study Concern Matrix Draft Existing Conditions Report



*Meeting:* Steering Committee Meeting #4

*Location:* Conference Call

 Date:
 June 10, 2020

 Time:
 1:00pm – 2:30pm

#### Attendees:

Steering Committee:		
Darin Alviano	Armstrong County	
Kristi Amato	Clarion County	
Amy Kessler	Northcentral RPO	
Travis Siegel	Northwest RPO	
Dave Tomaswick	PennDOT District 10	
Tim Jablunovsky	PennDOT District 10	
Lillian Gabreski	Southwestern Pennsylvania Commission	
Josh Spano	Southwestern Pennsylvania Commission	
Domenic D'Andrea	Southwestern Pennsylvania Commission	
Ryan Gordon	Southwestern Pennsylvania Commission	

McCormick Taylor Study Team: John Petulla Melissa Thomas Jennifer Threats Carrie Machuga

#### Purpose:

The purpose of the meeting was to discuss the results of the Future Conditions Analysis, review the potential Improvement Concepts, and outline the next steps to draft and finalize the Study Report.

#### Discussion:

John Petulla, consultant Study Project Manager, began the meeting by welcoming all attendees and asking all Steering Committee members to introduce themselves. In advance of the meeting, the Steering Committee received the meeting agenda, draft final study report outline, draft improvement concept mapping, and the concern area matrix and mapping.

Mr. Petulla briefly reviewed the work done since the previous Steering Committee meeting, including updates to the concern area matrix. The team also reviewed additional studies as suggested by the committee and updated the matrix with some additional concerns found there. The matrix was updated to show the locations with higher occurrence across the various data collection and analysis sources.

The team mapped the concern areas from the matrix. Clusters of related improvements were found at the north and south ends of the corridor, with potential intersection improvements in the middle portions of the corridor. Mapping of crash data along the corridor in relation to these locations was also reviewed. High occurrences of hit-fixed-object crashes are consistent with narrow lanes along the corridor, and there was a high occurrence of head-on crashes at many horizontal curves throughout the study area.

Mr. Petulla also mentioned the Future Conditions analysis which the team has been developing. Historic growth trends were reviewed and revealed that more growth has been happening along the portions of Route 28 that have been upgraded to four lanes (1% growth rates) than in portions that are two lanes ( $\frac{1}{-12}$ ). Working with SPC, the Study Team determined a  $\frac{1}{2}$ % growth rate would be utilized to consider future traffic projections. Mr. Petulla concluded that, based on the overall future conditions analysis, the existing corridor does not appear to have any major capacity or congestion issues. Only one area showed a degraded level of service in the future projections – the

area between Routes 1028 and 1035, just north of Kittanning. Most concerns identified were related to corridor operations and safety.

Melissa Thomas, Study Highway Lead, reviewed the draft improvement concepts developed to address the concerns identified along the corridor.

- Concern ID #6: Sloan Hill Road Sloan Hill Road intersects Route 28 at a skew, which causes sight distance concerns. The draft improvement concept improves the turning radius and realigns the intersection to be more perpendicular to Route 28. The concept would also include wider shoulders and a grade adjustment.
- Concern ID #8: Near Oscar Road This improvement concept would adjust the vertical grade over ¾ mile, which includes three crest curves and three sag curves. The concept includes several cuts and fills to achieve a smoother profile. This area has a high occurrence of hit-fixed-object crashes.
  - o Tim Jablunovsky, PennDOT District 10, requested a profile be added for this concept.
- Concern ID #14: Madison and Kohlersburg Roads This draft concept would reconfigure and better define this intersection where the two side roads approach Route 28. The concept would channelize the intersection to direct traffic through the intersection. This improvement would better define the intersection, remove pavement and add green space. Improving this intersection could also help with access management along the corridor. The study team also considered a roundabout design at this location; however, after a high-level benefit/cost analysis it was determined not feasible.
- Concern ID #25: Redbank Valley Trail Crossing The trail currently crosses Route 28 at a steep diagonal in an area with vertical and horizontal curves. The improvement concept would realign the trail to run parallel to Route 28 between the roadway and the river to a perpendicular crossing at the intersection with Middle Run Road. Route 28 would be shifted slightly away from the river using roughly the same footprint of the current roadway and trail. Other countermeasures such as rectangular rapid flashing beacons, could also be used to alert drivers of the trail crossing and give trail users more visibility.
- Concern ID #29: Mayport Road Mayport Road intersects Route 28 at a severe skew, causing sight
  distance concerns. The improvement concept would relocate the intersection south to a more perpendicular
  intersection with Route 28. The remainder of Mayport Road would end in a cul-de-sac. The relocated
  roadway would require a cut in order for Mayport Road to meet Route 28 with an eight-percent grade.
- Concern ID #33: Near Moore Road The curve in this area is substandard, and the conceptual improvement would flatten the curve and reduce the grade.
- Concern ID #35: Seldom Seen Road and Seneca Trail (T396) This improvement concept would flatten the curve near this intersection.

Following the discussion of the draft improvement concepts, the Steering Committee offered the following comments and/or questions:

- Dave Tomaswick, PennDOT District 10, requested that the current posted speed limits be added to each of the draft improvement concept displays.
- Josh Spano, SPC, requested that the team be as specific as possible when listing additional low-cost improvements in the final report documents.

 Darin Alviano, Armstrong County, asked whether the speed limits would be made consistent throughout the corridor. The improvements would help make the roadway meet design criteria which will improve safety, but speed limits will still vary throughout the corridor.

Mr. Petulla then reviewed the draft outline for the final study report. The report will conclude with a mini-Transportation Improvement Program, or mini-TIP. Mr. Petulla and the committee discussed how the mini-TIP will be organized and what will be included. Improvement concepts will be included in the mini-TIP, including those that have not been developed in detail as those discussed in the meeting today. As suggested by Amy Kessler, Northcentral RPO, all possible funding sources will be listed, as appropriate in the mini-TIP. For example, the trail improvement may qualify for funding through the Department of Conservation and Natural Resources. She also suggested organizing the mini-TIP according to planning district.

Ms. Kessler also asked whether the report can show the cost estimate for continuing the four-lane template for the length of the corridor and why incremental improvements were determined more effective. Mr. Petulla noted that the Existing Conditions Report included the cost estimate for the four-lane improvement, both from the 1994 study and updated with 2020 costs, and the final report can give details about why that improvement would not be cost-effective.

Domenic D'Andrea (SPC) asked that the team provide some basic cost-benefit information on the conceptual improvements, and Mr. Alviano agreed that it would help show that these improvements provide the best 'bang for the buck'. The team will work to incorporate any safety improvement, crash reduction and travel time benefits as the concepts are further developed.

Mr. Jablunovsky asked whether the website will be updated when the report is complete. The Study Team agreed to share the final report on the website and with an email to the individuals who have subscribed to the study email update list. A press release will also be drafted to announce the completion of the study.

The Study Team and Steering Committee members agreed that each MPO/RPO will need to determine the best way to present the findings to their boards of directors, due to the lack of in-person meetings at this time. SPC and Study Team members will be available to attend meetings (virtual or in-person) as needed to discuss the final report.

Ryan Gordan, SPC, closed the discussion by noting that the report should focus on three inter-related pieces: the concern matrix, concern area mapping, and the mini-TIP. These items should be stylized to connect and summarize the study visually.

The meeting was adjourned at approximately 2:30 p.m. by thanking the committee for their input and discussion during the meeting and throughout the study. This will be the final Steering Committee meeting.

The following is a list of next steps discussed during the meeting:

Follow-up item	Responsible party	Anticipated completion	Actual Completion
Add current posted speed	McCormick Taylor	6/26	
limits to all concept maps			
Provide a profile for	McCormick Taylor	6/26	
Concept #8			
Organize mini-TIP by	McCormick Taylor	6/26	
county			
Create matrix (or similar) of	McCormick Taylor	6/26	
funding sources to show			
which improvements may			
qualify for each			
Provide benefit-cost	McCormick Taylor	6/26	
analysis for concepts			
Stylize/coordinate the	McCormick Taylor	6/26	
matrix, concerns/concept			
mapping, and Mini-TIP			
Update website with final	McCormick Taylor	7/17	
report findings	-		

Prepared by:

McCORMICK TAYLOR, INC.

Copies:

Attendees MT Project File

Attachments:

Updated Concerns Matrix

Concerns Area Map

Crash Location Maps

Draft Improvement Concept Displays

Draft Final Report Outline

# APPENDIX B Public Comments Received

lat Ing	Additional Comments Fe	Feature Feature ID Type	Feature Description     Created(DD/MM/YYYY)     Inputter ID	Please describe the area of your opportunity/concern:	I use this area for: (0	Check all that apply) -							How frequently do y facility? (Select one)	ou use this	What about this location	n causes you cond	erns? (Check all that app	ly) -						Do you h for us to
					Local commuting (Less than 10 miles each way)	Regional commuting (More than 10 miles each way) freight, etc.)	Accessing government services	Accessing Redbank Valley Trail	Accessing local schools	Accessing sto services, goo healthcare	tores, Accessing ods, recreational opportunities Other	If Other, please explain	Daily Weekly	Monthly	Sidewalk ends/no Sidewalk sidewalk condition	No Peo shoulder saf	destrian Roadwa ety/visibility safety	y Shoulder condition Drai	Vehicle nage speeds	Proximity to large trucks/ vehicles	Crosswalk	Sidewalk not Americans with Disabilities Act (ADA) compliant	Connectivity Aesthetics	s Please explain your concern.
				Why does this significant corridor connecting										,								· ·	,	
				Pittsburgh with I-80 go through the center of a																				
41.004511 -79.31824	6	374402 point	2/8/2020 272976 Guest	small town and right in front of a school.																				
41.00425 -79.325312	2	374423 point	2/10/2020 273109		х								Х			X								
44 464605 - 70 00755	_	274570	2/40/2020 2724.02	heavy foot traffic along allegheny blvd. no											×									
41.164685 -79.09755	/	374570 point	2/10/2020 2/3163	SIDEWAIKS	X								X		X								X	heavy fact traffic for people commuting to
																								work or walking to businesses from truck
41 166954 -79 09758	1	374578 noint	2/10/2020 273163	no sidewalks	x								x		x	x					x			stons no sidewalks
41.100334 73.03730	<u> </u>	374378 point			A								X											ATV's cross roadway NO signage and is very
																								unsafe. Safe crossing to be installed for
41.143364 -79.14650	6	380371 point	2/15/2020 273780		x	x		x	x	x			x			x	x		х	х			x	proper line of sight.
				The cross walks are there but vehicles almost																				
				never stop. I walk around new Bethlehem a lot in																				
				the summer months with my young children. The																				
				amount of times we wait for several cars before																				
41.00425 -79.32531	2	374423 point	2/19/2020 2/41/4	someone is kind enough to let us cross is unreal.	X			X	X	X	X		X			X			X		X			This is a school and yet youte 29 is a MAIN
41 003869 -79 31811	3	380537 point	2/23/2020 273737						x				x			x								ROUTEL
41.005005 -75.51011.		586557 point	2/25/2020 2/3/3/						~				~			X								
				There is an icecream stand RIGHT along 28 there.																				
				People are constantly slowing down, pulling in																				
				and pulling out. A big truck coming either north																				
				or south on that road and there could be very																				
				bad accidents. Also, not even 200 yards North																				
				from the ice cream store is the entrance/exit to																				
				the new Dollar General. Cars, again, are slowing																				
				down for turning cars and crossing traffic. They																				
				say it was surveyed and there is enough viewing																				
				room to see oncoming southward cars. Yes,																				
				maybe if you are in a 'tall' vehicle but not a car. I																				
				can't tell you how many 'near misses' I've seen at																				
				both places. And there have also been accidents																				
40.00000 70.2500			2/26/2020 27/720 0.001	at both. DANGEROUS!!!!! Why wait till a life is															N N	v.				the contained it all an the first second
40.968999 -79.35684	4	380686 point	2/26/2020 2/4/30 Guest	Two pooplo killed in recent years creating the		+		_			X		×			×			X	X				i ve explained it all on the first screen.
				highway from the motel to the Bench Bacers																				
40 820727 -79 48809	8	380690 point	2/26/2020 274739	store.						x			x		x	x x		x	x					
						+																1		In summer there is lots of activity around this
																								business, it's hard to get in and out of parking
40 970179 -79 2520	3	380822 noint	2/29/2020 275059	Ice cream stand		x								x			х		x	x			1	lot almost got hit

		Do you have a photo of this area of concern for us to consider? Please upload it here.	Is there any other information you would like us to know about the Route 28 corridor?
cs	Please explain your concern.		
	heavy foot traffic for people commuting to work or walking to businesses from truck stops. no sidewalks		
	ATV's cross roadway NO signage and is very unsafe. Safe crossing to be installed for proper line of sight.		
	This is a school and yet route 28 is a MAIN ROUTE!		Route 28 is the main road of this area.
	I've explained it all on the first screen.		There is the sharp turn in South Bethlehem that some large vehicles, trucks, aren't familiar with and it's very difficult to maneuver. The roads in South Bethlehem are narrow and aren't always accomodating or safe for all vehicles.
	In summer there is lots of activity around this		
	business,it's hard to get in and out of parking lot,almost got hit.		

Addition	al Feature Feature	Feature Created Descripti (DD/MM/Y Inputter on YYY) ID Ir	Please describe the area of	l use this area for: (Check al	l that apply) -		How frequently do you use thi facility? (Select one)	is What about this loc	ation causes	s you concerns? (Check all that apply)		Do you have a photo of this area of concern for us to consider? Please upload it here.
				Local Regional commuti commuti Busine ng (Less ng (More Travel than 40 than 40 (Delive miles miles s, mov each each freight way) way) etc.)	erie Accessing ring governm t, ent services	Accessing stores,Accessing stores,Accessing AccessingAccessing services,services,recreatioRedbank ValleyAccessing goods,nalValleyIocalhealthcaropportunTrailschoolseitiesOther	ner, please in Daily Weekly Monthly	Shoulder No is too shoulder narrow	Poor shoulder condition	Lack of Travel lanes Lack of are too Debris bike lane bike lane narrow Di	Proximity to large Vehicle truck/ Roadway regional trail rainage speeds vehicles safety system Aesthetics concern.	plain your
40 08056 70 2447	274401 point	2/8/2020 272076 6	Add a bike trailhead in this									
41 01324 -79 3045	374573 point	2/10/2020 273163	bicycle crossing for rails to	x			x				X X X trails	or rails to
			Needs safe way for bicycles to cross 28 at fish basket crossing	g								
41.00043 -79.3342	380523	2/22/2020 274433	on Redbank valley trail.			x	х			x	x	
											Danger t and mot dangero hill, and distance	a trail users rists due to s curve, the he short sight Signage is
41.0146 -79.3009	380709	2/26/2020 274763	Opportunity to provide a continuous 90+ mile trail for bikes, hikers, pedestrians and alternate transportation from East Brady to Ridgway,, Elk County. Connection needed from Brookville Park to Allens Mills, including a crossing over I-80 which PA DOT removed. From there it can connect to Five Bridges Trail, Trail Town	r		x					X X very inac	equate.
41.15247 -79.0866	380713	2/26/2020 274763	Little Toby Trail.	x x		x	x	x x	x	x x x x	x x x x	PA Wilds Loop concept January 2019 meeting agenda.docx
41.01325 -79.3045	380718	2/26/2020 231922	The Redbank Valley Trail crosses Rt. 28 at this point. Motorist-facing signage is in place, but roadway markings would help alert drivers of the trail crossing.	e X		x x	x			x x	Roadway alert driv crossing increase X crossing	markings to ers of the trail vould he safety of rail users.
41.17077 -79.0953	380719	2/26/2020 231922	Ideally, this study would exten to include Rt. 28 as it continue under I-80 on the east side of Brookville. This site has the potential to connect the existing Redbank Valley Trail to the Tricounty Rails to Trails system further north.	nd es to X							The Red Trail count through towards but unim Bridges Bridges the Trice Trails system includes Little Tol Finding a over 1-80 a key in these two should b part of the	ank Valley d continue prookville he existing proved Five rail. The Five rail is part of unty Rails to em and he Clarion- y Trail. way under or is going to be ponnecting trails and explored as is study.

lat Ing	Additional Fe Comments ID	eature Feature Feature Type Description	Created(DD/ Inputter MM/YYYY) ID Ir	Please describe the area of putter your opportunity/concern:	I use this area for: (Check all th	hat apply) -				1				How frequently do yo facility? (Select one)	ou use this What about this	s location causes	you concerns? (Check al	that apply) -					Do you have a photo of this area of concern for us to consider? Please upload it here.	Is there any other information you would like us to know about the Route 28 corridor?	
					Local commuting (Less than	Regional commuting (More th	han 10 Business Travel (Deliveries,	Accessing governmen	nt Accessing Redbank	Accessing local	Accessing stores, service	ces, Accessing recreational	If Other, please		Pedestria Cyclis	ist Roadway N	Roadway lan Vehicle incline/gr ste	nbing Travel e on lanes are Int ep too on	ersecti too Congestio	Stopping or turning Co	Height weight onnectiv Loading restrict	or			
				90 degree right hand turn going North bound, slows th	10 miles each way)	miles each way)	moving freight, etc.)	services	Valley Trail	schools	goods, healthcare	opportunities	Other explain.	Daily Weekly	Monthly n safety safet	ty safety s	speeds ade gra	de narrow na	rrow n	Drainage vehicles ity	y zones ns	Please explain your concern. High roll over points, sharp tur and small lane width are a reci	rns ipe		
40.99809 -79.3423		374439 point	2/10/2020 273141	flow of traffic for tractor trailers and tri axles	x	x	X				x	X		X	×			x	x	x		for disaster. The lane needs widened. sharp curve hard for truck mu	ltiple		
40.99914 -79.3429		374572 point 380274 point	2/10/2020 2/3163	I believe the area of 28 from the hill, known in the area as 'Hog Back'Ito Distant could benefit from dedicated lanes for commercial trucks. The rt 28 follows the river an	d	X									x	x x	x x x		X			This entire stretch of 28 has always been hazardous, in my opinion. I've always heard tha was constructed the way it wa the scenic views in the past. T road design isn't safe for the v people drove today.	t 28 is for 'he vay	I really hope this study has positive results. I fear the roadway will continue to deteriorate and become even less safe in the coming years. With the precipitation our region has been taking on, there could potentially be more road washouts like we experienced recently.	
41.12774 -79.1705		380286 point	2/13/2020 273526	in many places the road is squeezed onto a very tight river bank. There is a lot of rock to be removed.									Narrow road access up thru the mountain and the RedBank X Creek	ins X		x	x	x x	x	x				It is a narrow roadway in many places.	
41.15242 -79.1014		380373 point	2/15/2020 273780		x	x	X	x	x	x	x	x	x	x x	x x x	x	x x	x x	x	x x x	x x	CONSTRUCT ALLEGHENY VALL EXPRESSWAY PENNDOT HAS PLANS!	EY		
40.83901 -79.3689 40.96455 -79.3609		380389 point 380274 point	2/17/2020 273893 2/18/2020 273998			X	X							X	X	X X X	X X X X X	X	X X	X X X	X				
40.96455 -79.3609		380274 point	2/19/2020 274174		X				X	x	X	X		x		X				X			Local fire departments in New Bethlehem cause a great deal of traffic with book drives on weekends where traffic is already greater than normal. I think this should be a huge concern for pedestrian safety, vehicle safety and congestion.		
40.99568 -79.3421		380460 point	2/19/2020 274183	Towns and hills are ridiculou to get through for almost all traffic from Brookville to Kittanning. Speed traps, intersections, hills, and curve make this route a pain in the butt to drive with most vehicles, even a car. It needs a bypass around most of it.	s	x								x	x x x	x	x	x		x					
40.02406 70.2621		280464 point	2/10/2020 27/180	lots of hills with no passing lanes to get around all these loaded freight trucks. No trucks, I can get home in 22 minutes from Kittanning. With trucks it takes upwards of 45 minutes because you can't get around them. It's 14 miles from Kittanning to my	1	~					Y	v							v	v		Roadway safety is bad, I've see cars pass trucks in a no passin zone (passing while going up a when the trucks are at their slowest). If every hill offered a passing zone, it would be safe Coming out of Goheenville, it's free for all speeding to get pas	en g hill the roads are rough, they need r. fixed and not just the taring in of the holes. That's ridiculous how it makes a thud noise every time you drive over those lines.		
40.99568 -79.3421		380460 point	2/21/2020 274335	In New Bethlehem, we have the Smuckers plant. I would like to see new access for truck traffic going to/from Smuckers directly off route 2 without going to the plant vi	8	X X								X X			× × X								
40.99526 -79.3299 40.96191 -79.3639		380514 point 380545 point	2/21/2020 274364 2/23/2020 273737	Penn Street. Passing lane too short	X	x	X	X	X	x				X	X	>	x			X		Passing lane too short.			
40.90677 -79.3713 40.99361 -79.339		380546 point 380563 point	2/23/2020 273737 2/23/2020 274504 G	Bend too sharpI think this would be a goodopportunity to bypass thisarea because there is a lot oftrucks that have trouble withthe turns in town andsometimes cause manybackups from them gettinguest	X	x	X						x	X				x x		x			I think this project would be a great idea. The road from Kittanning to New Bethlehem is horrible with a lot of vehicle fatalities and would be a upgrade for this area		
				A combination of steep hills and sharp turns make it dangerous for trucks																		There are alot of steep hills wi sharp turns at the bottom and	th		
40.96191 -79.3639		380545 point	2/25/2020 274617	Need 4 lanes in this area from kittanning to New Bethlehen then new reroute north of New Bethlehem to make for more activities and recreatio along North Fork.	n n n	X	X X				X	X		X X X	X X X X	>	x X X	X		X		Need to make this route easie travel to attract more revenue safety!	Not much level land north of New bethlehem within present route 28 now, and to attract more revenue for recreation, college, and freight, I feel a better solution to avoid heavy construction such as exploding mountain ranges to level or to avoid to many bridges and the upkeep of them is to reroute onto 66N at New r to Bethlehem and forward traffic to I and the Clarion exit/Easy travels for college students at CUP!		
40.99995 -79.3418		380823 point	2/29/2020 275059	Bend coming into town		x								x			x	x				This turn is a bottleneck,slows trucks and traffic down too m	uch.		
				Tight turn into congested area. This area would benefi by bypass or other handling CMV traffic Dangerous	t of																	The area generally around and through New Bethlehem is tig dangerous with many stopped slow moving vehicles. CMV ar bypass traffic would benefit greatly if a bypass route (straig with better lanes) could be	ht, l or nd ghter		
40.99548 -79.341		380998 point	3/4/2020 275390	curve.			x						x		x x	x	x x	x		x		designed and implimented.			

Additional	Feature Feature Feature ID Type Description	Created(DD/ Inputter MM/YYYY) ID Inp	utter Please describe the area of your opportunity/concern:	Luse this area for: (Check all that apply) -		How frequently do you use this facility?	What about this location	n causes you concerns? (Check all that apply) -					Do you have a photo of this areaIs there any other informationof concern for us to consider?you would like us to know aboutPlease upload it here.the Route 28 corridor?
40 837713 -79 466232	37/1363 point	2/7/2020 272911	This is a blind intersection. Many accidents have occurred here	Local commuting (Less than 10 miles each way)       Regional commuting (More than moving freight, etc.)       Accessing government services       Accessing Redbank services       Accessing Redbank services	g local Accessing stores, services, goods, healthcare Accessing recreational opportunities Other If Other, please explain.	Daily Weekly Monthly	v Pedestrian safety	Cyclist Roadway Vehicle Slow mo safety safety speeds vehicles	oving Stopping or Congestion turning vehicles	Connectivity access	Drainage Parking Signal timing maintenance	dge Sight distance No passing lane	Please explain your concern.
40.837713       -79.400232         40.868648       -79.42881         40.904491       -79.371154	374365 point           374364 point           374365 point	2/7/2020 272911 2/7/2020 272911 2/7/2020 272911	Blind intersection pulling onto Route 66/28 Blind intersection coming onto 66/28	A     A     A     A       M     X     A     A       X     A     A     A		X       X       X       X		X         X         X           X         X         X           X         X         X	× × × × × × × × × × × × × × × × × × ×				
40.917626       -79.365017         40.924014       -79.361562	374366 point 374367 point	2/7/2020 272911 2/7/2020 272911	Blind intersection heading southbound on 66/28 Blind Intersection High traffic area passes very popular IceCream stand. Very dangerous	X         Image: Constraint of the second secon		X X		X         X         X           X         X         X	X X				
40.971037 -79.352951	374368 point	2/7/2020 272911	turning off/on to 66/28 when this is open Dollar general store has poor line of sight. Entering/exiting this store is	is v	X V	X		x x x	X		X	X	
40.972921       -79.351079         40.97135       -79.352528         40.99912       -79.34296	374309 point           374370 point           374371 point	2/7/2020 272911 2/7/2020 272911 2/7/2020 272911	Cars parked at this business often obstruct view of northbound traffic Sharp turn has been the scene of many accidents	ic X X I I I I I I I I I I I I I I I I I		X X X		A         A         A           X         X         X           X         X         X           X         X         X			X .		
40.868648 -79.42881	374364 point	2/8/2020 272972	An opportunity to engage the PA State Legislature to authorize the	x International		X			x x	x x		X X	
			extension of the Pennsylvania Turnpike System from a point north ea Kittaning at the terminus of SR 28 Expressway to a point along I-80 in	ast of Inthe Inthe International	This is also the most direct route								Basically this corridor is in need of a completed expressway or turnpike to provide access to 1.80. For the longtorm
40.818083 -79.489783	374375 point	2/8/2020 272976 Gue	a metropolitan area the size of Pittsburgh is entitled to the Dwight D. Eisenhower National System of Interstate and Defense Highways.	X X X X X	between Pittsburgh and New X York City.	X	x	x x x x	x x	x x	x	x x	economic viability of the region this project must advance.
			This tight radius turn is emblematic of the problems with this corrido general. There is no consistent design typical section, design speed, o corridor context making this corridor extremely challenging to safely	or in for in the second s									
			navigate. Roadway improvements have obviously been conducted ad without any regard to the bigger picture or the fact that this is the mo	d-hoc host									
			corridor is deserving of at the very least a controlled/ limited access ri of-way from the terminus of SR 28 Expressway near Kittaning to a dire	right- rect									
			interchange with I-80 in the vicinity of Brookville.	m the									This curve requires no explanation as it is so bad. The fact that this curve is still part of
			low end new alignment such as US 222 from SR 309 to SR 611 as constructed in Eastern PA to the upper range of a full fledged limited		Most direct corridor between Pittsburgh and New York City, th	his							the PennDOT's 2 digit SR network is an embarrassment to our commonwealth. A
			An interesting concept would be to develop an alignment and typical		should not be discounted and the state this corridor is in is a disservice to the Pittsburgh	ne							access typical section is required for this critical connection between the Pittsburgh
40.99912 -79.34296	374371 point	2/8/2020 272976 Gue	section as a demonstration project of what a semi-autonomous vehic st corridor could look like in the future.	cle x x x x x	Region's connectivity to this         X       important city.	×	x	x x x x	x x	x x	xx	x	Region and the North East, New York City Included. Most Metropolitan Areas the size of
			A Direct interchange is required connecting I-80 with the New SR 28 Expressway which needs to be built to connect Pittsburgh with the N	North									Pittsburgh have direct access to their adjacent Interstates, the fact that this road
41.146965 -78.993888	374376 point	2/8/2020 272976 Gue	plan and constructed with the project unlike the I-80/I-99 interchange which has lagged for 15 or so years.	ge X X X		×		x x x	x x	x x	x x	x	is not a highway is a disgrace to our region and shows malfeasance from our regional planners.
			This exit is not explicitly and clearly marked as the best exit for SR 28 to Pittsburgh. An opportunity here would be to reporte SR 28 from exits and the second s	south exit 81									
			to exit 78 along I-80 and revise the current designation to be the Busi Route 28. More Clear Signing that this corridor leads to Pittsburgh ne	siness eeds	Connecting Pittsburgh to NYC								Making this corridor clear that it connects to
41.170674 -79.095651	374377 point	2/8/2020 272976 Gue	<ul> <li>to be added to the exit especially along the WB direction.</li> <li>The amount of congestion along this corridor is not consistent with mexpectations for long distance travel. This corridor connecting Pittsbu</li> </ul>	my logh log	X along the most direct route.					X X			Pittsburgh is critical.
41.166313 -79.097636	374378 point	2/8/2020 272976 Gue	with New York city needs to have controlled or limited access right-or and be designed for long distance travel. The corridor through this area is not consistent with the expectation	of-way X X		×		x x x	x x	x x	x	x	
41.014619 -79.303425	374379 point	2/8/2020 272976 Gue	through highway. Improvements should be made to provide a safe hi st speed road in this area.	iigh X X		×		x x x	x x	x x	x x	x x	
			This location is a prime example of failures of the SR 28 corridor proje over the past 3 decades. How do you make typical section improvem	ects hents									
			just north and just south of this location but still have a short section tight curve geometry and practically no shoulder. This critical corridor between Pittsburgh and the Northeast should not be subject to sudd	n with or den									
			and unexpected deterioration in typical section for short or long leng consistent typical section with controlled access or limited access righ	gths. A ht-of-									
40.906673 -79.371355	374380 point	2/8/2020 272976 Gue	<ul> <li>way is required for a corridor of this significance.</li> <li>Another example of corridor inconsistencies. Highway gets realigned this short section through Slabtown, but neither up-grade (relative to</li> </ul>	X     X       In     In       o the     In		X			X X	X X		X X	
			slope of the road not the quality of the project) included the construct of a truck climbing lane. This is totally inconsistent with the typical sections of other improvement project's along the corridor	iction									
			Corridor design criteria need to be approved with a final selected										
40.882 -79.391233	374381 point	2/8/2020 272976 Gue	St alternative before any additional inconsistent upgrades are construct Work with US congress and Senate to get this route added to the Appalachian Regional Corridor network to get it upgraded to an	ted. X X						X X			
41.089427 -79.227246	374382 point	2/8/2020 272976 Gue	appropriate alignment and typical section for a significant corridor st connecting Pittsburgh and I-80.	x x		x		x x x	x	x x	xx	x	
			With 322 already using this road; why not realign 28 onto I-80 to elim confusion and make a clear path all the way from I-80 to Pittsburgh.	ninate									
			If you were traveling west on I-80 and someone told you to get off at exit for Pittsburgh? Where would you get I-79? Why not make 28 the	t the e ideal									
41.160304 -79.074745 40.818341 -79.489719	374383 point 374384 point	2/8/2020 272976 Gue	route and corridor for travel from Pittsburgh to I-80. This is an opportunity for a round about; especially to signify the tran from one roadway typology to another.	nsition X X X I I I I I I I I I I I I I I I I		x x		x x x	x x x x	x x x	x x	x x x	
40.000000 70.405.470	274205 a sint	2/8/2020 272075 Cur	Realign cross roads to a single location to provide a more controlled a predictable corridor experience. Signalization should be avoided and	and V									
40.859208 -79.405478	574565 point	2/8/2020 2/29/6 Gue	Realign cross roads to a single location to provide a more controlled a predictable corridor experience. Signalization should be avoided and	and A A A A A A A A A A A A A A A A A A A									
40.971229 -79.352222	374386 point	2/8/2020 272976 Gue	st         roundabouts used instead (typical - corridor)           Realign cross roads to a single location to provide a more controlled a predictable corridor experience. Signalization should be avoided and	and		x			X X	X X	X X	X	
41.040227 -79.256972	374387 point	2/8/2020 272976 Gue	roundabouts used instead (typical - corridor) Realign cross roads to a single location to provide a more controlled a predictable corridor experience. Signalization should be avoided and	x         x         x           and		x		x x x	x x	x x	X	x x	
41.134348 -79.152858	374388 point	2/8/2020 272976 Gue	ist       roundabouts used instead (typical - corridor)         Good location for a round about to signify the change of roadway										
41.163374 -79.097537	374399 point 374390 point	2/8/2020 272976 Gue	st     typology.       Good location for a round about to signify the change of roadway       st     typology.										
41.163381 -79.098	374391 point	2/8/2020 272976 Gue	Round about needed here to alert drivers to the change in roadway t Traffic signals poorly timed; round about needed to allow smooth flo	type. by for the second s									
41.16959 -79.098027	374392 point	2/8/2020 272976 Gue	all travelers. Traffic signals poorly timed; round about needed to allow smooth flor	ow for							X		
41.167264 -79.097769	374394 point	2/8/2020 272976 Gue	Why does this significant corridor connecting Pittsburgh with I-80 go through the center of a small town.				x	x x x	x				
41.118804 -79.18959	374395 point	2/8/2020 272976 Gue	Why does this significant corridor connecting Pittsburgh with I-80 go through the center of a small town. Why does this significant corridor connecting Pittsburgh with I-80 go				X	x x x	x x	x x			
41.019508 -79.273357	374396 point 374397 point	2/8/2020 272976 Gue	stthrough the center of a small town.Why does this significant corridor connecting Pittsburgh with I-80 gostthrough the center of a small town.				X X	X X X X X X V	X X X	x x x v		x x x v	
40.970421 -79.354402	374398 point	2/8/2020 272976 Gue	Why does this significant corridor connecting Pittsburgh with I-80 go through the center of a small town.				x		x x	x x	X	X /	
40.838775 -79.465929	374399 point	2/8/2020 272976 Gue	wrny does this significant corridor connecting Pittsburgh with I-80 goistthrough the center of a small village.Why does this significant corridor connecting Pittsburgh with I-80 go				x	x x x x	x x	x x		x x	
40.821455 -79.487149	374400 point 374403 point	2/8/2020 272976 Gue	<ul> <li>through the center of a small town.</li> <li>This interchange is in consistent with the corridor providing access from the state of the state of</li></ul>	Image: Constraint of the second sec			X	X X X X	x x x	x x x		x x	
40.998723 -79.331177	374404 point	2/8/2020 272976 Gue	When SR 28 Expressway gets relocated across the Creek here make su there is a interchange for SR 66.	sure Contraction of the second se						x x			
			well above the posted limit. When pulling into or out of 1027 the fas moving traffic is a concern. A turning lane would help to get us out o	go st of the									
			travel lane to turn into 1027 when coming from kittanning. I put my signal on (especially in bad weather) at the top of the hill just past me early's auto repair. As i slow for the turn at the bottom of the hill per	erle sople	I use this intersection multiple times per day. I would say peop	ple							
40.894796 -79.372573	374410 point	2/9/2020 273059 Gue	generally swing out into the oncomming lane and continue at travel speed.	x x x x	X     X       X     X	ito s. X		x x x	x				The lack of passing lanes causes long back
40.842031 -79.463525	374414 point	2/9/2020 273073	The whole way between Kittanning and New Bethlehem	x x	x	x x		x x x	x				ups behind big trucks which can lead to drivers becoming reckless.
40.819073 -79.489811 40.999232 -79.34286	374416 point 374417 point	2/10/2020 273095 Gue	st Stop light and lack of signage for stop light	X         X         Image: Constraint of the second	X     A       X     A       X     A       A     A	X X			X X	x x	X	x	Too sharp of a bend. Basically 90 degree in South Bethlehem
41.046685 -79.253945	374418 point	2/10/2020 273101 Gue	Pulling out on Rt 28 from the Mayport road is very difficult and trucks	S V V V V V V V V V V V V V V V V V V V	X								
12.00, 200 -72.20091		2/ 10/ 2020 2/ 3109	South Bethlehem Borough and Mahoning Twp. If the roadway is impr this could bring more opportunities for industry in these area due to	proved Contraction									
40.999232 -79.34286	374417 point	2/10/2020 273117 Gue	easier access south to the Pittsburgh area. Please do not bypass the N Bethlehem area, or it will completely kill our town. Intersection of rt.28 and Putneyville Road. Area needs improved visib	New X bility	x	x		X					
40.971117 -79 352780	374424 noint	2/10/2020 272110	and better access. This entire area is dangerous with fast moving traff many trucks, the traffic from the Distant Delights created connection difficulty pulling out onto rt 28	ffic, and X X		×	Y						As described previously
		2/10/2020 2/3110											This access road is in a poor location. Is essentially at the crest of a hill. Poor
40.973049 -79.350826	374425 point	2/10/2020 273110	The access to Dollar General.	x x x	x x	x		x x x	X			x	visibility. Is especially dangerous if pulling         out and going north.         This access road is in a poor location. Is
40 972040 70 250020	37///26 point	2/10/2020 270110	The access to Dollar Concrol										essentially at the crest of a hill. Poor visibility. Is especially dangerous if pulling out and going porth
020066.51- 107-007	יווטקוטצדד יד 3, אין				<u>^</u>	I I^			<b> ^</b>	1			

|   |  
   
   |   
  |  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | This access road is in a poor location.<br>essentially at the crest of a hill. Poor   | 15  |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
---
--
--
--
--
--
--
--
--
--
--
--
--
---|---|-----|---
--
--
--
--
--
---
--
--
--
--
--
---|--|--|---
--
--
--
---|--
---|---|---
---|---|---|---|---
--
---|---------------------------------------|---------------------------------------|---|--|---|---|---|--|---
---|---|---|---|---------------------------------------|---|---------------|---|---|---|--
--
--|---------------------------------------|---|---|--|---|--
--|---
---|---|---|--|--|--|---|---|---|--|--|--
---
--
---|---------------------------------------|--|--|---|--
---|--
--|---|---|---|--|---------------------------------------|--|--|--|
| 40.973049 -79.350826  | 374427 point   
   
   | 2/10/2020 273110  
  | The access to Dollar General. X  
   
   | x   
   
   
   
   
   
  |  
  | X   | x   | x   | x  
   
   
   
   
   
  |  
   
   
   
   
  |  | x  | x x   | x  
   
   
   
  |  |   | x   
   | visibility. Is especially dangerous if pu<br>out and going north.<br>Long time problem in this area with t  | ling<br>uck   | | | | | | | | | | |
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   |   
  |  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | rollovers and such. If rt. 28 continues<br>right through New Bethlehem this tu<br>needs changed. Not being an enginee   | to go<br>n<br>r or  |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.998962       -79.342768         40.973462       -79.351746   | 374428 point<br>374429 point   
   
   | 2/10/2020 273110<br>2/10/2020 273126  
  | Sharp turn area on rt. 28.       X         Opportunity for a Sheetz or other larger gas station       X  
   
   | x<br>x  
   
   
   
   
   
  |  
  | x x   | x x | X   | X X  
   
   
   
   
   
  |  
   
   
   
   
  |  | X  | x   | x  
   
   
   
  |  |   | | | | | | | | | | |
   | construction worker, I don't know ho  | w.  |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.917609 -79.364644  | 374430 point   
   
   | 2/10/2020 273126  
  | The visibility of pulling out of Calhoun School Road is terrible.  
   
   | x   
   
   
   
   
   
  |  
  |   | x   | I travel this road<br>X X School.   | to work at a local<br>X  
   
   
   
   
   
  |  
   
   
   
   
  |  | x x  | x   | x  
   
   
   
  |  |   | x   
   | to see when pulling into or out of Cal<br>School Road.  | noun  | | | | | | | | | | |
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.956703 -79.363108  | 374431 point   
   
   | 2/10/2020 273126  
  | Very windy road with high-speed travelersXBetween Rt 85 & I-80 traffic flow issues. More passing lanes and or  
   
   | X   
   
   
   
   
   
  |  
  | x   | x x | x   | x  
   
   
   
   
   
  |  
   
   
   
   
  |  | x  | x   |  
   
   
   
  |  |   | | | | | | | | | | |
   | section of the road. The road is very   | /indy.  |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.822073       -79.486718         40.981469       -79.345208         41.040227       -79.256972  | 374433 point<br>374435 point<br>374387 point   
   
   | 2/10/2020         2/3133           2/10/2020         273133           2/10/2020         273133           2/10/2020         273139   
  | Rte 85 to I-80 has heavy congestion. Needs to be a divided highway.  
   
   | X<br>X  
   
   
   
   
   
  | X<br>X   
  | X X   |     |   | X X X X X X X X X X X X X X X X X X X  
   
   
   
   
   
  |  
   
   
   
   
  |  | x<br>x<br>x  | X   | X X<br>X X   
   
   
   
  | X X X X  |   | | | | | | | | | | |
   |   |   |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   |   
  | This is a very sharp turn and often people go very fast around this turn,<br>especially semi's/big trucks.<br>I travel this road everyday and this is probably the scariest part of the  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | even though the speed limit is 55mp<br>people take this turn way too fast. th   | -<br>e turn   |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.906376 -79.370001  | 374440 point   
   
   | 2/10/2020 273143  
  | road.<br>there is a pull off stop for big trucks that are going to go down the hill. the<br>hill as we call it, is called hog back.  
   
   | X   
   
   
   
   
   
  |  
  |   |     |   | X  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | is sharp and just awful.<br>Big trucks often dont use this pull off<br>they do, they slow just and go throug  | or if<br>h the  |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   |   
  | a lot of the time big trucks do not use this lane or if they do, they do not<br>stop at the end of it. they take the pull off to slow down and just roll<br>through the stop sign, they do not stop & look to see if there is anyone   
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | stop sign.<br>i'm not sure if they can't see people of<br>and they just keep going or what. I o   | oming<br>ten see  |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.02752 70.261168  | 274441 point   
   
   | 2/10/2020 2721.42   
  | coming.<br>it's not really safe of them to do a "rolling stop" when it's big trucks going  
   
   | ,   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | ×   
   | people hitting their breaks and slowi<br>down because a big truck pulled out  | g<br>n front  | | | | | | | | | | |
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.32732 773.301108   |  
   
   |   
  | to get onto Calhoun school Rd, you make a right off of 28. right before this   
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | ~   
   | I fear if I have to make a right onto th  | s road  | | | | | | | | | | |
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   |   
  | this road.<br>many people pass on this passing lane and they come flying up there and  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | People are behind me.<br>People go way to fast passing people<br>then for someone to turn off and eve   | and<br>ryone  |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.923319 -79.360952  | 374442 point   
   
   | 2/10/2020 273143  
  | then someone wants to turn, everyone is hitting their breaks and it could case an accident. not a good road to turn right on right after a passing lane  
   
   | x   
   
   
   
   
   
  |  
  |   |     |   | x  
   
   
   
   
   
  |  
   
   
   
   
  |  |  | x x   | x x  
   
   
   
  |  |   | | | | | | | | | | |
   | behind them breaks, it's an accident<br>to happen.  | vaiting   |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   |   
  | passing lane is not big/long enough when someone is following a semi/big   
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | I often do not pass semi/big trucks on<br>passing lane just because there is usu<br>bunch of cars behind the big truck ar   | this<br>ally a<br>d often   |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.954576 -79.363468  | 374443 point   
   
   | 2/10/2020 273143  
  | truck and there are 10-20 cars behind them.  
   
   | X   
   
   
   
   
   
  |  
  |   |     |   | X  
   
   
   
   
   
  |  
   
   
   
   
  |  |  | X   | x  
   
   
   
  |  |   | | | | | | | | | | |
   | times people are cut off when passin<br>People drive way to fast on this road<br>People down the hill from spaces cor   | ers to  |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   |   
  |  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | come into kittanning are often drivin<br>to fast for this turn. it goes the same  | s way<br>or   |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.820857 70.47724  |  
   
   | 2/10/2020 2721.42   
  |  
   
   | <i>v</i>  
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | hill. the turn is wide and i hate this of<br>not as much as the goheenville one b   | e too,<br>ut it's   |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.999134 -79.343035  | 374444 point<br>374445 point   
   
   | 2/10/2020 273143<br>2/10/2020 273145  
  | 90 degree left turn with a fuel depot on it.   
   
   | X X   
   
   
   
   
   
  | X  
  |   |     |   |  
   
   
   
   
   
  | X  
   
   
   
   
  |  | X  |   |  
   
   
   
  |  |   | X   
   | it's hard to see if your pulling out of t   | nis   | No  
   |   |   |   | | | | | | | | | |
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   |   
  |  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | road. its hard to tell if anyone it comi<br>other way to make a left turn. Not a<br>place to turn left.   | ood   |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   |   
  |  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | if you pulling out, it's what I like a cal<br>"poke and hope" you poke out and h<br>nothing is coming.  | a<br>ope  |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   |   
  |  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | people who turn left, I often see the<br>the vehicle more because a car just c  | n gas<br>me up  |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   |   
  |  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | over the hill.  | ant of  |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.846587 -79.461235  | 374446 point   
   
   | 2/10/2020 273143  
  | bad place to turn left when traffic from the other side is coming up from the hill.  
   
   | x   
   
   
   
   
   
  |  
  |   |     |   | x  
   
   
   
   
   
  |  
   
   
   
   
  |  | x  | x   |  
   
   
   
  |  |   | | | | | | | | | | |
   | me here because it's hard to tell if<br>something is coming up over that hill<br>Sweet delights is an ice cream store   | /crest.   |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   |   
  |  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | people during the months of march t<br>end of October eat here. this is a bus   | o the<br>v place.   |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   |   
  |  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | for children to be there, for vehicles<br>in and out of the parking lot and put   | ulling<br>eyville   |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   |   
  |  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | road.<br>If you were going south and turning l<br>onto putneyville road, people drive v   | eft<br>ay to  |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   |   
  |  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | fast coming up past the Dollar genera<br>someone is turning left, it could caus<br>accident.  | that if<br>an   |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   |   
  |  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   | I feel that this is a bad place to turn a<br>into. and a bad place for an ice cream<br>with so much traffic that drive way to   | nd pull<br>shop<br>fast.  |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.971049 -79.352241  | 374447 point<br>374449 point   
   
   | 2/10/2020 273143  
  | bad place to turn into with traffic  
   
   | x   
   
   
   
   
   
  |  
  |   |     |   | x  
   
   
   
   
   
  | x  
   
   
   
   
  | Pedestrian safety  |  | x x   | x x  
   
   
   
  |  | x   | x   
   | Maybe a slower speed limit around t<br>cream shop.  | e ice   | | | | | | | | | | |
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.879963 -79.392253  | 374463 point   
   
   | 2/10/2020 272156  
  | Need a passing lane going up hill to Robinson fruit market.  
   
   | × ×   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  | X   | ×  
   
   
   
  |  |   | | | | | | | | | | |
   |   |   |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
|   |  
   
   | 2/10/2020 2/3130  
  | South bound traffic is speeding. Very little site distance when entering 28/66 from Deanville road. Have almost been hit many times when trying  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  | X  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | ×   
   | I have been almost hit many times tr  | ing to<br>ment  | South of Brookville in Coder<br>Hollow, Turn is narrow, High  
   |   |   |   | | | | | | | | | |
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.938323 -79.363578  | 374465 point 374465  
   
   | 2/10/2020 273156  
  | South bound traffic is speeding. Very little site distance when entering<br>28/66 from Deanville road. Have almost been hit many times when trying<br>to enter 28/66 X<br>South bound traffic is speeding. Very little site distance when entering<br>28/66 from Deanville road. Have almost been bit many times when trying   
   
   | X   
   
   
   
   
   
  | x  
  |   |     |   | x  
   
   
   
   
   
  | X  
   
   
   
   
  |  | x  | x x   |  
   
   
   
  | x  |   | x   
   | I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.<br>I have been almost hit many times tr   | ing to<br>ment<br>ing to  | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turp is parrow. High   
   |   |   |   | | | | | | | | | |
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.938323 -79.363578<br>40.938323 -79.363578  | 374465 point<br>374466 point   
   
   | 2/10/2020 273156<br>2/10/2020 273156<br>2/10/2020 273156  
  | South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         28/66 from Deanville road. Have almost been hit many times when trying         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66  
   
   | x<br>x<br>x   
   
   
   
   
   
  | x<br>x   
  |   |     | Travel to and from  | X<br>X<br>m Brookville on  
   
   
   
   
   
  |  
   
   
   
   
  |  | x  | x x<br>x x  |  
   
   
   
  | x<br>x   |   | x<br>x  
   | I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.<br>I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.  | ing to<br>ment<br>ing to<br>ment  | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.  
   |   |   |   | | | | | | | | | |
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.938323 -79.363578<br>40.938323 -79.363578<br>41.134006 -79.152286  | 374465 point<br>374466 point<br>374568 point   
   
   | 2/10/2020 273156<br>2/10/2020 273156<br>2/10/2020 273156<br>2/10/2020 273164  
  | South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X  
   
   | x<br>x  
   
   
   
   
   
  | x<br>x   
  |   |     | Travel to and from<br>my way to Pittsburrespond there as<br>X local fire departm  | X X A A A A A A A A A A A A A A A A A A  
   
   
   
   
   
  | X  
   
   
   
   
  |  | x<br>x   | x x<br>x x<br>x x   |  
   
   
   
  | x  |   | x<br>x  
   | I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.<br>I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.  | ing to<br>ment<br>ing to<br>ment  | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.  
   |   |   |   | | | | | | | | | |
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.127248       -79.163718  | 374465 point<br>374466 point<br>374568 point<br>374569 point<br>374571 point   
   
   | 2/10/2020 273156<br>2/10/2020 273156<br>2/10/2020 273156<br>2/10/2020 273164<br>2/10/2020 273163<br>2/10/2020 273163  
  | South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X   
   
   | x<br>x<br>x   
   
   
   
   
   
  | x<br>x   
  |   |     | Travel to and from<br>my way to Pittsbur<br>respond there as<br>X local fire departm  | X X X X X X X X X X X X X X X X X X X  
   
   
   
   
   
  | x<br>X<br>X  
   
   
   
   
  |  | x<br>x<br>x  | x x<br>x x<br>x x<br>x x  |  
   
   
   
  | x x x  |   | x<br>x<br>x<br>x<br>x   
   | K I have been almost hit many times trenter 28 66. We also have farm equipentering the road also. I have been almost hit many times trenter 28 66. We also have farm equipentering the road also. intense curve with many accidents, pvisibility intersections  | ing to<br>ment<br>ing to<br>ment<br>oor   | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.  
   |   |   |   | | | | | | | | | |
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011  | 374465 point         374465 point         374466 point         374568 point         374569 point         374571 point         374574 point         374576 point  
   
   | 2/10/2020 273156<br>2/10/2020 273156<br>2/10/2020 273156<br>2/10/2020 273164<br>2/10/2020 273163<br>2/10/2020 273163<br>2/10/2020 273163<br>2/10/2020 273163<br>2/10/2020 273163  
  | South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve       X         poor sight on major intersection       X         bad curve       X  
   
   | x<br>x<br>x<br>x  
   
   
   
   
   
  | x<br>x<br>   
  |   |     | Image: Second state of the second s               | X X X X X X X X X X X X X X X X X X X  
   
   
   
   
  | x<br>x<br>x<br>x<br>x  
   
   
   
   
   
  |  | x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x   | x x<br>x x<br>x x<br>x x<br>x x<br>x x<br>x x<br>x x<br>x x<br>x x  |  
   
   
   
  | x  |   | X X X X X X X X X X X X X X X X X X X   | K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, pvisibility intersections         slow moving trucks going up hill and   
   | ing to<br>ment<br>ing to<br>ment<br>oor   | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.  |   |   
   |   |   
   |                                       |                                       |   |  |   |   |   |  |   
   |   |   |   |   |                                       |   |               |   |   |   |  |  
   
   |                                       |   |   |  |   |  | | | |
  |   |   |   |   |  
   |  |  |   |   |   |  |  |  |   |  
  |                                       |  |  |  
  |  |   |                         
  |  |   |   |   |  |                                       |  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911   | 374465 point         374465 point         374466 point         374568 point         374569 point         374571 point         374574 point         374575 point         374576 point         374577 point  
   
   | 2/10/2020 273156<br>2/10/2020 273156<br>2/10/2020 273156<br>2/10/2020 273164<br>2/10/2020 273163<br>2/10/2020 273163<br>2/10/2020 273163<br>2/10/2020 273163<br>2/10/2020 273163  
  | South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve         X         poor sight on major intersection         X         slow moving trucks going up hill         X         Local road that is at crest of hill. Very hard to pull across traffic here with  
   
   | x x x x x x x x x x x x x x x x x x x   
   
   
   
   
   
  | x<br>x<br>x<br>  
  |   |     | Image: state of the state o | X X X X X X X X X X X X X X X X X X X  
   
   
   
   
  | x<br>x<br>x<br>x   
   
   
   
   
   
  | Pedestrian safety  | x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x  | x x<br>x x<br>x x<br>x x<br>x x<br>x x<br>x x<br>x x<br>x x<br>x x  | X<br>X<br>X<br>X<br>X<br>X<br>X<br>X<br>X<br>X   
   
   
   
  | x  |   | x<br>x<br>x<br>x<br>x<br>x  | K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes  
   | ing to<br>ment<br>ing to<br>ment<br>oor   | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.  |   |   
   |   |   
   |                                       |                                       |   |  |   |   |   |  |   
   |   |   |   |   |                                       |   |               |   |   |   |  |  
   
   |                                       |   |   |  |   |  | | | |
  |   |   |   |   |  
   |  |  |   |   |   |  |  |  |   |  
  |                                       |  |  |  
  |  |   |   
  |  |   |   |   |  |                                       |  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.371568   | 374465 point         374465 point         374466 point         374568 point         374569 point         374571 point         374572 point         374574 point         374575 point         374576 point         374577 point         374579 point         374579 point         374580 point  
   
   | 2/10/2020 273156<br>2/10/2020 273156<br>2/10/2020 273156<br>2/10/2020 273164<br>2/10/2020 273163<br>2/10/2020 273163<br>2/10/2020 273163<br>2/10/2020 273163<br>2/10/2020 273163<br>2/10/2020 273163<br>2/10/2020 273163<br>2/11/2020 273175<br>2/11/2020 273175  
  | South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X                                  
   
   | x x x x x x x x x x x x x x x x x x x   
   
   
   
   
   
  | x x x x x x x x x x x x x x x x x x x  
  |   |     | Image: state of the state                | X     X       x     X       x     X       x     X       x     X       x     X       x     X       X     X       X     X       X     X       X     X       X     X       X     X       X     X       X     X       X     X       X     X       X     X       X     X       X     X       X     X   
   
   
   
   
   | x<br>x<br>x<br>x<br>x   
   
   
   
   
   
   | Pedestrian safety  | x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x  | x       x           | X   
   
   
   
   | X  |   | x<br>x<br>x<br>x<br>x<br>x  | K       I have been almost hit many times treenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times treenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, pvisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.   
  | ing to<br>ment<br>ing to<br>ment<br>oor<br>oor  | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.  |   |  
  |   |  
  |                                       |                                       |   |  |   |   |   |  |  
  |   |   |   |   |                                       |   |               |   |   |   |  |   
   
  |                                       |   |   |  |   |  | | | |
   |   |   |   |   |   
  |  |  |   |   |   |  |  |  |   |   
   |                                       |  |  |   
   |  |   |                                  
   |  |   |   |   |  |                                       |  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.371568         40.99912       -79.34296         41.136277       -79.14657  | 374465 point         374465 point         374466 point         374568 point         374569 point         374571 point         374572 point         374574 point         374575 point         374576 point         374577 point         374578 point         374579 point         374580 point         374580 point         374599 point  
   
   | 2/10/2020       273130         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273196   
  | South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve         X         poor sight on major intersection         X         slow moving trucks going up hill         X         Local road that is at crest of hill. Very hard to pull across traffic here with         limited view and time.         X         The sharp curve coming into Goheenville from Distant.  
   
   | x x x x x x x x x x x x x x x x x x x   
   
   
   
   
   
  | x x x x x x x x x x x x x x x x x x x  
  |   |     | Image: Second               | X X X X X X X X X X X X X X X X X X X  
   
   
   
   
  | X<br>X<br>X<br>X<br>X<br>X<br>X<br>X<br>X<br>X<br>X<br>X<br>X<br>X<br>X<br>X<br>X<br>X<br>X  
   
   
   
   
   
  | Pedestrian safety  | x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x  | x       x           | X  
   
   
   
  | X  | Image: select | X X X X X X X X X X X X X X X X X X X   | K       I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.         I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.         intense curve with many accidents, p<br>visibility intersections         slow moving trucks going up hill and<br>accessing progress st. No pedestrian<br>lanes         K         Limited sight distance.  
   | ing to<br>ment<br>ing to<br>ment<br>oor<br>oor<br>hen<br>r bike   | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.  |   |   |   |   
   
   |                                       |                                       |   |  |   |   |   |  |   |   |   |   |   
   |                                       |   |               |   |   |   |  |  
   
   |                                       |   |   |  |   |  | | | |
  |   |   |   |   |  |  |  |   |   |   
   |  |  |  |   |  
  |                                       |  |  |   |  |   
   |  |  |   
   |   |   |  |                                       |  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.371568         40.99912       -79.34296         41.136277       -79.14657   | 374465 point         374465 point         374466 point         374568 point         374569 point         374571 point         374572 point         374574 point         374575 point         374576 point         374577 point         374578 point         374579 point         374580 point         374580 point   
   
  | 2/10/2020       273156         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273196  
   | South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         Y         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve         X         poor sight on major intersection         X         slow moving trucks going up hill         X         slow moving trucks going up hill         X         Imited view and time.         X         The sharp curve coming into Goheenville from Distant.   
   
  | x x x x x x x x x x x x x x x x x x x  
   
   
   
   
   
   | x x x x x x x x x x x x x x x x x x x   
   |   |     | Image: Second | X     X       m Brookville on<br>burgh. Also<br>s a member of a<br>ment     X       X     X   
   
   
   
   
   | X   
   
   
   
   
   
   | Pedestrian safety  | x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x  | x       x         x | X   
   
   
   
   | X  |   | X X X X X X X X X X X X X X X X X X X   | K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         k         Limited sight distance.   
  | ing to<br>ment<br>ing to<br>ment<br>por<br>por<br>hen<br>r bike   | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.  |   |  
  |   |  
  |                                       |                                       |   |  |   |   |   |  |  
  |   |   |   |   |                                       |   |               |   |   |   |  |   
   
  |                                       |   |   |  |   |  | | | |
   |   |   |   |   |   
  |  |  |   |   |   |  |  |  |   |   
   |                                       |  |  |   
   |  |   |  |   
  |   |   |   |  |                                       |  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.331177         40.907007       -79.371568         40.99912       -79.14657   | 374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374572       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374580       point         374580       point         374589       point         374589       point  
   
   | 2/10/2020       273136         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273196         2/11/2020       273196         2/11/2020       273196  
  | South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve         X         poor sight on major intersection         X         slow moving trucks going up hill         X         Local road that is at crest of hill. Very hard to pull across traffic here with         limited view and time.         X         The sharp curve coming into Goheenville from Distant.         Needs some kind lit signs to
get drives attention to warn how sharp this corner is.   
  | x x x x x x x x x x x x x x x x x x x  
   
   
   
   
   
   | X X X X X X X X X X X X X X X X X X X   
   |   |     | Image: Second               | x x m Brookville on burgh. Also s a member of a ment X X X X X X X X X X X X X X X X X X X  
   
   
   
   
   | X X X X X X X X X X X X X X X X X X X   
   
   
   
   
   
   | Pedestrian safety  | x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x  | x       x         x | X   
   
   
   
   | x  |   | X X X X X X X X X X X X X X X X X X X   | K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         k         lanes  
   | ing to<br>ment<br>ing to<br>ment<br>oor<br>oor<br>hen<br>r bike   | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.  |   |   
   |   |   
   |                                       |                                       |   |  |   |   |   |  |   
   |   |   |   |   |                                       |   |               |   |   |   |  |  
   
   |                                       |   |   |  |   |  | | | |
  |   |   |   |   |  
   |  |  |   |   |   |  |  |  |   |  
  |                                       |  |  |  
  |  |   |  |  
   |   |   |   |  |                                       |  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         40.849189       -79.096911         40.998723       -79.331177         40.907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657  | 374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374579       point         374579       point         374579       point         374580       point         374580       point         374589       point         374589       point   
   
   | 2/10/2020       273136         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273187         2/11/2020       273189         2/11/2020       273196         2/11/2020       273196         2/11/2020       273196   
  | South bound traffic is speeding. Very little site distance when entering 28/66 from Deanville road. Have almost been hit many times when trying to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering 28/66 from Deanville road. Have almost been hit many times when trying to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering 28/66 from Deanville road. Have almost been hit many times when trying to enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         The sharp curve coming into Goheenville from Distant.       X    
    From mainly New Bethlehem to Kittanning. However the real problem is Brookville to Kittanning. The main problem is trucks. I drive this road at the problem is trucks 10 are a month from Brookville to Kittanning. The main problem is trucks. I drive this road  
   | x x x x x x x x x x x x x x x x x x x   
   
   
   
   
   
  | x x x x x x x x x x x x x x x x x x x  
  |   |     | Image: Second | x     x       x     x       y     x       y     x       y     x       y     x       x <td>x</td> <td>Pedestrian safety</td> <td>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x</td> <td>x       x         x</td> <td>X      </td> <td>x</td> <td></td> <td>X X X X X X X X X X X X X X X X X X X</td> <td>K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         lanes         K         Limited sight distance.</td> <td>ing to<br/>ment<br/>ing to<br/>ment<br/>oor<br/>oor<br/>hen<br/>r bike</td> <td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.</td>  
   
   
   
   
  | x  
   
   
   
   
   
  | Pedestrian safety  | x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x  | x       x         x | X  
   
   
   
  | x  |   | X X X X X X X X X X X X X X X X X X X   | K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         lanes         K         Limited sight distance.  
   | ing to<br>ment<br>ing to<br>ment<br>oor<br>oor<br>hen<br>r bike   | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.  |   |   
   |   |   
   |                                       |                                       |   |  |   |   |   |  |   
   |   |   |   |   |                                       |   |               |   |   |   |  |  
   
   |                                       |   |   |  |   |  | | | |
  |   |   |   |   |  
   |  |  |   |   |   |  |  |  |   |  
  |                                       |  |  |  
  |  |   |   
  |  |   |   |   |  |                                       |  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         40.849189       -79.096911         40.998723       -79.331177         40.907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.34296  | 374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374574       point         374575       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374580       point         374580       point         374580       point         374589       point         374589       point  
   
   | 2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273187         2/11/2020       273187         2/11/2020       273189         2/11/2020       273196         2/11/2020       273196  
  | South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve         poor sight on major intersection         bad curve         x         slow moving trucks going up hill         Local road that is at crest of hill. Very hard to pull across traffic here with         limited view and time.         X         The sharp curve coming into Goheenville from Distant.         Reeds some kind lit signs to get drives attention to warn how sharp this corner is.         From mainly New Bethlehem to Kittanning. However the real problem is Brookville to Kittanning. The main problem is trucks. I drive
this road atleast 20-30 times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and safe when you never encounter a truck from kittanning to 180. If you do you face time delays for work  
   | x x x x x x x x x x x x x x x x x x x   
   
   
   
   
   
  | x x x x x x x x x x x x x x x x x x x  
  |   |     | Image: Second | x     Image: second secon  
   
   
   
   
   | x   
   
   
   
   
   | Pedestrian safety   
  | x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x  | x       x         x | ×          ×          ×       ×         × </td <td>x      </td> <td></td> <td>x x x x x x x x x x x x x x x x x x x</td> <td>K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         lanes         K         Limited sight distance.         I         I         The freight trucks. They should just h         be forced to use 79 out of the city to</td> <td>ing to<br/>ment<br/>ing to<br/>ment<br/>over to<br/>seve to<br/>80</td> <td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.</td>  
   
   
   
   | x  |   | x x x x x x x x x x x x x x x x x x x   | K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         lanes         K         Limited sight distance.         I         I         The freight trucks. They should just h         be forced to use 79 out of the city to  
  | ing to<br>ment<br>ing to<br>ment<br>over to<br>seve to<br>80  | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.  |   |   |   |  
   
  |                                       |                                       |   |  |   |   |   |  |   |   |  
  |   |   |                                       |   |               |   |   |   |  |   
   
  |                                       |   |   |  |   |  | | | |
   |   |   |   |   |  |  |  |   |   |  
  |  |  |  |   |   
   |                                       |  |  |   |  |  
  |  |   
  |   |   |   |  |                                       |  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.331177         40.907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.999114       -79.342962         40.999114       -79.342962         40.9981824       -79.343995         41.163374       -79.097537   | 374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374579       point         374579       point         374580       point         374580       point         374580       point         374590       point         374589       point         374589       point         374589       point         374589       point  
   
   | 2/10/2020       273130         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273196         2/11/2020       273196         2/11/2020       273189         2/11/2020       273204   
  | South bound traffic is speeding. Very little site distance when entering       28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering       28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         From mainly New Bethlehem to Kittanning. However the real problem is Brookville to Kittanning. The main problem is trucks. I drive this road atleast 20-30 times a month from Brookville to Kittanning and then some. I have
noticed that traffic flows fine and safe when you never encounter a truck from kittanning to 180. If you do you face time delays for work meetings or healthcare. Or safety, most of these trucks are either going way to fast causing potential danger, or way to slow also causing danger.   
   | X         X <td< td=""><td>x x x x x x x x x x x x x x x x x x x</td><td>.       .         .</td><td></td><td>Image: Second second</td><td>x    </td><td>x</td><td>Pedestrian safety</td><td>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x</td><td>x       x         x</td><td>×       ×         ×       ×</td><td>x      </td><td></td><td>X X X X X X X X X X X X X X X X X X X</td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prisibility intersections         intense curve with many accidents, prisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Image: State of the freight trucks. They should just her forced to use 79 out of the city to and leave route 28 to local deliveries regular car traffic.</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>opor<br/>oor<br/>hen<br/>r bike<br/>hen<br/>r bike</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.</td></td<>  
   
   
   
   
   | x x x x x x x x x x x x x x x x x x x   
   
   | .       .         .   |     | Image: Second | x   
   
   
   
   
   | x   
   
   
   
   
   | Pedestrian safety   
  | x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x  | x       x         x | ×       ×           
   
   
   
   | x  |   | X X X X X X X X X X X X X X X X X X X   | K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prisibility intersections         intense curve with many accidents, prisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Image: State of the freight trucks. They should just her forced to use 79 out of the city to and leave route 28 to local deliveries regular car traffic.   
  | ing to<br>ment<br>ing to<br>ment<br>opor<br>oor<br>hen<br>r bike<br>hen<br>r bike   | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.  |   |   |   |  
   
  |                                       |                                       |   |  |   |   |   |  |   |   |  
                                      |   |   |                                       |   |               |   |   |   |  |   
   
  |                                       |   |   |  |   |  | | | |
   |   |   |   |   |  |  |  |   |   |  
  |  |  |  |   |   
   |                                       |  |  |   |  |  
  |  |   
  |   |   |   |  |                                       |  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.331177         40.907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         41.136277       -79.34296         41.136277       -79.34296         41.136277       -79.34296         41.136277       -79.342962         40.999114       -79.342962         40.999114       -79.342962         40.9981824       -79.343995         41.163374       -79.097537  | 374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374572       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374580       point         374590       point         374390       point <td>2/10/2020       273130         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273196         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204</td> <td>South bound traffic is speeding. Very little site distance when entering<br/>28/66 from Deanville road. Have almost been hit many times when trying<br/>to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering<br/>28/66 from Deanville road. Have almost been hit many times when trying<br/>to enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with<br/>limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         From mainly New Bethlehem to Kittanning. However the real problem is<br/>Brookville to Kittanning. The main problem is trucks. I drive this road<br/>atleast 20-30 times a month from Brookville to Kittanning and then some.<br/>I have noticed that traffic flows fine and safe when you never encounter a<br/>truck from kittanning to I80. If you do you face time delays for work<br/>meetings or healthcare. Or safety, most of these trucks are either going<br/>way to fast causing potential danger, or way to slow also causing danger.</td> <td>x         <td< td=""><td>x x x x x x x x x x x x x x x x x x x</td><td>.       .         .</td><td></td><td>Image: Second second</td><td>x m Brookville on burgh. Also s a member of a ment X X X X X X X X X X X X X X X X X X X</td><td>x</td><td>Pedestrian safety</td><td>Image: constraint of the sector of the sec</td><td>x       x         x</td><td>X       X         X</td><td>x      </td><td>Image: second second</td><td>X X X X X X X X X X X X X X X X X X X</td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prisibility intersections         intense curve with many accidents, prisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Image: State of the freight trucks. They should just here forced to use 79 out of the city to and leave route 28 to local deliveries regular car traffic.</td><td>ave to 80 and</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.</td></td<></td>  
   | 2/10/2020       273130         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273196         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204   
   
  | South bound traffic is speeding. Very little site distance when entering<br>28/66 from Deanville road. Have almost been hit many times when trying<br>to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering<br>28/66 from Deanville road. Have almost been hit many times when trying<br>to enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with<br>limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         From mainly New Bethlehem to Kittanning. However the real problem is<br>Brookville to Kittanning. The main problem is trucks. I drive this road<br>atleast 20-30 times a month from Brookville to Kittanning and then some.<br>I have noticed that traffic flows fine and safe when you never encounter a<br>truck from kittanning to I80. If you do you face time delays for work<br>meetings or healthcare. Or safety, most of these trucks are either going<br>way to fast causing potential danger, or way to slow also causing danger.  
   | x         x <td< td=""><td>x x x x x x x x x x x x x x x x x x x</td><td>.       .         .</td><td></td><td>Image: Second second</td><td>x m Brookville on burgh. Also s a member of a ment X X X X X X X X X X X X X X X X X X X</td><td>x</td><td>Pedestrian safety</td><td>Image: constraint of the sector of the sec</td><td>x       x         x</td><td>X       X         X       X         X       X         X       X        
X       X         X</td><td>x      </td><td>Image: second second</td><td>X X X X X X X X X X X X X X X X X X X</td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prisibility intersections         intense curve with many accidents, prisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Image: State of the freight trucks. They should just here forced to use 79 out of the city to and leave route 28 to local deliveries regular car traffic.</td><td>ave to 80 and</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.</td></td<>  
   
   
   
  | x x x x x x x x x x x x x x x x x x x  
   
  | .       .         .   |     | Image: Second               | x m Brookville on burgh. Also s a member of a ment X X X X X X X X X X X X X X X X X X X   
   
   
   
   
  | x  
   
   
   
   
  | Pedestrian safety  
   | Image: constraint of the sector of the sec | x       x         x | X       X         X  
   
   
  | x  
   | Image: second | X X X X X X X X X X X X X X X X X X X   | K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prisibility intersections         intense curve with many accidents, prisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Image: State of the freight trucks. They should just here forced to use 79 out of the city to and leave route 28 to local deliveries regular car traffic.   | ave to 80 and   
   | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.  |   |   |   | | | | | | | |
   |                                       |                                       |   |  |  
  |   |   |  |   |   |   |   |   |                                       |   |               |   
   |   |   |  |  
   |                                       |   |   |  |   |  
   |  |   |  
  |   |   |  |  |  |   |   |   |  |  |  |  
  |  
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  
   |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         40.849189       -79.096911         40.998723       -79.331177         40.9997007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.99914       -79.342962         40.9981824       -79.343995         41.163374       -79.097537         41.146843       -79.117534  | 374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374579       point         374579       point         374580       point         374580       point         374591       point   
   
   | 2/10/2020       273130         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273163         2/11/2020       273175         2/11/2020       273175         2/11/2020       273187         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204   
  | South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         28/66 from Deanville road. Have almost been hit many times when trying         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve         x         bad curve         x         slow moving trucks going up hill         X         Local road that is at crest of hill. Very hard to pull across traffic here with         limited view and time.         X         The sharp curve coming into Goheenville from Distant.         x   
   
   | X         X <td< td=""><td>x x x x x x x x x x x x x x x x x x x</td><td></td><td></td><td>Image: Second second</td><td>X     X       Important Sector     Important Sector       Important Sector     Important Sector<td>×         <td< td=""><td>Pedestrian safety</td><td>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x</td><td>x       x         x</td><td>x       x         x       x      <tr td=""> <td>x      </td><td>Image: second second</td><td>X X X X X X X X X X X X X X X X X X X</td><td>K       I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.         I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.         intense curve with many accidents, p<br/>visibility intersections         slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes         K         Limited sight distance.         Interse trucks. They should just h<br/>be forced to use 79 out of the city to<br/>and leave route 28 to local deliveries<br/>regular car traffic.         Again, there is a high volume of moto<br/>vehicle accidents in this stretch.</td><td>ing to   ing to   ment   ing to   ment   oor   oor   hen   r bike</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.</td></tr><tr><td>40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.31177         40.907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.99914       -79.342962         40.9981824       -79.343995         41.163374       -79.097537         41.146843       -79.117534</td><td>374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374579       point         374579       point         374580       point         374590       point         374590       point         374590       point         374590       point         374591       point</td><td>2/10/2020       273156         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273196         2/11/2020       273196         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020 
     273210         2/11/2020       273210         2/11/2020       273210</td><td>South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         x         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve         x         bad curve         x         slow moving trucks going up hill         x         Local road that is at crest of hill. Very hard to pull across traffic here with         limited view and time.         X         The sharp curve coming into Goheenville from Distant.         X         Needs some kind lit signs to get drives attention to warn how sharp this corner is.         From mainly New Bethlehem to Kittanning. However the real problem is Brookville to Xittanning. The main problem is trucks. I drive this road atleast 20-30 times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and safe when you never encounter a truck from kitanning. The main problem is trucks are either going way to fast causing potential danger, or way to slow also causing danger.         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X    <td>x x x x x x x x x x x x x x x x x x x</td><td>x x x x x x x x x x x x x x x x x x x</td><td>.       .       .         .       .       .     &lt;</td><td></td><td>Image: Second second</td><td>x     x       x     x       m Brookville on<br/>burgh. Also<br/>s a member of a<br/>ment     x       x     x</td><td>x</td><td>Pedestrian safety         Image: Pedestrian safety</td><td>Image: second second</td><td>x       x         x</td><td>X       X         I       I         I       X         I       X         I       X         X</td><td>x      </td><td>Image: second second</td><td>X X X X X X X X X X X X X X X X X X X</td><td>K       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         intense curve with many accidents, p       visibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes       Intense curve with many accidents, p         K       It mitted sight distance.       Intense curve with many accidents, p         K       Intense curve with many accidents, p       Intense curve with many accidents, p         Visibility intersections       Intense curve second curves going up hill and accessing progress st. No pedestrian lanes         K       Intense curve second curves, power second curvesecond curvesecond curvesecond curves, power second cur</td><td>ave to 80 and</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Image: South of Brookville in Pittsburgh the         Speed limit signs need to be         adjusted to more reasonable         Speeds. Some could be raised a         bit and other through this certain         towns could be lowered.         Image: South of From I80 to         Kittanning.         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South in the speed limits. Some</td></td></tr><tr><td>40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.163718         41.040026       -79.257263         41.145777       -79.114011         40.849189       -79.096911         40.849189       -79.371568         40.998723       -79.31177         40.9907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         41.136277       -79.14657         41.136277       -79.14657         41.136277       -79.342962         40.999114       -79.342962         40.9981824       -79.097537         41.16843       -79.117534         41.146843       -79.117534</td><td>374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374572       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374589       point         374590       point         374591       point         374590       point         374591       point         374591       point         374592       point</td><td>2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210</td><td>South bound traffic is speeding. Very little site distance when entering       28/66 from Deanville road. Have almost been hit many times when trying         X       South bound traffic is speeding. Very little site distance when entering       28/66 from Deanville road. Have almost been hit many times when trying         X       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         Needs some kind lit signs to get drives attention to warn how sharp this corner is.       From mainly New Bethlehem to Kittanning. However the real problem is Brookville to Kittanning. The main problem is trucks. I drive this road atleast 20-30 times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and safe when you never encounter a truck from kittanning to 180. If you do you face time delays for work meetings or healthcare. Or safety, most of these trucks are either going way to fast causing potential danger, or way to slow also causing danger.         est       Route 28 between the
areas of Airport Road Ext. and Cemetery Road.       X         v       V     <td>x x x x x x x x x x x x x x x x x x x</td><td>X         X</td><td>.       .       .         .       .       .     &lt;</td><td></td><td>Image: Second second</td><td>x     x       mm Brookville on burgh. Also is a member of a ment     x       X     x</td><td>X         <td< td=""><td>Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety</td><td>Image: Constraint of the sector of the se</td><td>x       x         x       x</td><td>X       X         I       I         I       X         I       X         I       X         X</td><td>X       Image: Constraint of the sector of the</td><td></td><td></td><td>K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         lanes         K         Limited sight distance.         Limited sight distance.         Visibility course 28 to local deliveries         regular car traffic.         Again, there is a high volume of moto         vehicle accidents in this stretch.         there is no signage directing people f         the Interstate to Pittsburgh and othe         south</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>opor<br/>poor<br/>hen<br/>r bike<br/></td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Iman</td></td<></td></td></tr><tr><td>40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.127248       -79.152286         41.1040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.371568         40.99912       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.999114       -79.342962         40.9981824       -79.343995         41.163374       -79.097537         41.146843       -79.117534         41.146843       -79.117534</td><td>374465       point         374466       point         374466       point         374568       point         374570       point         374571       point         374572       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374580       point         374591       point         374592       point         374593       point         374594       point         374595       point         374590       point         374591       point         374592       point         374593       point</td><td>2/10/2020       273156         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204</td></tr></td></td<><td>South bound traffic is speeding. Very little site distance when entering<br/>22/66 from Deanville road. Have almost been hit many times when trying<br/>to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering<br/>28/66 from Deanville road. Have almost been hit many times when trying<br/>to enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with<br/>limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         From mainly New Bethlehem to Kittanning. However the real problem is<br/>Brookville to Kittanning. The main problem is trucks. I drive this road<br/>atleast 20-30 times a month from Brookville to Kittanning and then some.<br/>I have noticed that traffic flows fine and safe when you never encounter a<br/>truck from kittanning to 180. If you do you face time delays for work<br/>meetings or healthcare. Or safety, most of these trucks are either going<br/>way to fast causing potential danger, or way to slow also causing danger.       X         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X         No signage on Interstate 80 that directs people to Pittsburgh or<br/>Punxsutawney       X</td><td>X         X      
  X         X         X         X         X         X         X         X         X         X         X         X         X         X         X         X         X         X         X         <td< td=""><td>x x x x x x x x x x x x x x x x x x x</td><td></td><td></td><td>Image: Second second</td><td>x     x       mBrookville on<br/>burgh. Also<br/>s a member of a<br/>ment     x       X     x</td><td>x         <td< td=""><td><ul> <li>Pedestrian safety</li> <li>Pedestrian safety</li> <li>Pedestrian safety</li> <li>Pedestrian safety</li> </ul></td><td>Image: constraint of the sector of the sec</td><td>x <math>x</math> <math>x</math></td><td>X      </td><td>x      </td><td></td><td>x x x x x x x x x x x x x x x x x x x</td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, pvisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Limited sight distance.         Limited sight distance.         Again, there is a high volume of the city to and leave route 28 to local deliveries regular car traffic.         Again, there is a high volume of motor vehicle accidents in this stretch.         there is no signage directing people for the linterstate to Pittsburgh and othe south         There is limited sight distance for trapulling out of Sloan Hill Road onto Rome pulling out</td><td>ing to ment ing to ment ing to ment ing to ment ing to ment in the ment in the</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Image: South of Brookville in Coder         Image: South of Brookville in Coder         Image: Source of the Source         Image: Source of the Source</td></td<></td></td<></td></td></td></td<> | x x x x x x x x x x x x x x x x x x x   
   |   |     | Image: Second | X     X       Important Sector     Important Sector       Important Sector     Important Sector <td>×         <td< td=""><td>Pedestrian safety</td><td>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x</td><td>x       x         x</td><td>x       x         x       x      <tr td=""> <td>x      </td><td>Image: second second</td><td>X X X X X X X X X X X X X X X X X X X</td><td>K       I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.         I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.     
   intense curve with many accidents, p<br/>visibility intersections         slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes         K         Limited sight distance.         Interse trucks. They should just h<br/>be forced to use 79 out of the city to<br/>and leave route 28 to local deliveries<br/>regular car traffic.         Again, there is a high volume of moto<br/>vehicle accidents in this stretch.</td><td>ing to   ing to   ment   ing to   ment   oor   oor   hen   r bike</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.</td></tr><tr><td>40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.31177         40.907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.99914       -79.342962         40.9981824       -79.343995         41.163374       -79.097537         41.146843       -79.117534</td><td>374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374579       point         374579       point         374580       point         374590       point         374590       point         374590       point         374590       point         374591       point</td><td>2/10/2020       273156         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273196         2/11/2020       273196         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210</td><td>South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         x         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve         x         bad curve         x         slow moving trucks going up hill         x         Local road that is at crest of hill. Very hard to pull across traffic here with         limited view and time.         X         The sharp curve coming into Goheenville from Distant.         X         Needs some kind lit signs to get drives attention to warn how sharp this corner is.         From mainly New Bethlehem to Kittanning. However the real problem is Brookville to Xittanning. The main problem is trucks. I drive this road atleast 20-30 times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and safe when you never encounter a truck from kitanning. The main problem is trucks are either going way to fast causing potential danger, or way to slow also causing danger.         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X    <td>x x x x x x x x x x x x x x x x x x x</td><td>x x x x x x x x x x x x x x x x x x x</td><td>.       .       .         .       .       .     &lt;</td><td></td><td>Image: Second second</td><td>x     x       x     x       m Brookville on<br/>burgh. Also<br/>s a member of a<br/>ment     x       x     x</td><td>x</td><td>Pedestrian safety         Image: Pedestrian safety</td><td>Image: second second</td><td>x       x         x</td><td>X       X         I       I         I       X         I       X         I       X         X</td><td>x      </td><td>Image: second second</td><td>X X X X X X X X X X X X X X X X X X X</td><td>K       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         intense curve with many accidents, p       visibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes       Intense curve with many accidents, p         K       It mitted sight distance.       Intense curve with many accidents, p         K       Intense curve with many accidents, p       Intense curve with many accidents, p         Visibility intersections       Intense curve second curves going up hill and accessing progress st. No pedestrian lanes         K       Intense curve second curves, power second curvesecond curvesecond curvesecond curves, power second cur</td><td>ave to 80 and</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Image: South of Brookville in Pittsburgh the         Speed limit signs need to be         adjusted to more reasonable         Speeds. Some could be raised a         bit and other through this certain         towns could be lowered.         Image: South of From I80 to         Kittanning.         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South in the speed limits. Some</td></td></tr><tr><td>40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.163718         41.040026       -79.257263         41.145777       -79.114011         40.849189       -79.096911         40.849189       -79.371568         40.998723       -79.31177         40.9907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         41.136277       -79.14657         41.136277       -79.14657         41.136277       -79.342962         40.999114       -79.342962         40.9981824       -79.097537         41.16843       -79.117534         41.146843       -79.117534</td><td>374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374572       point         374574
      point         374575       point         374576       point         374577       point         374578       point         374579       point         374589       point         374590       point         374591       point         374590       point         374591       point         374591       point         374592       point</td><td>2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210</td><td>South bound traffic is speeding. Very little site distance when entering       28/66 from Deanville road. Have almost been hit many times when trying         X       South bound traffic is speeding. Very little site distance when entering       28/66 from Deanville road. Have almost been hit many times when trying         X       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         Needs some kind lit signs to get drives attention to warn how sharp this corner is.       From mainly New Bethlehem to Kittanning. However the real problem is Brookville to Kittanning. The main problem is trucks. I drive this road atleast 20-30 times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and safe when you never encounter a truck from kittanning to 180. If you do you face time delays for work meetings or healthcare. Or safety, most of these trucks are either going way to fast causing potential danger, or way to slow also causing danger.         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X         v       V     <td>x x x x x x x x x x x x x x x x x x x</td><td>X         X</td><td>.       .       .         .       .       .     &lt;</td><td></td><td>Image: Second second</td><td>x     x       mm Brookville on burgh. Also is a member of a ment     x       X     x</td><td>X         <td< td=""><td>Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety</td><td>Image: Constraint of the sector of the se</td><td>x       x         x       x</td><td>X       X         I       I         I       X         I       X         I       X         X</td><td>X       Image: Constraint of the sector of the</td><td></td><td></td><td>K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         lanes         K         Limited sight distance.         Limited sight distance.         Visibility course 28 to local deliveries         regular car traffic.         Again, there is a high volume of moto         vehicle accidents in this stretch.         there is no signage directing people f         the Interstate to Pittsburgh and othe         south</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>opor<br/>poor<br/>hen<br/>r bike<br/></td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Iman</td></td<></td></td></tr><tr><td>40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.127248       -79.152286         41.1040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.371568         40.99912       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.999114       -79.342962         40.9981824       -79.343995         41.163374       -79.097537         41.146843       -79.117534         41.146843       -79.117534</td><td>374465       point         374466       point         374466       point         374568       point         374570       point         374571       point         374572       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374580       point         374591       point         374592       point         374593       point         374594       point         374595       point         374590       point         374591       point         374592       point         374593       point</td><td>2/10/2020       273156         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020     
 273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204</td></tr></td></td<><td>South bound traffic is speeding. Very little site distance when entering<br/>22/66 from Deanville road. Have almost been hit many times when trying<br/>to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering<br/>28/66 from Deanville road. Have almost been hit many times when trying<br/>to enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with<br/>limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         From mainly New Bethlehem to Kittanning. However the real problem is<br/>Brookville to Kittanning. The main problem is trucks. I drive this road<br/>atleast 20-30 times a month from Brookville to Kittanning and then some.<br/>I have noticed that traffic flows fine and safe when you never encounter a<br/>truck from kittanning to 180. If you do you face time delays for work<br/>meetings or healthcare. Or safety, most of these trucks are either going<br/>way to fast causing potential danger, or way to slow also causing danger.       X         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X         No signage on Interstate 80 that directs people to Pittsburgh or<br/>Punxsutawney       X</td><td>X         <td< td=""><td>x x x x x x x x x x x x x x x x x x x</td><td></td><td></td><td>Image: Second second</td><td>x     x       mBrookville on<br/>burgh. Also<br/>s a member of a<br/>ment     x       X     x</td><td>x         <td< td=""><td><ul> <li>Pedestrian safety</li> <li>Pedestrian safety</li> <li>Pedestrian safety</li> <li>Pedestrian safety</li> </ul></td><td>Image: constraint of the sector of the sec</td><td>x <math>x</math> <math>x</math></td><td>X      </td><td>x      </td><td></td><td>x x x x x x x x x x x x x x x x x x x</td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, pvisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Limited sight distance.         Limited sight distance.         Again, there is a high volume of the city to and leave route 28 to local deliveries regular car traffic.         Again, there is a high volume of motor vehicle accidents in this stretch.         there is no signage directing people for the linterstate to Pittsburgh and othe south         There is limited sight distance for trapulling out of Sloan Hill Road onto Rome pulling out</td><td>ing to ment ing to ment ing to ment ing to ment ing to ment in the ment in the</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Image: South of Brookville in Coder         Image: South of Brookville in Coder         Image: Source of the Source         Image: Source of the Source</td></td<></td></td<></td></td> | ×         × <td< td=""><td>Pedestrian safety</td><td>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x<br/>x</td><td>x       x         x</td><td>x       x         x       x      <tr td=""> <td>x      </td><td>Image: second second</td><td>X X X X X X X X X X X X X X X X X X X</td><td>K       I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.         I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.         intense curve with many accidents, p<br/>visibility intersections         slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes         K         Limited sight distance.         Interse trucks. They should just h<br/>be forced to use 79 out of the city to<br/>and leave route 28 to local deliveries<br/>regular car traffic.         Again, there is a high volume of moto<br/>vehicle accidents in this stretch.</td><td>ing to   ing to   ment   ing to   ment   oor   oor   hen   r bike</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.</td></tr><tr><td>40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.31177         40.907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.99914       -79.342962         40.9981824       -79.343995         41.163374       -79.097537         41.146843       -79.117534</td><td>374465       point         374465       point         374466       point         374568       point         374569       point  
      374571       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374579       point         374579       point         374580       point         374590       point         374590       point         374590       point         374590       point         374591       point</td><td>2/10/2020       273156         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273196         2/11/2020       273196         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210</td><td>South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         x         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve         x         bad curve         x         slow moving trucks going up hill         x         Local road that is at crest of hill. Very hard to pull across traffic here with         limited view and time.         X         The sharp curve coming into Goheenville from Distant.         X         Needs some kind lit signs to get drives attention to warn how sharp this corner is.         From mainly New Bethlehem to Kittanning. However the real problem is Brookville to Xittanning. The main problem is trucks. I drive this road atleast 20-30 times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and safe when you never encounter a truck from kitanning. The main problem is trucks are either going way to fast causing potential danger, or way to slow also causing danger.         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X    <td>x x x x x x x x x x x x x x x x x x x</td><td>x x x x x x x x x x x x x x x x x x x</td><td>.       .       .         .       .       .     &lt;</td><td></td><td>Image: Second second</td><td>x     x       x     x       m Brookville on<br/>burgh. Also<br/>s a member of a<br/>ment     x       x     x</td><td>x</td><td>Pedestrian safety         Image: Pedestrian safety</td><td>Image: second second</td><td>x       x         x</td><td>X       X         I       I         I       X         I       X         I       X         X</td><td>x      </td><td>Image: second second</td><td>X X X X X X X X X X X X X X X X X X X</td><td>K       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         intense curve with many accidents, p       visibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes       Intense curve with many accidents, p         K       It mitted sight distance.       Intense curve with many accidents, p         K       Intense curve with many accidents, p       Intense curve with many accidents, p         Visibility intersections       Intense curve second curves going up hill and accessing progress st. No pedestrian lanes         K       Intense curve second curves, power second curvesecond curvesecond curvesecond curves, power second cur</td><td>ave to 80 and</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Image: South of Brookville in Pittsburgh the         Speed limit signs need to be         adjusted to more reasonable         Speeds. Some could be raised a         bit and other through this certain         towns could be lowered.         Image: South of From I80 to         Kittanning.         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South in the speed limits. Some</td></td></tr><tr><td>40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.163718         41.040026       -79.257263         41.145777       -79.114011         40.849189       -79.096911         40.849189       -79.371568         40.998723       -79.31177         40.9907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         41.136277       -79.14657         41.136277       -79.14657         41.136277       -79.342962         40.999114       -79.342962         40.9981824       -79.097537         41.16843       -79.117534         41.146843       -79.117534</td><td>374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374572       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374589       point         374590       point         374591       point         374590       point         374591       point         374591       point         374592       point</td><td>2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210</td><td>South bound traffic is speeding. Very little site distance when entering       28/66 from Deanville road. Have almost been hit many times when trying         X       South bound traffic is speeding. Very little site distance when entering       28/66
from Deanville road. Have almost been hit many times when trying         X       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         Needs some kind lit signs to get drives attention to warn how sharp this corner is.       From mainly New Bethlehem to Kittanning. However the real problem is Brookville to Kittanning. The main problem is trucks. I drive this road atleast 20-30 times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and safe when you never encounter a truck from kittanning to 180. If you do you face time delays for work meetings or healthcare. Or safety, most of these trucks are either going way to fast causing potential danger, or way to slow also causing danger.         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X         v       V     <td>x x x x x x x x x x x x x x x x x x x</td><td>X         X</td><td>.       .       .         .       .       .     &lt;</td><td></td><td>Image: Second second</td><td>x     x       mm Brookville on burgh. Also is a member of a ment     x       X     x</td><td>X         <td< td=""><td>Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety</td><td>Image: Constraint of the sector of the se</td><td>x       x         x       x</td><td>X       X         I       I         I       X         I       X         I       X         X</td><td>X       Image: Constraint of the sector of the</td><td></td><td></td><td>K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         lanes         K         Limited sight distance.         Limited sight distance.         Visibility course 28 to local deliveries         regular car traffic.         Again, there is a high volume of moto         vehicle accidents in this stretch.         there is no signage directing people f         the Interstate to Pittsburgh and othe         south</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>opor<br/>poor<br/>hen<br/>r bike<br/></td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Iman</td></td<></td></td></tr><tr><td>40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.127248       -79.152286         41.1040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.371568         40.99912       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.999114       -79.342962         40.9981824       -79.343995         41.163374       -79.097537         41.146843       -79.117534         41.146843       -79.117534</td><td>374465       point         374466       point         374466       point         374568       point         374570       point         374571       point         374572       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374580       point         374591       point         374592       point         374593       point         374594       point         374595       point         374590       point         374591       point         374592       point         374593       point</td><td>2/10/2020       273156         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204</td></tr></td></td<> <td>South bound traffic is speeding. Very little site distance when entering<br/>22/66 from Deanville road. Have almost been hit many times when trying<br/>to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering<br/>28/66 from Deanville road. Have almost been hit many times when trying<br/>to enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with<br/>limited view
and time.       X         The sharp curve coming into Goheenville from Distant.       X         From mainly New Bethlehem to Kittanning. However the real problem is<br/>Brookville to Kittanning. The main problem is trucks. I drive this road<br/>atleast 20-30 times a month from Brookville to Kittanning and then some.<br/>I have noticed that traffic flows fine and safe when you never encounter a<br/>truck from kittanning to 180. If you do you face time delays for work<br/>meetings or healthcare. Or safety, most of these trucks are either going<br/>way to fast causing potential danger, or way to slow also causing danger.       X         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X         No signage on Interstate 80 that directs people to Pittsburgh or<br/>Punxsutawney       X</td> <td>X         <td< td=""><td>x x x x x x x x x x x x x x x x x x x</td><td></td><td></td><td>Image: Second second</td><td>x     x       mBrookville on<br/>burgh. Also<br/>s a member of a<br/>ment     x       X     x</td><td>x         <td< td=""><td><ul> <li>Pedestrian safety</li> <li>Pedestrian safety</li> <li>Pedestrian safety</li> <li>Pedestrian safety</li> </ul></td><td>Image: constraint of the sector of the sec</td><td>x <math>x</math> <math>x</math></td><td>X      </td><td>x      </td><td></td><td>x x x x x x x x x x x x x x x x x x x</td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, pvisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Limited sight distance.         Limited sight distance.         Again, there is a high volume of the city to and leave route 28 to local deliveries regular car traffic.         Again, there is a high volume of motor vehicle accidents in this stretch.         there is no signage directing people for the linterstate to Pittsburgh and othe south         There is limited sight distance for trapulling out of Sloan Hill Road onto Rome pulling out</td><td>ing to ment ing to ment ing to ment ing to ment ing to ment in the ment in the</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Image: South of Brookville in Coder         Image: South of Brookville in Coder         Image: Source of the Source         Image: Source of the Source</td></td<></td></td<></td> | Pedestrian safety  | x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x<br>x  | x       x         x | x       x         x      
x         x       x         x       x <tr td=""> <td>x      </td><td>Image: second second</td><td>X X X X X X X X X X X X X X X X X X X</td><td>K       I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.         I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.         intense curve with many accidents, p<br/>visibility intersections         slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes         K         Limited sight distance.         Interse trucks. They should just h<br/>be forced to use 79 out of the city to<br/>and leave route 28 to local deliveries<br/>regular car traffic.         Again, there is a high volume of moto<br/>vehicle accidents in this stretch.</td><td>ing to   ing to   ment   ing to   ment   oor   oor   hen   r bike</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.</td></tr> <tr><td>40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.31177         40.907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.99914       -79.342962         40.9981824       -79.343995         41.163374       -79.097537         41.146843       -79.117534</td><td>374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374579       point         374579       point         374580       point         374590       point         374590       point         374590       point         374590       point         374591       point</td><td>2/10/2020       273156         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273196         2/11/2020       273196         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210</td><td>South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         x         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve         x         bad curve         x         slow moving trucks going up hill         x         Local road that is at crest of hill. Very hard to pull across traffic here with         limited view and time.         X         The sharp curve coming into Goheenville from Distant.         X         Needs some kind lit signs to get drives attention to warn how sharp this corner is.         From mainly New Bethlehem to Kittanning. However the real problem is Brookville to Xittanning. The main problem is trucks. I drive this road atleast 20-30 times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and safe when you never encounter a truck from kitanning. The main problem is trucks are either going way to fast causing potential danger, or way to slow also causing danger.         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X    <td>x x x x x x x x x x x x x x x x x x x</td><td>x x x x x x x x x x x x x x x x x x x</td><td>.       .       .         .       .       .     &lt;</td><td></td><td>Image: Second second</td><td>x     x       x     x       m Brookville on<br/>burgh. Also<br/>s a member of a<br/>ment     x       x     x</td><td>x</td><td>Pedestrian safety         Image: Pedestrian safety</td><td>Image: second second</td><td>x       x         x</td><td>X       X         I       I         I       X         I       X         I       X         X</td><td>x      </td><td>Image: second second</td><td>X X X X X X X X X X X X X X X X X X X</td><td>K       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         intense curve with many accidents, p       visibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes       Intense curve with many accidents, p         K       It mitted sight distance.       Intense curve with many accidents, p         K       Intense curve with many accidents, p       Intense curve with many accidents, p         Visibility intersections       Intense curve second curves going up hill and accessing progress st. No pedestrian lanes         K       Intense curve second curves, power second curvesecond curvesecond curvesecond curves, power second cur</td><td>ave to 80 and</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Image: South of Brookville in Pittsburgh the         Speed limit signs need to be         adjusted to more reasonable         Speeds. Some could be raised a         bit and other through this certain         towns could be lowered.         Image: South of From I80 to         Kittanning.         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South in the speed limits. Some</td></td></tr> <tr><td>40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.163718         41.040026       -79.257263         41.145777       -79.114011         40.849189       -79.096911         40.849189       -79.371568         40.998723       -79.31177         40.9907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         41.136277       -79.14657         41.136277       -79.14657
        41.136277       -79.342962         40.999114       -79.342962         40.9981824       -79.097537         41.16843       -79.117534         41.146843       -79.117534</td><td>374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374572       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374589       point         374590       point         374591       point         374590       point         374591       point         374591       point         374592       point</td><td>2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210</td><td>South bound traffic is speeding. Very little site distance when entering       28/66 from Deanville road. Have almost been hit many times when trying         X       South bound traffic is speeding. Very little site distance when entering       28/66 from Deanville road. Have almost been hit many times when trying         X       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         Needs some kind lit signs to get drives attention to warn how sharp this corner is.       From mainly New Bethlehem to Kittanning. However the real problem is Brookville to Kittanning. The main problem is trucks. I drive this road atleast 20-30 times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and safe when you never encounter a truck from kittanning to 180. If you do you face time delays for work meetings or healthcare. Or safety, most of these trucks are either going way to fast causing potential danger, or way to slow also causing danger.         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X         v       V     <td>x x x x x x x x x x x x x x x x x x x</td><td>X         X</td><td>.       .       .         .       .       .     &lt;</td><td></td><td>Image: Second second</td><td>x     x       mm Brookville on burgh. Also is a member of a ment     x       X     x</td><td>X         <td< td=""><td>Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety</td><td>Image: Constraint of the sector of the se</td><td>x       x         x       x</td><td>X       X         I       I         I       X         I       X         I       X         X</td><td>X       Image: Constraint of the sector of the</td><td></td><td></td><td>K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         lanes         K         Limited sight distance.         Limited sight distance.         Visibility course 28 to local deliveries         regular car traffic.         Again, there is a high volume of moto         vehicle accidents in this stretch.         there is no signage directing people f         the Interstate to Pittsburgh and othe         south</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>opor<br/>poor<br/>hen<br/>r bike<br/></td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Iman</td></td<></td></td></tr> <tr><td>40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.127248       -79.152286         41.1040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.371568         40.99912       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.999114       -79.342962         40.9981824       -79.343995         41.163374       -79.097537         41.146843       -79.117534         41.146843       -79.117534</td><td>374465       point         374466       point         374466       point         374568       point         374570       point         374571       point         374572       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374580       point         374591       point         374592       point         374593       point         374594      
point         374595       point         374590       point         374591       point         374592       point         374593       point</td><td>2/10/2020       273156         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204</td></tr> | x  | Image: second | X X X X X X X X X X X X X X X X X X X   | K       I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.         I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.         intense curve with many accidents, p<br>visibility intersections         slow moving trucks going up hill and<br>accessing progress st. No pedestrian<br>lanes         K         Limited sight distance.         Interse trucks. They should just h<br>be forced to use 79 out of the city to<br>and leave route 28 to local deliveries<br>regular car traffic.         Again, there is a high volume of moto<br>vehicle accidents in this stretch.   | ing to   ing to   ment   ing to   ment   oor   oor   hen   r bike   
   | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.  | 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.31177         40.907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.99914       -79.342962         40.9981824       -79.343995         41.163374       -79.097537         41.146843       -79.117534 | 374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374579       point         374579       point         374580       point         374590       point         374590       point         374590       point         374590       point         374591       point | 2/10/2020       273156         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273196         2/11/2020       273196         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210 | South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         x         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve         x         bad curve         x         slow moving trucks going up hill         x         Local road that is at crest of hill. Very hard to pull across traffic here with         limited view and time.         X         The sharp curve coming into Goheenville from Distant.         X         Needs some kind lit signs to get drives attention to warn how sharp this corner is.         From mainly New Bethlehem to Kittanning. However the real problem is Brookville to Xittanning. The main problem is trucks. I drive this road atleast 20-30 times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and safe when you never encounter a truck from kitanning. The main problem is trucks are either going way to fast causing potential danger, or way to slow also causing danger.         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X <td>x x x x x x x x x x x x x x x x x x x</td> <td>x x x x x x x x x x x x x x x x x x x</td> <td>.       .       .         .       .       .     &lt;</td> <td></td> <td>Image: Second second</td> <td>x     x       x     x       m Brookville on<br/>burgh. Also<br/>s a member of a<br/>ment     x       x     x</td> <td>x</td> <td>Pedestrian safety         Image: Pedestrian safety</td> <td>Image: second second</td> <td>x       x         x      
x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x</td> <td>X       X         I       I         I       X         I       X         I       X         X</td> <td>x      </td> <td>Image: second second</td> <td>X X X X X X X X X X X X X X X X X X X</td> <td>K       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         intense curve with many accidents, p       visibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes       Intense curve with many accidents, p         K       It mitted sight distance.       Intense curve with many accidents, p         K       Intense curve with many accidents, p       Intense curve with many accidents, p         Visibility intersections       Intense curve second curves going up hill and accessing progress st. No pedestrian lanes         K       Intense curve second curves, power second curvesecond curvesecond curvesecond curves, power second cur</td> <td>ave to 80 and</td> <td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Image: South of Brookville in Pittsburgh the         Speed limit signs need to be         adjusted to more reasonable         Speeds. Some could be raised a         bit and other through this certain         towns could be lowered.         Image: South of From I80 to         Kittanning.         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South in the speed limits. Some</td> | x x x x x x x x x x x x x x x x x x x | x x x x x x x x x x x x x x x x x x x | .       .       .         .       .       .     < |  | Image: Second | x     x       x     x       m Brookville on<br>burgh. Also<br>s a member of a<br>ment     x       x     x | x | Pedestrian safety         Image: Pedestrian safety | Image: second | x       x         x | X       X         I       I         I       X         I       X         I       X         X | x | Image: second | X X X X X X X X X X X X X X X X X X X | K       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         intense curve with many accidents, p       visibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes       Intense curve with many accidents, p         K       It mitted sight distance.       Intense curve with many accidents, p         K       Intense curve with many accidents, p       Intense curve with many accidents, p         Visibility intersections       Intense curve second curves going up hill and accessing progress st. No pedestrian lanes         K       Intense curve second curves, power second curvesecond curvesecond curvesecond curves, power second cur | ave to 80 and | South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Image: South of Brookville in Pittsburgh the         Speed limit signs need to be         adjusted to more reasonable         Speeds. Some could be raised a         bit and other through this certain         towns could be lowered.         Image: South of From I80 to         Kittanning.         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South in the speed limits. Some | 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.163718         41.040026       -79.257263         41.145777       -79.114011         40.849189       -79.096911         40.849189       -79.371568         40.998723       -79.31177         40.9907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         41.136277       -79.14657         41.136277       -79.14657         41.136277       -79.342962         40.999114       -79.342962         40.9981824       -79.097537         41.16843       -79.117534         41.146843       -79.117534 | 374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374572       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374589       point         374590       point         374591       point         374590       point         374591       point         374591       point         374592       point | 2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210 | South bound traffic is speeding. Very little site distance when entering       28/66 from Deanville road. Have almost been hit many times
when trying         X       South bound traffic is speeding. Very little site distance when entering       28/66 from Deanville road. Have almost been hit many times when trying         X       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         Needs some kind lit signs to get drives attention to warn how sharp this corner is.       From mainly New Bethlehem to Kittanning. However the real problem is Brookville to Kittanning. The main problem is trucks. I drive this road atleast 20-30 times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and safe when you never encounter a truck from kittanning to 180. If you do you face time delays for work meetings or healthcare. Or safety, most of these trucks are either going way to fast causing potential danger, or way to slow also causing danger.         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X         v       V <td>x x x x x x x x x x x x x x x x x x x</td> <td>X         X</td> <td>.       .       .         .       .       .     &lt;</td> <td></td> <td>Image: Second second</td> <td>x     x       mm Brookville on burgh. Also is a member of a ment     x       X     x</td> <td>X         <td< td=""><td>Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety</td><td>Image: Constraint of the sector of the se</td><td>x       x         x       x</td><td>X       X         I       I         I       X         I       X         I       X         X</td><td>X       Image: Constraint of the sector of the</td><td></td><td></td><td>K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         lanes         K         Limited sight distance.         Limited sight distance.         Visibility course 28 to local deliveries         regular car traffic.         Again, there is a high volume of moto         vehicle accidents in this stretch.         there is no signage directing people f         the Interstate to Pittsburgh and othe         south</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>opor<br/>poor<br/>hen<br/>r bike<br/></td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Iman</td></td<></td> | x x x x x x x x x x x x x x x x x x x | X         X | .       .       .         .       .       .     < |  | Image: Second | x     x       mm Brookville on burgh. Also is a member of a ment     x       X     x | X         X <td< td=""><td>Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety</td><td>Image: Constraint of the sector of the se</td><td>x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x        
x       x         x       x</td><td>X       X         I       I         I       X         I       X         I       X         X</td><td>X       Image: Constraint of the sector of the</td><td></td><td></td><td>K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         lanes         K         Limited sight distance.         Limited sight distance.         Visibility course 28 to local deliveries         regular car traffic.         Again, there is a high volume of moto         vehicle accidents in this stretch.         there is no signage directing people f         the Interstate to Pittsburgh and othe         south</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>opor<br/>poor<br/>hen<br/>r bike<br/></td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Iman</td></td<> | Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety | Image: Constraint of the sector of the se | x       x         x       x | X       X         I       I         I       X         I       X         I       X         X | X       Image: Constraint of the sector of the |  |  | K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         lanes         K         Limited sight distance.         Limited sight distance.         Visibility course 28 to local deliveries         regular car traffic.         Again, there is a high volume of moto         vehicle accidents in this stretch.         there is no signage directing people f         the Interstate to Pittsburgh and othe         south | ing to<br>ment<br>ing to<br>ment<br>opor<br>poor<br>hen<br>r bike<br> | South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Iman | 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.127248       -79.152286         41.1040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.371568         40.99912       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.999114       -79.342962         40.9981824       -79.343995         41.163374       -79.097537         41.146843       -79.117534         41.146843       -79.117534 | 374465       point         374466       point         374466       point         374568       point         374570       point         374571       point         374572       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374580       point         374591       point         374592       point         374593       point         374594       point         374595       point         374590       point         374591       point         374592       point         374593       point | 2/10/2020       273156         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204 | South bound traffic is speeding. Very little site distance when entering<br>22/66 from Deanville road. Have almost been hit many times when trying<br>to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering<br>28/66 from Deanville road. Have almost been hit many times when trying<br>to enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with<br>limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         From mainly New Bethlehem to Kittanning. However the real problem is<br>Brookville to Kittanning. The main problem is trucks. I drive this road<br>atleast 20-30 times a month from Brookville to Kittanning and then some.<br>I have noticed that traffic flows fine and safe when you never encounter a<br>truck from kittanning to 180. If you do you face time delays for work<br>meetings or healthcare. Or safety, most of these trucks are either going<br>way to fast causing potential danger, or way to slow also causing danger.       X         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X         No signage on Interstate 80 that directs people to Pittsburgh or<br>Punxsutawney       X | X        
X         X         X         X         X         X <td< td=""><td>x x x x x x x x x x x x x x x x x x x</td><td></td><td></td><td>Image: Second second</td><td>x     x       mBrookville on<br/>burgh. Also<br/>s a member of a<br/>ment     x       X     x</td><td>x         <td< td=""><td><ul> <li>Pedestrian safety</li> <li>Pedestrian safety</li> <li>Pedestrian safety</li> <li>Pedestrian safety</li> </ul></td><td>Image: constraint of the sector of the sec</td><td>x <math>x</math> <math>x</math></td><td>X      </td><td>x      </td><td></td><td>x x x x x x x x x x x x x x x x x x x</td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, pvisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Limited sight distance.         Limited sight distance.         Again, there is a high volume of the city to and leave route 28 to local deliveries regular car traffic.         Again, there is a high volume of motor vehicle accidents in this stretch.         there is no signage directing people for the linterstate to Pittsburgh and othe south         There is limited sight distance for trapulling out of Sloan Hill Road onto Rome pulling out</td><td>ing to ment ing to ment ing to ment ing to ment ing to ment in the ment in the</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Image: South of Brookville in Coder         Image: South of Brookville in Coder         Image: Source of the Source         Image: Source of the Source</td></td<></td></td<> | x x x x x x x x x x x x x x x x x x x |  |  | Image: Second | x     x       mBrookville on<br>burgh. Also<br>s a member of a<br>ment     x       X     x | x         x <td< td=""><td><ul> <li>Pedestrian safety</li> <li>Pedestrian safety</li> <li>Pedestrian safety</li> <li>Pedestrian safety</li> </ul></td><td>Image: constraint of the sector of the sec</td><td>x <math>x</math> <math>x</math></td><td>X      </td><td>x      </td><td></td><td>x x x x x x x x x x x x x x x x x x x</td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, pvisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Limited sight distance.         Limited sight distance.         Again, there is a high volume of the city to and leave route 28 to local deliveries regular car traffic.         Again, there is a high volume of motor vehicle accidents in this stretch.         there is no signage directing people for the linterstate to Pittsburgh and othe south         There is limited sight distance for trapulling out of Sloan Hill Road onto Rome pulling out</td><td>ing to ment ing to ment ing to ment ing to ment ing to ment in the ment in the</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Image: South of Brookville in Coder         Image: South of Brookville in Coder         Image: Source of the Source         Image: Source of the Source</td></td<> | <ul> <li>Pedestrian safety</li> <li>Pedestrian safety</li> <li>Pedestrian safety</li> <li>Pedestrian safety</li> </ul> | Image: constraint of the sector of the sec | x $x$ | X | x |  | x x x x x x x x x x x x x x x x x x x | K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, pvisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Limited sight distance.         Limited sight distance.         Again, there is a high volume of the city to and leave route 28 to local deliveries regular car traffic.         Again, there is a high volume of motor vehicle accidents in this stretch.         there is no signage directing people for the linterstate to Pittsburgh and othe south         There is limited sight distance for trapulling out of Sloan Hill Road onto Rome pulling out | ing to ment in the | South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Image: South of Brookville in Coder         Image: South of Brookville in Coder         Image: Source of the Source         Image: Source of the Source |
| x   | Image: second  
   | X X X X X X X X X X X X X X X X X X X   
   
  | K       I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.         I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.         intense curve with many accidents, p<br>visibility intersections         slow moving trucks going up hill and<br>accessing progress st. No pedestrian<br>lanes         K         Limited sight distance.         Interse trucks. They should just h<br>be forced to use 79 out of the city to<br>and leave route 28 to local deliveries<br>regular car traffic.         Again, there is a high volume of moto<br>vehicle accidents in this stretch.  
   
   | ing to   ing to   ment   ing to   ment   oor   oor   hen   r bike   
   
   
   
   
  | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.   
   
  |   |     |   |  
   
   
   
   
  |  
   
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   |   |   
   |   |   |   |   
   |   |   
   |                                       |                                       |   |  |   |   |   |  |   
   |   |   |   |   |                                       |   |               |   |   |   |  |  
   
   |                                       |   |   |  |   |  | | | |
  |   |   |   |   |  
   |  |  |   |   |   |  |  |  |   |  
  |                                       |  |  |  
  |  |   |   
  |  |   |   |   |  |                                       |  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.31177         40.907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.99914       -79.342962         40.9981824       -79.343995         41.163374       -79.097537         41.146843       -79.117534   | 374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374579       point         374579       point         374580       point         374590       point         374590       point         374590       point         374590       point         374591       point  
   
   | 2/10/2020       273156         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273196         2/11/2020       273196         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210   
  | South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         x         South bound traffic is speeding. Very little site distance when entering         28/66 from Deanville road. Have almost been hit many times when trying         to enter 28/66         X         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve         x         bad curve         x         slow moving trucks going up hill         x         Local road that is at crest of hill. Very hard to pull across traffic here with         limited view and time.         X         The sharp curve coming into Goheenville from Distant.         X         Needs some kind lit signs to get drives attention to warn how sharp this corner is.         From mainly New Bethlehem to Kittanning. However the real problem is Brookville to Xittanning. The main problem is trucks. I drive this road atleast 20-30
times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and safe when you never encounter a truck from kitanning. The main problem is trucks are either going way to fast causing potential danger, or way to slow also causing danger.         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X <td>x x x x x x x x x x x x x x x x x x x</td> <td>x x x x x x x x x x x x x x x x x x x</td> <td>.       .       .         .       .       .     &lt;</td> <td></td> <td>Image: Second second</td> <td>x     x       x     x       m Brookville on<br/>burgh. Also<br/>s a member of a<br/>ment     x       x     x</td> <td>x</td> <td>Pedestrian safety         Image: Pedestrian safety</td> <td>Image: second second</td> <td>x       x         x</td> <td>X       X         I       I         I       X         I       X         I       X         X</td> <td>x      </td> <td>Image: second second</td> <td>X X X X X X X X X X X X X X X X X X X</td> <td>K       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         intense curve with many accidents, p       visibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes       Intense curve with many accidents, p         K       It mitted sight distance.       Intense curve with many accidents, p         K       Intense curve with many accidents, p       Intense curve with many accidents, p         Visibility intersections       Intense curve second curves going up hill and accessing progress st. No pedestrian lanes         K       Intense curve second curves, power second curvesecond curvesecond curvesecond curves, power second cur</td> <td>ave to 80 and</td> <td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Image: South of Brookville in Pittsburgh the         Speed limit signs need to be         adjusted to more reasonable         Speeds. Some could be raised a         bit and other through this certain         towns could be lowered.         Image: South of From I80 to         Kittanning.         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South in the speed limits. Some</td>  | x x x x x x x x x x x x x x x x x x x  
   
   
   
   
   
   | x x x x x x x x x x x x x x x x x x x   
   | .       .       .         .       .       .     < |     | Image: Second | x     x       x     x       m Brookville on<br>burgh. Also<br>s a member of a<br>ment     x       x     x   
   
   
   
   
   
   | x   
   
   
   
   
   | Pedestrian safety         Image: Pedestrian safety   | Image: second                | x       x         x | X       X         I       I         I       X         I       X         I       X         X   
   
   
   
   | x  | Image: second | X X X X X X X X X X X X X X X X X X X   | K       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         enter 28 66. We also have farm equipentering the road also.       I have been almost hit many times tr         intense curve with many accidents, p       visibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes       Intense curve with many accidents, p         K       It mitted sight distance.       Intense curve with many accidents, p         K       Intense curve with many accidents, p       Intense curve with many accidents, p         Visibility intersections       Intense curve second curves going up hill and accessing progress st. No pedestrian lanes         K       Intense curve second curves, power second curvesecond curvesecond curvesecond curves, power second cur  
  | ave to 80 and   | South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Image: South of Brookville in Pittsburgh the         Speed limit signs need to be         adjusted to more reasonable         Speeds. Some could be raised a         bit and other through this certain         towns could be lowered.         Image: South of From I80 to         Kittanning.         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South of Image: South in the speed limits. Some         Image: South in the speed limits. Some   |   |   |   |  
   
  |                                       |                                       |   |  |   |   |   |  |   |   |   |   |  
  |                                       |   |               |   |   |   |  |   
   
  |                                       |   |   |  |   |  | | | |
   |   |   |   |   |  |  |  |   |   |  
  |  |  |  |   |   
   |                                       |  |  |   |  |  
  |  |  |   |   |   |  |                                       |   
  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.163718         41.040026       -79.257263         41.145777       -79.114011         40.849189       -79.096911         40.849189       -79.371568         40.998723       -79.31177         40.9907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         41.136277       -79.14657         41.136277       -79.14657         41.136277       -79.342962         40.999114       -79.342962         40.9981824       -79.097537         41.16843       -79.117534         41.146843       -79.117534   | 374465       point         374465       point         374466       point         374568       point         374569       point         374571       point         374572       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374589       point         374590       point         374591       point         374590       point         374591       point         374591       point         374592       point  
   
   | 2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210  
  | South bound traffic is speeding. Very little site distance when entering       28/66 from Deanville road. Have almost been hit many times when trying         X       South bound traffic is speeding. Very little site distance when entering       28/66 from Deanville road. Have almost been hit many times when trying         X       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         Needs some kind lit signs to get drives attention to warn how sharp this corner is.       From mainly New Bethlehem to Kittanning. However the real problem is Brookville to Kittanning. The main problem is trucks. I drive
this road atleast 20-30 times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and safe when you never encounter a truck from kittanning to 180. If you do you face time delays for work meetings or healthcare. Or safety, most of these trucks are either going way to fast causing potential danger, or way to slow also causing danger.         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X         v       V <td>x x x x x x x x x x x x x x x x x x x</td> <td>X         X</td> <td>.       .       .         .       .       .     &lt;</td> <td></td> <td>Image: Second second</td> <td>x     x       mm Brookville on burgh. Also is a member of a ment     x       X     x</td> <td>X         <td< td=""><td>Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety</td><td>Image: Constraint of the sector of the se</td><td>x       x         x       x</td><td>X       X         I       I         I       X         I       X         I       X         X</td><td>X       Image: Constraint of the sector of the</td><td></td><td></td><td>K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         lanes         K         Limited sight distance.         Limited sight distance.         Visibility course 28 to local deliveries         regular car traffic.         Again, there is a high volume of moto         vehicle accidents in this stretch.         there is no signage directing people f         the Interstate to Pittsburgh and othe         south</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>opor<br/>poor<br/>hen<br/>r bike<br/></td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Iman</td></td<></td>   | x x x x x x x x x x x x x x x x x x x  
   
   
   
   
   
   | X           
   | .       .       .         .       .       .     < |     | Image: Second | x     x       mm Brookville on burgh. Also is a member of a ment     x       X     x  
   
   
   
   
   
   | X         X <td< td=""><td>Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety</td><td>Image: Constraint of the sector of the se</td><td>x       x         x       x</td><td>X       X         I       I         I       X         I       X         I       X         X</td><td>X       Image: Constraint of the sector of the</td><td></td><td></td><td>K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         lanes         K         Limited sight distance.         Limited sight distance.         Visibility course 28 to local deliveries         regular car traffic.         Again, there is a high volume of moto         vehicle accidents in this stretch.         there is no signage directing people f         the Interstate to Pittsburgh and othe         south</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>opor<br/>poor<br/>hen<br/>r bike<br/></td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Iman</td></td<>  
   
   
   
   
   | Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety         Pedestrian safety  | Image: Constraint of the sector of the se                | x       x           | X       X         I       I         I       X         I       X         I       X         X   
   
   
   
   | X       Image: Constraint of the sector of the |   |   | K       I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         I have been almost hit many times tr         enter 28 66. We also have farm equip         entering the road also.         intense curve with many accidents, p         visibility intersections         slow moving trucks going up hill and         accessing progress st. No pedestrian         lanes         K         Limited sight distance.         Limited sight distance.         Visibility course 28 to local deliveries         regular car traffic.         Again, there is a high volume of moto         vehicle accidents in this stretch.         there is no signage directing people f         the Interstate to Pittsburgh and othe         south   | ing to<br>ment<br>ing to<br>ment<br>opor<br>poor<br>hen<br>r bike<br>  
  | South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: South of Brookville in Coder         Iman   |   |   |   | | | | | | | |
  |                                       |                                       |   |  |   
   |   |   |  |   |   |   |   |   |                                       |   |               |  
  |   |   |  |   
  |                                       |   |   |  |   
   |  |  |   |   
   |   |   |  |  |  |   |   |   |  |  |  |   
   |   
   |                                       |  |  |   |  |  
  |  |  |   |   |   |  |                                       |  |  
   |  |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.127248       -79.152286         41.1040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.371568         40.99912       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.999114       -79.342962         40.9981824       -79.343995         41.163374       -79.097537         41.146843       -79.117534         41.146843       -79.117534  | 374465       point         374466       point         374466       point         374568       point         374570       point         374571       point         374572       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374580       point         374591       point         374592       point         374593       point         374594       point         374595       point         374590       point         374591       point         374592       point         374593       point   
   
   | 2/10/2020       273156         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204  
  |  
   
   |   
   
   
   
   
   
  |  
  |   |     |   |  
   
   
   
   
   
  |  
   
   
   
   
  |  |  |   |  
   
   
   
  |  |   | | | | | | | | | | |
   |   |   |   
   |   |   |   |   
   |                                       |                                       |   |  |   |  
  |   |  |   |   |   |   |   |                                       |   |               |   |   |   
   |  |  
   |                                       |   |   |  |   |  | | | | |
  |   |   |   |  
  |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.127248       -79.0163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.999723       -79.331177         40.907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         41.136374       -79.097537         40.981824       -79.343995         41.163374       -79.097537         41.146843       -79.117534         41.170411       -79.100301         40.818083       -79.486718         40.822073       -79.486718  | 374465       point         374465       point         374466       point         374568       point         374571       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374579       point         374580       point         374591       point         374592       point         374593       point         374594       point         374595       point         374590       point         374591       point         374592       point         374593       point         374594       point         374595       point         374591       point         374592       point         374593       point         374594       point         374595       point         374591       point         374592       point         374403       point         374433       point <td>2/10/2020       2/73156         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273196         2/11/2020       273196         2/11/2020       273196         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210<td>South bound traffic is speeding. Very little site distance when entering<br/>28/66 from Deanville road. Have almost been hit many times when trying<br/>28/66 from Deanville road. Have almost been hit many times when trying<br/>to enter 28/66         X           Too many motor vehicle accidents with limited acces for fire departments         X           dangerous curve         X           low visibility curve         X           slow moving trucks going up hill         X           Local road that is at crest of hill. Very hard to pull across traffic here with<br/>limited view and time.         X           The sharp curve coming into Goheenville from Distant.         X           The sharp curve coming into Goheenville from Distant.         X           From mainly New Bethlehem to Kittanning. However the real problem is<br/>Brookville to Kittanning. The main problem is trucks. I drive this road<br/>atleast 20-30 times a month from Brookville to Kittanning and then some.<br/>I have noticed that traffic flows fine and safe when you never encounter a<br/>truck from kittanning to 180. If you do you face time delays for work<br/>meetings or healthcar. Or safety, most of these trucks are either going<br/>way to fast causing potential danger, or way to slow also causing danger.         X           est         Route 28 between the areas of Airport Road Ext. and Cemetery Road.         X           There is limited visibility for people pulling out of Sloan Hill Road ontot<br/>Route 28.         X</td><td>X         <td< td=""><td>x x x x x x x x x x x x x x x x x x x</td><td></td><td></td><td>Image: second second</td><td>x     x       y     x       y     x       y     x       y     x       y     x       x     x  </td><td>x         <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: constraint of the sector of the sec</td><td>x <math>x</math> <math>x</math></td><td>X      </td><td></td><td></td><td>x       x         x</td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Limited sight distance for trap         Limited sight distance for trap         Limited sight distance for trap         Limited sight for cars turning onto Sloan         R</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing to<br/>ment<br/>por<br/>por<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/></td></td<></td></td<></td></td>  
  | 2/10/2020       2/73156         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273196         2/11/2020       273196         2/11/2020       273196         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210 <td>South bound traffic is speeding. Very little site distance when entering<br/>28/66 from Deanville road. Have almost been hit many times when trying<br/>28/66 from Deanville road. Have almost been hit many times when trying<br/>to enter 28/66         X           Too many motor vehicle accidents with limited acces for fire departments         X           dangerous curve         X           low visibility curve         X           slow moving trucks going up hill         X           Local road that is at crest of hill. Very hard to pull across traffic here with<br/>limited view and time.         X           The sharp curve coming into Goheenville from Distant.         X           The sharp curve coming into Goheenville from Distant.         X           From mainly New Bethlehem to Kittanning. However the real problem is<br/>Brookville to Kittanning. The main problem is trucks. I drive this road<br/>atleast 20-30 times a month from Brookville to Kittanning and then some.<br/>I have noticed that traffic flows fine and safe when you never encounter a<br/>truck from kittanning to 180. If you do you face time delays for work<br/>meetings or healthcar. Or safety, most of these trucks are either going<br/>way to fast causing potential danger, or way to slow also causing danger.         X           est         Route 28 between the areas of Airport Road Ext. and Cemetery Road.         X           There is limited visibility for people pulling out of Sloan Hill Road ontot<br/>Route 28.         X</td> <td>X         <td< td=""><td>x x x x x x x x x x x x x x x x x x x</td><td></td><td></td><td>Image: second second</td><td>x     x       y     x       y     x       y     x       y     x       y     x       x     x  </td><td>x         <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: constraint of the sector of the sec</td><td>x <math>x</math> <math>x</math></td><td>X      </td><td></td><td></td><td>x       x         x</td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prisibility intersections         slow moving trucks going up hill and
accessing progress st. No pedestrian lanes         K         Limited sight distance.         Limited sight distance for trap         Limited sight distance for trap         Limited sight distance for trap         Limited sight for cars turning onto Sloan         R</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing to<br/>ment<br/>por<br/>por<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/></td></td<></td></td<></td>   | South bound traffic is speeding. Very little site distance when entering<br>28/66 from Deanville road. Have almost been hit many times when trying<br>28/66 from Deanville road. Have almost been hit many times when trying<br>to enter 28/66         X           Too many motor vehicle accidents with limited acces for fire departments         X           dangerous curve         X           low visibility curve         X           slow moving trucks going up hill         X           Local road that is at crest of hill. Very hard to pull across traffic here with<br>limited view and time.         X           The sharp curve coming into Goheenville from Distant.         X           The sharp curve coming into Goheenville from Distant.         X           From mainly New Bethlehem to Kittanning. However the real problem is<br>Brookville to Kittanning. The main problem is trucks. I drive this road<br>atleast 20-30 times a month from Brookville to Kittanning and then some.<br>I have noticed that traffic flows fine and safe when you never encounter a<br>truck from kittanning to 180. If you do you face time delays for work<br>meetings or healthcar. Or safety, most of these trucks are either going<br>way to fast causing potential danger, or way to slow also causing danger.         X           est         Route 28 between the areas of Airport Road Ext. and Cemetery Road.         X           There is limited visibility for people pulling out of Sloan Hill Road ontot<br>Route 28.         X  
   
  | X         X <td< td=""><td>x x x x x x x x x x x x x x x x x x x</td><td></td><td></td><td>Image: second second</td><td>x     x       y     x       y     x       y     x       y     x       y     x       x     x  </td><td>x         <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: constraint of the sector of the sec</td><td>x <math>x</math> <math>x</math></td><td>X      </td><td></td><td></td><td>x       x         x</td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Limited sight distance for trap         Limited sight distance for trap         Limited sight distance for trap         Limited sight for cars turning onto Sloan         R</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing to<br/>ment<br/>por<br/>por<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/></td></td<></td></td<>  
   
   
   
   
  | x x x x x x x x x x x x x x x x x x x  
  |   |     | Image: second | x     x       y     x       y     x       y     x       y     x       y     x       x     x  
   
   
   
   
   
  | x         x <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: constraint of the sector of the sec</td><td>x <math>x</math> <math>x</math></td><td>X      </td><td></td><td></td><td>x       x         x</td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Limited sight distance for trap         Limited sight distance for trap         Limited sight distance for trap         Limited sight for cars turning onto Sloan         R</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing to<br/>ment<br/>por<br/>por<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/></td></td<>   
   
   
   
  | Pedestrian safety  
   | Image: constraint of the sector of the sec | x $x$   | X  
   
   
  |  
   |   | x       x         x | K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Limited sight distance for trap         Limited sight distance for trap         Limited sight distance for trap         Limited sight for cars turning onto Sloan         R  | ing to<br>ment<br>ing to<br>ment<br>ing to<br>ment<br>por<br>por<br>ing<br>ing<br>ing<br>ing<br>ing<br>ing<br>ing<br>ing  
   | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>  |   |   |   | | | | | | | |
   |                                       |                                       |   
   |  |   |   |   |  |   |   |   |   |   |                                       |   
   |               |   |   |   |  |  
   |                                       |   |   |  |  
  |  |   
  |   |   |   |   |  |  |  |   |   |   |  |  |  |  
  |  
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |   
  |  |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.14657         41.14577       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.331177         40.99912       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.34296         41.136277       -79.343995         41.163374       -79.097537         40.9981824       -79.343995         41.146843       -79.117534         41.170411       -79.100301         40.818083       -79.489783         40.822073       -79.486718         40.835803       -79.468292  | 374465       point         374465       point         374466       point         374568       point         374570       point         374571       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374580       point         374591       point         374590       point         374590       point         374591       point         374592       point         374593       point         374594       point         374595       point         374590       point         374591       point         374592       point         374593       point         374594       point  
   
   | 2/10/2020       2/73156         2/10/2020       273156         2/10/2020       273153         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273163         2/11/2020       273163         2/11/2020       273163         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273231         2/11/2020       273231         2/11/2020       273231         2/11/2020       273231 <td>South bound traffic is speeding. Very little site distance when entering<br/>22/66 from Deanville road. Have almost been hit many times when trying<br/>22/66 from Deanville road. Have almost been hit many times when trying<br/>22/66 from Deanville road. Have almost been hit many times when trying<br/>to enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with<br/>limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         The sharp curve coming into Goheenville from Distant.       X         From mainly New Bethlehem to Kittanning. However the real problem is<br/>Brookville to Kittanning. The main problem is trucks. I drive this road<br/>atteast 20-30 times a month from Brookville to Kittanning and then some.<br/>I have noticed that traffic flows fine and safe when you never encounter a<br/>truck from Kittanning to 180. If you doy uf face time delays for work<br/>meetings or healthcare. Or safety, most of these trucks are either going<br/>way to fast causing potential danger, or way to slow also causing danger.       X         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X         There is limited visibility for people pulling out of Sloan Hill Road onto<br/>Route 28.       X     <!--</td--><td>X         <td< td=""><td>x         <td< td=""><td></td><td></td><td>Image: Second second</td><td>x     x       m Brookville on purgh. Also is a member of a ment     x       x     x  </td><td>x         <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: set of the set of the</td><td>x       x         x       x</td><td>X      </td><td>x      </td><td></td><td></td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 60. We also have farm equipenter 28 for local deliveries regular car traffic.         Again, there is a high volume of motor vehicle accidents in this stretch.         There is no signage directing people for the Interstate to Pittsburgh and othe south         There is limited sight distance for trapulling out of Sloan Hill Road onto Roas well as for cars turning onto Sloan Road from Roat turks.         There is no passing lane on this porting the hill so passenger cars regularly ge behind large trucks.</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>oor<br/>oor<br/>ing to<br/>ment<br/>oor<br/>ing to<br/>ing to</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/></td></td<></td></td<></td></td<></td></td>   
  | South bound traffic is speeding. Very little site distance when entering<br>22/66 from Deanville road. Have almost been hit many times when trying<br>22/66 from Deanville road. Have almost been hit many times when trying<br>22/66 from Deanville road. Have almost been hit many times when trying<br>to enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with<br>limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         The sharp curve coming into Goheenville from Distant.       X         From mainly New Bethlehem to Kittanning. However the real problem is<br>Brookville to Kittanning. The main problem is trucks. I drive this road<br>atteast 20-30 times a month from Brookville to Kittanning and then some.<br>I have noticed that traffic flows fine and safe when you never encounter a<br>truck from Kittanning to 180. If you doy uf face time delays for work<br>meetings or healthcare. Or safety, most of these trucks are either going<br>way to fast causing potential danger, or way to slow also causing danger.       X         est       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X         There is limited visibility for people pulling out of Sloan Hill Road onto<br>Route 28.       X </td <td>X         <td< td=""><td>x         <td< td=""><td></td><td></td><td>Image: Second second</td><td>x     x       m Brookville on purgh. Also is a member of a ment     x       x     x  </td><td>x         <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: set of the set of the</td><td>x       x         x       x</td><td>X      </td><td>x      </td><td></td><td></td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 60. We also have farm equipenter 28 for local deliveries regular car traffic.         Again, there is a high volume of motor vehicle accidents in this stretch.         There is no signage directing people for the Interstate to Pittsburgh and othe south         There is limited sight distance for trapulling out of Sloan Hill Road onto Roas well as for cars turning onto Sloan Road from Roat turks.         There is no passing lane on this porting the hill so passenger cars regularly ge behind large trucks.</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>oor<br/>oor<br/>ing to<br/>ment<br/>oor<br/>ing to<br/>ing to</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/></td></td<></td></td<></td></td<></td>   | X         X <td< td=""><td>x         <td< td=""><td></td><td></td><td>Image: Second second</td><td>x     x       m Brookville on purgh. Also is a member of a ment     x       x     x       x     x       x     x       x     x       x     x       x     x       x     x       x     x  
    x     x       x     x  </td><td>x         <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: set of the set of the</td><td>x       x         x       x</td><td>X      </td><td>x      </td><td></td><td></td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 60. We also have farm equipenter 28 for local deliveries regular car traffic.         Again, there is a high volume of motor vehicle accidents in this stretch.         There is no signage directing people for the Interstate to Pittsburgh and othe south         There is limited sight distance for trapulling out of Sloan Hill Road onto Roas well as for cars turning onto Sloan Road from Roat turks.         There is no passing lane on this porting the hill so passenger cars regularly ge behind large trucks.</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>oor<br/>oor<br/>ing to<br/>ment<br/>oor<br/>ing to<br/>ing to</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/></td></td<></td></td<></td></td<>  
   
   
   
  | x         x <td< td=""><td></td><td></td><td>Image: Second second</td><td>x     x       m Brookville on purgh. Also is a member of a ment     x       x     x  </td><td>x         <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: set of the set of the</td><td>x       x         x    
  x         x       x</td><td>X      </td><td>x      </td><td></td><td></td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 60. We also have farm equipenter 28 for local deliveries regular car traffic.         Again, there is a high volume of motor vehicle accidents in this stretch.         There is no signage directing people for the Interstate to Pittsburgh and othe south         There is limited sight distance for trapulling out of Sloan Hill Road onto Roas well as for cars turning onto Sloan Road from Roat turks.         There is no passing lane on this porting the hill so passenger cars regularly ge behind large trucks.</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>oor<br/>oor<br/>ing to<br/>ment<br/>oor<br/>ing to<br/>ing to</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/></td></td<></td></td<>  |   |     | Image: Second | x     x       m Brookville on purgh. Also is a member of a ment     x       x     x  
   
   
   
   
  | x         x <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: set of the set of the</td><td>x       x         x       x</td><td>X      </td><td>x      </td><td></td><td></td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 60. We also have farm equipenter 28 for local deliveries regular car traffic.         Again, there is a high volume of motor vehicle accidents in this stretch.         There is no signage directing people for the Interstate to Pittsburgh and othe south         There is limited sight distance for trapulling out of Sloan Hill Road onto Roas well as for cars turning onto Sloan Road from Roat turks.         There is no passing lane on this porting the hill so passenger cars regularly ge behind large trucks.</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>oor<br/>oor<br/>ing to<br/>ment<br/>oor<br/>ing to<br/>ing to</td><td>South of Brookville in Coder<br/>Hollow. Turn is narrow. High<br/>traffic area.<br/>South of Brookville in Coder<br/>Hollow. Turn is narrow.
High<br/>traffic area.<br/></td></td<>   
   
   
   
  | Pedestrian safety  | Image: set of the | x       x           | X   
   
   
   
   | x  |   |   | K       I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 60. We also have farm equipenter 28 for local deliveries regular car traffic.         Again, there is a high volume of motor vehicle accidents in this stretch.         There is no signage directing people for the Interstate to Pittsburgh and othe south         There is limited sight distance for trapulling out of Sloan Hill Road onto Roas well as for
cars turning onto Sloan Road from Roat turks.         There is no passing lane on this porting the hill so passenger cars regularly ge behind large trucks.   | ing to<br>ment<br>ing to<br>ment<br>oor<br>oor<br>ing to<br>ment<br>oor<br>ing to<br>ing to   | South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>South of Brookville in Coder<br>Hollow. Turn is narrow. High<br>traffic area.<br>  |   |   |   |  
   
  |                                       |                                       |   |  |   |   |   |  |   |   |   |   |  
  |                                       |   |               |   |   |   |  |   
   
  |                                       |   |   |  |   |  | | | |
   |   |   |   |   |  |  |  |   |   |  
  |  |  |  |   |   
   |                                       |  |  |   |  |  
  |  |  |  
  |   |   |  |                                       |  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.998723       -79.31177         40.907007       -79.34296         41.136277       -79.14657         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.999114       -79.342962         40.999114       -79.343995         41.163374       -79.097537         41.163374       -79.097537         41.146843       -79.117534         40.818083       -79.489783         40.822073       -79.486718         40.849113       -79.459043  | 374405       point         374465       point         374466       point         374568       point         374570       point         374571       point         374572       point         374573       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374580       point         374590       point         374590       point         374590       point         374591       point         374592       point         374593       point         374594       point         374595       point         374591       point         374592       point         374593       point         374594       point         374595       point         374594       point         374595       point         374594       point         374617       point <td>2/10/2020       2/3136         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273187         2/11/2020       273189         2/11/2020       273196         2/11/2020       273196         2/11/2020       273196         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273231         2/11/2020       273311<td>South bound traffic is speeding. Very little site distance when entering<br/>28/66 from Dearville road. Have almost been hit many times when trying<br/>to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering<br/>28/66 from Dearville road. Have almost been hit many times when trying<br/>to enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with<br/>limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         The sharp curve coming into Goheenville from Distant.       X         Prook way that traffic flows fine and safe when you never encounter a<br/>truck from kittanning. The main problem is trucks. I drive this road<br/>atteast 20-30 times a month from Brookville to Kittanning and then some.<br/>I have noticed that traffic flows fine and safe when you never encounter a<br/>truck from kittanning to 180. If you do you face time delays for work<br/>meetings on halthcare. Or safety, most of these trucks are either going<br/>way to fast causing potential danger, or way to slow also causing danger.       X         est       No signage on Interstate 80 that directs people to Pittsburgh or<br/>Punxsutawney       X         X       X       X<!--</td--><td>x         x</td><td>x         <td< td=""><td></td><td></td><td>Image: second second</td><td>x     x       x     x       member of a member of a ment     x       x     x</td><td>x         <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: set of the set of the</td><td>x       x         x       x</td><td>X      </td><td>x      </td><td></td><td></td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prvisibility intersections         intense         intense curve with many accidents, prvisibility intersections         intense         intense         intense         intense         intense         intense         intense         intense         intense         <t< td=""><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing to<br/>ment<br/>or<br/>or<br/>ing to<br/>ing to</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></t<></td></td<></td></td<></td></td></td>  
   | 2/10/2020       2/3136         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273187         2/11/2020       273189         2/11/2020       273196         2/11/2020       273196         2/11/2020       273196         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273231         2/11/2020       273311 <td>South bound traffic is speeding. Very little site distance when entering<br/>28/66 from Dearville road. Have almost been hit many times when trying<br/>to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering<br/>28/66 from Dearville road. Have almost been hit many times when trying<br/>to enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with<br/>limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         The sharp curve coming into Goheenville from Distant.       X         Prook way that traffic flows fine and safe when you never encounter a<br/>truck from kittanning. The main problem is trucks. I drive this road<br/>atteast 20-30 times a month from Brookville to Kittanning and then some.<br/>I have noticed that traffic flows fine and safe when you never encounter a<br/>truck from kittanning to 180. If you do you face time delays for work<br/>meetings on halthcare. Or safety, most of these trucks are either going<br/>way to fast causing potential danger, or way to slow also causing danger.       X         est       No signage on Interstate 80 that directs people to Pittsburgh or<br/>Punxsutawney       X         X       X       X<!--</td--><td>x         x</td><td>x         <td< td=""><td></td><td></td><td>Image: second second</td><td>x     x       x     x       member of a member of a ment     x       x     x</td><td>x         <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: set of the set of the</td><td>x       x         x       x</td><td>X      </td><td>x      </td><td></td><td></td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prvisibility intersections         intense         intense curve with many accidents, prvisibility intersections         intense         intense         intense         intense         intense         intense         intense         intense         intense         <t< td=""><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing to<br/>ment<br/>or<br/>or<br/>ing to<br/>ing to</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></t<></td></td<></td></td<></td></td>  
  | South bound traffic is speeding. Very little site distance when entering<br>28/66 from Dearville road. Have almost been hit many times when trying<br>to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering<br>28/66 from Dearville road. Have almost been hit many times when trying<br>to enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         Local road that is at crest of hill. Very hard to pull across traffic here with<br>limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         The sharp curve coming into Goheenville from Distant.       X         Prook way that traffic flows fine and safe when you never encounter a<br>truck from kittanning. The main problem is trucks. I drive this road<br>atteast 20-30 times a month from Brookville to Kittanning and then some.<br>I have noticed that traffic flows fine and safe when you never encounter a<br>truck from kittanning to 180. If you do you face time delays for work<br>meetings on halthcare. Or safety, most of these trucks are either going<br>way to fast causing potential danger, or way to slow also causing danger.       X         est       No signage on Interstate 80 that directs people to Pittsburgh or<br>Punxsutawney       X         X       X       X </td <td>x         x</td> <td>x         <td< td=""><td></td><td></td><td>Image: second second</td><td>x     x       x     x       member of a member of a ment     x       x     x</td><td>x         <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: set of the set of the</td><td>x       x         x       x</td><td>X      </td><td>x      </td><td></td><td></td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prvisibility intersections         intense         intense curve with many accidents, prvisibility intersections         intense         intense         intense         intense         intense         intense         intense         intense         intense         <t< td=""><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing to<br/>ment<br/>or<br/>or<br/>ing to<br/>ing to</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></t<></td></td<></td></td<></td> | x           
   
   
   
   
   
  | x         x <td< td=""><td></td><td></td><td>Image: second second</td><td>x     x       x     x       member of a member of a ment     x       x     x</td><td>x         <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: set of the set of the</td><td>x       x         x       x</td><td>X      </td><td>x      </td><td></td><td></td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prvisibility intersections         intense         intense curve with many accidents, prvisibility intersections         intense         intense         intense         intense         intense         intense         intense         intense         intense         <t< td=""><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing to<br/>ment<br/>or<br/>or<br/>ing to<br/>ing to</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></t<></td></td<></td></td<>   |   |     | Image: second | x     x       x     x       member of a member of a ment     x       x     x   
   
   
   
   
   
  | x         x <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: set of the set of the</td><td>x       x         x       x</td><td>X      </td><td>x      </td><td></td><td></td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prvisibility intersections         intense         intense curve with many accidents, prvisibility intersections         intense         intense         intense         intense         intense         intense         intense         intense         intense         <t< td=""><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing to<br/>ment<br/>or<br/>or<br/>ing to<br/>ing to</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></t<></td></td<>  
   
   
   
   | Pedestrian safety  | Image: set of the | x       x           | X  
   
   
   
  | x  |   
   |   | K       I have been almost hit many times trenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 66. We also have farm equipentering the road also.         I have been almost hit many times trenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, prvisibility intersections         intense         intense curve with many accidents, prvisibility intersections         intense         intense         intense         intense         intense         intense         intense         intense         intense <t< td=""><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing to<br/>ment<br/>or<br/>or<br/>ing to<br/>ing to</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></t<> | ing to<br>ment<br>ing to<br>ment<br>ing to<br>ment<br>or<br>or<br>ing to<br>ing to  | South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I |   |   |   | | | | |
   |                                       |                                       |   |  |  
  |   |   |  |   |   |   |   |   |                                       |   |               |   
           |   |   |  |  
   |                                       |   |   |  |   |  |   
  |   |  
  |   |   |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  
   |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.458807         40.999723       -79.31177         40.999723       -79.31568         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.999114       -79.342962         40.999114       -79.342962         40.9981824       -79.097537         41.163374       -79.097537         41.163374       -79.097537         41.170411       -79.100301         40.818083       -79.489783         40.822073       -79.468292         40.835803       -79.468292         40.835803       -79.468292   | 374405       point         374465       point         374466       point         374466       point         374568       point         374568       point         374570       point         374571       point         374572       point         374573       point         374574       point         374575       point         374576       point         374577       point         374578       point         374580       point         374580       point         374580       point         374580       point         374580       point         374590       point         374591       point         374592       point         374593       point         374594       point         374595       point         374591       point         374592       point         374593       point         374594       point         374595       point         374594       point         374617       point <td>2/10/2020       2/3136         2/10/2020       2/3156         2/10/2020       2/3156         2/10/2020       2/3163         2/10/2020       2/3163         2/10/2020       2/3163         2/10/2020       2/3163         2/10/2020       2/3163         2/10/2020       2/3163         2/10/2020       2/3163         2/10/2020       2/3163         2/11/2020       2/3175         2/11/2020       2/3175         2/11/2020       2/3178         2/11/2020       2/3189         2/11/2020       2/3318         2/11/2020       2/3318         2/11/2020       2/3318         2/11/2020       2/3318         2/11/2020       2/33204         2/11/2020       2/32204         2/11/2020       2/32207         2/11/2020       2/32207         2/11/2020       2/32207         2/11/2020       2/32207         2/11/2020       2/3231         2/11/2020       2/3331         2/11/2020       2/33311         2/11/2020       2/33311         2/11/2020       2/33311         2/11/2020       2</td> <td>South bound traffic is speeding. Very little site distance when entering       28/66 from Dearville road. Have almost been hit many times when trying         to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering       28/66 from Dearville road. Have almost been hit many times when trying         28/66 from Dearville road. Have almost been hit many times when trying       X         28/66 from Dearville road. Have almost been hit many times when trying       X         28/66 from Dearville road. Have almost been hit many times when trying       X         or enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         coal road that is at crest of hill. Very hard to pull across traffic here with limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         From mainly New Bethlehem to Kittanning. However the real problem is Brookoil to Kittanning and then some.       N at traffic flows fire and safe when you never encounter a truck from Kittannit for BR. If you do you face time delays for work meetings or healthcare. Or safety, most of these trucks are either going eset way to fast causing potential danger, or way to slow</td> <td>x         x</td> <td>x x x x x x x x x x x x x x x x x x x</td> <td></td> <td></td> <td>Image: second second</td> <td>x     Important of a symmetry of</td> <td>x         <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: set of the set of the</td><td>x       x         x       x</td><td>x      </td><td></td><td></td><td></td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, pvisibility intersections         intense curve with many accidents, pvisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Limited sight distance for trangulary exeluct be lara tor the rest or passing lane</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing to<br/>ment<br/>ing to<br/>ing to</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></td<></td>  | 2/10/2020       2/3136         2/10/2020       2/3156         2/10/2020       2/3156         2/10/2020       2/3163         2/10/2020       2/3163         2/10/2020       2/3163         2/10/2020       2/3163         2/10/2020       2/3163         2/10/2020       2/3163         2/10/2020       2/3163         2/10/2020       2/3163         2/11/2020       2/3175         2/11/2020       2/3175         2/11/2020       2/3178         2/11/2020       2/3189         2/11/2020       2/3318         2/11/2020       2/3318         2/11/2020       2/3318         2/11/2020       2/3318         2/11/2020       2/33204         2/11/2020       2/32204         2/11/2020       2/32207         2/11/2020       2/32207         2/11/2020       2/32207         2/11/2020       2/32207         2/11/2020       2/3231         2/11/2020       2/3331         2/11/2020       2/33311         2/11/2020       2/33311         2/11/2020       2/33311         2/11/2020       2   
   
   | South bound traffic is speeding. Very little site distance when entering       28/66 from Dearville road. Have almost been hit many times when trying         to enter 28/66       X         South bound traffic is speeding. Very little site distance when entering       28/66 from Dearville road. Have almost been hit many times when trying         28/66 from Dearville road. Have almost been hit many times when trying       X         28/66 from Dearville road. Have almost been hit many times when trying       X         28/66 from Dearville road. Have almost been hit many times when trying       X         or enter 28/66       X         Too many motor vehicle accidents with limited acces for fire departments       X         dangerous curve       X         low visibility curve       X         poor sight on major intersection       X         bad curve       X         slow moving trucks going up hill       X         coal road that is at crest of hill. Very hard to pull across traffic here with limited view and time.       X         The sharp curve coming into Goheenville from Distant.       X         From mainly New Bethlehem to Kittanning. However the real problem is Brookoil to Kittanning and then some.       N at traffic flows fire and safe when you never encounter a truck from Kittannit for BR. If you do you face time delays for work meetings or healthcare. Or safety, most of these trucks are either going eset way to fast causing potential danger, or way to slow   
   
  | x          
   
   
   
   
   | x x x x x x x x x x x x x x x x x x x   
   
   |   |     | Image: second | x     Important of a symmetry of  
   
   
   
   
   | x         x <td< td=""><td>Pedestrian safety         Pedestrian safety</td><td>Image: set of the set of the</td><td>x       x         x       x</td><td>x      </td><td></td><td></td><td></td><td>K       I have been almost hit many times trenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, pvisibility intersections         intense curve with many accidents, pvisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Limited sight distance for trangulary exeluct be lara tor the rest or passing lane</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing to<br/>ment<br/>ing to<br/>ing to</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></td<>   
   
   
   
   
   | Pedestrian safety  | Image: set of the | x       x           | x  
   
   
   
  |  |   |   | K       I have been almost hit many times trenter 28 66. We also have farm equipenter 28 66. We also have farm equipenter 28 66. We also have farm equipentering the road also.         intense curve with many accidents, pvisibility intersections         intense curve with many accidents, pvisibility intersections         slow moving trucks going up hill and accessing progress st. No pedestrian lanes         K         Limited sight distance.         Limited sight distance for trangulary exeluct be lara tor the rest or passing lane  
   | ing to<br>ment<br>ing to<br>ment<br>ing to<br>ment<br>ing to<br>ing to  | South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I |   |   |   | | | | | | |
  |                                       |                                       |   |  |   |   |   |             
  |   |   |   |   |   |                                       |   |               |   |   |   |  
   |   
  |                                       |   |   |  |   |  | | | | |
   |   |   |   |   
   |  |  |  |   |   |   |  |  |  |   |   
   
   |                                       |  |  |   |  |  
  |  |  |   |   |   |  |                                       |  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.136277       -79.163718         41.040026       -79.257263         41.145777       -79.114011         40.998723       -79.391177         40.998723       -79.31177         40.999723       -79.34296         41.136277       -79.14657         40.99912       -79.34296         41.136277       -79.14657         40.99914       -79.342962         40.99914       -79.342962         40.99914       -79.342962         40.99914       -79.342962         40.99914       -79.342962         41.163374       -79.097537         41.163374       -79.117534         41.146843       -79.117534         41.146843       -79.489783         40.818083       -79.489783         40.842073       -79.468292         40.84211       -79.463836         40.84221       -79.463836         40.853257       -79.455182         40.867094       -79.434919 | 374405         point           374465         point           374466         point           374568         point           374569         point           374570         point           374571         point           374572         point           374573         point           374574         point           374575         point           374576         point           374577         point           374578         point           374579         point           374580         point           374591         point           374590         point           374590         point           374591         point           374592         point           374593         point           374594         point           374595         point           374591         point           374592         point           374593         point           374594         point           374595         point           374595         point           374595         point <td>2/10/2020       273136         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273178         2/11/2020       273189         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311<td>South bound Taffic is speeding. Very little site distance when entering         28/66 from Dearville road. Have almost been hit many times when trying         to enter 28/66         South bound traffic is speeding. Very little site distance when entering         28/66 from Dearville road. Have almost been hit many times when trying         to enter 28/66         Year         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve         poor sight on major intersection         bad curve         X         slow moving trucks going up hill         tocal road that is at crest of hill. Very hard to pull across traffic here with         Imited view and time.         The sharp curve coming into Goheenville from Distant.         Inthe sharp curve coming into Goheenville from Distant.         Prom mainly New Bethlehem to Kittanning, However the real problem is Brookville to Kittanning. The main problem is trucks. I drive this road atteast 20-30 times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and aske when you neve encounter a truck from kittanning to 180. If you do you face time delays for work meetings or healthcare. Or safety, most of these trucks are either going way to fast causing potential danger, or way to slow also causing danger.         set       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X         There</td><td>x         x       <td>x         <td< td=""><td></td><td></td><td>Image: second second</td><td>x     x       x     x       y     x       y     x       y     x       y     x       x<td></td><td><ul> <li>Antipact of the second s</li></ul></td><td>Image: set of the set of the</td><td>x       x         x       x</td><td>x      </td><td></td><td></td><td></td><td>K         I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           K           Limited sight distance.           K           Limited sight distance for tra<br/>south           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Ro<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this portit<br/>the hill so passenger cars reg</td><td>ing to ment ing to</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></td></td<></td></td></td>   
  | 2/10/2020       273136         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273163         2/11/2020       273175         2/11/2020       273178         2/11/2020       273178         2/11/2020       273189         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311 <td>South bound Taffic is speeding. Very little site distance when entering         28/66 from Dearville road. Have almost been hit many times when trying         to enter 28/66         South bound traffic is speeding. Very little site distance when entering         28/66 from Dearville road. Have almost been hit many times when trying         to enter 28/66         Year         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve         poor sight on major intersection         bad curve         X         slow moving trucks going up hill         tocal road that is at crest of hill. Very hard to pull across traffic here with         Imited view and time.         The sharp curve coming into Goheenville from Distant.         Inthe sharp curve coming into Goheenville from Distant.         Prom mainly New Bethlehem to Kittanning, However the real problem is Brookville to Kittanning. The main problem is trucks. I drive this road atteast 20-30 times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and aske when you neve encounter a truck from kittanning to 180. If you do you face time delays for work meetings or healthcare. Or safety, most of these trucks are either going way to fast causing potential danger, or way to slow also causing danger.         set       Route 28 between the areas of Airport Road Ext. and Cemetery Road.       X         There</td> <td>x         x       <td>x         <td< td=""><td></td><td></td><td>Image: second second</td><td>x     x       x     x       y     x       y     x       y     x       y     x       x<td></td><td><ul> <li>Antipact of the second s</li></ul></td><td>Image: set of the set of the</td><td>x       x         x       x</td><td>x      </td><td></td><td></td><td></td><td>K         I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           K           Limited sight distance.           K           Limited sight distance for tra<br/>south           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Ro<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this portit<br/>the hill so passenger cars reg</td><td>ing to ment ing to</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></td></td<></td></td>  | South bound Taffic is speeding. Very little site distance when entering         28/66 from Dearville road. Have almost been hit many times when trying         to enter 28/66         South bound traffic is speeding. Very little site distance when entering         28/66 from Dearville road. Have almost been hit many times when trying         to enter 28/66         Year         Too many motor vehicle accidents with limited acces for fire departments         dangerous curve         low visibility curve         poor sight on major intersection         bad curve         X         slow moving trucks going up hill         tocal road that is at crest of hill. Very hard to pull across traffic here with         Imited view and time.         The sharp curve coming into Goheenville from Distant.         Inthe sharp curve coming into Goheenville from Distant.         Prom mainly New Bethlehem to Kittanning, However the real problem is Brookville to Kittanning. The main problem is trucks. I drive this road atteast 20-30 times a month from Brookville to Kittanning and then some. I have noticed that traffic flows fine and aske when you neve encounter a truck from kittanning to 180. If you do you face time delays for work meetings or healthcare. Or safety, most of these trucks are either going way to fast causing potential danger, or way to slow also causing danger.         set       Route 28 between the areas of Airport Road Ext. and Cemetery Road.      
X         There  
   | x         x <td>x         <td< td=""><td></td><td></td><td>Image: second second</td><td>x     x       x     x       y     x       y     x       y     x       y     x       x<td></td><td><ul> <li>Antipact of the second s</li></ul></td><td>Image: set of the set of the</td><td>x       x         x       x</td><td>x      </td><td></td><td></td><td></td><td>K         I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           K           Limited sight distance.           K           Limited sight distance for tra<br/>south           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Ro<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this portit<br/>the hill so passenger cars reg</td><td>ing to ment ing to</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></td></td<></td>   
   
   
   
   | x     
   x         x <td< td=""><td></td><td></td><td>Image: second second</td><td>x     x       x     x       y     x       y     x       y     x       y     x       x<td></td><td><ul> <li>Antipact of the second s</li></ul></td><td>Image: set of the set of the</td><td>x       x         x       x</td><td>x      </td><td></td><td></td><td></td><td>K         I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           K           Limited sight distance.           K           Limited sight distance for tra<br/>south           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Ro<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this portit<br/>the hill so passenger cars reg</td><td>ing to ment ing to</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></td></td<> |   |     | Image: second | x     x       x     x       y     x       y     x       y     x       y     x       x <td></td> <td><ul> <li>Antipact of the second s</li></ul></td> <td>Image: set of the set of the</td> <td>x       x         x       x</td> <td>x      </td> <td></td> <td></td> <td></td> <td>K         I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           K           Limited sight distance.           K           Limited sight distance for tra<br/>south           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Ro<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this portit<br/>the hill so passenger cars reg</td> <td>ing to ment ing to</td> <td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td>   
   
   
   
  |  
   
   
   
   
   
  | <ul> <li>Antipact of the second s</li></ul> | Image: set of the | x       x           | x  
   
   
   
  |  |   |   | K         I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.           I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.           intense curve with many accidents, p<br>visibility intersections           slow moving trucks going up hill and<br>accessing progress st. No pedestrian<br>lanes           K           Limited sight distance.           K           Limited sight distance for tra<br>south           Limited sight distance for tra<br>pulling out of Sloan Hill Road onto Ro<br>as well as for cars turning onto Sloan<br>Road from Route 28.           There is no passing lane on this portit<br>the hill so passenger cars reg  
   | ing to ment ing to  | South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I |   |   |   | | | | | | | |
  |                                       |                                       |   |  |   
   |   |   |  |   |   |   |   |   |                                       |   |               |   |  
  |   |  |   
  |                                       |   |   |  |   |  |  
   |   |   |   
   |   |  |  |  |   |   |   |  |  |  |   |   
   
   |                                       |  |  |   |  |  
  |  |  |   |   |   |  |                                       |  |  |   
  |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.162984       -79.096911         40.998723       -79.31177         40.998723       -79.31177         40.999723       -79.34296         41.136277       -79.14657         41.136277       -79.34296         41.136277       -79.342962         40.999114       -79.342962         40.999114       -79.342962         41.163374       -79.097537         41.163374       -79.097537         41.16843       -79.117534         41.170411       -79.100301         40.849113       -79.459043         40.849113       -79.459043         40.849113       -79.459043         40.849113       -79.459043         40.849113       -79.459043         40.849113       -79.455182         40.867094       -79.434919  | 374405       point         374465       point         374466       point         374568       point         374569       point         374571       point         374572       point         374573       point         374574       point         374575       point         374576       point         374577       point         374578       point         374579       point         374580       point         374580       point         374590       point         374590       point         374591       point         374592       point         374593       point         374594       point         374595       point         374591       point         374592       point         374593       point         374594       point         374595       point         374591       point         374592       point         374593       point         374594       point         374617       point <td><ul> <li>2/10/2020</li> <li>2/3136</li> <li>2/10/2020</li> <li>2/3156</li> <li>2/10/2020</li> <li>2/3163</li> <li>2/11/2020</li> <li>2/3175</li> <li>2/11/2020</li> <li>2/3189</li> <li>2/11/2020</li> <li>2/3310</li> <li>3/3</li> <li>3/3</li> <li>2/11/2020</li> <li>2/3207</li> <li>3/4</li> <li>3/4<td>South bound tartic is speeding. Very little site distance when entering<br/>28/66 from Deanville road. Have almost been hit many times when trying<br/>to enter 28/66         X           South bound tartific is speeding. Very little site distance when entering<br/>28/66 from Deanville road. Have almost been hit many times when trying<br/>to enter 28/66         X           Too many motor vehicle accidents with limited acces for fire departments         X           dangerous curve         X           tow risbility curve         X           poor sight on major intersection         X           bad curve         X           slow moving trucks going up hill         X           Local road that is at crest of hill. Very hard to pull across traffic here with<br/>limited view and time.         X           The sharp curve coming into Goheenville from Distant.         X           From mainly New Bethlehem to Kittanning. However the real problem is<br/>Brookville to Kittanning. The main problem is trucks. I drive this road<br/>atleast 20-30 times a month from Brookille to Kittanning and then some<br/>i have noticed that traffic flows fine and safe when you never encounter a<br/>truck from Kittanning to LI 'you do you face ture delays for work<br/>meetings or healthcare. Or safety, most of these trucks are either going<br/>way to fast causing potential danger, or way to slow also causing danger.         X           est         Route 28 between the areas of Airport Road Ext. and Cemetery Road.         X           There is in passing lane on this portion of the hill.         X         X</td><td>x           x</td><td>x x x x x x x x x x x x x x x x x x x</td><td></td><td></td><td>Image: second second</td><td>x     x       x     x       y     x       y     x       y     x       x     x  </td><td>x         <td< td=""><td>Image: Constraint set of the set of</td><td>Image: set of the set of the</td><td>x       x         x       x</td><td><math>\times</math> <math> \cdot</math> <math>\cdot</math> <math>\cdot</math></td><td></td><td></td><td></td><td>K         I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           Limited sight distance.           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Ro<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this portit<br/>the hill so passenger cars regularly get stuck bel<br/>large trucks.           There is no passing lane on this hill at<br/>passenger cars regularly get stuck</td><td>ing to<br/>ment ing to<br/>ment ing to ment ing to</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></td<></td></li></ul></td> | <ul> <li>2/10/2020</li> <li>2/3136</li> <li>2/10/2020</li> <li>2/3156</li> <li>2/10/2020</li> <li>2/3163</li> <li>2/11/2020</li> <li>2/3175</li> <li>2/11/2020</li> <li>2/3189</li> <li>2/11/2020</li> <li>2/3310</li> <li>3/3</li> <li>3/3</li> <li>2/11/2020</li> <li>2/3207</li> <li>3/4</li> <li>3/4<td>South bound tartic is speeding. Very little site distance when entering<br/>28/66 from Deanville road. Have almost been hit many times when trying<br/>to enter 28/66         X           South bound tartific is speeding. Very little site distance when entering<br/>28/66 from Deanville road. Have almost been hit many times when trying<br/>to enter 28/66         X           Too many motor vehicle accidents with limited acces for fire departments         X           dangerous curve         X           tow risbility curve         X           poor sight on major intersection         X           bad curve         X           slow moving trucks going up hill         X           Local road that is at crest of hill. Very hard to pull across traffic here with<br/>limited view and time.         X           The sharp curve coming into Goheenville from Distant.         X           From mainly New Bethlehem to Kittanning. However the real problem is<br/>Brookville to Kittanning. The main problem is trucks. I drive this road<br/>atleast 20-30 times a month from Brookille to Kittanning and then some<br/>i have noticed that traffic flows fine and safe when you never encounter a<br/>truck from Kittanning to LI 'you do you face ture delays for work<br/>meetings or healthcare. Or safety, most of these trucks are either going<br/>way to fast causing potential danger, or way to slow also causing danger.         X           est         Route 28 between the areas of Airport Road Ext. and Cemetery Road.         X           There is in passing lane on this portion of the hill.         X         X</td><td>x           x  
        x           x</td><td>x x x x x x x x x x x x x x x x x x x</td><td></td><td></td><td>Image: second second</td><td>x     x       x     x       y     x       y     x       y     x       x     x  </td><td>x         <td< td=""><td>Image: Constraint set of the set of</td><td>Image: set of the set of the</td><td>x       x         x       x</td><td><math>\times</math> <math> \cdot</math> <math>\cdot</math> <math>\cdot</math></td><td></td><td></td><td></td><td>K         I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           Limited sight distance.           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Ro<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this portit<br/>the hill so passenger cars regularly get stuck bel<br/>large trucks.           There is no passing lane on this hill at<br/>passenger cars regularly get stuck</td><td>ing to<br/>ment ing to<br/>ment ing to ment ing to</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></td<></td></li></ul> | South bound tartic is speeding. Very little site distance when entering<br>28/66 from Deanville road. Have almost been hit many times when trying<br>to enter 28/66         X           South bound tartific is speeding. Very little site distance when entering<br>28/66 from Deanville road. Have almost been hit many times when trying<br>to enter 28/66         X           Too many motor vehicle accidents with limited acces for fire departments         X           dangerous curve         X           tow risbility curve         X           poor sight on major intersection         X           bad curve         X           slow moving trucks going up hill         X           Local road that is at crest of hill. Very hard to pull across traffic here with<br>limited view and time.         X           The sharp curve coming into Goheenville from Distant.         X           From mainly New Bethlehem to Kittanning. However the real problem is<br>Brookville to Kittanning. The main problem is trucks. I drive this road<br>atleast 20-30 times a month from Brookille to Kittanning and then some<br>i have noticed that traffic flows fine and safe when you never encounter a<br>truck from Kittanning to LI 'you do you face ture delays for work<br>meetings or healthcare. Or safety, most of these trucks are either going<br>way to fast causing potential danger, or way to slow also causing danger.         X           est         Route 28 between the areas of Airport Road Ext. and Cemetery Road.         X           There is in passing lane on this portion of the hill.         X         X  
   | x             
   
   
   
   
   
  | x x x x x x x x x x x x x x x x x x x  
  |   |     | Image: second | x     x       x     x       y     x       y     x       y     x       x     x  
   
   
   
   
   
  | x         x <td< td=""><td>Image: Constraint set of the set of</td><td>Image: set of the set of the</td><td>x       x         x       x</td><td><math>\times</math> <math> \cdot</math> <math>\cdot</math> <math>\cdot</math></td><td></td><td></td><td></td><td>K         I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           Limited sight distance.           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Ro<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this portit<br/>the hill so passenger cars regularly get stuck bel<br/>large trucks.           There is no passing lane on this hill at<br/>passenger cars regularly get stuck</td><td>ing to<br/>ment ing to<br/>ment ing to ment ing to</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></td<>  
   
   
   
   | Image: Constraint set of the set of                                      | Image: set of the | x       x           | $\times$ $ \cdot$ $\cdot$  
   
   
   
  |  |   |   | K         I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.           I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.           intense curve with many accidents, p<br>visibility intersections           slow moving trucks going up hill and<br>accessing progress st. No pedestrian<br>lanes           Limited sight distance.           Limited sight distance for tra<br>pulling out of Sloan Hill Road onto Ro<br>as well as for cars turning onto Sloan<br>Road from Route 28.           There is no passing lane on this portit<br>the hill so passenger cars regularly get stuck bel<br>large trucks.           There is no passing lane on this hill at<br>passenger cars regularly get stuck  
   | ing to<br>ment ing to<br>ment ing to ment ing to  | South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I |   |   |   |  
   
  |                                       |                                       |   |  |   |   |   |  |   |   |   |   |  
  |                                       |   |               |   |   |   |  |   
  |                                       |   |  
  |  |   |  |  
   |   |   |   |   |  |  |  |   |   |   |  |  |  
   |   |   
   |                                       |  |  |   |  | | |
  |  |  |   |   |   |  |                                       |   
  |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         41.162984       -79.096911         40.849189       -79.371568         40.998723       -79.31177         40.907007       -79.371568         40.99912       -79.34296         41.136277       -79.14657         40.99912       -79.342962         41.136277       -79.14657         40.99914       -79.342962         41.163374       -79.097537         41.163374       -79.097537         41.146843       -79.117534         41.146843       -79.117534         41.170411       -79.400301         40.849113       -79.459043         40.849113       -79.459043         40.849113       -79.459043         40.853257       -79.455182         40.867094       -79.455182         40.867094       -79.434919                              | 374465         point           374466         point           374466         point           374568         point           374569         point           374571         point           374572         point           374573         point           374574         point           374575         point           374576         point           374577         point           374578         point           374579         point           374580         point           374580         point           374580         point           374580         point           374580         point           374580         point           374590         point           374590         point           374591         point           374592         point           374593         point           374594         point           374595         point           374595         point           374595         point           374617         point           374618         point <td>2/10/2020       273136         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273163         2/11/2020       273176         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311<td>South bound Torffic is speeding. Very little site distance when entering<br/>28/66 from Deamille road. Have almost been hit many times when trying<br/>to enter 28/66         X           South bound traffic is speeding. Very little site distance when entering<br/>28/66 from Deamille road. Have almost been hit many times when trying<br/>to enter 28/66         X           Too many motor vehicle accidents with limited acces for fire departments         X           dangerous curve         X           jow sight on major intersection         X           bad curve         X           slow moving trucks going up hill         X           Local road that is a trees of hill. Very hard to pull across traffic here with<br/>limited wand time.         X           The sharp curve coming into Goheenville from Distant.         X           From mainly New Bethelhem to Kittanning, However the real problem is<br/>Brookville to Kittanning. The main problem is trucks. I drive this road<br/>ateast 20.30 times a month from Brookville to Kittanning and then some.<br/>I have notice that traffic flows frane das das trucks. I drive this road<br/>ateast 20.30 times a month from Brookville to Kittanning and then some.<br/>I have notice that traffic flows frane das das trucks. I drive this road<br/>ateast 20.30 times at most problem is trucks. I drive this road<br/>ateast 20.30 times to ateast the dispect or work<br/>meetings or heathcr.ce. Or starky, most of thes trucks are etter going<br/>way to fast causing potential danger, or way to slow also causing danger.           est         Route 28 between the areas of Airport Road Ext. and Cemetery Road.         X           There is no passing lane on</td><td>x         <td< td=""><td>x x x x x x x x x x x x x x x x x x x</td><td></td><td></td><td>Image: second second</td><td>x     i       x     i       im Brookville on<br/>uurgh. Also<br/>s a member of a<br/>ment     x       x     i       x</td><td></td><td>Image: Constraint of the second se</td><td>Image: set of the set of the</td><td>x       x         x</td><td>×       -         ×       ×         ×</td><td></td><td></td><td></td><td>K         I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           Limited sight distance.           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Ro<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this hill at<br/>passenger cars regularly get stuck bel<br/>large trucks.           There is no passing lane on this hill at<br/>passenger cars regularly get stuck bel<br/>large trucks.           There is limited</td><td>ing to<br/>ment<br/>ing t</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></td<></td></td>  | 2/10/2020       273136         2/10/2020       273156         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273163         2/11/2020       273176         2/11/2020       273178         2/11/2020       273189         2/11/2020       273189         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311         2/11/2020
      273311 <td>South bound Torffic is speeding. Very little site distance when entering<br/>28/66 from Deamille road. Have almost been hit many times when trying<br/>to enter 28/66         X           South bound traffic is speeding. Very little site distance when entering<br/>28/66 from Deamille road. Have almost been hit many times when trying<br/>to enter 28/66         X           Too many motor vehicle accidents with limited acces for fire departments         X           dangerous curve         X           jow sight on major intersection         X           bad curve         X           slow moving trucks going up hill         X           Local road that is a trees of hill. Very hard to pull across traffic here with<br/>limited wand time.         X           The sharp curve coming into Goheenville from Distant.         X           From mainly New Bethelhem to Kittanning, However the real problem is<br/>Brookville to Kittanning. The main problem is trucks. I drive this road<br/>ateast 20.30 times a month from Brookville to Kittanning and then some.<br/>I have notice that traffic flows frane das das trucks. I drive this road<br/>ateast 20.30 times a month from Brookville to Kittanning and then some.<br/>I have notice that traffic flows frane das das trucks. I drive this road<br/>ateast 20.30 times at most problem is trucks. I drive this road<br/>ateast 20.30 times to ateast the dispect or work<br/>meetings or heathcr.ce. Or starky, most of thes trucks are etter going<br/>way to fast causing potential danger, or way to slow also causing danger.           est         Route 28 between the areas of Airport Road Ext. and Cemetery Road.         X           There is no passing lane on</td> <td>x         <td< td=""><td>x x x x x x x x x x x x x x x x x x x</td><td></td><td></td><td>Image: second second</td><td>x     i       x     i       im Brookville on<br/>uurgh. Also<br/>s a member of a<br/>ment     x       x     i       x</td><td></td><td>Image: Constraint of the second se</td><td>Image: set of the set of the</td><td>x       x         x</td><td>×       -         ×       ×         ×</td><td></td><td></td><td></td><td>K         I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           Limited sight distance.           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Ro<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this hill at<br/>passenger cars regularly get stuck bel<br/>large trucks.           There is no passing lane on this hill at<br/>passenger cars regularly get stuck bel<br/>large trucks.           There is limited</td><td>ing to<br/>ment<br/>ing t</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></td<></td>  | South bound Torffic is speeding. Very little site distance when entering<br>28/66 from Deamille road. Have almost been hit many times when trying<br>to enter 28/66         X           South bound traffic is speeding. Very little site distance when entering<br>28/66 from Deamille road. Have almost been hit many times when trying<br>to enter 28/66         X           Too many motor vehicle accidents with limited acces for fire departments         X           dangerous curve         X           jow sight on major intersection         X           bad curve         X           slow moving trucks going up hill         X           Local road that is a trees of hill. Very hard to pull across traffic here with<br>limited wand time.         X           The sharp curve coming into Goheenville from Distant.         X           From mainly New Bethelhem to Kittanning, However the real problem is<br>Brookville to Kittanning. The main problem is trucks. I drive this road<br>ateast 20.30 times a month from Brookville to Kittanning and then some.<br>I have notice that traffic flows frane das das trucks. I drive this road<br>ateast 20.30 times a month from Brookville to Kittanning and then some.<br>I have notice that traffic flows frane das das trucks. I drive this road<br>ateast 20.30 times at most problem is trucks. I drive this road<br>ateast 20.30 times to ateast the dispect or work<br>meetings or heathcr.ce. Or starky, most of thes trucks are etter going<br>way to fast causing potential danger, or way to slow also causing danger.           est         Route 28 between the areas of Airport Road Ext. and Cemetery Road.         X           There is no passing lane on  
   
   | x         x <td< td=""><td>x x x x x x x x x x x x x x x x x x x</td><td></td><td></td><td>Image: second second</td><td>x     i       x     i       im Brookville on<br/>uurgh. Also<br/>s a member of a<br/>ment     x       x     i       x</td><td></td><td>Image: Constraint of the second se</td><td>Image: set of the set of the</td><td>x       x         x</td><td>×       -         ×       ×         ×</td><td></td><td></td><td></td><td>K         I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           Limited sight distance.           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Ro<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this hill at<br/>passenger cars regularly get stuck bel<br/>large trucks.           There is no passing lane on this hill at<br/>passenger cars regularly get stuck bel<br/>large trucks.           There is limited</td><td>ing to<br/>ment<br/>ing t</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I</td></td<>   
   
   
   
   | x x x x x x x x x x x x x x x x x x x   
   |   
   |     | Image: second | x     i       x     i       im Brookville on<br>uurgh. Also<br>s a member of a<br>ment     x       x     i       x  
   
   
   
   
   |   
   
   
   
   
   | Image: Constraint of the second se                                      | Image: set of the | x       x         x | ×       -         ×       ×         ×   
   
   
   
   |  |   |  
  | K         I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.           I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.           intense curve with many accidents, p<br>visibility intersections           slow moving trucks going up hill and<br>accessing progress st. No pedestrian<br>lanes           Limited sight distance.           Limited sight distance for tra<br>pulling out of Sloan Hill Road onto Ro<br>as well as for cars turning onto Sloan<br>Road from Route 28.           There is no passing lane on this hill at<br>passenger cars regularly get stuck bel<br>large trucks.           There is no passing lane on this hill at<br>passenger cars regularly get stuck bel<br>large trucks.           There is limited   | ing to<br>ment<br>ing t | South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High         traffic area.         Image: I |   |   |   |   
   
   |                                       |                                       |   |  |   |   |   |  |   |   |   |   |   
   |                                       |   |               |   |   |   |  |  
   |                                       |   
   |   |  |   |  | | | | | | |
  |   |   |   |   |  |  |  |   |   |   |   
  |  |  |   |  
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  
   |  |  |
| 40.938323       -79.363578         40.938323       -79.363578         41.134006       -79.152286         41.136277       -79.14657         41.127248       -79.163718         41.040026       -79.257263         41.145777       -79.114011         40.998723       -79.31177         40.999723       -79.31177         40.999723       -79.314657         41.136277       -79.14657         40.99912       -79.342962         41.136277       -79.14657         40.99914       -79.342962         40.999144       -79.342962         40.9981824       -79.343995         41.163374       -79.9097537         41.163374       -79.117534         41.146843       -79.117534         40.82073       -79.486718         40.849113       -79.486718         40.849113       -79.468292         40.8421       -79.463836         40.853257       -79.455182         40.867094       -79.434919         40.867025       -79.434919         40.867024       -79.433097                              | 374465       point         374466       point         374466       point         374568       point         374569       point         374571       point         374575       point         374576       point         374577       point         374578       point         374579       point         374579       point         374580       point         374590       point         374590       point         374590       point         374590       point         374591       point         374592       point         374593       point         374594       point         374595       point         374596       point         374597       point         374598       point         374599       point         374590       point         374591       point         374592       point         374593       point         374617       point         374618       point         374620       point <td>2/10/2020       273130         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273163         2/11/2020       273176         2/11/2020       273178         2/11/2020       273178         2/11/2020       273189         2/11/2020       273106         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311<td>South bound Torffic is speeding. Very little site distance when entering<br/>28/66 from Dearville road. Have almost been hit many times when trying<br/>to enter 28/66         X           South bound traffic is speeding. Very little site distance when entering<br/>28/66 from Dearville road. Have almost been hit many times when trying<br/>to enter 28/66         X           Too many motor vehicle accidents with limited acces for fire departments         X           dangerous curve         X           low visibility curve         X           slow moving trucks going up hill         X           local road that is a crest of hill. Very hard to pull across traffic here with<br/>limited view and time.         X           The sharp curve coming into Goheenville from Distant.         X           The sharp curve coming into Goheenville from Distant.         X           From mainly New Bethlehem to Kittanning. However the real problem is<br/>Brookville to Kittanning. The main problem is trucks. I drive this road<br/>aluest 20 30 times a month from Brookville to Kittanning and then some.<br/>I have noted that traffic lows fine and safe when you a vere concounter a<br/>truck from kittanning. The main problem is trucks. I drive this road<br/>aluest 20 30 times a month from Brookville to Kittanning and then some.<br/>I have noted that traffic lows fine and safe there you nger<br/>set way to fast causing potential danger, or way to slow also causing danger.         X           set         Route 28 between the areas of Airport Road Ext, and Cemetery Road.         X           There is no passing lane on this hill.         X         X</td><td>x         x       <td></td><td></td><td></td><td>Image: second second second from my ways to Pittsburg       Image: second second second second second from my ways to Pittsburg       Image: second sec</td><td>x     instant       x     instant    <t< td=""><td>x         <td< td=""><td>Image: Constraint set of the set of</td><td>.       X         .</td><td></td><td>x <math>x</math> <math>x</math></td><td>x      </td><td></td><td></td><td>I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           Limited sight distance.           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Re<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this portit<br/>the hill so passenger cars regularly get stuck bel<br/>large trucks.           There is no passing lane on this hi</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing<br/>ing to<br/>ment<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Image: South of Pittsburgh the speed limit signs need to be adjusted to more reasonable speeds. Some could be raised a bit and other through this certain towns could be lowered.         Image: Trucks are the only thing that has ever been a problem while using the corridor from 180 to Kittanning.         Image: Image:</td></td<></td></t<></td></td></td>  
   | 2/10/2020       273130         2/10/2020       273156         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/10/2020       273163         2/11/2020       273163         2/11/2020       273176         2/11/2020       273178         2/11/2020       273178         2/11/2020       273189         2/11/2020       273106         2/11/2020       273204         2/11/2020       273204         2/11/2020       273207         2/11/2020       273207         2/11/2020       273207         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273210         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311         2/11/2020       273311 <td>South bound Torffic is speeding. Very little site distance when entering<br/>28/66 from Dearville road. Have almost been hit many times when trying<br/>to enter 28/66         X           South bound traffic is speeding. Very little site distance when entering<br/>28/66 from Dearville road. Have almost been hit many times when trying<br/>to enter 28/66         X           Too many motor vehicle accidents with limited acces for fire departments         X           dangerous curve         X           low visibility curve         X           slow moving trucks going up hill         X           local road that is a crest of hill. Very hard to pull across traffic here with<br/>limited view and time.         X           The sharp curve coming into Goheenville from Distant.         X           The sharp curve coming into Goheenville from Distant.         X           From mainly New Bethlehem to Kittanning. However the real problem is<br/>Brookville to Kittanning. The main problem is trucks. I drive this road<br/>aluest 20 30 times a month from Brookville to Kittanning and then some.<br/>I have noted that traffic lows fine and safe when you a vere concounter a<br/>truck from kittanning. The main problem is trucks. I drive this road<br/>aluest 20 30 times a month from Brookville to Kittanning and then some.<br/>I have noted that traffic lows fine and safe there you nger<br/>set way to fast causing potential danger, or way to slow also causing danger.         X           set         Route 28 between the areas of Airport Road Ext, and Cemetery Road.         X           There is no passing lane on this hill.         X         X</td> <td>x         x       <td></td><td></td><td></td><td>Image: second second second from my ways to Pittsburg       Image: second second second second second from my ways to Pittsburg       Image: second sec</td><td>x     instant       x     instant    <t< td=""><td>x         <td< td=""><td>Image: Constraint set of the set of</td><td>.       X         .</td><td></td><td>x <math>x</math> <math>x</math></td><td>x      </td><td></td><td></td><td>I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           Limited sight distance.           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Re<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this portit<br/>the hill so passenger cars regularly get stuck bel<br/>large trucks.           There is no passing lane on this hi</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing<br/>ing to<br/>ment<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Image: South of Pittsburgh the speed limit signs need to be adjusted to more reasonable speeds. Some could be raised a bit and other through this certain towns could be lowered.         Image: Trucks are the only thing that has ever been a problem while using the corridor from 180 to Kittanning.         Image: Image:</td></td<></td></t<></td></td>   
  | South bound Torffic is speeding. Very little site distance when entering<br>28/66 from Dearville road. Have almost been hit many times when trying<br>to enter 28/66         X           South bound traffic is speeding. Very little site distance when entering<br>28/66 from Dearville road. Have almost been hit many times when trying<br>to enter 28/66         X           Too many motor vehicle accidents with limited acces for fire departments         X           dangerous curve         X           low visibility curve         X           slow moving trucks going up hill         X           local road that is a crest of hill. Very hard to pull across traffic here with<br>limited view and time.         X           The sharp curve coming into Goheenville from Distant.         X           The sharp curve coming into Goheenville from Distant.         X           From mainly New Bethlehem to Kittanning. However the real problem is<br>Brookville to Kittanning. The main problem is trucks. I drive this road<br>aluest 20 30 times a month from Brookville to Kittanning and then some.<br>I have noted that traffic lows fine and safe when you a vere concounter a<br>truck from kittanning. The main problem is trucks. I drive this road<br>aluest 20 30 times a month from Brookville to Kittanning and then some.<br>I have noted that traffic lows fine and safe there you nger<br>set way to fast causing potential danger, or way to slow also causing danger.         X           set         Route 28 between the areas of Airport Road Ext, and Cemetery Road.         X           There is no passing lane on this hill.         X         X   
   | x         x <td></td> <td></td> <td></td> <td>Image: second second second from my ways to Pittsburg       Image: second second second second second from my ways to Pittsburg       Image: second sec</td> <td>x     instant       x     instant    <t< td=""><td>x         x   
     x         <td< td=""><td>Image: Constraint set of the set of</td><td>.       X         .</td><td></td><td>x <math>x</math> <math>x</math></td><td>x      </td><td></td><td></td><td>I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           Limited sight distance.           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Re<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this portit<br/>the hill so passenger cars regularly get stuck bel<br/>large trucks.           There is no passing lane on this hi</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing<br/>ing to<br/>ment<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Image: South of Pittsburgh the speed limit signs need to be adjusted to more reasonable speeds. Some could be raised a bit and other through this certain towns could be lowered.         Image: Trucks are the only thing that has ever been a problem while using the corridor from 180 to Kittanning.         Image: Image:</td></td<></td></t<></td>   
   
   
   
  |  
   
  |   |     | Image: second second second from my ways to Pittsburg       Image: second second second second second from my ways to Pittsburg       Image: second sec   | x     instant       x     instant <t< td=""><td>x         <td< td=""><td>Image: Constraint set of the set of</td><td>.       X         .</td><td></td><td>x <math>x</math> <math>x</math></td><td>x      </td><td></td><td></td><td>I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           Limited sight distance.           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Re<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this portit<br/>the hill so passenger cars regularly get stuck bel<br/>large trucks.           There is no passing lane on this hi</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing<br/>ing to<br/>ment<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Image: South of Pittsburgh the speed limit signs need to be adjusted to more reasonable speeds. Some could be raised a bit and other through this certain towns could be lowered.         Image: Trucks are the only thing that has ever been a problem while using the corridor from 180 to Kittanning.         Image: Image:</td></td<></td></t<>   
   
   
   
   
  | x         x <td< td=""><td>Image: Constraint set of the set of</td><td>.       X         .</td><td></td><td>x <math>x</math> <math>x</math></td><td>x      </td><td></td><td></td><td>I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           I have been almost hit many times tr<br/>enter 28 66. We also have farm equip<br/>entering the road also.           intense curve with many accidents, p<br/>visibility intersections           slow moving trucks going up hill and<br/>accessing progress st. No pedestrian<br/>lanes           Limited sight distance.           Limited sight distance for tra<br/>pulling out of Sloan Hill Road onto Re<br/>as well as for cars turning onto Sloan<br/>Road from Route 28.           There is no passing lane on this portit<br/>the hill so passenger cars regularly get stuck bel<br/>large trucks.           There is no passing lane on this hi</td><td>ing to<br/>ment<br/>ing to<br/>ment<br/>ing<br/>ing to<br/>ment<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing<br/>ing</td><td>South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Image: South of Pittsburgh the speed limit signs need to be adjusted to more reasonable speeds. Some could be raised a bit and other through this certain towns could be lowered.         Image: Trucks are the only thing that has ever been a problem while using the corridor from 180 to Kittanning.         Image: Image:</td></td<>   
   
   
   
  | Image: Constraint set of the set of                                      | .       X         .   
                                      |   | x $x$  
   
   
  | x  
   |   |   | I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.           I have been almost hit many times tr<br>enter 28 66. We also have farm equip<br>entering the road also.           intense curve with many accidents, p<br>visibility intersections           slow moving trucks going up hill and<br>accessing progress st. No pedestrian<br>lanes           Limited sight distance.           Limited sight distance for tra<br>pulling out of Sloan Hill Road onto Re<br>as well as for cars turning onto Sloan<br>Road from Route 28.           There is no passing lane on this portit<br>the hill so passenger cars regularly get stuck bel<br>large trucks.           There is no passing lane on this hi   | ing to<br>ment<br>ing to<br>ment<br>ing<br>ing to<br>ment<br>ing<br>ing<br>ing<br>ing<br>ing<br>ing<br>ing<br>ing<br>ing<br>ing   
  | South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Hollow. Turn is narrow. High traffic area.         Image: South of Brookville in Coder         Image: South of Pittsburgh the speed limit signs need to be adjusted to more reasonable speeds. Some could be raised a bit and other through this certain towns could be lowered.         Image: Trucks are the only thing that has ever been a problem while using the corridor from 180 to Kittanning.         Image:   |   |   |   | | | | | | | | |
   |                                       |                                       |   |  |  
  |   |   |  |   |   |   |   |   |                                       |   |               |   |   
   |   |  |  
   |                                       |   |   |  |   |  |   
  |   |   |  
  |   |  |  |  |   |   |   |  |  |  |   |  
   
  |                                       |  |  |   |  |   
   |  |  |   |   |   |  |                                       |  |  |  |

40 877528 -79 39512	374625 point	2/12/2020 273311	Now that this section of the road has been improved, I find myself			This dip is now very easy to speed through as a result of the improvements that were made in the past few years
40.885947 -79.3901	374626 point	2/12/2020 273311	There is no passing lane on this hill.     X     X       There is limited sight distance for people entering and existing Pebinson's     Image: Control of the speed minit.     Image: Control of the speed minit.	A     A     A       X     X		X     There is limited sight distance for vehicles       Image in the past few years.
40.887975 -79.387592	374627 point	2/12/2020 273311	Greenhouse.     X     X	x x	x x x	X     Greenhouse.       This section of the road features a rather
						is quite narrow in this area with limited sight distance. I always worry that an oncoming
40.907109 -79.371125 40.924298 -79.361618	374628 point 374629 point	2/12/2020 273311 2/12/2020 273311	This sharp bend with limited sight distance is kind of frightening to       Image: Construction       X       Image:	x         x         x           x         x         x	x         x	X     vehicle will not negotiate the turn and run       X     into me.       X     X
41.001948 -79.338256	377137 point	2/12/2020 273105	Sharp turn in south bethlehem !!! Big trucks have trouble with it !!!  From Kittanning to Brookville, it is a 1940's era road	x x		Image:
40.875534 -79.403422	377142 point 377150 point	2/12/2020 273395	Always get stuck behind slow moving trucks .       Image: Alway			Always slower moving g trucks coming up       that hill
41.145777 -79.114011	374576 point	2/12/2020 273400	28 close to Brookville there are many wrecks here a lot on a Saturday night.	I use this Road mainly to go to my       Daughters hose. She lives off of       X		I think vehicles are going too fast.
40.832032 -79.476289	377163 point	2/12/2020 273408				Speed / Traffic enforcement* Vehicle     speed traveled is dangerous. Nebedy goes
						the posted speed limit. 28 is seen as a shortcut to and from Pittsburgh and they
						expect to travel interstate speed plus on it. This entire strip of road is small town / farming community. Drivers do not follow
						at safe distances so they smash into stopping or turning vehicles. Dump trucks Route 28 is route 68 twin.
						and logging trucks traveling at unsafe       Honestly if people want to drive         speeds, going with the flow of gravity and       fast, and don\'t want to deal with         just letting their truck go as fast as it can       slow moving traffic or farm
						down the hill. Line of sight on hills and       equipment, or slow down         curves need to be investigated. There are       through towns, they need to         blind bills you don\'t know a car is stopped       travel L80 West Brookville, to L79
						Image: State of the state
			Brookville To Kittaanning, Speed enforcement severely lacking. Speed			through Summerville to include their own       52 min         residents. Signs for farm equipment as well       I-80 to B-ville-SR28-Pitt = 80.8         as trucks entering exiting highway signs may       miles 1hr 36 min
41.089427 -79.227246 41.007949 -79.31197	374382 point 380268 point	2/12/2020         273230           2/13/2020         273462	limit is 55 mph or less. Vehicles travel a lot faster (65+).       X       X       X         Need lots of lanes outside M&S Meats because they are fantastic!       X       X       X	X       X       X       X         X       Image: Constraint of the second sec	x       x	help a little.     Minimum times without delays.       Image: Second and the s
				Ytravel tis daily go through the		out the road beside A Plus you can NOT see to the left for oncoming traffic. Accidents
41.001948 -79.338256	377137 point	2/13/2020 273485	the intersection at The A Plus has NO stop light. X	Intersection gointo to Kittanning,       Brookville, Clarion going       X       anywhere		time. This road leads to park and is heavily used to bypass town and the lights
40.810439 -79.551543	374403 point	2/13/2020 273496	Image: Marcine Strate       X       X       X       X       X         1130 Ridge Road, Templeton, Pa. 16259       Image: Marcine Strate       Image: M	X     X     X       Image: Second se	Image: Second	Improve Ridge Road access off ramp. Travel
			ACTIVE, Public Event OHV family fun rides and ATV, dirt bikes and Woods Racing events. See Www.riderplanetusa.com. Venue is 5 west of Rt 28 on			use of OHV, utility trailers and camper vehicles of all sizes. Sometimes heavy traffic
			Ridge Road and Scrubgrass and Mahoning Creeks. OHV Park scenic kayaking, canoeing and fishing. Proposed off ramp to park. Contact Armstrong Planning & Developments and County Commissioner's for			to Scrubgrass Village OHV Park. Sometimes       Ito Scrubgrass Village OHV Park. Sometimes         traffic is backed up 1 mile on Ridge Road at       Yes, traffic is very slow to get         entrance to park. County economical       from Kittanning to Interstate 80
40.868648 -79.42881	374364 point	2/13/2020 273516	update information Truly yours, Frank Garmong, Owner and President of Scrubgrass Village, Inc. 724-868-2382	x x		development is a big economical generator       due to the many hills and heavy         for the county       truck traffic
						corridor North on Rt 66 and connect at Clarion for North 66
			Accessing Redbank			traffic instead of connecting at Brookville. With a store at the interscection of 66/28 I see a lot
41.001826 -79.331122 40.875072 -79.404252	380285 point 380304 point	2/13/2020         273526           2/14/2020         273593	Traffic flow bi-passing New Bethlehem       Valley Trail         slow truck traffic       Image: Construct traffic descent flow of the truck traffic descent flow of truck traffic descent flow of the truck traffic descent flow of the truck traffic descent flow of truck traffic descent flow	X       I own a business on Broad Street       X       I own a business on Broad Street       X         X       X       X       I own a business on Broad Street       X       X       X       X	x         x	X     of traffic on 66       Image: Constraint of the system of th
						driven this road for over 30 years. Both directions it is not wide enough, especially
40.906306 -79.371533	380314 point	2/14/2020 273604	This turn is extremely dangerous and needs to be straightened.       Accessing Redbank         X       Valley Trail	x x x	x x x	When a semi takes the turn and you areThere needs to be a four lanedriving the opposite direction. It needs tohighway continued up fromXXbe straightened.Kittanning to Brookville.
40.873171       -79.406444         40.923799       -79.358842	380325 point 380329 point	2/14/2020         273621           2/14/2020         273643	It's terrible. Like a race roadway.	X       X       X       X         X       X       X       X	x     x <td>Image: Marcine State       X       Needs to be four lanes         Image: Marcine State       X       Image: Marcine State         Image: Marcine State       X       Image: Marcine State         Image: Marcine State       Image: Marcine State       Image: Marcine State</td>	Image: Marcine State       X       Needs to be four lanes         Image: Marcine State       X       Image: Marcine State         Image: Marcine State       X       Image: Marcine State         Image: Marcine State       Image: Marcine State       Image: Marcine State
40.874773 -79.408153	374624 point	2/14/2020 273638	widen any work out to four lanes! There is a lot of places to go through       Accessing Redbank         farm land instead of following the present route!       X       X         Valley Trail       Valley Trail	x x	x x x x x x x	X       X       X       In present state there are too many ess curves and narrow curves in poor weather!
40.999654 -79.334057	380330 point	2/14/2020 273647	businesses and industry to consider locating in the New Bethlehem area, which are greatly needed in that region. X	x x	x x x x	New Bethlehem causing congestion and       safety concerns.
40.999028 -79.342542	380337 point	2/15/2020 273673	Coming through this big bend and then through New Bethlehem is the slowest part of the trip	x	x x x	It's just slow going in general to move       through the town. Signals, parked cars,       X
						Overall, this stretch of 28 is pretty
						fact there is no cellphone service for much of the expanse as well.
						If you break down in a certain area (namely around Brookville) you must rely on the kindness of
						strangers because Verizon phones do not have service, which is ludicrous and downright
						dangerous. In addition, if we are speaking economically? There is
						no industry and little economic opportunity along this corridor. It could use a large 24 hour gas
			I hope this is the correct area, but I do know it is before Brookville and			station that has a bathroom/facilities just to begin
41.119558 -79.189607	380338 point	2/15/2020 273671	bottom of the hill gets flooded out and there is nowhere safe to escape or turn around. Luckily, my car gracefully floated across the road at the time. X	x	x	As Trientioned, in neavy rains it hoods       withthere is really nothing on         quickly with no place to pull over or turn       this whole stretch until you reach         around safely.       Brookville.
41.046685 -79.253945	374418 point	2/15/2020 273687		Travel this to get to 422 to go to     X       X     Holidaysburg	x x x	X       X       X       Image: A set of the set of t
			Better signage needed saving that this is the best exit to take Boute 28 to			development along the corridor and am interested in seeing the results of the planned study for a
			Pittsburgh. 28 could be rerouted to run concurrent with I-80 between exits, or the interchange could be reconfigured for a potential freeway re-			People could miss their exit or become between Kittanning and
40.82623 -79.481911	377142 point	2/15/2020 273692 2/15/2020 273730	routing of 28 as has been proposed.     X       Image: A state of 28 as has been proposed.     X       Image: A state of 28 as has been proposed.     X       Image: A state of 28 as has been proposed.     X	X     X       Image: Constraint of the second state of the	X     X     X     X     X       X     X     X     X     X	X     Confused leading to longer travel times.     Brookville.       Image: Strate in the strate in
				The twists and turns and ups and downs for healthcare professional and patient transport makes		
				access to specialists not available in the central PA 80 corridor more challenging than it already is A		So go fact como go clow bit an abrunt turn
40.853257 -79.455182	374620 point	2/15/2020 273738		patient in pain, sick and immobile has an awful ride.	x x x x x x	X     hill
						I have lived in this area my entire life, and there are many accidents on this turn every year. This turn needs to be eliminated for
40.999232-79.3428641.016228-79.300025	374417 point 374449 point	2/15/2020         273747           2/15/2020         273758	90° turn in South Bethlehem Borough       X         Image: Constraint of the second secon	Image: Second	x     x	X     every traveler's safety.       Image: A state of the st
40.999114 -79.342962	374589 point	2/15/2020 273766	calls there with car coming the other way or cars not slowing down behind ne.	x		Image: Constraint of the sector of the se
41.149398       -79.109749         41.133885       -79.148201         41.128454       -79.177384	380367 point 380368 point 380369 point	2/15/2020         2/3/80           2/15/2020         273780           2/15/2020         273780           2/15/2020         273780	Intersection of snyder Road and Route 28XXXXImage: Snyder Road and Route 28XXXX	XXXXXXXXXXXX	X     X     X     X     X       Image: Second state	X     X     X     Compared by the second s
						Section from Rose Township line to Jefferson County line is unsafe due to drainage, sight distances
						and curves. Even PennDot when replaced drainage cross pipes
41.134314 -79.150282	380370 point	2/15/2020 273780	x x x x	x     x     x       Image: Im	x x x x x x x x x x x x x x	X     X     X     X     Were installed has created road surface concerns.       Improving the installed has created road     28 UNSAFE     surface concerns.       Improving the installed has created road     surface concerns.
						Large brick plant with employees and tax base for area. Submitter should view the surroundings Traffic making deliveries and
41.119526 -79.187528	380372 point	2/15/2020 273780	X     X     X     X       Dangerous area of road, requiring slowing down, for a very sharp turp     V     V	X     X     X       Image: Second se	x     x     x     x     x     x     x     x	X     X       pickup does create safety concern       See previous comments, a dangerous sharp       turn with intersections
						it is hard to see in both directions at that       point_slight knob and curve there plus
40.837713 -79.466232	374363 point	2/15/2020 273793	very dangerous to pull onto 66 from Anderson Creek rd	x     x     x	x x x x	Speed of vehicles approaching from either     would love to see mostly 4 lane       X     Sight distance is a big concern about
			You need to get the Goheenville Dip project started . It's been to long in	I live in this area so I pull out onto 28 multiple times each day leaving for work I drive mini		vehicles coming in the south bound lane when you trying to enter 28 and travel north. Another concern is the road surface
40.904491 -79.371154	374365 point	2/16/2020 273843	the process.     X     X       sharp turn in South Bethlehem when a tractor trailer is going the other	X     school bus.     X	x     x     x     x     x     x     x	X     X     it's terribly rough through this area.     would be a great help.
40.99747       -79.341149         41.174065       -79.095421         40.906306       -79.371533	380379 point 380380 point 380381 point	2/16/2020         273878         Gu           2/16/2020         273881           2/16/2020         273882	way crossing over the center line       X       Image: Construct the center line       X         Image: Lots of turk traffic       X       Image: Construct traffic       X	x         X             Image: Constraint of the second s	X     Image: Constraint of the second s	Image: Constraint of the second sec
41.040227-79.25697241.127248-79.16371841.118211-79.192026	374387 point 380382 point 380383 point	2/16/2020         273884           2/16/2020         273887           2/16/2020         273887           2/16/2020         273897	X     x     x       X     x     x	X     X     X       Image: Constraint of the second secon	X     X     X     X       X     X     X     X       X     X     X     X       X     X     X     X       X     X     X       X     X     X	
	I'					

41.019508 -79 272257	380384 noint	2/16/2020	273887			χ Ι Ι	Iv Iv	X X					
41.016228 -79.300025	37449 point	2/16/2020	273887 X			X IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII							
41.010765 -79.307105 41.001948 -79.338256	380385 point 380386 point	2/16/2020	273887 X 273887 X			X X		x x x x x x	X X X				
40.973049 -79.350826	380387 point	2/16/2020	273887 X			X X			X X X				
10.011203 75.101000													This a wonderful area of Western
													PA and the small town s have much to offer for those traveling
			This a great town just North of Pittsburgh Many opportunities for										through. If proper want to
		o // = /0000	economic development. Great place to raise a family; yet close to the city									Speeds should be a little slower15-25 mph	take 79 North or South to access I-
41.000062 -79.325356		2/1//2020	273948     N     X     X       This turn is extremely sharp and contributes often to vehicular accidents,     Image: Contribute of the start of the sta										80
40.999014 -79.343151	380401 point	2/17/2020	273966       especially by tractor-trailers.       X       X         This turn is very dangerous. There is little visibility of the roadway around       X       X		X X X X		X X	X X					
40.906969 -79.37127	380402 point	2/17/2020	273966 the bend for drivers. X		X X	X	x x	X					
			needs to be addressed. There are small lanes, roadways and a few homes										
41.14572 -79.114471	380407 point	2/18/2020	along this stretch and if you look back through the years you will see there are far too many accidents.			x	x	x			x		
40.956703 -79.363108	374431 point	2/18/2020	273998 X	X		X	X	x x x		X			
41.145777 -79.114011	374576 point	2/18/2020	274060 is too sharp. X X	X	x	x	x x	x			x		
			Very dangerous pulling onto route 28 from Jefferson cemetery road. Have to roll windows down to listen for vehicles coming around the curves									Blind curvesvery dangerous pulling onto route 28 from Jefferson cemetery road as	
41 133885 -79 148201	380368 noint	2/18/2020	before pulling out. Have almost been hit there before. Also pulling onto				X	x				well as turning onto jefferdon cemetery	
41.142586 -79.14537	380441 point	2/18/2020	274098     Blind curve many accidents happen here     X			X	X X X	x x			x		
41.003171 -79.298233	380442 point 380442 point	2/18/2020	274104         Guest         X           274107         X	X	X     X       X     X								
													28 between New Bethlehem and Kittaning is slow, too winding.
													The travel time to Pittsburgh
40.99747 -79.341149	380379 point	2/19/2020	274115 This corner slows down traffic, and is a safety concern.			x	x x						lane.
40.810439 -79.551543 41.145777 -79.114011	374403 point 374576 point	2/19/2020 2/19/2020	274151 X		X     X     X     X       X     X     X     X	X X	X X X X	x x		x			
			The major issue in the proposed area is Hogback Hill, both for vehicular									Historic improvements have not really made it that much safer. The steep grade presents	Improving the corridor while minimizing the impact on
			and freight traffic. Even with the improvements made over the past 50									a problem for truckers. The numerous	communities and the
40.877269 -79.393957	380458 point	2/19/2020	274176 many curves.	x x	x	x	x					inclement weather.	of the project.
			This intersection is the site of many crashes and site distance is an issue. This intersection has been worked on over the years, but perhaps could										
41.040142 -79.257279	380459 point	2/19/2020	274184 still be improved.		x x	X	X X				x	This area has little or no herm area with	
40.96123 -79.364125	380473 point	2/19/2020	274197 X			x	x		x	x	x	trees growing over roadway.	
												inis stretch of roadway needs resurfaced and widened to provide safety and	
40.920643 -79.364125	380474 point	2/19/2020	274197 X	X		X	X			X	+	elimination of some curves. Turn at bottom of hill is narrow and this	
40.834483 -79.471913	380476 point	2/19/2020	274197 X	X	x x	x	x x			x	x	area has little to no berm.	
												People merge last minute, causing accidents	
												on split by highland park bridge 28S. There is a need for 2 lanes going straight towards	
			The highland park split on 28S needs to be two lanes, reduce accidents									the city to reduce accidents and evening	
40.49528       -79.908106         40.849825       -79.458898	380479 point 380484 point	2/19/2020	274209     from people merging last minute.     X     X       274242     X     X     X			X	X X X X	X X X			X X	rush hour congestion.	
40.853071 -79.455315 40.854337 -79.45156	380485 point 380486 point	2/20/2020	274242 274242			X X	X X		X X	X X	X X X		
40.873067 -79.412225	380487 point	2/20/2020	274242		X X	X	X	x x x	X	X	X X		
40.906772 -79.371153	380488 point 380489 point	2/20/2020	274242     Goheenville curve     X     X	X	X X X	X X			X X	X X	X X X		
40.917777 -79.364957 40.946889 -79.363827	380490 point 380491 point	2/20/2020	274242X274242From Mahoning Creek Bridge to Distant on north end.XXX		X X	X X	X X X X	X X X	X	X X	X X	Narrow.	
			00 <sup>2</sup> turn in South Bothlohom Porough Now Pothlohom tight access										
			narrow. Why not build new road across State Game Lands to north side of										
			New Bethlehem to current Route 28 beyond Redbank High School area, with a new Bridge "Access" across Redbank Creek intersecting with Route										
			66 north downtown New Bethlehem at Broad Street and Wood Street. Do NOT cut off New Bethlehem and Boute 66 North to Clarion and the										
			University and I-80 west and route 66 North to Bradford/Olean, NY and										
40.996209 -79.342073	380492 point	2/20/2020	274242 northern Pennsylvania, New York State and Ohio through Clarion. X X	x x x x	x x x x	x	x x x	x	x x	x x x	x x		
41.039369 -79.257315	380493 point	2/20/2020	274242 X X	X X	X X	X		X X X	X X	X	X X	I already explained some of them on the	
												previous page. It is a BLIND turn at the top	
												turn.You can end up in an accident coming	
					I use this road daily to go to pull							from Brrokville onto Moore Road, or going onto 28 from Moore Road to Brookville or	
			When coming from Brookville it is hard to turn onto Moore Road, if there		onto 28 and to come home from							the other direction to Summerville. During	
			are cars coming from Summerville and you get caught waiting to turn and		depending on where I am going							weather warms up and then freezes again,	
			someone comes around the turn heading to SummervilleBAM, you are going to be in serious trouble. People have been hit in the rear and in the		to and coming from. The residents on Moore Road							there is some runoff onto the right side of the road heading south coming up around	
			frontside trying to pull into and out of this road onto 28. It is a serious hazard. Need to come up with something to make this turn safer for		shouldn't have to worry about							the turn that freezes over and makes it very slippery, especially in the early morning	
41.127075 -79.164665	380494 point	2/20/2020	274244 Guest everyone that uses it and for the residents that live there.		they leave their house. X		x x	x x				hours.	
												If you are entering Rt. 28 from Mechling road to go south, the site distance is only	
												about 100 feet in an uphill direction, traffic	
												road due to the crest of the hill. This is a	
40.850286 -79.458244	380495 point	2/20/2020	274256 Guest There is limited sight at the Mechling Road intersection. X X	x x	x x x x	x	x				x	road due to the crest of the hill. This is a danger to the motoring public.	How it will impact our church and
40.850286 -79.458244	380495 point	2/20/2020	274256     Guest     There is limited sight at the Mechling Road intersection.     X     X       274266     A dangerous sharp turn and very busy intersection with cars, tractor     X		x x x x	x	X				x	road due to the crest of the hill. This is a danger to the motoring public.	How it will impact our church and private school campus development plan
40.850286 -79.458244 41.039369 -79.257315	380495 point 380493 point	2/20/2020	274256       Guest       There is limited sight at the Mechling Road intersection.       X       X         274256       A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment       X       X         274266       Need passing lanes. had a chance to do it before a few years ago and did       X       X	x x	x x x x x x		x x	x x x			x x	Can not see a car pulling out of Mechning         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557	380495 point 380493 point 380493 point 380497 point 380498 point	2/20/2020 2/20/2020 2/20/2020 2/20/2020	274256GuestThere is limited sight at the Mechling Road intersection.XX274266A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipmentXImage: Constraint of the constraint of	x x	x       x       x       x         Image: Second sec	x x x x	x X	x x x x x x	X		x x	Can not see a car pulling out of Mechning         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557	380495 point 380493 point 380493 point 380497 point 380498 point	2/20/2020 2/20/2020 2/20/2020 2/20/2020	274256GuestThere is limited sight at the Mechling Road intersection.XX274266A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipmentX274268Need passing lanes. had a chance to do it before a few years ago and did not.X274273Image: Construction of the temperatureX	x x	x x x x x x x x x x x x x x x x x x x	x x x x x	x X	x     x     x       x     x     x       x     x     x       x     x     x	X		x x	Image: Carr putting out of Mechning         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557	380495 point 380493 point 380497 point 380497 point 380498 point	2/20/2020 2/20/2020 2/20/2020 2/20/2020	274256GuestThere is limited sight at the Mechling Road intersection.XX274266A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipmentX274268Need passing lanes. had a chance to do it before a few years ago and did not.X274273Image: Comparison of the temperatureX	x     x       x     x	x x x x x x x	x x x x	x X	x     x     x       x     x     x       x     x     x       x     x     x	X		x x x x x x	Image: Carr pulling out of Mechning         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557	380495       point         380493       point         380493       point         380493       point         380493       point         380494       point         380495       point         9000000000000000000000000000000000000	2/20/2020 2/20/2020 2/20/2020 2/20/2020	274256GuestThere is limited sight at the Mechling Road intersection.XX274266A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipmentX274268Need passing lanes. had a chance to do it before a few years ago and did not.X274273Image: Constraint of the second seco	x x	x       x       x         Image: Second		x X	x x x x x x x x x x x x x x x x x x x	X		x x x	Image: Call Not see a call pulling out of Mechning         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589	380495       point         380493       point         380493       point         380497       point         380498       point         380498       point         380504       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020	274256       Guest       There is limited sight at the Mechling Road intersection.       X       X         274256       A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment       X       X         274266       Need passing lanes. had a chance to do it before a few years ago and did not.       X       X         274273       Image: Comparison of the transmitted sight at the direction @ 55 mph.       X       X		x       x       x         Image: Second	x x x x x x x x x x x x x x x x x x x		x x x	X     Image: Constraint of the second s		x x x x x x x	Image: Call Hold see a call pulling out of Mechning         road due to the crest of the hill. This is a         danger to the motoring public.         Image: No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Image: Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908	380495       point         380493       point         380493       point         380497       point         380498       point         380504       point         380505       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020	274256       Guest       There is limited sight at the Mechling Road intersection.       X       X         274256       A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment       X       X         274268       Need passing lanes. had a chance to do it before a few years ago and did not.       X       X         274273       Image: Comparison of the time direction @ 55 mph.       X       X         274288       Guest       bad turn either direction @ 55 mph.       X	x x	x       x       x         Image: Second	x x x x x x x x x x x x x x x		x x x x x x x x x x x x x x x x x x x			x x x x x x x	Can not see a car pulling out of interning         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908	380495       point         380493       point         380493       point         380497       point         380498       point         380498       point         380504       point         380505       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020	274256       Guest       There is limited sight at the Mechling Road intersection.       X       X         274256       A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment       X       X         274266       Need passing lanes. had a chance to do it before a few years ago and did not.       X       X         274273       Image: Comparison of the transmitted sight at the direction @ 55 mph.       X       X         274288       Guest       bad intersection       X       X		x       x       x         Image: Second	x x x x x x x x x x		x     x     x       x     x     x       x     x     x       x     x     x       x     x     x       x     x     x       x     x     x       x     x     x       x     x     x       x     x     x       x     x     x       x     x     x			x x x x x x x x x x x x x x x x x x x	Image: Carrier of the start of the crest of the hill. This is a danger to the motoring public.         Image: No passing lane. You often get behind slow moving tractor trailers going up the hill.         Image: Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widened as well as lessened by removing and reshaping the adjoining hillside. I would not want to live in Goheenville as is.         Image: This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out onto 28/66.         Image: The sum of the section is at the top pass slow moving up to the section.	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073	380495       point         380493       point         380493       point         380497       point         380498       point         380498       point         380504       point         380505       point         380506       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020	274256GuestThere is limited sight at the Mechling Road intersection.XX274266A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipmentX274268Need passing lanes. had a chance to do it before a few years ago and did not.X274273Image: Comparison of the temperatureX274288Guestbad turn either direction @ 55 mph.Image: Comparison of temperature274288Guestbad intersectionX274288Guestbad intersectionX274288Guestneeds a passing lane especially for trucksX		x       x       x         Image: state	x x x x x x x x x x x x	x X	x x x x x x x x x x x x x x x x x x x			x x x x x x x x	Image: California set a californing out of Weetining         road due to the crest of the hill. This is a         danger to the motoring public.         Image: No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Image: Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073	380495       point         380493       point         380493       point         380497       point         380498       point         380498       point         380504       point         380505       point         380506       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020	274256     Guest     There is limited sight at the Mechling Road intersection.     X     X       274256     A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment     X       274268     Need passing lanes. had a chance to do it before a few years ago and did not.     X       274273     Image: Comparison of trailers and much farm equipment     X       274288     Guest     bad turn either direction @ 55 mph.     X       274288     Guest     bad intersection     X       274288     Guest     bad intersection     X	x     x       x <td>x     x     x       Image: Sector of the se</td> <td>x x x x x x x x x x x x x x x x x x x</td> <td></td> <td>x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x</td> <td></td> <td></td> <td>x x x x x x x x x x x x x x x x x x x</td> <td>Can not see a car pulling out on Meetining         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this</td> <td>How it will impact our church and private school campus development plan.</td>	x     x     x       Image: Sector of the se	x x x x x x x x x x x x x x x x x x x		x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x			x x x x x x x x x x x x x x x x x x x	Can not see a car pulling out on Meetining         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073         40.881339       -79.39168	380495       point         380493       point         380493       point         380497       point         380498       point         380498       point         380504       point         380505       point         380506       point         380507       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020	274256       Guest       There is limited sight at the Mechling Road intersection.       X       X         274266       A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment       X       X         274268       Need passing lanes. had a chance to do it before a few years ago and did not.       X       X         274268       not.       X       X       X         274273       Image: Comparison of trailers and the track of the		x       x       x         Image: Second	x     x       x     x       x     x       x     x       x     x       x     x       x     x       x     x       x     x       x     x       x     x       x     x       x     x		x x x x x x x			x x x x x x x x x x x x x x x x x x x	Image: Call Hold See a call pulling out of Mechning         road due to the crest of the hill. This is a         danger to the motoring public.         Image: No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Image: Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073         40.881339       -79.39168	380495       point         380493       point         380493       point         380497       point         380498       point         380509       point         380504       point         380505       point         380506       point         380507       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020	274256       Guest       There is limited sight at the Mechling Road intersection.       X       X         274266       A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment       X       X         274268       Need passing lanes. had a chance to do it before a few years ago and did not.       X       X         274268       Need passing lanes. had a chance to do it before a few years ago and did not.       X       X         274273       Image: Comparison of the comparison		x       x       x         Image: second	x x x x x x x x x x x x x x x x x x x		x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x			x x x x x x x x x x x x x x x x x x x	Image: Call Hold See a call pulling out of Mechning         road due to the crest of the hill. This is a         danger to the motoring public.         Image: No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Image: Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         there have been several accidents over the         years from trucks taking this turn too fast. It	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073         40.881339       -79.39168	380495       point         380493       point         380493       point         380497       point         380498       point         380498       point         380504       point         380505       point         380506       point         380507       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 1 2/20/2020 1 2/20/2020 1 1 1 1 1 1 1 1 1 1 1 1 1	274256       Guest       There is limited sight at the Mechling Road intersection.       X       X         274266       A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment       X       X         274268       Need passing lanes. had a chance to do it before a few years ago and did not.       X       X         274273       Image: Comparison of the trailers of trailers of the trailers of traile		x       x       x         Image: second			x x x x x			x x x x x x x x x x x x x x x x x x x	Image: Initial set and a pulling but on Mechning         road due to the crest of the hill. This is a         danger to the motoring public.         Image: Initial set and the motoring public.	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073         40.881339       -79.39168         40.999057       -79.342792	380495       point         380493       point         380493       point         380497       point         380498       point         380498       point         380504       point         380505       point         380506       point         380507       point         380508       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020	274256     Guest     There is limited sight at the Mechling Road intersection.     X     X       274266     A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment     X       274268     Need passing lanes. had a chance to do it before a few years ago and did not.     X       274273     Image: Comparison of the trailers of trailers of trailers of trailers of trailers of trailers.       274288     Guest     bad turn either direction @ 55 mph.     X       274288     Guest     bad intersection     X       274288     Guest     bad intersection     X       274288     Guest     needs a passing lane especially for trucks     X       274288     Guest     needs a passing lane     X       274288     Guest     needs a passing lane     X	x     x       x       x <t< td=""><td>x       x       x         x       x       x</td><td>.       .</td><td></td><td>x x x x x x x x x x x x x x x x x x x</td><td></td><td></td><td>x x x x x x x x x x x x x x x x x x x</td><td>Image: Carl pulling out of Niechning         road due to the crest of the hill. This is a         danger to the motoring public.         Image: Carl public data of the hill. This is a         danger to the motoring public.         Image: Carl public data of the hill.         Image: Carl public data of the hill public data data of the hill.</td><td>How it will impact our church and private school campus development plan.</td></t<>	x       x       x         x       x       x	.       .		x x x x x x x x x x x x x x x x x x x			x x x x x x x x x x x x x x x x x x x	Image: Carl pulling out of Niechning         road due to the crest of the hill. This is a         danger to the motoring public.         Image: Carl public data of the hill. This is a         danger to the motoring public.         Image: Carl public data of the hill.         Image: Carl public data of the hill public data data of the hill.	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073         40.881339       -79.39168         40.999057       -79.342792	380495       point         380493       point         380493       point         380497       point         380498       point         380497       point         380498       point         380498       point         380504       point         380505       point         380506       point         380507       point         380508       point         380508       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 1 2/20/2020 1 2/20/2020 1 2/20/2020 1 1 1 1 1 1 1 1 1 1 1 1 1	274256     Guest     There is limited sight at the Mechling Road intersection.     X     X       274266     A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment     X       274268     Need passing lanes. had a chance to do it before a few years ago and did not.     X       274273     Image: Comparison of the comparison	x     x       x	x       x       x         Image: Second	x       x         x       x		x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x			x x x x x x x x x x x x x x x x x x x	Can house a car putning out of Meetining         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         there have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         90,       Distant should be bypassed entirely. The         passing lane ends half way up the hill so if	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073         40.881339       -79.39168         40.999057       -79.342792	380495       point         380493       point         380493       point         380497       point         380498       point         380504       point         380505       point         380506       point         380507       point         380508       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020	274256     Guest     There is limited sight at the Mechling Road intersection.     X     X       274266     A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment     X       274268     Need passing lanes. had a chance to do it before a few years ago and did not.     X       274273     Need passing lanes. had a chance to do it before a few years ago and did not.     X       274273     Need passing lanes. had a chance to do it before a few years ago and did not.     X       274273     Need passing lanes.     X       274288     Guest     bad turn either direction @ 55 mph.     X       274288     Guest     bad intersection     X       274288     Guest     needs a passing lane especially for trucks     X       274288     Guest     needs a passing lane     X       274288     Guest     needs a passing lane     X		x       x       x         x       x       x	x       x         x       x		x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x			x         x <td< td=""><td>Can hold see a car pulling out of Meetining         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside.         hillside.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         90,       Distant should be bypassed entirely. The         passing lane ends half way up the hill so if       you get stuck behind one or more slow         moving trucks you have</td><td>How it will impact our church and private school campus development plan.</td></td<>	Can hold see a car pulling out of Meetining         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside.         hillside.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         90,       Distant should be bypassed entirely. The         passing lane ends half way up the hill so if       you get stuck behind one or more slow         moving trucks you have	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073         40.881339       -79.39168         40.999057       -79.342792	380495       point         380493       point         380497       point         380497       point         380498       point         380498       point         380504       point         380505       point         380506       point         380507       point         380508       point         380508       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 1 2/20/2020 1 2/20/2020 1 2/20/2020 1 1 1 1 1 1 1 1 1 1 1 1 1	274256     Guest     There is limited sight at the Mechling Road intersection.     X     X       274266     A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment     X       274268     Need passing lanes. had a chance to do it before a few years ago and did not.     X       274273     Image: Additional action of the few years ago and did not.     X       274288     Guest     bad turn either direction @ 55 mph.     X       274288     Guest     bad intersection     X       274288     Guest     needs a passing lane especially for trucks     X       274288     Guest     needs a passing lane     X       274288     Guest     sharp turn for tractor trailers.     X		x       x         x	x       x         x       x		x       x         x			x         x <td< td=""><td>Can not see a car pulling out of Meching         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         there have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of      &lt;</td><td>How it will impact our church and private school campus development plan.</td></td<>	Can not see a car pulling out of Meching         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         there have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of      <	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073         40.881339       -79.39168         40.999057       -79.342792	380495       point         380493       point         380493       point         380497       point         380498       point         380498       point         380504       point         380505       point         380506       point         380507       point         380508       point         380509       point         380504       point         380505       point         380506       point         380507       point         380508       point         380509       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 1 2/20/2020 1 2/20/2020 1 1 1 1 1 1 1 1 1 1 1 1 1	274256     Guest     There is limited sight at the Mechling Road intersection.     X     X       274266     A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment     X       274268     Need passing lanes. had a chance to do it before a few years ago and did not.     X       274273     Image: Comparison of the time direction @ 55 mph.     Image: Comparison of time direction @ 55 mph.       274288     Guest     bad turn either direction @ 55 mph.     X       274288     Guest     bad intersection     X       274288     Guest     bad intersection     X       274288     Guest     bad intersection     X       274288     Guest     needs a passing lane especially for trucks     X       274288     Guest     needs a passing lane     X       274288     Guest     sharp turn for tractor trailers.     X		x       x       x         Image: state	.       .       .       .       .         x       .       .       .       .         x       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       . <td></td> <td>x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x</td> <td></td> <td></td> <td>x         <td< td=""><td>Call this see a car publing out of McErling         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         90,         Distant should be bypassed entirely. The         passing lane ends half way up the hill so if         you get stuck behin</td><td>How it will impact our church and private school campus development plan.</td></td<></td>		x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x			x         x <td< td=""><td>Call this see a car publing out of McErling         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         90,         Distant should be bypassed entirely. The         passing lane ends half way up the hill so if         you get stuck behin</td><td>How it will impact our church and private school campus development plan.</td></td<>	Call this see a car publing out of McErling         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         90,         Distant should be bypassed entirely. The         passing lane ends half way up the hill so if         you get stuck behin	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.8874784       -79.408073         40.881339       -79.39168         40.999057       -79.342792	380495       point         380493       point         380493       point         380494       point         380495       point         380496       point         380497       point         380498       point         380499       point         380504       point         380505       point         380506       point         380507       point         380508       point         380508       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 1 2/20/2020 1 2/20/2020 1 1 1 1 1 1 1 1 1 1 1 1 1	274255     Guest     There is limited sight at the Mechling Road intersection.     X     X       274265     A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment     X       274268     Need passing lanes. had a chance to do it before a few years ago and did not.     X       274273     Image: Comparison of the comparison		x       x       x         Image: state	.       .		x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x			x x x x x x x x x x x x x x x x x x x	In this set at a pulling out of whething         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         there have been several accidents over the         years from trucks taking this turn to fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         90,         Distant should be bypassed entirely. The         passing lane ends half way up the hill so if         you get stuck behind on	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073         40.881339       -79.39168         40.999057       -79.342792	380495       point         380493       point         380493       point         380497       point         380498       point         380504       point         380505       point         380506       point         380507       point         380508       point         380509       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 1 2/20/2020 1 2/20/2020 1 1 1 1 1 1 1 1 1 1 1 1 1	274226     Guest     There is limited sight at the Mechling Road intersection.     X     X       27426     A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment     X       274268     Need passing lanes. had a chance to do it before a few years ago and did     X       274273     Image: Comparison of trailers, and much farm equipment     X       274288     Guest     Need passing lanes. had a chance to do it before a few years ago and did     X       274288     Guest     bad turn either direction @ 55 mph.     X       274288     Guest     bad intersection     X       274288     Guest     bad intersection     X       274288     Guest     needs a passing lane especially for trucks     X       274288     Guest     needs a passing lane     X       274288     Guest     sharp turn for tractor trailers.     X	x     x       x	x       x       x         Image: second	.       .       x         x       .       .         x       .       .         .       .       .		x x x x x x x x x x x x x x x x x x x x			x         x <td< td=""><td>Initial See a car public out of Nechning         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         90,         Distant should be bypassed entirely. The         passing lane ends half way up the hill so if         you get stuck behind one or more slow         moving trucks you have to follo</td><td>How it will impact our church and private school campus development plan.</td></td<>	Initial See a car public out of Nechning         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         90,         Distant should be bypassed entirely. The         passing lane ends half way up the hill so if         you get stuck behind one or more slow         moving trucks you have to follo	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.881339       -79.39168         40.881339       -79.39168         40.999057       -79.342792	380495       point         380493       point         380493       point         380497       point         380498       point         380509       point         380505       point         380506       point         380507       point         380508       point         380509       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 1 2/20/2020 1 2/20/2020 1 1 1 1 1 1 1 1 1 1 1 1 1	274256     Guest     There is limited sight at the Mechling Road intersection.     x     X       274266     A dangerous sharp turn and very busy intersection with cars, tractor trailers, and nuch farm equipment     x       274268     Need passing lanes. had a chance to do it before a few years ago and did not.     x       274268     Need passing lanes. had a chance to do it before a few years ago and did not.     x       274268     Need passing lanes. had a chance to do it before a few years ago and did not.     x       274288     Guest     bad turn either direction @ 55 mph.     X       274288     Guest     bad intersection     X       274288     Guest     needs a passing lane especially for trucks     X       274288     Guest     needs a passing lane     X       274288     Guest     needs a passing lane     X       274288     Guest     needs a passing lane     X		x       x       x         Image: Second	.       .       x         x       .       .         x       .       .         .       .       .		x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x			x         x <td< td=""><td>In the see a car public but of Nechning         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         there have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         90,         Distant should be bypassed entirely. The         passing lane ends half way up the hill so if         you get stuck behind on</td><td>How it will impact our church and private school campus development plan.</td></td<>	In the see a car public but of Nechning         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         there have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         90,         Distant should be bypassed entirely. The         passing lane ends half way up the hill so if         you get stuck behind on	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073         40.881339       -79.39168         40.999057       -79.342792	<ul> <li>380495 point</li> <li>380493 point</li> <li>380497 point</li> <li>380497 point</li> <li>380498 point</li> <li>380508 point</li> <li>380506 point</li> <li>380507 point</li> <li>380507 point</li> <li>380508 point</li> </ul>	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 1 2/20/2020 1 2/20/2020 1 1 1 1 1 1 1 1 1 1 1 1 1	2742 56     Guest     There is limited sight at the Mechling Road intersection.     X     X       2742 66     A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment     X       2742 68     Need passing lanes. had a chance to do it before a few years ago and did not.     X       2742 73     Need passing lanes. had a chance to do it before a few years ago and did not.     X       2742 73     Need passing lanes. had a chance to do it before a few years ago and did not.     X       2742 74     Need passing lanes. had a chance to do it before a few years ago and did not.     X       2742 75     Need passing lanes. had a chance to do it before a few years ago and did not.     X       2742 76     Definition of the direction of the fore a few years ago and did not.     X       2742 78     Guest     Ded turn either direction of 55 mph.     X       2742 78     Guest     Ded intersection     X       2742 78     Guest     needs a passing lane especially for trucks     X       2742 78     Guest     needs a passing lane     X       2742 78     Guest     sharp turn for tractor trailers.     X	x     x       x	x       x       x         Image: Second	x x x x x x x x x x x x x x x x x x x		x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x         x       x       x			x x x x x x x x x x x x x x x x x x x	Initial See a car pulling out of Nechning         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow moving tractor trailers going up the hill.         Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widened as well as lessened by removing and reshaping the adjoining hillside. I would not want to live in Goheenville as is.         This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out onto 28/66.         There is limited opportunities to pass slow moving wehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving trucks you have to follow them for approximately ten miles to pass them. Cutting a new road to the east behind the main village and between the golf course and game commission and extending the passing lanes in both directions would make the commute safer for the village residents as well as the drivers. This would also straighten the road out and eliminate several intersection especially the one near the top where Dollar General enters with	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.9006439       -79.370589         40.849456       -79.458908         40.881339       -79.39168         40.881339       -79.39168         40.999057       -79.39168         40.999055       -79.342792         40.999055       -79.342792         40.999055       -79.342792         40.999055       -79.342792	380495       point         380493       point         380497       point         380497       point         380498       point         380497       point         380498       point         380509       point         380500       point         380501       point         380502       point         380503       point         380504       point         380505       point         380506       point         380507       point         380508       point         380509       point         380509       point         380509       point         380509       point	2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 2/20/2020 1 2/20/2020 2/20/20 2/20/20 2/20/20 2/20/20 2/20/20 2/20/20 2/20/20 2/20/20 2/20/20 2	274286     Guest     There is limited sight at the Mechling Road intersection.     X     X       274286     A dangerous sharp turn and very buy intersection with cars, tractor trailers, and much farm equipment     X       274286     Need passing lanes. had a chance to do it before a few years ago and did not.     X       274286     Need passing lanes. had a chance to do it before a few years ago and did not.     X       274286     Need passing lanes. had a chance to do it before a few years ago and did not.     X       274286     Guest     bad turn either direction @ 55 mph.     X       274288     Guest     bad intersection     X       274288     Guest     needs a passing lane especially for trucks     X       274288     Guest     needs a passing lane especially for trucks     X       274288     Guest     sharp turn for tractor trailers.     X       274288     Guest     sharp turn for tractor trailers.     X		x       x       x         Image: Second state	.       .       .       .         x       .       .       .         .       <		x       x         x       x			x         x	can due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow moving tractor trailers going up the hill.         Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widened as well as lessened by removing and reshaping the adjoining hillside. I would not want to live in Goheenville as is.         This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out noto 28/66.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         there have been several accidents over the years from trucks taking this turn too fast. It need to be redesigned, widened and made less severe of a turn ie 60 degrees instead of 90,         Distant should be bypassed entirely. The passing lane ends half way up the hill so if you get stuck behind one or more slow moving trucks you have to follow them for approximately ten miles to pass them. Cutting a new road to the east behind the main village and between the golf course and game commission and extending the passing lanes in both directions would make the commute safer for the village residents as well as the drivers. This would also straighten the road out and eliminate several intersections especially the one near the top where Dollar General enters with little sight distance.	How it will impact our church and private school campus development plan.
40.850286       .79.458244         41.039369       .79.257315         40.882223       .79.390862         40.969772       .79.355557         40.906439       .79.370589         40.849456       .79.458908         40.881339       .79.39168         40.999057       .79.39168         40.999057       .79.342792         40.999055       .79.355316         40.969256       .79.355316	380495       point         380493       point         380493       point         380497       point         380498       point         380504       point         380505       point         380506       point         380507       point         380508       point         380509       point         380509       point         380509       point         380509       point         380509       point         380509       point         380508       point         380509       point	<ul> <li>2/20/2020</li> </ul>	274226     Guest     There is limited sight at the Mechling Road intersection.     X     X       274266     A dangerous sharp turn and very busy intersection with cars, tractor     X     X       274268     Need passing lanes. had a chance to do it before a few years ago and did     X     X       274273     Image: Add a chance to do it before a few years ago and did     X     X       274288     onot.     Need passing lanes. had a chance to do it before a few years ago and did     X       274284     onot.     Need passing lanes. had a chance to do it before a few years ago and did     X       274285     Guest     bad turn either direction @ 55 mph.     X       274288     Guest     needs a passing lane especially for trucks     X       274288     Guest     needs a passing lane     X       274288     Guest     needs a passing lane     X       274288     Guest     sharp turn for tractor trailers.     X       274288     Guest     sharp turn for tractor trailers.     X       274288     Guest     sharp turn for tractor trailers.     X	x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x       x         x       x       x         x       x       x         x       x       x       x         x       x       x       x         x       x       x       x         x       x       x       x         x       x       x       x         x       x       x       x         x       x       x       x       x         x       x       x       x       x       x         x       x       x       x       x       x       x         x       x       x       x       x       x       x       x	x       x       x         Image: Second	.       .       .       .         x       .       .       .         .       <		x       x       x         x       x       x			x x x x x x x x x x x x x x x x x x x	can not see a car public of the hill. This is a danger to the motoring public.         No passing lane. You often get behind slow moving tractor trailers going up the hill.         Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widened as well as lessened by removing and reshaping the adjoining hillside. I would not want to live in Goheenville as is.         This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out not 28/66.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass them of a paproximately the miles to pass them.         Cutting a ne ends half way up the hill so if you get stuck behind one or more slow moving trucks you have to follow them f	How it will impact our church and private school campus development plan.
40.850286       .79.458244         41.039369       .79.257315         40.882223       .79.390862         40.969772       .79.355557         40.9006439       .79.370589         40.849456       .79.458908         40.874784       .79.408073         40.881339       .79.39168         40.909057       .79.39168         40.999055       .79.342792         40.999055       .79.355316         40.969256       .79.355316         40.969256       .79.074745	380495       point         380493       point         380497       point         380498       point         380499       point         380490       point         380491       point         380492       point         380493       point         380494       point         380504       point         380505       point         380506       point         380507       point         380508       point         380509       point         380509       point         380509       point         380509       point         380509       point         380509       point         380508       point         380509       point	<ul> <li>2/20/2020</li> </ul>	274256     Guest     There is limited sight at the Mechling Road intersection.     X     X       274266     A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm coujoment.     X     X       274268     Need passing lanes. had a chance to do it before a few years ago and did not.     X     X       274273     Image: Add a chance to do it before a few years ago and did not.     X     X       274288     Guest     bad turn either direction @ 55 mph.     X     X       274288     Guest     bad turn either direction @ 55 mph.     X     X       274288     Guest     needs a passing lane especially for trucks     X     X       274288     Guest     needs a passing lane especially for trucks     X     X       274288     Guest     needs a passing lane     X     X       274288     Guest     sharp turn for tractor trailers.     X     X       274288     Guest     sharp turn for tractor trailers.     X     X       274288     Guest     sharp turn for tractor trailers.     X     X       274288     Guest     This area needs a bypass.     X     X       274288     Guest     This area needs a bypass.     X     X       274288     Guest     This area needs a bypass.     X	x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x         x       x       x         x       x       x         x       x       x         x       x       x       x         x       x       x       x         x       x       x       x         x       x       x       x         x       x       x       x         x       x       x       x         x       x       x       x       x         x       x       x       x       x       x         x       x       x       x       x       x       x         x       x       x       x       x       x       x       x	x       x       x         Image: Second state	.       .       .         x       .       .         x       .       .         .       .       .		x       x       x         x       x       x			x       x         x       x	Lan hot see a Lan public of Mechning road due to the crest of the hill. This is a danger to the motoring public.         No passing lane. You often get behind slow moving tractor trailers going up the hill.         Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widened as well as lessened by removing and reshaping the adjoining hillside. I would not want to live in Goheenville as is.         This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out onto 28/66.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There ave been several accidents over the years from trucks taking this turn too fast. It need to be redesigned, widened and made less severe of a turn ie 60 degrees instead of 90,         Distant should be bypassed entirely. The passing lane ends half way up the hill so if you get stuck behind one or more slow moving trucks you have to follow them for approximately ten miles to pass them. Cutting a new road to the east behind the main village and between the golf course and game commission and extending the passing lanes in both directions would make the commute safer for the village residents as well as the drivers. This would also straighten the road	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.9006439       -79.370589         40.849456       -79.458908         40.881339       -79.39168         40.999057       -79.39168         40.999057       -79.39168         40.999057       -79.342792         40.999057       -79.342792         40.999055       -79.355316         40.969256       -79.355316         41.071988       -79.237402         41.002894       -79.341557	380495       point         380493       point         380497       point         380498       point         380499       point         380490       point         380491       point         380492       point         380504       point         380505       point         380506       point         380507       point         380508       point         380509       point         380510       point	<ul> <li>2/20/2020</li> </ul>	274236     Guest     There is limited sight at the Mechling Road intersection.     X     X       274266     A dangerous sharp turn and very busy intersection with cars, tractor     X     X       274267     Need passing lanes. had a chance to do it before a few years ago and did     X       274273     Image: Comparison of the comparison of th	x       x         x	x       x       x       x         Image: Section of the s	.       .       .       .         x       .       .         .       .       . <td></td> <td>x       x       x         x       x       x</td> <td></td> <td></td> <td>x       x         x       x</td> <td>In this is a danger to the motoring public.         No passing lane. You often get behind slow moving tractor trailers going up the hill.         Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widened as well as lessened by removing and reshaping the adjoining hillside. I would not want to live in Goheenville as is.         This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out onto 28/66.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         there have been several accidents over the years from trucks taking this turn too fast. It need to be redesigned, widened and made less severe of a turn ie 60 degrees instead of 90,         Distant should be bypassed entirely. The passing lane ends half way up the hill so if you get stuck behind one or more slow moving trucks you have to follow them for approximately ten miles to pass them. Cutting a new road to the east behind the main village and between the golf course and game commission and extending the passing lanes in both directions would make the commute safer for the village residents as well as the drivers. This would also straighten the road out and elimitet severel intersections especially the one near the top where Dollar General enters with little sight distance.</td> <td>How it will impact our church and private school campus development plan.</td>		x       x       x         x       x       x			x       x         x       x	In this is a danger to the motoring public.         No passing lane. You often get behind slow moving tractor trailers going up the hill.         Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widened as well as lessened by removing and reshaping the adjoining hillside. I would not want to live in Goheenville as is.         This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out onto 28/66.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         there have been several accidents over the years from trucks taking this turn too fast. It need to be redesigned, widened and made less severe of a turn ie 60 degrees instead of 90,         Distant should be bypassed entirely. The passing lane ends half way up the hill so if you get stuck behind one or more slow moving trucks you have to follow them for approximately ten miles to pass them. Cutting a new road to the east behind the main village and between the golf course and game commission and extending the passing lanes in both directions would make the commute safer for the village residents as well as the drivers. This would also straighten the road out and elimitet severel intersections especially the one near the top where Dollar General enters with little sight distance.	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.900439       -79.370589         40.849456       -79.458908         40.881339       -79.39168         40.999057       -79.39168         40.999057       -79.39168         40.999057       -79.342792         40.999055       -79.342792         40.999055       -79.355316         40.969256       -79.355316         41.160304       -79.237402         41.071988       -79.237402         41.002894       -79.341557	380495       point         380493       point         380493       point         380497       point         380498       point         380499       point         380490       point         380501       point         380502       point         380503       point         380504       point         380505       point         380506       point         380507       point         380508       point         380509       point         380509       point         380509       point         380509       point         380509       point         380510       point	<ul> <li>2/20/2020</li> <li>3/4</li> </ul>	274256     Guest     There is limited sight at the Meching Road intersection.     x     x       274266     A dangerous sharp turn and very busy intersection with cars, tractor trailers, and much farm equipment.     x     x       274268     Need passing lanes. had a chance to do it before a few years ago and did not.     x     x       274273     Image: Comparison of the straight of the direction @ 55 mph.     Image: Comparison of the straight of the direction @ 55 mph.     X       274288     Guest     bad intersection     X     X       274288     Guest     needs a passing lane especially for trucks     X       274288     Guest     needs a passing lane     X       274288     Guest     needs a passing lane     X       274288     Guest     needs a passing lane     X       274288     Guest     sharp turn for tractor trailers.     X       274288     Guest     sharp turn for tractor trailers.     X       274288     Guest     this area needs a bypass.     X       274288     Guest     This area needs a bypass.     X       274284     Guest     This area needs a bypass.     X       274288     Guest     This area needs a bypass.     X       274284     Guest     This area needs a bypass.     X       274284     G	x       x         x	x       x       x       x         Image: Section of the s	.       .       .       .         x       .       .         .       .       . <td></td> <td>x       x       x         x       x       x</td> <td></td> <td></td> <td>x       x         x       x</td> <td>In this is a danger to the motoring public.         No passing lane. You often get behind slow moving tractor trailers going up the hill.         Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widened as well as lessened by removing and reshaping the adjoining hillside. I would not want to live in Goheenville as is.         This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out onto 28/66.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         there have been several accidents over the years from trucks taking this turn too fast. It need to be redesigned, widened and made less severe of a turn ie 60 degrees instead of 90,         Distant should be bypassed entirely. The passing lane ends half way up the hill so if you get stuck behind one or more slow moving trucks you have to follow them for approximately ten miles to pass them. . Cutting a new road to the east behind the main village and between the golf course and game commission and extending the passing lanes in both directions would make the commute safer for the village residents as well as the drivers. This would also straighten the road out and eliminate several intersections especially the one near the top where Dollar General enters with little sight distance.</td> <td>How it will impact our church and private school campus development plan.</td>		x       x       x         x       x       x			x       x         x       x	In this is a danger to the motoring public.         No passing lane. You often get behind slow moving tractor trailers going up the hill.         Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widened as well as lessened by removing and reshaping the adjoining hillside. I would not want to live in Goheenville as is.         This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out onto 28/66.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         there have been several accidents over the years from trucks taking this turn too fast. It need to be redesigned, widened and made less severe of a turn ie 60 degrees instead of 90,         Distant should be bypassed entirely. The passing lane ends half way up the hill so if you get stuck behind one or more slow moving trucks you have to follow them for approximately ten miles to pass them. . Cutting a new road to the east behind the main village and between the golf course and game commission and extending the passing lanes in both directions would make the commute safer for the village residents as well as the drivers. This would also straighten the road out and eliminate several intersections especially the one near the top where Dollar General enters with little sight distance.	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073         40.881339       -79.39168         40.999057       -79.39168         40.999057       -79.342792         40.999057       -79.355316         40.969256       -79.3741557         40.969256       -79.3741557	380495       point         380493       point         380493       point         380494       point         380495       point         380496       point         380497       point         380508       point         380509       point         380510       point         380511       point	<ul> <li>2/20/2020</li> </ul>	224226     Guest     There is limited sight at the Mechling Road intersection.     X     X       224226     A dangerous sharp turn and very busy intersection with cars, tractor     X     X       224226     Need passing lones. had a chance to do it before a few years ago and dd     X     X       224228     Need passing lones. had a chance to do it before a few years ago and dd     X     X       224228     Image: and much fame equipment     X     X       224228     Guest     bad turn either direction @ 55 mph.     X       224288     Guest     bad intersection     X       224288     Guest     needs a passing lane especially for trucks     X       224288     Guest     needs a passing lane     X       224288     Guest     sharp turn for tractor trailers.     X       224288     Guest     sharp turn for tractor trailers.     X       224288     Guest     this area needs a bypass.     X	x       x         x	x       x       x         Image: Section of the sec	.       .       x         x       .       .         x       .       .         x       .       .         .       .       .		x       x       x         x       x       x			x       x         x       x	In the set of the full. This is a danger to the motoring public.         Image: The motoring public.	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073         40.881339       -79.39168         40.999057       -79.39168         40.999057       -79.39168         40.999057       -79.39168         40.999057       -79.39168         40.999057       -79.39168         40.999057       -79.39168         40.999057       -79.39168         40.999057       -79.342792         40.999055       -79.342792         40.969256       -79.355316         41.071988       -79.237402         41.002894       -79.341557	380495       point         380493       point         380504       point         380505       point         380506       point         380507       point         380508       point         380509       point         380509       point         380509       point         380509       point         380509       point         380509       point         380511       point	<ul> <li>2/20/2020</li> </ul>	274226     Fuere is limited sight at the Mechling Road intersection.     x     X       27426     A dangerous sharp turn and very busy intersection with cars, tractor     x     X       27426     Need passing lanes. had a chance to do it before a few years ago and dd     x     X       274273     Image: and much fame equipment     X     X       274284     Suest     bad turn either direction @ 55 mph.     X       274285     Guest     bad intersection     X       274284     Guest     bad intersection     X       274285     Guest     bad intersection     X       274286     Guest     needs a passing lane especially for trucks     X       274286     Guest     needs a passing lane     X       274286     Guest     harp turn for tractor trailers.     X       274288     Guest     tharp turn for tractor trailers.     X       274288     Guest     tharp turn for tractor trailers.     X       274288     Guest     tharp turn for tractor trailers.     X       274288     Guest     this area needs a bypass.     X       274284     Guest     This area needs a bypass.     X       274284     Guest     This area needs a bypass.     X       274291     Near the wagon wheel restaurant <t< td=""><td>x     x       x    </td><td>x       x       x       x         Image: Section of the s</td><td>.       .       x         x       .       .         x       .       .         .       .       .</td><td></td><td>x       x         x</td><td></td><td></td><td>x       x         x       x</td><td>Lainto: see a Lai Dung Gut Or Mechning         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside.         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         there have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         90,         Distant should be bypassed entirely. The         passing lane ends half way up the hill so if         you get stuck behind one or more slow</td><td>How it will impact our church and private school campus development plan.</td></t<>	x     x       x	x       x       x       x         Image: Section of the s	.       .       x         x       .       .         x       .       .         .       .       .		x       x         x			x       x         x       x	Lainto: see a Lai Dung Gut Or Mechning         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillside.         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles especially trucks on this         road whether travelling North or South.         there have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         90,         Distant should be bypassed entirely. The         passing lane ends half way up the hill so if         you get stuck behind one or more slow	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.881339       -79.39168         40.881339       -79.39168         40.999057       -79.39168         40.999057       -79.342792         40.999057       -79.355316         40.969256       -79.355316         41.160304       -79.074745         41.002894       -79.341557	380495       point         380493       point         380504       point         380505       point         380506       point         380507       point         380508       point         380509       point         380509       point         380509       point         380510       point         380511       point	<ul> <li>2/20/2020</li> <li>3/1</li> </ul>	274226     Guest     There is limited sight at the Mechling Road intersection.     X     X       274226     A dangerous sharp turn and very busy intersection with cars, tractor     X     X       27428     Need passing lanes. had a chance to do it before a few years ago and dd     X     X       27428     Need passing lanes. had a chance to do it before a few years ago and dd     X     X       27428     Suest     bad turn either direction @ 55 mph.     X       27428     Guest     bad intersection     X       27428     Guest     needs a passing lane especially for trucks     X       27428     Guest     needs a passing lane     X       27428     Guest     sharp turn for tractor trailers.     X       27428     Guest     sharp turn for tractor trailers.     X       27428     Guest     This area needs a bypass.     X       27428     Guest </td <td>x       x         x       x</td> <td>x       x       x         Image: Second state state</td> <td>.       .       x         x       .       .         x       .       x         .       .       x         .       .       .</td> <td></td> <td>xx</td> <td></td> <td></td> <td>x       x         x       x</td> <td>Lai Hot see a car public.         Image: A car public car car car car car car car car car ca</td> <td>How it will impact our church and private school campus development plan.</td>	x       x         x       x	x       x       x         Image: Second state	.       .       x         x       .       .         x       .       x         .       .       x         .       .       .		xx			x       x         x       x	Lai Hot see a car public.         Image: A car public car car car car car car car car car ca	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.881339       -79.458908         40.881339       -79.39168         40.999057       -79.39168         40.999057       -79.342792         40.999057       -79.342792         40.999057       -79.355316         40.969256       -79.355316         41.160304       -79.237402         41.002894       -79.341557	380495       point         380493       point         380497       point         380498       point         380497       point         380498       point         380499       point         380504       point         380505       point         380506       point         380507       point         380508       point         380509       point         380510       point         380511       point	<ul> <li>2/20/2020</li> </ul>	274256     Guest     There is limited sight at the Meching Road intersection.     X     X       274266     A dangerous sharp turn and very busy intersection with cars, tractor     X     X       274276     Need passing lanes. Ind a danace to do it before a few years ago and did     X     X       274278     Image: Anima danace to do it before a few years ago and did     X     X       274278     Image: Anima danace to do it before a few years ago and did     X     X       274288     Guest     bad turn either direction @ 55 mph.     X     X       274288     Guest     bad intersection     X     X       274288     Guest     needs a passing lane especially for trucks     X     X       274288     Guest     needs a passing lane especially for trucks     X     X       274288     Guest     needs a passing lane     X     X       274288     Guest     needs a passing lane     X     X       274288     Guest     parp turn for tractor trailers.     X     X       274288     Guest     this area needs a bypass.     X     X       274288     Guest     This area needs a bypass.     X     X       274288     Guest     This area needs a bypass.     X     X       274292     Guest     T		x       x       x       x         x       x       x <td>.       .       x         x       .       .</td> <td></td> <td>x       x         x</td> <td></td> <td></td> <td>x       x         x       x</td> <td>Lain to: See a Lai pulming Out of Mechning         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillide. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles specially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles despecially trucks on this         road whether travelling North or South.         there have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         90,         Distant should be bypassed entirely. The         passing lane ends half way up the hill so if         you get stuck behind</td> <td>How it will impact our church and private school campus development plan.</td>	.       .       x         x       .       .		x       x         x			x       x         x       x	Lain to: See a Lai pulming Out of Mechning         road due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and reshaping the adjoining         hillide. I would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving vehicles specially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving vehicles despecially trucks on this         road whether travelling North or South.         there have been several accidents over the         years from trucks taking this turn too fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         90,         Distant should be bypassed entirely. The         passing lane ends half way up the hill so if         you get stuck behind	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073         40.881339       -79.39168         40.999057       -79.39168         40.999057       -79.342792         40.999057       -79.342792         40.999057       -79.355316         40.969256       -79.355316         41.160304       -79.237402         41.002894       -79.341557	380495       point         380493       point         380493       point         380494       point         380495       point         380496       point         380497       point         380498       point         380499       point         380504       point         380505       point         380506       point         380507       point         380508       point         380509       point         380510       point         380511       point	<ul> <li>2/20/2020</li> </ul>	274256     Guest     There is limited sight at the Mechling Road intersection.     X     X       274266     A dangerous sharp turn and very busy intersection with cars, tractor     X     X       274286     Need passing lines. had a chance to do it before a few years ago and did     X     X       274287     not.     X     X       274288     Guest     bad turn either direction @ 55 mph.     X       274288     Guest     bad intersection     X       274288     Guest     needs a passing line especially for trucks     X       274288     Guest     needs a passing line     X       274288     Guest     sharp turn for tractor trailers.     X       274288     Guest     sharp turn for tractor trailers.     X       274288     Guest     this area needs a bypass.     X       274284     Guest     This area needs a bypass.     X       274284     Liset the wagon wheel restaurant     X		x       x       x       x         Image: Second sec	.       .       .       .         x       .       .       .         x       .       .       .         .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         .       .       .       .       .         . </td <td></td> <td>x       x         x</td> <td></td> <td></td> <td>x x x x x x x x x x x x x x x x x x x</td> <td>road due to the creat of the hill. This is a danger to the motoring public.  No passing lane. You often get behind slow moving tractor trailers going up the hill.  Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widened as well as lessened by removing and reshaping the adjoining hillisfie. I would not want to live in Goheenville as is. This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out onto 28/66. There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South. There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South. There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South. There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South. There is limited opportunities to pass slow moving vehicles taking this turn too fast. It need to be redesigned, widened and made less severe of a turn le 60 degrees instead of 90, Distant should be bypassed entirely. The passing lane ends half way up the hill so if you get stuck behind one or more slow moving trucks you have to follow them for approximately ten miles to pass them. Cutting a new road to the east behind the main village and between the golf course and game commission and extending the passing lanes in both directions would make the commute safer for the village residents as well as the drivers. This would also straighten the road out and eliminate several intersections especially the one near the top where Dollar General enters with little sight distance. There are a number of small communities on Route 28 from New Bethlehem to Brookville. Many of them have reduced speed limit, however the Shannondale area of Route 28 toil has a speed limit that is too fast for tractor trailers, log trucks, tan</td> <td>How it will impact our church and private school campus development plan.</td>		x       x         x			x x x x x x x x x x x x x x x x x x x	road due to the creat of the hill. This is a danger to the motoring public.  No passing lane. You often get behind slow moving tractor trailers going up the hill.  Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widened as well as lessened by removing and reshaping the adjoining hillisfie. I would not want to live in Goheenville as is. This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out onto 28/66. There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South. There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South. There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South. There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South. There is limited opportunities to pass slow moving vehicles taking this turn too fast. It need to be redesigned, widened and made less severe of a turn le 60 degrees instead of 90, Distant should be bypassed entirely. The passing lane ends half way up the hill so if you get stuck behind one or more slow moving trucks you have to follow them for approximately ten miles to pass them. Cutting a new road to the east behind the main village and between the golf course and game commission and extending the passing lanes in both directions would make the commute safer for the village residents as well as the drivers. This would also straighten the road out and eliminate several intersections especially the one near the top where Dollar General enters with little sight distance. There are a number of small communities on Route 28 from New Bethlehem to Brookville. Many of them have reduced speed limit, however the Shannondale area of Route 28 toil has a speed limit that is too fast for tractor trailers, log trucks, tan	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.881339       -79.39168         40.881339       -79.39168         40.999057       -79.39168         40.999057       -79.342792         40.999057       -79.342792         40.999057       -79.355316         40.969256       -79.355316         41.160304       -79.237402         41.002894       -79.341557	380495       point         380493       point         380493       point         380494       point         380495       point         380496       point         380497       point         380498       point         380499       point         380490       point         380504       point         380505       point         380506       point         380507       point         380508       point         380509       point <td><ul> <li>2/20/2020</li> <li>3/1</li> </ul></td> <td>274226     Guest     There is limited sight at the Maching Road intersection.     X     X       274226     A dangerous sharp turn and very busy intersection with cars, tractor     X     X       274226     Need passing lanes. Ind a charne to do it before a few years ago and did     X     X       274228     Need passing lanes. Ind a charne to do it before a few years ago and did     X     X       274228     Duel turn either direction @ 55 mph.     X     X       274228     Guest     Ded turn either direction @ 55 mph.     X       274228     Guest     needs a passing lane especially for trucks     X       274228     Guest     needs a passing lane     X       274228     Guest     This area needs a bypass.     X       274228     Guest     This area needs a bypass.     X       274234     Neer the</td> <td></td> <td>x       x       x         Image: Second second</td> <td>.       .       .       .         x       .       .<td></td><td>xxx</td><td></td><td></td><td>x       x         x</td><td>Call Not see a Car pump group to Meeting         read due to the crest of the hill. This is a danger to the motoring public.         No passing lane. You often get behind slow moving tractor trailers going up the hill.         Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widered as well as lessened by removing and respains the adjoining hillside. I would not want to live in Goheenville as is.         This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out onto 28/66.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There have been several accidents over the years from trucks taking this turn to fast. It need to be redesigned, widened and made less severe of a turn ie 60 degrees instead of 90.         Distant should be bypassed entirely. The passing lane ends half way up the hill so if you get stuck behind one or more slow moving trucks you have to follow them for approximately ten miles to pass them.         Cutting a new road to the east behind the main village and between the golf course and game commission and extending the passing lanes in both directions would make the commute safer for the village residents as swell as the drivers. This would also straighten the road out and eliminate several intersection sepecially the one near the top where Dollar Gene</td><td>How it will impact our church and private school campus development plan.</td></td>	<ul> <li>2/20/2020</li> <li>3/1</li> </ul>	274226     Guest     There is limited sight at the Maching Road intersection.     X     X       274226     A dangerous sharp turn and very busy intersection with cars, tractor     X     X       274226     Need passing lanes. Ind a charne to do it before a few years ago and did     X     X       274228     Need passing lanes. Ind a charne to do it before a few years ago and did     X     X       274228     Duel turn either direction @ 55 mph.     X     X       274228     Guest     Ded turn either direction @ 55 mph.     X       274228     Guest     needs a passing lane especially for trucks     X       274228     Guest     needs a passing lane     X       274228     Guest     This area needs a bypass.     X       274228     Guest     This area needs a bypass.     X       274234     Neer the		x       x       x         Image: Second	.       .       .       .         x       .       . <td></td> <td>xxx</td> <td></td> <td></td> <td>x       x         x</td> <td>Call Not see a Car pump group to Meeting         read due to the crest of the hill. This is a danger to the motoring public.         No passing lane. You often get behind slow moving tractor trailers going up the hill.         Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widered as well as lessened by removing and respains the adjoining hillside. I would not want to live in Goheenville as is.         This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out onto 28/66.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There have been several accidents over the years from trucks taking this turn to fast. It need to be redesigned, widened and made less severe of a turn ie 60 degrees instead of 90.         Distant should be bypassed entirely. The passing lane ends half way up the hill so if you get stuck behind one or more slow moving trucks you have to follow them for approximately ten miles to pass them.         Cutting a new road to the east behind the main village and between the golf course and game commission and extending the passing lanes in both directions would make the commute safer for the village residents as swell as the drivers. This would also straighten the road out and eliminate several intersection sepecially the one near the top where Dollar Gene</td> <td>How it will impact our church and private school campus development plan.</td>		xxx			x       x         x	Call Not see a Car pump group to Meeting         read due to the crest of the hill. This is a danger to the motoring public.         No passing lane. You often get behind slow moving tractor trailers going up the hill.         Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widered as well as lessened by removing and respains the adjoining hillside. I would not want to live in Goheenville as is.         This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out onto 28/66.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There is limited opportunities to pass slow moving vehicles especially trucks on this road whether travelling North or South.         There have been several accidents over the years from trucks taking this turn to fast. It need to be redesigned, widened and made less severe of a turn ie 60 degrees instead of 90.         Distant should be bypassed entirely. The passing lane ends half way up the hill so if you get stuck behind one or more slow moving trucks you have to follow them for approximately ten miles to pass them.         Cutting a new road to the east behind the main village and between the golf course and game commission and extending the passing lanes in both directions would make the commute safer for the village residents as swell as the drivers. This would also straighten the road out and eliminate several intersection sepecially the one near the top where Dollar Gene	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.874784       -79.408073         40.881339       -79.39168         40.999057       -79.39168         40.999057       -79.342792         40.999057       -79.355316         40.969256       -79.355316         41.160304       -79.237402         41.002894       -79.341557         41.002894       -79.341557	380495       point         380493       point         380493       point         380494       point         380495       point         380496       point         380497       point         380498       point         380504       point         380505       point         380506       point         380507       point         380508       point         380509       point         380510       point         380511       point         380511       point	<ul> <li>2/20/2020</li> <li>3/1</li> </ul>	27425     Guest     There is limited sight at the Mechling Road intersection.     x     x       27426     A dargepoint sharp turn and very bury intersection with cars, tractor trailers, and much farm equipment     x     x       27428     Need parsing turns, had a chance to doit before a few years ago and did one.     x     x       274284     Guest     bad turn either direction @ 55 mph.     x     x       274288     Guest     bad intersection     x     x       274288     Guest     needs a passing lane especially for trucks     x     x       274288     Guest     needs a passing lane especially for trucks     x     x       274288     Guest     needs a passing lane     x     x       274288     Guest     sharp turn for tractor trailers.     x     x       274288     Guest     this area needs a bypass.     x     x       274288     Guest     This area needs a bypass.     x     x       274289     Guest     This area needs a bypass.     x     x       274281     Guest     This area needs a bypass.     x     x       274281     Guest     This area needs a bypass.     x     x       274281     Guest     This area needs a bypass.     x       274331     Herei the wagon wheel		x       x       x         Image: Second	.       .       x         x       .       .		x       x       x         x       x       x			x       x         x	Call files are a call pointing         read due to the crest of the hill. This is a         danger to the motoring public.         No passing lane. You often get behind slow         moving tractor trailers going up the hill.         Regardless of speed limit people will take         this turn as fast as they think they can. This         turn should be widened as well as lessened         by removing and resphang the adjoining         hillside. 1 would not want to live in         Goheenville as is.         This intersection is at the top of a hill next         to a church. There is very little sight if you         are pulling out onto 28/66.         There is limited opportunities to pass slow         moving whicles especially trucks on this         road whether travelling North or South.         There is limited opportunities to pass slow         moving whicles especially trucks on this         road whether travelling North or South.         there have been several accidents over the         years from trucks taking this turn to fast. It         need to be redesigned, widened and made         less severe of a turn ie 60 degrees instead of         gon         Distant should be bypassed entirely. The         passing lane ends half way up the hill so if         you get stuck behind one or more slo	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.906439       -79.370589         40.849456       -79.458908         40.881339       -79.39168         40.999057       -79.39168         40.999057       -79.39168         40.999057       -79.342792         40.969256       -79.355316         41.100304       -79.074745         41.002894       -79.341557	380495point380495point380497point380497point380498point380504point380505point380506point380507point380508point380509point	<ul> <li>2/20/2020</li> <li>3/1</li> <li>3/1</li> <li>4/1</li>     &lt;</ul>	27425     Guest     There is limited sight at the Mechling Road intersection.     x     x       27426     A dargerous shurp turn and very bury intersection with car, tractor trailers, and much furm equipment.     x     x       27428     Need passing lanes, had a charce to do it before a few years ago and did not.     x     x       27428     Image of the state of the		x       x       x         Image: Second	.       .       .       .         x       <		x       x       x         x       x       x			x       x         x	read due to the crest of the hill. This is a danger to the motoring public.	How it will impact our church and private school campus development plan.
40.850286       -79.458244         41.039369       -79.257315         40.882223       -79.390862         40.969772       -79.355557         40.909439       -79.370589         40.849456       -79.458908         40.881339       -79.39168         40.999057       -79.39168         40.999057       -79.39168         40.999057       -79.342792         40.999057       -79.342792         40.999055       -79.355316         41.160304       -79.074745         41.002894       -79.3341557	380495       point         380493       point         380497       point         380498       point         380497       point         380498       point         380504       point         380505       point         380506       point         380507       point         380508       point         380509       point <td><ul> <li>2/20/2020</li> <li>3/1</li> </ul></td> <td>27428     Guest     There is limited sight at the Mechling Read interaction.     x     x       27428     Adargerous sharp turn and very bury intersection with cars, tractor trailers, and much fame explained.     x     x       27428     Need passing lanes, had a chance to do it before a few years ago and did not.     x     x       27428     Guest     bad turn either direction @ 55 mph.     X     x       27428     Guest     bad intersection     x     x       27428     Guest     bad intersection     x     x       27428     Guest     bad intersection     x     x       27428     Guest     needs a passing lane especially for trucks     x     x       27428     Guest     needs a passing lane     x     x       27428     Guest     sharp turn for tractor trailers.     x     x       27428     Guest     This area needs a bygass.     x     x       27428     Guest     Nort inter wagon wheet restaurut     x</td> <td></td> <td>x       x       x         Image: Second second</td> <td>.       .       .       .         x       .       .<td></td><td>x       x         x</td><td></td><td></td><td>x       x         x</td><td>read use to the crest of the hill. This is a danger to the motoring public.  No passing lane. You often get behind slow moving tractor trailers going up the hill.  Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widened as well as lessened by removing and reshaping the adjoining hillside. I would not want to live in Gobnerwille as is. This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out onto 28/66. There is limited opportunities to pass slow moving webicles especially trucks on this road whether travelling North or South. There is limited opportunities to pass slow moving webicles especially trucks on this road whether travelling North or South. There is form truck staing this turn to fast. It need to be redesigned, widened and made less severe of a turn le 60 degrees instead of 90. Distant should be bypassed entirely. The passing lane ends half way up the hills oif you get stuck behind one or more slow moving trucks you have to follow them for approximately ten miles to pass them. Cutting a new road to the east behind the main village and between the golf course and game commission and extending the passing lane in both directions would make the commute safer for the village residents as well as the drivers. This would also straighten the road out and eliminate several intersection sepecially the one near the top where Dollar General enters with little sight distance. There are a number of small communities on Route 28 from New Bethlehem to Brookville. Many of them have reduced speed limits, however the Shannondale area of Route 28 tom the safe. It is dangerous even for School buses that have to stop on Route 28. There have been many accidents. For more information about this dangerous intersection here on this flat area of Route 28. There have been many accidents. For more information about this dangerous area, contact the Road Supervisors of PennDOT in Indiana, Pa. at 724-357-2800.</td><td>How it will impact our church and private school campus development plan.</td></td>	<ul> <li>2/20/2020</li> <li>3/1</li> </ul>	27428     Guest     There is limited sight at the Mechling Read interaction.     x     x       27428     Adargerous sharp turn and very bury intersection with cars, tractor trailers, and much fame explained.     x     x       27428     Need passing lanes, had a chance to do it before a few years ago and did not.     x     x       27428     Guest     bad turn either direction @ 55 mph.     X     x       27428     Guest     bad intersection     x     x       27428     Guest     bad intersection     x     x       27428     Guest     bad intersection     x     x       27428     Guest     needs a passing lane especially for trucks     x     x       27428     Guest     needs a passing lane     x     x       27428     Guest     sharp turn for tractor trailers.     x     x       27428     Guest     This area needs a bygass.     x     x       27428     Guest     Nort inter wagon wheet restaurut     x		x       x       x         Image: Second	.       .       .       .         x       .       . <td></td> <td>x       x         x</td> <td></td> <td></td> <td>x       x         x</td> <td>read use to the crest of the hill. This is a danger to the motoring public.  No passing lane. You often get behind slow moving tractor trailers going up the hill.  Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widened as well as lessened by removing and reshaping the adjoining hillside. I would not want to live in Gobnerwille as is. This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out onto 28/66. There is limited opportunities to pass slow moving webicles especially trucks on this road whether travelling North or South. There is limited opportunities to pass slow moving webicles especially trucks on this road whether travelling North or South. There is form truck staing this turn to fast. It need to be redesigned, widened and made less severe of a turn le 60 degrees instead of 90. Distant should be bypassed entirely. The passing lane ends half way up the hills oif you get stuck behind one or more slow moving trucks you have to follow them for approximately ten miles to pass them. Cutting a new road to the east behind the main village and between the golf course and game commission and extending the passing lane in both directions would make the commute safer for the village residents as well as the drivers. This would also straighten the road out and eliminate several intersection sepecially the one near the top where Dollar General enters with little sight distance. There are a number of small communities on Route 28 from New Bethlehem to Brookville. Many of them have reduced speed limits, however the Shannondale area of Route 28 tom the safe. It is dangerous even for School buses that have to stop on Route 28. There have been many accidents. For more information about this dangerous intersection here on this flat area of Route 28. There have been many accidents. For more information about this dangerous area, contact the Road Supervisors of PennDOT in Indiana, Pa. at 724-357-2800.</td> <td>How it will impact our church and private school campus development plan.</td>		x       x         x			x       x         x	read use to the crest of the hill. This is a danger to the motoring public.  No passing lane. You often get behind slow moving tractor trailers going up the hill.  Regardless of speed limit people will take this turn as fast as they think they can. This turn should be widened as well as lessened by removing and reshaping the adjoining hillside. I would not want to live in Gobnerwille as is. This intersection is at the top of a hill next to a church. There is very little sight if you are pulling out onto 28/66. There is limited opportunities to pass slow moving webicles especially trucks on this road whether travelling North or South. There is limited opportunities to pass slow moving webicles especially trucks on this road whether travelling North or South. There is form truck staing this turn to fast. It need to be redesigned, widened and made less severe of a turn le 60 degrees instead of 90. Distant should be bypassed entirely. The passing lane ends half way up the hills oif you get stuck behind one or more slow moving trucks you have to follow them for approximately ten miles to pass them. Cutting a new road to the east behind the main village and between the golf course and game commission and extending the passing lane in both directions would make the commute safer for the village residents as well as the drivers. This would also straighten the road out and eliminate several intersection sepecially the one near the top where Dollar General enters with little sight distance. There are a number of small communities on Route 28 from New Bethlehem to Brookville. Many of them have reduced speed limits, however the Shannondale area of Route 28 tom the safe. It is dangerous even for School buses that have to stop on Route 28. There have been many accidents. For more information about this dangerous intersection here on this flat area of Route 28. There have been many accidents. For more information about this dangerous area, contact the Road Supervisors of PennDOT in Indiana, Pa. at 724-357-2800.	How it will impact our church and private school campus development plan.

									Especially in the summer when traffic is high	I would travel more often if the road didn't get so congested. In
40.971049 -79.352241	374447 point	2/21/2020	274354       This is a tough spot to get out onto the road from sweet delights. We stop         274354       there every trip to cooks forest.		X     The current route slows traffic as	x x	x		its dangerous due to turning and stopping vehicles.	the summer the traffic backs up at the stop lights.
					it travels trough towns and cities while also adding to accidents. This three city stretch would be a					
41.001027 -79.333107	380515 point	2/21/2020	274366 A main road going through towns and cities.		great place for a new section which could start in state game X lands.	x x x x	x x x	x	All of these problems beg to be addressedby a new section that bypasses this currentXsection.	
40.82623       -79.481911         41.01447       -79.292525	377142 point 380519 point	2/22/2020 2/22/2020	274389       Guest		X         Image: Constraint of the second secon	X	X X	X	X     X       X     X       No should to drive around debris. People	
41.128364 -79.179024	380520 point	2/22/2020	274407       Run off always leaving rock debris in roadway       X         This area should have a passing zone because of semi traffic. There was a       Image: Constraint of the second seco		x	x x		x x	travel so fast and suddenly have to stop when the come upon the debris.	
40.876953 -79.398272	380521 point	2/22/2020	good opportunity to widen the road when they redid the road a few years back. The hills going both ways have the semi's at times going 25 mph 274414 which holds up alot of traffic				x x		x	
40.070555 75.550272										We need there to be a route that carries trucks , commuters, travelers around New Pothlohom
										New Bethlehem should be used as a small town for the residents
41.002134 -79.330763	380538 point	2/23/2020	273737 X X	X X X	X X X		x x x	X IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII		of the area. Route 28 needs to bypass the whole New Bethlehem/south
										Bethlehem, Hawthorn, Alcola area. This is a residential area not an area that should be used as
41.011526 -79.287419	380539 point	2/23/2020	273737 X X	x x	x x	x x		x x		the main route between Kittanning 28/422 to get to 80.
41.015055 75.274710		2/23/2020								We really need to move the
40.999246 -79.341637	380541 point	2/23/2020	273737 X	x	Access to doctors     X				Narrow, with no safe places to pull off the	all the small towns along route 28
									road completely DEER INFESTED Extremely dark at night because of dense	
			Narrow Limited Sightlines						forest overgrowth DEER INFESTED Limited Visibility	Just widening the existing road does not address the dangerous cuerves and wooded areas. This
40.905177 -79.371267	380542 point	2/23/2020	274453     Deer infested     X       273737     Dangerous hill     X	x x x	X X Weekly	x x	x x	x	X     X   This area needs to be bypassed DEER INFESTED	area should be bypassed entirely, not merely "upgraded."
					This area is especially dangerous in the summer. 28 is extremely buck with traffic going to cook					
40.970853 -79.352881	380544 point	2/23/2020	273737 Dangerous intersection/ dangerous area to access businesses X X X	x x x	X     of the putneyville road.     X	x	x			
40.892616       -79.376681         40.867388       -79.432635	380547 point 380548 point	2/23/2020	273737     X     X       273737     X     X		Image: Constraint of the second se		x x x x x x x x x x x x x x x x x x x		Allegheny County requires this road, unless	
									one has the time to take US119 & US22. There is a lot of commercial traffic on PA 28 between Pittsburgh and I-80, and there is no	
					Traveling from DuBeis to				suitable connector between the two for traffic destinations to the east of DuBois.	
					Northern Allegheny County requires this road, unless one has				An Interstate Specification divided highway, similar to the recent development of US-46	The current right of way mostly
					the time to take US119 & US22. There is a lot of commercial traffic on PA 28 between Pittsburgh and				in West Virginia would provide an economic boon to the communities along the existing highway, which have to risk life and limb	follows the 1830-vintage horse trails and Indian paths that followed Red Bank Creek.
					I-80, and there is no suitable connector between the two for traffic destinations to the east of				(and DEER INFESTATIONS) to travel to "the big city" for medical, educational and business needs	Today's heavy truck traffic
			PA 28 from Brookville to Distant is a primative back road, with heavy traffic and heavily DEER INFESTED.		DuBois.				Simply widening the existing roadway would	route passes through, as well as posing the risk of an eventual haz-
			As the road winds and twists along the serpentine meanders of Red Bank Creek, and winds and weaves its way through numerous small villages, the		An Interstate Specification divided highway, similar to the recent development of US-46 in				be a colossal waste of taxpayer money. Simply widening the existing roadway would do absolutely NOTHING to improve safety or	mat spill into Red Bank Creek, which would be a tremendous catastrophe, given that the ONLY
			limited sightlines carry the potential for accidents with other vehicles and pedestrians.		West Virginia would provide an economic boon to the				address the concerns of limited sightlines and DEER INFESTATION, both of which become prohibitive issues at night DA 28 is	access road for responders would be blocked by the draffic backing
			Moreover, the roadway is very narrow and hilly and there is insufficient shoulder area to safely pull off the road should the need arise.		highway, which have to risk life and limb (and DEER				a very important highway and deserves a new corridor.	wreck.
41.129537 -79.17707	380549 point	2/23/2020	This ancient footpath needs to be relegated to a secondary status, and an274453entirely new corridor needs to be developed,.X	x	INFESTATIONS) to travel to "the big city" for medical, educational         X       and business needs.	x x x x	x x x	x x x	KFeel free to toll it like PA-43 and PA-66 inXXsouthwestern PA. I would GLADLY pay a toll	This road is almost 100 years overdue for realignment and replacement!
									Were Rte.28 merges at Milville either way ramps are extremely congested plus vision is limited. Also seems merging is excessive.	
40 486057 70 0704 40	200550 moint	2/22/2225	274457 Bottle Neck						The entrance ramp from Millvale to Rte.28 North is very dangerous due to line of	
40.486037       -79.372148         40.818013       -79.489565         40.907689       -79.370517	380550 point 380551 point 380552 point	2/23/2020 2/23/2020 2/23/2020	274437     Bottle Neck     X       274492     X     X       274492     X     X       274492     X     X		A       A       A         A       A       A         A       A       A         A       A       A         A       A       A         A       A       A         A       A       A         A       A       A         A       A       A         A       A       A         A       A       A         A       A       A         A       A       A         A       A       A	X         X         X           X         X         X           X         X         X			X     Vision, excess speed,       X     X       X     X	
40.978177 -79.345199 40.999273 -79.342823	380553 point 380554 point	2/23/2020	274492 X 274492 X		x	x x x x			X trucks turning curve use both lanes and go too fast	
41.039993 -79.257207	380555 point	2/23/2020	274492 X		X X		x x x			It needs to be a 4 lane highway that is routed through
										undeveloped land near the original route of travel. There is a
										the travel corridor that could be used to route a 4 lane without
40.854337 -79.45156	380486 point	2/24/2020	274519 X X	x	x x	x x	x x x	x x	x x	disturbing existing homes and businesses. Get it built !! Bypass New
41.001948 -79.338256	380565 point	2/24/2020	274548       Bypass New Bethlehem.       X       X         Improving this corridor couldn't come soon enough. They've been working on improving Rt 28 since I was a kid. Such an improvement when       Improving Rt 28 since I was a kid. Such an improvement when       Improving Rt 28 since I was a kid. Such an improvement when	x		x	x x x			Bethlehem
41.056868 -79.243837	380567 point	2/24/2020	274551 they opened the four lane between Tarentum and Brackenridge. X		x I I I I I I I I I I I I I I I I I I I	x x	x	X	X     X     The safety of the route needs improvement       This corridor is used by so many different       turnes of treffic and is as beguilty populated	
									with wildlife. If the people that use this corridor on a daily basis treat it with care,	
			The entire route 28 from Kittanning to Brookville is a rural route and should be treated as such. The speed limit should be regulated to 45 mph. There is truck traffic, pedestrian traffic and agricultural traffic. There						reduce their speeds, and have patience, we will all benefit. These are small towns with schools, family farms, and mom and pop	
40.942943 -79.363316	380586 point	2/24/2020	274567       should be no expansion to ruin our beautiful landscape.       X       X		x     x     x       Image: Im		x x		stores. Do not destroy what we hold dear! From New Beth to Kittanning in either direction is frustrating. Slow moving	
									vehicles and limited opportunities for passing. I can't imagine the positive	
									northern towns like clarion and brookville if this stretch was 4 lanes both directions.	
40.968978 -79.356199	380642 point	2/25/2020	The entire stretch between New Beth and Kittanning. Both North and         274628         South directions.		x x	x x x	x x x	x x	Going North is worse than South due far lessXpassing opportunities.This area has the worst congestion/no	I am happy that it is being looked into.
40.867571 -79.432839	380644 point	2/25/2020	274628       The 5-8 miles from Kittanning or to Kittanning.         Image: Constraint of the second sec		X     X       Image: Second sec	x         x         x           Image: I	x x x	x         x	X     passing lanes for either direction.       Ideally this entire route would be a 4 lane       divided highway	thanks
40.051600 70.05155			274628						should be NO TRUCKS! Trucks should use I- 79 to go south. This stretch should be for	
אפטבכציט <del>י</del> -/9.364588	380646 point	2/25/2020	2/4020       Entire stretch between New Beth and Kittanning         Better corridor will increase travel and tourism. I have traveled this route         hundreds of times. It is scenic and well maintained even in winter.						A     X     Cars and local delivery only.	tnanks
41.011143 -79.305115	380655 point	2/25/2020	274650       Upgrading will only increase it's value and usage       X         The whole route needs upgraded! I still can't understand why a climbing lane wasn't installed at the bottom of the hill leading up to Orchard Hills       X							
			when they re-aligned the curve. They had a lane in place for the trucks as a "temporary" lane and then put grass on it! What a WASTE! Also need climbing lanes on hills prior to Palmers Convenience Store. Winter							
			maintenance in Clarion County is horrible. You can be on wet roads in Armstrong and you cross the bridge in New Bethlehem and they are snow							
40.969314 -79.357133 40.877743 -79.401078	380668 point 380670 point	2/25/2020 2/25/2020	covered. ( Don't give me the "I 80 excuse" Armstrong has Rt 422). I've274674been driving that road daily for 35 years.274674						x	see above
									This is also where the public turns to get to the Rails to Trails entrance at Moore Road. When someone is sitting on 28 to make a	
									left, they're sitting ducks - as we are when trying to turn left into our driveway. Every	
			this is a blind curve whether you're heading north or south. we live here.						year since we've lived there, a vehicle has crashed into our yard going too fast around the bend. Our neighbor's family has been	
			There have been many accidents and dozens of deer killed. It's almost						rear-ended on several occasions waiting to turn on to Moore Road.	People drive way too fast in a lot of spots on 28. I also frequently
			impossible to get out of our driveway at different times of the day. Perhans widening the road on the west side would belo. The storm drains							drive to Ditteburgh via 20 and the
41.127105 -79.16419	380685 point	2/26/2020	impossible to get out of our driveway at different times of the day. Perhaps widening the road on the west side would help. The storm drains are also clogged in this area and the water from the hill pours down and 274719 remains icy in the winter.		x	x x	x	x	The road needs widened and the storm X drainage fixed.	drive to Pittsburgh via 28 and the winding curves have speed limits that no one pays attention to.
41.127105 -79.16419 40.868648 -79.42881	380685 point 374364 point	2/26/2020	impossible to get out of our driveway at different times of the day.         Perhaps widening the road on the west side would help. The storm drains         are also clogged in this area and the water from the hill pours down and         274719         Z74721			x x	x	x	X       The road needs widened and the storm drainage fixed.         Got to cross traffic to turn onto ridge road and can not see over the top of hill for oncoming traffic.	drive to Pittsburgh via 28 and the winding curves have speed limits that no one pays attention to.
41.127105 -79.16419 40.868648 -79.42881 41.089427 -79.227246	380685 point 374364 point	2/26/2020	impossible to get out of our driveway at different times of the day.       Perhaps widening the road on the west side would help. The storm drains are also clogged in this area and the water from the hill pours down and       X         274719       remains icy in the winter.       X         274721       Care of Penn St above high school by the twp. Speed of traffic and safety of students. Lack of concern by two and local police. My house has been hit twice by cars and my daughter by a car. She is fine now       Y		X     X     I live 1/8 of a mile off rt 28     Y	x x x	x x x		X       The road needs widened and the storm drainage fixed.         Got to cross traffic to turn onto ridge road and can not see over the top of hill for oncoming traffic.         SPEED and by passing 28	drive to Pittsburgh via 28 and the winding curves have speed limits that no one pays attention to.

		Right across the bridge in New Bethlehem there is a VERY busy Sunoco station with two side roads also pulling in and out within the same "block" area. Visitation is bad depending on how the people park in front of the Sunoco. If they park RIGHT by the road parallel with the 28 you cannot							
40.999841 -79.332945	380688 point 2/	see oncoming traffic from the south with the possibility of pulling out of a vehicle. Perhaps some sort of traffic control would help. No everyone26/2020274730Guestreduces speed from 35 to 25 when entering the town.		x x		x x	x x x x x		The entire route 28 corridor
40.849923 -79.458651	380693 point 2/	26/2020274739The roadway between Sloan Hill Road and Mechling Road needs shaved down to increase visibility for all motoristsX	x x x x x	x x x x			x x x x x x x x x x x x x x x x x x x	Road and Mechling Road. Hill top needs shaved down to increase safety and visibility.	to provide alternating passing lanes and middle turning lanes where needed.
								Route 28 is always concerned about connecting to route 80. With Pennsylvania so high on the tourist industry, Route 28 is	
								the gateway to the North from Pittsburgh and Armstrong County. PennDOT does not normally do traffic counts on weekends and holidays but route 28 needs to have these	
		Install a round-about at the route 85 intersection. PennDOT probably						counts done. People call 911 during holiday weekends reporting the traffic light at 85 is malfunctioning because they sometime have to sit through three light cycles to get	
40.818114 -79.489728	380694 point 2/	26/2020274739Already owns enough right of way and traffic patterns vary so much not only throughout the day but at different times of the year as well.X	x x x x x	x x x x x		xx	x x x x x x x x x x x x x x x x x x x	through the intersection. A round about would solve all traffic amount issues. The Tickle Hill to Anderson Creek Rd Project	
								back on PennDOT' s priorities list. The sharp curve needs removed along with better visibility to enter on to 28 from Anderson	
								Creek Road. Also, during snow event vehicles slide off of route 28 into the Tickle farm field which closes the roadway until rescue workers can pull the vehicle onto the	
40.836089 -79.468457	380695 point 2/	26/2020       274739       complete the Tickle Hill Project to Anderson Creek Road.       X         Image: Complete the Complete the Tickle Hill Project to Anderson Creek Road.       X         Image: Complete the Complete the Tickle Hill Project to Anderson Creek Road.       X         Image: Complete the Complete the Tickle Hill Project to Anderson Creek Road.       X         Image: Complete the Complete the Tickle Hill Project to Anderson Creek Road.       X         Image: Complete the Comp	x     x     x     x	x x x x x			x         x         x         x         x         x         x           Image: Im	roadway again. Delays behind truck traffic could be improved with additional lanes. Vehicles try to pass in locations where they shouldn't	
40.96457 -79.360725	380696 point 2/	26/2020       274742       in recent years have made significant improvements. Additional lanes of traffic would be helpful to reduce delays behind truck traffic.         26/2020       274742       The increased Truck Traffic on the residential areas of New Bethlehem         26/2020       274749       could cause noise and traffic problems	x x	X     Visiting friends in Kittanning	x	x x	x x x x x	and could cause accidents to many drivers and their passengers.	None
41.000357 75.357572		This is a sharp turn with no stop signs. In my sedan it feels too sharp. I can only imagine what 18-wheelers experience. I suggest rerouting down Putneyville Rd & South Street. With proper expansion of the road of		Driving to Pittsburgh for Specialist				This corner is entirely too sharp for all the	
40.998962 -79.342768		26/2020 274755 course.						I think from New Bethlehem to Kittaning should be 2 lanes in either direction the	
								entire distance. More than once I've had to follow slow or freight traffic for miles before I could pass. Also, I've been at a standstill often because of an accident. With more	
40.995561 -79.341912 40.81194 -79.491352	380707 point 2/	26/2020       274755       From New Bethlehem to Kittaning         26/2020       274763       From Kittaning to New Bethlehem is terrible driving, even with the         26/2020       274763       climbing lanes.		Image: Second state     Image: Second state       Imag	x	x	x x x x x x x x x x x x x x x x x x x	Ianes emergency services could easily close         X       a lane and traffic would continue to move.         X	
									Slow moving traffic is a concern. The speed limit between New Bethlehem and the Indiana junction is usually 55, with a few
									exceptions. When you go the speed limit, then come over a hill and find a vehicle going 35 below
									very dangerous situation. Some folks pull out in front of you then go slow. My other favorite is folks
									we think they own the passing lanemaybe some reminder signs to get back over into the right lane. The law stipulates that
		Keep the speed limit consistent. The four lane speed limits should be 65 and remain consistent between 422 and Route 66. Speed limit jumps around and you never know what it is. Signs say one thing and gps says							the passing lane is for ACTIVE PASSINGnot a travel lane. Same thing with the 3 lane passing lanes north of 422. We travel 28
40.804424 -79.487383	380722 point 2/	26/2020 274787 something else. 55 mpg is ridiculous across the bridge and up to the Indiana junction. No one follows it anyway!		x I I I I I I I I I I I I I I I I I I I	X		x x	Consistency in speed limits.	because we have to NOT because we like it! I think it's great that improvements are being studied.
									My only concern is long hills and stretches without passing lanes. Sometimes I get stuck following behind a slow truck or farm
41.001375 -79.332058	380723 point 2/	26/2020 274790	x		X	x	x x x x x		equipment and it slows me down a little. the road is horrible!! twists, turn,
40.889694 -79.381837 40.999082 -79.343187	380724 point 2/ 380725 point 2/	26/2020       274794         26/2020       274795         Create more gradual turn. Slow area, especially with truck traffic.	x constraints of the second se				X     X     X     X     X     X     X     X       I     X     X     X     X     I <td>Difficult for trucks to make turn. When traveling northbound sometimes need to stop for vehicles traveling southbound</td> <td>up down, not safe. very stressful</td>	Difficult for trucks to make turn. When traveling northbound sometimes need to stop for vehicles traveling southbound	up down, not safe. very stressful
40.941201 -79.364603	380726 point 2/	26/2020 274795 Hogback hill passing zone	x	x			x x	Limited visibility in southbound passing lane. Recent fatal accident highlighted a potential safety issue here. It is unsettling when traveling southbound	
40.906744 -79.371276	380727 point 2/	26/2020 274795 Goheenville blind turn	x I I I I I I I I I I I I I I I I I I I	x			x x x x x x x x x x x x x x x x x x x	around this turn. Any way to create a more gradual turn, widen the road or remove banks for visibility would be helpful. Commonly waiting for slow moving trucks	
40.882719 -79.391069	380728 point 2/	26/2020 274795 Needed northbound passing zone	x	x				on this hill. Passing zone needed. Seems there is plenty of available space to make X this happen.	
40.834683 -79.471421	380729 point 2/	26/2020 274795 Widen turn	x	x			x	Tight coming around this turn, especially when passing tractor trailers here. Seems like there could be an opportunity to widen.	
				to travel. It has improved since PennDot made some improvements but it is a very					
				hazardous road to exit and enter.The intersections are all very dangerous from Kittanning to Distant. I use to travel ever					
				day from New Bethlehem to Kittanning and I saw a lot of accidents over the years.It is better but still has along way to				The worst one I believe is coming north and	With the amount of traffic it is
40.99574 -79.336942	380734 point 2/	27/2020 274818 X		go. X			Image: second	X       turning towards Templeton         This area is so very narrow. Many times I         travel through here and envision a         catastrophe when a big rig is barreling	definitely a sub standard road.
40 907446 -79 370807	380735 point 2/	This area is so very narrow. Many times I travel through here and envision a catastrophe when a big rig is barreling towards me and crushing me. The oncoming traffic is coming downhill and fast at times and any slip in iudgement there is no room for error.		v v	Y			towards me and crushing me. The oncoming traffic is coming downhill and fast at times and any slip in judgement there is	
40.907440 -79.970807								Very tricky area to pull out of the gas station. You have to watch the little hilltop to the right ( south of the store) just past	
			Regional commuting (More than Accessing government	Accessing stores, services, Accessing recreational			Vehicle Stopping or	no oncoming traffic if you want to pull out and head north. It's impossible to pull out from the left side of the parking lot and	
40.869955 -79.422506	380736 point 2/	27/2020 274832 Poor sight lines.	10 miles each way)     services	goods, healthcare opportunities	Weekly		speeds     turning vehicles     Sight dist	tance see in the little dip if can proceed safely. This area has a section that is always sagging. Fear it will give our like the road did by Dayton recently. The sagging part is	
								on the northbound lane. Often times has patches and cones marking it. Can see the road slowly washing away.	
40.854491 -79.450919	380737 point 2/	27/2020 274832 Caving road	x x	x x	X			Also this section could use a passing lane. Cut the hillside out ( southbound side) and X move it all over and include a passing lane. Fast moving vehicles here. People fly up to	
								this road and put on turn signals to late and and sudden braking by followers. Also it's unnerving to come up to this road	
40.837867 -79.466548	380738 point 2/	27/2020 274832 Turning issue	x x	x x	x			from of you as they can't see very well from the north side. Another place where when traveling and	
								there's a sudden onset of turning right for the people behind. A turning lane would be fantastic here. Ensure the safety of people exiting and those following.	
								People not used to the area could rear end someone here. It's just such a sudden near stop and slow down from a major highway for people to make the right turn	
40.877669 -79.394743	380739 point	27/2020 274832 Make a turning lane.			x			off the highway. And also for people turning off from the northbound lane it's potentially dangerous. People fly through X here.	
· · · · · · · · · · · · · · · · · · ·	. 2/	· · · · · · · · · · · · · · · · · · ·		I I I	<u> </u>			· · ·	

40.872416 -79.413097	374623 point	3/4/2020         275373         X			
41.004304 -79.327824	380918 point	3/3/2020         257000         Guest         Dangerous intersections with access points           3/3/2020         257000         Guest         Signalization         Image: Constructions with access points         Image: Constructions with access points         Image: Constructions with access points	A         Indveiling to my camp           X         Indveiling to my camp	A         X         X         X         X         X           X	
41.015467 -79.300609	380837 point	3/1/2020       275114       Hawthorn to New Bethlehem are bottle neck delays driving.       X         3/3/2020       257000 Guest       Dangerous intersections with access points       X	X     X     X	x     x     x     x	X     Mathematical Structure     X     The travel considerably.       V     V     V
					unpredictable time wise. Really should be 4       dangerous with large trucks.         lane the entire way. Large trucks can delay       Passing those trucks especially in
41.001058 -19.330868	380836 point	Syl/2020     Z/SIL2     Dottemetrolly new betmement when traveling to Pittsburgin     X     X			A     Start       Image: Construction of the start     Image: Construction of the start       Image: Construction of the start     Image: Construction of the start       Image: Construction of the start     Image: Construction of the start       Image: Construction of the start     Image: Construction of the start       Image: Construction of the start     Image: Construction of the start
					work, bypassing the towns and adding passing lanes on the steeper hills would be a good
					from Brookville to Kitanning would be a major boon to traffic and commuters. If that won't
40.824145 -79.48412	380821 point	2/29/2020       275059       dangerous .Going south it backs things up in traffic.       X		x         x         x         x           Image: Ima	Image: Marcine Stress         X         Afraid of being hit by on coming traffic.         Finding a way to make 28 4-lane
		Line			A         A         A         A         Currey inclues and bruges;         To write inclues and bruges;           Image: Imag
41.00047 -79 330098	380820 point	2/29/2020 275054 relocate to due to its setting! X X X X X X X X X X X X X X X X X X X			X     X     X     X     X     X     Bethlehem the way it is and make for less     area my haul life from 2 wheels to       X     X     X     X     X     X     X     18 wheels
		convert rt66 into 4 lanes from this point north and make more revenue for towns along rt66 such as Clarion to build more, attract more for college			with the wide valley in between there       would love to give ideas and help         leave the scenic rt28 north of New       if all possible Traveled this
		widen road, several communities with excessive speed changes so,			Bethlehem and Clarion is now your going am a professional of duty and
		Night of here traveling rt28 has too much congestion, not mich flat land to			Clarion has your potential especially with
					recreation, college, job opportunities along I- 80/ future 4 lane rt66, perfect idea I say!
					level than 28north of New Bethlehem now and also is center of every attraction such as
					on to 66n to Clarion where the land is more
					make enough room for New Bethlehem to
					4 lanes to Clarion from kittanning after you
40.879963 -79.392253	374463 point	2/29/2020     275054     speeds of 65 mph and less tailgaters!!!!     X     X	X X pass X X	x x x x x	x x x
		tractor trailer traffic climbing these hils. This route has alot of potential for travelers, especially freight but need to make this a road that can permit	slow speed due to them being cautious!!!! With few places to		a line of traffic behind them
		Traveling north and south in this area needs passing lanes due to the	driver or you will be traveling at		not for a professional driver with
			with this area, it is either very		this route is an exciting race track
			experienced freight hauler to drive. If a driver is not familiar		that person to understand this road better At this moment.
			This is a difficult route even for an		Yes, seek someone with a loaded tractor trailer and ride along with
+1.115111 -\3.505535		Z/Z3/Z020         Z4100/04/31         Specu         A         E         E           Image: A final state of the state o			
41 112111 70 205202	290912 point	2/29/2020 241607 Guest Speed			Note     Note       Speed limit drops suddenly no warning signs
40.998962 -79.342768	380811 point	2/29/2020       241607 Guest       This turn is terrible for semi trucks as well as cars. It's a blind turn and a major hazard       X       X			
40.907572 -79.370624	380810 point	2/29/2020       275028       avoid slower traffic ahead. This road needs to be more straight for traffic         X	x		
		Ly Loy Loo     Ly Loo <thly loo<="" td="" th<=""><td></td><td></td><td></td></thly>			
40.836375 -79 470872	380805 point	2/28/2020       273634       Kittanning to brookville, there's plents of undeveloped land to pass         X	X Drive this route everyday. X		West towards Butler anyway, there are       think I might go off the deep         X       already other four lane roads in those areas
		you draw a straight line from the end of the four lanes just outside			the commerce is South of Kittanning or path would displace me again, I
		There isn't a good reason to make this 4 lanes to brookville, although, if			courtesy. I don't believe there needs to be live close enough to 28 near four lanes the whole way to Brookville. All Shannondale, that if a proposed
					Baum???? Maybe add some pull off areas       by the development of the route         for the slow trucks to let people by as a       28 corridor at Slate Lick. I now
					they were upgrading at Pine Creek and displaced NOT ONCE, BUT TWICE,
					I think it would be good. But Why in       I am particulary adamant about         Gods name didn't PennDot do this when       this because my family has been
					and add a third lane at a couple of spots and and ruin farmland for this!!!
					was done by Baum Pump Station and what
					Straighten where you can. Similar to what
40.872391 -79.413202	380774 point	2/27/2020 274887 INTERSECTION OF RT 66 AND OSCAR RD. X	X EMERGENCY CALLS X	x x x	CARS HAVE ENDED UP IN THE YARD OF THE       X   HOUSE AND HAVE HIT THE HOUSE.
					STOPPING TO TURN OFF OF 66 SOUTH BOUND OR PULLING OUT OF THE OSCAR RD
					NOT ENOUGH LINE OF SITE FOR CARS
40.849323 -79.459024	380773 point	2/27/2020 274887 RD.	X AVOID IT	x x x	
41.016901 -79.30201	380772 point	2/27/2020       274784 Guest       Sharp turn-people driving too fast       X         LINE OF SITE FORVEHICLS ENTERING/LEAVING RT 66 FROM SLOAN HILL       X       Image: Constraint of the second state of	Image: Second	X X X I I I I I I I I I I I I I I I I I	
40.998641 -79.342194	380767 point	2/27/2020 274863 Guest between embankment or ledge.	x	x x x	
40.971229 -79.352222	374386 point	2/27/2020     274832     Parking on road     X     X	x x x	x x x x	X and can't safely.
					traffic at this major intersection. People are         trying to exit off 28 onto putneyville road
					dangerous as there is sometime single lane
					is still part of state maintenance here) and it limits the ability to get on 28. Makes it
					People park here to get ice cream. They park on putneyville road. Both sides ( which
40.998962 -79.342768	380741 point	2/27/2020 274832 Turning trucks. X	x x x		Practically a 90 degree turn for semis. Dumb
					And also lots of turn overs as well. This turn is iust dumb.
					traffic needs to stop for a north bound semi.
					Somis take this turn so wide. South hound
40.917525 -79.365054	380740 point	2/27/2020 274832 Sight lines X	x x x		X Had potential to be a deadly place.
					All the time
					just hidden till you get to the top, is that
					are speeding through the passing lane and
					on non locals may not know to look out for left turning vehicles from the porth - Reople
					When coming up the passing lane , unaware

# APPENDIX C Online Mapping Survey Questions

#### Route 28 Corridor Study Wiki-map Survey Questions 01.17.20

#### ADD PROBLEM OR OPPORTUNITY

- Select a point type and then place on map.
   [Each point type receives a different list of concerns Q4-7]
  - Traveling via a car
  - Traveling via bike
  - Traveling via walking
  - Traveling via truck/freight vehicle
- 2. I use this area for: (Select all that apply)
  - Local commuting (Less than 10 miles each way)
  - Regional commuting (More than 10 miles each way)
  - Business travel (Deliveries, moving freight, etc.)
  - Accessing government services
  - Accessing Redbank Valley Trail
  - Accessing local schools
  - Accessing stores, services, goods, healthcare
  - Accessing recreational opportunities
- 3. How frequently do you use this facility?
  - Daily
  - Weekly
  - Monthly
- 4. What about this location causes you concerns? [CARS]
  - Pedestrian Safety
  - Cyclist Safety
  - Vehicle speeds
  - Slow moving vehicles
  - Congestion
  - Stopping or turning vehicles
  - Lack of connectivity
  - Interstate access
  - Roadway safety
  - Drainage
  - Parking
  - Signal timing
  - Roadway or bridge maintenance
  - Sight Distance
- 5. What about this location causes you concerns? [BIKES]
  - No shoulder
#### Route 28 Corridor Study Wiki-map Survey Questions 01.17.20

- Shoulder is too narrow
- Poor shoulder condition
- Debris
- Lack of bike lane
- Lack of protected bike lane
- Travel lanes are too narrow
- Drainage
- Vehicle speeds
- Roadway safety
- Proximity to large trucks/vehicles
- Connectivity to regional trail system
- Aesthetics
- 6. What about this location causes you concerns? [FREIGHT]
  - Pedestrian Safety
  - Cyclist Safety
  - Vehicle speeds
  - Roadway incline/grade
  - No climbing lane on steep grade
  - Travel lanes are too narrow
  - Intersection too narrow to safely turn
  - General congestion
  - Stopping or turning vehicles
  - Lack of connectivity
  - Shoulder width/condition
- 7. What about this location causes you concerns? [WALKING]
  - Sidewalk ends/no sidewalk
  - Sidewalk condition
  - Pedestrian safety/visibility
  - Roadway safety
  - No shoulder
  - Shoulder condition
  - Drainage
  - Vehicle speeds
  - Proximity to large trucks/vehicles
  - Crosswalk
  - Sidewalk not Americans with Disabilities Act (ADA) compliant
  - Connectivity
  - Aesthetics
- 8. Please explain your concern. (open-ended)

- 9. Do you have a photo of this area of concern for us to consider? Please upload it here.
- 10. Is there any other information you would like us to know about the Route 28 corridor? (openended)

Click submit to return to the map to add any additional problems or concerns.

# APPENDIX D Public Concern Map





Route 28 Kittanning to I-80 Regional Corridor Planning Study Public Survey Concern Locations

## Legend

County Boundary Municipal Boundary Route 28 Study Corridor State Routes





# APPENDIX E Stakeholder Meeting Minutes



Meeting:	Stakeholder Interview Meeting - Brookville	Date:	February 26, 2020
Location:	Jefferson County Conservation District	Time:	10:00am to 11:30am

Attendees: See attached sign-in sheet

Purpose: The purpose of the meeting was to interview a variety of stakeholders for the Route 28 Corridor Study Project to obtain input from their local knowledge for consideration of proposed improvement within the study.

*Discussion:* The format of the meeting followed an initial list of questioned provided to the stakeholders to guide the discussion. This list provided a general outline of project specific question regarding the use, operation and safety within the Route 28 Corridor. The following information provided a summary of the stakeholders input at the meeting and discussion:

- Traffic signals are not synchronized, and during an emergency detour situation, can cause traffic congestion. Presently, municipalities control them, but it would be good if a centralized authority made up of various stakeholders had operational control during emergencies.
- When traffic is detoured on I-80, some vehicles don't use the posted detour, and a lot of traffic is converging in Brookville at the intersection of SR 28 and US 322 near Sheetz. When I-80 is detoured, need coordination in Brookville due to traffic gridlock at that intersection.
- There is no parallel route for I-80 closures, people don't realize the detours and cell phones will just bring them right back into the detour. It was suggested to install message boards on parallel routes to control traffic on SR 28.
- Recently, a tanker had an accident on I-80, and traffic was detoured to SR 28. Traffic was at a standstill for hours and hazardous material freight was coming off the interstate onto SR 28 which creates potential for accident or contamination that close to the Red Bank Creek. There is a need for a spill response team or plan along the corridor. During detour traffic, it is also extremely difficult for local emergency vehicles to get through the detour congestion since the shoulders on the corridor are so narrow. They cannot bypass the traffic.
- I-80 has no signage to show that SR 28 leads to Pittsburgh, and the Pittsburgh Airport.
- Many accidents occur from the Brookville Borough line to Snyder Road.
- Coder Road experiences accidents with commercial vehicles turning into Coder Road.
- There are landslides that occur north of Summerville.
- There are issues on Anderson Creek Road with commercial vehicles in the wintertime getting stuck on the top of the hill due to the steep grade.
- The Redbank Creek runs parallel to SR 28. The main concerns are with its proximity to the roadway, including potential for hazardous materials spills, flooding, ice jams, and narrow shoulders around the Summerville area.
- I-80/SR 322/SR 28 is a potential economic hub/area for development that would benefit from improved alignment and traffic conditions.
- Mendenhall Road is a safety concern due to sight distance/blind curve.
- Mayport Road is a safety concern as trucks have difficulty turning here due to the skew of the intersection, which is compounded by poor sight distance caused by the hill and the curvature of the roadway.
- Amy Kessler asked the question if there would be an increase in freight traffic due to the Shell Pennsylvania Petrochemicals Complex in Beaver County (cracker plant). The consensus was there would not be significant changes, though some minor manufacturing trips to process the plastic pellets could use the corridor.
- Since the turnpike tolls are high, and some trucks use 28 as a connector. This increases commuter and truck traffic on SR 28. Fuel tax is also too high. Many trucks will drop down to take 68 and pay the lower gas tax in Maryland.
- The issue with possible tolling of major highways and its implication on SR 28 was discussed.
- The Potters Mills project further east on US 322 was discussed. It was the consensus that when this project is complete more traffic that would use the Turnpike will instead be using SR 28 as an alternate route since it's a better connection.
- Jefferson County PennDOT maintenance stated that there are several crash clusters along SR 28 due to hills and curves. They also reiterated that congestion becomes an issue when traffic is detoured from I-80, but vehicles are following GPS instead of the posted detour. Noted a need for coordinated overhead messaging signs. Transporting a sign out from the

District office to tell people to stay on the detour route takes too long to be efficient at moving people before it becomes gridlock.

- There is inconsistency in speed limit and prevailing speed on SR 28 for the length of the corridor.
- The Redbank Valley Trail does not have good connections to Route 28. There is a lack of signage denoting where the trail can be accessed. The current trail crossing north New Bethlehem is perceived as particularly challenging.
- The Mayport curve was discussed as having sight distance concerns.
- The Baxter curve was discussed as having issues due to geometry and sight distance. Trucks also speed through Baxter. A possible improvement would be Baxter and Summerville widening and flattening the existing curves.
- It was mentioned that cell phone coverage along SR 28 is inconsistent, which could cause concerns for vehicle breakdowns and for those following GPS.
- Miller Transportation indicated they have daily deliveries on the corridor and speed is an issue for them. They would like to see a 4-lane roadway from Brookville to Kittanning as they are expecting deliveries to grow.
- The Conservation District indicated that water quality and spills were a major concern with the potential for increased traffic and the frequent use of Route 28 as a I-80 detour route.
- Amy Kessler asked about truck parking on the corridor. Generally the consensus was that truck parking presents little concern
  along the corridor. No one noted designated or unofficial locations of truck parking overnight on the corridor. The
  representative of the local freight community said that more shippers are providing overnight amenities at their facilities due to
  the new regulations. Haulers are also considering changes to their hours of operation to take shipments to more effectively
  meet the regulations.
- Hazen interchange was discussed as a possible future development project that could impact the traffic on SR 28.
- ATV crossings were noted along SR 28. ATV signs in the area around Dewey Road.
- In general, school bus stops along the corridor are hazardous, particularly where there is a 3-lane section with a passing lane. Cars will pass school buses even when they are supposed to stop. For example, south of Coder Hollow, a bus stop is located where the 3-lane road begins. Not an ideal place for a bus stop as people are speeding to get to the 3-lane road and pass slower moving vehicles.
- The guide rail is thought to be insufficient in Summerville and Baxter because you are so close to the water. It was noted that in recent years, a vehicle ran off the road and a woman drowned in the creek.
- In the summer, farming equipment using the road south of Summerville and throughout the corridor often slows traffic.
- The following tourism draws were discussed:
  - o Cooks Forest draws a lot of traffic from Pittsburgh
  - o Trout season
  - o Deer Season
  - o Poker Runs
  - o Peanut Butter Festival
  - o Historic Brookville
  - o Laurel Festival
  - o Several festivals in the summer
  - o Hazen Flea Market
  - o Autumn Leaf Festival
- Companies located along the corridor are doing their own shipping which increases the number of trucks on the road. Logging company employs independent drivers.

A list of action items was developed to summarize the stakeholders input and potential improvement areas within the study. The study team will further evaluate these stakeholder concern locations with our existing conditions, crash history, geometric conditions, public input, and operational conditions. The stakeholder action items to be considered are listed below:

#### Action Item List:

- Determine existing Variable Messaging Signing (VMS) that exists on I-80 and its proximity to the Route 28 Corridor.
- Further discuss areas where VMS placement along the corridor at strategic locations may provide helpful information during an I-80 emergency detour for travelers to consider prior to entering into congested areas to reduce gridlock. Also, this could serve as advanced warning for winter weather events or incidents along Route 28.
- Evaluate potential directional signing updates along I-80 to indicate that Route 28 connects to Pittsburgh and the Pittsburgh International Airport.
- Potential areas where emergency responders may have difficulty getting through congested areas during the use of Rt 28 as an I-80 detour route.
- Further investigate specific concerns noted by stakeholders at the following locations:
  - Brookville Borough line to Snyder Road
  - Route 28 near the Redbank Creek near Summerville
  - Mendenhall Road sight distance
  - Route 28 and Mayport Road sight distance/truck turning concerns with entrance skew
  - Summerville and Baxter potential for deficient guide rail

The meeting was adjourned at approximately 11:15 a.m. by thanking the stakeholders for their feedback and time.

Prepared by: McCORMICK TAYLOR, INC. Copies:

Attendees MT Project File

Attachments:

Meeting Sign-in Sheet

Pagel of 2

Stakeholder Outreach INTERVIEW INVITATION SIGN IN SHEET BROOKVILLE February 26, 2020

STUDY STUDY	5 TO 1-80
E B	TRNMING
CORRI	FROM HIT

NAME	ORGANIZATION	EMAIL	PHONE
Josh Spano	SPC	) spande Sparganay	
Ashley Tracy	We Corruice Tag le	autracy a uncornico day be	
Kari Shedlock	French Encinerias	Kshedlocke frenchenar can	
Mary Eberhardt	French Engineering	Weberhardt Chenchener.c	the
tran Schoss	SPC 0	PSCHOSS @ spergion.	610
Deb Wilson	SCOD	Joed @ windstream. met	
Any Kirster	NC 2.7.0	Any Oncentral. cn	814-773.3142
PAUE TONIASMICK	PENNUDON DISTRICT 10	DOWASUACK @ PA . 401	724 357 2845
Aurie Ledacie	K K		
Steve MC Nevsen	Willestabrichtion Solu	smepherson Owiller Fabrication solutions.com	8/4-715-0691
Joe Barber	Barber Toucking	jor Obarbutrucking, con	814-913-1526
AARON EMHOEF	PENNDOT	demberferg.g.v	814-939-8167
-back Madson	Jeffer on Ount,	Unatione deferrances A la	P14-P49-1653
AFRIS BUILTER SNAL	20 Ac Prese Co.	4 bolles Alteranty B.	car 849 -1652
Jak fisan K	Tipperson, chy	the sare at a pethoseveral	848.1453

Page Zef Z

Stakeholder Outreach INTERVIEW INVITATION SIGN IN SHEET BROOKVILLE February 26, 2020

	5 🚬
SNE	- F
	N N
	ξĒ
-	
	2
20	00
C	) 😤

	849.5052	849-4009							
PHONE	may Br. Com	, por to way							
EMAIL	+2ersta Chercon	cclor ko Jefterend							
ORGANIZATION	JEFFERSON GURY	Selferantin 1 1 911							
NAME	TRAD ZENTS	Chreis Clerk							

Ø



Meeting:	Stakeholder Interview Meeting – New Bethlehem	Dat
Location:	New Bethlehem Public Library Community Room	Tim

 Date:
 February 26, 2020

 Time:
 1:00pm to 2:30pm

Attendees: See attached sign-in sheet

*Purpose:* The purpose of the meeting was to interview a variety of stakeholders for the Route 28 Corridor Study to obtain input from their local knowledge for consideration of proposed improvement within the study.

*Discussion:* The format of the meeting followed an initial list of questioned provided to the stakeholders to guide the discussion. This list provided a general outline of project specific question regarding the use, operation and safety within the Route 28 Corridor. The following information provided a summary of the stakeholders input at the meeting and discussion:

- The pedestrian crossing at Redbank Valley School is challenging with fast-moving vehicles nearby and many pedestrians. Vehicles typically park across SR 28 from the school and children cross SR 28 to get to their parents. They would like to evaluate a sign and/or traffic signal.
- The trail crossing is under PUC authority because it's a railbanked corridor. The crossing is particularly difficult and would benefit from signing in advance of and at the crossing, flashing lights, as well as a realignment of the trail so that it is perpendicular to the road and shortened, instead of crossing at a diagonal. The painted crosswalk across SR 28 was removed due to driver complaints, but the location has anecdotally had numerous accidents with folks driving off the road.
- The question was also posed if the restrictions on Tourist Oriented Directional Signing (TODS) could be lessened. The town would benefit from markers for economic development of businesses on trail, including B&B's, as well as for parking areas.
- There may be trail counts done by the Redbank Valley Trail Association, though most counters have been damaged or stolen. Study team will look into obtaining previous counts taken of the trail users.
- The Mahoning Township supervisors mentioned a study that was done to look at locations for the trail or roadway in front of Nolf Chrysler, that would side cut the hill, flatten the trail past Chrysler but there was a wetland issue that stopped the study moving forward. Wetland mitigation was mentioned as a potential solution for the project. Study team will look into obtaining this information.
- Redbank Valley High School has issues with pedestrians crossing the street during the school dismissal hour at 3:10pm. Parents park in the Subway and Chiropractor parking lots and then jump onto Route 28. They said there is plenty of parking in the back of the school, but that parents and students don't want to use it. They have crossing guards but are curious if a traffic signal could help. It's primarily drivers, with some walking students crossing to walk down the trail to get back to their homes. Dr. Mastillo, superintendent of the Redbank Valley School District, was supposed to attend but could not at the last minute, study team will follow up with him.
- It was discussed that congestion becomes an issue when traffic is detoured from I-80 but vehicles are following GPS instead of the posted detour.
- There is a operational concern at the SR 28/SR 66 intersection when trying to detour trucks due to geometric constraints. Trucks frequently hit the building and traffic signals at this location. The pole has been hit 8 times since the pedestrian ramp was installed. One day there was a bollard, but it kept getting hit and never came back. Cars also regularly pull beyond the stop bar and this creates congestion because trucks cannot navigate the turn with them there.
- Generally, the PSP has issues along SR 28 due to hills, climbing lanes (or lack of) needed at Hogback Hill and Orchardville Hill toward Exxon Station to Baum Pump Station. Other issues include snow, trucks that get diverted from I-80, and speeding along the corridor.
- PSP said speed along Route 28 is a safety concern, but there is not a high rate of crashes in this area of Route 28 if you compare it to the lower portion of Route 28.

- There is a choke point at the bridge in New Bethlehem over Redbank Creek which causes congestion. Any major crash, spill, or slide would wreak havoc on the transportation system because there is no way around it. The transportation system is very limited in this area.
- It was indicated that there should be improvements to the crosswalks throughout New Bethlehem and Hawthorn.
- Speed is an issue at the mini mall. The speed limit is 35 mph in one direction and 25 mph in the other. PennDOT mentioned that it should not be signed differently in opposing directions, and that the roadway needs to meet certain requirements to be posted at 25mph, including 85<sup>th</sup> percentile speed and residential density.
- There was another speed limit difference noted in Hawthorn, where it is 45 mph in one direction and 35 mph in the other. PennDOT again stated that it should not be signed as such.
- Along SR 28 from Kittanning, there are issues with erosion which is causing the guiderail to shift.
- Generally, the Redbank Creek runs along SR 28 too close to the road (horizontally and vertically) and during the winter months, ice jams cause issues over the roadway, including flooding. It was suggested that the stream needs to be dredged in some areas to remove debris. The Leisure Run flood is still being cleaned up.
- The 3-lane roadway ends at the Mahoning Creek Bridge.
- There is a 55/40/55 speed differential through difficult geometry which makes traveling through Distant difficult.
- A northbound turning lane begins where a passing lane ends at the crest of a hill at Calhoun School Road. This poses a safety concern for potential rear end and head on collisions. People think this is an extension of the passing lane and use it for passing.
- There is an ice cream shop directly adjacent to SR 28 that is very popular near Distant. Distant Dairy and Dollar General have a lot of traffic and generate pedestrians close to the roadway. Dollar General is noted as a difficultarea to pull out of due to blind curves. Some places in Distant lack sidewalks.
- There are rockslide and hill side erosion issues along the corridor which occur frequently and in many places.
- The intersection of SR 28 and SR 536 Mayport Road has deficient sight distance.
- Smucker's currently has access issues to their plant that could be addressed with a future project. In particular, the intersection of Wood and Penn poses an issue for trucks driving to Smucker's having to use local roads. Trucks get trapped and end up driving into people's yards and break the curb and sidewalk. They would like to see Smucker's have their own access road, but a study was done in the past and there was possibly a problem with sight distance that could not be overcome. Ms. Amato was involved with the Economic Development Commission with this study. The study team will obtain a copy.
- New Bethlehem Borough provided a list of issues that are included as an attachment to this summary.
- The passing lane at Distant is not long enough coming up the hill, then you hit 40mph, and SR 1004 is a quick turn with poor deceleration length.
- Upper/Lower Hayes at 28, and South Main Street could use a turn lane to separate turning vehicles from the general through traffic.
- Parking near the Sunoco/Key Beverage on Broad Street causes issues for traffic traveling WB turning into Sunoco. It could use a turn lane or restrict some parking closer to the area to provide room to turn into these businesses.
- There is acid mine drainage from Summerville to Moore Road in Corsica.
- On the 3 lane sections of SR 28, it has been noticed by PSP that vehicles in the opposing outermost lane do not stop for school buses when they legally are required to.
- There are sight distance issues at the PennDOT maintenance/school bus turnaround location at the Jefferson County line.
- The sidewalks in Distant and South Bethlehem are in poor condition.
- It was suggested that turning lanesare needed at Sloan Hill Road and Calhoun Crest.
- There are little to no issues with freight loading in the downtown New Bethlehem area. There aren't many places that freight has to stop.
- The following tourism draws were discussed:
  - o Redbank Valley Trail

- o Redbank Creek during trout season
- o Bed and Breakfast locations
- o Local campgrounds
- o The County Fair at the end of July is a large traffic generator
- o Poker Runs (ATV event)
- o Peanut Butter Festival
- Friday night football games
- o Deer season
- o I-80/SR 28 in Brookville is a route to the Pittsburgh International Airport

The meeting was adjourned at approximately 1:15 p.m. by thanking the stakeholders for their feedback and time. A list of action items was developed to summarize the stakeholders input and potential improvement areas within the study. The study team will further evaluate these stakeholder concern locations with our existing conditions, crash history, geometric conditions, public input, and operational conditions. The stakeholder action items to be considered are listed below:

#### Action Item List:

- Consider potential for climbing lanes at Hogback Hill and Orchardville Hill toward Exxon Station to Baum Pump Station.
- Consider potential/need for alternate route to bypass bridge in New Bethlehem over Redbank Creek during an incident.
- Consider designated crosswalk improvements for consistent and safe pedestrian access across Route 28.
- Obtain trail counts and previous studies on crossing locations performed by the Redbank Valley Trail Assocation.
- Obtain Smucker's access study for consideration.
- Connect with school superintendent separately to note New Bethlehem School District's concerns along the corridor.
- Document areas of inconsistent speed limits along Route 28 and in certain area in NB and SB directions.
- Investigate potential narrow shoulders or flooding issues where Redbank Creek is close to Route 28.
- Consider potential turning lanes at Upper/Lower Hayes Road and at South Main Street.
- Consider pedestrian access and sidewalks in Distant and South Bethlehem.
- Consider improvements at Sloan Hill Road and Calhoun School Road to improve sight distance and safety.
- Further investigate specific concerns noted by stakeholders at the following locations:
  - o Pedestrian crossing at Redbank Valley High School.
  - o Redbank Trail crossing at Route 28.
  - o SR 28/SR 66 intersection geometric improvements for trucks to navigate the intersection.
  - o Calhoun School Road where the northbound passing lane ends at the crest of a hill and stops in a turning lane.
  - Pedestrian connections and sight distance at Distant Dairy and Dollar General.
  - o SR 28 and SR 536 Mayport Road and potential improvements to address deficient sight distance.
  - Hogback Hill potential lengthening of passing lane coming up into Distant.
  - o Jefferson County line PennDOT maintenance/school bus turnaround location sight distance issues.

Prepared by:

McCORMICK TAYLOR, INC.

Copies:

Attendees

MT Project File

<u>Attachments:</u> Meeting Sign-in Sheet Borough of New Bethlehem Identified Areas of Concern Photos of Meeting Stakeholder Outreach INTERVIEW INVITATION SIGN IN SHEET

> ROUTE28 CORRIDOR STUDY

NEW BETHLEHEM February 26, 2020

PHONE			814-319-5200		814-221-9819	814-319-3401	734-543-3011	724 357 2645	814-226-4000,×2800	(14-329-544)	60 GH-275-2003	814 226 -8200	8121-522-218	H (Project Team)	
EMAIL			tomseidlelyaha	2			ESINKOCA. GOV	DOMASMICICO P. GON	a Lamato & Co. Clanon.		moyor ON entsethlehents,	Jelizer@ pa.gov	schateer (By mail. rom	edlock Wary Eberhand	
ORGANIZATION	XX	8PC	mahan 1 Two	Hauthon	MAHONING TWP	Hawthorn Boro.	PSP KITAWNING	PENNIDOT DISTRICT 10	Clarier Co. Planning	Mahoning Teep ARWS	New Bethlehen Maxis	Cloren Court, PenDUT	New Berly Berly Weils Aron	we. Evian Schoss, kani sh	
NAME	guer e la daver	Ryan Gordon	Tom Seidle	TERRY BEDMU	HEN BIAKE	Mallinda Little	ERIC SIMKU	PAUE TOMAINICK	Krish' Amoto	Re-14 Schoeckerst	Gerton Berrows	Jush Climps	Saudy meter	Ashley Tracy, Josh Sod	



Meeting:	Stakeholder Interview Meeting - Kittanning	Date:	February 26, 2020
Location:	The Belmont Complex	Time:	4:00pm to 5:30pm
Attendees:	See attached sign-in sheet		
Purpose:	The purpose of the meeting was to interview a variety of stakeholders for	or the Ro	ute 28 Corridor Study Project.

Discussion: The following outlines the highlights of the discussion:

- The concerns expressed by the EMS/Ambulance representative were that the hills and geometry of SR 28 present a challenge in getting patients to the most appropriate local hospital. The Armstrong Hospital has advanced cardiac technologies that other local hospitals do not, and many times flights are needed to get patients to the Armstrong Hospital.
- Truck traffic presents an operational and safety concern due to speed differentials between cars and trucks. Many times, vehicles pass slow moving trucks in a no passing zone. Suggested a need for additional truck climbing lanes near Orchardville.
- Spacious Corners / Sloan Hill Road has poor sight distance due to the hill and curve.
- At the top of Hogback Hill at the truck weigh station, sight distance is poor, and trucks are slowing down, stopping, pulling over in this location. Trucks also sometimes don't stop as directed and roll through the brake check area and pull out in front of cars.
- Goheenville speeding issues are noted. An improved project in this area is currently being designed by PennDOT.
- The concerns expressed by the local trucking company, who delivers heating oil and other seasonal products, were that
  houses are too close to the road in many locations. Other areas of concern were brake check stops, the Baum Pump
  Station, and the "tickle turn" by Horse Trader just north of SR 85 that has a sharp turn that is difficult for trucks to
  maneuver at high speeds. There was a recent project that fixed some geometric issues but the project limits did not
  address that turn. They would like to see the improvements continued to address the sharp turn.
- The crosswalk at Fish Basket needs to be straight across the road. (This is the New Bethlehem crossing of the Redbank Valley Trail).
- Speeding is a concern at the 15 mph curve in South Bethlehem. Trucks frequently overtrack and sometimes roll over.
- The discussion regarding the traffic models incorporating drawing additional freight traffic from other major adjacent highways such as I-79, I-80, Route 8, and US 119 was discussed. It was determined that the tools to address this quantitatively are limited, so this would be considered qualitatively..
- There are sight distance and access concerns coming out of Oscar Road.
- There is significant congestion in the afternoon in New Bethlehem. Better coordination of the two signals in New Bethlehem was suggested.
- There is a crash history in Distant due to the narrow roadway/shoulders and the stream located so close to the road, north of Wadding Road to Redding Road.
- There is an active slide at the Pine Creek Bridge.
- Other general concerns included narrow shoulders, lack of truck lanes, trout and deer season congestion, Sloan Hill Road blind curve with buses pulling out, sight distance at Lower Hays to Upper Hays Run, and SR 28 near SR 1035 Oscar Rd needs truck lanes and wider shoulders.
- The following tourism draws were discussed:
  - o Port Armstrong Folk Fest
  - o Armstrong Festival
  - o Arts on Allegheny
  - o ATV events
  - o Cooks Forest

- o Autumn Leaf Festival
- o Peanut Butter Festival
- o Proposed ATV Facilities large scale improvements, Poker Runs, Scrubgrass Run, a big draw

The meeting was adjourned at approximately 5:15 p.m. by thanking the stakeholders for their feedback and time. A list of action items was developed to summarize the stakeholders input and potential improvement areas within the study. The study team will further evaluate these stakeholder concern locations with our existing conditions, crash history, geometric conditions, public input, and operational conditions. The stakeholder action items to be considered are listed below:

#### Action Item List:

- Consider EMS provider concerns with Route 28 geometry and access to Armstrong Hospital.
- Consider local freight provider concerns with Route 28.
- Consider a need for additional truck climbing lanes near Orchardville.
- Consider better coordination of the two signals through New Bethlehem.
- Further investigate specific concerns noted by stakeholders at the following locations:
  - o Sloan Hill Road sight distance.
  - o Hogback Hill in general at the truck weigh station.
  - o Route 28 at the Redbank Trail concerns for pedestrians crossing.
  - o 15mph curve south of New Bethlehem where trucks frequently overtrack and sometimes roll over.
  - Oscar Road sight distance and truck access concerns.
  - o Lower Hayes Run turning vehicle provisions.
  - Discuss with School District separately their concerns along the corridor.
  - o Coordinate with Armstrong County on planned and potential future developments.

#### Prepared by:

McCORMICK TAYLOR, INC.

#### Copies:

#### Attendees

#### MT Project File

<u>Attachments:</u> Meeting Sign-in Sheet Photos of Meeting

ROUTE28 CORRIDOR STUDY

Stakeholder Outreach INTERVIEW INVITATION SIGN IN SHEET

KITTANNING February 26, 2020

NAME	ORGANIZATION	EMAIL	PHONE
NUMED S, KAMMERDIEVER	L BEECS TWP .		724 - 545 - 7142
Allie PANCA	HMNIStrena Co Planning	arpence a corrisorance.	a. US 724-5418-3734
Carmen Juhnsen	Phone Co. Perelopment	Let chusaule to armstrange have	124.548.3121
Tavis Tongravicii	PENNUO DATAIRE IC	DTOMASHICK @ PA HO	724 357 2845
Bu Class	Freqs Two March	WCST 87 Ochitaca	724954679
Lynde Pozzato	AKSTming chambe	L lynde cakstans c	01, 724 224-3400
MILE COONT Len	ARM. G. ECONNING DET	Moevers but E currants	ON 194241 12 40. NO.
Steven Dalla	Kittemaine Then VFI	) stelibation years.	724 - 664 -3995
Keith Buseic	Bagligars IN	K cithe bearigned	1734-55-3562
Audy Breddigan	Bradiband Inc	and to be radiance	758-525-756
Jase Orter	Acmy	forser. Orter@AHN. eg	à 412 491-9256
Justin Nolder	Arm. Co. Econ. Dev.	ir nolde (C) co. armstrong. De	w 734-548-1500
Ruan Gordon, Ashley Tr	acu kar Shedlock, W	any Ebarhart Project Tea	(m)

## APPENDIX F Existing Conditions Memorandum







## Prepared by:



Prepared for:



## Table of Contents

## CONTENTS

Table of Contents	2
List of Exhibits	3
Appendices	4
Study Area	5
Transportation and Land Use Context	5
Geography	5
Steering Committee & Study Goals	7
Previous Studies	8
Previous and Related Studies	8
Traffic Analysis	12
Existing Traffic Conditions	12
Counted Intersections	14
Traffic Analysis Methodology	18
Synchro and Intersection Control Assumptions	
Highway Capacity Analysis Assumptions	
Speed and Travel Times	
Grades	
Detour Conditions	
Streetlight Data	40
Safety Analysis	47
Methodology	47
Crash History Analysis	47
Crash Rate Comparison	51
PennDOT Safety Screening	
Safety Summary	52
Multimodal Facilities	61
Distant	61
South Bethlehem	61
New Bernlenem	
Redbank Valley Trail Crossing	
Hawthorn	
Geometric Considerations	
Design Criteria	71
Typical Sections	71
Horizontal and Vertical Geometry	71
Community Outreach	76
Stakeholder Outreach	76
Public Survey	77
Field Observations	
Field View	82
Conclusion	84

### List of Exhibits

Exhibit 1 – Study Area Limits	6
Exhibit 2 – Previous Studies Areas of Concern	10
Exhibit 3 – Estimated Cost Breakdown for 1994 and 2020	11
Exhibit 4 – Average Daily Traffic Data	12
Exhibit 5 – Route 28 Permanent Count Station Hourly Traffic Counts	12
Exhibit 6 – PennDOT Count Stations	13
Exhibit 7 – Counted Intersections	14
Exhibit 8 – Turning Movement Count Locations	15
Exhibit 9 – Peak Hour Volumes and Truck Percentages (2019 AM Peak)	16
Exhibit 10 - Peak Hour Volumes and Truck Percentages (2019 PM Peak)	17
Exhibit 11 – Intersection Characteristics	19
Exhibit 12 – Level of Service Criteria for Signalized and Unsignalized Intersections	19
Exhibit 13 – Intersection Level of Service (2019 AM)	20
Exhibit 14 - Intersection Level of Service (2019 PM)	23
Exhibit 15 - Level of Service Thresholds for Interstates	26
Exhibit 16 - Level of Service Thresholds for Twolane Highways	26
Exhibit 17 – Highway Capacity Analysis Results for General Segments	27
Exhibit 18 – Highway Capacity Analysis Results for Climbing Lanes	28
Exhibit 19 – Speed Limits	30
Exhibit 20 – Maximum Observed Speeds All Vehicles	31
Exhibit 21 – Speed Differential between Cars and Trucks	32
Exhibit 22 – Grades and Climbing Lanes	34
Exhibit 23 - Route 28 Posted Detour Routes	36
Exhibit 24 – I-80 Posted Detour Routes	37
Exhibit 25 - Southbound Route 28 Speed Effects during I-80 Closure (Near US 322)	38
Exhibit 26 - Southbound Route 28 Speed Effects during I-80 Closure (Near New Bethlehem)	38
Exhibit 27 - Southbound Route 28 Speed Effects during I-80 Closure (Near Kittanning)	39
Exhibit 28 - Trip Characteristics	40
Exhibit 29 - Home Grids for Route 28 Corridor Travelers	41
Exhibit 30 - Origin-Destination Heat Map (Weekdays)	41
Exhibit 31 - Redbank Valley Trail (New Bethlehem) User Demographics	42
Exhibit 32 - Redbank Valley Trail (New Bethlehem) Trip Characteristics	43
Exhibit 33 - Distribution of Traffic Passing a Point On Route 28 near South Main St Brookville	44
Exhibit 34 - Distribution of Traffic Passing a Point On Route 28 near South Main St Brookville	45
Exhibit 35 - Top Routes from Pittsburgh to Brookville	46
Exhibit 36 – Geographic Context of Overall Crash Frequency	47
Exhibit 37 – Crashes by Context Area	48
Exhibit 38 – Crash Location Breakdown	49
Exhibit 39 – Crash Type Breakdown	49
Exhibit 40 – Crash Severity Breakdown	49
Exhibit 41 – Crash Time of Day Breakdown	50
Exhibit 42 – Crash Weather Condition Breakdown	50
Exhibit 43 – Crash Seasonality Breakdown	50
Exhibit 44 – Crash Illumination Type Breakdown	50
Exhibit 45 – Crash History Comparison (Fatalities)	53
Exhibit 46 – Crash History Comparison (Hit Fixed Object)	54

Exhibit 47 - Crash History Collision Type Analysis (Insets 1)	55
Exhibit 48 - Crash History Collision Type Analysis (Insets 2)	56
Exhibit 49 - Crash History Collision Type Analysis (Insets 3)	57
Exhibit 50 – Crashes Involving a Pedestrian	58
Exhibit 51 – Crashes Involving a School Bus	59
Exhibit 52 – PennDOT Safety Screening Segments	60
Exhibit 53 – Redbank Valley Trail System	64
Exhibit 54 - Multimodal Facilities (Distant)	65
Exhibit 55 – Multimodal Facilities (South Bethlehem)	66
Exhibit 56 - Multimodal Facilities (New Bethlehem)	67
Exhibit 57 – Multimodal Facilities (New Bethlehem Plaza and High School Area)	68
Exhibit 58 - Multimodal Facilities (Redbank Valley Trail Crossing of Route 28)	69
Exhibit 59 - Multimodal Facilities (Hawthorn)	70
Exhibit 60 – Design Chart Horizontal Radii	71
Exhibit 61 – Areas with Horizontal Radii Less Than Current Recommended Design Value	72
Exhibit 62 – Areas of Horizontal Deficiency	73
Exhibit 63 – Area with Vertical Grades Exceeding Maximum Design Grade	74
Exhibit 64 – Vertical Deficiency	75
Exhibit 65 – Stakeholder Concern Locations	78
Exhibit 66 – Public Survey Concern Locations	79
Exhibit 67 – Summary of Public Survey Concern by Mode	80
Exhibit 68 – Field Observation Locations	83

### Appendices

Appendix A – Cost Estimate Appendix B – Capacity Analysis Appendix C – Design Criteria Appendix D – Stakeholder Meeting Minutes Appendix E – Survey Summary Appendix F – Field Notes

#### Study Area

#### Transportation and Land Use Context

The Route 28 Corridor Study focus area encompasses an approximately 40-mile length of Route 28 from the US 422 interchange near Kittanning to the south to the I-80 interchange near Brookville in the north (**EXHIBIT 1**). The land use surrounding the corridor is primarily agricultural, low-density residential, and undeveloped forest. Communities developed along Route 28 in support of the industries of lumber, mining, farming, and manufacturing in the early 1800's and 1900's, including Kittanning (est. 1803, pop. 3795), New Bethlehem (est. 1853, pop. 929), Hawthorn (est. 1916, pop. 466), Summerville (est. 1887, pop. 528), Brookville (est. 1830, pop. 3933) and villages such as Distant and Orchardville. Many of these industries continue to operate along the corridor to this day, though at reduced capacity similar to the trends of the region and nation for similar types of roadway and demographics. Freight operators in the corridor typically deliver heating oil, timber, coal, aggregates, and mechanical equipment.

Route 28 was designated from Pittsburgh to Kittanning in 1927. In the highway expansion era of the 1960's, the route was widened from Pittsburgh to Kittanning to a primarily four-lane divided expressway. Early studies evaluated widening of the remainder of Route 28 from Kittanning to Interstate 80. Over the years, a series of improvements to the existing two-lane template have been made within the study corridor to improve operations and safety and regional connectivity.

The corridor today serves many purposes. It serves short trips for residents and local agriculture and business owners, and longer regional trips for Pittsburgh-bound commuters and freight operators. Taking New Bethlehem as the approximate middle point of the corridor, it takes approximately 1 hour 10 minutes to drive to Pittsburgh along Route 28. The corridor between Pittsburgh and I-80 provides a critical temporary detour of I-80 traffic during fairly frequent traffic incidents on I-80.

The surrounding land and environmental features draw outdoor enthusiasts, including hunting, fishing, camping, and ATV riding. ATV organizations on the corridor frequently host Runs, which draw thousands of ATVs to the valley and its trails. Redbank



Creek offers trout fishing and kayaking activities. The creek runs roughly parallel to the corridor north of New Bethlehem, visibly close to the roadway in some areas where it winds through Summerville toward Brookville. Businesses are frequently located directly adjacent to the corridor. Route 28 runs through the Central Business District of New Bethlehem and the campus of Redbank Valley High School. There is an at-grade trail crossing of the Redbank Valley Trail in New Bethlehem. The last train ran on the rail corridor in 2007, when it was railbanked and transformed into the Redbank Valley Trail, a 51-mile non-motorized trail that connects from Brookville in the north, westward to the Armstrong Trail.

#### Geography

Route 28 runs through unique geography that could roughly be broken down into three sections. The southern section from approximately Kittanning to New Bethlehem hosts mountainous terrain adjoining steep slopes with long grades exceeding 9% in some areas and winding turns. Truck climbing lanes and brake check areas are found throughout this portion of the corridor. In the middle section of the corridor from approximately New Bethlehem to Summerville, the mountains begin to break to flatter, rolling hills with passing zones and clearer lines of sight. The northern section of the corridor from Summerville to US 322 has rolling terrain, but winds horizontally around the mountain and generally follows the Redbank Creek. The segment from US 322 to I-80 is built-up with commercial businesses and densely spaced driveways, travel service amenities, signals, and four lanes of traffic with turning lanes.

Exhibit 1 – Study Area Limits



#### Steering Committee & Study Goals

Steering Committee Members Southwestern Pennsylvania Commission North Central RPO Northwest RPO Armstrong County Clarion County Jefferson County PennDOT District 10 The purpose of this study is to understand and address the present and future needs of the Route 28 corridor, from an operational and safety perspective for all modes of travel to support current and future business development and enhance the quality of life for the residents along the corridor. A Steering Committee was established to guide the study and make decisions as it progressed. The goals of the study were developed with the Steering Committee. These goals were used to guide conversations with the public and corridor stakeholders to uncover specific areas of concern or opportunity for improvements. These goals will also be used to determine the effectiveness of conceptual improvement alternatives.

#### **Route 28 Study Corridor Goals:**

- Improve Safety improve safety for all modes of transportation
  - Improve Security improve security by maintaining critical assets such as bridges and reducing emergency response times
- Support Regional Economic Development promote the corridor as a regional trade route between I-80 and Pittsburgh, in addition to attracting new businesses
  - **Promote Tourism** promote tourism to historic locations, trails, and outdoors activities
- Facilitate Regional Connectivity facilitate connections to regional routes
  - Accommodate Multimodal Use improve existing and plan for new multimodal connections to nonmotorized facilities
  - Accommodate Freight Movement facilitate access for freight and trucks
- Improve Operations improve operations and reduce congestion
  - Improve Resiliency / Reliability provide reliable travel times
  - Focus on Asset Preservation maintain a good state of repair of assets such as bridges, guide rail, signs, drainage, slopes, lighting, and pavement structure





- Minimize Environmental Impacts minimize impacts to the environment and community
  - Improve Quality of Life improve quality of life by providing access to a safe and efficient transportation system and public resources
  - Gain Community Buy-in/Satisfaction promote projects that have broad community support and meet the study's goals, and minimize impacts to the traveling public during construction



#### **Previous Studies**

#### Previous and Related Studies

The Route 28 Corridor is also known as the Alexander H. Lindsay Memorial Highway or the Allegheny Valley Expressway. This section of the Route 28 Corridor from Kittanning to Brookville, mile marker 40 to mile marker 80 of the 98 mile corridor has been the subject or mentioned in a number of studies over the past 30 years. The relevant previous studies were reviewed for their findings to assist in evaluating the corridor to consider advancing with future conceptual improvements with this study (EXHIBIT 2).

The studies consulted included:

- <u>State Route 28 Feasibility Study Kittanning to I-80 Armstrong, Clarion & Jefferson Counties,</u> <u>Pennsylvania</u>. Michael Baker, Int'I. June 1994.
- Armstrong County Comprehensive Plan. Mullin & Lonergan Associates Incorporated, 2005.
- <u>Clarion County Comprehensive Plan</u>. Clarion County Planning Commission & Graney, Grossman, Ray and Associates, 2004.
- Jefferson County Comprehensive Plan Update 2018. The EADS Group, July 2018.
- <u>North Central PA RPO Long Range Transportation Plan.</u> North Central PA Rural Planning Organization, July 2017.
- North Central PA Regional Safety Study. McCormick Taylor, March 2012.
- <u>Northwest PA Commission 2015-2040 Long Range Transportation Plan.</u> Northwest PA Commission, June 2015.
- <u>Redbank Valley Trail Feasibility Study.</u> Mackin Engineering Company, June 2011.
- <u>Smart Moves for a Changing Region.</u> Southwestern Pennsylvania Commission, 2019.
- <u>Southwestern Pennsylvania Regional Freight Plan.</u> Resource System Group Inc. (RSG), French Engineering, Whitman, Requardt, and Associates, LLP (WRA), 2016.

The most recent previous study was the <u>State Route 28 Feasibility Study Kittanning to I-80 Armstrong, Clarion & Jefferson Counties, Pennsylvania</u>. Michael Baker, Int'I., June 1994. This feasibility study examined the section of Route 28 between Kittanning, PA and Interstate 80. The initial recommendation based on a Preliminary Location Study for State Route 28 completed by The Pennsylvania Department of Transportation in the 1960's was to extend a 4 lane, limited access facility from Aspinwall to I-80. A portion of this recommendation was built in the 1970s and 1980s terminating in Kittanning, PA. This study examined the feasibility of continuing the 4-lane template from Kittanning to I-80. As part of the study a conceptual cost estimate was completed to complete this widening. This cost estimate was examined and escalated to 2020 dollars (EXHIBIT 3). While this estimate accounts for the construction cost, it does not take into account more stringent modern environmental regulations. In particular, regulations related to stormwater management volume and rate management and water quality treatment and the mitigation of protected environmental features such as streams and wetlands

located throughout the corridor. Accounting of this design, permitting, environmental and community impacts, construction, and future maintenance, presents potentially hidden costs which would place a further strain on initial design and construction costs and future PennDOT maintenance of the permitted stormwater and mitigation features.

The Southwestern Pennsylvania Regional Freight Plan provided insight into the freight movement within the region. Most of the report focused on the I-80 & I-79 corridors. There were three potential future project recommendations specifically related to the RT 28 Corridor.

- RT 28 Truck Climbing Lane
- RT 28 Geometry Improvements
- RT 28 North Lane Expansion to County Line

The County Comprehensive Plans were reviewed for recommendations and future goals of each county. Some of the specific local concerns related to this study from the individual Comprehensive Plans include:

#### Armstrong County:

- Maintaining the 372 state owned bridges
- Public opinion favors improved public transportation
- Longer than state average commuting times

#### Clarion County:

- Desire to retain young workers in the area
- Public opinion favors improved public transportation
- Public opinion favors recreational trails in the area
- Some interchange areas with commercial development are seeing some traffic congestion. Route 68 between PA-66 to I-80

#### Jefferson County:

- No major North/South routes, lack of limited access highways in the area.
- Limited public transportation available in Jefferson County
- Freight rail lines operate in the County but no rail passenger service



Exhibit 2 – Previous Studies Areas of Concern

#### Exhibit 3 – Estimated Cost Breakdown for 1994 and 2020

	Michael Baker's 1994 Study		McCormick Taylor's 2020 Study Update	
ltem	Cost/Mile (1994)	35 Miles (1994)	Cost/Mile (2020)	35 Miles (2020)
Clearing and Grubbing	\$150,000	\$5,250,000	\$150,000	\$5,250,000
Roadway Excavation	\$3,000,000	\$105,000,000	\$3,567,000	\$124,845,000
Pavement, Shoulders, Curbs	\$3,200,000	\$112,000,000	\$4,460,000	\$156,100,000
Drainage	\$900,000	\$31,500,000	\$1,200,000	\$42,000,000
Guiderail and Barrier	\$70,000	\$2,450,000	\$132,000	\$4,620,000
Right-of-Way Fence	\$110,000	\$3,850,000	\$158,400	\$5,544,000
Landscaping	\$130,000	\$4,550,000	\$217,545	\$7,614,075
Temporary Traffic Control	\$210,000	\$7,350,000	\$351,418	\$12,299,630
Utility Relocations	\$200,000	\$7,000,000	\$334,684	\$11,713,940
Bridges, Box and Arch Culverts	\$3,900,000	\$136,500,000	\$6,526,331	\$228,421,585
Signalization and Signing	\$30,000	\$1,050,000	\$50,203	\$1,757,105
Pavement Markings and Delineators	\$20,000	\$700,000	\$33,469	\$1,171,415
Erosion and Sedimentation Control	\$250,000	\$8,750,000	\$418,355	\$14,642,425
Miscellaneous	\$400,000	\$14,000,000	\$669,368	\$23,427,880
Mobilization/Field Office	\$450,000	\$15,750,000	\$753,039	\$26,356,365
Stormwater Management	-	-	\$418,355	\$14,642,425
Subtotal		\$455,700,000		\$680,405,845
Design Engineering (10%) \$45,570,000		\$68,040,585		
Construction Engineering (5%) \$22,785,000		(10%) \$68,040,585		
Subtotal		\$524,055,000	\$816,487,01	
Right-of-Way		\$26,202,750		\$40,824,351
TOTAL		\$550,257,750		\$857,311,365

See **APPENDIX A** for the Full Cost Estimate explanation.

#### **Traffic Analysis**

#### **Existing Traffic Conditions**

Traffic conditions vary along the approximately 40-mile length of the Route 28 study corridor. The Average Daily Traffic (ADT) is a measure of the vehicle volume passing over a segment of roadway in a 24-hour period. Average Daily Truck Traffic (ADTT) measures only truck traffic. The most recent ADT data collected between 2017 and 2019 shows ADTs ranging from 5,600 to 7,300 vehicles per day south of New Bethlehem to 4,100 to 4,600 vehicles per day north of New Bethlehem (**EXHIBIT 4**). Truck percentages are consistently around 15%, which is fairly high compared to the statewide average.

**EXHIBIT 5** shows the hourly distribution of traffic from the six count stations. Traffic during the PM peak hour is generally higher than the AM, with passenger cars showing the biggest variation in hourly volumes likely due to commuter and school traffic. Truck volumes are relatively consistent throughout the daylight hours, picking up in the early morning around 5am and tapering off in the late afternoon around 4pm. This may reflect daylight operations of resource extraction industries such as timber, coal, natural gas, fuel and heating oil, and equipment hauling. This data reflects observations on the corridor. This data is referenced from six (6) regularly counted PennDOT count stations along the Route 28 corridor (**EXHIBIT 6**).

ID	Location	Year	ADT	ADTT	Truck %
11706	Route 28 north of SR 85	2019	7,298	1,140	15.6
164	Route 28 south of Calhoun School Rd	2019	5,601	881	15.7
165	Route 28 south of South Bethlehem	2019	7,320	1,031	14.1
1342	Route 28 north of New Bethlehem	2017	7,025	821	11.7
31595	Route 28 near North Passing Zones	2018	4,147	624	15.0
32137	Route 28 north of Summerville	2018	4,635	731	15.8

#### Exhibit 4 – Average Daily Traffic Data

#### Exhibit 5 – Route 28 Permanent Count Station Hourly Traffic Counts





Exhibit 6 – PennDOT Count Stations

#### **Counted Intersections**

In order to pinpoint locations of concern for existing and future traffic operations, turning movement counts were collected at 16 intersections along the corridor previously identified by the Steering Committee as higher volume or potentially congested intersections (EXHIBIT 7 and EXHIBIT 8). The counts were conducted using MioVision camera technology. Passenger cars and heavy vehicles were counted on Tuesday, November 19, 2019, an average weekday while school was in session. Count data for the AM and PM peak hours can be found in the diagrams in EXHIBIT 9 and EXHIBIT 10, respectively, along with truck percentages and peak hour factors.

Due to the length of the study corridor, intersections were grouped by area to determine the AM and PM peak hours. Some intersections belong to no grouping as they are isolated and far from the influence of other intersections. Generally, the AM peak hours began between 7:15 AM and 7:45 AM, and the PM peak hours began between 3:15 PM and 4:00 PM. Car and truck volumes were left unbalanced due to the distance between intersections along the corridor with intermediate driveways and businesses. A minimum value of 1 vehicle was applied for each movement that is allowed. This was done to improve reasonableness for the operational analysis, as zero values can create errors in the results.

ID	Intersection Name
1	SR 28 & SR 85
2	SR 28 & SR 1004 (Madison Road) & Kohlersburg Road
3	SR 28 & Kohlersburg Road
4	SR 28 & SR 1025 (Putneyville Road)
5	SR 28 (Broad Street) & SR 66 (Wood Street)
7	SR 28 & Center Street / Walker Flat Road
8	SR 28 & SR 536 (Mayport Road)
9	SR 28 & Carrier Street
10	SR 28 & South Main Street
11	SR 28 & SR 0322
12	SR 36 & I-80 EB Ramps
13	SR 36 & I-80 WB Ramps
14	SR 28 & Waterford Pike
15	SR 28 & I-80 EB Ramps
16	SR 28 & I-80 WB Ramps

#### **Exhibit 7 – Counted Intersections**



Exhibit 8 – Turning Movement Count Locations



Exhibit 9 – Peak Hour Volumes and Truck Percentages (2019 AM Peak)



Exhibit 10 - Peak Hour Volumes and Truck Percentages (2019 PM Peak)

#### Traffic Analysis Methodology

Capacity and level of service (LOS) analyses were completed to evaluate the operational performance of vehicular traffic within the study area. These analyses were completed for Base Year 2019 (Existing) and will be conducted for the future year 2045 in the Future Conditions Memorandum. The traffic analysis software used to analyze the operations at intersections was TrafficWare Synchro 10.3, Build 28, Revision 0. For two-lane highway, freeway, and ramp segments, the software McTrans Highway Capacity Software 7 (HCS) was used. HCS7 uses the *Highway Capacity Manual, 6<sup>th</sup> Edition* methodology to develop Level of Service measures.

#### Synchro and Intersection Control Assumptions

Traffic signal plans were obtained from the PennDOT District 10-0 Traffic Unit for the signalized intersection locations on the corridor. The AM and PM peak period timing plan phasing, cycle lengths, splits, and offsets were input to Synchro software. The following parameters were used in the intersection traffic analysis:

- Peak hour factors were input by intersection by peak hour.
- Traffic volumes and heavy vehicle percentages by movement were also input by peak hour.
- Where applicable, the phasing and timings were translated to NEMA-compliant phasing to obtain consistent delay and level of service results.
- Parameters from *PennDOT Publication 46 Traffic Engineering Manual* such as lost time adjustments and saturation flow rates were asserted according to information such as land use for intersections.
- Intersections were assumed as "rural" type except for the intersections in New Bethlehem and Brookville which were analyzed as "suburban".

Synchro assumptions for the intersections are listed in **EXHIBIT 11**. The Level of Service criteria used for signalized and unsignalized intersections is shown in **EXHIBIT 12**. The delay and Level of Service results from the Synchro analysis follow *Highway Capacity Manual*, 6<sup>th</sup> Edition methodology, except where it cannot provide information due to complex geometry. In those cases, Synchro results for delay were used. LOS results for the 2019 AM peak hour and 2019 PM peak hour are found in **EXHIBIT 13** and **EXHIBIT 14** respectively.

All intersections currently operate at a LOS "C" or better overall. The left-turns at the signal at SR 85 (intersection #1) operate under protected-only phasing, when coupled with long cycle times leads to poor levels of service in the peak hours. In the PM peak hour, the signalized off-ramp at I-80 and SR 36 (intersection #13) exhibits a poor level of service for left-turns which are also protected-only. In general, capacity at intersections is not a major concern.
ID	Intersection Name	Control Type	AM Peak Hour	PM Peak Hour	Grouping	Land Use Type
1	SR 85	Signal	7:15	4:00	None - isolated	Rural
2	Madison/Kohlersburg Rd	Stop	7:15	4:15	None - isolated	Rural
3	Kohlersburg Rd	Stop	7:15	3:15	1	Suburban
4	Putneyville Rd	Stop	7:15	3:15	1	Suburban
5	Broad at Wood	Signal	7:15	3:15	1	Suburban
7	Hawthorn	Stop	7:30	4:15	None - isolated	Rural
8	Mayport	Stop	7:15	3:30	None - isolated	Rural
9	Carrier St	Stop	7:15	3:00	None - isolated	Rural
10	South Main	Stop	7:45	3:45	2	Suburban
11	SR 322	Signal	7:45	3:45	2	Suburban
12	Waterford Pike	Stop	7:45	3:45	2	Suburban
13	I-80 EB Ramps at SR 36	Signal	7:45	3:45	2	Suburban
14	I-80 WB Ramps at SR 36	Signal	7:45	3:45	2	Suburban
15	I-80 EB Ramps at SR 28	Stop	7:30	3:45	3	Suburban
16	I-80 WB Ramps at SR 28	Stop	7:30	3:45	3	Suburban

# Exhibit 11 – Intersection Characteristics

Exhibit 12 – Level of Service Criteria for Signalized and Unsignalized Intersections

Level of Service	Interse (second	ction Delay ds/vehicle)
Service	Signalized	Unsignalized
А	0 - 10	0 - 10
В	> 10 - 20	> 10 - 15
С	> 20 - 35	> 15 - 25
D	> 35 - 55	> 25 - 35
E	> 55 - 80	> 35 - 50
F	> 80	> 50

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
			FD	EBL	67.3	E	F 4 7	D		
		SK 85	EB	EBT/R	40.9	D	51.7	D		
				WBL	47.8	D	41 4	D		
		SK 85	VV B	WBT/R	26.3	С	41.4	D		
1	SR 28 @ SR 85			NBL	319.2	F			38.3	D
		SR 28	NB	NBT	18.8	В	29.7	С		
				NBR	0	А				
		CD 20	CD	SBL	129.6	F	27 E	D		
		JR 20	JD	SBT/R	28.7	С	57.5	U		
	SR 28 at SR 1004 (Madison Rd)	SR 1004	EB	EBL/R	12.6	В	12.6	В		
2		SR 28	NB	NBL/T	9.3(L)	А	0.5	А	3	А
		SR 28	SB	SBT/R	0	А	0	А		
		SR 1004	EB	EBL/T/R	6.8	А	6.8	А		A
21	Kohlersburg Rd at SR	Slip Ramp	WB	WBL/T/R	7.4	А	7.4	А	7 1	
21	1004 (Madison Rd)	SR 1004	NB	NBL/T/R	7.9	А	7.9	А	7.1	
		Kburg Rd	SB	SBL/T/R	7.3	А	7.3	А		
		Kburg Rd	EB	EBL/R	13.4	В	13.4	В		
3	SR 28 @ Kohlersburg Rd	SR 28	NB	NBL/T	8.7(L)	А	0	А	0.2	А
		SR 28	SB	SBT/R	0	А	0	А		
		SR 28	EB	EBL/T/R	8.9(L)	А	0.1	А		
4		50.20	\ <b>\</b> /₽	WBL	9.4	А	1 2	Δ		
	SR 28 @ SR 839	JN 20	VVD	WBT/R	0	А	1.2	A	2.1	А
		SR 839	NB	NBL/T/R	11	В	11	В		
		Short St	SB	SBL/T/R	24.9	С	24.9	С		

Exhibit 13 – Intersection Level of Service (2019 AM)

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
		CD 20	50	EBL	9	А	0.1			
		SR 28	EB	EBT/R	7.7	А	8.1	A		
5	SR 28 at SR 66	SR 28	WB	WBL/T/R	19.1	В	19.1	В	14.6	В
		Wood St	NB	NBL/T/R	13.5	В	13.5	В		
		SR 66	SB	SBL/T/R	19.1	В	19.1	В		
		SR 28	EB	EBL/T/R	9.5 (L)	А	0.3	А		
_		SR 28	WB	WBL/T/R	9.6(L)	А	0.2	А	1.2	
/	SR 28 at Center St	Walker Flat Rd	NB	NBL/T/R	13.3	В	13.3	В	1.2	A
		Center St	SB	SBL/T/R	12.1	В	12.1	В		
		SR 28	EB	EBL/T/R	9(L)	А	0.2	А		
0	SR 28 at Mayport Rd SR 536	SR 28	WB	WBL/T/R	9.3(L)	А	0.6	А	2.6	٥
ð		Mayport Rd	NB	NBL/T/R	11.1	В	11.1	В	2.0	А
		Driveway	SB	SBL/T/R	12	В	12	В		
		SR 28	EB	EBL/T/R	8.8(L)	А	0.3	А		
٩	SR 28 at Carrier St	SR 28	WB	WBL/T/R	9.1(L)	А	1.3	А		A
5	SN 28 at carrier St	Carrier St	NB	NBL/T/R	9.8	А	9.8	А	2.5	
		Carrier St	SB	SBL/T/R	10.5	В	10.5	В		
		Driveway	EB	EBL/T/R	10.8	В	10.8	В		
10	SR 28 at S Main St	S. Main St	WB	WBL/T/R	10	В	10	В	2.3	А
		SR 28	NB	NBL/T/R	8.2(L)	А	0	А		
		SR 28	SB	SBL/T/R	8.7(L)	А	2.7	А		
		SR 322	EB	EBL/T/R	16.6	В	16.6	В		
11		SR 322	WB	WBL/T/R	14.9	В	14.9	В		
	SR 28 at SR 322	SR 28	NB	NBL	10.7	B	13.6	В	12.9	В
		<b>CD 3C</b>	CD	NB1/R	14	В	0.7	٨		
		SK 36	SB	SBL	9.4	A	9.7	A		

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
				SBT	10.2	В				
				SBR	0	А				
		L-80 Ramps	FB	EBL/T	31.1	С	22	C		
		1-00 Namps	LD	EBR	34.5	С	55	C		
12	SR 36 at I-80 EB Ramps	SR 36	NB	NBT/R	7	А	6.8	А	11.1	В
		50.26	CD	SBL	4	А	7 1	Δ		
		3K 30	JD	SBT	8.4	А	7.1	A		
				WBL/T	30.2	С	22.2	C		
		I-80 Ramps	VV B	WBR	34.4	С	32.2	L		
13	SR 36 at I-80 WB Ramps	CD 2C	ND	NBL	3.7	А	0 9	•	10.5	В
		SK 30	NB	NBT	0.1	А	0.9	А		
		SR 36	SB	SBT/R	7.6	А	7.5	А		
		SR 28	EB	EBL/T	9(L)	А	0.1	А	0.1	
14	SR 28 at Waterford Pike	SR 28	WB	WBT/R	0	А	0	А		А
14		Waterford Pike	SB	SBL/R	9.8	А	9.8	А	0.1	~
		I-80 Ramps	EB	EBL/T/R	10.1	В	10.1	В		
15	SR 28 at I-80 EB Ramps	SR 28	NB	NBT/R	0	А	0	А	3.6	А
		SR 28	SB	SBL/T	8.3(L)	А	0.2	А		
		I-80 Ramps	WB	WBL/T/R	9.8	А	9.8	А		
16	SR 28 at I-80 WB Ramps	SR 28	NB	NBL/T	8.3(L)	А	1.7	А	2.8	А
		SR 28	SB	SBT/R	0	А	0	А		
		SR 28	EB	EBT/R	0	А	0	А		А
81	SR 28 at Dairy Rd	SR 28	WB	WBL/T	9.2(L)	А	0.1	А	0.2	
		Dairy Rd	NB	NBL/R	10.6	В	10.6	В		

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
			ED.	EBL	51.7	D	47 7	D		
		SK 85	EB	EBT/R	44.3	D	47.7	D		
	SR 28 @ SR 85			WBL	50.5	D	45	D		
		38 83	VVB	WBT/R	29.2	С	45	D		
1				NBL	108.3	F			34.9	С
		SR 28	NB	NBT	24.1	С	26.8	С		
				NBR	0	А				
		CD 70	CD	SBL	117.2	F	20.2	C		
		JN 20	30	SBT/R	23.3	С	29.2	C		
	SR 28 at SR 1004 (Madison Rd)	SR 1004	EB	EBL/R	13.3	В	13.3	В		
2		SR 28	NB	NBL/T	9.2(L)	А	0.7	А	2	А
		SR 28	SB	SBT/R	0	А	0	А		
		SR 1004	EB	EBL/T/R	7.3	А	7.3	А	7.5	۸
21	Kohlersburg Rd at SR	Slip Ramp	WB	WBL/T/R	7.6	А	7.6	А		
21	1004 (Madison Rd)	SR 1004	NB	NBL/T/R	7.8	А	7.8	А	7.5	A
		Kburg Rd	SB	SBL/T/R	7.3	А	7.3	А		
		Kburg Rd	EB	EBL/R	14.6	В	14.6	В		
3	SR 28 @ Kohlersburg Rd	SR 28	NB	NBL/T	8.9(L)	А	0	А	0.2	А
		SR 28	SB	SBT/R	0	А	0	А		
		SR 28	EB	EBL/T/R	9.1(L)	А	0	А		
4		50.20		WBL	9.5	А	1 0	٨		
	SR 28 @ SR 839	JN 20	VVD	WBT/R	0	А	1.9	A	1.8	A
		SR 839	NB	NBL/T/R	10.6	В	10.6	В		
		Short St	SB	SBL/T/R	24.8	С	24.8	С		

## Exhibit 14 - Intersection Level of Service (2019 PM)

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS	
		CD 20	ED.	EBL	9.4	А	0.0	٥			
		SK 28	EB	EBT/R	8.3	А	8.6	A			
5	SR 28 at SR 66	SR 28	WB	WBL/T/R	19.3	В	19.3	В	15.6	В	
		Wood St	NB	NBL/T/R	13.5	В	13.5	В			
		SR 66	SB	SBL/T/R	19.7	В	19.7	В			
		SR 28	EB	EBL/T/R	9.7(L)	А	0.5	А			
7	7 SR 28 at Center St	SR 28	WB	WBL/T/R	9.5(L)	А	0.4	А	1.4		
/	SR 28 at Center St	Walker Flat Rd	NB	NBL/T/R	15.3	С	15.3	С	1.4	A	
		Center St	SB	SBL/T/R	12.5	В	12.5	В			
		SR 28	EB	EBL/T/R	9.2(L)	А	0.1	А			
0	SR 28 at Mayport Rd SR 536	SR 28	WB	WBL/T/R	9.4(L)	А	1.4	А	2.2	^	
õ		Mayport Rd	NB	NBL/T/R	13.1	В	13.1	В	5.5	~	
		Driveway	SB	SBL/T/R	14	В	14	В			
		SR 28	EB	EBL/T/R	9.3(L)	А	0.1	А	2.4		
0	SP 29 at Carrier St	SR 28	WB	WBL/T/R	9.1(L)	А	1.4	А		А	
9	SR 20 dt Carrier St	Carrier St	NB	NBL/T/R	11.4	В	11.4	В	2.4		
		Carrier St	SB	SBL/T/R	12.1	В	12.1	В			
		Driveway	EB	EBL/T/R	11.2	В	11.2	В			
10	SP 28 at S Main St	S. Main St	WB	WBL/T/R	12.4	В	12.4	В	Л	Δ	
10	SK 20 dt S Main St	SR 28	NB	NBL/T/R	8.6(L)	А	0.1	А	4	A	
		SR 28	SB	SBL/T/R	8.6(L)	А	0.8	А			
		SR 322	EB	EBL/T/R	18.5	В	18.5	В			
11		SR 322	WB	WBL/T/R	16.4	В	16.4	В			
	SR 28 at SR 322	CD 20	ND	NBL	NBL 12.4 B 15.4 D 14.1	14.1	В				
		3R 20	IND	NBT/R	16	В	15.4 B	В			
		SR 36	SB	SBL	9.3	А	10	А			

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
				SBT	11.1	В				
				SBR	0	А				
			ED	EBL/T	29.5	С	22.0	C		
			ED	EBR	36.8	D	55.9	Ľ		
12	SR 36 at I-80 EB Ramps	SR 36	NB	NBT/R	8.7	А	8.5	А	13.2	В
		CD 2C	CD.	SBL	5.1	А	0 1	•		
		SK 36	SB	SBT	9.4	А	8.2	A		
			14/5	WBL/T	174	F	07.4	_		
		I-80 Ramps	VV B	WBR	32.7	С	97.1	F		
13	SR 36 at I-80 WB Ramps	65.96	ND	NBL	5.7	А	1 5		29.7	С
		SK 36	NB	NBT	0.2	А	1.5	A		
		SR 36	SB	SBT/R	10.9	В	10.8	В		
		SR 28	EB	EBL/T	9.6(L)	А	0.2	А		
1/	SR 28 at Waterford Pike	SR 28	WB	WBT/R	0	А	0	А	0.2	٨
14	SK 20 at Waterioru Fike	Waterford Pike	SB	SBL/R	13.4	В	13.4	В	0.2	A
		I-80 Ramps	EB	EBL/T/R	10.1	В	10.1	В		
15	SR 28 at I-80 EB Ramps	SR 28	NB	NBT/R	0	А	0	А	2.4	А
		SR 28	SB	SBL/T	8.7(L)	А	0.5	А		
		I-80 Ramps	WB	WBL/T/R	12.6	В	12.6	В		
16	SR 28 at I-80 WB Ramps	SR 28	NB	NBL/T	8.6(L)	А	3.1	А	3.3	А
		SR 28	SB	SBT/R	0	А	0	А		
		SR 28	EB	EBT/R	0	А	0	А		
81	SR 28 at Dairy Rd	SR 28	WB	WBL/T	9.2(L)	А	0	А	0.1	А
		Dairy Rd	NB	NBL/R	11.1	В	11.1	В		

#### Highway Capacity Analysis Assumptions

Highway Capacity Software 7 (HCS7) was used to analyze the operations of two-lane highways, freeway segments, and ramps. Assumptions behind HCS inputs such as free flow speed, peak hour factor, terrain type, and driver population are as follows:

- Highway free flow speeds were assumed as posted speed limit plus 5 miles per hour. Ramp free flow speeds were assumed as posted speed plus 5 miles per hour.
- All were assumed to have rolling terrain, a familiar driver population, non-severe weather, and rural area type.

Where no corridor-specific data was available to assert otherwise, default values in HCS were maintained. These assumptions were carried through to all future year analyses.

Level of service from HCS7 reflects the criteria outlined in the *Highway Capacity Manual, 6<sup>th</sup> Edition.* Level of service for basic freeway segments and freeway merge and diverge segments can be found in **EXHIBIT 15**. Level of service for freeways and merge and diverge segments is based on roadway density in passenger cars per mile per lane. There are no weaving segments in existing or future conditions within the area of influence.

Level of service thresholds for two-lane highways can be found in **EXHIBIT 16**. For two-lane highways of Class I, level of service is based on the segment average travel speed (ATS) in miles per hour, and percent time spent following (PTSF) in percent. Class II two-lane highway level of service is based on PTSF.

Since the corridor is over 40 miles long and has varying lane and shoulder widths, the capacity analysis focused on five representative typical sections along the corridor, as well as nine locations of existing climbing lanes, and four areas with significant grades for potential climbing lanes.

Level of Service	Interstate Density (pc/mi/In)
А	>0-11
В	>11-18
С	>18-26
D	>26-35
Е	>35-45
F	Demand exceeds capacity

### Exhibit 15 - Level of Service Thresholds for Interstates

#### Exhibit 16 - Level of Service Thresholds for Twolane Highways

Level of	Class I Higl	Class I Highway					
Service	Average Travel Speed (mph)	PTSF%	PTSF%				
А	>55	<=35	<=40				
В	>50-55	>35-50	>40-55				
С	>45-50	>50-65	>55-70				
D	>40-45	>65-80	>70-85				
E	<=40	>80	>85				

#### Traffic Analysis Results

**EXHIBIT 17** shows the results from the Highway Capacity Analysis for general corridor segments. Inputs and outputs from the highway capacity analysis can be found in **APPENDIX B**. In general, the analysis shows acceptable levels of service on the typical sections.

**EXHIBIT 18** shows the results for the segments where the uphill grade is significant or over a long length, such as for the currently 1-lane segments at southbound ID #92. At this location, the LOS is E due to a low average travel speed. Anything at or below 40mph is considered failing for Class I Highways. This may be a candidate for a future climbing lane, pending the traffic criteria and warrants are met.

This traffic analysis along with field observations and input from locals have shown that while roadway capacity isn't the main issue, the likelihood of experiencing a slow down during a long trip due to following a slow-moving vehicle without frequent opportunities to pass causes significant driver frustration. A driver's anticipation that a long trip should be at highway speeds of 55mph or more also factors into the perceived poor operations, due to frequent speed limit changes below 55mph throughout communities on the corridor.

## Exhibit 17 – Highway Capacity Analysis Results for General Segments

				2019								
				AI	M Peak Hou	r	PM Peak Hour					
ID	Direction	Southern Terminus	Northern Terminus	Average Travel Speed (mph)	Percent Time Spent Following	Level of Service	Average Travel Speed (mph)	Percent Time Spent Following	Level of Service			
1	Northbound	Occor Pd	Baum Pump	46.8	56	С	45.3	76.9	D			
1	Southbound	Uscar Ru	Station	46.2	72.2	D	45.6	62.5	С			
	Northbound	SB Truck	0.3 miles	47.5	68	D	47.1	68.5	D			
2	Southbound	Climbing Lane	south of King St	47.9	58.6	С	47.4	66.2	D			
2	Northbound		Yearney	47.5	66.3	D	48.1	60.7	С			
5	Southbound	Longview Ru	Lane	47.8	61.8	С	48.1	66.5	D			
1	Northbound	Dewey Rd	SP 2001	45.5	58.1	С	45.4	52.9	С			
4 5	Southbound	Dewey Nu	517 2001	45.7	50.7	С	44.9	64.6	D			
	Northbound	Moore Rd	Mendenhall	46.5	63.1	С	46.3	49.9	С			
	Southbound		Rd	47.2	43.7	С	45.3	71.1	D			

				2019									
			ļ	AM Peak Hour			PM Peak Hour						
ID	Direction	Configuration	Average Travel Speed (mph)	Percent Time Spent Following	Level of Service	Average Travel Speed (mph)	Percent Time Spent Following	Level of Service					
10	Northbound	2 Lanes	53.9	7.6	В	54.3	12.7	В					
11	Northbound	2 Lanes	53	6	В	56.4	8.6	А					
12	Northbound	2 Lanes	53.5	6	В	56.8	8.6	А					
13	Northbound	2 Lanes	52.4	6.6	В	50.3	6.1	В					
90	Northbound	1 Lane	42	48.5	D	41.4	77	D					
91	Northbound	1 Lane	44	47	D	43.8	65.7	D					
14	Southbound	2 Lanes	52.7	6.9	В	53.7	5.8	В					
15	Southbound	2 Lanes	53.4	7.2	В	54.7	6	В					
16	Southbound	2 Lanes	57.1	7	А	53.7	9.7	В					
17	Southbound	2 Lanes	54.4	2.7	В	56.6	6.9	А					
18	Southbound	2 Lanes	53	4	В	53.6	10.1	В					
92	Southbound	1 Lane	39.1	59.2	E	40.5	44.2	D					
93	Southbound	1 Lane	43.2	59.2	D	44.4	44.2	D					

# Exhibit 18 – Highway Capacity Analysis Results for Climbing Lanes

#### Speed and Travel Times

Speed and travel time are noted concerns for residents and businesses that use the Route 28 corridor. Observations on the corridor show that getting stuck behind a slow-moving vehicle in an area with no climbing lanes or passing zones creates driver frustration, leading to aggressive driving behavior such as speeding and improper passing. The data shows a wide range of preferred speeds for travelers on the corridor, as well as the speed differentials between passenger cars and large commercial vehicles.

**Speed limits** fluctuate throughout the corridor from 25mph in built-up areas like New Bethlehem, to 35mph leaving the city, 40 mph, and 45mph around curves and 55mph in most sections between communities. The speed limit fluctuates frequently between Distant, New Bethlehem, and Hawthorn. It was noted during stakeholder interviews that speed limits may not be consistently posted for the same segment of roadway in opposing directions. Current posted speed limits are shown in **EXHIBIT 19**.

SPC provided observed speed and travel time data for the corridor from INRIX. INRIX is a data repository for historical congested travel speeds and travel times. There are 13 INRIX segments that cover the length of the Route 28 corridor, ranging from 0.1 to 7.4 miles in length. On average, the segments are about 3 miles in length. The date range used in the INRIX analysis was the average of weekday peak 7-8 AM hour and 4-5 PM hours in 2018. The free flow speed referenced for this study was assumed to be the maximum observed average speed on weekdays or weekends.

**Speeding** is a noted concern – maximum observed speeds are shown in **EXHIBIT 20**. In areas like New Bethlehem, maximum speeds range from 35 to 40 mph in the posted 25 mph zone. Most segments in the corridor have maximum observed speeds trending above 55 mph, including on areas with significant grades and curvature. On average, the maximum speeds for cars on the corridor is 57 mph. The average maximum speed for trucks on the corridor is 51 mph. This 6 mph speed differential is exacerbated on areas where there are significant grades. **EXHIBIT 21** illustrates the speed differentials between passenger cars and trucks. The longest segment of speed differential between cars and trucks is from approximately Goheenville to Distant (5 to 10 mph difference) over the area known locally as Hogback Hill. Field observations and GIS data noted areas of significant grade







change in this area. Another segment with a high-speed differential between cars and trucks is coming into South Bethlehem around the 15 mph curve through New Bethlehem (10 to 15 mph difference).

Exhibit 19 – Speed Limits





Exhibit 20 – Maximum Observed Speeds All Vehicles



Exhibit 21 – Speed Differential between Cars and Trucks

### Grades

Roadway grades were mapped for the corridor to better understand areas where cars and trucks are subject to different acceleration and braking requirements. Grades were mapped using elevations captured at 1000-foot intervals. In the northbound direction, the uphill grades (> 3%) are shown in red, and downhill grades (< 3%) are shown in blue. Anything between 3% grade was shown as "rolling" or "flat". Based upon the observed average maximum speed for cars and truck at approximately 55 MPH, grades exceeding 5% have been identified. This correlates with PennDOT's Design Manual 2 maximum vertical grade criteria of 5% based upon functional classification of the Route 28 Study Corridor. This vertical grade is shown to provide an understanding of locations where existing grades may be effecting traffic operations.

The mapped grade data was compared to the locations of existing truck climbing lanes and passing zones, in order to understand where truck climbing lanes might be warranted (EXHIBIT 22). General purpose passing zones on relatively flat surfaces are also included on this map to give an idea of how frequently there are opportunities to overtake vehicles. The map shows locations south of New Bethlehem that have steep grades for long stretches with no climbing lanes.









Exhibit 22 – Grades and Climbing Lanes

#### **Detour Conditions**

Posted detour routes on Route 28 can be seen in **EXHIBIT 22**. Detour traffic from I-80 was a concern noted by nearly all stakeholders as portions of the SR 28 corridor are marked for the Orange, Blue, and Green detours converging at US 322 as shown in **EXHIBIT 23**. Detour traffic from travelers following their personal navigation devices and getting back on to be detoured again was identified as an issue.

INRIX historical speed data was used to understand the range of influence and operational impact of I-80 detour traffic on the corridor. Incident logs were pulled to identify dates of full roadway closures on I-80 in the vicinity of the study area. This data was analyzed to evaluate historical hourly speed data. One particular closure of I-80 was examined. This was an incident that occurred on August 8<sup>th</sup>, 2016 where I-80 had a significant hours-long closure due to a multi-vehicle accident. The closure started around 2pm and extended through the PM peak hours. This incident was evaluated using three INRIX segments of probe data on SR 28 – near I-80, the middle of the corridor near New Bethlehem, and the south near Kittanning.

**EXHIBIT 24** shows the southbound segment of Route 28 in the vicinity of US 322, closest on the corridor. Average hourly speeds drop from approximately 32 mph before the closure down to about 5mph for three hours during the closure, as traffic has detoured traffic away from I-80. The congestion lasts until approximately 9pm when speeds return to about 31mph. **EXHIBIT 25** shows the southbound segment of Route 28 approximately 20 miles south of I-80 near New Bethlehem. New Bethlehem speeds began to drop from 40mph at 3pm to a low of 19mph at 7pm. Speeds in New Bethlehem climbed back to free flow by about 8pm. **EXHIBIT 26** shows the southernmost segment of the Route 28 corridor approximately 35 miles south of I-80 near Kittanning. A small drop in speed was experienced around 2pm, perhaps as travelers were notified of the closure and changed their routes mid-navigation.

This analysis supports that interstate closures can have widespread impacts on the corridor traffic operations. This in conjunction with detour route choice and signage, and travelers using personal devices to navigate off of I-80 create bottleneck







conditions that are challenging for emergency responders, residents, and the traveling public.

The New Bethlehem bridge was identified by stakeholders as an infrastructure security concern as there is no redundancy in the roadway system. The Black Detour route is posted for the New Bethlehem bridge closures. The typically 17-mile stretch of Route 28 is detoured westward at a length of more than 43 miles through many villages and communities that are not easily navigable by trucks to reach New Bethlehem or Kittanning.



Exhibit 23 - Route 28 Posted Detour Routes

Exhibit 24 – I-80 Posted Detour Routes







Exhibit 26 - Southbound Route 28 Speed Effects during I-80 Closure (Near New Bethlehem)







#### Streetlight Data

Streetlight is a big-data company that provides analyzed by transportation planners to examine



travel behavior and traveler demographics. Streetlight provides data for personal and commercial travel types. It also provides some information on multimodal travel including bicyclists and pedestrians. Access to the Streetlight data service was provided by the Southwestern Pennsylvania Commission's subscription in support of the Route 28 Corridor Study.

The data was analyzed to understand existing travel conditions on the Route 28 corridor, such as the lengths of trips. EXHIBIT 27 shows general characteristics of all trips over the 40-mile length of the study corridor. More than half of the trips on the corridor are over 60 minutes in duration, with a large number of trips over 120 minutes. This trip duration includes commercial vehicle traffic, which may have hauling routes along the corridor or destined northward to Forest, Elk or Venango counties. Trip lengths correspond with the trip duration, with a majority of trips longer than 30 miles. More than half of the travel speeds are between 30 and 50mph, with approximately 16% traveling 50 to 70mph.





Who does the Route 28 corridor serve? EXHIBIT 28 shows the geographic spread of the home locations of travelers. The cluster shows that travelers on this 40-mile section of the Route 28 corridor primarily live and work in areas adjacent to the corridor to the east and west. There are fewer home locations of Route 28 travelers north of I-80. The cluster of home locations stretches as far southwest as Pittsburgh, with a few isolated clusters focused primarily in places that are accessible via Route 28, I-80, I-79, US 422, and US 322 such as Youngstown, Erie, Altoona, and State College. The public survey conducted for this study was targeted to the zip codes surrounding the corridor and advertised on the Southwestern Pennsylvania Commission's social media pages.

Where are people going on the Route 28 corridor, and at what levels of frequency? EXHIBIT 29 uses a point in the middle of the corridor to show all personal trips passing through this point on a weekday and their origins and destinations. This map highlights a distinct diagonal pattern of trips that follows the trajectory of the corridor. There is a large geographic catchment area in the northeast counties (Forest, Elk, Warren, McKean, Clearfield, Cameron) for Route 28 traffic destined to Kittanning and Pittsburgh, as well as hauling, tourist-related traffic for outdoors activities to the northeast counties.



Exhibit 29 - Home Grids for Route 28 Corridor Travelers

Exhibit 30 - Origin-Destination Heat Map (Weekdays)



How are people using the multimodal facilities on the corridor? The Open Street Map alignment data for the Redbank Valley Trail and Armstrong County Trail were imported to understand bicycle and pedestrian usage of the trail system (EXHIBIT 30). A point in New Bethlehem was chosen to see a snapshot of the trail user demographics and trip characteristics. EXHIBIT 31 shows the education, family status, and income levels of trail users. EXHIBIT 32 shows the trip duration characteristics of the trips on the trail.

The largest proportion of trips on the corridor are 45-60 minutes in length, which reveals a tremendous benefit to public health in the communities that it serves. The length of the trail and access available to users along the Route 28 Corridor provides a great regional recreational asset.





Exhibit 31 - Redbank Valley Trail (New Bethlehem) User Demographics



Exhibit 32 - Redbank Valley Trail (New Bethlehem) Trip Characteristics



Streetlight data was used to examine the distribution of trips passing a point near the intersection of Route 28 and South Main Street in Brookville. It shows traffic coming from approximately Williamsport and Brookville in the east, from areas slightly north of the I-80 interchange such as Sigel and Brockway down through Kittanning and Pittsburgh. Applying a filter to the proportion of traffic shows the popular destinations of traffic past this point. Approximately 15% of trips passing this point are destined to Kittanning (**EXHIBIT 34**). Approximately 4% of trips passing this intersection are destined to Pittsburgh (**EXHIBIT 35**). This finding shows that the corridor primarily serves demand to Kittanning and communities along the Route 28 corridor, rather than functioning currently as a regional through route.

#### Exhibit 33 - Distribution of Traffic Passing a Point On Route 28 near South Main St Brookville



### (Filtered by 15%)

## Exhibit 34 - Distribution of Traffic Passing a Point On Route 28 near South Main St Brookville (Filtered by 4%)



**EXHIBIT 36** shows a Top Route from Pittsburgh to a point east of Brookville. It highlights two main routes: the Route 28 corridor, and the I-79 to I-80 corridor. The Streetlight Index is a proportional approximation of traffic along the route. The Streetlight Index for the Route 28 corridor (80.6 miles, 1h 31m) is 65 versus an index of 26 for I-79 to I-80 (118 miles, 1h 50m). This shows that Route 28 is approximately three times more popular than I-79 to I-80 for this origin-destination zone pair. The reverse is also true. The trip southbound from Brookville to Pittsburgh shows Route 28 almost four times more popular with an index of 87 compared to I-80 to I-79 with an index of 23. However, we do not currently observe a significant amount of through traffic on this route because there is not significant demand between these two points. For example, about 4% of traffic passing South Main Street near Brookville is destined to/from Pittsburgh. Most trips were destined adjacent to the along the Route 28 Corridor or Kittanning.



#### Exhibit 35 - Top Routes from Pittsburgh to Brookville

In summary, the Streetlight data for the Route 28 corridor confirms the understanding that a majority of trips on the corridor are longer distance trips that service residences, business, and industry in the vicinity of the 40-mile corridor and beyond, into the rural counties in the northeast. It also indicates that Route 28 is a preferred route for the regional connection from Pittsburgh to I-80, though geometric constraints and economic conditions may play a role in the low demand between the two points currently.

# Safety Analysis

### Methodology

The most recent five years of available crash data (2013 to 2017) were compiled from the Pennsylvania Crash Information Tool (PCIT). Information relating to vehicle crash type, injury severity, weather conditions, time of day, seasonality, illumination, and roadway condition were analyzed to identify crash patterns and locations where the overall crash and fatality rates are higher than the statewide average.

The Department of Transportation defines a "reportable crash" as those that involve a fatality, injury, or require towing of one or more vehicles. Therefore, the crash system includes data from those "reportable" incidents only. The segments encompass approximately 40 miles of roadway network along Route 28 from Kittanning to I-80.



#### **Crash History Analysis**

Analysis of the crash data along the Route 28 corridor identified 291 reported motor vehicle crashes within the five-year period 2013 to 2017. Reported crash cluster patterns and trends are summarized below.

To drill down into the crash patterns, sub-segments of the corridor were chosen for analysis among different land use and transportation contexts. **EXHIBIT 37** shows the crash frequency analysis from south to north along the corridor. **EXHIBIT 37** shows the boundaries. From south to north, these included:

- Hayes Hollow area from US 422 through SR 85 to SR 1035 (Oscar Road)
- Goheenville area from SR 1018 to the Mahoning Creek
- Distant area from the Mahoning Creek to the 15mph curve south of South Bethlehem
- New Bethlehem area from the 15mph curve in South Bethlehem to west of SR 1013
- Hawthorn area from SR 1013 through SR 536 Mayport Road to Sandy Flat Road
- Summerville area from Sandy Flat Road to south of South Main Street
- Brookville area from South Main Street through US 322 to the I-80 ramps

### Exhibit 36 – Geographic Context of Overall Crash Frequency

Context	Length	Crashes	Percent	Crashes/Mile
Hayes Hollow	7.2	96	33%	13.3
New Bethlehem	3.7	36	12%	9.7
Summerville	7.3	63	22%	8.7
Goheenville	6.2	37	13%	6.0
Hawthorn	8.0	44	15%	5.5
Brookville	1.7	7	2%	4.1
Distant	4.1	8	3%	2.0
Total	38.2	291	100%	-

Exhibit 37 – Crashes by Context Area



A general safety analysis of the entire corridor existing conditions was prepared to examine crash contributing factors and details such as location, type, severity, time of day, weather, seasonality, and illumination type. The crash location information shows that of the 291 reported crashes, 232 (80 percent) occurred at a mid-segment location, 56 (19 percent) occurred at an intersection, and remaining 3 crashes are identified as other types (1 percent) (EXHIBIT 39). The primary crash type observed involved vehicles hitting fixed objects (40 percent), angle crashes (20 percent), and rear-end crashes (14 percent) (EXHIBIT 39).

Approximately 5 percent of the crashes involved serious to fatal injuries (**EXHIBIT 40**). Overnight and mid-day were the highest time periods for crashes, with 70 percent of the daily crashes combined (**EXHIBIT 42**). 74 percent of crashes occurring during no adverse weather conditions (**EXHIBIT 42**). Winter and fall were the highest seasons for crashes at around 63 percent combined (**EXHIBIT 44**). 61 percent of crashes occurring in the daylight (**EXHIBIT 45**).

#### Exhibit 38 – Crash Location Breakdown

Crash Location	Number of Crashes	Percentage
Mid-segment	232	80%
Intersection (Four-way, Multi-Leg, T, Y)	56	19%
Other	3	1%
Total	291	100%

### Exhibit 39 – Crash Type Breakdown

Type of Crash	Number of Crashes	Percentage
Hit fixed object	117	40%
Angle	59	20%
Rear-end	41	14%
Other or unknown	37	13%
Non-Collision	16	5%
Head-on	10	3%
Sideswipe (same dir)	4	1%
Sideswipe (opp dir)	4	1%
Hit pedestrian	3	1%
Total	291	100%

### Exhibit 40 – Crash Severity Breakdown

Crash Severity	Number of Crashes	Percentage
Not injured	154	53%
Minor Injury	53	18%
Possible Injury	46	16%
Unknown injury	15	5%
Serious Injury	14	5%
Unknown if injured	5	2%
Fatal Injury	4	1%
Total	291	100%

# Exhibit 41 – Crash Time of Day Breakdown

Crash Time	Number of Crashes	Percentage
Overnight	119	41%
Mid-Day	71	24%
PM Peak	59	20%
AM Peak	42	14%
Total	291	100%

## Exhibit 42 – Crash Weather Condition Breakdown

Weather Condition	Number of Crashes	Percentage
No adverse conditions	208	71%
Snow	37	13%
Rain	35	12%
Fog	6	2%
Sleet (hail)	2	1%
Unknown	2	1%
Other	1	0%
Rain and fog	0	0%
Sleet and fog	0	0%
Total	291	100%

## Exhibit 43 – Crash Seasonality Breakdown

Season	Number of Crashes	Percentage
Fall	83	29%
Winter	74	25%
Summer	69	24%
Spring	65	22%
Total	291	100%

## Exhibit 44 – Crash Illumination Type Breakdown

Illumination Condition	Number of Crashes	Percentage
Daylight	160	55%
Dark - no street lights	102	35%
Dark - street lights	18	6%
Dawn	7	2%
Dusk	2	1%
Dark - unknown	1	0%
Other	1	0%
Total	291	100%

### Crash Rate Comparison

An annualized crash rate for each segment was calculated for the five-year period for comparison to the Pennsylvania statewide average crash rate. The crash data was converted to an annual crashes per 100 million vehicle miles traveled by segment for comparison to the most recent available crash information from PennDOT, *2017 Pennsylvania Crash Facts and Statistics*. The crash rate was calculated by dividing the annual crash frequency by the current average annual daily traffic and segment distance found in PennDOT's Roadway Inventory Management System (RIMS) data. For comparison, Pennsylvania's 2017 overall statewide crash rate was 126.8 crashes per hundred million vehicle-miles of travel; the 2017 statewide fatality rate was 1.12 fatalities per hundred million vehicle-miles of travel.

The corridor had higher than statewide average rates of fatalities on three segments – in the vicinity between Kittanning and Goheenville and near Hawthorn (**EXHIBIT 45**). There were four fatal crashes reported in the period from 2013-2017. Of those, three were head-on collisions, and one was a hit fixed object collision. All occurred during dry roadway conditions, 3 were in daylight. One included a heavy vehicle. Three of the crashes were in 2015, and one was in 2013. There was no pattern in the time of day or location.

The other higher-than-statewide-average crash frequency on the corridor is hit fixed object collisions. There are two major segments for high Hit Fixed Object type crashes, between Goheenville and Distant, and between Summerville and Brookville (EXHIBIT 46). Geometric constraints may play a factor in these types of collisions.

Of the 291 crashes, 153 closed a lane of traffic (53%) for some period of time. Of those, 34 (12%) were reported as requiring a traffic detour. On average, each of the detours were in place for three hours.

There were three pedestrian-involved crashes, two of which occurred in downtown New Bethlehem and one on a segment of Route 28 near Shannondale Road where there are no pedestrian facilities (EXHIBIT 50). There were four crashes involving school buses, one including a loaded school bus in the AM peak hour with three injuries and 34 people involved. Two of the school bus collisions were rear end accidents, both of which occurred around the curve north of Summerville between Coder Road and Seldom Seen Road, including the one with the loaded school bus (EXHIBIT 51). Limited sight distance and speeds seem to be contributing factors in this area.

The outreach to project stakeholders and the public identified key segments and intersections as potential safety concerns. The crash patterns and history at these locations were further analyzed to determine if a correctable pattern of collisions could be identified. The crash patterns were analyzed in the following insets:

### EXHIBIT 47 shows:

- Mayport Road SR 536 At this location, there were two angle and one hit fixed object crash in the five year period.
- Sloan Hill Road / Mechling Road At this location, there was one hit fixed object, one angle, and one head on collision. This inset also shows the Lower Hayes Road area locally known as the Hayes Dip. There were no crashes reported at this location in the five-year period.
- SR 85 At this location, there were two rear end collisions, two hit fixed object, and two angle collisions. Rear end and angle collisions are common at signalized intersections.

### EXHIBIT 48 shows:

- 15 mph curve leading into South Bethlehem at this location, there were two hit fixed object crashes.
- 45mph curve between New Bethlehem and Hawthorn at this location, there was one hit fixed object crash. There is a cluster of crashes at the location of the Redbank Valley Trail crossing just to the south of this curve. Though there are no reported pedestrian hits. It is unclear from the data whether these were near-misses with bicyclists and pedestrians, or if these were run-off-the-road crashes due to the geometry of the roadway.
- Distant at this location, there was only one hit fixed object crash.

EXHIBIT 49 shows:

- South Main Street at this location, there were no crashes.
- Broad at Wood Street and greater New Bethlehem in this area, there are few crashes. There were two
  pedestrian-involved accidents downtown.
- SR 1035 (Oscar Road) at this location, there are a few hit fixed object crashes nearby and one rear end on SR 28.

## PennDOT Safety Screening

SPC provided a PennDOT rates were compared. PennDOT conducts a statewide inventory of observed crashes versus predicted crashes based on roadway geometry and the Highway Safety Manual. Through this process, PennDOT identifies roadway segments with observed crashes greater than the predicted amount of crashes. These are identified as areas with excess crashes. **EXHIBIT 52** shows segments along the Route 28 corridor that have been identified as areas of potential excess crashes. This identification may provide insight on locations where crashes are occurring more frequently than predicted, thus enabling engineers to identify correctable design features.

### Safety Summary

The project-specific crash history analysis comparison against the statewide average rate coupled with PennDOT's predictive safety screening processes help the project team to identify areas with correctable safety features. The statistical patterns generally support concern areas that were identified by the steering committee, public, and stakeholders. In most cases, geometric constraints including horizontal and vertical curvature and poor sight distance may contribute to the high Hit Fixed Object crash type found on the winding curves of the corridor. The safety information is accounted for in the evaluation matrix and used to develop the purpose and need for certain improvement concepts.



Exhibit 45 – Crash History Comparison (Fatalities)



Exhibit 46 – Crash History Comparison (Hit Fixed Object)


Exhibit 47 - Crash History Collision Type Analysis (Insets 1)



Exhibit 48 - Crash History Collision Type Analysis (Insets 2)



Exhibit 49 - Crash History Collision Type Analysis (Insets 3)



Exhibit 50 – Crashes Involving a Pedestrian



Exhibit 51 – Crashes Involving a School Bus



Exhibit 52 – PennDOT Safety Screening Segments

### **Multimodal Facilities**

While the Route 28 corridor today primarily serves passenger car and commercial freight traffic, the corridor also serves pockets of multimodal activity surrounding communities and areas like Distant, South Bethlehem, New Bethlehem, Redbank Valley High School, the Redbank Valley Trail, and Hawthorn. This section describes the land use context and multimodal facilities in each of these areas.

#### Distant

Distant is a primarily residential community with homes with close setbacks and driveways directly accessing Route 28. There are also agricultural uses nearby including Bostonia Farms. The speed limit in Distant is reduced from 55 mph coming up Hogback Hill to 40 mph through town. Distant is home to pedestriangenerating stores such as Sweet Delights ice cream and a Dollar General which was built in recent years. There is approximately 1000 feet of sidewalk on the north side of Route 28 from the SR 1004 intersection to a residential endpoint approximately 200 feet west of Sweet Delights on the opposite side of the roadway. The



Dollar General is approximately 1000 feet further east. There are no marked crosswalks or ADA-compliant curb ramps in this area. The sidewalk is narrow but in overall good condition without significant heaving, cracking, or overgrowth. A general inventory of Distant's multimodal facilities and pedestrian generators is shown in **EXHIBIT 54**.

#### South Bethlehem

Rounding the 15mph curve going northbound on Route 28 entering South Bethlehem, sidewalks begin and are located on both sides of the roadway through a traditional residential street grid. Many of the sidewalks and curb ramps are narrow, heaved due to tree roots, overgrown with grass, cracked, and have no curb ramps. In one instance, there is a step at the ramp. There are no marked crosswalks or pedestrian crossing signs in this area. West of the curve, there is a pedestrian bridge over the Redbank Creek which provides an official access point to the Redbank Valley Trail. This access is not signed from the roadway or connected to the community by sidewalk. At the intersection with SR 839 / Putneyville Road, there are three curb ramps with detectable warning surfaces. A general inventory of South Bethlehem's multimodal facilities and pedestrian generators is shown in **EXHIBIT 55**.

#### New Bethlehem

The bridge over Redbank Creek crossing into New Bethlehem from South Bethlehem has sidewalks and curb ramps on both sides. In downtown New Bethlehem, there is a walkable street grid with sidewalks on both sides of the street, recently updated curb ramps with detectable warning surfaces, mid-block pedestrian crossings, and parking on both sides of the street. The speed limit in this segment is reduced to 25 mph. Sidewalk on the north side of the roadway ends around Keck Avenue near the Smucker's facility, but continues on the south side of the corridor toward the Library and mini-mall. A general inventory of New Bethlehem's multimodal facilities and pedestrian generators is shown in **EXHIBIT 56**.



#### Library and Redbank Valley High School

Heading north on Route 28, the speed limit is 35mph towards the plaza, which has a Riverside grocery store, Burger King, a plaza with restaurants, and the New Bethlehem Public Library. The sidewalk continues on to the Redbank Valley High School football field and main building. Across the street from the high school's main entrance is a cluster of small businesses including a chiropractor and a Subway restaurant. There is one marked pedestrian crossing across Route 28 near the main entrance, and signs for "no parking". Parking in the business lots around dismissal time is a problem for these businesses. Student dismissal was a concern for stakeholders, as large numbers of students cross to be picked up, and walkers cross the street to use the rail trail which leads back to their homes in the heart of downtown New Bethlehem. The sidewalk ends at the edge of the Redbank Valley High School property approximately 900 feet east of the high school crosswalk. A general inventory of this area's



multimodal facilities and pedestrian generators is shown in **EXHIBIT 57**.



#### Redbank Valley Trail Crossing

Heading north away from the High School, the speed limit picks up again to 45 mph near M&S Meats. The building density in this area decreases and the roadway curvature resumes. Approximately 0.75 miles east of the last sidewalk, the Redbank Valley Trail crosses the Route 28 corridor at an angle between two horizontal curves. There is signage for trail ahead and what remains of a marked crossing. Stakeholder interviews indicated that the trail is under Public Utility Commission (PUC) jurisdiction, and that the PUC responded to complaints about the location of the crossing by removing the crosswalk striping. An aerial view of the trail crossing location at Route 28 is shown in **EXHIBIT 58**.

#### Hawthorn

In Hawthorn, approximately 0.5 mi of sidewalk network is present on the northern side of Route 28 from Yost to E 1st Street. The Redbank Valley Trail runs is visible from Route 28 and runs parallel to the roadway in this area at approximately 15 to 50 feet away, but there are no marked crossings across Route 28. This area was reported as a hot spot for canoe and kayak activity in the summer months due to the accessibility of the Redbank Creek in the area. Hawthorn is also home to Redbank Valley Municipal Park, where the Clarion County Fair is held each year, and also has camp sites, shelters, and RV hookups. North of this area, Route 28 and the Redbank Valley Trail diverge as the trail follows the river. Fishbasket Indian Town historical marker in this area depicts where Native Americans settled on the river. A general inventory of Hawthorn's multimodal facilities and pedestrian generators is shown in **EXHIBIT 59**.

The crash analysis revealed four school bus-involved crashes, three pedestrian-involved crashes, and no bicycle-involved crashes. Two of the pedestrian-involved crashes were in downtown New Bethlehem at midblock locations.



Another mode that is prevalent on the corridor are ATVs.

Popular ATV trails cross the corridor and frequent poker runs are a large regional tourism draw.



Exhibit 53 – Redbank Valley Trail System













Exhibit 57 – Multimodal Facilities (New Bethlehem Plaza and High School Area)



ossina 0.03 0.06 0.12 0.18 0.24 Miles Route 28 Kittanning to I-80 Regional Corridor Planning Study Multimodal Facilities (Redbank Valley Trail Crossing of Route 28) Legend RORRIDOR STUDY Trail Bridges County Boundary Trailheads \*\* Municipal Boundary

Redbank Valley Trail

State Routes

Exhibit 58 - Multimodal Facilities (Redbank Valley Trail Crossing of Route 28)

FROM HITTANNING TO 1-80

#### Exhibit 59 - Multimodal Facilities (Hawthorn)



# **Geometric Considerations**

#### Design Criteria

The RT 28 Corridor has a functional classification of Regional Arterial. The Area System designation is Rural. There are five speed limit changes noted through the study area; 25 MPH, 35 MPH, 40 MPH, 45 MPH, and 55 MPH. Design Criteria charts considering new construction were developed the corridor following guidance found in PennDOT Publication 13M Design Manual Part 2 Highway Design. The design criteria data was used as a basis for comparison to the existing Route 28 Study Corridor roadway geometry and widths. These tables and related charts can be found in **APPENDIX C**.

#### **Typical Sections**

The typical section is consistent throughout the corridor. In general, the lane width is about 11' but can vary between 10' to 12' in width. The shoulders vary between 3' to 9' in width though the corridor. Most of the shoulders are 6' in width or less and only in a few locations near major intersections do they get wider.

#### Horizontal and Vertical Geometry

Existing horizontal radii through the corridor were weighted against the current design criteria. Speeds up to 40 MPH were limited to a maximum super elevation rate of 6%. For the higher speed limits 45 MPH & 55 MPH a slightly higher maximum super elevation rate of 8% is permitted with shoulder rounding. Based on these values the minimum design horizontal radii are shown in **EXHIBIT 60**. There are currently 18 notable areas with horizontal radii less than that current recommended design values (**EXHIBIT 61** and **EXHIBIT 62**).

Speed	Minimum Horizontal Radius (ft)
25 MPH	144
35 MPH	340
40 MPH	485
45 MPH	587
55 MPH	960

#### Exhibit 60 – Design Chart Horizontal Radii

Exhibit 61 – Areas with Horizontal Radii Less Than Current Recommended Design Value

ID	Existing Radius (ft)	Speed	Min Radius (ft) For Speed	Location or Nearest Cross Street	
1	700	55 MPH	> 960	Jaraly Lane	
2	600	55 MPH	> 960	Iron Bridge Road / Lower Hayes Road	
3	903	55 MPH	> 960	Mechling Road	
4	600	55 MPH	> 960	SR 1035 (Oscar Road)	
5	600	55 MPH	> 960	W. Caldwell Road/ Kuhns Road	
6	650	55 MPH	> 960	Calhoun School Road	
7	450	55 MPH	> 960	T602 (Tipple Road)	
8	500	55 MPH	> 960	Wadding Road	
9	45	25 MPH	> 144	SR 1004 (Madison Road) / Kohlersburg Road	
10	600	55 MPH	> 960	Golf Link Road	
11	250	35 MPH	> 340	South Street	
12	75	35 MPH	> 340	South New Bethlehem; N Main/ W Broad	
13	350	45 MPH	> 587	Red Bank Valley Trail Crossing	
14	450	45 MPH	> 587	TR921	
15	700	55 MPH	> 960	Sandy Flat Road	
16	780	55 MPH	> 960	Moore Road	
17	900	55 MPH	> 960	Seneca Trail / Seldom Seen Road	
18	80	35 MPH	> 340	US 322	



Exhibit 62 – Areas of Horizontal Deficiency

Existing vertical grades vary throughout the corridor. Many roadway sections have grades exceeding the desired current design maximum vertical grades of 5% (55 MPH) or 6% (up to 45 MPH). Excessive vertical grades not only make maintaining speeds difficult for larger truck traffic but also can limit sight distance for passing or entering roadways at intersections. In examining the corridor there are 10 notable areas with vertical grades exceeding the current maximum design grade (EXHIBIT 63 and EXHIBIT 64).

ID	Existing Grade (%)	Speed	Max Grade (%) For Speed	Location or Nearest Cross Street
1	7.6-8.4	55 MPH	5	Jaraly Lane
2	7.7-9.0	55 MPH	5	Iron Bridge Road
3	8.9	55 MPH	5	SR 1035 (Oscar Road)
4	8.8	55 MPH	5	SR 1018
5	7.3-8.5	55 MPH	5	SR 1027
6	7.1-9.2	55 MPH	5	T602 (Tipple Road)
7	6.9-8.8	40 MPH	6	Near Distant, PA
8	6.5-7.6	55 MPH	5	Golf Link Road
9	6.8	55 MPH	5	SR 0536 (Mayport Road)

#### Exhibit 63 – Area with Vertical Grades Exceeding Maximum Design Grade

Exhibit 64 – Vertical Deficiency



# **Community Outreach**

Public and stakeholder outreach is a critical component of understanding the local perspective of needs and opportunities along the Route 28 corridor.

#### Stakeholder Outreach

The Steering Committee identified key stakeholders including county commissioners, municipal leaders, business owners, freight haulers, school district staff, emergency service providers, and state police. Stakeholder meetings were held on February 26, 2020 in three locations to get a broad geographic spread of comments, and for ease of attendance. The morning meeting was held at the Jefferson County Conservation District office in Brookville, the afternoon meeting at the Redbank Valley Public Library in New Bethlehem, and the evening meeting at the Belmont Complex in Kittanning. Attendee list and meeting minutes can be found in **APPENDIX D**. Areas of concern identified through the stakeholder interviews were summarized into 24 unique locations and mapped in



#### **EXHIBIT** 65.

#### Public Survey

In order to collect broad public input on the current conditions of the Route 28 Corridor from Kittanning to I-80, the study team utilized an online WikiMap survey. The survey was available at <u>https://wikimapping.com/Route-28-Corridor-Study-Kittanning-to-</u> <u>I-80.html</u> from Friday, February 7 through Friday, March 6, 2020. The Steering Committee member organizations promoted the survey through a press release, emails, and social media. Direct links to the mapping survey were also available on the study website (www.Route28CorridorStudy.com).

The interactive map allowed users to place points on a map of the corridor to identify areas of concern or opportunities for improvement related to vehicular, freight, bicycle, and pedestrian traffic. Each mode included targeted survey questions to collect



specific details about the concern or opportunity. A copy of all survey questions is included in APPENDIX E.

During the course of the survey period, 305 total points were placed by 151 unique users. A majority (269) of points were related to vehicular traffic. Nineteen (19) were related to freight; ten (10) related to pedestrians; and seven (7) related to bicycles. There were 730 log-ins to the WikiMap site which includes visitors who entered the site multiple times and those who entered the site but did not complete the surveys.

Areas of concern were summarized into 31 unique locations and mapped in **EXHIBIT 66**. The survey points revealed common areas of concern, some of which were corridor-wide. In each survey by travel mode, the public was prompted to select from several options for "What about this location causes you concern?"

**EXHIBIT 67** displays the frequency of concerns for each mode. While each mode varied slightly in the options, the most common concerns were roadway safety; vehicle speeds, slow moving vehicles, intersection sight distance, and visibility of pedestrians and bicycles on the roadway.

The concerns highlighted by the Key Stakeholder interviews and the public survey comments aligned with the goals set out by the Study Team and Steering Committee early in the study process. Concerns and comments focused on the safety of the corridor, citing intersections with poor sight distance and speed differentials; the importance of ensuring connectivity of the corridor with other destinations and regions; and the improvement of operations by reducing congestion, especially when the corridor is used as a detour route. Public input was also vital to give local perspective and insight into corridor use related to special events which the study team cannot gather in other ways.

Both the stakeholders and general public identified specific concern locations which often overlapped with each other and with locations identified by other study analysis. The concerns and comments from the stakeholders and the general public were compiled with data and analysis of different aspects of the corridor and contributed to the identification of study concern areas which will be further studied during the next phases of the study.



Exhibit 65 – Stakeholder Concern Locations



Exhibit 66 – Public Survey Concern Locations

Exhibit 67 – Summary of Public Survey Concern by Mode



**Pedestrian Concerns** 

25 selections





## **Field Observations**

#### **Field View**

Field observations were conducted on January 13<sup>th</sup>, 2020 to gather photographs, observations, and key measurements of current corridor conditions. Refer to **APPENDIX F** for detailed notes and images. The examined areas were identified by the Steering Committee or through desktop research prior to field work. In general, many of these locations identified by the Steering Committee have limited sight distance due to the horizontal and vertical curvature of the roadway. There are also locations of tight geometry that are difficult for large vehicles to navigate, with evidence of overtracking and sign hits throughout the corridor. Speed differentials were noticeable, with a spectrum ranging from speeding in excess of the 55mph posted speed limit, aggressive passing behavior, while other vehicles were traveling 10-15mph below the speed limit.

**EXHIBIT 68** shows the locations of observations, which included:

- Redbank Valley Trail
- Downtown New Bethlehem
- 15mph Curve in South Bethlehem
- Distant
- Signage
- Trucks and freight
- Retroreflectivity
- Speeds
- Sight Distance and Geometry at:
  - o Sloan Hill Road
  - o SR 1035 (Oscar Road)
  - o SR 1004 (Kohlersburg/Madison Road)
  - SR 1025 (Putneyville Road)
  - SR 0536 (Mayport Road)
  - o South Main Street
  - o SR 1028 (Anderson Creek Road)
  - Poverty Hill Road
  - o Toadtown Road/Anderson Road/Creek Street
- SR 28 guiderail erosion at various locations









322 25 BROOKVILLE 23 24 SUMMERVILLE 3 Jefferson County Clarion County 222 66 NEW-BETHLEHEN 20 HAWTHORN 19 13 16 18 1112 DISTANT (1030 GOHEENVILLE 16 17 15 14 (101) 422 KITTANNING 0 2 6 8 10 1 4 Miles Route 28 Kittanning to I-80 Regional Corridor Planning Study **Field Observation Locations** Legend County Boundary Observation K Municipal Boundary Route 28 Study Corridor CORRIDOR STUDY State Routes FROM HITTANNING TO 1-80

Exhibit 68 – Field Observation Locations

## Conclusion

This Existing Conditions Report is a culmination of data research including previous studies, field observations, surveys of stakeholders and public input. The corridor geometry was examined to compare the existing conditions against current roadway design criteria standards. Traffic operations were observed and modeled through the project area to identify any areas of substandard traffic flow. All collected data was weighed equally and utilized to identify specific areas of concern throughout the corridor.

These areas were compiled into a single list and assigned a priority based on the number of categories where the location was found. The areas that received the highest priority will be further evaluated in the future conditions portion of this study.

The study team will develop conceptual improvements to address the safety, geometric and operational concerns at these locations. Conceptual improvements will be organized into short-, medium- and long-term improvements which can be programmed and implemented by the appropriate agency as resources and funding allow.

# APPENDIX A Cost Estimate

	Michael Baker's 1994 Study		McCormick Taylor's 2020 Study Update	
Item	Cost/Mile (1994)	35 Miles (1994)	Cost/Mile (2020)	35 Miles (2020)
Clearing and Grubbing	\$150,000	\$5,250,000	\$150,000 <sub>1a</sub>	\$5,250,000
Roadway Excavation	\$3,000,000	\$105,000,000	\$3,567,000 <sub>2a</sub>	\$124,845,000
Pavement, Shoulders, Curbs	\$3,200,000	\$112,000,000	\$4,460,000 <sub>3a</sub>	\$156,100,000
Drainage	\$900,000	\$31,500,000	\$1,200,000 <sub>4a</sub>	\$42,000,000
Guiderail and Barrier	\$70,000	\$2,450,000	\$132,000 <sub>5a</sub>	\$4,620,000
Right-of-Way Fence	\$110,000	\$3,850,000	\$158,400 <sub>6a</sub>	\$5,544,000
Landscaping	\$130,000	\$4,550,000	\$217,545 <sub>7a</sub>	\$7,614,075
Temporary Traffic Control	\$210,000	\$7,350,000	\$351,418 <sub>8a</sub>	\$12,299,630
Utility Relocations	\$200,000	\$7,000,000	\$334,684 <sub>9a</sub>	\$11,713,940
Bridges, Box and Arch Culverts	\$3,900,000	\$136,500,000	\$6,526,331 <sub>10a</sub>	\$228,421,585
Signalization and Signing	\$30,000	\$1,050,000	\$50,203 <sub>11a</sub>	\$1,757,105
Pavement Markings and Delineators	\$20,000	\$700,000	\$33,469 <sub>12a</sub>	\$1,171,415
Erosion and Sedimentation Control	\$250,000	\$8,750,000	\$418,355 <sub>13a</sub>	\$14,642,425
Miscellaneous	\$400,000	\$14,000,000	\$669,368 14a	\$23,427,880
Mobilization/Field Office	\$450,000	\$15,750,000	\$753,039 <sub>15a</sub>	\$26,356,365
Stormwater Management	-	-	\$418,355 <sub>16a</sub>	\$14,642,425
Subtotal		\$455,700,000		\$680,405,845
Design Engineering (10%)		\$45,570,000		\$68,040,585 <sub>17a</sub>
Construction Engineering (5%)		\$22,785,000	(10%)	\$68,040,585 <sub>18a</sub>
Subtotal		\$524,055,000		\$816,487,014
Right-of-Way		\$26,202,750		\$40,824,351 <sub>19a</sub>
TOTAL		\$550,257,750		\$857,311,365

1a. Assume same lump sum cost per mile from previous Baker Study

\$150,000 per mile x 35 miles = \$5,250,000

2a. \$240 per CY

Assume added pavement widening of 38 ft (2 x 11ft lanes + 2 x 8ft shoulders = 38 ft) Assume pavement depth of 2ft Assume excavation cost will also include potential for rock excavation, any geotechnical treatments or shoring as needed

\$240 per cy x 1 cy / 27 cf x 38 ft x 2 ft x 5280 ft / mile = \$3,566,933.33 ~ use \$3,567,000 per mile

\$3,567,000 per mile x 35 miles = \$124,845,000

#### 3a. \$200 per SY

Assume pavement will include all paving materials, subbase, underdrain, curb or barrier if needed Assume added pavement width of 38 ft ( $2 \times 11$  ft lanes +  $2 \times 8$  ft shoulders = 38 ft)

\$200 x 1sy / 9 ft x 38 ft x 5280 ft / mile = \$4,458,666.66 ~ use \$4,460,000 per mile

\$4,460,000 per mile x 35 miles = \$156,100,000

4a. \$ 100 per LF of pipe on each side of the road, 1 inlet every 150 lf on each side of road

5280 / 150 = 35.2 inlets per mile ~ use 36 inlets each side x 2 = 72 inlets x \$2000/ inlet = \$144,000

\$100 / If x 2 sides x 5280 ft = \$1,056,000

\$ 1,056,000 + \$144,000 = \$1,200,000 cost per mile x 35 miles = \$42,000,000

5a. \$25 per LF\$25 x 5280 ft / mile = \$132,000 x 35 miles = \$4,620,000

6a. \$30 per LF \$30 x 5280 lf / mile = \$158,400 x 35 miles = \$5,544,000

- 7a. to 15a. Escalation of cost at a rate of 2% per year for 26 years.
- 16a. Used same amount as Erosion and Sedimentation Control.
- 17a. 10% of first subtotal construction costs
- 18a. 10% of first subtotal construction costs
- 19a. 5% of second subtotal construction costs

# APPENDIX B Highway Capacity Analysis




# HCM 6th Signalized Intersection Summary 1: SR 28 & SR 85

	≯	→	$\mathbf{r}$	4	+	•	•	Ť	۲	1	ŧ	~
Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations	۲	4Î		ň	eî 🕺		٦	•	1	ľ	el el	
Traffic Volume (veh/h)	28	41	10	205	87	16	7	176	159	29	303	71
Future Volume (veh/h)	28	41	10	205	87	16	7	176	159	29	303	71
Initial Q (Qb), veh	0	0	0	0	0	0	0	0	0	0	0	0
Ped-Bike Adj(A_pbT)	1.00		1.00	1.00		1.00	1.00		1.00	1.00		1.00
Parking Bus, Adj	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
Work Zone On Approach		No			No			No			No	
Adj Sat Flow, veh/h/ln	1632	1593	1593	1529	1555	1555	1672	1672	1646	1247	1299	1299
Adj Flow Rate, veh/h	34	49	0	247	105	0	8	212	0	35	365	0
Peak Hour Factor	0.83	0.83	0.83	0.83	0.83	0.83	0.83	0.83	0.83	0.83	0.83	0.83
Percent Heavy Veh, %	4	7	7	9	7	7	14	14	16	17	13	13
Cap, veh/h	42	90		276	337		6	622		33	492	
Arrive On Green	0.03	0.06	0.00	0.19	0.22	0.00	0.00	0.37	0.00	0.03	0.38	0.00
Sat Flow, veh/h	1554	1593	0	1456	1555	0	1593	1672	1395	1188	1299	0
Grp Volume(v), veh/h	34	49	0	247	105	0	8	212	0	35	365	0
Grp Sat Flow(s),veh/h/ln	1554	1593	0	1456	1555	0	1593	1672	1395	1188	1299	0
Q Serve(g_s), s	1.7	2.3	0.0	12.9	4.4	0.0	0.3	7.1	0.0	2.2	19.0	0.0
Cycle Q Clear(g_c), s	1.7	2.3	0.0	12.9	4.4	0.0	0.3	7.1	0.0	2.2	19.0	0.0
Prop In Lane	1.00		0.00	1.00		0.00	1.00		1.00	1.00		0.00
Lane Grp Cap(c), veh/h	42	90		276	337		6	622		33	492	
V/C Ratio(X)	0.81	0.54		0.89	0.31		1.32	0.34		1.07	0.74	
Avail Cap(c_a), veh/h	418	275		395	337		273	1035		193	771	
HCM Platoon Ratio	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
Upstream Filter(I)	1.00	1.00	0.00	1.00	1.00	0.00	1.00	1.00	0.00	1.00	1.00	0.00
Uniform Delay (d), s/veh	37.8	35.9	0.0	30.9	25.7	0.0	38.9	17.7	0.0	38.0	21.0	0.0
Incr Delay (d2), s/veh	29.4	5.0	0.0	16.9	0.5	0.0	280.3	1.2	0.0	91.6	7.7	0.0
Initial Q Delay(d3),s/veh	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
%ile BackOfQ(50%),veh/In	1.0	1.0	0.0	5.5	1.6	0.0	0.6	2.6	0.0	1.4	6.1	0.0
Unsig. Movement Delay, s/veh	. = .			.= .							~~ ~	
LnGrp Delay(d),s/veh	67.3	40.9	0.0	47.8	26.3	0.0	319.2	18.8	0.0	129.6	28.7	0.0
LnGrp LOS	E	D		D	С		ŀ	В		F	С	
Approach Vol, veh/h		83	А		352	А		220	А		400	A
Approach Delay, s/veh		51.7			41.4			29.7			37.5	
Approach LOS		D			D			С			D	
Timer - Assigned Phs	1	2	3	4	5	6	7	8				
Phs Duration (G+Y+Rc), s	8.5	36.7	21.6	11.4	7.9	37.2	9.1	23.9				
Change Period (Y+Rc), s	* 5.8	7.1	6.3	6.5	7.1	7.1	6.5	6.5				
Max Green Setting (Gmax), s	* 13	48.9	21.7	14.0	13.9	46.9	21.5	14.0				
Max Q Clear Time (g_c+l1), s	4.2	9.1	14.9	4.3	2.3	21.0	3.7	6.4				
Green Ext Time (p_c), s	0.0	6.1	0.4	0.1	0.0	9.2	0.0	0.1				
Intersection Summary												
HCM 6th Ctrl Delay			38.3									
HCM 6th LOS			D									

#### Notes

\* HCM 6th computational engine requires equal clearance times for the phases crossing the barrier. Unsignalized Delay for [NBR, EBR, WBR, SBR] is excluded from calculations of the approach delay and intersection delay.

Route 28 Corridor Study 7:45 am 11/19/2019 Existing Conditions - AM Peak ANT

Intersection						
Int Delay, s/veh	3					
N /		NDT	CDT			
iviovement	NRL	INRI	SRT	SRK	SEL	SER
Lane Configurations		्स	- <b>†</b>		۰¥	
Traffic Vol, veh/h	8	143	198	0	81	19
Future Vol, veh/h	8	143	198	0	81	19
Conflicting Peds, #/hr	0	0	0	0	0	0
Sign Control	Free	Free	Free	Free	Stop	Stop
RT Channelized	-	None	-	None	-	None
Storage Length	-	-	-	-	0	-
Veh in Median Storage,	# -	0	0	-	0	-
Grade, %	-	7	-6	-	0	-
Peak Hour Factor	87	87	87	87	87	87
Heavy Vehicles, %	25	13	16	0	6	5
Mvmt Flow	9	164	228	0	93	22

Major/Minor	Major1	Ν	/lajor2	Ν	/linor2		
Conflicting Flow All	228	0	-	0	410	228	
Stage 1	-	-	-	-	228	-	
Stage 2	-	-	-	-	182	-	
Critical Hdwy	4.9	-	-	-	8.1	6.4	
Critical Hdwy Stg 1	-	-	-	-	5.46	-	
Critical Hdwy Stg 2	-	-	-	-	5.46	-	
Follow-up Hdwy	3.5	-	-	-	3	3.4	
Pot Cap-1 Maneuver	841	-	-	0	563	785	
Stage 1	-	-	-	0	932	-	
Stage 2	-	-	-	0	981	-	
Platoon blocked, %		-	-				
Mov Cap-1 Maneuver	· 841	-	-	-	556	785	
Mov Cap-2 Maneuver	· _	-	-	-	556	-	
Stage 1	-	-	-	-	921	-	
Stage 2	-	-	-	-	981	-	
Approach	NB		SB		SE		
HCM Control Delay, s	s 0.5		0		12.6		
HCM LOS					В		
Minor Lane/Major Mv	mt	NBL	NBT S	SELn1	SBT		
Capacity (veh/h)		841	-	589	-		
HCM Lane V/C Ratio		0.011	-	0.195	-		
HCM Control Delay (s	5)	9.3	0	12.6	-		
HCM Lane LOS		А	А	В	-		
HCM 95th %tile Q(vel	h)	0	-	0.7	-		

0.2					
EBL	EBR	NBL	NBT	SBT	SBR
Y			- सी	4	
8	1	1	285	232	3
8	1	1	285	232	3
0	0	0	0	0	0
Stop	Stop	Free	Free	Free	Free
-	None	-	None	-	None
0	-	-	-	-	-
# 0	-	-	0	0	-
8	-	-	-4	-2	-
91	91	91	91	91	91
13	0	0	9	13	0
9	1	1	313	255	3
	0.2 EBL ¥ 8 8 8 0 Stop - 0 # 0 # 0 8 91 13 9	0.2 EBL EBR ✓ EBR 3 8 1 8 1 8 1 0 0 5top Stop 5top Stop 0 1 0 0 1 1 0 0 1 1 1 1 1 1 1 1 1 1 1 1 1	0.2 EBL EBR NBL Y 8 1 1 8 1 1 0 0 0 Stop Stop Free - None - 0 - 8 - 10 - 9 - 9 - 9 - 9 - 9 - 9 - 9 - 9	0.2       EBR       NBL       NBT         ♥       ● <t< td=""><td>0.2         EBL       EBR       NBL       NBT       SBT         ✓       ✓       ✓       ✓       ✓         Ø       1       285       232       232         Ø       1       285       232         Ø       1       285       232         Ø       0       0       0       0         Stop       Stop       Free       Free       Free         None       -       None       -       -         Ø       -       0       0       0       0         Ø       -       -       Ø       0       0         Ø       91       91       91       91       91         Ø       1       313       255</td></t<>	0.2         EBL       EBR       NBL       NBT       SBT         ✓       ✓       ✓       ✓       ✓         Ø       1       285       232       232         Ø       1       285       232         Ø       1       285       232         Ø       0       0       0       0         Stop       Stop       Free       Free       Free         None       -       None       -       -         Ø       -       0       0       0       0         Ø       -       -       Ø       0       0         Ø       91       91       91       91       91         Ø       1       313       255

Major/Minor	Minor2	Ν	1ajor1	Maj	or2				
Conflicting Flow All	572	257	258	0	-	0			
Stage 1	257	-	-	-	-	-			
Stage 2	315	-	-	-	-	-			
Critical Hdwy	8.13	7	4.3	-	-	-			
Critical Hdwy Stg 1	7.13	-	-	-	-	-			
Critical Hdwy Stg 2	7.13	-	-	-	-	-			
Follow-up Hdwy	3	3.1	3	-	-	-			
Pot Cap-1 Maneuver	415	785	980	-	-	-			
Stage 1	801	-	-	-	-	-			
Stage 2	731	-	-	-	-	-			
Platoon blocked, %				-	-	-			
Mov Cap-1 Maneuve	r 415	785	980	-	-	-			
Mov Cap-2 Maneuve	r 415	-	-	-	-	-			
Stage 1	800	-	-	-	-	-			
Stage 2	731	-	-	-	-	-			

Approach	EB	NB	SB	
HCM Control Delay, s	13.4	0	0	
HCM LOS	В			

Minor Lane/Major Mvmt	NBL	NBT E	BLn1	SBT	SBR
Capacity (veh/h)	980	-	438	-	-
HCM Lane V/C Ratio	0.001	-	0.023	-	-
HCM Control Delay (s)	8.7	0	13.4	-	-
HCM Lane LOS	А	А	В	-	-
HCM 95th %tile Q(veh)	0	-	0.1	-	-

#### Intersection

Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations		\$		<u>ک</u>	et 👘			\$			\$	
Traffic Vol, veh/h	2	318	2	38	252	5	3	0	79	5	1	1
Future Vol, veh/h	2	318	2	38	252	5	3	0	79	5	1	1
Conflicting Peds, #/hr	0	0	0	0	0	0	0	0	0	0	0	0
Sign Control	Free	Free	Free	Free	Free	Free	Stop	Stop	Stop	Stop	Stop	Stop
RT Channelized	-	-	None	-	-	None	-	-	None	-	-	None
Storage Length	-	-	-	120	-	-	-	-	-	-	-	-
Veh in Median Storage,	# -	0	-	-	0	-	-	0	-	-	0	-
Grade, %	-	-5	-	-	3	-	-	-7	-	-	7	-
Peak Hour Factor	78	78	78	78	78	78	78	78	78	78	78	78
Heavy Vehicles, %	50	9	50	3	14	0	67	0	6	20	0	0
Mvmt Flow	3	408	3	49	323	6	4	0	101	6	1	1

Major/Minor	Major1		N	lajor2		Ν	/linor1		Ν	/linor2			
Conflicting Flow All	329	0	0	411	0	0	841	843	410	890	841	326	
Stage 1	-	-	-	-	-	-	416	416	-	424	424	-	
Stage 2	-	-	-	-	-	-	425	427	-	466	417	-	
Critical Hdwy	4.3	-	-	4.3	-	-	6.37	5.1	5.56	8.7	7.9	6.9	
Critical Hdwy Stg 1	-	-	-	-	-	-	5.37	4.1	-	7.7	6.9	-	
Critical Hdwy Stg 2	-	-	-	-	-	-	5.37	4.1	-	7.7	6.9	-	
Follow-up Hdwy	3	-	-	3	-	-	3	4	3.1	3	4	3.1	
Pot Cap-1 Maneuver	926	-	-	867	-	-	377	420	732	198	219	713	
Stage 1	-	-	-	-	-	-	763	700	-	575	501	-	
Stage 2	-	-	-	-	-	-	756	695	-	534	506	-	
Platoon blocked, %		-	-		-	-							
Mov Cap-1 Maneuver	926	-	-	867	-	-	357	394	732	163	206	713	
Mov Cap-2 Maneuver	· -	-	-	-	-	-	357	394	-	163	206	-	
Stage 1	-	-	-	-	-	-	760	697	-	573	472	-	
Stage 2	-	-	-	-	-	-	710	655	-	458	504	-	
Approach	EB			WB			NB			SB			
HCM Control Delay, s	6.1			1.2			11			24.9			
HCM LOS							В			С			

Minor Lane/Major Mvmt	NBLn1	EBL	EBT	EBR	WBL	WBT	WBR	SBLn1
Capacity (veh/h)	705	926	-	-	867	-	-	190
HCM Lane V/C Ratio	0.149	0.003	-	-	0.056	-	-	0.047
HCM Control Delay (s)	11	8.9	0	-	9.4	-	-	24.9
HCM Lane LOS	В	А	А	-	А	-	-	С
HCM 95th %tile Q(veh)	0.5	0	-	-	0.2	-	-	0.1

### HCM 6th Signalized Intersection Summary 5: SR 28 & SR 66

	۶	<b>→</b>	$\mathbf{\hat{v}}$	4	+	•	1	Ť	۲	5	ŧ	~
Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations	5	î,			4			4			\$	
Traffic Volume (veh/h)	127	223	2	1	182	85	1	2	1	146	4	86
Future Volume (veh/h)	127	223	2	1	182	85	1	2	1	146	4	86
Initial Q (Qb), veh	0	0	0	0	0	0	0	0	0	0	0	0
Ped-Bike Adj(A_pbT)	1.00		1.00	1.00		1.00	1.00		1.00	1.00		1.00
Parking Bus, Adj	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
Work Zone On Approach		No			No			No			No	
Adj Sat Flow, veh/h/ln	1418	1557	1557	1519	1519	1519	1028	1028	1028	1685	1685	1685
Adj Flow Rate, veh/h	163	286	3	1	233	109	1	3	1	187	5	110
Peak Hour Factor	0.78	0.78	0.78	0.78	0.78	0.78	0.78	0.78	0.78	0.78	0.78	0.78
Percent Heavy Veh, %	16	5	5	8	8	8	50	50	50	0	0	0
Cap, veh/h	464	803	8	69	297	139	113	194	56	334	22	141
Arrive On Green	0.12	0.52	0.50	0.28	0.30	0.28	0.27	0.29	0.29	0.27	0.29	0.27
Sat Flow, veh/h	1350	1538	16	1	979	456	106	674	195	777	78	490
Grp Volume(v), veh/h	163	0	289	343	0	0	5	0	0	302	0	0
Grp Sat Flow(s),veh/h/ln	1350	0	1554	1436	0	0	975	0	0	1345	0	0
Q Serve(g_s), s	3.9	0.0	5.8	0.0	0.0	0.0	0.0	0.0	0.0	10.3	0.0	0.0
Cycle Q Clear(g_c), s	3.9	0.0	5.8	11.8	0.0	0.0	0.2	0.0	0.0	11.1	0.0	0.0
Prop In Lane	1.00		0.01	0.00		0.32	0.20		0.20	0.62		0.36
Lane Grp Cap(c), veh/h	464	0	811	477	0	0	344	0	0	472	0	0
V/C Ratio(X)	0.35	0.00	0.36	0.72	0.00	0.00	0.01	0.00	0.00	0.64	0.00	0.00
Avail Cap(c_a), veh/h	579	0	1387	886	0	0	618	0	0	873	0	0
HCM Platoon Ratio	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
Upstream Filter(I)	1.00	0.00	1.00	1.00	0.00	0.00	1.00	0.00	0.00	1.00	0.00	0.00
Uniform Delay (d), s/veh	8.6	0.0	7.4	17.0	0.0	0.0	13.5	0.0	0.0	17.7	0.0	0.0
Incr Delay (d2), s/veh	0.5	0.0	0.3	2.0	0.0	0.0	0.0	0.0	0.0	1.4	0.0	0.0
Initial Q Delay(d3),s/veh	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
%ile BackOfQ(50%),veh/In	1.0	0.0	1.6	3.8	0.0	0.0	0.0	0.0	0.0	3.4	0.0	0.0
Unsig. Movement Delay, s/veh	~ ~											
LnGrp Delay(d),s/veh	9.0	0.0	1.1	19.1	0.0	0.0	13.5	0.0	0.0	19.1	0.0	0.0
LnGrp LOS	A	A	A	В	A	A	В	A	A	В	A	A
Approach Vol, veh/h		452			343			5			302	
Approach Delay, s/veh		8.1			19.1			13.5			19.1	
Approach LOS		A			В			В			В	
Timer - Assigned Phs	1	2		4		6		8				
Phs Duration (G+Y+Rc), s	11.5	21.0		20.2		32.5		20.2				
Change Period (Y+Rc), s	6.0	6.0		6.0		6.0		6.0				
Max Green Setting (Gmax), s	10.0	30.0		30.0		46.0		30.0				
Max Q Clear Time (g_c+I1), s	5.9	13.8		2.2		7.8		13.1				
Green Ext Time (p_c), s	0.2	1.2		0.0		1.1		1.1				
Intersection Summary												
HCM 6th Ctrl Delay			14.6									
HCM 6th LOS			В									

	1.1
Inters	section
IIII CI C	SCOUOT

Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations		÷			\$			\$			\$	
Traffic Vol, veh/h	7	241	9	6	230	1	12	2	13	4	2	8
Future Vol, veh/h	7	241	9	6	230	1	12	2	13	4	2	8
Conflicting Peds, #/hr	0	0	0	0	0	0	0	0	0	0	0	0
Sign Control F	Free	Free	Free	Free	Free	Free	Stop	Stop	Stop	Stop	Stop	Stop
RT Channelized	-	-	None									
Storage Length	-	-	-	-	-	-	-	-	-	-	-	-
Veh in Median Storage, #	ŧ -	0	-	-	0	-	-	0	-	-	0	-
Grade, %	-	1	-	-	-1	-	-	9	-	-	-3	-
Peak Hour Factor	82	82	82	82	82	82	82	82	82	82	82	82
Heavy Vehicles, %	0	12	0	0	13	0	8	0	0	0	0	13
Mvmt Flow	9	294	11	7	280	1	15	2	16	5	2	10

Major/Minor	Major1		Ν	/lajor2			Minor1		Ν	/linor2			
Conflicting Flow All	281	0	0	305	0	0	619	613	300	622	618	281	
Stage 1	-	-	-	-	-	-	318	318	-	295	295	-	
Stage 2	-	-	-	-	-	-	301	295	-	327	323	-	
Critical Hdwy	4.9	-	-	4.9	-	-	8.1	8.3	6.4	8.1	5.9	6.4	
Critical Hdwy Stg 1	-	-	-	-	-	-	7.98	7.3	-	5.5	4.9	-	
Critical Hdwy Stg 2	-	-	-	-	-	-	7.98	7.3	-	5.5	4.9	-	
Follow-up Hdwy	3.5	-	-	3.5	-	-	3	4	3.4	3	4	3.4	
Pot Cap-1 Maneuver	802	-	-	785	-	-	382	302	713	379	452	732	
Stage 1	-	-	-	-	-	-	675	561	-	862	706	-	
Stage 2	-	-	-	-	-	-	696	580	-	832	690	-	
Platoon blocked, %		-	-		-	-							
Mov Cap-1 Maneuver	802	-	-	785	-	-	368	294	713	361	441	732	
Mov Cap-2 Maneuver	-	-	-	-	-	-	368	294	-	361	441	-	
Stage 1	-	-	-	-	-	-	666	553	-	850	698	-	
Stage 2	-	-	-	-	-	-	677	574	-	799	680	-	
Approach	FB			WB			NB			SB			
HCM Control Delay s	03			0.2			13.3			12.1			
HCM LOS	0.0			0.2			13.5 R			12.1 R			
							U			U			
Minor Lane/Major Mvr	nt	NBLn1	EBL	EBT	EBR	WBL	WBT	WBR S	SBLn1				

IVITION LATE/IVIAJON IVIVITIL	NDLIII	LDL	LDI	LDK	VVDL	VVDI	VVDR -	SDLIT
Capacity (veh/h)	468	802	-	-	785	-	-	527
HCM Lane V/C Ratio	0.07	0.011	-	-	0.009	-	-	0.032
HCM Control Delay (s)	13.3	9.5	0	-	9.6	0	-	12.1
HCM Lane LOS	В	А	А	-	А	А	-	В
HCM 95th %tile Q(veh)	0.2	0	-	-	0	-	-	0.1

#### Intersection

Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations		4			4			4			4	
Traffic Vol, veh/h	3	128	26	8	111	1	29	4	23	4	6	4
Future Vol, veh/h	3	128	26	8	111	1	29	4	23	4	6	4
Conflicting Peds, #/hr	2	0	0	0	0	2	0	0	0	0	0	0
Sign Control	Free	Free	Free	Free	Free	Free	Stop	Stop	Stop	Stop	Stop	Stop
RT Channelized	-	-	None									
Storage Length	-	-	-	-	-	-	-	-	-	-	-	-
Veh in Median Storage,	# -	0	-	-	0	-	-	0	-	-	0	-
Grade, %	-	6	-	-	-2	-	-	-3	-	-	12	-
Peak Hour Factor	75	75	75	75	75	75	75	75	75	75	75	75
Heavy Vehicles, %	0	6	15	25	9	0	14	0	4	25	0	0
Mvmt Flow	4	171	35	11	148	1	39	5	31	5	8	5

		I N	/laior2			Minor1		Ν	/linor2			
151	0	0	206	0	0	374	370	189	388	387	151	
-	-	-		-	-	197	197	-	173	173	-	
-	-	-	-	-	-	177	173	-	215	214	-	
4.9	-	-	4.9	-	-	8.1	5.9	6.4	8.1	8.9	6.4	
-	-	-	-	-	-	5.64	4.9	-	8.75	7.9	-	
-	-	-	-	-	-	5.64	4.9	-	8.75	7.9	-	
3.5	-	-	3.5	-	-	3	4	3.4	3	4	3.4	
900	-	-	857	-	-	602	599	826	587	425	869	
-	-	-	-	-	-	956	766	-	846	677	-	
-	-	-	-	-	-	978	782	-	777	632	-	
	-	-		-	-							
899	-	-	857	-	-	581	587	826	552	417	868	
-	-	-	-	-	-	581	587	-	552	417	-	
-	-	-	-	-	-	951	762	-	841	667	-	
-	-	-	-	-	-	947	770	-	739	629	-	
EB			WB			NB			SB			
0.2			0.6			11.1			12			
						В			В			
	RI n1	FRI	FRT	FRP	WRI	W/RT	WRP	SRI n1				
	662	000	LDT	LDI	057	1001		50000				
0	112	0 00 4	-	-	007	-	-	0.025				
0.	. I I J 11 1	0.004	-	-	0.012	-	-	0.000				
	151 - - 4.9 - 3.5 900 - - 899 - - 899 - - - 899 - - - 899 - - - -	151       0         151       0         -       -         4.9       -         -       -         3.5       -         900       -         -       -         899       -         -       -         899       -         0.2       -         t       NBLn1         662       0.113         11.1	Iajoi I       0         151       0         -       -         -       -         4.9       -         -       -         3.5       -         900       -         -       -         900       -         -       -         899       -         -       -         899       -         -       -         0.2       -         t       NBLn1         EB       -         0.2       -         662       899         0.113       0.004         11.1       9	Indication       Investigation         151       0       0       206         -       -       -       -         4.9       -       -       -         4.9       -       -       -         -       -       -       -         3.5       -       3.5       -         900       -       857       -         -       -       -       -         900       -       857       -         -       -       -       -         899       -       -       -         -       -       -       -         B99       -       -       -         -       -       -       -         2       -       -       -         -       -       -       -         -       -       -       -         -       -       -       -         -       -       -       -         -       -       -       -         -       -       -       -         -       -       -       -         - </td <td>Itel of 1       Itel of 1         151       0       0       206       0         -       -       -       -       -         4.9       -       4.9       -       -         -       -       -       -       -         3.5       -       3.5       -       -         900       -       857       -       -         -       -       -       -       -         900       -       857       -       -         -       -       -       -       -         -       -       -       -       -         899       -       857       -       -         -       -       -       -       -         -       -       -       -       -         -       -       -       -       -         -       -       -       -       -         -       -       -       -       -         -       -       -       -       -         -       -       -       -       -         -       -       -       <td< td=""><td>Iter of the point of the</td><td>Integer 1       Integer 2       Integer 4         151       0       0       206       0       0       374         -       -       -       -       -       197         -       -       -       -       197         4.9       -       4.9       -       -       177         4.9       -       4.9       -       -       8.1         -       -       -       -       5.64         -       -       -       -       5.64         3.5       -       3.5       -       3         900       -       857       -       602         -       -       -       -       978         -       -       -       -       978         -       -       -       -       978         -       -       -       -       581         -       -       -       -       581         -       -       -       -       581         -       -       -       -       947         EB       WB       WB       NB       NB         0.2</td><td>Indicitize       Initial Product of the second state of the second</td><td>Initial of 1       Initial of 2       Initial 1       Initial 1       Initial 1         151       0       0       206       0       0       374       370       189         -       -       -       -       197       197       -         4.9       -       -       177       173       -         4.9       -       4.9       -       8.1       5.9       6.4         -       -       -       5.64       4.9       -         -       -       -       5.64       4.9       -         3.5       -       3.5       -       3       4       3.4         900       -       857       -       602       599       826         -       -       -       -       978       782       -         -       -       -       -       978       782       -         -       -       -       -       581       587       826         -       -       -       -       581       587       -         -       -       -       -       581       587       -         -</td><td>Indicitie       Indicitie       Indicitie       Indicitie         151       0       0       206       0       0       374       370       189       388         -       -       -       -       197       197       -       173         -       -       -       -       197       197       -       173         -       -       -       -       177       173       -       215         4.9       -       4.9       -       -       8.1       5.9       6.4       8.1         -       -       -       -       5.64       4.9       -       8.75         3.5       -       3.5       -       -       3       4       3.4       3         900       -       857       -       602       599       826       587         -       -       -       978       782       -       777         -       -       -       978       782       -       777         -       -       -       581       587       826       552         -       -       -       581       587       &lt;</td><td>Indicitize       Indicitize       Indicitize       Indicitize         151       0       0       206       0       0       374       370       189       388       387         -       -       -       -       197       197       -       173       173         -       -       -       -       197       197       -       173       173         -       -       -       -       197       197       -       173       173         -       -       4.9       -       -       8.1       5.9       6.4       8.1       8.9         -       -       -       -       5.64       4.9       -       8.75       7.9         3.5       -       -       3       4       3.4       3       4         900       -       857       -       602       599       826       587       425         -       -       -       978       782       -       777       632         -       -       -       978       587       826       552       417         -       -       -       581       587<td>Indicitie       Market i       Market i       Market i       Market i         151       0       0       206       0       0       374       370       189       388       387       151         -       -       -       -       -       197       197       -       173       173       -         4.9       -       4.9       -       -       8.1       5.9       6.4       8.1       8.9       6.4         -       -       -       5.64       4.9       -       8.75       7.9       -         -       -       3.5       -       -       5.64       4.9       -       8.75       7.9       -         3.5       -       3.5       -       -       3.4       3.4       3.4       3.4       3.4         900       -       857       -       602       599       826       587       425       869         -       -       -       978       782       777       632       -         -       -       -       581       587       826       552       417       868         -       -       -</td></td></td<></td>	Itel of 1       Itel of 1         151       0       0       206       0         -       -       -       -       -         4.9       -       4.9       -       -         -       -       -       -       -         3.5       -       3.5       -       -         900       -       857       -       -         -       -       -       -       -         900       -       857       -       -         -       -       -       -       -         -       -       -       -       -         899       -       857       -       -         -       -       -       -       -         -       -       -       -       -         -       -       -       -       -         -       -       -       -       -         -       -       -       -       -         -       -       -       -       -         -       -       -       -       -         -       -       - <td< td=""><td>Iter of the point of the</td><td>Integer 1       Integer 2       Integer 4         151       0       0       206       0       0       374         -       -       -       -       -       197         -       -       -       -       197         4.9       -       4.9       -       -       177         4.9       -       4.9       -       -       8.1         -       -       -       -       5.64         -       -       -       -       5.64         3.5       -       3.5       -       3         900       -       857       -       602         -       -       -       -       978         -       -       -       -       978         -       -       -       -       978         -       -       -       -       581         -       -       -       -       581         -       -       -       -       581         -       -       -       -       947         EB       WB       WB       NB       NB         0.2</td><td>Indicitize       Initial Product of the second state of the second</td><td>Initial of 1       Initial of 2       Initial 1       Initial 1       Initial 1         151       0       0       206       0       0       374       370       189         -       -       -       -       197       197       -         4.9       -       -       177       173       -         4.9       -       4.9       -       8.1       5.9       6.4         -       -       -       5.64       4.9       -         -       -       -       5.64       4.9       -         3.5       -       3.5       -       3       4       3.4         900       -       857       -       602       599       826         -       -       -       -       978       782       -         -       -       -       -       978       782       -         -       -       -       -       581       587       826         -       -       -       -       581       587       -         -       -       -       -       581       587       -         -</td><td>Indicitie       Indicitie       Indicitie       Indicitie         151       0       0       206       0       0       374       370       189       388         -       -       -       -       197       197       -       173         -       -       -       -       197       197       -       173         -       -       -       -       177       173       -       215         4.9       -       4.9       -       -       8.1       5.9       6.4       8.1         -       -       -       -       5.64       4.9       -       8.75         3.5       -       3.5       -       -       3       4       3.4       3         900       -       857       -       602       599       826       587         -       -       -       978       782       -       777         -       -       -       978       782       -       777         -       -       -       581       587       826       552         -       -       -       581       587       &lt;</td><td>Indicitize       Indicitize       Indicitize       Indicitize         151       0       0       206       0       0       374       370       189       388       387         -       -       -       -       197       197       -       173       173         -       -       -       -       197       197       -       173       173         -       -       -       -       197       197       -       173       173         -       -       4.9       -       -       8.1       5.9       6.4       8.1       8.9         -       -       -       -       5.64       4.9       -       8.75       7.9         3.5       -       -       3       4       3.4       3       4         900       -       857       -       602       599       826       587       425         -       -       -       978       782       -       777       632         -       -       -       978       587       826       552       417         -       -       -       581       587<td>Indicitie       Market i       Market i       Market i       Market i         151       0       0       206       0       0       374       370       189       388       387       151         -       -       -       -       -       197       197       -       173       173       -         4.9       -       4.9       -       -       8.1       5.9       6.4       8.1       8.9       6.4         -       -       -       5.64       4.9       -       8.75       7.9       -         -       -       3.5       -       -       5.64       4.9       -       8.75       7.9       -         3.5       -       3.5       -       -       3.4       3.4       3.4       3.4       3.4         900       -       857       -       602       599       826       587       425       869         -       -       -       978       782       777       632       -         -       -       -       581       587       826       552       417       868         -       -       -</td></td></td<>	Iter of the point of the	Integer 1       Integer 2       Integer 4         151       0       0       206       0       0       374         -       -       -       -       -       197         -       -       -       -       197         4.9       -       4.9       -       -       177         4.9       -       4.9       -       -       8.1         -       -       -       -       5.64         -       -       -       -       5.64         3.5       -       3.5       -       3         900       -       857       -       602         -       -       -       -       978         -       -       -       -       978         -       -       -       -       978         -       -       -       -       581         -       -       -       -       581         -       -       -       -       581         -       -       -       -       947         EB       WB       WB       NB       NB         0.2	Indicitize       Initial Product of the second state of the second	Initial of 1       Initial of 2       Initial 1       Initial 1       Initial 1         151       0       0       206       0       0       374       370       189         -       -       -       -       197       197       -         4.9       -       -       177       173       -         4.9       -       4.9       -       8.1       5.9       6.4         -       -       -       5.64       4.9       -         -       -       -       5.64       4.9       -         3.5       -       3.5       -       3       4       3.4         900       -       857       -       602       599       826         -       -       -       -       978       782       -         -       -       -       -       978       782       -         -       -       -       -       581       587       826         -       -       -       -       581       587       -         -       -       -       -       581       587       -         -	Indicitie       Indicitie       Indicitie       Indicitie         151       0       0       206       0       0       374       370       189       388         -       -       -       -       197       197       -       173         -       -       -       -       197       197       -       173         -       -       -       -       177       173       -       215         4.9       -       4.9       -       -       8.1       5.9       6.4       8.1         -       -       -       -       5.64       4.9       -       8.75         3.5       -       3.5       -       -       3       4       3.4       3         900       -       857       -       602       599       826       587         -       -       -       978       782       -       777         -       -       -       978       782       -       777         -       -       -       581       587       826       552         -       -       -       581       587       <	Indicitize       Indicitize       Indicitize       Indicitize         151       0       0       206       0       0       374       370       189       388       387         -       -       -       -       197       197       -       173       173         -       -       -       -       197       197       -       173       173         -       -       -       -       197       197       -       173       173         -       -       4.9       -       -       8.1       5.9       6.4       8.1       8.9         -       -       -       -       5.64       4.9       -       8.75       7.9         3.5       -       -       3       4       3.4       3       4         900       -       857       -       602       599       826       587       425         -       -       -       978       782       -       777       632         -       -       -       978       587       826       552       417         -       -       -       581       587 <td>Indicitie       Market i       Market i       Market i       Market i         151       0       0       206       0       0       374       370       189       388       387       151         -       -       -       -       -       197       197       -       173       173       -         4.9       -       4.9       -       -       8.1       5.9       6.4       8.1       8.9       6.4         -       -       -       5.64       4.9       -       8.75       7.9       -         -       -       3.5       -       -       5.64       4.9       -       8.75       7.9       -         3.5       -       3.5       -       -       3.4       3.4       3.4       3.4       3.4         900       -       857       -       602       599       826       587       425       869         -       -       -       978       782       777       632       -         -       -       -       581       587       826       552       417       868         -       -       -</td>	Indicitie       Market i       Market i       Market i       Market i         151       0       0       206       0       0       374       370       189       388       387       151         -       -       -       -       -       197       197       -       173       173       -         4.9       -       4.9       -       -       8.1       5.9       6.4       8.1       8.9       6.4         -       -       -       5.64       4.9       -       8.75       7.9       -         -       -       3.5       -       -       5.64       4.9       -       8.75       7.9       -         3.5       -       3.5       -       -       3.4       3.4       3.4       3.4       3.4         900       -       857       -       602       599       826       587       425       869         -       -       -       978       782       777       632       -         -       -       -       581       587       826       552       417       868         -       -       -

Intersection													
Int Delay, s/veh	2.3												
Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR	
Lane Configurations		\$			\$			\$			\$		
Traffic Vol, veh/h	6	141	7	13	68	7	5	5	36	1	5	1	
Future Vol, veh/h	6	141	7	13	68	7	5	5	36	1	5	1	
Conflicting Peds, #/hr	0	0	0	0	0	0	0	0	0	0	0	0	
Sign Control	Free	Free	Free	Free	Free	Free	Stop	Stop	Stop	Stop	Stop	Stop	
RT Channelized	-	-	None										
Storage Length	-	-	-	-	-	-	-	-	-	-	-	-	
Veh in Median Storage,	# -	0	-	-	0	-	-	0	-	-	0	-	
Grade, %	-	0	-	-	0	-	-	2	-	-	-2	-	
Peak Hour Factor	91	91	91	91	91	91	91	91	91	91	91	91	
Heavy Vehicles, %	0	8	0	31	13	0	0	0	6	0	0	0	
Mvmt Flow	7	155	8	14	75	8	5	5	40	1	5	1	

Major/Minor N	Major1		Ν	Major2			Vinor1		1	Minor2			
Conflicting Flow All	83	0	0	163	0	0	283	284	159	303	284	79	
Stage 1	-	-	-	-	-	-	173	173	-	107	107	-	
Stage 2	-	-	-	-	-	-	110	111	-	196	177	-	
Critical Hdwy	4.9	-	-	4.9	-	-	8.1	6.9	6.46	8.1	6.1	6.4	
Critical Hdwy Stg 1	-	-	-	-	-	-	6.5	5.9	-	5.7	5.1	-	
Critical Hdwy Stg 2	-	-	-	-	-	-	6.5	5.9	-	5.7	5.1	-	
Follow-up Hdwy	3.5	-	-	3.5	-	-	3	4	3.4	3	4	3.4	
Pot Cap-1 Maneuver	956	-	-	891	-	-	713	609	857	687	649	955	
Stage 1	-	-	-	-	-	-	943	745	-	1059	820	-	
Stage 2	-	-	-	-	-	-	1030	798	-	954	772	-	
Platoon blocked, %		-	-		-	-							
Mov Cap-1 Maneuver	956	-	-	891	-	-	694	594	857	639	633	955	
Mov Cap-2 Maneuver	-	-	-	-	-	-	694	594	-	639	633	-	
Stage 1	-	-	-	-	-	-	935	739	-	1051	807	-	
Stage 2	-	-	-	-	-	-	1005	785	-	896	766	-	
Approach	ED			\//D			ND			CD			
Approach				1.2						10 5			
HCM Control Delay, S	0.3			1.3			9.8			10.5			
HCM LUS							A			В			
Minor Lane/Major Mvm	nt	NBLn1	EBL	EBT	EBR	WBL	WBT	WBR	SBLn1				
Capacity (veh/h)		798	956	-	-	891	-	-	666				
HCM Lane V/C Ratio		0.063	0.007	-	-	0.016	-	-	0.012				
HCM Control Delay (s)		9.8	8.8	0	-	9.1	0	-	10.5				

HCM Control Delay (s) 9.8 1.1 0.5 HCM Lane LOS А А А А А В --HCM 95th %tile Q(veh) 0.2 0 0 0 ----

#### Intersection

Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations		÷			÷			÷			÷	
Traffic Vol, veh/h	2	1	1	20	1	24	1	138	47	40	86	1
Future Vol, veh/h	2	1	1	20	1	24	1	138	47	40	86	1
Conflicting Peds, #/hr	0	0	0	0	0	0	0	0	0	0	0	0
Sign Control	Stop	Stop	Stop	Stop	Stop	Stop	Free	Free	Free	Free	Free	Free
RT Channelized	-	-	None									
Storage Length	-	-	-	-	-	-	-	-	-	-	-	-
Veh in Median Storage,	# -	0	-	-	0	-	-	0	-	-	0	-
Grade, %	-	2	-	-	-1	-	-	1	-	-	-1	-
Peak Hour Factor	90	90	90	90	90	90	90	90	90	90	90	90
Heavy Vehicles, %	0	0	0	10	0	8	0	9	2	8	13	0
Mvmt Flow	2	1	1	22	1	27	1	153	52	44	96	1

Major/Minor	Minor2		Ν	/linor1		ſ	Major1		Ν	/lajor2			
Conflicting Flow All	380	392	97	367	366	179	97	0	0	205	0	0	
Stage 1	185	185	-	181	181	-	-	-	-	-	-	-	
Stage 2	195	207	-	186	185	-	-	-	-	-	-	-	
Critical Hdwy	7.5	6.9	6.4	7	6.3	6.18	4.3	-	-	4.3	-	-	
Critical Hdwy Stg 1	6.5	5.9	-	6	5.3	-	-	-	-	-	-	-	
Critical Hdwy Stg 2	6.5	5.9	-	6	5.3	-	-	-	-	-	-	-	
Follow-up Hdwy	3	4	3.1	3	4	3.1	3	-	-	3	-	-	
Pot Cap-1 Maneuver	634	524	1019	682	577	922	1112	-	-	1022	-	-	
Stage 1	927	735	-	956	761	-	-	-	-	-	-	-	
Stage 2	914	718	-	950	758	-	-	-	-	-	-	-	
Platoon blocked, %								-	-		-	-	
Mov Cap-1 Maneuver	593	499	1019	655	550	922	1112	-	-	1022	-	-	
Mov Cap-2 Maneuver	· 593	499	-	655	550	-	-	-	-	-	-	-	
Stage 1	926	701	-	955	760	-	-	-	-	-	-	-	
Stage 2	885	717	-	904	723	-	-	-	-	-	-	-	

Approach	EB	WB	NB	SB	
HCM Control Delay, s	10.8	10	0	2.7	
HCM LOS	В	В			

Minor Lane/Major Mvmt	NBL	NBT	NBR	EBLn1\	VBLn1	SBL	SBT	SBR
Capacity (veh/h)	1112	-	-	629	771	1022	-	-
HCM Lane V/C Ratio	0.001	-	-	0.007	0.065	0.043	-	-
HCM Control Delay (s)	8.2	0	-	10.8	10	8.7	0	-
HCM Lane LOS	А	А	-	В	В	А	А	-
HCM 95th %tile Q(veh)	0	-	-	0	0.2	0.1	-	-

# HCM 6th Signalized Intersection Summary 11: SR 28 & SR 322

	۶	-	$\mathbf{F}$	4	+	•	•	Ť	1	1	Ļ	~
Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations		\$			4		ሻ	ĥ		۲	•	7
Traffic Volume (veh/h)	52	92	16	11	82	214	19	137	21	152	99	152
Future Volume (veh/h)	52	92	16	11	82	214	19	137	21	152	99	152
Initial Q (Qb), veh	0	0	0	0	0	0	0	0	0	0	0	0
Ped-Bike Adj(A_pbT)	1.00		1.00	1.00		1.00	1.00		1.00	1.00		1.00
Parking Bus, Adj	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
Work Zone On Approach		No			No			No			No	
Adj Sat Flow, veh/h/ln	1665	1665	1665	2078	2078	2078	1707	1623	1623	1674	1575	1758
Adj Flow Rate, veh/h	58	102	0	12	91	0	21	152	0	169	110	0
Peak Hour Factor	0.90	0.90	0.90	0.90	0.90	0.90	0.90	0.90	0.90	0.90	0.90	0.90
Percent Heavy Veh, %	8	8	8	7	7	7	5	11	11	9	16	3
Cap, veh/h	193	220		115	385		545	413		586	544	
Arrive On Green	0.18	0.20	0.00	0.18	0.20	0.00	0.05	0.25	0.00	0.14	0.35	0.00
Sat Flow, veh/h	395	1100	0	112	1918	0	1626	1623	0	1594	1575	1490
Grp Volume(v), veh/h	160	0	0	103	0	0	21	152	0	169	110	0
Grp Sat Flow(s),veh/h/ln	1494	0	0	2030	0	0	1626	1623	0	1594	1575	1490
Q Serve(q s), s	2.2	0.0	0.0	0.0	0.0	0.0	0.4	3.3	0.0	3.1	2.1	0.0
Cycle Q Clear(q c), s	4.1	0.0	0.0	1.8	0.0	0.0	0.4	3.3	0.0	3.1	2.1	0.0
Prop In Lane	0.36		0.00	0.12		0.00	1.00		0.00	1.00		1.00
Lane Grp Cap(c), veh/h	379	0		453	0		545	413		586	544	
V/C Ratio(X)	0.42	0.00		0.23	0.00		0.04	0.37		0.29	0.20	
Avail Cap(c_a), veh/h	990	0		1292	0		1256	1315		1138	1276	
HCM Platoon Ratio	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
Upstream Filter(I)	1.00	0.00	0.00	1.00	0.00	0.00	1.00	1.00	0.00	1.00	1.00	0.00
Uniform Delay (d), s/veh	15.5	0.0	0.0	14.6	0.0	0.0	10.6	13.2	0.0	9.0	9.9	0.0
Incr Delay (d2), s/veh	1.1	0.0	0.0	0.4	0.0	0.0	0.0	0.8	0.0	0.4	0.3	0.0
Initial Q Delay(d3),s/veh	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
%ile BackOfQ(50%),veh/ln	1.3	0.0	0.0	0.8	0.0	0.0	0.1	0.9	0.0	0.8	0.6	0.0
Unsig. Movement Delay, s/veh												
LnGrp Delay(d),s/veh	16.6	0.0	0.0	14.9	0.0	0.0	10.7	14.0	0.0	9.4	10.2	0.0
LnGrp LOS	В	А		В	А		В	В		А	В	
Approach Vol, veh/h		160	А		103	А		173	А		279	A
Approach Delay, s/veh		16.6			14.9			13.6			9.7	
Approach LOS		В			В			В			А	
Timer - Assigned Phs	1	2		4	5	6		8				
Phs Duration (G+Y+Rc) s	12.0	17.0		14.2	81	20.9		14.2				
Change Period $(Y+Rc)$ s	7.0	7.0		65	7.0	7.0		65				
Max Green Setting (Gmax) s	20.0	34.0		26.0	20.0	34.0		26.0				
Max O Clear Time $(q, c+11)$ s	5 1	53		6.1	20.0	<u> </u>		3.8				
Green Ext Time (n_c) s	0.7	0.7		0.1	0.0	0.5		0.4				
	0.7	0.7		0.7	0.0	0.0		0.7				
Intersection Summary			12.0									
			12.9									
			В									

#### Notes

Unsignalized Delay for [NBR, EBR, WBR, SBR] is excluded from calculations of the approach delay and intersection delay.

## · \* + \* \* \* \* \* \* \* \* \* \* \*

Movement EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR	
Lane Configurations	4	1					<b>4</b> 16		- <b>N</b>	<b>#</b> #		
Traffic Volume (veh/h) 62	1	81	0	0	0	0	243	115	121	278	0	
Future Volume (veh/h) 62	1	81	0	0	0	0	243	115	121	278	0	
Initial Q (Qb), veh 0	0	0				0	0	0	0	0	0	
Ped-Bike Adj(A_pbT) 1.00		1.00				1.00		1.00	1.00		1.00	
Parking Bus, Adj 1.00	1.00	1.00				1.00	1.00	1.00	1.00	1.00	1.00	
Work Zone On Approach	No						No			No		
Adj Sat Flow, veh/h/ln 1722	1949	1722				0	1623	1623	1300	1755	0	
Adj Flow Rate, veh/h 71	1	93				0	279	132	139	320	0	
Peak Hour Factor 0.87	0.87	0.87				0.87	0.87	0.87	0.87	0.87	0.87	
Percent Heavy Veh, % 16	0	16				0	9	9	43	11	0	
Cap, veh/h 186	3	148				0	1250	576	568	2529	0	
Arrive On Green 0.09	0.10	0.10				0.00	0.61	0.60	0.03	0.25	0.00	
Sat Flow, veh/h 1832	26	1459				0	2132	945	1238	3423	0	
Grp Volume(v), veh/h 72	0	93				0	208	203	139	320	0	
Grp Sat Flow(s),veh/h/ln1857	0	1459				0	1542	1453	1238	1668	0	
Q Serve(g_s), s 2.6	0.0	4.3				0.0	4.3	4.5	2.5	5.2	0.0	
Cycle Q Clear(g_c), s 2.6	0.0	4.3				0.0	4.3	4.5	2.5	5.2	0.0	
Prop In Lane 0.99		1.00				0.00		0.65	1.00		0.00	
Lane Grp Cap(c), veh/h 189	0	148				0	940	886	568	2529	0	
V/C Ratio(X) 0.38	0.00	0.63				0.00	0.22	0.23	0.24	0.13	0.00	
Avail Cap(c_a), veh/h 244	0	192				0	940	886	720	2529	0	
HCM Platoon Ratio 1.00	1.00	1.00				1.00	1.00	1.00	0.33	0.33	1.00	
Upstream Filter(I) 1.00	0.00	1.00				0.00	1.00	1.00	0.97	0.97	0.00	
Uniform Delay (d), s/veh 29.9	0.0	30.2				0.0	6.2	6.4	3.8	8.3	0.0	
Incr Delay (d2), s/veh 1.3	0.0	4.3				0.0	0.5	0.6	0.2	0.1	0.0	
Initial Q Delay(d3),s/veh 0.0	0.0	0.0				0.0	0.0	0.0	0.0	0.0	0.0	
%ile BackOfQ(50%),veh/ln1.1	0.0	1.5				0.0	1.2	1.2	0.4	1.2	0.0	
Unsig. Movement Delay, s/veh												
LnGrp Delay(d),s/veh 31.1	0.0	34.5				0.0	6.7	7.0	4.0	8.4	0.0	
LnGrp LOS C	A	С				A	A	A	A	A	A	
Approach Vol, veh/h	165						411			459		
Approach Delay, s/veh	33.0						6.8			7.1		
Approach LOS	С						А			А		
Timer - Assigned Phs 1	2		4		6							
Phs Duration (G+Y+Rc), \$0.4	47.7		11.9		58.1							
Change Period (Y+Rc), s 6.0	6.0		* 5.8		6.0							
Max Green Setting (Gmak), G	31.0		* 8.2		50.0							
Max Q Clear Time (g_c+I1),5s	6.5		6.3		7.2							
Green Ext Time (p_c), s 0.3	7.2		0.1		7.0							
Intersection Summary												
HCM 6th Ctrl Delay		11.1										
HCM 6th LOS		В										

#### Notes

\* HCM 6th computational engine requires equal clearance times for the phases crossing the barrier.

## **ノ → > ィ ← べ ヘ ↑ ァ > ↓ イ**

Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR	
Lane Configurations					- सी	1	- ሽ	- 11			- <b>†</b> Ъ		
Traffic Volume (veh/h)	0	0	0	99	1	89	66	239	0	0	294	80	
Future Volume (veh/h)	0	0	0	99	1	89	66	239	0	0	294	80	
Initial Q (Qb), veh				0	0	0	0	0	0	0	0	0	
Ped-Bike Adj(A_pbT)				1.00		1.00	1.00		1.00	1.00		1.00	
Parking Bus, Adj				1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	
Work Zone On Approach	h				No			No			No		
Adj Sat Flow, veh/h/ln				1398	2024	1398	1581	1455	0	0	1585	1585	
Adj Flow Rate, veh/h				112	1	101	75	272	0	0	334	91	
Peak Hour Factor				0.88	0.88	0.88	0.88	0.88	0.88	0.88	0.88	0.88	
Percent Heavy Veh, %				44	0	44	12	21	0	0	23	23	
Cap, veh/h				242	2	150	631	2024	0	0	1388	373	
Arrive On Green				0.11	0.13	0.13	0.14	1.00	0.00	0.00	0.59	0.58	
Sat Flow, veh/h				1911	17	1185	1506	2837	0	0	2426	630	
Grp Volume(v), veh/h				113	0	101	75	272	0	0	213	212	
Grp Sat Flow(s), veh/h/In	1			1928	0	1185	1506	1382	0	0	1505	1471	
Q Serve(g_s), s				3.8	0.0	5.7	1.1	0.0	0.0	0.0	4.7	4.9	
Cycle Q Clear(g_c), s				3.8	0.0	5.7	1.1	0.0	0.0	0.0	4.7	4.9	
Prop In Lane				0.99		1.00	1.00		0.00	0.00		0.43	
Lane Grp Cap(c), veh/h				244	0	150	631	2024	0	0	890	870	
V/C Ratio(X)				0.46	0.00	0.67	0.12	0.13	0.00	0.00	0.24	0.24	
Avail Cap(c_a), veh/h				361	0	222	742	2024	0	0	890	870	
HCM Platoon Ratio				1.00	1.00	1.00	2.00	2.00	1.00	1.00	1.00	1.00	
Upstream Filter(I)				1.00	0.00	1.00	0.98	0.98	0.00	0.00	1.00	1.00	
Uniform Delay (d), s/veh	I			28.8	0.0	29.2	3.6	0.0	0.0	0.0	6.8	6.9	
Incr Delay (d2), s/veh				1.4	0.0	5.2	0.1	0.1	0.0	0.0	0.6	0.7	
Initial Q Delay(d3),s/veh				0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
%ile BackOfQ(50%),veh	ı/ln			1.7	0.0	1.6	0.2	0.0	0.0	0.0	1.3	1.4	
Unsig. Movement Delay	, s/veh												
LnGrp Delay(d),s/veh				30.2	0.0	34.4	3.7	0.1	0.0	0.0	7.4	7.6	
LnGrp LOS				С	A	С	A	A	A	A	A	A	
Approach Vol, veh/h					214			347			425		
Approach Delay, s/veh					32.2			0.9			7.5		
Approach LOS					С			A			A		
Timer - Assigned Phs	1	2		4		6							
Phs Duration (G+Y+Rc)	, s9.8	46.4		13.8		56.2							
Change Period (Y+Rc),	s 6.0	6.0		* 5.9		6.0							
Max Green Setting (Gma	ax <b>9</b> , <b>G</b>	31.0		* 12		46.0							
Max Q Clear Time (g_c+	-113),15	6.9		7.7		2.0							
Green Ext Time (p_c), s	0.1	7.4		0.3		6.0							
Intersection Summary													
HCM 6th Ctrl Delay			10.5										
HCM 6th LOS			В										

#### Notes

\* HCM 6th computational engine requires equal clearance times for the phases crossing the barrier.

0.1					
EBL	EBT	WBT	WBR	SBL	SBR
	- <del>द</del>	el 👘		۰¥	
2	254	306	22	1	1
2	254	306	22	1	1
0	0	0	0	0	0
Free	Free	Free	Free	Stop	Stop
-	None	-	None	-	None
-	-	-	-	0	-
# -	0	0	-	0	-
-	-9	9	-	-10	-
88	88	88	88	88	88
0	9	6	9	0	0
2	289	348	25	1	1
	0.1 EBL 2 2 0 Free - - - - 88 88 0 2	0.1 EBL EBT 2 254 2 254 2 254 0 00 Free Free Free None 2 0 # − 9 88 88 88 0 9 2 289	0.1       WBT         EBL       EBT       WBT         2       254       306         2       254       306         2       254       306         2       254       306         2       254       306         0       0       0         Free       Free       Free         None       -       -         4       0       0         9       88       88         0       9       6         2       289       348	0.1       WBT       WBR         EBL       EBT       WBT       WBR         2       254       306       22         2       254       306       22         2       254       306       22         2       254       306       22         0       0       0       0         Free       Free       Free       Free         None       -       None         -       -       -       -         # -       0       0       -         # -       0       0       -         # -       0       0       -         88       88       88       88         0       9       6       9         2       289       348       25	0.1       WBT       WBR       SBL         EBL       EBT       WBT       WBR       SBL <ul> <li>1</li> <li>2</li> <li>254</li> <li>306</li> <li>222</li> <li>11</li> <li>254</li> <li>306</li> <li>22</li> <li>11</li> <li>254</li> <li>306</li> <li>22</li> <li>11</li> <li>254</li> <li>306</li> <li>22</li> <li>11</li> <li>254</li> <li>306</li> <li>22</li> <li>11</li> <li>300</li> <li>0</li> <li< td=""></li<></ul>

Major/Minor	Major1	Ν	/lajor2	ľ	Minor2		
Conflicting Flow All	373	0	-	0	654	361	
Stage 1	-	-	-	-	361	-	
Stage 2	-	-	-	-	293	-	
Critical Hdwy	4.3	-	-	-	4.4	5.2	
Critical Hdwy Stg 1	-	-	-	-	3.4	-	
Critical Hdwy Stg 2	-	-	-	-	3.4	-	
Follow-up Hdwy	3	-	-	-	3	3.1	
Pot Cap-1 Maneuver	894	-	-	-	700	802	
Stage 1	-	-	-	-	988	-	
Stage 2	-	-	-	-	1026	-	
Platoon blocked, %		-	-	-			
Mov Cap-1 Maneuver	r 894	-	-	-	698	802	
Mov Cap-2 Maneuver	r -	-	-	-	698	-	
Stage 1	-	-	-	-	985	-	
Stage 2	-	-	-	-	1026	-	
Approach	EB		WB		SB		
HCM Control Delay, s	s 0.1		0		9.8		
HCM LOS					А		
Minor Lane/Major Mv	mt	EBL	EBT	WBT	WBR S	SBLn1	
Capacity (veh/h)		894	-	-	-	746	
HCM Lane V/C Ratio		0.003	-	-	-	0.003	
HCM Control Delay (s	s)	9	0	-	-	9.8	
HCM Lane LOS		А	A	-	-	А	
HCM 95th %tile Q(vel	h)	0	-	-	-	0	

Intore	COC	non
ппен:	SEU	IUH

Int Delay, s/veh

Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations		4						A			- <b>4</b> ↑	
Traffic Vol, veh/h	65	1	78	0	0	0	0	71	52	3	148	0
Future Vol, veh/h	65	1	78	0	0	0	0	71	52	3	148	0
Conflicting Peds, #/hr	0	0	0	0	0	0	0	0	0	0	0	0
Sign Control	Stop	Stop	Stop	Stop	Stop	Stop	Free	Free	Free	Free	Free	Free
RT Channelized	-	-	None	-	-	None	-	-	Yield	-	-	None
Storage Length	-	-	-	-	-	-	-	-	-	-	-	-
Veh in Median Storage,	,# -	0	-	-	16979	-	-	0	-	-	0	-
Grade, %	-	-3	-	-	-2	-	-	1	-	-	-1	-
Peak Hour Factor	71	71	71	71	71	71	71	71	71	71	71	71
Heavy Vehicles, %	15	0	10	0	0	0	0	14	23	0	13	0
Mvmt Flow	92	1	110	0	0	0	0	100	73	4	208	0

Major/Minor	Minor2			Major1		I	Major2			
Conflicting Flow All	266	316	104	-	0	0	100	0	0	
Stage 1	216	216	-	-	-	-	-	-	-	
Stage 2	50	100	-	-	-	-	-	-	-	
Critical Hdwy	6.5	5.9	6.8	-	-	-	4.3	-	-	
Critical Hdwy Stg 1	5.5	4.9	-	-	-	-	-	-	-	
Critical Hdwy Stg 2	5.5	4.9	-	-	-	-	-	-	-	
Follow-up Hdwy	3	4	3.1	-	-	-	3	-	-	
Pot Cap-1 Maneuver	828	636	998	0	-	-	1110	-	0	
Stage 1	943	754	-	0	-	-	-	-	0	
Stage 2	1135	830	-	0	-	-	-	-	0	
Platoon blocked, %					-	-		-		
Mov Cap-1 Maneuver	825	0	998	-	-	-	1110	-	-	
Mov Cap-2 Maneuver	825	0	-	-	-	-	-	-	-	
Stage 1	943	0	-	-	-	-	-	-	-	
Stage 2	1130	0	-	-	-	-	-	-	-	
Approach	EB			NB			SB			
HCM Control Delay, s	10.1			0			0.2			

HCM LOS B

Minor Lane/Major Mvmt	NBT	NBR E	EBLn1	SBL	SBT
Capacity (veh/h)	-	-	911	1110	-
HCM Lane V/C Ratio	-	-	0.223	0.004	-
HCM Control Delay (s)	-	-	10.1	8.3	0
HCM Lane LOS	-	-	В	А	Α
HCM 95th %tile Q(veh)	-	-	0.9	0	-

#### Intersection

Movement EBL EBT EBR WBL WBT WBR	r NBL NBT NBR SE	BL SBT SBR
Lane Configurations	4ħ	A⊅
Traffic Vol, veh/h 0 0 0 73 1 3	3 26 108 0	0 82 63
Future Vol, veh/h 0 0 0 73 1 3	3 26 108 0	0 82 63
Conflicting Peds, #/hr 0 0 0 0 0	0 0 0 0	0 0 0
Sign Control Stop Stop Stop Stop Stop	p Free Free Free Fre	e Free Free
RT Channelized None None	e None	Yield
Storage Length		
Veh in Median Storage, # - 2 0 ·	0 -	- 0 -
Grade, %31	7 -	- 0 -
Peak Hour Factor 89 89 89 89 89 89	9 89 89 89 8	89 89 89
Heavy Vehicles, % 0 0 0 18 0 33	3 27 19 0	0 9 14
Mvmt Flow 0 0 0 82 1 3	3 29 121 0	0 92 71

Major/Minor	Minor1		N	Major1		М	ajor2			
Conflicting Flow All	225	271	61	92	0	-	-	-	0	
Stage 1	179	179	-	-	-	-	-	-	-	
Stage 2	46	92	-	-	-	-	-	-	-	
Critical Hdwy	6.96	6.3	7.46	4.3	-	-	-	-	-	
Critical Hdwy Stg 1	5.96	5.3	-	-	-	-	-	-	-	
Critical Hdwy Stg 2	5.96	5.3	-	-	-	-	-	-	-	
Follow-up Hdwy	3	4	3.1	3	-	-	-	-	-	
Pot Cap-1 Maneuver	852	649	1051	1117	-	0	0	-	-	
Stage 1	960	763	-	-	-	0	0	-	-	
Stage 2	1133	827	-	-	-	0	0	-	-	
Platoon blocked, %					-			-	-	
Mov Cap-1 Maneuver	828	0	1051	1117	-	-	-	-	-	
Mov Cap-2 Maneuver	828	0	-	-	-	-	-	-	-	
Stage 1	933	0	-	-	-	-	-	-	-	
Stage 2	1133	0	-	-	-	-	-	-	-	
Approach	WB			NB			SB			
HCM Control Delay, s	9.8			1.7			0			
HCM LOS	А									

Minor Lane/Major Mvmt	NBL	NBTWBL	1 SBT	SBR
Capacity (veh/h)	1117	- 83	5	· -
HCM Lane V/C Ratio	0.026	- 0.10	4	
HCM Control Delay (s)	8.3	0.1 9	8	· -
HCM Lane LOS	А	A	A	
HCM 95th %tile Q(veh)	0.1	- 0	3	· -

ersection		
	itersection	
ersection Delay, s/veh /.1	itersection Delay, s/veh	7.1
ersection LOS A	itersection LOS	А

Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations		4			ef 🔰			<del>ب</del> ا			el 🗧	
Traffic Vol, veh/h	3	0	82	0	34	7	8	0	0	0	18	0
Future Vol, veh/h	3	0	82	0	34	7	8	0	0	0	18	0
Peak Hour Factor	0.87	0.87	0.87	0.87	0.87	0.87	0.87	0.87	0.87	0.87	0.87	0.87
Heavy Vehicles, %	0	0	7	0	15	0	25	0	0	0	0	0
Mvmt Flow	3	0	94	0	39	8	9	0	0	0	21	0
Number of Lanes	0	1	0	0	1	0	0	1	0	0	1	0
Approach	EB				WB		NB				SB	
Opposing Approach	WB				EB		SB				NB	
Opposing Lanes	1				1		1				1	
Conflicting Approach Left	SB				NB		EB				WB	
Conflicting Lanes Left	1				1		1				1	
Conflicting Approach Right	NB				SB		WB				EB	
Conflicting Lanes Right	1				1		1				1	
HCM Control Delay	6.8				7.4		7.9				7.3	
HCM LOS	А				А		А				А	

Lane	NBLn1	EBLn1	WBLn1	SBLn1	
Vol Left, %	100%	4%	0%	0%	
Vol Thru, %	0%	0%	83%	100%	
Vol Right, %	0%	96%	17%	0%	
Sign Control	Stop	Stop	Stop	Stop	
Traffic Vol by Lane	8	85	41	18	
LT Vol	8	3	0	0	
Through Vol	0	0	34	18	
RT Vol	0	82	7	0	
Lane Flow Rate	9	98	47	21	
Geometry Grp	1	1	1	1	
Degree of Util (X)	0.012	0.093	0.055	0.024	
Departure Headway (Hd)	4.793	3.414	4.177	4.157	
Convergence, Y/N	Yes	Yes	Yes	Yes	
Сар	745	1046	857	858	
Service Time	2.835	1.445	2.202	2.197	
HCM Lane V/C Ratio	0.012	0.094	0.055	0.024	
HCM Control Delay	7.9	6.8	7.4	7.3	
HCM Lane LOS	А	А	А	А	
HCM 95th-tile Q	0	0.3	0.2	0.1	

WRL	WRI	NRL	NRK
	् भी	- Y	
1	116	4	1
1	116	4	1
0	0	0	0
Free	Free	Stop	Stop
-	None	-	None
-	-	0	-
-	0	0	-
-	-3	-5	-
75	75	75	75
0	9	0	0
1	155	5	1
F	VBL 1 1 0 - - - - - - - - - - - 75 0 1	VBL         WBT           1         116           1         116           0         0           Free         Free           -         None           -         -           -         0           -         -           -         0           -         -           -         0           -         -           -         0           -         -           75         755           0         9           1         155	VBL         WBT         NBL           1         116         4           1         116         4           0         0         0           Free         Stop         -           None         -         -           -         -         0         0           -         0         0         -           -         -         0         0           -         -         0         0           -         -         0         0           -         -         0         0           -         -         0         0           -         -         0         0           -         -         3         -55           75         75         75         75           0         9         0         1           1         155         5         5

Major/Minor	Major	1 [	Major2	ľ	Minor1	
Conflicting Flow All	(	0 C	207	0	361	204
Stage 1			-	-	204	-
Stage 2			-	-	157	-
Critical Hdwy			4.9	-	8.1	6.4
Critical Hdwy Stg 1			-	-	4.4	-
Critical Hdwy Stg 2			-	-	4.4	-
Follow-up Hdwy			3.5	-	3	3.4
Pot Cap-1 Maneuver			857	-	617	810
Stage 1			-	-	1017	-
Stage 2			-	-	1057	-
Platoon blocked, %				-		
Mov Cap-1 Maneuver			857	-	616	810
Mov Cap-2 Maneuver			-	-	616	-
Stage 1			-	-	1017	-
Stage 2			-	-	1056	-
Annroach	FF	3	WR		NR	
HCM Control Delay		)	0.1		10.6	
HCM LOS		J	0.1		10.0 R	
					D	
Minor Lane/Major Mvr	nt	NBLn1	EBT	EBR	WBL	WBT
Capacity (veh/h)		647	-	-	857	-

	047	-	- 007		
HCM Lane V/C Ratio	0.01	-	- 0.002	-	
HCM Control Delay (s)	10.6	-	- 9.2	0	
HCM Lane LOS	В	-	- A	А	
HCM 95th %tile Q(veh)	0	-	- 0	-	

# HCM 6th Signalized Intersection Summary 1: SR 28 & SR 85

	≯	-	$\mathbf{\hat{z}}$	4	+	•	1	Ť	۲	1	Ļ	~
Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations	ľ	4Î		7	el el		٦	<b>†</b>	1	7	el el	
Traffic Volume (veh/h)	94	107	10	186	65	30	14	418	296	17	257	36
Future Volume (veh/h)	94	107	10	186	65	30	14	418	296	17	257	36
Initial Q (Qb), veh	0	0	0	0	0	0	0	0	0	0	0	0
Ped-Bike Adj(A_pbT)	1.00		1.00	1.00		1.00	1.00		1.00	1.00		1.00
Parking Bus, Adj	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
Work Zone On Approach		No			No			No			No	
Adj Sat Flow, veh/h/ln	1684	1645	1645	1542	1619	1619	1581	1764	1790	1389	1324	1324
Adj Flow Rate, veh/h	103	118	0	204	71	0	15	459	0	19	282	0
Peak Hour Factor	0.91	0.91	0.91	0.91	0.91	0.91	0.91	0.91	0.91	0.91	0.91	0.91
Percent Heavy Veh, %	0	3	3	8	2	2	21	7	5	6	11	11
Cap, veh/h	121	150		230	276		17	688		20	500	
Arrive On Green	0.08	0.09	0.00	0.16	0.17	0.00	0.01	0.39	0.00	0.02	0.38	0.00
Sat Flow, veh/h	1604	1645	0	1469	1619	0	1506	1764	1517	1323	1324	0
Grp Volume(v), veh/h	103	118	0	204	71	0	15	459	0	19	282	0
Grp Sat Flow(s),veh/h/ln	1604	1645	0	1469	1619	0	1506	1764	1517	1323	1324	0
Q Serve(g_s), s	5.1	5.6	0.0	10.9	3.0	0.0	0.8	17.1	0.0	1.1	13.5	0.0
Cycle Q Clear(g_c), s	5.1	5.6	0.0	10.9	3.0	0.0	0.8	17.1	0.0	1.1	13.5	0.0
Prop In Lane	1.00		0.00	1.00		0.00	1.00		1.00	1.00		0.00
Lane Grp Cap(c), veh/h	121	150		230	276		17	688		20	500	
V/C Ratio(X)	0.85	0.79		0.89	0.26		0.87	0.67		0.94	0.56	
Avail Cap(c_a), veh/h	361	340		335	284		253	1047		227	753	
HCM Platoon Ratio	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
Upstream Filter(I)	1.00	1.00	0.00	1.00	1.00	0.00	1.00	1.00	0.00	1.00	1.00	0.00
Uniform Delay (d), s/veh	36.5	35.5	0.0	33.0	28.8	0.0	39.4	20.1	0.0	39.3	19.7	0.0
Incr Delay (d2), s/veh	15.2	8.7	0.0	17.5	0.5	0.0	68.9	4.0	0.0	77.9	3.6	0.0
Initial Q Delay(d3),s/veh	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
%ile BackOfQ(50%),veh/in	2.4	2.5	0.0	4./	1.1	0.0	0.6	7.0	0.0	0.8	4.2	0.0
Unsig. Movement Delay, s/veh	<b>F4 7</b>	44.0	0.0		00.0	0.0	100.0	014	0.0	447.0	00.0	0.0
LnGrp Delay(d),s/ven	51.7	44.3	0.0	50.5	29.2	0.0	108.3	24.1	0.0	117.2	23.3	0.0
LnGrp LUS	D	D		D	075		F	0		F	J	
Approach Vol, veh/h		221	A		2/5	A		4/4	A		301	A
Approach Delay, s/veh		47.7			45.0			26.8			29.2	
Approach LOS		D			D			С			С	
Timer - Assigned Phs	1	2	3	4	5	6	7	8				
Phs Duration (G+Y+Rc), s	7.5	38.7	19.3	14.3	8.5	37.7	13.0	20.6				
Change Period (Y+Rc), s	* 5.8	7.1	6.3	6.5	7.1	7.1	6.5	6.5				
Max Green Setting (Gmax), s	* 14	47.9	18.7	17.0	13.9	45.9	18.5	14.5				
Max Q Clear Time (g_c+l1), s	3.1	19.1	12.9	7.6	2.8	15.5	7.1	5.0				
Green Ext Time (p_c), s	0.0	12.5	0.3	0.2	0.0	7.5	0.2	0.1				
Intersection Summary												
HCM 6th Ctrl Delay			34.9									
HCM 6th LOS			С									

#### Notes

\* HCM 6th computational engine requires equal clearance times for the phases crossing the barrier. Unsignalized Delay for [NBR, EBR, WBR, SBR] is excluded from calculations of the approach delay and intersection delay.

Route 28 Corridor Study 3:45 pm 11/19/2019 Existing Conditions - PM Peak ANT

Intersection						
Int Delay, s/veh	2					
Movement	MRI	MRT	SBT	SBD	SEL	SED
MOVEMENT	NDL	NDT	501	JUK	JLL	JER
Lane Configurations		- सी	- <b>†</b>		- Y	
Traffic Vol, veh/h	23	272	166	0	47	16
Future Vol, veh/h	23	272	166	0	47	16
Conflicting Peds, #/hr	0	0	0	0	0	0
Sign Control	Free	Free	Free	Free	Stop	Stop
RT Channelized	-	None	-	None	-	None
Storage Length	-	-	-	-	0	-
Veh in Median Storage,	# -	0	0	-	0	-
Grade, %	-	7	-6	-	0	-
Peak Hour Factor	93	93	93	93	93	93
Heavy Vehicles, %	9	6	13	0	6	13
Mvmt Flow	25	292	178	0	51	17

Major/Minor	Major1	Ν	/lajor2	Ν	/linor2		
Conflicting Flow All	178	0	-	0	520	178	
Stage 1	-	-	-	-	178	-	
Stage 2	-	-	-	-	342	-	
Critical Hdwy	4.9	-	-	-	8.1	6.4	
Critical Hdwy Stg 1	-	-	-	-	5.46	-	
Critical Hdwy Stg 2	-	-	-	-	5.46	-	
Follow-up Hdwy	3.5	-	-	-	3	3.4	
Pot Cap-1 Maneuver	879	-	-	0	459	838	
Stage 1	-	-	-	0	986	-	
Stage 2	-	-	-	0	821	-	
Platoon blocked, %		-	-				
Mov Cap-1 Maneuver	879	-	-	-	443	838	
Mov Cap-2 Maneuver	-	-	-	-	443	-	
Stage 1	-	-	-	-	952	-	
Stage 2	-	-	-	-	821	-	
Approach	NB		SB		SE		
HCM Control Delay, s	0.7		0		13.3		
HCM LOS					В		
Minor Lane/Major Mvr	nt	NBL	NBT S	SELn1	SBT		
Capacity (veh/h)		879	-	503	-		
HCM Lane V/C Ratio		0.028	-	0.135	-		
HCM Control Delay (s	)	9.2	0	13.3	-		
HCM Lane LOS		А	А	В	-		
HCM 95th %tile Q(veh	ו)	0.1	-	0.5	-		

Interception						
Intersection						
Int Delay, s/veh	0.2					
Movement	EDI	EDD	NDI	NDT	CDT	CDD
woverneni	EDL	EDK	INDL	INDI	SDI	JDK
Lane Configurations	۰¥			- सी	4	
Traffic Vol, veh/h	8	2	1	331	310	11
Future Vol, veh/h	8	2	1	331	310	11
Conflicting Peds, #/hr	0	0	0	0	0	0
Sign Control	Stop	Stop	Free	Free	Free	Free
RT Channelized	-	None	-	None	-	None
Storage Length	0	-	-	-	-	-
Veh in Median Storage,	# 0	-	-	0	0	-
Grade, %	8	-	-	-4	-2	-
Peak Hour Factor	95	95	95	95	95	95
Heavy Vehicles, %	0	0	100	8	5	9
Mvmt Flow	8	2	1	348	326	12

Major/Minor	Minor2	N	lajor1	Ma	ajor2	
Conflicting Flow All	682	332	338	0	-	0
Stage 1	332	-	-	-	-	-
Stage 2	350	-	-	-	-	-
Critical Hdwy	8	7	4.3	-	-	-
Critical Hdwy Stg 1	7	-	-	-	-	-
Critical Hdwy Stg 2	7	-	-	-	-	-
Follow-up Hdwy	3	3.1	3	-	-	-
Pot Cap-1 Maneuver	346	700	920	-	-	-
Stage 1	720	-	-	-	-	-
Stage 2	701	-	-	-	-	-
Platoon blocked, %				-	-	-
Mov Cap-1 Maneuver	r 346	700	920	-	-	-
Mov Cap-2 Maneuver	r 346	-	-	-	-	-
Stage 1	719	-	-	-	-	-
Stage 2	701	-	-	-	-	-
Approach	FB		NB		SB	

Approach	EB	NB	SB	
HCM Control Delay, s	14.6	0	0	
HCM LOS	В			

Minor Lane/Major Mvmt	NBL	NBT EBLn1	SBT	SBR	
Capacity (veh/h)	920	- 385	-	-	
HCM Lane V/C Ratio	0.001	- 0.027	-	-	
HCM Control Delay (s)	8.9	0 14.6	-	-	
HCM Lane LOS	А	A B	-	-	
HCM 95th %tile Q(veh)	0	- 0.1	-	-	

1			11.1	
Int	erg	ser	`TIC	าท
	<b>U</b> I.		Juc	,,,,

				= .								
Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations		4		٦.	1			4			4	
Traffic Vol, veh/h	1	366	1	89	353	8	1	2	58	2	1	1
Future Vol, veh/h	1	366	1	89	353	8	1	2	58	2	1	1
Conflicting Peds, #/hr	0	0	0	0	0	0	1	0	0	0	0	1
Sign Control	Free	Free	Free	Free	Free	Free	Stop	Stop	Stop	Stop	Stop	Stop
RT Channelized	-	-	None									
Storage Length	-	-	-	120	-	-	-	-	-	-	-	-
Veh in Median Storage, a	# -	0	-	-	0	-	-	0	-	-	0	-
Grade, %	-	-5	-	-	3	-	-	-7	-	-	7	-
Peak Hour Factor	95	95	95	95	95	95	95	95	95	95	95	95
Heavy Vehicles, %	0	6	0	0	5	13	0	0	3	0	0	0
Mvmt Flow	1	385	1	94	372	8	1	2	61	2	1	1

Major/Minor	Major1		Ν	/lajor2		[	Vinor1		Ν	/linor2			
Conflicting Flow All	380	0	0	386	0	0	954	956	386	983	952	377	
Stage 1	-	-	-	-	-	-	388	388	-	564	564	-	
Stage 2	-	-	-	-	-	-	566	568	-	419	388	-	
Critical Hdwy	4.3	-	-	4.3	-	-	5.7	5.1	5.53	8.5	7.9	6.9	
Critical Hdwy Stg 1	-	-	-	-	-	-	4.7	4.1	-	7.5	6.9	-	
Critical Hdwy Stg 2	-	-	-	-	-	-	4.7	4.1	-	7.5	6.9	-	
Follow-up Hdwy	3	-	-	3	-	-	3	4	3.1	3	4	3.1	
Pot Cap-1 Maneuver	889	-	-	885	-	-	384	377	754	173	181	660	
Stage 1	-	-	-	-	-	-	846	712	-	464	411	-	
Stage 2	-	-	-	-	-	-	719	636	-	594	527	-	
Platoon blocked, %		-	-		-	-							
Mov Cap-1 Maneuver	889	-	-	885	-	-	350	337	754	145	162	659	
Mov Cap-2 Maneuver	-	-	-	-	-	-	350	337	-	145	162	-	
Stage 1	-	-	-	-	-	-	845	711	-	464	367	-	
Stage 2	-	-	-	-	-	-	639	569	-	544	526	-	
Approach	EB			WB			NB			SB			
HCM Control Delay, s	0			1.9			10.6			24.8			
HCM LOS							В			С			
Minor Lano/Major Myr	nt N	IRI n1	FRI	FRT	FRD	W/RI			SRI n1				

Minor Lane/Major Mvmt	NBLn1	EBL	EBT	EBR WB	l WBT	WBR	SBLn1	
Capacity (veh/h)	712	889	-	- 88	5-	-	186	
HCM Lane V/C Ratio	0.09	0.001	-	- 0.10	6 -	-	0.023	
HCM Control Delay (s)	10.6	9.1	0	- 9.	5-	-	24.8	
HCM Lane LOS	В	А	А		۰ A	-	С	
HCM 95th %tile Q(veh)	0.3	0	-	- 0.	4 -	-	0.1	

### HCM 6th Signalized Intersection Summary 5: SR 28 & SR 66

	۶	→	$\mathbf{\hat{z}}$	4	+	•	1	Ť	1	1	Ļ	~
Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations	5	î,			4			4			4	
Traffic Volume (veh/h)	117	255	2	1	258	112	5	4	4	170	6	143
Future Volume (veh/h)	117	255	2	1	258	112	5	4	4	170	6	143
Initial Q (Qb), veh	0	0	0	0	0	0	0	0	0	0	0	0
Ped-Bike Adj(A_pbT)	1.00		0.97	0.99		0.99	1.00		0.99	0.99		0.99
Parking Bus, Adj	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
Work Zone On Approach		No			No			No			No	
Adj Sat Flow, veh/h/ln	1481	1557	1557	1582	1582	1582	1685	1685	1685	1685	1685	1685
Adj Flow Rate, veh/h	122	266	2	1	269	117	5	4	4	177	6	149
Peak Hour Factor	0.96	0.96	0.96	0.96	0.96	0.96	0.96	0.96	0.96	0.96	0.96	0.96
Percent Heavy Veh, %	11	5	5	3	3	3	0	0	0	0	0	0
Cap, veh/h	426	788	6	65	340	147	219	170	133	303	27	187
Arrive On Green	0.09	0.51	0.49	0.31	0.33	0.31	0.29	0.31	0.31	0.29	0.31	0.29
Sat Flow, veh/h	1410	1543	12	1	1041	451	418	548	429	657	86	605
Grp Volume(v), veh/h	122	0	268	387	0	0	13	0	0	332	0	0
Grp Sat Flow(s),veh/h/ln	1410	0	1554	1493	0	0	1396	0	0	1349	0	0
Q Serve(g_s), s	2.9	0.0	5.7	0.0	0.0	0.0	0.0	0.0	0.0	11.6	0.0	0.0
Cycle Q Clear(g_c), s	2.9	0.0	5.7	13.4	0.0	0.0	0.3	0.0	0.0	12.8	0.0	0.0
Prop In Lane	1.00		0.01	0.00		0.30	0.38		0.31	0.53		0.45
Lane Grp Cap(c), veh/h	426	0	794	526	0	0	496	0	0	492	0	0
V/C Ratio(X)	0.29	0.00	0.34	0.74	0.00	0.00	0.03	0.00	0.00	0.67	0.00	0.00
Avail Cap(c_a), veh/h	571	0	1312	868	0	0	827	0	0	822	0	0
HCM Platoon Ratio	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
Upstream Filter(I)	1.00	0.00	1.00	1.00	0.00	0.00	1.00	0.00	0.00	1.00	0.00	0.00
Uniform Delay (d), s/veh	9.0	0.0	8.1	17.3	0.0	0.0	13.5	0.0	0.0	18.1	0.0	0.0
Incr Delay (d2), s/veh	0.4	0.0	0.2	2.0	0.0	0.0	0.0	0.0	0.0	1.6	0.0	0.0
Initial Q Delay(d3),s/veh	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
%ile BackOfQ(50%),veh/In	0.8	0.0	1.6	4.5	0.0	0.0	0.1	0.0	0.0	4.0	0.0	0.0
Unsig. Movement Delay, s/veh												
LnGrp Delay(d),s/veh	9.4	0.0	8.3	19.3	0.0	0.0	13.5	0.0	0.0	19.7	0.0	0.0
LnGrp LOS	A	A	A	В	A	А	В	A	A	В	A	<u> </u>
Approach Vol, veh/h		390			387			13			332	
Approach Delay, s/veh		8.6			19.3			13.5			19.7	
Approach LOS		A			В			В			В	
Timer - Assigned Phs	1	2		4		6		8				
Phs Duration (G+Y+Rc), s	10.3	23.2		22.2		33.5		22.2				
Change Period (Y+Rc), s	6.0	6.0		6.0		6.0		6.0				
Max Green Setting (Gmax), s	10.0	30.0		30.0		46.0		30.0				
Max Q Clear Time (q_c+I1), s	4.9	15.4		2.3		7.7		14.8				
Green Ext Time (p_c), s	0.1	1.4		0.0		1.0		1.2				
Intersection Summary												
HCM 6th Ctrl Delay			15.6									
HCM 6th LOS			В									

Int	~ r ~		+!~	-
In	ers	ec	UΟ	n

		FDT			MOT		NIDI	NDT		0.01	ODT	000
Movement	ERF	FRI	EBR	WBL	WBI	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations		4			- 44			4			- 44	
Traffic Vol, veh/h	13	218	10	11	257	6	15	1	2	8	2	12
Future Vol, veh/h	13	218	10	11	257	6	15	1	2	8	2	12
Conflicting Peds, #/hr	0	0	0	0	0	0	0	0	0	0	0	0
Sign Control F	ree	Free	Free	Free	Free	Free	Stop	Stop	Stop	Stop	Stop	Stop
RT Channelized	-	-	None	-	-	None	-	-	None	-	-	None
Storage Length	-	-	-	-	-	-	-	-	-	-	-	-
Veh in Median Storage, #	-	0	-	-	0	-	-	0	-	-	0	-
Grade, %	-	1	-	-	-1	-	-	9	-	-	-3	-
Peak Hour Factor	85	85	85	85	85	85	85	85	85	85	85	85
Heavy Vehicles, %	0	6	0	0	5	0	0	0	0	13	0	8
Mvmt Flow	15	256	12	13	302	7	18	1	2	9	2	14

Major/Minor	Major1		Ν	/lajor2		ļ	Minor1		Ν	/linor2			
Conflicting Flow All	309	0	0	268	0	0	632	627	262	626	630	306	
Stage 1	-	-	-	-	-	-	292	292	-	332	332	-	
Stage 2	-	-	-	-	-	-	340	335	-	294	298	-	
Critical Hdwy	4.9	-	-	4.9	-	-	8.1	8.3	6.4	8.1	5.9	6.4	
Critical Hdwy Stg 1	-	-	-	-	-	-	7.9	7.3	-	5.63	4.9	-	
Critical Hdwy Stg 2	-	-	-	-	-	-	7.9	7.3	-	5.63	4.9	-	
Follow-up Hdwy	3.5	-	-	3.5	-	-	3	4	3.4	3	4	3.4	
Pot Cap-1 Maneuver	782	-	-	811	-	-	372	294	750	377	446	708	
Stage 1	-	-	-	-	-	-	712	583	-	817	685	-	
Stage 2	-	-	-	-	-	-	653	546	-	854	705	-	
Platoon blocked, %		-	-		-	-							
Mov Cap-1 Maneuver	782	-	-	811	-	-	352	282	750	363	427	708	
Mov Cap-2 Maneuver	-	-	-	-	-	-	352	282	-	363	427	-	
Stage 1	-	-	-	-	-	-	696	570	-	798	672	-	
Stage 2	-	-	-	-	-	-	626	536	-	830	689	-	
Approach	EB			WB			NB			SB			
HCM Control Delay, s	0.5			0.4			15.3			12.5			
HCM LOS							С			В			
Minor Lano/Major Mun	ot N	IDI n1	EDI	EDT	EDD	\//DI			DIn1				

Minor Lane/Major Mvmt	NBLn1	EBL	EBT	EBR	WBL	WBT	WBR 3	SBLn1	
Capacity (veh/h)	369	782	-	-	811	-	-	504	
HCM Lane V/C Ratio	0.057	0.02	-	-	0.016	-	-	0.051	
HCM Control Delay (s)	15.3	9.7	0	-	9.5	0	-	12.5	
HCM Lane LOS	С	А	А	-	А	А	-	В	
HCM 95th %tile Q(veh)	0.2	0.1	-	-	0	-	-	0.2	

#### Intersection

Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations		\$			\$			\$			\$	
Traffic Vol, veh/h	1	140	36	30	165	14	39	12	18	10	9	6
Future Vol, veh/h	1	140	36	30	165	14	39	12	18	10	9	6
Conflicting Peds, #/hr	0	0	0	0	0	0	0	0	0	0	0	0
Sign Control	Free	Free	Free	Free	Free	Free	Stop	Stop	Stop	Stop	Stop	Stop
RT Channelized	-	-	None									
Storage Length	-	-	-	-	-	-	-	-	-	-	-	-
Veh in Median Storage,	# -	0	-	-	0	-	-	0	-	-	0	-
Grade, %	-	6	-	-	-2	-	-	-3	-	-	12	-
Peak Hour Factor	83	83	83	83	83	83	83	83	83	83	83	83
Heavy Vehicles, %	0	9	8	7	8	0	10	0	6	20	11	0
Mvmt Flow	1	169	43	36	199	17	47	14	22	12	11	7

Major/Minor I	Major1		Major2		1	Minor1		Ν	/linor2			
Conflicting Flow All	216	0 0	212	0	0	482	481	191	491	494	208	
Stage 1	-		-	-	-	193	193	-	280	280	-	
Stage 2	-		-	-	-	289	288	-	211	214	-	
Critical Hdwy	4.9		4.9	-	-	8.1	5.9	6.4	8.1	9.01	6.4	
Critical Hdwy Stg 1	-		-	-	-	5.6	4.9	-	8.7	8.01	-	
Critical Hdwy Stg 2	-		-	-	-	5.6	4.9	-	8.7	8.01	-	
Follow-up Hdwy	3.5		3.5	-	-	3	4	3.4	3	4.099	3.4	
Pot Cap-1 Maneuver	850		853	-	-	493	528	824	484	334	806	
Stage 1	-		-	-	-	962	769	-	684	550	-	
Stage 2	-		-	-	-	861	711	-	786	615	-	
Platoon blocked, %				-	-							
Mov Cap-1 Maneuver	850		853	-	-	458	502	824	444	318	806	
Mov Cap-2 Maneuver	-		-	-	-	458	502	-	444	318	-	
Stage 1	-		-	-	-	961	768	-	683	524	-	
Stage 2	-		-	-	-	796	677	-	750	614	-	
Approach	EB		WB			NB			SB			
HCM Control Delay, s	0.1		1.4			13.1			14			
HCM LOS						В			В			
Minor Lane/Major Mvm	nt NBL	n1 EBL	EBT	EBR	WBL	WBT	WBR S	SBLn1				
Capacity (veh/h)	5	27 850	-	-	853	-	-	429				
HCM Lane V/C Ratio	0.1	58 0.001	-	-	0.042	-	-	0.07				

HCM Control Delay (s)	13.1	9.2	0	-	9.4	0	-	14
HCM Lane LOS	В	Α	А	-	Α	А	-	В
HCM 95th %tile Q(veh)	0.6	0	-	-	0.1	-	-	0.2

Intersection													
Int Delay, s/veh	2.4												
Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR	
Lane Configurations		\$			\$			\$			\$		
Traffic Vol, veh/h	2	113	10	38	200	17	9	11	19	8	9	5	
Future Vol, veh/h	2	113	10	38	200	17	9	11	19	8	9	5	
Conflicting Peds, #/hr	0	0	1	1	0	0	0	0	0	0	0	0	
Sign Control	Free	Free	Free	Free	Free	Free	Stop	Stop	Stop	Stop	Stop	Stop	
RT Channelized	-	-	None										
Storage Length	-	-	-	-	-	-	-	-	-	-	-	-	
Veh in Median Storage,	# -	0	-	-	0	-	-	0	-	-	0	-	
Grade, %	-	0	-	-	0	-	-	2	-	-	-2	-	
Peak Hour Factor	91	91	91	91	91	91	91	91	91	91	91	91	
Heavy Vehicles, %	50	7	0	11	7	0	0	0	5	0	0	0	
Mvmt Flow	2	124	11	42	220	19	10	12	21	9	10	5	

Major/Minor N	/lajor1		Ν	Major2		I	Minor1		N	Ainor2			
Conflicting Flow All	239	0	0	136	0	0	456	458	131	464	454	230	
Stage 1	-	-	-	-	-	-	135	135	-	314	314	-	
Stage 2	-	-	-	-	-	-	321	323	-	150	140	-	
Critical Hdwy	4.9	-	-	4.9	-	-	8.1	6.9	6.45	8.1	6.1	6.4	
Critical Hdwy Stg 1	-	-	-	-	-	-	6.5	5.9	-	5.7	5.1	-	
Critical Hdwy Stg 2	-	-	-	-	-	-	6.5	5.9	-	5.7	5.1	-	
Follow-up Hdwy	3.5	-	-	3.5	-	-	3	4	3.4	3	4	3.4	
Pot Cap-1 Maneuver	833	-	-	913	-	-	517	477	890	509	531	783	
Stage 1	-	-	-	-	-	-	994	777	-	830	683	-	
Stage 2	-	-	-	-	-	-	766	631	-	1007	797	-	
Platoon blocked, %		-	-		-	-							
Mov Cap-1 Maneuver	833	-	-	912	-	-	484	450	889	466	501	783	
Mov Cap-2 Maneuver	-	-	-	-	-	-	484	450	-	466	501	-	
Stage 1	-	-	-	-	-	-	990	774	-	828	647	-	
Stage 2	-	-	-	-	-	-	709	598	-	965	794	-	
Annroach	FR			W/B			MB			SB			
HCM Control Delay s	0.1		-	11			11 /			12.1			
HCM LOS	0.1			1.7			R			R			
							U			U			
Minor Lane/Major Mvm	t	NBLn1	EBL	EBT	EBR	WBL	WBT	WBR S	SBLn1				
Capacity (veh/h)		605	833	-	-	912	-	-	530				
HCM Lane V/C Ratio		0.071	0.003	-	-	0.046	-	-	0.046				
UCM Control Doloy (c)		11 /	0.2	0		01	0		10.1				

HCM Control Delay (s) 11.4 9.3 0 9.1 0 12.1 HCM Lane LOS В А А А А В --HCM 95th %tile Q(veh) 0.2 0 0.1 0.1 ----

4

#### Intersection

Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations		¢			\$			\$			\$	
Traffic Vol, veh/h	3	1	2	106	2	35	1	122	36	19	177	5
Future Vol, veh/h	3	1	2	106	2	35	1	122	36	19	177	5
Conflicting Peds, #/hr	0	0	0	0	0	0	0	0	0	0	0	0
Sign Control	Stop	Stop	Stop	Stop	Stop	Stop	Free	Free	Free	Free	Free	Free
RT Channelized	-	-	None									
Storage Length	-	-	-	-	-	-	-	-	-	-	-	-
Veh in Median Storage,	# -	0	-	-	0	-	-	0	-	-	0	-
Grade, %	-	2	-	-	-1	-	-	1	-	-	-1	-
Peak Hour Factor	83	83	83	83	83	83	83	83	83	83	83	83
Heavy Vehicles, %	0	0	0	3	0	3	0	12	0	5	8	0
Mvmt Flow	4	1	2	128	2	42	1	147	43	23	213	6

Major/Minor	Minor2		Ν	/linor1		ſ	Major1			Major2			
Conflicting Flow All	455	454	216	435	436	169	219	0	0	190	0	0	
Stage 1	262	262	-	171	171	-	-	-	-	-	-	-	
Stage 2	193	192	-	264	265	-	-	-	-	-	-	-	
Critical Hdwy	7.5	6.9	6.4	6.93	6.3	6.13	4.3	-	-	4.3	-	-	
Critical Hdwy Stg 1	6.5	5.9	-	5.93	5.3	-	-	-	-	-	-	-	
Critical Hdwy Stg 2	6.5	5.9	-	5.93	5.3	-	-	-	-	-	-	-	
Follow-up Hdwy	3	4	3.1	3	4	3.1	3	-	-	3	-	-	
Pot Cap-1 Maneuver	559	480	867	619	529	936	1011	-	-	1034	-	-	
Stage 1	832	675	-	971	768	-	-	-	-	-	-	-	
Stage 2	917	730	-	865	703	-	-	-	-	-	-	-	
Platoon blocked, %								-	-		-	-	
Mov Cap-1 Maneuver	522	468	867	604	515	936	1011	-	-	1034	-	-	
Mov Cap-2 Maneuver	- 522	468	-	604	515	-	-	-	-	-	-	-	
Stage 1	831	658	-	970	767	-	-	-	-	-	-	-	
Stage 2	872	729	-	839	685	-	-	-	-	-	-	-	

Approach	EB	WB	NB	SB	
HCM Control Delay, s	11.2	12.4	0.1	0.8	
HCM LOS	В	В			

Minor Lane/Major Mvmt	NBL	NBT	NBR	EBLn1\	NBLn1	SBL	SBT	SBR
Capacity (veh/h)	1011	-	-	589	660	1034	-	-
HCM Lane V/C Ratio	0.001	-	-	0.012	0.261	0.022	-	-
HCM Control Delay (s)	8.6	0	-	11.2	12.4	8.6	0	-
HCM Lane LOS	А	А	-	В	В	А	А	-
HCM 95th %tile Q(veh)	0	-	-	0	1	0.1	-	-

# HCM 6th Signalized Intersection Summary 11: SR 28 & SR 322

	۶	→	$\mathbf{\hat{z}}$	4	+	•	٠	Ť	1	5	ŧ	~
Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations		4			\$		ሻ	f,		5	•	1
Traffic Volume (veh/h)	67	147	28	30	137	270	24	122	16	234	148	64
Future Volume (veh/h)	67	147	28	30	137	270	24	122	16	234	148	64
Initial Q (Qb), veh	0	0	0	0	0	0	0	0	0	0	0	0
Ped-Bike Adj(A_pbT)	1.00		1.00	1.00		1.00	1.00		1.00	1.00		1.00
Parking Bus, Adj	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
Work Zone On Approach		No			No			No			No	
Adj Sat Flow, veh/h/ln	1764	1764	1764	2167	2167	2167	1665	1637	1637	1758	1674	1730
Adj Flow Rate, veh/h	73	160	0	33	149	0	26	133	0	254	161	0
Peak Hour Factor	0.92	0.92	0.92	0.92	0.92	0.92	0.92	0.92	0.92	0.92	0.92	0.92
Percent Heavy Veh, %	1	1	1	1	1	1	8	10	10	3	9	5
Cap, veh/h	184	269		140	411		487	380		645	601	
Arrive On Green	0.20	0.22	0.00	0.20	0.22	0.00	0.05	0.23	0.00	0.18	0.36	0.00
Sat Flow, veh/h	381	1224	0	228	1870	0	1586	1637	0	1674	1674	1466
Grp Volume(v), veh/h	233	0	0	182	0	0	26	133	0	254	161	0
Grp Sat Flow(s),veh/h/ln	1605	0	0	2098	0	0	1586	1637	0	1674	1674	1466
Q Serve(g_s), s	2.8	0.0	0.0	0.0	0.0	0.0	0.6	3.2	0.0	4.6	3.2	0.0
Cycle Q Clear(g_c), s	6.2	0.0	0.0	3.4	0.0	0.0	0.6	3.2	0.0	4.6	3.2	0.0
Prop In Lane	0.31		0.00	0.18		0.00	1.00		0.00	1.00		1.00
Lane Grp Cap(c), veh/h	419	0		507	0		487	380		645	601	
V/C Ratio(X)	0.56	0.00		0.36	0.00		0.05	0.35		0.39	0.27	
Avail Cap(c_a), veh/h	1112	0		1408	0		1108	1210		1088	1237	
HCM Platoon Ratio	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
Upstream Filter(I)	1.00	0.00	0.00	1.00	0.00	0.00	1.00	1.00	0.00	1.00	1.00	0.00
Uniform Delay (d), s/veh	16.9	0.0	0.0	15.8	0.0	0.0	12.3	15.2	0.0	8.7	10.8	0.0
Incr Delay (d2), s/veh	1.6	0.0	0.0	0.6	0.0	0.0	0.1	0.8	0.0	0.6	0.3	0.0
Initial Q Delay(d3),s/veh	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
%ile BackOfQ(50%),veh/In	2.2	0.0	0.0	1.6	0.0	0.0	0.2	1.0	0.0	1.3	1.0	0.0
Unsig. Movement Delay, s/veh												
LnGrp Delay(d),s/veh	18.5	0.0	0.0	16.4	0.0	0.0	12.4	16.0	0.0	9.3	11.1	0.0
LnGrp LOS	В	А		В	А		В	В		A	В	
Approach Vol, veh/h		233	А		182	А		159	А		415	A
Approach Delay, s/veh		18.5			16.4			15.4			10.0	
Approach LOS		В			В			В			А	
Timer - Assigned Phs	1	2		4	5	6		8				
Phs Duration (G+Y+Rc), s	14.5	17.0		15.9	8.4	23.0		15.9				
Change Period (Y+Rc), s	7.0	7.0		6.5	7.0	7.0		6.5				
Max Green Setting (Gmax), s	20.0	34.0		31.0	20.0	34.0		31.0				
Max Q Clear Time (g_c+I1), s	6.6	5.2		8.2	2.6	5.2		5.4				
Green Ext Time (p_c), s	1.1	0.6		1.2	0.0	0.8		0.9				
Intersection Summary												
HCM 6th Ctrl Delay			14.1									
HCM 6th LOS			В									

#### Notes

Unsignalized Delay for [NBR, EBR, WBR, SBR] is excluded from calculations of the approach delay and intersection delay.

# · \* + + \* \* \* \* \* \* \* \* \* \* \*

Movement EBL EBT EBR WBL W	BT WBR NBL	NBT NBR SBL	SBT SBR	
Lane Configurations		ላሴ ካ	<b>#†</b>	
Traffic Volume (veh/h) 85 1 128 0	0 0 0	319 161 126	316 0	
Future Volume (veh/h) 85 1 128 0	0 0 0	319 161 126	316 0	
Initial Q (Qb), veh 0 0 0	0	0 0 0	0 0	
Ped-Bike Adj(A_pbT) 1.00 1.00	1.00	1.00 1.00	1.00	
Parking Bus, Adj 1.00 1.00 1.00	1.00	1.00 1.00 1.00	1.00 1.00	
Work Zone On Approach No		No	No	
Adj Sat Flow, veh/h/ln 1878 1949 1878	0	1694 1694 1300	1812 0	
Adj Flow Rate, veh/h 96 1 144	0	358 181 142	355 0	
Peak Hour Factor 0.89 0.89 0.89	0.89	0.89 0.89 0.89	0.89 0.89	
Percent Heavy Veh, % 5 0 5	0	4 4 43	7 0	
Cap, veh/h 239 2 207	0	1201 597 497	2514 0	
Arrive On Green 0.12 0.13 0.13	0.00	0.58 0.56 0.03	0.24 0.00	
Sat Flow, veh/h 1838 19 1591	0	2166 1035 1238	3534 0	
Grp Volume(v), veh/h 97 0 144	0	275 264 142	355 0	
Grp Sat Flow(s),veh/h/ln1857 0 1591	0	1609 1507 1238	1722 0	
Q Serve(g_s), s 3.4 0.0 6.1	0.0	6.1 6.4 2.8	5.7 0.0	
Cycle Q Clear(g_c), s 3.4 0.0 6.1	0.0	6.1 6.4 2.8	5.7 0.0	
Prop In Lane 0.99 1.00	0.00	0.69 1.00	0.00	
Lane Grp Cap(c), veh/h 241 0 207	0	928 870 497	2514 0	
V/C Ratio(X) 0.40 0.00 0.70	0.00	0.30 0.30 0.29	0.14 0.00	
Avail Cap(c_a), veh/h 271 0 232	0	928 870 643	2514 0	
HCM Platoon Ratio 1.00 1.00 1.00	1.00	1.00 1.00 0.33	0.33 1.00	
Upstream Filter(I) 1.00 0.00 1.00	0.00	1.00 1.00 0.96	0.96 0.00	
Uniform Delay (d), s/veh 28.4 0.0 29.1	0.0	7.6 7.8 4.8	9.3 0.0	
Incr Delay (d2), s/veh 1.1 0.0 7.7	0.0	0.8 0.9 0.3	0.1 0.0	
Initial Q Delay(d3),s/veh 0.0 0.0 0.0	0.0	0.0 0.0 0.0	0.0 0.0	
%ile BackOfQ(50%),veh/In1.4 0.0 2.5	0.0	1.9 1.9 0.5	1.5 0.0	
Unsig. Movement Delay, s/veh				
LnGrp Delay(d),s/veh 29.5 0.0 36.8	0.0	8.4 8.7 5.1	9.4 0.0	
LnGrp LOS C A D	Α	A A A	A A	
Approach Vol, veh/h 241		539	497	
Approach Delay, s/veh 33.9		8.5	8.2	
Approach LOS C		А	A	
Timer - Assigned Phs 1 2 4	6			
Phs Duration (G+Y+Rc), \$0.7 45.4 13.9	56.1			
Change Period (Y+Rc), s 6.0 6.0 * 5.8	6.0			
Max Green Setting (Gmat), © 30.0 * 9.2	49.0			
Max Q Clear Time (g_c+l14), & 8.4 8.1	7.7			
Green Ext Time (p_c), s 0.3 8.9 0.1	7.8			
Intersection Summary				
J				
HCM 6th Ctrl Delay 13.2				

#### Notes

\* HCM 6th computational engine requires equal clearance times for the phases crossing the barrier.

## **ノーション・**ー ヘ イ ノ シ ↓ イ

Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR	
Lane Configurations					्स	1	<u> </u>	- • • •			<b>≜</b> †⊅		
Traffic Volume (veh/h)	0	0	0	125	1	150	95	298	0	0	321	80	
Future Volume (veh/h)	0	0	0	125	1	150	95	298	0	0	321	80	
Initial Q (Qb), veh				0	0	0	0	0	0	0	0	0	
Ped-Bike Adj(A_pbT)				1.00		1.00	1.00		1.00	1.00		1.00	
Parking Bus, Adj				1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	
Work Zone On Approach	1				No			No			No		
Adj Sat Flow, veh/h/ln				1441	602	1441	1652	1427	0	0	1613	1613	
Adj Flow Rate, veh/h				137	1	165	104	327	0	0	353	88	
Peak Hour Factor				0.91	0.91	0.91	0.91	0.91	0.91	0.91	0.91	0.91	
Percent Heavy Veh, %				41	100	41	7	23	0	0	21	21	
Cap, veh/h				115	1	246	578	1782	0	0	1242	306	
Arrive On Green				0.19	0.20	0.20	0.15	1.00	0.00	0.00	0.51	0.50	
Sat Flow, veh/h				569	4	1221	1573	2782	0	0	2518	600	
Grp Volume(v), veh/h				138	0	165	104	327	0	0	220	221	
Grp Sat Flow(s), veh/h/ln				573	0	1221	1573	1356	0	0	1533	1504	
Q Serve(g_s), s				14.1	0.0	8.7	1.9	0.0	0.0	0.0	5.8	6.0	
Cycle Q Clear(g_c), s				14.1	0.0	8.7	1.9	0.0	0.0	0.0	5.8	6.0	
Prop In Lane				0.99		1.00	1.00		0.00	0.00		0.40	
Lane Grp Cap(c), veh/h				115	0	246	578	1782	0	0	781	766	
V/C Ratio(X)				1.20	0.00	0.67	0.18	0.18	0.00	0.00	0.28	0.29	
Avail Cap(c_a), veh/h				115	0	246	683	1782	0	0	781	766	
HCM Platoon Ratio				1.00	1.00	1.00	2.00	2.00	1.00	1.00	1.00	1.00	
Upstream Filter(I)				1.00	0.00	1.00	0.95	0.95	0.00	0.00	1.00	1.00	
Uniform Delay (d), s/veh				28.4	0.0	25.8	5.6	0.0	0.0	0.0	9.8	10.0	
Incr Delay (d2), s/veh				145.6	0.0	6.9	0.1	0.2	0.0	0.0	0.9	0.9	
Initial Q Delay(d3),s/veh				0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
%ile BackOfQ(50%),veh/	/ln			6.4	0.0	2.7	0.5	0.1	0.0	0.0	1.8	1.9	
Unsig. Movement Delay,	s/veh												
LnGrp Delay(d),s/veh				174.0	0.0	32.7	5.7	0.2	0.0	0.0	10.7	10.9	
LnGrp LOS				F	Α	С	Α	Α	А	Α	В	В	
Approach Vol, veh/h					303			431			441		
Approach Delay, s/veh					97.1			1.5			10.8		
Approach LOS					F			А			В		
Timer - Assigned Phs	1	2		4		6							
Phs Duration (G+Y+Rc),	\$0.3	40.7		19.0		51.0							
Change Period (Y+Rc), s	6.0	6.0		* 5.9		6.0							
Max Green Setting (Gma	ax <b>9</b> , <b>G</b>	30.0		* 13		45.0							
Max Q Clear Time (g_c+	113),95	8.0		16.1		2.0							
Green Ext Time (p_c), s	0.1	7.3		0.0		7.3							
Intersection Summary													
HCM 6th Ctrl Delay			29.7										
HCM 6th LOS			С										
Timer - Assigned Phs Phs Duration (G+Y+Rc), Change Period (Y+Rc), s Max Green Setting (Gma Max Q Clear Time (g_c+ Green Ext Time (p_c), s Intersection Summary HCM 6th Ctrl Delay HCM 6th LOS	1 \$0.3 \$ 6.0 ax9, & 113,9\$ 0.1	2 40.7 6.0 30.0 8.0 7.3	29.7 C	4 19.0 * 5.9 * 13 16.1 0.0		6 51.0 6.0 45.0 2.0 7.3							

#### Notes

\* HCM 6th computational engine requires equal clearance times for the phases crossing the barrier.

Intersection						
Int Delay, s/veh	0.2					
		FDT	WDT			
Movement	FRF	FRI	WRI	WBK	SBL	SBR
Lane Configurations		- सी	- î>		۰¥	
Traffic Vol, veh/h	13	493	385	9	4	1
Future Vol, veh/h	13	493	385	9	4	1
Conflicting Peds, #/hr	0	0	0	0	0	0
Sign Control	Free	Free	Free	Free	Stop	Stop
RT Channelized	-	None	-	None	-	None
Storage Length	-	-	-	-	0	-
Veh in Median Storage,	# -	0	0	-	0	-
Grade, %	-	-9	9	-	-10	-
Peak Hour Factor	77	77	77	77	77	77
Heavy Vehicles, %	0	2	2	0	25	0
Mvmt Flow	17	640	500	12	5	1

Major/Minor	Major1	Ν	/lajor2	[	Vinor2	
Conflicting Flow All	512	0	-	0	1180	506
Stage 1	-	-	-	-	506	-
Stage 2	-	-	-	-	674	-
Critical Hdwy	4.3	-	-	-	4.65	5.2
Critical Hdwy Stg 1	-	-	-	-	3.65	-
Critical Hdwy Stg 2	-	-	-	-	3.65	-
Follow-up Hdwy	3	-	-	-	3	3.1
Pot Cap-1 Maneuver	800	-	-	-	411	690
Stage 1	-	-	-	-	880	-
Stage 2	-	-	-	-	792	-
Platoon blocked, %		-	-	-		
Mov Cap-1 Maneuver	. 800	-	-	-	397	690
Mov Cap-2 Maneuver	· -	-	-	-	397	-
Stage 1	-	-	-	-	851	-
Stage 2	-	-	-	-	792	-
Approach	EB		WB		SB	
HCM Control Delay, s	6 0.2		0		13.4	
HCM LOS					В	
Minor Lane/Major Mvi	mt	EBL	EBT	WBT	WBR S	SBLn1
Capacity (veh/h)		800	-	-	-	434
HCM Lane V/C Ratio		0.021	-	-	-	0.015
HCM Control Delay (s	5)	9.6	0	-	-	13.4
HCM Lane LOS		А	А	-	-	В
HCM 95th %tile Q(vel	h)	0.1	-	-	-	0

#### Intersection

Int Delay, s/veh

Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations		\$						<b>∱î</b> ≽			-4†	
Traffic Vol, veh/h	79	1	44	0	0	0	0	204	72	9	145	0
Future Vol, veh/h	79	1	44	0	0	0	0	204	72	9	145	0
Conflicting Peds, #/hr	0	0	0	0	0	0	0	0	0	0	0	0
Sign Control	Stop	Stop	Stop	Stop	Stop	Stop	Free	Free	Free	Free	Free	Free
RT Channelized	-	-	None	-	-	None	-	-	Yield	-	-	None
Storage Length	-	-	-	-	-	-	-	-	-	-	-	-
Veh in Median Storage,	# -	0	-	-	16979	-	-	0	-	-	0	-
Grade, %	-	-3	-	-	-2	-	-	1	-	-	-1	-
Peak Hour Factor	85	85	85	85	85	85	85	85	85	85	85	85
Heavy Vehicles, %	8	0	11	0	0	0	0	6	7	22	7	0
Mvmt Flow	93	1	52	0	0	0	0	240	85	11	171	0

Major/Minor	Minor2			Major1		Ν	lajor2			
Conflicting Flow All	313	433	86	-	0	0	240	0	0	
Stage 1	193	193	-	-	-	-	-	-	-	
Stage 2	120	240	-	-	-	-	-	-	-	
Critical Hdwy	6.36	5.9	6.82	-	-	-	4.3	-	-	
Critical Hdwy Stg 1	5.36	4.9	-	-	-	-	-	-	-	
Critical Hdwy Stg 2	5.36	4.9	-	-	-	-	-	-	-	
Follow-up Hdwy	3	4	3.1	-	-	-	3	-	-	
Pot Cap-1 Maneuver	784	558	1024	0	-	-	994	-	0	
Stage 1	975	769	-	0	-	-	-	-	0	
Stage 2	1055	740	-	0	-	-	-	-	0	
Platoon blocked, %					-	-		-		
Mov Cap-1 Maneuver	775	0	1024	-	-	-	994	-	-	
Mov Cap-2 Maneuver	775	0	-	-	-	-	-	-	-	
Stage 1	975	0	-	-	-	-	-	-	-	
Stage 2	1042	0	-	-	-	-	-	-	-	
Approach	EB			NB			SB			
HCM Control Delay, s	10.1			0			0.5			

HCM LOS B

Minor Lane/Major Mvmt	NBT	NBR	EBLn1	SBL	SBT	
Capacity (veh/h)	-	-	849	994	-	
HCM Lane V/C Ratio	-	-	0.172	0.011	-	
HCM Control Delay (s)	-	-	10.1	8.7	0	
HCM Lane LOS	-	-	В	А	А	
HCM 95th %tile Q(veh)	-	-	0.6	0	-	

#### Intersection

Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations					÷			-4†			<b>∱î</b> ≽	
Traffic Vol, veh/h	0	0	0	59	1	9	96	185	0	0	92	88
Future Vol, veh/h	0	0	0	59	1	9	96	185	0	0	92	88
Conflicting Peds, #/hr	0	0	0	0	0	0	0	0	0	0	0	0
Sign Control	Stop	Stop	Stop	Stop	Stop	Stop	Free	Free	Free	Free	Free	Free
RT Channelized	-	-	None	-	-	None	-	-	None	-	-	Yield
Storage Length	-	-	-	-	-	-	-	-	-	-	-	-
Veh in Median Storage,	# -	2	-	-	0	-	-	0	-	-	0	-
Grade, %	-	-3	-	-	-1	-	-	7	-	-	0	-
Peak Hour Factor	87	87	87	87	87	87	87	87	87	87	87	87
Heavy Vehicles, %	0	0	0	8	0	11	7	8	0	0	5	15
Mvmt Flow	0	0	0	68	1	10	110	213	0	0	106	101

Major/Minor	Mino	1		Major1		N	lajor2			
Conflicting Flow All	48	6 53	9 107	106	0	-	-	-	0	
Stage 1	43	3 43	3 -	-	-	-	-	-	-	
Stage 2	Į	3 10	6 -	-	-	-	-	-	-	
Critical Hdwy	6.	6 6	3 7.02	4.3	-	-	-	-	-	
Critical Hdwy Stg 1	5.7	6 5.	3 -	-	-	-	-	-	-	
Critical Hdwy Stg 2	5.7	6 5.	3 -	-	-	-	-	-	-	
Follow-up Hdwy		3	4 3.1	3	-	-	-	-	-	
Pot Cap-1 Maneuver	58	6 46	6 987	1105	-	0	0	-	-	
Stage 1	71	5 59	9 -	-	-	0	0	-	-	
Stage 2	112	7 81	6 -	-	-	0	0	-	-	
Platoon blocked, %					-			-	-	
Mov Cap-1 Maneuver	52	0	0 987	1105	-	-	-	-	-	
Mov Cap-2 Maneuver	52	0	0 -	-	-	-	-	-	-	
Stage 1	63	4	0 -	-	-	-	-	-	-	
Stage 2	112	7	0 -	-	-	-	-	-	-	
Approach	N	В		NB			SB			
HCM Control Delay, s	12	6		3.1			0			
HCM LOS		В								
Minor Lane/Major Mvmt	NBL NBTWBL	1 SB	t SBR							

Capacity (veh/h)	1105	- 555	-	-
HCM Lane V/C Ratio	0.1	- 0.143	-	-
HCM Control Delay (s)	8.6	0.2 12.6	-	-
HCM Lane LOS	А	A B	-	-
HCM 95th %tile Q(veh)	0.3	- 0.5	-	-

## Intersection Delay, s/veh 7.5 Intersection LOS A

Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR
Lane Configurations		4			4Î			र्स			ef 👘	
Traffic Vol, veh/h	0	49	17	0	90	15	17	6	0	0	14	3
Future Vol, veh/h	0	49	17	0	90	15	17	6	0	0	14	3
Peak Hour Factor	0.93	0.93	0.93	0.93	0.93	0.93	0.93	0.93	0.93	0.93	0.93	0.93
Heavy Vehicles, %	0	0	10	0	4	0	12	0	0	0	0	0
Mvmt Flow	0	53	18	0	97	16	18	6	0	0	15	3
Number of Lanes	0	1	0	0	1	0	0	1	0	0	1	0
Approach		EB			WB		NB				SB	
Opposing Approach		WB			EB		SB				NB	
Opposing Lanes		1			1		1				1	
Conflicting Approach Left		SB			NB		EB				WB	
Conflicting Lanes Left		1			1		1				1	
Conflicting Approach Right		NB			SB		WB				EB	
Conflicting Lanes Right		1			1		1				1	
HCM Control Delay		7.3			7.6		7.8				7.3	
HCM LOS		А			А		А				А	

Lane	NBLn1	EBLn1	WBLn1	SBLn1	
Vol Left, %	74%	0%	0%	0%	
Vol Thru, %	26%	74%	86%	82%	
Vol Right, %	0%	26%	14%	18%	
Sign Control	Stop	Stop	Stop	Stop	
Traffic Vol by Lane	23	66	105	17	
LT Vol	17	0	0	0	
Through Vol	6	49	90	14	
RT Vol	0	17	15	3	
Lane Flow Rate	25	71	113	18	
Geometry Grp	1	1	1	1	
Degree of Util (X)	0.031	0.077	0.126	0.021	
Departure Headway (Hd)	4.583	3.904	4.01	4.129	
Convergence, Y/N	Yes	Yes	Yes	Yes	
Сар	772	911	891	855	
Service Time	2.664	1.954	2.05	2.214	
HCM Lane V/C Ratio	0.032	0.078	0.127	0.021	
HCM Control Delay	7.8	7.3	7.6	7.3	
HCM Lane LOS	А	А	А	А	
HCM 95th-tile Q	0.1	0.2	0.4	0.1	

0.1					
EBT	EBR	WBL	WBT	NBL	NBR
4			- <del>द</del>	۰¥	
162	6	1	207	2	1
162	6	1	207	2	1
0	0	0	0	0	0
Free	Free	Free	Free	Stop	Stop
-	None	-	None	-	None
-	-	-	-	0	-
# 0	-	-	0	0	-
2	-	-	-3	-5	-
83	83	83	83	83	83
9	0	0	8	0	0
195	7	1	249	2	1
	0.1 EBT 162 162 0 Free - - - # 0 2 83 9 195	0.1           EBT         EBR           162         6           162         6           0         0           Free         Free           Free         None           -         -           # 0         -           2         -           83         83           9         0           195         7	0.1 EBT EBR WBL 162 6 11 162 6 11 162 6 11 162 6 11 0 0 0 Free Free Free - None - Free - # 0 - 3 - 4 0 - 3 - 4 0  5 - 4 0  5 - 5 - 6 - 7 - 8 - 8 - 8 - 8 - 8 - 9 0 0 195 7 1	0.1       EBR       WBL       WBT         EBT       EBR       WBL       WBT         162       6       1       207         162       6       1       207         162       6       1       207         0       0       0       0         Free       Free       Free       Free         None       -       None         -       -       -       -         # 0       -       -       -         # 0       -       -       -         # 0       -       -       -         # 0       -       -       -         # 0       -       -       -         # 0       -       -       -         # 0       -       -       -         # 0       -       -       -         # 0       -       -       -         # 0       -       -       -         # 0       -       -       -         # 0       -       -       -         # 0       -       -       -         # 0       0       8	0.1       EBR       WBL       WBT       NBL         EBT       EBR       WBL       WBT       NBL         162       6       1       207       2         162       6       1       207       2         162       6       1       207       2         0       0       0       0       0         Free       Free       Free       Stop         -       None       -       0         -       0       0       0       0         #0       -       7       0       0         #0       -       -       0       0         #0       -       -       0       0         #0       -       -       0       0         #0       -       -       0       0         #10       -       -       0       0         #10       -       -       0       0         #2       -       -       -       0         #2       -       -       -       0         #3       83       83       83       83         #3

Major/Minor	Major1	Ν	Aajor2		Vinor1		
Conflicting Flow All	0	0	202	0	450	199	
Stage 1	-		-	-	199	-	
Stage 2	-	-	-	-	251	-	
Critical Hdwy	-	-	4.9	-	8.1	6.4	
Critical Hdwy Stg 1	-	-	-	-	4.4	-	
Critical Hdwy Stg 2	-		-	-	4.4	-	
Follow-up Hdwy	-	-	3.5	-	3	3.4	
Pot Cap-1 Maneuver	-	-	861	-	523	815	
Stage 1	-	-	-	-	1021	-	
Stage 2	-	-	-	-	979	-	
Platoon blocked, %	-	-		-			
Mov Cap-1 Maneuve	r -	-	861	-	522	815	
Mov Cap-2 Maneuve	r -	-	-	-	522	-	
Stage 1	-	-	-	-	1021	-	
Stage 2	-	-	-	-	978	-	
Approach	EB	i i	WB		NB		
HCM Control Delay, s	s 0		0		11.1		
HCM LOS					В		
Minor Lane/Major Mv	mt	NBLn1	EBT	EBR	WBL	WBT	
Capacity (veh/h)		593	-	-	861	-	
HCM Lane V/C Ratio		0.006	-	-	0.001	-	
HCM Control Delay (s	s)	11.1	-	-	9.2	0	

В

0

-

-

-

-

А

0

А

-

HCM Lane LOS

HCM 95th %tile Q(veh)

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 NB Oscar Road to Baum Pump Sta From/To Boggs Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 6.0 ft % Trucks and Dusce Lane width 11.0 ft % Trucks crawling 0.0 Geoment length 1.0 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 No-passing zones 100 13 % % mi/hr 00 - mi % No-passing zones 100 % - % Access point density 13 /mi Up/down Analysis direction volume, Vd 220 veh/h Opposing direction volume, Vo 403 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.2 1.8 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.865 0.906 0.80 Grade adj. factor,(note-1) fg 0.95 388 pc/h Directional flow rate, (note-2) vi 571 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 3.3 mi/h Free-flow speed, FFSd 56.3 mi/h mi/h Adjustment for no-passing zones, fnp 2.1 Average travel speed, ATSd 46.8 mi/h Percent Free Flow Speed, PFFS 83.1 %

Percent Time-Spent-Follow:	ing			
Direction Analysis(d) PCE for trucks, ET 1.7		Oppo	osing 1.4	(0)
PCE for RVs, ER1.0Heavy-vehicle adjustment factor, fHV0.917Grade adjustment factor, (note-1) fg0.83Directional flow rate (note-2) vi353	~/h		1.0 0.951 0.95 544	nc/h
Base percent time-spent-following,(note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	41.7 36.4 56.0	00	511	20/11
Level of Service and Other Performa	ance Me	easure	es	
Level of service, LOS	С			
Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60	0.16 67 220	vel vel	h-mi h-mi	
Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	1635 1700 1635	vel vel vel vel	h/h h/h h/h h/h	
Passing Lane Analysis_				
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	Lu -	1.0 - 46.8 56.0 C	mi mi mi/h
Average Travel Speed with Pass:	ing Lar	ne		
Downstream length of two-lane highway within effect length of passing lane for average travel speed	tive d, Lde	-	_	mi
Length of two-lane highway downstream of effective length of the passing lane for average travel s Adj. factor for the effect of passing lane	speed,	Ld ·	_	mi
on average speed, fpl Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFF	FSpl	-	- - 0.0	0 0
Percent Time-Spent-Following with H	Passing	g Lane	e	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followin Length of two-lane highway downstream of effective	tive le ng, Lde length	ength e -	_	mi
the passing lane for percent time-spent-follow: Adj. factor for the effect of passing lane on percent time-spent-following, fpl	ing, Lo	- 10 - - 1	_	mi
Percent time-spent-following including passing lane, PTSFpl			_	00
Level of Service and Other Performance Measur	res wit	ch Pas	ssing	Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	E -	vel	h-h	
Bicycle Level of Service	e			
Posted speed limit, Sp	55			
---	-------			
Percent of segment with occupied on-highway parking	0			
Pavement rating, P	3			
Flow rate in outside lane, vOL	268.3			
Effective width of outside lane, We	23.00			
Effective speed factor, St	4.79			
Bicycle LOS Score, BLOS	7.02			
Bicycle LOS	F			

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodPM Peak 1/30/2020 Highway SR 28 NB Oscar Road to Baum Pump Sta From/To Boggs Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 6.0 ft % Trucks and Dusce Lane width 11.0 ft % Trucks crawling 0.0 Comment length 1.0 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 No-passing zones 100 13 % % mi/hr % mi % No-passing zones 100 % % Access point density 13 /mi Up/down \_ Analysis direction volume, Vd 542 veh/h Opposing direction volume, Vo 310 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 1.7 2.1 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.960 0.938 Grade adj. factor,(note-1) fg 0.97 0.85 619 pc/h Directional flow rate, (note-2) vi 414 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed,(note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 3.3 mi/h Free-flow speed, FFSd 56.3 mi/h mi/h Adjustment for no-passing zones, fnp 3.0 Average travel speed, ATSd 45.3 mi/h Percent Free Flow Speed, PFFS 80.4 %

Percent Time-Spent-Followi	ing			
DirectionAnalysis(d)PCE for trucks, ET1.2PCE for RVs, ER1.0Heavy-webicle adjustment factorfHV0.988		Оррс	sing 1.6 1.0	( 0 )
Grade adjustment factor, (note-1) fg 0.97 Directional flow rate (note-2) vi 602 pc	۲/h		0.87	pc/h
Base percent time-spent-following, (note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	55.9 34.7 76.9	olo		PC/ 11
Level of Service and Other Performa	ance Me	easure	s	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS CdATS	D 0.35 144 542 3.2 1669	veh veh veh	1-mi 1-mi 1-h	
Capacity from PTSF, CdPTSF Directional Capacity	1700 1669	veh veh	n/h n/h	
Passing Lane Analysis_				
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	1 Lu - 4 7 E	0 	mi mi mi/h
Average Travel Speed with Passi	ing Lar	ne		
Downstream length of two-lane highway within effect length of passing lane for average travel speed	cive d, Lde	_		mi
Length of the passing lane for average travel s Adj. factor for the effect of passing lane	speed,	Ld -	-	mi
on average speed, fpl Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFF	FSpl	- - C	.0	8
Percent Time-Spent-Following with F	Passing	g Lane	è	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followir Length of two-lane highway downstream of effective	tive le ng, Lde length	ength e - n of		mi
the passing lane for percent time-spent-followi Adj. factor for the effect of passing lane on percent time-spent-following, fpl	ing, Lo	1 -		mi
Percent time-spent-following including passing lane, PTSFpl		-	-	00
Level of Service and Other Performance Measur	res wit	ch Pas	sing	Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	E -	veh	ı-h	
Bicycle Level of Service	e			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	576.6
Effective width of outside lane, We	23.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	4.65
Bicycle LOS	Е

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 SB Oscar Road to Baum Pump Sta From/To Boggs Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 6.0 ft % Trucks and Dusce Lane width 11.0 ft % Trucks crawling 0.0 Comment length 1.0 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 No-passing zones 100 13 % % mi/hr 00 - mi % No-passing zones 100 % - % Access point density 13 /mi Up/down Analysis direction volume, Vd 403 veh/h Opposing direction volume, Vo 220 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 1.9 2.2 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.903 0.874 0.92 Grade adj. factor,(note-1) fg 0.78 527 pc/h Directional flow rate, (note-2) vi 351 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed,(note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 3.3 mi/h Free-flow speed, FFSd 56.3 mi/h 3.3 mi/h Adjustment for no-passing zones, fnp Average travel speed, ATSd 46.2 mi/h Percent Free Flow Speed, PFFS 82.0 %

Percent Time-Spent-Follows	ing			
Direction Analysis(d)		Opp	osing	( 0 )
PCE for trucks, ET 1.4			1.7	
PCE for RVS, ER			1.0	
Heavy-vehicle adjustment factor, fHV 0.954			0.923	3
Grade adjustment factor, (note-1) ig 0.92	- / la		0.82	
Directional flow rate, (note-2) vi 499 pc	2/n 40 0	0	316	pc/n
Base percent time-spent-following, (note-4) BPTSFd	48.8	6		
Adjustment for no-passing zones, inp	30.4 72 2	Ŷ		
Percent time-spent-torrowing, Pisra	12.2	6		
Level of Service and Other Performa	ance Me	easur	res	
Level of service, LOS	D			
Volume to capacity ratio, v/c	0.27			
Peak 15-min vehicle-miles of travel, VMT15	110	ve	eh-mi	
Peak-hour vehicle-miles of travel, VMT60	403	ve	eh-mi	
Peak 15-min total travel time, TT15	2.4	ve	eh-h	
Capacity from ATS, CdATS	1641	ve	eh/h	
Capacity from PTSF, CdPTSF	1700	ve	eh/h	
Directional Capacity	1641	ve	eh/h	
Passing Lane Analysis_				
Total length of analysis segment, Lt			1.0	mi
Length of two-lane highway upstream of the passing	lane,	Lu	-	mi
Length of passing lane including tapers, Lpl			-	mi
Average travel speed, ATSd (from above)			46.2	mi/h
Percent time-spent-following, PTSFd (from above)			72.2	
Level of service, LOSd (from above)			D	
Average Travel Speed with Passi	ing Lan	ie		
De materie langth of the lang bight of ithin offer				
Downstream length of two-lane highway within effect	live			
length of passing lane for average travel speed	ı, Lae		-	mı
Length of two-lane nighway downstream of effective		⊤ -1		
length of the passing lane for average travel s	speea,	Lа	-	mı
Adj. factor for the effect of passing lane				
on average speed, Ipl			-	
Average travel speed including passing lane, ATSpi	10-1		-	٥.
Percent free flow speed including passing lane, PF	Spi		0.0	6
Percent Time-Spent-Following with H	Passing	l Lar	ne	
Downstream length of two-lane highway within effect	ive le	na+r	ı	
of passing lane for percent time-spent-following	na I.de	,	_	mi
Length of two-lane highway downstream of effective	length	of		
the passing lane for percent time-spent-followi	ina I.d		_	mi
Adj factor for the effect of passing lane	Liig, 10			
on percent time-spent-following fnl			_	
Dergent time-spent-following				
including passing lane, PTSFpl			-	00
Level of Service and Other Performance Measur	res wit	h Pa	assing	Lane
			2	
Level of service including passing lane, LOSpl	Е			
Peak 15-min total travel time, TT15	-	ve	eh-h	
Bicycle Level of Service	2			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	438.0
Effective width of outside lane, We	23.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	6.81
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodPM Peak 1/30/2020 Highway SR 28 SB Oscar Road to Baum Pump Sta From/To Boggs Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 6.0 ft % Trucks and Dusce Lane width 11.0 ft % Trucks crawling 0.0 Geoment length 1.0 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 No-passing zones 100 Peak hour factor, PHF 0.82 % 0.0 % 0.0 mi/hr % - mi % No-passing zones 100 % - % Access point density 13 /mi Up/down Analysis direction volume, Vd 310 veh/h Opposing direction volume, Vo 542 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.0 1.6 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.917 0.949 Grade adj. factor,(note-1) fg 0.88 0.98 468 pc/h Directional flow rate, (note-2) vi 711 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 3.3 mi/h Free-flow speed, FFSd 56.3 mi/h mi/h Adjustment for no-passing zones, fnp 1.6 Average travel speed, ATSd 45.6 mi/h Percent Free Flow Speed, PFFS 80.9 %

Percent Time-Spent-Follow:	ing		
Direction Analysis(d) PCE for trucks, ET 1.6 PCE for RVs, ER 1.0 Heavy-vehicle adjustment factor, fHV 0.949 Grade adjustment factor, (note-1) fg 0.89 Directional flow rate, (note-2) vi 448 pc Base percent time-spent-following, (note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	c/h 49.8 31.8 62.5	Oppos: 1 1 0 6 %	ing (o) .0 .000 .98 74 pc/h
Level of Service and Other Performa	ance Me	easures_	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	C 0.23 95 310 2.1 1656 1700 1656	veh-t veh-t veh-l veh/l veh/l veh/l	ni ni n n
Passing Lane Analysis_			
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	1.0 Lu - 45 62 C	0 mi mi mi .6 mi/h .5
Average Travel Speed with Pass:	ing Lar	ne	
Downstream length of two-lane highway within effect length of passing lane for average travel speed Length of two-lane highway downstream of effective	tive d, Lde	_	mi
length of the passing lane for average travel s Adj. factor for the effect of passing lane	speed,	Ld -	mi
Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFR	FSpl	- 0.0	) <del>ද</del>
Percent Time-Spent-Following with I	Passing	g Lane	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followin Length of two-lane highway downstream of effective	tive le ng, Lde lengtł	ength e - n of	mi
the passing lane for percent time-spent-follow: Adj. factor for the effect of passing lane on percent time-spent-following, fpl	ing, Lo	d – –	mi
Percent time-spent-following including passing lane, PTSFpl		_	8
Level of Service and Other Performance Measur	res wit	ch Pass:	ing Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	E -	veh-l	n
Bicycle Level of Service	e		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	378.0
Effective width of outside lane, We	23.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	5.49
Bicycle LOS	Е

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 NB Between Distant and South Beth From/To Jurisdiction Mahoning Twnshp, Armstrong Co Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 6.0 ft % Trucks and Dusce Lane width 11.0 ft % Trucks crawling 0.0 Comment length 0.5 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 No-passing zones 100 10 % % mi/hr 00 - mi % No-passing zones 100 % - % Access point density 10 /mi Up/down Analysis direction volume, Vd 285 veh/h Opposing direction volume, Vo 232 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.1 2.2 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.910 0.903 Grade adj. factor,(note-1) fg 0.85 0.81 433 pc/h Directional flow rate, (note-2) vi 373 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed,(note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 2.5 mi/h Free-flow speed, FFSd 57.1 mi/h mi/h Adjustment for no-passing zones, fnp 3.4 47.5 Average travel speed, ATSd mi/h Percent Free Flow Speed, PFFS 83.1 %

Percent Time-Spent-Followi	ng		
Direction Analysis(d) PCE for trucks, ET 1.6		Opposing 1.7	(0)
PCE for RVs, ER1.0Heavy-vehicle adjustment factor, fHV0.949Grade adjustment factor, (note-1) fg0.87Dimensional flam mate (mate 2) min406	- / h	1.0 0.94 0.84	1
Base percent time-spent-following, (note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	42.7 46.8 68.0	345 % %	pe/n
Level of Service and Other Performa	ance Me	easures	
	D		
Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	0.20 42 143 0.9 1656 1700	veh-mi veh-mi veh-h veh/h veh/h veh/h	
	1050	V C11/ 11	
Passing Lane Analysis_			······
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	0.5 Lu – 47.5 68.0 D	mi mi mi/h
Average Travel Speed with Passi	lng Lar	1e	
Downstream length of two-lane highway within effect	ive		
length of passing lane for average travel speed Length of two-lane highway downstream of effective	l, Lde	_	mi
length of the passing lane for average travel s Adj. factor for the effect of passing lane	speed,	Ld –	mi
on average speed, fpl Average travel speed including passing lane, ATSpl		-	
Percent free flow speed including passing lane, PFF	Spl	0.0	8
Percent Time-Spent-Following with F	Passing	g Lane	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followin Length of two-lane highway downstream of effective	ive le ng, Lde length	ength e - n of	mi
the passing lane for percent time-spent-followi Adj. factor for the effect of passing lane	ing, Lo	d –	mi
Percent time-spent-following including passing lane PTSEpl		_	<u>ş</u>
Level of Service and Other Derformance Measur	reg wit	h Passing	Lane
Bever of Service and Other Performance Measur	.co wil	LII FABBIIIS	Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	E -	veh-h	
Bicycle Level of Service	<u> </u>		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	335.3
Effective width of outside lane, We	23.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	5.43
Bicycle LOS	Е

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodPM Peak 1/30/2020 Highway SR 28 NB Between Distant and South Beth From/To Jurisdiction Mahoning Twnshp, Armstrong Co Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 6.0 ft % Trucks and Duber Lane width 11.0 ft % Trucks crawling 0.0 Geoment length 0.5 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 No-passing zones 100 10 % % mi/hr 00 - mi % No-passing zones 100 % - % Access point density 10 /mi Up/down Analysis direction volume, Vd 332 veh/h Opposing direction volume, Vo 312 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.0 2.0 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.926 0.926 Grade adj. factor,(note-1) fg 0.88 0.87 463 pc/h Directional flow rate, (note-2) vi 440 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 2.5 mi/h Free-flow speed, FFSd 57.1 mi/h mi/h Adjustment for no-passing zones, fnp 3.0 Average travel speed, ATSd 47.1 mi/h Percent Free Flow Speed, PFFS 82.5 %

Percent Time-Spent-Followi	ng			
Direction Analysis(d) PCE for trucks, ET 1.6		Oppo	osing 1.6	( 0 )
PCE for RVs, ER1.0Heavy-vehicle adjustment factor, fHV0.954Grade adjustment factor, (note-1) fg0.89			1.0 0.954 0.88	
Directional flow rate, (note-2) vi 444 pc Base percent time-spent-following, (note-4) BPTSFd	c/h 46.0	olo	422	pc/h
Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	43.9 68.5	00		
Level of Service and Other Performa	ance Me	easure	es	
Level of service, LOS	D			
Volume to capacity ratio, v/c	0.23			
Peak 15-min vehicle-miles of travel, VMT15	47	veł	n-mi	
Peak-hour vehicle-miles of travel, VMT60	166	veł	n-mi	
Peak 15-min total travel time, TT15	1.0	veł	n-h	
Capacity from ATS, CdATS	1661	veł	n/h	
Capacity from PTSF, CdPTSF	1700	veł	n/h	
Directional Capacity	1661	veł	n/h	
Passing Lane Analysis_				
Total length of analysis segment Lt		(	05	mi
Length of two-lane highway unstream of the passing	lano	T.11 -	_	mi
Longth of pagaing lang ingluding taporg. In	ranc,	шu		mi
Decrease travel aread DTCd (from chous)		-	- 1 - 1	mi /b
Average traver speed, Also (from above)		2	±/.⊥	111 / 11
Percent time-spent-following, PTSFd (from above)		t	08.5	
Level of service, LOSd (from above)		1		
Average Travel Speed with Passi	lng Lar	ne		
Downstream length of two-lane highway within effect	ive			
length of passing lane for average travel speed	l, Lde	-	-	mi
Length of two-lane highway downstream of effective		т -1		
length of the passing lane for average travel s	speea,	La -	-	mı
Adj. factor for the effect of passing lane				
on average speed, fpl		-	_	
Average travel speed including passing lane, ATSpl		-	-	
Percent free flow speed including passing lane, PFF	rSpl	(	0.0	00
Percent Time-Spent-Following with F	Passing	g Lane	e	
Downstream length of two-lane highway within effect	cive le	enath		
of passing lane for percent time-spent-followir	na. T.de	در	_	mi
Length of two-lane highway downstream of effective	lonath	- of		
the pagging lane for pergent time grant followi	na Id			mi
Add for the offert of percent lime-spent-10110W1	шу, шо	· -		1111
Auj. Lactor for the effect of passing lane				
on percent time-spent-tollowing, fpl		-	-	
Percent time-spent-following			_	۶.
including passing lane, pisrpi		-	-	6
Level of Service and Other Performance Measur	res wit	h Pas	ssing 1	Lane
Level of service including passing lane. LOSpl	Е			
Peak 15-min total travel time, TT15	-	vel	n-h	
Bicycle Level of Service	2			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	377.3
Effective width of outside lane, We	23.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	5.12
Bicycle LOS	Ε

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 SB Between Distant and South Beth From/To Jurisdiction Mahoning Twnshp, Armstrong Co Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 6.0 ft % Trucks and Dusce Lane width 11.0 ft % Trucks crawling 0.0 Comment length 0.5 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 No-passing zones 100 10 % % mi/hr 00 - mi % No-passing zones 100 % - % Access point density 10 /mi Up/down Analysis direction volume, Vd 232 veh/h Opposing direction volume, Vo 285 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.2 2.1 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.865 0.875 Grade adj. factor,(note-1) fg 0.79 0.83 357 pc/h Directional flow rate, (note-2) vi 413 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 2.5 mi/h Free-flow speed, FFSd 57.1 mi/h mi/h Adjustment for no-passing zones, fnp 3.2 Average travel speed, ATSd 47.9 mi/h Percent Free Flow Speed, PFFS 84.0 %

Percent Time-Spent-F	ollowing		
Direction Analysi PCE for trucks, ET 1.7	s(d)	Opposing 1.7	( 0 )
PCE for RVs, ER 1.0		1.0	
Heavy-vehicle adjustment factor, fHV 0.9	17	0.917	
Grade adjustment factor. (note-1) fg 0.8	2	0.85	
Directional flow rate (note-2) vi 325	- pc/h	385	pc/h
Page pergent time_spent_following (note_4) PD	PC/11 TCFA 36 1	205	20/11
Adjustment for no pagging gones for	10.1	0	
Adjustment for no-passing zones, inp	49.2	0,	
Percent time-spent-tottowing, Pisra	58.0	6	
Level of Service and Other Pe	rformance Mea	asures	
Level of service, LOS	С		
Volume to capacity ratio, v/c	0.15		
Peak 15-min vehicle-miles of travel. VMT15	31	veh-mi	
Deak-hour vehicle-miles of travel VMT60	116	veh-mi	
Dook 15 min totol travel time TT15		ven mi	
Generative from ATC Colored clime, 1115	1625	ven-n	
Capacity from AIS, CUAIS	1035	ven/n	
Capacity from PTSF, CdPTSF	1700	veh/h	
Directional Capacity	1635	veh/h	
Passing Lane Ana	lysis		
Total length of analyzic segment. It		0 5	mi
Ionath of two long bighters ungtreem of the ne	aging long T	0.5	
Length of two-lane highway upstream of the pa	ssing lane, l	_u –	m1
Length of passing lane including tapers, Lpl		-	mı
Average travel speed, ATSd (from above)		47.9	mi/h
Percent time-spent-following, PTSFd (from abo	ve)	58.6	
Level of service, LOSd (from above)		C	
Average Travel Speed with	Passing Lane	<u></u>	
De materie landth of the land birth of this			
Downstream length of two-lane highway within	errective		
length of passing lane for average travel	speed, Lde	-	mı
Length of two-lane highway downstream of effe	ctive		
length of the passing lane for average tr	avel speed, I	Ld -	mi
Adj. factor for the effect of passing lane			
on average speed, fpl		-	
Average travel speed including passing lane,	ATSpl	-	
Percent free flow speed including passing lan	e, PFFSpl	0.0	00
Percent Time-Spent-Following	with Passing	Lane	
Downstream length of two-lane highway within	effective ler	ngth	
of passing lane for percent time-spent-fo	llowing, Lde	-	mi
Length of two-lane highway downstream of effe	ctive length	of	
the passing lane for percent time-spent-f	ollowing, Ld	_	mi
Adj factor for the effect of passing lane	0110.1.1.9, 14		
on pergent time grant following fol			
Deuroph time ment falleuing, ipi		-	
including passing lane. PTSFpl		_	0
I and of Gaussian and Other Dauf	Meessee		- T
Level of Service and Other Performance	measures with	1 Passing	Lane
Level of service including passing lane, LOSp	1 E		
Peak 15-min total travel time, TT15	_	veh-h	
	oruico		
Bicycle Level Of S	етитсе		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	244.2
Effective width of outside lane, We	23.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	6.97
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodPM Peak 1/30/2020 Highway SR 28 SB Between Distant and South Beth From/To Jurisdiction Mahoning Twnshp, Armstrong Co Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 6.0 ft % Trucks and Dusc. Lane width 11.0 ft % Trucks crawling 0.0 Comment length 0.5 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 No-passing zones 100 10 % % mi/hr ~ - mi % No-passing zones 100 % - % Access point density 10 /mi Up/down Analysis direction volume, Vd 312 veh/h Opposing direction volume, Vo 332 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.0 2.0 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.962 0.962 0.87 Grade adj. factor,(note-1) fg 0.88 419 pc/h Directional flow rate, (note-2) vi 441 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 2.5 mi/h Free-flow speed, FFSd 57.1 mi/h mi/h Adjustment for no-passing zones, fnp 3.0 Average travel speed, ATSd 47.4 mi/h Percent Free Flow Speed, PFFS 83.1 %

Percent Time-Spent-Follow	ving			
Direction Analysis(d) PCE for trucks, ET 1.6		Opr	osing 1.6	( 0 )
PCE for RVs, ER1.0Heavy-vehicle adjustment factor, fHV0.977Conde adjustment factor, from 0.977			1.0 0.977	7
Directional flow rate, (note-1) ig 0.88 Directional flow rate, (note-2) vi 408 p	oc/h	0,	0.89 429	pc/h
Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	44.7 66.2	00		
Level of Service and Other Perform	nance Me	easur	res	
	D			
Level of service, LOS Volume to capacity ratio v/c	D 0 21			
Peak 15-min vehicle-miles of travel VMT15	44	Ve	∍h_mi	
Peak-hour vehicle-miles of travel. VMT60	156	VE	h-mi	
Peak 15-min total travel time, TT15	0.9	ve	≥h−h	
Capacity from ATS, CdATS	1680	ve	≥h/h	
Capacity from PTSF, CdPTSF	1700	ve	≥h/h	
Directional Capacity	1680	ve	≥h/h	
Passing Lane Analysis	8			
Total length of analysis segment Lt			0 5	mi
Length of two-lane highway upstream of the passing	lane.	T.11	-	mi
Length of passing lane including tapers. Lpl	,,	24	_	mi
Average travel speed, ATSd (from above)			47.4	mi/h
Percent time-spent-following, PTSFd (from above)			66.2	
Level of service, LOSd (from above)			D	
Average Travel Speed with Pass	sing La	ne		
Downstream length of two-lane highway within effect	rtive			
length of passing lane for average travel spee	a. Ide		_	mi
Length of two-lane highway downstream of effective				
length of the passing lane for average travel	speed,	Ld	-	mi
Adj. factor for the effect of passing lane				
on average speed, fpl			_	
Average travel speed including passing lane, ATSpl	L		-	
Percent free flow speed including passing lane, PF	FSpl		0.0	010
Percent Time-Spent-Following with	Passing	g Lar	1e	
Deventure length of the leng bighter within offer	****** 1	~ ~ ~ + k	-	
of pagaing long for paragent time aport followi	na Id	engti	1	mi
Jongth of two long highway downgtroom of offortive	ling, Lae	e b of	-	
the passing lane for percent time-spent-follow	vina L	4	_	mi
Adj factor for the effect of passing lane	ving, n	a		
on percent time-spent-following, fpl			_	
Percent time-spent-following				
including passing lane, PTSFpl			-	90
Level of Service and Other Performance Measu	ures wit	th Pa	assing	Lane
Lovel of genuine including president love IOC 1	P			
Peak 15-min total travel time, TT15	巴 一	ve	eh-h	
Bicycle Level of Servic	ce			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	350.6
Effective width of outside lane, We	23.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	3.79
Bicycle LOS	D

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 NB Longview / Yearney From/To Redbank Township, Clarion Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.79 Highway class Class 1 Shoulder width 4.0 ft % Trucks and buses 11 % 11.0ft% Trucks crawling0.00.6miTruck crawl speed0.0Rolling% Recreational vehicles0 Lane width % Segment length mi/hr Rolling 8 Terrain type - mi % No-passing zones 100 - % Access point density 4 Grade: Length 8 Up/down /mi Analysis direction volume, Vd 258 veh/h Opposing direction volume, Vo 236 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.1 2.1 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.892 0.892 Grade adj. factor,(note-1) fg 0.85 0.83 431 pc/h Directional flow rate, (note-2) vi 403 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 1.0 mi/h Free-flow speed, FFSd mi/h 57.3 mi/h Adjustment for no-passing zones, fnp 3.3 Average travel speed, ATSd 47.5 mi/h Percent Free Flow Speed, PFFS 83.0 %

Percent Time-Spent-Fo	llowing		
Direction Analysis PCE for trucks, ET 1.6	(d)	Opposing 1.7	( 0 )
PCE for RVs, ER 1.0		1.0	
Heavy-vehicle adjustment factor, fHV 0.93	8	0.929	1
Grade adjustment factor. (note-1) fg 0.86		0 85	
Directional flow rate (note-2) vi 405	pc/h	379	pc/h
Base percent time-spent-following (note-4) BPT	2777 277 277	9, 9	20/11
Adjustment for no-passing zones fun	46 3	0	
Percent time-spent-following, PTSFd	66 3	0	
reroene erme spene rorrowing, ribra		•	
Level of Service and Other Per	formance Mea	sures	
Level of service, LOS	D		
Volume to capacity ratio, v/c	0.20		
Peak 15-min vehicle-miles of travel, VMT15	49	veh-mi	
Peak-hour vehicle-miles of travel VMT60	155	veh-mi	
Deak 15-min total travel time TT15	1 0	ven mi	
Capacity from ATS COATS	1646	ven n web/b	
Capacity from DECE CODECE	1700	vell/ll	
Capacity from PTSF, COPTSF	1/00	ven/n	
Directional Capacity	1646	ven/n	
Passing Lane Anal	ysis		
Total length of analysis segment It		0 6	mi
Ionath of two long highway unstroom of the neg	aina lono I	0.0	mi
Length of two-lane highway upstream of the pas	Sing lane, L	iu –	uu 1
Length of passing fame including tapers, Lpf		- 47 F	lll⊥ mi (la
Average travel speed, ATSd (from above)	- )	47.5	m1/11
Percent time-spent-following, PISFd (from abov	e)	66.3	
Level of service, LOSd (from above)		D	
Average Travel Speed with	Passing Lane	·	
De materie langelt of the lange bight of this			
Downstream length of two-lane highway within e	iiective		
length of passing lane for average travel	speea, Lae	-	mı
Length of two-lane highway downstream of effec	tive		
length of the passing lane for average tra	vel speed, L	id –	mı
Adj. factor for the effect of passing lane			
on average speed, fpl		-	
Average travel speed including passing lane, A	TSpl	-	
Percent free flow speed including passing lane	, PFFSpl	0.0	00
Percent Time-Spent-Following w	ith Passing	Lane	
Downstream length of two-lane highway within e	ffective len	gth	
of passing lane for percent time-spent-fol	lowing, Lde	-	mi
Length of two-lane highway downstream of effect	tive length	of	
the passing lane for percent time-spent-fo	llowing, Ld	-	mi
Adj. factor for the effect of passing lane			
on percent time-spent-following, fpl		_	
Percent time-spent-following			
including passing lane, PTSFpl		-	00
Level of Service and Other Performance M	leasures with	Passing	Lane
	-		
Level of service including passing lane, LOSpl	E	- 1 1	
Peak 15-min total travel time, TT15	-	veh-h	
Bicycle Level of Se	rvice		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	326.6
Effective width of outside lane, We	15.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	7.75
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodPM Peak 1/30/2020 Highway SR 28 NB Longview / Yearney From/To Redbank Township, Clarion Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.83 Highway class Class 1 Shoulder width 4.0 ft % Trucks and buses б % 11.0ft% Trucks crawling0.00.6miTruck crawl speed0.0Rolling% Recreational vehicles0 Lane width % Segment length mi/hr Rolling 8 Terrain type mi % No-passing zones 100 % Access point density 4 - mi Grade: Length 8 Up/down \_ /mi Analysis direction volume, Vd 228 veh/h Opposing direction volume, Vo 274 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.1 2.1 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.938 0.938 Grade adj. factor,(note-1) fg 0.81 0.85 362 pc/h Directional flow rate, (note-2) vi 414 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 1.0 mi/h Free-flow speed, FFSd mi/h 57.3 mi/h Adjustment for no-passing zones, fnp 3.2 Average travel speed, ATSd 48.1 mi/h Percent Free Flow Speed, PFFS 83.9 %

Percent Time-Spent-Follo	owing			
Direction Analysis(d) PCE for trucks, ET 1.7	)	Opp	osing 1.6	( 0 )
PCE for RVs, ER 1.0			1.0	
Heavy-vehicle adjustment factor, fHV 0.960			0.965	5
Grade adjustment factor,(note-1) fg 0.84			0.87	
Directional flow rate,(note-2) vi 341	pc/h		393	pc/h
Base percent time-spent-following, (note-4) BPTSFC	d 38.4	olo		
Adjustment for no-passing zones, fnp	48.0	0		
Percent time-spent-following, PTSFd	60.7	50		
Level of Service and Other Performed	rmance M	easur	es	
Level of service, LOS	С			
Volume to capacity ratio, v/c	0.16			
Peak 15-min vehicle-miles of travel, VMT15	41	ve	h-mi	
Peak-hour vehicle-miles of travel, VMT60	137	ve	h-mi	
Peak 15-min total travel time, TT15	0.9	ve	h-h	
Capacity from ATS, CdATS	1669	ve	h/h	
Capacity from PTSF, CdPTSF	1700	ve	h/h	
Directional Capacity	1669	ve	h/h	
Passing Lane Analys	is			
Total length of analysis segment, Lt	_		0.6	mi
Length of two-lane highway upstream of the passir	ng lane,	Lu	-	mi
Length of passing lane including tapers, Lpl			-	mi
Average travel speed, ATSd (from above)			48.1	mi/h
Percent time-spent-following, PTSFd (from above)			60.7	
Level of service, LOSd (from above)			C	
Average Travel Speed with Pas	ssing La	ne		
Downstream length of two-lane highway within effe	active			
length of passing lane for average travel spe	and Lda		_	mi
Length of two-lane highway downstream of effective				
length of the pagging lane for average travel	laneed	ъđ	_	mi
Adj factor for the effect of pagging lane	i speed,	ЦЦ		
on average speed fn]			_	
Average travel speed including pagging lane ATS	01		_	
Percent free flow speed including passing lane, All	PFFSpl		0 0	0
refecte file filow speed including pubbing func, i	LIIOPI		0.0	0
Percent Time-Spent-Following with	h Passin	g Lan	.e	
Downstream length of two-lane highway within effe	ective l	ength	L	
of passing lane for percent time-spent-follow	wing, Ld	.e	-	mi
Length of two-lane highway downstream of effective	ve lengt	h of		
the passing lane for percent time-spent-follo	owing, L	d	-	mi
Adj. factor for the effect of passing lane				
on percent time-spent-following, fpl			_	
Percent time-spent-following				
including passing lane, PTSFpl			-	00
Level of Service and Other Performance Meas	sures wi	th Pa	ssing	Lane
	_			
Level of service including passing lane, LOSpl	Ε		, .	
Peak 15-min total travel time, TT15	-	ve	h-h	
Bicycle Level of Serve	ice			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	274.7
Effective width of outside lane, We	15.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	5.79
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 SB Longview / Yearney From/To Redbank Township, Clarion Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.86 Highway class Class 1 Shoulder width 4.0 ft % Trucks and buses 13 % 11.0ft% Trucks crawling0.00.6miTruck crawl speed0.0Rolling% Recreational vehicles0 Lane width % Segment length mi/hr Rolling 8 Terrain type mi % No-passing zones 100
% Access point density 4 Grade: Length 8 Up/down /mi Analysis direction volume, Vd 236 veh/h Opposing direction volume, Vo 258 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.2 2.1 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.865 0.875 Grade adj. factor,(note-1) fg 0.81 0.83 392 pc/h Directional flow rate, (note-2) vi 413 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 1.0 mi/h Free-flow speed, FFSd mi/h 57.3 mi/h Adjustment for no-passing zones, fnp 3.2 Average travel speed, ATSd 47.8 mi/h Percent Free Flow Speed, PFFS 83.5 %

Percent Time-Spent-Foll	owing			
Direction Analysis(d PCE for trucks, ET 1.7	)	Opj	posing 1.7	( 0 )
PCE for RVs, ER 1.0			1.0	
Heavy-vehicle adjustment factor, fHV 0 917			0 91'	7
Grade adjustment factor (note-1) fa 0.84			0.91	
Directional flow rate (note 2) wi	ng/h		205	ng/h
Directional riow rate, (note-2) vi 550		0.	200	pe/m
Base percent time-spent-tottowing, (note-4) BPISF	u 38.5	6		
Adjustment for no-passing zones, inp	48.6	•		
Percent time-spent-following, PTSFd	61.8	90		
Level of Service and Other Perfo	rmance M	leasu	res	
Level of service, LOS	С			
Volume to capacity ratio, v/c	0.17			
Peak 15-min vehicle-miles of travel, VMT15	41	V	≏h-mi	
Deak-hour vehicle-miles of travel VMT60	142	374	≏h_mi	
Dook 15 min totol travel time TT15			ab $b$	
Generative from ATC GAATC	1625	~	=11-11 ab /b	
Capacity from AIS, COAIS	1035	V		
Capacity from PTSF, CdPTSF	T.100	V	eh/h	
Directional Capacity	1635	V	eh/h	
Passing Lane Analys	is			
Total length of analysis segment It			06	mi
Longth of two long highway upgtroom of the page	ng lang	т.,	0.0	mi
Length of two-falle highway upstream of the passi	ng lane,	ьu	-	
Length of passing lane including tapers, Lpi			-	m1
Average travel speed, ATSd (from above)			47.8	mı/h
Percent time-spent-following, PTSFd (from above)			61.8	
Level of service, LOSd (from above)			С	
Average Travel Speed with Pa	ssing La	ine		
Deventreen length of two leng highway within off	oatino			
Jonath of margine long for anomal translate	ective			
length of passing lane for average travel sp	eea, Lae		-	ml
Length of two-lane highway downstream of effecti	ve			
length of the passing lane for average trave	l speed,	Ld	-	mi
Adj. factor for the effect of passing lane				
on average speed, fpl			-	
Average travel speed including passing lane, ATS	pl		-	
Percent free flow speed including passing lane,	PFFSpl		0.0	00
Percent Time-Spent-Following wit	h Passin	ıq Laı	ne	
		-		
Downstream length of two-lane highway within eff	ective l	engtl	h	
of passing lane for percent time-spent-follo	wing, Ld	le	-	mi
Length of two-lane highway downstream of effective	ve lengt	h of		
the passing lane for percent time-spent-foll	owing, I	d	_	mi
Adj. factor for the effect of passing lane	57			
on percent time-spent-following fpl			_	
Dergent time_gnent_following				
including passing lane, PTSFpl			_	8
Level of Service and Other Performance Mea	gureg wi	th D:	agging	Lane
Bever of bervice and other refformance mea	DATCD WI		200111J	
Level of service including passing lane, LOSpl	Е			
Peak 15-min total travel time, TT15	-	V	eh-h	
Bicycle Level of Serv	ice			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	274.4
Effective width of outside lane, We	15.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	8.55
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodPM Peak 1/30/2020 Highway SR 28 SB Longview / Yearney From/To Redbank Township, Clarion Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.88 Highway class Class 1 Shoulder width 4.0 ft % Trucks and buses 4 % 11.0ft% Trucks crawling0.00.6miTruck crawl speed0.0Rolling% Recreational vehicles0 Lane width % Segment length mi/hr Rolling 8 Terrain type mi % No-passing zones 100 % Access point density 4 – mi Grade: Length 8 Up/down \_ /mi Analysis direction volume, Vd 274 veh/h Opposing direction volume, Vo 228 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.1 2.2 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.958 0.954 Grade adj. factor,(note-1) fg 0.84 0.80 387 pc/h Directional flow rate, (note-2) vi 339 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 1.0 mi/h Free-flow speed, FFSd mi/h 57.3 mi/h Adjustment for no-passing zones, fnp 3.6 Average travel speed, ATSd 48.1 mi/h Percent Free Flow Speed, PFFS 84.0 %

Percent Time-Spent-Fo	llowing		
Direction Analysis PCE for trucks, ET 1.6	(d)	Opposing 1.7	( 0 )
PCE for RVs, ER 1.0		1.0	
Heavy-vehicle adjustment factor, fHV 0.97	7	0 973	
Grade adjustment factor (note-1) fa 0.86		0.83	
Directional flow rate (note 2) wi	ng/h	201	ng/h
Directional riow rate, (note-2) vi 5/1		ے کے C م	pe/m
Base percent time-spent-following, (note-4) BPT	SFG 39.5	6	
Adjustment for no-passing zones, inp	50.4	•	
Percent time-spent-following, PTSFd	66.5	50	
Level of Service and Other Per	formance Me	asures	
Level of service, LOS	D		
Volume to capacity ratio, v/c	0.19		
Peak 15-min vehicle-miles of travel. VMT15	47	veh-mi	
Deak-bour vehicle-miles of travel VMT60	164	veh_mi	
Dook 15 min total travel time TT15	1 0	ven mi	
Generative from ATC (d)TC	1.0	ven-n	
Capacity from AIS, COAIS	1080	ven/n	
Capacity from PTSF, CdPTSF	1700	veh/h	
Directional Capacity	1680	veh/h	
Passing Lane Anal	ysis		
Total length of analysis segment Lt		06	mi
I ongth of two long highway ungtroom of the nog	aina lana	U.U	mi
Length of two-lane highway upstream of the pas	sing lane,	Lu -	111 I
Length of passing lane including tapers, Lpi		-	
Average travel speed, ATSd (from above)		48.1	mı/h
Percent time-spent-following, PTSFd (from abov	e)	66.5	
Level of service, LOSd (from above)		D	
Average Travel Speed with	Passing Lan	e	
Deventreen length of two leng highway within a	ffogtimo		
Jonath of magine long for another transf			
length of passing lane for average travel	speea, Lae	-	mı
Length of two-lane highway downstream of effec	tive	_	
length of the passing lane for average tra	vel speed,	Ld -	mi
Adj. factor for the effect of passing lane			
on average speed, fpl		-	
Average travel speed including passing lane, A	TSpl	-	
Percent free flow speed including passing lane	, PFFSpl	0.0	00
Percent Time-Spent-Following w	ith Passing	Lane	
	2		
Downstream length of two-lane highway within e	ffective le	ngth	
of passing lane for percent time-spent-fol	lowing, Lde	-	mi
Length of two-lane highway downstream of effec	tive length	of	
the passing lane for percent time-spent-fo	llowing, Ld	_	mi
Adj factor for the effect of passing lane	110,1119, 10		
on pergent time grant following fr			
Devrent time ment fellewing, the		-	
including passing lane. PTSFpl		_	010
			-
Level of Service and Other Performance M	easures wit	n Passing	Lane
Level of service including passing lane, LOSpl	. E		
Peak 15-min total travel time, TT15	-	veh-h	
Bicycle Level of Se	rvice		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	311.4
Effective width of outside lane, We	15.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	5.25
Bicycle LOS	Е

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 NB Dewey Rd / SR 2001 From/To Redbank Township, Clarion Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 5.0 ft % Trucks and Dusc. Lane width 11.0 ft % Trucks crawling 0.0 Comment length 0.9 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 No-passing zones 87 20 % 2 mi/hr % - mi % No-passing zones 87 - % Access point density 20 8 Access point density 20 /mi Up/down Analysis direction volume, Vd 150 veh/h Opposing direction volume, Vo 116 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.3 2.5 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.917 0.905 0.74 Grade adj. factor,(note-1) fg 0.71 283 pc/h Directional flow rate, (note-2) vi 231 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 5.0 mi/h Free-flow speed, FFSd mi/h 53.3 mi/h Adjustment for no-passing zones, fnp 3.8 Average travel speed, ATSd 45.5 mi/h Percent Free Flow Speed, PFFS 85.5 %

Percent Time-Spent-Foll	owing			
Direction Analysis(d PCE for trucks, ET 1.8	1)	Op	posing 1.8	( 0 )
PCE for RVs, ER 1.0			1.0	
Heavy-vehicle adjustment factor, fHV 0.947			0.94	7
Grade adjustment factor, (note-1) fg 0.79			0.76	
Directional flow rate, (note-2) vi 257	pc/h		207	pc/h
Base percent time-spent-following, (note-4) BPTSF	'd 26.4	8		-
Adjustment for no-passing zones, fnp	57.3	5		
Percent time-spent-following, PTSFd	58.1	. %		
Level of Service and Other Perfo	ormance	Measu	res	
Level of service. LOS	С			
Volume to capacity ratio $v/c$	0 1 2	)		
Deak 15-min vehicle-miles of travel VMT15	43		oh_mi	
Peak hour uchigle miles of travel, VMT60	125	v 	ch mi	
Peak 15 min total travel time TT15	133	V	ch h	
Conscient from ATC (d)TC	1.5	V	en-n	
Capacity from AIS, COAIS	1700			
Capacity from PTSF, COPTSF	1/00	) V	en/n	
Directional Capacity	1664	e v	ren/n	
Passing Lane Analys	sis			
Total length of analysis segment. It			0.9	mi
Length of two-lane highway upstream of the passi	ng lane	T.11	_	mi
Length of passing lane including tapers []	ing ranc	., ца	_	mi
Average travel speed ATSd (from above)			15 5	mi/h
Dergent time_spect, Albu (110m above)			-J.J 50 1	111 / 11
Level of geruige 100d (from above)			20.I	
Level of service, Losa (from above)			C	
Average Travel Speed with Pa	assing I	ane		
Downstream length of two-lane highway within eff	ective			
length of passing lane for average travel sp	peed. Ld	le	_	mi
Length of two-lane highway downstream of effecti	ve			
length of the passing lane for average trave	l speed	b.T	_	mi
Adj factor for the effect of passing lane	I Spece	, ца		
an average greed fri				
Nucreas travel aread including reaging long ATC	'm 1		-	
Average traver speed including passing lane, Als	prec~1		-	0_
Percent free flow speed including passing fane,	PLLSDT		0.0	6
Percent Time-Spent-Following wit	h Passi	.ng La	ne	
Downstream length of two-lane highway within off	ective	lenat	h	
of passing lane for percent time-spent-follo	wing T	.do	_	mi
Length of two-lane highway downstream of effecti	wing, i	th of		
the pagging lane for pergent time grout foll	owing	JUH OL TA		mi
Ine passing faile for percent time-spent-for	.owing,	цα	-	1111
Auj. factor for the effect of passing lane				
on percent time-spent-following, fpl			-	
Percent time-spent-following			_	9
Including Passing lane, Pistpi			—	-0
Level of Service and Other Performance Mea	sures w	vith P	assing	Lane
Level of service including passing lane LOSpl	ज			
Deak 15-min total travel time TT15	-		-eh-h	
reak is min cotar traver time, iiis	—	V		
Bicycle Level of Serv	vice			
Posted speed limit, Sp	55			
---	-------			
Percent of segment with occupied on-highway parking	0			
Pavement rating, P	3			
Flow rate in outside lane, vOL	192.3			
Effective width of outside lane, We	25.00			
Effective speed factor, St	4.79			
Bicycle LOS Score, BLOS	3.94			
Bicycle LOS	D			

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodPM Peak 1/30/2020 Highway SR 28 NB Dewey Rd / SR 2001 From/To Redbank Township, Clarion Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 5.0 ft % Trucks and Duber Lane width 11.0 ft % Trucks crawling 0.0 Comment length 0.9 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 No-passing zones 87 20 Peak hour factor, PHF 0.89 9 % 0.0 % 0.0 mi/hr 8 - mi % No-passing zones 87 - % Access point density 20 8 Access point density 20 /mi Up/down Analysis direction volume, Vd 161 veh/h Opposing direction volume, Vo 208 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.4 2.2 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.888 0.903 Grade adj. factor,(note-1) fg 0.73 0.78 279 pc/h Directional flow rate, (note-2) vi 332 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 5.0 mi/h Free-flow speed, FFSd mi/h 53.3 mi/h Adjustment for no-passing zones, fnp 3.1 Average travel speed, ATSd 45.4 mi/h Percent Free Flow Speed, PFFS 85.2 %

Percent Time-Spent-Follow:	ing		
DirectionAnalysis(d)PCE for trucks, ET1.8PCE for RVs, ER1.0		Opposin 1.7 1.0	g (o)
Heavy-vehicle adjustment factor, fHV0.933Grade adjustment factor, (note-1) fg0.79Directional flow rate, (note-2) vi245	c/h	0.9 0.8 303	41 2 pc/h
Base percent time-spent-following,(note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	28.1 55.4 52.9	010 010	
Level of Service and Other Performa	ance Me	easures	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	C 0.11 41 145 0.9 1656 1700 1656	veh-mi veh-mi veh-h veh/h veh/h veh/h	
Passing Lane Analysis			
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	0.9 Lu - 45.4 52.9 C	mi mi mi mi/h
Average Travel Speed with Pass:	ing Lar	ne	
Downstream length of two-lane highway within effect length of passing lane for average travel speed	tive d, Lde	-	mi
length of the passing lane for average travel s Adj. factor for the effect of passing lane	speed,	Ld -	mi
Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFI	FSpl	- 0.0	8
Percent Time-Spent-Following with 1	Passing	g Lane	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followin Length of two-lane highway downstream of effective	tive le ng, Lde length	ength e - n of	mi
the passing lane for percent time-spent-follow: Adj. factor for the effect of passing lane on percent time-spent-following, fpl	ing, Lo	d – b	mi
Percent time-spent-following including passing lane, PTSFpl		-	20
Level of Service and Other Performance Measur	res wit	th Passin	g Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	E -	veh-h	
Bicycle Level of Service	e		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	180.9
Effective width of outside lane, We	21.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	5.56
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 SB Dewey Rd / SR 2001 From/To Redbank Township, Clarion Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 5.0 ft % Trucks and Dusce Lane width 11.0 ft % Trucks crawling 0.0 Comment length 0.9 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 No-passing zones 72 20 % % mi/hr 8 - mi % No-passing zones 72 - % Access point density 20 8 Access point density 20 /mi Up/down Analysis direction volume, Vd 116 veh/h Opposing direction volume, Vo 150 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.4 2.3 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.877 0.885 0.72 Grade adj. factor,(note-1) fg 0.76 266 pc/h Directional flow rate, (note-2) vi 323 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 5.0 mi/h Free-flow speed, FFSd mi/h 53.3 mi/h Adjustment for no-passing zones, fnp 3.0 Average travel speed, ATSd 45.7 mi/h Percent Free Flow Speed, PFFS 85.8 %

Percent Time-Spent-Follow:	ing		
DirectionAnalysis(d)PCE for trucks, ET1.8PCE for RVs, ER1.0		Opposing 1.7 1.0	g (o)
Heavy-vehicle adjustment factor, fHV 0.926 Grade adjustment factor, (note-1) fg 0.78 Directional flow rate, (note-2) vi 233 pc	c/h	0.92	35 1 pc/h
Base percent time-spent-following,(note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	26.2 54.7 50.7	90 80	<u> </u>
Level of Service and Other Perform	ance Me	easures	
Level of service, LOS	С		
Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60	0.10 38 104	veh-mi veh-mi	
Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	0.8 1651 1700 1651	veh/h veh/h veh/h	
Passing Lane Analysis		,	
Total length of analysis segment. Lt		0.9	mi
Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above)	lane,	Lu – 45.7 50.7	mi mi mi/h
Average Travel Speed with Pass:	ing Lai	ne	
Devent room longth of two long highway within offer	+ 1 110		
length of passing lane for average travel speed Length of two-lane highway downstream of effective	d, Lde	-	mi
length of the passing lane for average travel : Adj. factor for the effect of passing lane	speed,	Ld -	mi
Average travel speed including passing lane, ATSpl	ECml	-	٥.
Percent free flow speed including passing fane, Pri	rspi	0.0	6
Percent Time-Spent-Following with I	Passing	g Lane	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followin Length of two-lane highway downstream of effective	tive le ng, Lde lengtl	ength e - h of	mi
the passing lane for percent time-spent-follow: Adj. factor for the effect of passing lane on percent time-spent-following, fpl	ing, Lo	d – –	mi
Percent time-spent-following including passing lane, PTSFpl		_	%
Level of Service and Other Performance Measur	res wi	th Passing	g Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	E -	veh-h	
Bicycle Level of Service	e		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	168.1
Effective width of outside lane, We	27.72
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	4.28
Bicycle LOS	D

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodPM Peak 1/30/2020 Highway SR 28 SB Dewey Rd / SR 2001 From/To Redbank Township, Clarion Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 5.0 ft % Trucks and Dusc. Lane width 11.0 ft % Trucks crawling 0.0 Comment length 0.9 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 \* No-passing zones 72 20 % % mi/hr % - mi % No-passing zones 72 - % Access point density 20 8 Access point density 20 /mi Up/down Analysis direction volume, Vd 208 veh/h Opposing direction volume, Vo 161 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.1 2.3 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.929 0.917 0.81 Grade adj. factor,(note-1) fg 0.76 374 pc/h Directional flow rate, (note-2) vi 312 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 5.0 mi/h Free-flow speed, FFSd mi/h 53.3 mi/h Adjustment for no-passing zones, fnp 3.1 44.9 Average travel speed, ATSd mi/h Percent Free Flow Speed, PFFS 84.3 %

Percent Time-Spent-Follo	owing			
Direction Analysis(d) PCE for trucks, ET 1.7	)	0ppos 1	sing (o) L.7	
PCE for RVs, ER1.0Heavy-vehicle adjustment factor, fHV0.953Grade adjustment factor, (note-1) fg0.84		1 ( (	L.O ).953 ) 81	
Directional flow rate, (note-2) vi 351 Base percent time-spent-following, (note-4) BPTSFG	pc/h d 36.3	00	282 ]	pc/h
Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	51.0 64.6	0/0		
Level of Service and Other Perfor	rmance M	easures	5	
Level of service, LOS	D			
Volume to capacity ratio, v/c	0.17			
Peak 15-min vehicle-miles of travel, VMT15	63	veh-	-mi	
Peak-hour vehicle-miles of travel, VMT60	187	veh-	-mi	
Peak 15-min total travel time, TT15	1.4	veh-	-h	
Capacity from ATS, CdATS	1664	veh/	/h	
Capacity from PTSF, CdPTSF	1700	veh/	/h	
Directional Capacity	1664	veh/	/h	
Passing Lane Analysi	is			
Total length of analysis segment, Lt		0.	.9 m:	i
Length of two-lane highway upstream of the passir	ng lane,	Lu –	m:	i
Length of passing lane including tapers, Lpl		-	m	i
Average travel speed, ATSd (from above)		44	1.9 m:	i/h
Percent time-spent-following, PTSFd (from above)		64	ł.6	
Level of service, LOSd (from above)		D		
Average Travel Speed with Pas	ssing La	ne		
Downstream length of two-lane highway within effe	ective			
length of passing lane for average travel spe	eed, Lde	_	m:	i
Length of two-lane highway downstream of effectiv	ve			
length of the passing lane for average travel	l speed,	Ld -	m:	i
Adj. factor for the effect of passing lane				
on average speed, fpl		-		
Average travel speed including passing lane, ATSp	pl	-		
Percent free flow speed including passing lane, H	PFFSpl	0.	.0 %	
Percent Time-Spent-Following with	n Passing	g Lane_		
Downstream length of two-lane highway within effe	active 1	enath		
of pagging lang for percent time-spent-follow	ving Id		m	i
Length of two-lane highway downstream of effectiv	ve lengt	h of		±
the passing lane for percent time-spent-follo	wing. L	d –	m	i
Adj. factor for the effect of passing lane	у, ц			_
on percent time-spent-following, fpl		-		
Percent time-spent-following				
including passing lane, PTSFpl		-	00	
Level of Service and Other Performance Meas	sures wi	th Pass	sing Lan	e
Level of service including pagaing long IOG-1	υ			
Peak 15-min total travel time, TT15	<u>н</u>	veh-	-h	
Biquale Level of Servi	ice			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	281.1
Effective width of outside lane, We	21.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	5.05
Bicycle LOS	Ε

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 NB Moore Rd / Mendenhall Rd From/To Jurisdiction Clover Township, Jefferson Co Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 4.0 ft % Trucks and Dusc. Lane width 11.0 ft % Trucks crawling 0.0 Comment length 0.9 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 No-passing zones 100 14 % % mi/hr % - mi % No-passing zones 100 % - % Access point density 14 /mi Up/down Analysis direction volume, Vd 185 veh/h Opposing direction volume, Vo 106 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.2 2.6 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.912 0.887 0.78 Grade adj. factor, (note-1) fg 0.70 333 pc/h Directional flow rate, (note-2) vi 219 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 3.5 mi/h Free-flow speed, FFSd 54.8 mi/h 4.0 mi/h Adjustment for no-passing zones, fnp Average travel speed, ATSd 46.5 mi/h Percent Free Flow Speed, PFFS 84.9 %

Percent Time-Spent-Follow:	ing		
DirectionAnalysis(d)PCE for trucks, ET1.7PCE for RVs, ER1.0		Opposing 1.8 1.0	g (o)
Heavy-vehicle adjustment factor, fHV 0.947 Grade adjustment factor, (note-1) fg 0.82 Directional flow rate, (note-2) vi 305 pc	c/h	0.94 0.76 190	40 5 pc/h
Base percent time-spent-following,(note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	30.6 52.8 63.1	୰ଡ଼	-
Level of Service and Other Performa	ance Me	easures	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF	C 0.14 53 166 1.1 1661 1700	veh-mi veh-mi veh-h veh/h veh/h	
Directional Capacity	1661	veh/h	
Passing Lane Analysis			
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	0.9 Lu - 46.5 63.1 C	mi mi mi mi/h
Average Travel Speed with Pass:	ing Lar	ne	
Downstream length of two-lane highway within effect length of passing lane for average travel speed	tive d, Lde	_	mi
Length of two-rane highway downstream of effective length of the passing lane for average travel a Adj. factor for the effect of passing lane	speed,	Ld -	mi
Average travel speed, IPI Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFI	FSpl	- 0.0	સ્
Percent Time-Spent-Following with 1	Passing	g Lane	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followin Length of two-lane highway downstream of effective	tive le ng, Lde length	ength e - h of	mi
the passing lane for percent time-spent-follow: Adj. factor for the effect of passing lane on percent time-spent-following, fpl	ing, Lo	d –	mi
Percent time-spent-following including passing lane, PTSFpl		_	8
Level of Service and Other Performance Measu	res wit	th Passing	g Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	E -	veh-h	
Bicycle Level of Service	e		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	237.2
Effective width of outside lane, We	15.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	б.40
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodPM Peak 1/30/2020 Highway SR 28 NB Moore Rd / Mendenhall Rd From/To Jurisdiction Clover Township, Jefferson Co Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 4.0 ft % Trucks and Dusce Lane width 11.0 ft % Trucks crawling 0.0 Comment length 0.9 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 No-passing zones 100 14 % % mi/hr % mi % No-passing zones 100 %
% Access point density 14 /mi Up/down Analysis direction volume, Vd 158 veh/h Opposing direction volume, Vo 285 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.3 2.0 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.895 0.917 Grade adj. factor,(note-1) fg 0.76 0.88 306 pc/h Directional flow rate, (note-2) vi 465 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 3.5 mi/h Free-flow speed, FFSd 54.8 mi/h mi/h Adjustment for no-passing zones, fnp 2.5 Average travel speed, ATSd 46.3 mi/h Percent Free Flow Speed, PFFS 84.5 %

Percent Time-Spent-Follow:	ing			
Direction Analysis(d) PCE for trucks, ET 1 7		Opp	osing 1.6	( 0 )
PCE for RVs ER 10			1 0	
Heavy-vehicle adjustment factor fHV 0.941			0 940	)
Grade adjustment factor. (note-1) fg 0.80			0.89	
Directional flow rate (note-2) vi 276 pc	c/h		444	pc/h
Base percent time-spent-following, (note-4) BPTSFd	33.1	00		F. C. /
Adjustment for no-passing zones, fnp	43.8			
Percent time-spent-following, PTSFd	49.9	00		
Level of Service and Other Performa	ance Me	easur	es	
	a			
Level of service, LOS	0 1 2			
Volume to capacity ratio, v/c	0.13		10	
Peak 15-min vehicle-miles of travel, VMT15	4/	Ve		
Peak-nour venicle-miles of travel, VMT60	142	ve	h h	
Generative from ATC - GdATC	1.0	ve	211-11 b / b	
Capacity from ATS, COATS	1700	Ve	211/11	
Capacity from PTSF, COPTSF	1/00 1/00	Ve	211/11	
Directional Capacity	1020	VE	211/11	
Passing Lane Analysis				
Total length of analysis segment, Lt			0.9	mi
Length of two-lane highway upstream of the passing	lane,	Lu	_	mi
Length of passing lane including tapers, Lpl			_	mi
Average travel speed, ATSd (from above)			46.3	mi/h
Percent time-spent-following, PTSFd (from above)			49.9	
Level of service, LOSd (from above)			С	
Average Travel Speed with Pass:	ing Lar	ne		
Downstream length of two-lane highway within effect	tive			
length of passing lane for average travel speed	d, Lde		-	mi
Length of two-lane highway downstream of effective	-			
length of the passing lane for average travel s	speed,	Ld	-	mı
Adj. factor for the effect of passing lane				
on average speed, fpl			-	
Average travel speed including passing lane, ATSpl			-	<u>,</u>
Percent free flow speed including passing lane, PFI	FSpl		0.0	90
Percent Time-Spent-Following with H	Passing	g Lan	ie	
Downstream length of two-lane highway within effect	tive le	enath	1	
of passing lane for percent time-spent-following	na, I.de	2	_	mi
Length of two-lane highway downstream of effective	length	- n of		
the passing lane for percent time-spent-follow	ina. Lá	3	_	mi
Adj factor for the effect of passing lane		~		
on percent time-spent-following, fpl			_	
Percent time-spent-following				
including passing lane, PTSFpl			-	00
Level of Service and Other Performance Measur	res wit	ch Pa	ssing	Lane
Lovel of genuine including reaction love too l	T			
Level of service including passing lane, LOSpl	Е		la 1-	
Peak 15-min total travel time, TT15	-	ve	en-h	
Bicycle Level of Service	e			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	207.9
Effective width of outside lane, We	18.15
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	6.19
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 SB Moore Rd / Mendenhall Rd From/To Clover Township, Jefferson Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 4.0 ft % Trucks and Dusce Lane width 11.0 ft % Trucks crawling 0.0 Comment length 0.9 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 No-passing zones 100 14 % % mi/hr 00 - mi % No-passing zones 100 % - % Access point density 14 /mi Up/down Analysis direction volume, Vd 106 veh/h Opposing direction volume, Vo 185 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.6 2.2 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.839 0.874 0.70 Grade adj. factor,(note-1) fg 0.77 226 pc/h Directional flow rate, (note-2) vi 344 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 3.5 mi/h Free-flow speed, FFSd 54.8 mi/h mi/h Adjustment for no-passing zones, fnp 3.2 Average travel speed, ATSd 47.2 mi/h Percent Free Flow Speed, PFFS 86.2 %

Percent Time-Spent-Follow	ing			
Direction Analysis(d) PCE for trucks, ET 1.8		Opı	posing 1.7	( 0 )
PCE for RVs, ER 1.0			1.0	
Heavy-vehicle adjustment factor, fHV 0.912			0.923	3
Grade adjustment factor, (note-1) fg 0.75			0.82	/ le
Directional flow rate, (note-2) vi 194 p	oc/n	0,	306	pc/n
Adjustment for no-passing zones for	23.2 52.8	6		
Percent time-spent-following, PTSFd	43.7	00		
Level of Service and Other Derform	ance M	22011	6 G G	
hever of Service and Other Perform		casu		
Level of service, LOS	С			
Volume to capacity ratio, v/c	0.08			
Peak 15-min vehicle-miles of travel, VMT15	30	ve	eh-mi	
Peak-hour vehicle-miles of travel, VMT60	95	ve	eh-mi	
Peak 15-min total travel time, TT15	0.6	ve	eh-h	
Capacity from ATS, CdATS	1641	ve	eh/h	
Capacity from PTSF, CdPTSF	1700	ve	eh/h	
Directional Capacity	1641	ve	eh/h	
Passing Lane Analysis	l			
			0 0	
Total length of analysis segment, Lt	1	Ŧ	0.9	mi
Length of two-lane highway upstream of the passing	lane,	Lu	-	m1
Length of passing lane including tapers, Lpi			-	
Average travel speed, Also (from above)			41.2	111 / 11
Level of service LOSd (from above)			43.7 C	
Level of Service, Losa (from above)			C	
Average Travel Speed with Pass	ing Lar	ne		
Downstream length of two-lane highway within effect	tive			
length of passing lane for average travel spee	d, Lde		_	mi
Length of two-lane highway downstream of effective	2			
length of the passing lane for average travel	speed,	Ld	_	mi
Adj. factor for the effect of passing lane	-			
on average speed, fpl			_	
Average travel speed including passing lane, ATSpl			-	
Percent free flow speed including passing lane, PF	FSpl		0.0	00
Dorgont Time Spont Following with	Dagain	~ T ~ 1		
Percent lime-spent-following with	Passing	J Lai	Ie	
Downstream length of two-lane highway within effec	tive le	engtl	ı	
of passing lane for percent time-spent-followi	ng, Lde	9	-	mi
Length of two-lane highway downstream of effective	length	n of		
the passing lane for percent time-spent-follow	ing, Lo	f	-	mi
Adj. factor for the effect of passing lane				
on percent time-spent-following, fpl			-	
Percent time-spent-following				
including passing lane, PTSFpl			-	00
Level of Service and Other Performance Measu	res wit	ch Pa	assing	Lane
Level of service including passing lane LOSpl	Э			
Peak 15-min total travel time, TT15	-	ve	eh-h	
Bicycle Level of Servic	e			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	132.5
Effective width of outside lane, We	22.05
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	6.42
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodPM Peak 1/30/2020 Highway SR 28 SB Moore Rd / Mendenhall Rd From/To Jurisdiction Clover Township, Jefferson Co Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Shoulder width 4.0 ft % Trucks and Dusce Lane width 11.0 ft % Trucks crawling 0.0 Comment length 0.9 mi Truck crawl speed 0.0 Polling % Recreational vehicles 0 No-passing zones 100 14 % % mi/hr % - mi % No-passing zones 100 % - % Access point density 14 /mi Up/down Analysis direction volume, Vd 285 veh/h Opposing direction volume, Vo 158 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 2.0 2.2 PCE for RVs, ER 1.1 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.943 0.933 0.91 Grade adj. factor,(note-1) fg 0.77 481 pc/h Directional flow rate, (note-2) vi 319 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 3.5 mi/h Free-flow speed, FFSd 54.8 mi/h 3.3 mi/h Adjustment for no-passing zones, fnp Average travel speed, ATSd 45.3 mi/h Percent Free Flow Speed, PFFS 82.6 %

Percent Time-Spent-Follow:	ing			
Direction Analysis(d) PCE for trucks, ET 1.4		Opp	osing 1.7	( 0 )
PCE for RVs, ER 1.0			1.0	
Heavy-vehicle adjustment factor, fHV 0.977			0.960	0
Grade adjustment factor. (note-1) fg 0.91			0 81	•
Directional flow rate (note-2) vi 465 p	∼/h		295	pc/h
Base percent time-spent-following (note-4) BPTSEd	45 8	0	295	P0/11
Adjustment for no-passing zones for	41 3	0		
Percent time-spent-following PTSEd	71 1	0		
reroene erme spene rorrowing, riora	,	0		
Level of Service and Other Performa	ance Me	easur	res	
Level of service, LOS	D			
Volume to capacity ratio, $v/c$	0.25			
Peak 15-min vehicle-miles of travel, VMT15	93	Ve	h-mi	
Deak-hour vehicle-miles of travel VMT60	256	ve	h-mi	
Deak 15-min total travel time TT15	2 1	v C 176	$h_h$	
Capacity from ATS COATS	1660		h/h	
Capacity from DEGE CODEGE	1700		=11/11 >b/b	
Capacity from PTSF, COPTSF	1/00	VE		
Directional Capacity	1669	ve	en/n	
Passing Lane Analysis				
Total length of analysis segment It			0 9	mi
Ionath of two long highway unstroom of the pagaing	lana	т.,	0.9	mi
Length of two-falle highway upstream of the passing	Talle,	шu	-	
Length of passing lane including tapers, Lpi			-	m1
Average travel speed, AISd (from above)			45.3	mı/h
Percent time-spent-following, PTSFd (from above)			71.1	
Level of service, LOSd (from above)			D	
Average Travel Speed with Pass:	ing Lar	ne		
Downstream length of two-lane highway within effect	tive			
length of passing lane for average travel speed	d, Lde		-	mı
Length of two-lane highway downstream of effective				
length of the passing lane for average travel s	speed,	Ld	-	mi
Adj. factor for the effect of passing lane				
on average speed, fpl			-	
Average travel speed including passing lane, ATSpl			-	
Percent free flow speed including passing lane, PFI	FSpl		0.0	90
Percent Time-Spent-Following with 1	Passing	g Lar	ne	
	_			
Downstream length of two-lane highway within effect	tive le	ength	l	
of passing lane for percent time-spent-following	ng, Lde	2	-	mi
Length of two-lane highway downstream of effective	length	ı of		
the passing lane for percent time-spent-follow	ing, Lċ	1	-	mi
Adj. factor for the effect of passing lane	- 1			
on percent time-spent-following, fpl			_	
Percent time-spent-following				
including passing lane, PTSFpl			-	00
Level of Service and Other Performance Measur	res wit	:h Pa	assing	Lane
Level of service including passing lane, LOSpl	Ε			
Peak 15-min total travel time, TT15	-	ve	eh-h	
Bicycle Level of Service	e			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	413.0
Effective width of outside lane, We	15.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	6.00
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Analysis Time Period PM Peak Highway SR 28 - Existing CL NB1 0.5 miles north of SR 85 From/To Jurisdiction Rayburn Township, Armstrong Co Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.94 Highway class Class 1 Shoulder width 6.0 ft % Trucks and buses 6 % 11.0ft% Trucks crawling0.00.9miTruck crawl speed0.0 Lane width % Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 Grade: Length 0.73 mi % No-passing zones 0 % Access point density 1 Up/down 5.5 00 /mi Analysis direction volume, Vd 542 veh/h Opposing direction volume, Vo 310 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 8.9 1.4 PCE for RVs, ER 1.0 1.0 Heavy-vehicle adj. factor,(note-5) fHV 0.677 0.977 0.87 Grade adj. factor,(note-1) fg 1.00 979 pc/h Directional flow rate, (note-2) vi 338 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 0.3 mi/h Free-flow speed, FFSd 59.3 mi/h mi/h Adjustment for no-passing zones, fnp 1.5 Average travel speed, ATSd 47.6 mi/h Percent Free Flow Speed, PFFS 80.2 %

Percent Time-Spent-Follows	ing		
Direction Analysis(d) PCE for trucks, ET 1.0 PCE for RVs ER 1.0		Opposing 1.1 1 0	(0)
Heavy-vehicle adjustment factor, fHV 1.000 Grade adjustment factor, (note-1) fg 1.00		0.99	4
Directional flow rate, (note-2) vi 577 pc Base percent time-spent-following, (note-4) BPTSFd	c/h 52.7	332 %	pc/h
Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	12.0 60.3	00	
Level of Service and Other Performa	ance Me	asures	
Level of service, LOS	С		
Volume to capacity ratio, v/c	0.50		
Peak 15-min vehicle-miles of travel, VMT15	130	veh-mi	
Peak-hour vehicle-miles of travel, VMT60	488	veh-mi	
Peak 15-min total travel time, TT15	2.7	veh-h	
Capacity from ATS, CdATS	1151	veh/h	
Capacity from PTSF, CdPTSF	1700	veh/h	
Directional Capacity	1151	veh/h	
Passing Lane Analysis_			
Total length of analysis segment, Lt		0.9	mi
Length of two-lane highway upstream of the passing	lane.	T <sub>11</sub> 1 0.0	mi
Length of passing lane including tapers []	ranc,	0 9	mi
Augrage travel apoed ATSd (from above)		47 6	mi/b
Develope time group following DECEd (from above)		47.0	111 / 11
Percent time-spent-following, Pisra (from above)		60.3	
Level of service, LOSA (from above)		Ċ	
Average Travel Speed with Passi	ing Lan	ie	
Downstream length of two-lane highway within effect	cive		
length of passing lane for average travel speed Length of two-lane highway downstream of effective	d, Lde	0.00	mi
length of the passing lane for average travel s Adj. factor for the effect of passing lane	speed,	Ld 0.00	mi
on average speed, fpl		1.14	
Average travel speed including passing lane, ATSpl		54.3	
Percent free flow speed including passing lane, PFI	FSpl	91.4	00
Percent Time-Spent-Following with H	Passing	Lane	
Downstream length of two-lane highway within effect	cive le	ength	
of passing lane for percent time-spent-followin	ng, Lde	e 0.00	mi
the passing lane for percent time-spent-follows	ing, Ld	0.00	mi
Adj. factor for the effect of passing lane			
on percent time-spent-following, fpl		0.21	
Percent time-spent-following			
including passing lane, PTSFpl		12.7	00
Level of Service and Other Performance Measur	res wit	h Passing	Lane
Level of service including passing lane, LOSpl	В		
Peak 15-min total travel time, TT15	2.4	veh-h	
Bicycle Level of Service	e		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	576.6
Effective width of outside lane, We	23.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	4.65
Bicycle LOS	Е

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Agency, 201Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 - Existing CL NB2 btw SR 1027 and SR 1016 From/To Boggs Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.76 Highway class Class 1 Shoulder width 5.0 ft % Trucks and buses 13 % 11.0ft% Trucks crawling0.00.7miTruck crawl speed0.0 Lane width % Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type % Grade: Length 0.53 mi % No-passing zones 0 8 Access point density 1 /mi Up/down 5.6 00 Analysis direction volume, Vd 151 veh/h Opposing direction volume, Vo 217 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 7.4 1.4 PCE for RVs, ER 1.4 1.0 Heavy-vehicle adj. factor,(note-5) fHV 0.545 0.951 0.61 Grade adj. factor,(note-1) fg 1.00 598 pc/h Directional flow rate, (note-2) vi 300 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 0.3 mi/h Free-flow speed, FFSd 58.0 mi/h mi/h Adjustment for no-passing zones, fnp 1.6 Average travel speed, ATSd 49.5 mi/h Percent Free Flow Speed, PFFS 85.3 %

Percent Time-Spent-Follow	ving		
DirectionAnalysis(d)PCE for trucks, ET1.0PCE for RVs, ER1.0Heavy-vehicle adjustment factor, fHV1.000Grade adjustment factor, (note-1) fg1.00		Opposing 1.1 1.0 0.987 1.00	( 0 )
Directional flow rate, (note-2) vi 199 p Base percent time-spent-following, (note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	24.1 24.1 14.8 30.1	289 % %	pc/h
Level of Service and Other Perform	mance Me	easures	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	C 0.21 35 106 0.7 927 1700 927	veh-mi veh-mi veh-h veh/h veh/h veh/h	
Passing Lane Analysis	5		
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	g lane,	0.7 Lu 0.0 0.7 49.5 30.1 C	mi mi mi/h
Average Travel Speed with Pass	sing Lar	ne	
Downstream length of two-lane highway within effect length of passing lane for average travel spec Length of two-lane highway downstream of effective length of the passing lane for average travel	ctive ed, Lde	0.00 Ld 0.00	mi
Adj. factor for the effect of passing lane	Speed,		iii 1
on average speed, fpl	1	1.07	
Percent free flow speed including passing lane, PF	FFSpl	91.3	00
Percent Time-Spent-Following with	Passing	g Lane	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followi Length of two-lane highway downstream of effective	ctive le ing, Lde	ength e 0.00	mi
the passing lane for percent time-spent-follow Adj. factor for the effect of passing lane	wing, Lo	a 0.00	mi
on percent time-spent-following, fpl Percent time-spent-following		0.20	
including passing lane, PTSFpl		6.0	010
Level of Service and Other Performance Measu	ures wit	ch Passing	Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	в 0.7	veh-h	
Bicycle Level of Servic	ce		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	198.7
Effective width of outside lane, We	24.92
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	6.41
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Date Performed1/30/202Analysis Time PeriodPM Peak Highway SR 28 - Existing CL NB2 btw SR 1027 and SR 1016 From/To Boggs Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.90 Highway class Class 1 Shoulder width 5.0 ft % Trucks and buses б % 11.0ft% Trucks crawling0.00.7miTruck crawl speed0.0 Lane width % Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 Grade: Length 0.53 mi % No-passing zones 0 8 Access point density 1 Up/down 5.6 00 /mi Analysis direction volume, Vd 295 veh/h Opposing direction volume, Vo 182 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 7.4 1.5 PCE for RVs, ER 1.0 1.1 Heavy-vehicle adj. factor,(note-5) fHV 0.722 0.971 0.67 Grade adj. factor,(note-1) fg 1.00 678 pc/h Directional flow rate,(note-2) vi 208 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 0.3 mi/h Free-flow speed, FFSd 58.0 mi/h 1.7 mi/h Adjustment for no-passing zones, fnp Average travel speed, ATSd 49.4 mi/h Percent Free Flow Speed, PFFS 85.2 %

Percent Time-Spent-Followi	ing		
Direction Analysis(d) PCE for trucks, ET 1.0 PCE for RVs, ER 1.0 Heavy-vehicle adjustment factor, fHV 1.000 Grade adjustment factor, (note-1) fg 1.00 Directional flow rate, (note-2) vi 328 pc Base percent time-spent-following, (note-4) BPTSFd Adjustment for no-passing zones, fnp	c/h 32.3 14.0	Opposing 1.1 1.0 0.994 1.00 203 %	(o) pc/h
Percent time-spent-following, PTSFd	40.9	010	
Level of Service and Other Performa	ance Me	asures	
	_		
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	C 0.27 57 206 1.2 1227 1700 1227	veh-mi veh-mi veh-h veh/h veh/h veh/h	
Passing Lane Analysis_			
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	0.7 Lu 0.0 0.7 49.4 40.9 C	mi mi mi/h
Average Travel Speed with Passi	ing Lan	ie	
Downstream length of two-lane highway within effect length of passing lane for average travel speed Length of two-lane highway downstream of effective length of the passing lane for average travel s Adj. factor for the effect of passing lane on average speed, fpl Average travel speed including passing lane, ATSpl	tive d, Lde speed,	0.00 Ld 0.00 1.14 56.4	mi mi
Percent free flow speed including passing lane, PFF	FSpl	97.1	00
Percent Time-Spent-Following with B	Passing	Jane	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followir Length of two-lane highway downstream of effective	tive le ng, Lde length	ength e 0.00	mi
the passing lane for percent time-spent-followi Adj. factor for the effect of passing lane	ing, Ld	0.00	mi
on percent time-spent-following, fpl Percent time-spent-following		0.21	
including passing lane, PTSFpl		8.6	<u>0</u>
Level of Service and Other Performance Measur	res wit	h Passing	Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	A 1.0	veh-h	
Bicycle Level of Service	2		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	327.8
Effective width of outside lane, We	21.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	4.80
Bicycle LOS	Ε

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 - Existing CL NB3 0.4 mi south of Distant From/To Boggs Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.76 Highway class Class 1 Shoulder width 5.0 ft % Trucks and buses 13 % 11.0ft% Trucks crawling0.00.5miTruck crawl speed0.0 Lane width % Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 0.35 mi % No-passing zones 0 8.5 % Access point density 0 Grade: Length 8 Up/down 8.5 /mi Analysis direction volume, Vd 151 veh/h Opposing direction volume, Vo 217 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 6.2 1.4 PCE for RVs, ER 1.0 1.5 Heavy-vehicle adj. factor,(note-5) fHV 0.598 0.951 Grade adj. factor,(note-1) fg 0.59 1.00 563 pc/h Directional flow rate, (note-2) vi 300 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 0.0 mi/h Free-flow speed, FFSd 58.3 mi/h mi/h Adjustment for no-passing zones, fnp 1.6 Average travel speed, ATSd 50.0 mi/h Percent Free Flow Speed, PFFS 85.8 %

Percent Time-Spent-Follo	wing		
DirectionAnalysis(d)PCE for trucks, ET1.0PCE for RVs, ER1.0Heavy-vehicle adjustment factor, fHV1.000Grade adjustment factor, (note-1) fg1.00Directional flow rate, (note-2) vi199	pc/h	Opposing 1.1 1.0 0.987 1.00 289	(0) 7 pc/h
Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	24.1 14.8 30.1	\$ \$	
Level of Service and Other Perfor	mance Me	easures	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	B 0.19 25 76 0.5 1051 1700 1051	veh-mi veh-mi veh-h veh/h veh/h veh/h	
Passing Lane Analysi	ន		
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	g lane,	0.5 Lu 0.0 0.5 50.0 30.1 B	mi mi mi/h
Average Travel Speed with Pas	sing Lar	ie	
Downstream length of two-lane highway within effe length of passing lane for average travel spe Length of two-lane highway downstream of effectiv length of the passing lane for average travel	ctive ed, Lde e speed,	0.00 Ld 0.00	mi mi
Adj. factor for the effect of passing lane		1 07	
Average travel speed including passing lane, ATSp	1	53.5	
Percent free flow speed including passing lane, P	FFSpl	91.8	00
Percent Time-Spent-Following with	Passing	J Lane	
Downstream length of two-lane highway within effe of passing lane for percent time-spent-follow Length of two-lane highway downstream of effectiv	ctive le ing, Lde e length	ength e 0.00	mi
the passing lane for percent time-spent-follo Adj. factor for the effect of passing lane	wing, Lo	0.00	mi
on percent time-spent-following, fpl Percent time-spent-following		0.20	
including passing lane, PTSFpl		6.0	00
Level of Service and Other Performance Meas	ures wit	h Passing	Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	В 0.5	veh-h	
Bicycle Level of Servi	ce		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	198.7
Effective width of outside lane, We	24.92
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	6.41
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Date Performed1/30/202Analysis Time PeriodPM Peak Highway SR 28 - Existing CL NB3 0.4 mi south of Distant From/To Boggs Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.90 Highway class Class 1 Shoulder width 5.0 ft % Trucks and buses б % 11.0ft% Trucks crawling0.00.5miTruck crawl speed0.0 Lane width % Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 0.35 mi % No-passing zones 0 8.5 % Access point density 0 Grade: Length 8 8.5 Up/down /mi Analysis direction volume, Vd 295 veh/h Opposing direction volume, Vo 182 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 6.1 1.5 PCE for RVs, ER 1.0 1.2 Heavy-vehicle adj. factor,(note-5) fHV 0.765 0.971 Grade adj. factor,(note-1) fg 0.65 1.00 659 pc/h Directional flow rate, (note-2) vi 208 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 0.0 mi/h Free-flow speed, FFSd mi/h 58.3 mi/h Adjustment for no-passing zones, fnp 1.7 Average travel speed, ATSd 49.8 mi/h Percent Free Flow Speed, PFFS 85.5 %

Percent Time-Spent-Followi	ing		
Direction Analysis(d) PCE for trucks, ET 1.0 PCE for RVs, ER 1.0 Heavy-vehicle adjustment factor, fHV 1.000 Grade adjustment factor, (note-1) fg 1.00 Directional flow rate, (note-2) vi 328 pc Base percent time-spent-following, (note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following PTSFd	c/h 32.3 14.0 40 9	Opposing 1.1 1.0 0.994 1.00 203 %	(o) A pc/h
	10.5	Ū	
Level of Service and Other Performa	ance Me	easures	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	C 0.25 41 148 0.8 1323 1700 1323	veh-mi veh-mi veh-h veh/h veh/h veh/h	
Passing Lane Analysis_			
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	0.5 Lu 0.0 0.5 49.8 40.9 C	mi mi mi/h
Average Travel Speed with Passi	ing Lar	ne	
Downstream length of two-lane highway within effect length of passing lane for average travel speed Length of two-lane highway downstream of effective length of the passing lane for average travel s Adj. factor for the effect of passing lane on average speed, fpl Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFF	zive d, Lde speed, FSpl	0.00 Ld 0.00 1.14 56.8 97.4	mi mi %
Percent Time-Spent-Following with F	Passino	r Lane	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followir Length of two-lane highway downstream of effective	ive length	ength e 0.00 n of	mi
the passing lane for percent time-spent-followi Adj. factor for the effect of passing lane	ing, Lċ	a 0.00	mi
on percent time-spent-following, fpl Percent time-spent-following		0.21	
including passing lane, PTSFpl		8.6	9 0
Level of Service and Other Performance Measur	res wit	ch Passing	Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	A 0.7	veh-h	
Bicycle Level of Service	e		
Posted speed limit, Sp	55		
---	-------		
Percent of segment with occupied on-highway parking	0		
Pavement rating, P	3		
Flow rate in outside lane, vOL	327.8		
Effective width of outside lane, We	21.00		
Effective speed factor, St	4.79		
Bicycle LOS Score, BLOS	4.80		
Bicycle LOS	Ε		

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Date Performed1/30/202Analysis Time PeriodAM Peak Highway SR 28 - Existing CL NB4 2.25 mi south of South Main St From/To Clover Township, Jefferson Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.78 Highway class Class 1 Shoulder width 5.0 ft % Trucks and buses 8 % 11.0ft% Trucks crawling0.01.0miTruck crawl speed0.0 Lane width % Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 Grade: Length 0.81 mi % No-passing zones 0 % Access point density 12 Up/down 5.1 00 /mi Analysis direction volume, Vd 185 veh/h Opposing direction volume, Vo 106 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 7.9 1.8 PCE for RVs, ER 1.0 1.3 Heavy-vehicle adj. factor,(note-5) fHV 0.644 0.940 0.67 Grade adj. factor,(note-1) fg 1.00 550 pc/h Directional flow rate, (note-2) vi 145 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 3.0 mi/h Free-flow speed, FFSd 55.3 mi/h mi/h Adjustment for no-passing zones, fnp 1.0 Average travel speed, ATSd 48.9 mi/h Percent Free Flow Speed, PFFS 88.5 %

Percent Time-Spent-Follo	owing		
DirectionAnalysis(dPCE for trucks, ET1.0PCE for RVs, ER1.0	)	Opposing 1.1 1.0	( 0 )
Heavy-vehicle adjustment factor, fHV1.000Grade adjustment factor, (note-1) fg1.00	(1	0.992 1.00	
Base percent time-spent-following, (note-4) BPTSFG	pc/n d 24.9	137 %	pc/n
Percent time-spent-following, PTSFd	33.0	00	
Level of Service and Other Performance.	rmance Me	easures	
Level of service, LOS	С		
Volume to capacity ratio, v/c	0.22		
Peak 15-min vehicle-miles of travel, VMT15	59	veh-mi	
Peak-hour vehicle-miles of travel, VMT60	185	veh-mi	
Peak 15-min total travel time, TT15	1.2	veh-h	
Capacity from ATS, CdATS	1098	veh/h	
Capacity from PTSF, CdPTSF	1700	veh/h	
Directional Capacity	1098	veh/h	
Passing Lane Analys:	is		
Total length of analysis segment. Lt		1 0	mi
Length of two-lane highway unstream of the naggin	ng lang	T.11 0 0	mi
Longth of pagging lane ingluding taporg. Inl	ing rane,	1 0	mi
Dengen of passing falle including tapers, up		10 0	⊥ 
Average travel speed, ATSG (from above)		48.9	m1/11
Percent time-spent-following, PTSFd (from above)		33.0	
Level of service, LOSd (from above)		C	
Average Travel Speed with Pas	ssing Lar	1e	
Downstream length of two-lane highway within effe	ective		
length of passing lane for average travel spe Length of two-lane highway downstream of effective	eed, Lde ve	0.00	mi
length of the passing lane for average trave. Adj. factor for the effect of passing lane	l speed,	Ld 0.00	mi
on average speed, fpl		1.07	
Average travel speed including passing lane, ATS	pl	52.4	
Percent free flow speed including passing lane, I	PFFSpl	94.7	010
Percent Time-Spent-Following with	h Passing	g Lane	
Downstream length of two-lane highway within eff	ective le	angth	
of passing lane for percent time-spent-follow	wing, Lde	e 0.00	mi
Length of two-lane highway downstream of effectiv	ve length	n of	
the passing lane for percent time-spent-follo Adj factor for the effect of passing lane	owing, Lo	a 0.00	mi
on percent time-spent-following, fpl		0.20	
Percent time-spent-following			
including passing lane, PTSFpl		6.6	90
Level of Service and Other Performance Meas	sures wit	ch Passing	Lane
Level of service including passing lang IOST	Þ		
Peak 15-min total travel time, TT15	1.1	veh-h	
Bicycle Level of Serv	ice		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	237.2
Effective width of outside lane, We	21.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	5.32
Bicycle LOS	Ε

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Analysis Time Period PM Peak Highway SR 28 - Existing CL NB4 2.25 mi south of South Main St From/To Clover Township, Jefferson Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.76 Highway class Class 1 Shoulder width 5.0 ft % Trucks and buses 9 % 11.0 ft % Trucks crawling 1.0 mi Truck crawl speed 0.0 Lane width % 0.0 Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 Grade: Length 0.81 mi % No-passing zones 0 % Access point density 12 /mi Up/down 5.1 00 Analysis direction volume, Vd 158 veh/h Opposing direction volume, Vo 285 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 7.9 1.3 PCE for RVs, ER 1.0 1.3 Heavy-vehicle adj. factor,(note-5) fHV 0.617 0.974 0.65 Grade adj. factor,(note-1) fg 1.00 518 pc/h Directional flow rate, (note-2) vi 385 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 3.0 mi/h Free-flow speed, FFSd 55.3 mi/h mi/h Adjustment for no-passing zones, fnp 1.3 Average travel speed, ATSd 47.0 mi/h Percent Free Flow Speed, PFFS 84.9 ŝ

Percent Time-Spent-Follows	ing		
DirectionAnalysis(d)PCE for trucks, ET1.0PCE for RVs, ER1.0Heavy-vehicle adjustment factor, fHV1.000Grade adjustment factor, (note-1) fg1.00		Opposing 1.1 1.0 0.99 1.00	1
Directional flow rate, (note-2) vi 208 pc Base percent time-spent-following, (note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	c/h 25.7 13.1 30.3	378 % %	pc/h
Level of Service and Other Performa	ance Me	asures	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	C 0.20 52 158 1.1 1052 1700 1052	veh-mi veh-mi veh-h veh/h veh/h veh/h	
Passing Lane Analysis_			
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	1.0 Lu 0.0 1.0 47.0 30.3 C	mi mi mi/h
Average Travel Speed with Passi	ing Lan	.e	
Downstream length of two-lane highway within effect length of passing lane for average travel speed Length of two-lane highway downstream of effective	cive d, Lde	0.00	mi
length of the passing lane for average travel s Adj. factor for the effect of passing lane	speed,	Ld 0.00	mi
on average speed, fpl Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFF	FSpl	1.07 50.3 90.9	8
Percent Time-Spent-Following with H	Passing	Lane	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followir Length of two-lane highway downstream of effective	tive le ng, Lde length	ength e 0.00 u of	mi
the passing lane for percent time-spent-following Adj. factor for the effect of passing lane	ing, Ld	l 0.00	mi
on percent time-spent-following, fpl Percent time-spent-following including passing lane PTSFpl		0.20 6 1	<u>0</u>
Level of Service and Other Performance Measure	res wit	h Passing	Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	B 1.0	veh-h	
Bicycle Level of Service	e		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	207.9
Effective width of outside lane, We	24.36
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	4.87
Bicycle LOS	Е

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Agency/co.Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 - Existing CL SB1 near SR 1027 From/To Boggs Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.88 Highway class Class 1 Shoulder width5.0ft% Trucks and buses15Lane width11.0ft% Trucks crawling0.0Segment length1.2miTruck crawl speed0.0 % % mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 0.99 mi % No-passing zones 0 6.4 % Access point density 5 Grade: Length 8 Up/down 6.4 /mi Analysis direction volume, Vd 217 veh/h Opposing direction volume, Vo 151 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 10.3 1.6 PCE for RVs, ER 1.4 1.0 Heavy-vehicle adj. factor,(note-5) fHV 0.419 0.917 Grade adj. factor,(note-1) fg 0.58 1.00 1015 pc/h Directional flow rate,(note-2) vi 187 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 1.3 mi/h Free-flow speed, FFSd 57.0 mi/h mi/h Adjustment for no-passing zones, fnp 1.5 Average travel speed, ATSd 46.2 mi/h Percent Free Flow Speed, PFFS 81.0 %

Percent Time-	-Spent-Followi	ing			
Direction PCE for trucks. ET	Analysis(d)		Opp	osing 1.1	( 0 )
PCE for RVs. ER	1.0			1.0	
Heavy-vehicle adjustment factor, fHV	0.993			0.985	5
Grade adjustment factor.(note-1) fg	1.00			1.00	
Directional flow rate, (note-2) vi	248 pc	c/h		174	pc/h
Base percent time-spent-following, (not	ce-4) BPTSFd	25.9	00		F. C. /
Adjustment for no-passing zones, fnp		14.8			
Percent time-spent-following, PTSFd		34.6	00		
Level of Service and (	)ther Performa	ance Me	easur	res	
Level of service LOS		С			
Volume to gapagity ratio $w/g$		0 31			
Dock 15 min wohigle miles of travel 1	7M.T.1 5	0.54 7/	110	h mi	
Peak 15-mill venicie-miles of travel, (		74	ve	-11-1111 	
Peak-nour vehicle-miles of travel, VM	.60	200 1 C	VE		
Peak 15-min total travel time, TT15		1.0	ve	en-n	
Capacity from ATS, CdATS		121	ve	en/h	
Capacity from PTSF, CdPTSF		1652	ve	eh/h	
Directional Capacity		721	ve	eh/h	
Passing I	ane Analysis_				
Total length of analysis segment. Lt				1.2	mi
Length of two-lane highway upstream of	the passing	lane.	Lu	0.0	mi
Length of passing lane including taper	rs. Lol	,		1 2	mi
Average travel speed ATSd (from above				46 2	mi/h
Percent time-spent-following PTSEd (f	from above)			34 6	
Level of service. LOSd (from above)	itom above,			C	
				C	
Average Travel Spee	ed with Passi	ing Lan	le		
Downstream length of two-lane highway	within effect	cive			
length of passing lane for average	e travel speed	d, Lde		0.00	mi
Length of two-lane highway downstream	of effective	.,			
length of the passing lane for ave	rage travel s	speed	ЪЛ	0 00	mi
Adj factor for the effect of passing	lano	speca,	Ца	0.00	
an average greed fri	Talle			1 1 1	
Dir average speed, ipi					
Average craver speed including passing	j lane, Alopi	70-7		02.7	Q,
Percent free from speed including pass	sing lane, Pri	гарт		92.5	6
Percent Time-Spent-Fol	lowing with B	Passing	l Lar	ne	
Downstream length of two-lane highway	within effect	tive le	nath	1	
of passing lane for percent time-s	spent-followir	na. Ide		0.00	mi
Length of two-lane highway downstream	of effective	lenath	I of	5.00	
the passing lane for percent time	gnent_follow;	ing ta		0 00	mi
Adi factor for the officet of paceting	lane	тид, по	L	0.00	
Auj. Lactor for the effect of passing				0 00	
on percent time-spent-following, I	Ът			0.20	
including passing lane, PTSFpl				6.9	00
			h n-	aataa	Lana
Level of Service and Other Perio	ormance Measur	es wit	.m Pa	assing	Lane
Level of service including passing lar	ne, LOSpl	В			
Peak 15-min total travel time. TT15		_ 1.4	ve	h-h	
- call 10 min cocar craver crac, 1115		<b>- •</b> •	vC		
Bicycle Lev	vel of Service	e			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	246.6
Effective width of outside lane, We	21.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	8.40
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodPM Peak 1/30/2020 Highway SR 28 - Existing CL SB1 near SR 1027 From/To Boggs Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.95 Highway class Class 1 Shoulder width 5.0 ft % Trucks and buses 13 % 11.0ft% Trucks crawling0.01.2miTruck crawl speed0.0 Lane width % Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 0.99 mi % No-passing zones 0 6.4 % Access point density 5 Grade: Length 8 Up/down 6.4 /mi Analysis direction volume, Vd 182 veh/h Opposing direction volume, Vo 295 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 10.3 1.4 PCE for RVs, ER 1.5 1.0 Heavy-vehicle adj. factor,(note-5) fHV 0.454 0.951 Grade adj. factor,(note-1) fg 0.55 1.00 767 pc/h Directional flow rate, (note-2) vi 327 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 1.3 mi/h Free-flow speed, FFSd 57.0 mi/h mi/h Adjustment for no-passing zones, fnp 1.5 47.1 Average travel speed, ATSd mi/h Percent Free Flow Speed, PFFS 82.6 %

Percent Time-Spent-Followi	ing		
DirectionAnalysis(d)PCE for trucks, ET1.0PCE for RVs, ER1.0Heavy-vehicle adjustment factor, fHV1.000Grade adjustment factor, (note-1) fg1.00		Opposing 1.1 1.0 0.987 1.00	(o) 7
Directional flow rate, (note-2) vi 192 po Base percent time-spent-following, (note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	c/h 23.8 14.0 29.1	315 % %	pc/h
Level of Service and Other Performa	ance Me	asures	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	C 0.25 57 218 1.2 780 1659 780	veh-mi veh-mi veh-h veh/h veh/h veh/h	
Passing Lane Analysis_			
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	1.2 Lu 0.0 1.2 47.1 29.1 C	mi mi mi/h
Average Travel Speed with Passi	ing Lan	.e	
Downstream length of two-lane highway within effect length of passing lane for average travel speed Length of two-lane highway downstream of effective	cive 1, Lde	0.00	mi
length of the passing lane for average travel s Adj. factor for the effect of passing lane on average speed, fpl	speed,	Ld 0.00	mi
Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFF	FSpl	53.7 94.1	20
Percent Time-Spent-Following with F	Passing	Lane	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followir Length of two-lane highway downstream of effective	tive le ng, Lde length	ength e 0.00 u of	mi
the passing lane for percent time-spent-following Adj. factor for the effect of passing lane	ing, Ld	0.00	mi
on percent time-spent-following, fpl Percent time-spent-following including passing lane, PTSFpl		5.8	00
Level of Service and Other Performance Measur	res wit	h Passing	Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	B 1.1	veh-h	
Bicycle Level of Service	2		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	191.6
Effective width of outside lane, We	21.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	7.29
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Agency/co.Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 - Existing CL SB2 north of Calhoun Rd From/To Jurisdiction Mahoning Twnshp, Armstrong Co Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.88 Highway class Class 1 Shoulder width 8.0 ft % Trucks and buses 15 % 11.0ft% Trucks crawling0.01.7miTruck crawl speed0.0 Lane width % Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type % Length1.39mi% No-passing zones0Up/down5.9%Access point density4 Grade: Length 8 /mi Analysis direction volume, Vd 217 veh/h Opposing direction volume, Vo 151 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 11.5 1.6 PCE for RVs, ER 1.4 1.0 Heavy-vehicle adj. factor,(note-5) fHV 0.387 0.917 Grade adj. factor,(note-1) fg 0.57 1.00 1118 pc/h Directional flow rate,(note-2) vi 187 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed,(note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 1.0 mi/h Free-flow speed, FFSd 58.6 mi/h mi/h Adjustment for no-passing zones, fnp 1.6 Average travel speed, ATSd 46.8 mi/h Percent Free Flow Speed, PFFS 79.9 %

Percent Time-Spent-Follow	ing			
DirectionAnalysis(d)PCE for trucks, ET1.4PCE for RVs, ER1.0		Opp	osing 1.1 1.0	( 0 )
Heavy-vehicle adjustment factor, fHV 0.943 Grade adjustment factor, (note-1) fg 1.00 Directional flow rate (note-2) vi 261 p	c/h		0.985 1.00	b DC/h
Base percent time-spent-following, (note-4) BPTSFd Adjustment for no-passing zones, fnp	27.0	00	1/1	pc/ II
Percent time-spent-following, PTSFd	35.9	5		
Level of Service and Other Perform	ance Me	easur	es	
Level of service, LOS	С			
Volume to capacity ratio, v/c	0.37			
Peak 15-min vehicle-miles of travel, VMT15	105	ve	h-mi-	
Peak-hour vehicle-miles of travel VMT60	369	ve	h-mi	
Deak 15-min total travel time TT15	2 2	v C 17 C	h_h	
Capacity from ATS COMTS	670	v C 17 C	h/h	
Capacity from DECE (dDECE	1 5 7 0	v e	$\frac{11}{11}$	
Capacity from PTSF, COPTSF	15/9	VE		
Directional Capacity	670	Ve	iu/u	
Passing Lane Analysis				
Total length of analysis segment Lt			1 7	mi
Length of two-lane highway unstream of the pagging	lane	Τ.,		mi
Length of pagging long including tapong. In	Talle,	шu	1 7	mi
Dengen of passing fane including tapers, up			$\perp$ ./	lll⊥ 
Average travel speed, Also (from above)			40.0	111 / 11
Percent time-spent-following, PTSFd (from above)			35.9	
Level of service, LOSd (from above)			C	
Average Travel Speed with Pass	ing Lar	ne		
Downstream length of two-lane highway within effec	+ 1 770			
length of passing lane for average travel spee	d, Lde		0.00	mi
Length of two-lane highway downstream of effective	_	_		
length of the passing lane for average travel	speed,	Ld	0.00	mi
Adj. factor for the effect of passing lane				
on average speed, tpl			1.14	
Average travel speed including passing lane, ATSpl			53.4	
Percent free flow speed including passing lane, PF	FSpl		91.1	00
Percent Time-Spent-Following with	Passing	g Lar	1e	
Deverture levels of the level bighter within offer	+ 1 -		_	
of pagaing long for research time means follow		-iig t i	1 0 0 0	
of passing lane for percent time-spent-followi	ng, Lae	3	0.00	mı
Length of two-lane highway downstream of effective	lengtr	l OI		
the passing lane for percent time-spent-follow	ing, Lo	1	0.00	mı
Adj. factor for the effect of passing lane				
on percent time-spent-following, fpl			0.20	
Percent time-spent-following				
including passing lane, PTSFpl			7.2	00
Level of Service and Other Performance Measu	res wit	ch Pa	assing	Lane
Lovel of gervice including pagaing long 100-1	D			
Deck 15 min total traval time mult	р 2 0		h h	
reak 15-min local llavel lime, TT15	∠.∪	VE	:11-11	
Bicycle Level of Servic	e			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	246.6
Effective width of outside lane, We	27.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	6.96
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodPM Peak 1/30/2020 Highway SR 28 - Existing CL SB2 north of Calhoun Rd From/To Jurisdiction Mahoning Twnshp, Armstrong Co Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.95 Highway class Class 1 Shoulder width 8.0 ft % Trucks and buses 13 % 11.0ft% Trucks crawling0.0%1.7miTruck crawl speed0.0mi/hr Lane width Segment length Specific Grade % Recreational vehicles 0 Terrain type 8 Length1.39mi% No-passing zones0Up/down5.9%Access point density4 Grade: Length 8 /mi Analysis direction volume, Vd 182 veh/h Opposing direction volume, Vo 295 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 11.5 1.4 PCE for RVs, ER 1.0 1.5 Heavy-vehicle adj. factor,(note-5) fHV 0.422 0.951 Grade adj. factor,(note-1) fg 0.54 1.00 841 pc/h Directional flow rate,(note-2) vi 327 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h \_ Observed total demand, (note-3) V veh/h Estimated Free-Flow Speed: Base free-flow speed,(note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 1.0 mi/h Free-flow speed, FFSd 58.6 mi/h mi/h Adjustment for no-passing zones, fnp 1.5 Average travel speed, ATSd 48.0 mi/h Percent Free Flow Speed, PFFS 81.9 %

Percent Time-Spent-Followi	ing		
DirectionAnalysis(d)PCE for trucks, ET1.4PCE for RVs, ER1.0Heavy-vehicle adjustment factor, fHV0.952Grade adjustment factor, (note-1) fg1.00Directional flow rate, (note-2) vi201 pcBase percent time-spent-following (note-4)BPTSEd	c/h 24 7	Opposing 1.1 1.0 0.98 1.00 315	(0) 7 pc/h
Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	14.0 30.2	o 0	
Level of Service and Other Performa	ance Me	easures	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	C 0.26 81 309 1.7 728 1594 728	veh-mi veh-mi veh-h veh/h veh/h veh/h	
Passing Lane Analysis_			
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	1.7 Lu 0.0 1.7 48.0 30.2 C	mi mi mi/h
Average Travel Speed with Passi	ing Lan	ie	
Downstream length of two-lane highway within effect length of passing lane for average travel speed Length of two-lane highway downstream of effective	cive 1, Lde	0.00	mi
length of the passing lane for average travel s Adj. factor for the effect of passing lane	speed,	Ld 0.00	mi
Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFF	FSpl	54.7 93.4	8
Percent Time-Spent-Following with H	Passing	Jane	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followir Length of two-lane highway downstream of effective	tive le ng, Lde length	ength e 0.00 n of	mi
the passing lane for percent time-spent-followi Adj. factor for the effect of passing lane	ing, Ld	l 0.00	mi
on percent time-spent-following, fpf Percent time-spent-following including passing lane, PTSFpl		6.0	20
Level of Service and Other Performance Measur	res wit	h Passing	Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	B 1.5	veh-h	
Bicycle Level of Service	2		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	191.6
Effective width of outside lane, We	27.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	5.85
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 - Existing CL SB3 btw Distant and S Bethlehem From/To Mahoning Twnshp, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.95 Highway class Class 1 Angriway classClassIPeak nour factor, PHF0.95Shoulder width10.0ft% Trucks and buses13Lane width11.0ft% Trucks crawling0.0Segment length0.9miTruck crawl speed0.0 % % mi/hr Specific Grade % Recreational vehicles 0 Terrain type % 0.69 mi % No-passing zones 0 4.8 % Access point density 2 Grade: Length 8 Up/down /mi Analysis direction volume, Vd 232 veh/h Opposing direction volume, Vo 285 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 7.1 1.4 PCE for RVs, ER 1.3 1.0 Heavy-vehicle adj. factor,(note-5) fHV 0.556 0.951 Grade adj. factor,(note-1) fg 0.68 1.00 646 pc/h Directional flow rate, (note-2) vi 316 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 0.5 mi/h Free-flow speed, FFSd 59.1 mi/h mi/h Adjustment for no-passing zones, fnp 1.6 Average travel speed, ATSd 50.1 mi/h Percent Free Flow Speed, PFFS 84.7 %

Percent Time-Spent-Follow	ving		
Direction Analysis(d) PCE for trucks, ET 1.0		Opposing 1.1	( 0 )
PCE for RVs, ER1.0Heavy-vehicle adjustment factor, fHV1.000Grade adjustment factor, (note-1) fg1.00		1.0 0.987 1.00	
Directional flow rate, (note-2) vi 244 p Base percent time-spent-following, (note-4) BPTSFd	28.0	304 %	pc/h
Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	15.3 34.8	00	
Level of Service and Other Perform	nance Me	easures	
Level of service, LOS	В		
Volume to capacity ratio, v/c	0.25		
Peak 15-min vehicle-miles of travel, VMT15	55	veh-mi	
Peak-nour vehicle-miles of travel, VMT60	209	ven-mi web b	
Capacity from ATS COATS	1.1 976	ven-n veh/h	
Capacity from DTSE CODTSE	970 1700	vell/ll veh/h	
Directional Capacity	976	veh/h	
Passing Lane Analysis	8		
Total length of analysis segment, Lt		0.9	mi
Length of two-lane highway upstream of the passing	g lane,	Lu 0.0	mi
Length of passing lane including tapers, Lpl		0.9	mi
Average travel speed, ATSd (from above)		50.1	mi/h
Percent time-spent-following, PTSFd (from above)		34.8	
Level of service, LOSd (from above)		В	
Average Travel Speed with Pass	sing Lar	ne	
Downstream length of two-lane highway within effect	ctive		
length of passing lane for average travel spee Length of two-lane highway downstream of effective	ed, Lde e	0.00	mi
length of the passing lane for average travel Adj. factor for the effect of passing lane	speed,	Ld 0.00	mi
on average speed, fpl		1.14	
Average travel speed including passing lane, ATSpl	-	57.1	
Percent free flow speed including passing lane, PF	FSpl	96.6	010
Percent Time-Spent-Following with	Passing	g Lane	
Downstream length of two-lane highway within effect	tive le	ength	mi
Length of two-lane highway downstream of effective	lenath		1111
the passing lane for percent time-spent-follow	ving, Lo	d 0.00	mi
on percent time-spent-following, fpl		0.20	
Percent time-spent-following including passing lane, PTSFpl		7.0	00
Level of Service and Other Performance Measu	ires wit	ch Passing	Lane
Level of service including passing lane IOSpl	Δ		
Peak 15-min total travel time, TT15	1.0	veh-h	
Bicycle Level of Servic	ce		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	244.2
Effective width of outside lane, We	31.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	4.81
Bicycle LOS	Ε

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Date Performed1/30/202Analysis Time PeriodPM Peak Highway SR 28 - Existing CL SB3 Btw Distant and S Bethlehem From/To Mahoning Twnshp, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.89 Highway class Class 1 Highway classClassFillPeak nour factor, Phr0.09Shoulder width10.0ft% Trucks and buses4Lane width11.0ft% Trucks crawling0.0Segment length0.9miTruck crawl speed0.0 % % mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 0.69 mi % No-passing zones 0 4.8 % Access point density 2 Grade: Length 8 Up/down /mi Analysis direction volume, Vd 312 veh/h Opposing direction volume, Vo 332 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 7.1 1.3 PCE for RVs, ER 1.0 1.2 Heavy-vehicle adj. factor,(note-5) fHV 0.803 0.988 0.74 Grade adj. factor,(note-1) fg 1.00 590 pc/h Directional flow rate, (note-2) vi 378 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed,(note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 0.5 mi/h Free-flow speed, FFSd 59.1 mi/h mi/h Adjustment for no-passing zones, fnp 1.4 Average travel speed, ATSd 50.2 mi/h Percent Free Flow Speed, PFFS 84.9 %

Percent Time-Spent-Followi	ing		
Direction Analysis(d) PCE for trucks, ET 1.0 PCE for RVs, ER 1.0 Heavy-vehicle adjustment factor, fHV 1.000 Grade adjustment factor,(note-1) fg 1.00 Directional flow rate,(note-2) vi 351 pc	c/h	Opposing 1.1 1.0 0.99 1.00 375	(0) 6 pc/h
Base percent time-spent-following,(note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	38.5 15.5 46.0	010 010	
Level of Service and Other Performa	ance Me	asures	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	B 0.25 79 281 1.6 1384 1700 1384	veh-mi veh-mi veh-h veh/h veh/h veh/h	
Passing Lane Analysis_			
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	0.9 Lu 0.0 0.9 50.2 46.0 B	mi mi mi/h
Average Travel Speed with Passi	ing Lan	e	
Downstream length of two-lane highway within effect length of passing lane for average travel speed Length of two-lane highway downstream of effective	ive 1, Lde	0.00	mi
length of the passing lane for average travel s Adj. factor for the effect of passing lane on average speed, fpl	speed,	Ld 0.00 1.07	mi
Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFF	Spl	53.7 90.8	<u>0</u>
Percent Time-Spent-Following with B	Passing	Lane	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followir Length of two-lane highway downstream of effective	ive le ng, Lde length	ength 0.00 of	mi
the passing lane for percent time-spent-followi Adj. factor for the effect of passing lane	ing, Ld	0.00	mi
on percent time-spent-following, fpl Percent time-spent-following including passing lane PTSEpl		0.21	9
Level of Service and Other Performance Measur	res wit	h Passing	Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	B 1.5	veh-h	
Bicycle Level of Service	2		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	350.6
Effective width of outside lane, We	31.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	1.63
Bicycle LOS	В

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Date Performed1/30/202Analysis Time PeriodAM Peak Highway SR 28 - Existing CL SB4 Just west of Summerville From/To Jurisdiction Clover Township, Jefferson Co Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.83 Highway class Class 1 Shoulder width 5.0 ft % Trucks and buses 12 % 11.0ft% Trucks crawling0.01.1miTruck crawl speed0.0 Lane width % Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 0.88 mi % No-passing zones 0 6.0 % Access point density 5 Grade: Length 8 Up/down 6.0 /mi Analysis direction volume, Vd 73 veh/h Opposing direction volume, Vo 154 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 9.7 1.6 PCE for RVs, ER 1.0 1.6 Heavy-vehicle adj. factor,(note-5) fHV 0.489 0.933 0.47 Grade adj. factor,(note-1) fg 1.00 383 pc/h Directional flow rate, (note-2) vi 199 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 1.3 mi/h Free-flow speed, FFSd 57.0 mi/h mi/h Adjustment for no-passing zones, fnp 1.7 Average travel speed, ATSd 50.9 mi/h Percent Free Flow Speed, PFFS 89.2 %

Percent Time-Spent-Follo	wing		
DirectionAnalysis(d)PCE for trucks, ET1.0PCE for RVs, ER1.0		Opposing 1.1 1.0	( 0 )
Heavy-vehicle adjustment factor, fHV1.000Grade adjustment factor, (note-1) fg1.00	(1	0.988	<i>(</i> <b>1</b>
Base percent time-spent-following, (note-4) BPTSFd	pc/n l 10.3	% 188	pc/n
Percent time-spent-following, PTSFd	13.7	0- 0	
Level of Service and Other Perfor	mance Me	asures	
Level of service, LOS	В		
Volume to capacity ratio, v/c	0.11		
Peak 15-min vehicle-miles of travel, VMT15	24	veh-mi	
Peak-hour vehicle-miles of travel, VMT60	80	veh-mı	
Peak 15-min total travel time, TT15	0.5	veh-h	
Capacity from ATS, CdATS	836	veh/h	
Capacity from PTSF, CdPTSF	1679	veh/h	
Directional Capacity	836	veh/h	
Passing Lane Analysi	.s		
Total length of analysis segment, Lt		1.1	mi
Length of two-lane highway upstream of the passin	ıg lane,	Lu 0.0	mi
Length of passing lane including tapers, Lpl		1.1	mi
Average travel speed, ATSd (from above)		50.9	mi/h
Percent time-spent-following, PTSFd (from above)		13.7	
Level of service, LOSd (from above)		В	
Average Travel Speed with Pas	sing Lan	.e	
Downstream length of two-lane highway within effe	octive		
length of passing lane for average travel spe Length of two-lane highway downstream of effectiv	ed, Lde	0.00	mi
length of the passing lane for average travel Adj. factor for the effect of passing lane	speed,	Ld 0.00	mi
on average speed, fpl		1.07	
Average travel speed including passing lane, ATSp	1	54.4	
Percent free flow speed including passing lane, P	FFSpl	95.4	00
Percent Time-Spent-Following with	Passing	Lane	
Downstream length of two-lane highway within effe	ctive le	ngth	
of passing lane for percent time-spent-follow	ving, Lde	0.00	mi
Length of two-lane highway downstream of effectiv	re length	. oi	
the passing lane for percent time-spent-follo	wing, Ld	0.00	mı
Adj. factor for the effect of passing lane			
on percent time-spent-following, fpl		0.20	
Percent time-spent-following including passing lane, PTSFpl		2.7	8
Level of Service and Other Derformance Meas	ureg wit	h Passing	Lane
ICVEL OF SERVICE and Other Ferrormance Meas	-	II FADDINY	
Level of service including passing lane, LOSpl	В	, ,	
Peak 15-min total travel time, TT15	0.4	veh-h	
Bicycle Level of Servi	.ce		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	88.0
Effective width of outside lane, We	31.16
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	3.79
Bicycle LOS	D

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Date Performed1/30/20.Analysis Time PeriodPM Peak Highway SR 28 - Existing CL SB4 Just west of Summerville From/To Jurisdiction Clover Township, Jefferson Co Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.85 Highway class Class 1 Shoulder width 5.0 ft % Trucks and buses б % 11.0ft% Trucks crawling0.01.1miTruck crawl speed0.0 Lane width % Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 0.88 mi % No-passing zones 0 6.0 % Access point density 5 Grade: Length % Up/down 6.0 /mi Analysis direction volume, Vd 214 veh/h Opposing direction volume, Vo 125 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 9.7 1.7 PCE for RVs, ER 1.0 1.4 Heavy-vehicle adj. factor,(note-5) fHV 0.656 0.960 Grade adj. factor,(note-1) fg 0.59 1.00 650 pc/h Directional flow rate, (note-2) vi 153 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 1.3 mi/h Free-flow speed, FFSd 57.0 mi/h mi/h Adjustment for no-passing zones, fnp 1.2 49.7 Average travel speed, ATSd mi/h Percent Free Flow Speed, PFFS 87.1 ŝ

Percent Time	e-Spent-Followi	ing		
Direction PCE for trucks, ET	Analysis(d) 1.0	QD	posing 1.1	( 0 )
PCE for RVs, ER	1.0		1.0	
Heavy-vehicle adjustment factor, fHV	0.998		0.994	
Grade adjustment factor.(note-1) fg	1.00		1.00	
Directional flow rate (note-2) vi	252 pc	r/h	148	pc/h
Base percent time-spent-following (no	TP-4) RDTSFd	26.2 %	110	20/11
Adjustment for no-passing zones from	Jee I, Bribia	122		
Dergent time_gnent_following DTSEd		13.5 21.6 8		
reicent time-spent-tottowing, rista		54.0 %		
Level of Service and	Other Performa	ance Measu	res	
Level of service, LOS		С		
Volume to capacity ratio, $v/c$		0 22		
Deak 15-min vehicle-miles of travel	<u>ت</u> אתי15	69 v	oh-mi	
Desk-bour webigle-miles of travel W	νμτε0	225 77	ch mi	
Poak 15 min total travel time TT15	1100	255 V 1 / <del>1</del>		
Peak 15-min total travel time, 1115		1.4 V		
Capacity from AIS, COAIS		1120 V		
Capacity from PTSF, CoPTSF		1689 V	en/n	
Directional Capacity		1120 V	eh/h	
Passing	Lane Analysis_			
Total longth of analyzing gogmont. It			1 1	mi
Ionath of two long highway upstroom	of the persing	lana Iu	1.1	mi
Length of two-falle highway upstream (	or the passing	Iane, Lu	0.0	····
Length of passing lane including tape	èrs, црі			m1
Average travel speed, ATSd (from abov	ze)		49.7	mı/n
Percent time-spent-following, PTSFd	(from above)		34.6	
Level of service, LOSd (from above)			С	
Average Travel Spe	eed with Passi	ing Lane		
Downstream length of two-lane highway	/ within effect	lve	0 00	
length of passing lane for average	ge travel speed	d, Lae	0.00	mı
Length of two-lane highway downstream	n of effective			
length of the passing lane for av	verage travel s	speed, Ld	0.00	mi
Adj. factor for the effect of passing	g lane			
on average speed, fpl			1.14	
Average travel speed including passing	ng lane, ATSpl		56.6	
Percent free flow speed including pas	ssing lane, PFE	FSpl	99.2	00
Percent Time-Spent-Fo	ollowing with B	Passing La	ne	
Downstream length of two-lane highway	y within effect	tive lengt	h	
of passing lane for percent time-	-spent-followir	ng, Lde	0.00	mi
Length of two-lane highway downstream	n of effective	length of		
the passing lane for percent time	e-spent-followi	ing, Ld	0.00	mi
Adj. factor for the effect of passing	g lane			
on percent time-spent-following,	fpl		0.20	
Percent time-spent-following	L			
including passing lane, PTSFpl			6.9	00
Level of Service and Other Peri	formance Measur	res with P	assing	Lane
			-	
Level of service including passing la	ane, LOSpl	A		
Peak 15-min total travel time, TT15		1.2 v	eh-h	
Biquele Le	evel of Service	2		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	251.8
Effective width of outside lane, We	21.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	4.67
Bicycle LOS	Ε

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Date Performed1/30/202Analysis Time PeriodAM Peak Highway SR 28 - Existing CL SB5 1.1 miles S of S Main St From/To Rose Township, Jefferson Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.80 Highway class Class 1 Shoulder width 6.0 ft % Trucks and buses 12 % 11.0ft% Trucks crawling0.01.4miTruck crawl speed0.0 Lane width % Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 Grade: Length 1.21 mi % No-passing zones 0 % Access point density 15 /mi Up/down 4.4 00 Analysis direction volume, Vd 106 veh/h Opposing direction volume, Vo 185 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 8.5 1.5 PCE for RVs, ER 1.0 1.3 Heavy-vehicle adj. factor,(note-5) fHV 0.526 0.943 Grade adj. factor, (note-1) fg 0.67 1.00 376 pc/h Directional flow rate, (note-2) vi 245 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 3.8 mi/h Free-flow speed, FFSd 55.8 mi/h mi/h Adjustment for no-passing zones, fnp 1.5 Average travel speed, ATSd 49.5 mi/h Percent Free Flow Speed, PFFS 88.7 ŝ

Percent Time-Spent-Follows	ing		
DirectionAnalysis(d)PCE for trucks, ET1.0PCE for RVs, ER1.0Heavy-vehicle adjustment factor, fHV0.995Grade adjustment factor, (note-1) fg1.00Directional flow rate, (note-2) vi133 pcPage pergent time grant following (note 4) PDTSEd	c/h	Opposing 1.1 1.0 0.988 1.00 234	(o) B pc/h
Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	12.7 20.1	8 8	
Level of Service and Other Performa	ance Me	easures	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	C 46 148 0.9 1131 1649 1131	veh-mi veh-mi veh-h veh/h veh/h veh/h	
Passing Lane Analysis_			
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	1.4 Lu 0.0 1.4 49.5 20.1 C	mi mi mi/h
Average Travel Speed with Passi	ing Lan	1e	
Downstream length of two-lane highway within effect length of passing lane for average travel speed Length of two-lane highway downstream of effective	tive d, Lde	0.00	mi
Adj. factor for the effect of passing lane on average speed, fpl	speed,	1.07	
Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFF	FSpl	53.0 94.9	80
Percent Time-Spent-Following with F	Passing	g Lane	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followin Length of two-lane highway downstream of effective	tive le ng, Lde length	ength e 0.00 1 of	mi
the passing lane for percent time-spent-follows Adj. factor for the effect of passing lane	ing, Ld	a 0.00	mi
on percent time-spent-following, fpl Percent time-spent-following including passing lane, PTSFpl		4.0	8
Level of Service and Other Performance Measur	res wit	h Passing	Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	B 0.9	veh-h	
Bicycle Level of Service	e		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	132.5
Effective width of outside lane, We	30.99
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	4.05
Bicycle LOS	D

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Date Performed1/30/20.Analysis Time PeriodPM Peak Highway SR 28 - Existing CL SB5 1.1 miles S of S Main St From/To Rose Township, Jefferson Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.69 Highway class Class 1 Shoulder width 6.0 ft % Trucks and buses 6 % 11.0ft% Trucks crawling0.01.4miTruck crawl speed0.0 Lane width % Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 Grade: Length 1.21 mi % No-passing zones 0 8 Access point density 15 /mi Up/down 4.4 00 Analysis direction volume, Vd 285 veh/h Opposing direction volume, Vo 158 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 7.9 1.5 PCE for RVs, ER 1.0 1.0 Heavy-vehicle adj. factor,(note-5) fHV 0.708 0.971 Grade adj. factor,(note-1) fg 0.82 1.00 711 pc/h Directional flow rate, (note-2) vi 236 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 3.8 mi/h Free-flow speed, FFSd 55.8 mi/h mi/h Adjustment for no-passing zones, fnp 1.5 47.0 Average travel speed, ATSd mi/h Percent Free Flow Speed, PFFS 84.1 %

Percent Time-Spent-Follow:	ing		
DirectionAnalysis(d)PCE for trucks, ET1.0PCE for RVs, ER1.0User webigle adjustment factor full1.000		Opposing 1.1 1.0	(0)
Grade adjustment factor, inv 1.000 Directional flow rate, (note-2) vi 418	c/h	0.99 1.00 230	4 pc/h
Base percent time-spent-following,(note-4) BPTSFd Adjustment for no-passing zones, fnp	39.8 12.9	8	F 0 / 11
Percent time-spent-following, PTSFd	48.1	00	
Level of Service and Other Performa	ance Mea	asures	
Level of service, LOS	С		
Volume to capacity ratio, v/c	0.30		
Peak 15-min vehicle-miles of travel VMT15	145	veh-mi	
Desk-hour vehicle-miles of travel VMT60	200	ven mi	
Deak 15 min total travel time TT15	2 1		
Generative from ANG GAANG	J.⊥ 1.2E0	vell-ll	
Capacity from AIS, COAIS	1358	ven/n	
Capacity from PTSF, COPTSF	1649	ven/n	
Directional Capacity	1358	veh/h	
Passing Lane Analysis			
Total length of analysis segment Lt		14	mi
Longth of two long highway ungtroom of the pagging	lana T		mi
Length of two-falle highway upstream of the passing	Ialle, I	1 U.U	
Length of passing fane including tapers, Lpi		1.4	
Average travel speed, ATSd (from above)		47.0	mı/h
Percent time-spent-following, PTSFd (from above)		48.1	
Level of service, LOSd (from above)		C	
Average Travel Speed with Pass:	ing Lane	2	
Downstream length of two-lane highway within effect	- 1 170		
length of passing lane for average travel speed	d. Lde	0.00	mi
Length of two-lane highway downstream of effective	.,		
length of the pagging lane for average travel	aneed I	000 6.	mi
Adi factor for the officiat of pagaing lane	speed, i	Ja 0.00	
Auj. factor for the effect of passing falle		1 1 1	
on average speed, ipi		1.14	
Average travel speed including passing lane, ATSpl	1	53.6	•
Percent free flow speed including passing lane, PF	-Spl	95.9	6
Percent Time-Spent-Following with	Passing	Lane	
Downstream length of two-lane highway within effect	-ive ler	nath	
of pagging lang for pargent time_grant following		0 00	mi
Jensth of the long highway demotered of offerting	lg, Lue	0.00	
Length of two-lane highway downstream of effective	Tengtu	OI 0.00	
the passing lane for percent time-spent-follow:	ing, La	0.00	mı
Adj. factor for the effect of passing lane			
on percent time-spent-following, fpl		0.21	
Percent time-spent-following			
including passing lane, PTSFpl		10.1	00
Level of Service and Other Performance Measur	res with	n Passing	Lane
Lowel of gorwige including pagaing long (00-1	D		
Deck 15 min total traceal time mm15	D 0 7	Joh h	
Peak is-min colar travel time, TT15	2.1	ven-n	
Bicycle Level of Service	e		
Posted speed limit, Sp	55		
---	-------		
Percent of segment with occupied on-highway parking	0		
Pavement rating, P	3		
Flow rate in outside lane, vOL	413.0		
Effective width of outside lane, We	23.00		
Effective speed factor, St	4.79		
Bicycle LOS Score, BLOS	4.48		
Bicycle LOS	D		

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Date Performed1/30/202Analysis Time PeriodAM Peak Highway SR 28 - Proposed CL NBX1 Pine Furnace to SR 1029 From/To Boggs Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.82 Highway class Class 1 Shoulder width 3.0 ft % Trucks and buses 13 % 11.0 ft % Trucks crawling 1.4 mi Truck crawl speed Lane width 0.0 2 0.0 Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 1.38mi% No-passing zones100%4.0%Access point density13/mi Grade: Length Up/down Analysis direction volume, Vd 220 veh/h Opposing direction volume, Vo 403 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 8.7 1.2 PCE for RVs, ER 1.0 1.2 Heavy-vehicle adj. factor,(note-5) fHV 0.500 0.975 Grade adj. factor,(note-1) fg 0.75 1.00 715 pc/h Directional flow rate, (note-2) vi 504 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 3.0 mi/h Adj. for access point density,(note-3) fA 3.3 mi/h Free-flow speed, FFSd 53.8 mi/h 2.3 mi/h Adjustment for no-passing zones, fnp Average travel speed, ATSd 42.0 mi/h Percent Free Flow Speed, PFFS 78.1 %

Percent Time-Spent-Follow:	ing		
Direction Analysis(d) PCE for trucks, ET 1.0 PCE for RVs, ER 1.0 Heavy-vehicle adjustment factor, fHV 0.997 Grade adjustment factor,(note-1) fg 0.99 Directional flow rate,(note-2) vi 271 pc Base percent time-spent-following,(note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	c/h 34.0 40.9 48.5	Opposing 1.0 1.0 1.00 1.00 491 % %	(o) 0 pc/h
Level of Service and Other Performa	ance Me	easures	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	D 0.25 94 308 2.2 1063 1649 1063	veh-mi veh-mi veh-h veh/h veh/h veh/h	
Passing Lane Analysis_			
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	1.4 Lu - - 42.0 48.5 D	mi mi mi/h
Average Travel Speed with Pass:	ing Lar	ne	
Downstream length of two-lane highway within effect length of passing lane for average travel speed Length of two-lane highway downstream of effective	tive d, Lde	-	mi
Adj. factor for the effect of passing lane on average speed, fpl	speed,	Ld -	mı
Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFF	FSpl	- 0.0	8
Percent Time-Spent-Following with H	Passing	g Lane	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followin Length of two-lane highway downstream of effective	tive le ng, Lde length	ength e - n of	mi
the passing lane for percent time-spent-follow: Adj. factor for the effect of passing lane on percent time-spent-following, fpl	ing, Lo	- £	mi
Percent time-spent-following including passing lane, PTSFpl		-	<u>%</u>
Level of Service and Other Performance Measur	res wit	ch Passing	Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	E -	veh-h	
Bicycle Level of Service	e		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	268.3
Effective width of outside lane, We	14.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	8.69
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Analysis Time Period PM Peak Highway SR 28 - Proposed CL NBX1 Pine Furnace to SR 1029 From/To Boggs Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.94 Highway class Class 1 Shoulder width 3.0 ft % Trucks and buses б % 11.0 ft % Trucks crawling 1.4 mi Truck crawl speed Lane width 0.0 2 Segment length 0.0 mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 Grade: Length 1.38 mi % No-passing zones 100 8 Access point density 13 /mi Up/down 4.0 00 Analysis direction volume, Vd 542 veh/h Opposing direction volume, Vo 310 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 7.6 1.4 PCE for RVs, ER 1.0 1.0 Heavy-vehicle adj. factor,(note-5) fHV 0.715 0.977 Grade adj. factor,(note-1) fg 0.95 1.00 849 pc/h Directional flow rate, (note-2) vi 338 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 3.0 mi/h Adj. for access point density,(note-3) fA 3.3 mi/h Free-flow speed, FFSd 53.8 mi/h mi/h Adjustment for no-passing zones, fnp 3.2 Average travel speed, ATSd 41.4 mi/h Percent Free Flow Speed, PFFS 77.0 ŝ

Percent Time-Spent-Follow:	ing			
Direction Analysis(d) PCE for trucks ET 1 0		Opp	osing	( 0 )
$\begin{array}{ccc} \text{PCE IOI CLUCKS, EI & I.U \\ \text{DCF for RVg FR} & 1.0 \\ \end{array}$			1 0	
Heavy-vehicle adjustment factor fHV 1 000			1.0 0.994	L
Grade adjustment factor (note-1) fg 0.97			1 00	L
Directional flow rate. (note-2) vi 594 pc	r/h		332	pc/h
Base percent time-spent-following.(note-4) BPTSFd	53.7	8	001	F 0 / 11
Adjustment for no-passing zones, fnp	36.3	Ū.		
Percent time-spent-following, PTSFd	77.0	00		
Level of Service and Other Performa	ance Me	easur	es	
Lavel of complete LOG	D			
Level of service, Los				
Volume to capacity fatto, V/C	0.43		h	
Peak 15-min vehicle-miles of travel, VMT15	202	ve	n-mi b mi	
Peak-nour vehicle-miles of travel, VMT60	159	ve	n-mi b b	
Generative from ADC (dADC)	4.9	ve	11-11 h /h	
Capacity from ATS, COATS	1331 1640	ve	11/11 h/h	
Capacity from PTSF, COPTSF	1049 1021	ve	11/11 h/h	
Directional Capacity	1331	ve	11 / 11	
Passing Lane Analysis_				
Total length of analysis segment, Lt			1.4	mi
Length of two-lane highway upstream of the passing	lane,	Lu	-	mi
Length of passing lane including tapers, Lpl			-	mi
Average travel speed, ATSd (from above)			41.4	mi/h
Percent time-spent-following, PTSFd (from above)			77.0	
Level of service, LOSd (from above)			D	
Average Travel Speed with Pass:	ing Lan	.e		
De materie landth of the land high a dithin offer				
Downstream length of two-lane highway within effect	cive J rda			
Ingth of two long highway downstroom of offortive	л, цае		-	1111
Length of two-lane nighway downstream of effective		тa		
length of the passing lane for average travel s	speea,	Цα	-	mı
Adj. Tactor for the effect of passing lane				
Average speed, ipi			-	
Percent free flow greed including pagging lane, Alspi	renl		- 0	Q.
refeate field fill speed including passing fame, Fr	гэрт		0.0	o
Percent Time-Spent-Following with H	Passing	l Lan	e	
Downstream length of two-lane highway within effect	tive le	ngth		
of passing lane for percent time-spent-following	ng, Lde	2	_	mi
Length of two-lane highway downstream of effective	length	ı of		
the passing lane for percent time-spent-follow:	ing, Ld	L	-	mi
Adj. factor for the effect of passing lane	2			
on percent time-spent-following, fpl			-	
Percent time-spent-following				
including passing lane, PTSFpl			-	00
Level of Service and Other Performance Measur	res wit	h Pa	ssing	Lane
Level of service including passing lang LOSA	r.			
Deak 15-min total travel time TT15	凸 _		h_h	
reak 15-min local llavel lime, 1115	-	ve	11-11	
Bicycle Level of Service	е			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	576.6
Effective width of outside lane, We	14.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	6.31
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Date Performed1/30/202Analysis Time PeriodAM Peak Highway SR 28 - Proposed CL NBX2 North of SR 1018 From/To Boggs Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.76 Highway class Class 1 Shoulder width 4.0 ft % Trucks and buses 13 % 11.0ft% Trucks crawling0.00.9miTruck crawl speed0.0 Lane width 2 Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 0.90 mi % No-passing zones 100 % 6.4 % Access point density 10 /mi Grade: Length Up/down Analysis direction volume, Vd 151 veh/h Opposing direction volume, Vo 217 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 9.8 1.4 PCE for RVs, ER 1.0 1.5 Heavy-vehicle adj. factor,(note-5) fHV 0.466 0.951 Grade adj. factor, (note-1) fg 0.56 1.00 761 pc/h Directional flow rate, (note-2) vi 300 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 2.5 mi/h Free-flow speed, FFSd 55.8 mi/h mi/h Adjustment for no-passing zones, fnp 3.5 Average travel speed, ATSd 44.0 mi/h Percent Free Flow Speed, PFFS 78.9 ŝ

Percent Time-Spent-Followi	ng			
Direction Analysis(d) PCE for trucks, ET 1.0		0pp	osing 1.1	(0)
PCE for RVs, ER1.0Heavy-vehicle adjustment factor, fHV1.000Grade adjustment factor, (note-1) fg1.00Directional flow rate, (note-2) vi199pc	c/h		1.0 0.987 1.00 289	pc/h
Base percent time-spent-following,(note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	24.1 56.2 47.0	010		
Level of Service and Other Performa	ance Me	easur	es	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	D 0.25 45 136 1.0 797 1674 797	ve ve ve ve	h-mi h-mi h-h h/h h/h h/h	
Passing Lane Analysis_				
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	Lu	0.9 - 44.0 47.0 D	mi mi mi/h
Average Travel Speed with Passi	lng Lar	ne		
Downstream length of two-lane highway within effect length of passing lane for average travel speed	ive 1, Lde		_	mi
Length of two-lane highway downstream of effective length of the passing lane for average travel s Adj. factor for the effect of passing lane	speed,	Ld	-	mi
Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFF	Spl		- 0.0	00
Percent Time-Spent-Following with F	Passing	g Lan	e	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followir Length of two-lane highway downstream of effective	ive le ng, Lde length	ength e 1 of	-	mi
the passing lane for percent time-spent-followi Adj. factor for the effect of passing lane on percent time-spent-following, fpl	lng, Lo	1	_	mi
Percent time-spent-following including passing lane, PTSFpl			-	00
Level of Service and Other Performance Measur	res wit	:h Pa	ssing	Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	E -	ve	h-h	
Bicycle Level of Service	2			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	198.7
Effective width of outside lane, We	18.68
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	7.77
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Analysis Time Period PM Peak Highway SR 28 - Proposed CL NBX2 North of SR 1018 From/To Boggs Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.90 Highway class Class 1 Shoulder width 4.0 ft % Trucks and buses б % 11.0 ft % Trucks crawling 0.9 mi Truck crawl speed 0.0 Lane width 2 0.0 Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 0.90 mi % No-passing zones 100 % 6.4 % Access point density 10 /mi Grade: Length Up/down Analysis direction volume, Vd 295 veh/h Opposing direction volume, Vo 182 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 9.8 1.5 PCE for RVs, ER 1.0 1.2 Heavy-vehicle adj. factor,(note-5) fHV 0.654 0.971 0.62 Grade adj. factor,(note-1) fg 1.00 808 pc/h Directional flow rate, (note-2) vi 208 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 2.5 mi/h Free-flow speed, FFSd 55.8 mi/h 4.1 mi/h Adjustment for no-passing zones, fnp Average travel speed, ATSd 43.8 mi/h Percent Free Flow Speed, PFFS 78.6 ŝ

Percent Time-Spent-F	'ollowing		
Direction Analysi PCE for trucks, ET 1.1	.s(d)	Opposing 1.1	( 0 )
PCE for RVs, ER 1.0	)	1.0	
Heavy-vehicle adjustment factor, fHV 0.9	96	0.994	ŀ
Grade adjustment factor (note-1) fg 1 (	10	1 00	-
Directional flow rate (note-2) vi 320	h ng/h	203	nc/h
Page pergent time great following (note 4) PE		205 9	pc/m
Base percent time-spent-torrowing, (note-4) Br	-15FU 52.4	6	
Adjustment for no-passing zones, inp	53.8	0	
Percent time-spent-following, PTSFd	65.7	5	
Level of Service and Other Pe	rformance Mea	sures	
Level of service, LOS	D		
Volume to capacity ratio, v/c	0.29		
Peak 15-min vehicle-miles of travel. VMT15	74	veh-mi	
Peak-hour vehicle-miles of travel VMT60	265	veh-mi	
Deak 15-min total travel time TT15	1 7	ven mi	
Conscitut from ATS COATS	1117	vch h	
Capacity from AIS, CUAIS		vell/ll	
Capacity from PTSF, COPTSF	1088	ven/n	
Directional Capacity		ven/n	
Passing Lane Ana	lysis		
Total length of analysis segment. It		0.9	mi
Length of two-lane highway upstream of the pa	aging lane I.	11 -	mi
Longth of pagaing long ingluding tapara Inl	issing tane, i	u	mi
Deligin of passing falle including tapers, bpi		40.0	
Average travel speed, Also (from above)	· · · · · ·	43.0	111 / 11
Percent time-spent-following, PTSFd (from abo	ive)	05./	
Level of service, LOSA (from above)		D	
Average Travel Speed with	Passing Lane		
Downstream length of two-lane highway within	offoctivo		
length of pagging lang for average travel	aneed Ide	_	mi
I anoth of two long highway downstroom of offe	. speed, Lde	-	
Length of two-lane highway downstream of effe	ctive	-	
length of the passing lane for average tr	avel speed, L	d -	mı
Adj. factor for the effect of passing lane			
on average speed, fpl		-	
Average travel speed including passing lane,	ATSpl	-	
Percent free flow speed including passing lar	ie, PFFSpl	0.0	00
Percent Time-Spent-Following	with Passing	Lane	
		. 1	
Downstream length of two-lane highway within	errective len	gth	
of passing lane for percent time-spent-fo	llowing, Lde	-	mi
Length of two-lane highway downstream of effe	ctive length	of	
the passing lane for percent time-spent-f	ollowing, Ld	-	mi
Adj. factor for the effect of passing lane			
on percent time-spent-following, fpl		_	
Percent time-spent-following			
including passing lane, PTSFpl		-	00
Level of Service and Other Performance	Measures with	Passing	Lane
	.1		
Level of service including passing lane, LOSp	)工 臣	_ 1 1	
Peak 15-min total travel time, TT15	-	veh-h	
Bicycle Level of S	Service		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	327.8
Effective width of outside lane, We	15.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	5.88
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Date Performed1/30/202Analysis Time PeriodAM Peak Highway SR 28 - Proposed CL SBX1 North of SR 1028 From/To Rayburn Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Peak hour factor, PHF 0.88 Shoulder width 3.0 ft % Trucks and buses 15 % 11.0ft% Trucks crawling0.00.6miTruck crawl speed0.0 Lane width % Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 0.62 mi % No-passing zones 100 7.4 % Access point density 19 Grade: Length 8 Up/down /mi Analysis direction volume, Vd 217 veh/h Opposing direction volume, Vo 151 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 8.8 1.6 PCE for RVs, ER 1.0 1.4 Heavy-vehicle adj. factor,(note-5) fHV 0.462 0.917 Grade adj. factor,(note-1) fg 0.53 1.00 1007 pc/h Directional flow rate,(note-2) vi 187 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 3.0 mi/h Adj. for access point density,(note-3) fA 4.8 mi/h Free-flow speed, FFSd 52.3 mi/h 3.9 mi/h Adjustment for no-passing zones, fnp Average travel speed, ATSd 39.1 mi/h Percent Free Flow Speed, PFFS 74.9 %

Percent Time-Spent-Follow:	ing			
Direction Analysis(d) PCE for trucks, ET 1.0 PCE for RVs, ER 1.0 Heavy-vehicle adjustment factor, fHV 1.000 Grade adjustment factor, (note-1) fg 1.00 Directional flow rate, (note-2) vi 247 pc Base percent time-spent-following, (note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	c/h 25.8 57.0 59.2	Oppo % %	sing ( 1.1 1.0 0.985 1.00 174	o) pc/h
Level of Service and Other Performa	ance Me	easure	s	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	E 0.31 37 130 0.9 785 1630 785	veh veh veh veh veh	-mi -mi -h /h /h /h	
Passing Lane Analysis_				
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	0 Lu - 3 5 E	.6 9.1 9.2	mi mi mi/h
Average Travel Speed with Pass:	ing Lar	ne		
Downstream length of two-lane highway within effect length of passing lane for average travel speed Length of two-lane highway downstream of effective length of the passing lane for average travel s	tive d, Lde speed,	- Ld -		mi mi
Adj. factor for the effect of passing lane on average speed, fpl	2	-		
Percent free flow speed including passing lane, PFF	FSpl	0	.0	90 0
Percent Time-Spent-Following with H	Passing	g Lane		
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followin Length of two-lane highway downstream of effective	tive le ng, Lde length	ength e - n of		mi
the passing lane for percent time-spent-follow: Adj. factor for the effect of passing lane on percent time-spent-following, fpl	ing, Lo	- £		mi
Percent time-spent-following including passing lane, PTSFpl		_		<u>8</u>
Level of Service and Other Performance Measur	res wit	ch Pas	sing I	ane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	E -	veh	-h	
Bicycle Level of Service	e			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	246.6
Effective width of outside lane, We	14.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	9.62
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Analysis Time Period PM Peak Highway SR 28 - Proposed CL SBX1 North of SR 1028 From/To Rayburn Township, Armstrong Co Jurisdiction Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.95 Highway class Class 1 Shoulder width 3.0 ft % Trucks and buses 13 % 11.0 ft % Trucks crawling 0.6 mi Truck crawl speed Lane width 0.0 2 0.0 Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 0.62 mi % No-passing zones 100 7.4 % Access point density 19 Grade: Length 8 Up/down /mi Analysis direction volume, Vd 182 veh/h Opposing direction volume, Vo 295 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 8.8 1.4 PCE for RVs, ER 1.0 1.5 Heavy-vehicle adj. factor,(note-5) fHV 0.498 0.951 Grade adj. factor, (note-1) fg 0.50 1.00 769 pc/h Directional flow rate, (note-2) vi 327 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 3.0 mi/h Adj. for access point density,(note-3) fA 4.8 mi/h Free-flow speed, FFSd 52.3 mi/h mi/h Adjustment for no-passing zones, fnp 3.2 Average travel speed, ATSd 40.5 mi/h Percent Free Flow Speed, PFFS 77.6 %

Percent Time-Spent-Follow:	ing		
Direction Analysis(d) PCE for trucks, ET 1.0 PCE for RVs, ER 1.0 Heavy-vehicle adjustment factor, fHV 1.000 Grade adjustment factor, (note-1) fg 1.00 Directional flow rate, (note-2) vi 192 pc Base percent time-spent-following, (note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	c/h 23.8 54.0 44.2	Opposit 1. 1. 0. 1. 31 %	ing (0) .1 .0 .987 .00 L5 pc/h
Level of Service and Other Performa	ance Me	easures_	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	D 0.23 29 109 0.7 847 1639 847	veh-r veh-r veh-ł veh/ł veh/ł veh/ł	ni ni 1 1 1
Passing Lane Analysis_			
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	0.6 Lu – 40. 44. D	5 mi mi mi .5 mi/h .2
Average Travel Speed with Pass:	ing Lar	ne	
Downstream length of two-lane highway within effect length of passing lane for average travel speed Length of two-lane highway downstream of effective	tive d, Lde	-	mi
Adj. factor for the effect of passing lane on average speed, fpl	speed,	La - -	mı
Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFF	FSpl	- 0.0	) %
Percent Time-Spent-Following with H	Passing	g Lane	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followin Length of two-lane highway downstream of effective	tive le ng, Lde length	ength e - 1 of	mi
the passing lane for percent time-spent-follow: Adj. factor for the effect of passing lane on percent time-spent-following, fpl	ing, Lo	1 – 1 –	mi
Percent time-spent-following including passing lane, PTSFpl		_	8
Level of Service and Other Performance Measur	res wit	ch Passi	ing Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	E -	veh-ł	1
Bicycle Level of Service	e		

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	191.6
Effective width of outside lane, We	14.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	8.52
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Analysis Time Period AM Peak Highway SR 28 - Proposed CL SBX2 Pine Furnace to Mechling Rd From/To Jurisdiction Rayburn Township, Armstrong Co Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Peak hour factor, PHF 0.88 Shoulder width 4.0 ft % Trucks and buses 15 % 11.0 ft % Trucks crawling 0.9 mi Truck crawl speed Lane width 0.0 % Segment length 0.0 mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 0.88 mi % No-passing zones 100 5.5 % Access point density 9 Grade: Length 8 Up/down /mi Analysis direction volume, Vd 217 veh/h Opposing direction volume, Vo 151 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 9.7 1.6 PCE for RVs, ER 1.0 1.4 Heavy-vehicle adj. factor,(note-5) fHV 0.433 0.917 Grade adj. factor,(note-1) fg 0.59 1.00 965 pc/h Directional flow rate, (note-2) vi 187 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 2.3 mi/h Free-flow speed, FFSd 56.0 mi/h mi/h Adjustment for no-passing zones, fnp 3.9 Average travel speed, ATSd 43.2 mi/h Percent Free Flow Speed, PFFS 77.0 ŝ

Percent Time-Spent-Follows	ing		
Percent Time-Spent-FollowiDirectionAnalysis(d)PCE for trucks, ET1.0PCE for RVs, ER1.0Heavy-vehicle adjustment factor, fHV0.996Grade adjustment factor, (note-1) fg1.00Directional flow rate, (note-2) vi247Base percent time-spent-following, (note-4)BPTSFdAdjustment for no-passing zones, fnpPercent time-spent-following, PTSFdLevel of Service and Other PerformanceLevel of Service and Other Performance	c/h 25.8 57.0 59.2 ance Me	Opposin 1.1 1.0 0.9 1.0 174 % %	g (0) 85 0 pc/h
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	D 0.33 55 195 1.3 741 1674 741	veh-mi veh-mi veh-h veh/h veh/h veh/h	
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	0.9 Lu - 43.2 59.2 D	mi mi mi mi/h
Average Travel Speed with Passi Downstream length of two-lane highway within effect length of passing lane for average travel speed Length of two-lane highway downstream of effective length of the passing lane for average travel s Adj. factor for the effect of passing lane on average speed, fpl Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFF	ing Lar tive d, Lde speed, FSpl	ne Ld - - - 0.0	mi mi %
Percent Time-Spent-Following with F Downstream length of two-lane highway within effect of passing lane for percent time-spent-followin Length of two-lane highway downstream of effective the passing lane for percent time-spent-followin Adj. factor for the effect of passing lane on percent time-spent-following, fpl Percent time-spent-following including passing lane, PTSFpl	Passing tive le ng, Lde length ing, Lo	g Lane ength e - n of d - - -	mi mi %
Level of Service and Other Performance Measur Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15 Bicycle Level of Service	res wit E - e	th Passin veh-h	g Lane

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	246.6
Effective width of outside lane, We	15.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	9.48
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed 1/30/2020 Analysis Time Period PM Peak Highway SR 28 - Proposed CL SBX2 Pine Furnace to Mechling Rd From/To Jurisdiction Rayburn Township, Armstrong Co Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Highway class Class 1 Peak hour factor, PHF 0.95 Shoulder width 4.0 ft % Trucks and buses 13 % 11.0ft% Trucks crawling0.00.9miTruck crawl speed0.0 Lane width % Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 0.88 mi % No-passing zones 100 5.5 % Access point density 9 Grade: Length 8 Up/down /mi Analysis direction volume, Vd 182 veh/h Opposing direction volume, Vo 295 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 9.7 1.4 PCE for RVs, ER 1.0 1.5 Heavy-vehicle adj. factor,(note-5) fHV 0.469 0.951 Grade adj. factor,(note-1) fg 0.56 1.00 729 pc/h Directional flow rate, (note-2) vi 327 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 1.7 mi/h Adj. for access point density,(note-3) fA 2.3 mi/h Free-flow speed, FFSd 56.0 mi/h mi/h Adjustment for no-passing zones, fnp 3.4 Average travel speed, ATSd 44.4 mi/h Percent Free Flow Speed, PFFS 79.3 ŝ

Percent Time-Spent-Follows	ing			
Direction Analysis(d) PCE for trucks, ET 1.0 PCE for RVs, ER 1.0 Heavy-vehicle adjustment factor, fHV 1.000 Grade adjustment factor, (note-1) fg 1.00 Directional flow rate, (note-2) vi 192 pc Base percent time-spent-following, (note-4) BPTSFd Adjustment for no-passing zones, fnp Percent time-spent-following, PTSFd	C/h 23.8 54.0 44.2	Opp % %	oosing 1.1 1.0 0.987 1.00 315	(0) , pc/h
Level of Service and Other Performa	ance Me	easur	es	
Level of service, LOS Volume to capacity ratio, v/c Peak 15-min vehicle-miles of travel, VMT15 Peak-hour vehicle-miles of travel, VMT60 Peak 15-min total travel time, TT15 Capacity from ATS, CdATS Capacity from PTSF, CdPTSF Directional Capacity	D 0.24 43 164 1.0 802 1677 802	ve ve ve ve ve	h-mi h-mi h-h h/h h/h h/h	
Passing Lane Analysis_				
Total length of analysis segment, Lt Length of two-lane highway upstream of the passing Length of passing lane including tapers, Lpl Average travel speed, ATSd (from above) Percent time-spent-following, PTSFd (from above) Level of service, LOSd (from above)	lane,	Lu	0.9 - 44.4 44.2 D	mi mi mi/h
Average Travel Speed with Pass	ing Lar	ne		
Downstream length of two-lane highway within effect length of passing lane for average travel speed Length of two-lane highway downstream of effective	tive d, Lde		_	mi
length of the passing lane for average travel s Adj. factor for the effect of passing lane	speed,	Ld	-	mi
Average travel speed including passing lane, ATSpl Percent free flow speed including passing lane, PFF	FSpl		- 0.0	8
Percent Time-Spent-Following with H	Passing	g Lan	.e	
Downstream length of two-lane highway within effect of passing lane for percent time-spent-followin Length of two-lane highway downstream of effective	tive le ng, Lde length	ength e n of	L 	mi
the passing lane for percent time-spent-following. Adj. factor for the effect of passing lane on percent time-spent-following, fpl	ing, Lo	1	-	mi
Percent time-spent-following including passing lane, PTSFpl			-	<u>0</u>
Level of Service and Other Performance Measur	res wit	:h Pa	ssing	Lane
Level of service including passing lane, LOSpl Peak 15-min total travel time, TT15	E -	ve	h-h	
Bicycle Level of Service	e			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	191.6
Effective width of outside lane, We	15.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	8.37
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

Phone: Fax: E-Mail: \_\_\_\_\_Directional Two-Lane Highway Segment Analysis\_\_\_\_\_\_ Analyst French Agency/Co. French Engineering Date Performed1/30/202Analysis Time PeriodAM Peak 1/30/2020 Highway SR 28 - Existing CL NB1 0.5 miles north of SR 85 From/To Jurisdiction Rayburn Township, Armstrong Co Analysis Year 2019 Description SR 28 Corridor Study \_\_\_\_\_Input Data\_\_\_\_\_ Peak hour factor, PHF 0.82 Highway class Class 1 Shoulder width 6.0 ft % Trucks and buses 13 % 11.0ft% Trucks crawling0.00.9miTruck crawl speed0.0 Lane width % Segment length mi/hr Specific Grade % Recreational vehicles 0 Terrain type 8 Grade: Length 0.73 mi % No-passing zones 0 8 Access point density 1 Up/down 5.5 00 /mi Analysis direction volume, Vd 220 veh/h Opposing direction volume, Vo 403 veh/h \_\_\_\_\_Average Travel Speed\_\_\_\_\_Average Travel Speed\_\_\_\_\_ Direction Analysis(d) Opposing (o) PCE for trucks, ET 8.9 1.2 PCE for RVs, ER 1.0 1.3 Heavy-vehicle adj. factor,(note-5) fHV 0.492 0.975 0.61 Grade adj. factor,(note-1) fg 1.00 894 pc/h Directional flow rate, (note-2) vi 504 pc/h Free-Flow Speed from Field Measurement: Field measured speed, (note-3) S FM mi/h Observed total demand, (note-3) V \_ veh/h Estimated Free-Flow Speed: Base free-flow speed, (note-3) BFFS 60.0 mi/h Adj. for lane and shoulder width, (note-3) fLS 0.4 mi/h Adj. for access point density,(note-3) fA 0.3 mi/h Free-flow speed, FFSd 59.3 mi/h mi/h Adjustment for no-passing zones, fnp 1.2 Average travel speed, ATSd 47.3 mi/h Percent Free Flow Speed, PFFS 79.7 ŝ

Percent Time-Spent-Follo	owing		
DirectionAnalysis(d)PCE for trucks, ET1.0PCE for RVs, ER1.0	)	Opposing 1.0 1.0	( 0 )
Heavy-vehicle adjustment factor, fHV1.000Grade adjustment factor, (note-1) fg1.00		1.000	
Directional flow rate, (note-2) vi 268 Base percent time-spent-following, (note-4) BPTSFC	pc/h d 33.7	491 %	pc/h
Adjustment for no-passing zones, inp Percent time-spent-following, PTSFd	12.2 38.0	00	
Level of Service and Other Perfor	rmance Me	easures	
Level of service, LOS	С		
Volume to capacity ratio, v/c	0.32		
Peak 15-min vehicle-miles of travel, VMT15	60	veh-mi	
Peak-hour vehicle-miles of travel, VMT60	198	veh-mi	
Peak 15-min total travel time, TT15	1.3	veh-h	
Capacity from ATS, CdATS	836	veh/h	
Capacity from PTSF, CdPTSF	1700	veh/h	
Directional Capacity	836	veh/h	
Passing Lane Analysi	is		
Total length of analysis segment, Lt		0.9	mi
Length of two-lane highway upstream of the passir	ng lane,	Lu 0.0	mi
Length of passing lane including tapers. Lpl		0.9	mi
Average travel speed ATSd (from above)		47 3	mi/h
Dercent time-spect, Alba (110m above)		38 0	(((± / 11
Level of service, LOSd (from above)		C	
Average Travel Speed with Pas	ssing Lar	1e	
Deverture levels of the level bighter within offe			
length of passing lane for average travel spe Length of two-lane highway downstream of effective	eed, Lde ve	0.00	mi
length of the passing lane for average travel Adj. factor for the effect of passing lane	l speed,	Ld 0.00	mi
on average speed fnl		1 1 1	
Average travel speed including pagging lane ATS	-1	52 0	
Percent free flow speed including passing lane, H	PFFSpl	90.8	00
Percent Time-Spent-Following with	n Passing	g Lane	
Downstream length of two-lane highway within effe	active le	anath	
of passing lane for percent time-spent-follow	wing, Lde	e 0.00	mi
Length of two-lane highway downstream of effective	ve length	n of	
the passing lane for percent time-spent-follo	owing, Lo	a 0.00	mi
an persont time apont following fol		0 20	
Develope the second falls is a		0.20	
including passing lane, PTSFpl		7.6	00
Level of Service and Other Performance Meas	sures wit	ch Passing	Lane
Level of service including passing lang LOSA	D		
Peak 15-min total travel time, TT15	1.1	veh-h	
Bicycle Level of Servi	ice		
_			

Posted speed limit, Sp	55
Percent of segment with occupied on-highway parking	0
Pavement rating, P	3
Flow rate in outside lane, vOL	268.3
Effective width of outside lane, We	23.00
Effective speed factor, St	4.79
Bicycle LOS Score, BLOS	7.02
Bicycle LOS	F

- 1. Note that the adjustment factor for level terrain is 1.00, as level terrain is one of the base conditions. For the purpose of grade adjustment, specific dewngrade segments are treated as level terrain.
- 2. If vi (vd or vo ) >= 1,700 pc/h, terminate analysis-the LOS is F.
- 3. For the analysis direction only and for v>200 veh/h.
- 4. For the analysis direction only.
- 5. Use alternative Exhibit 15-14 if some trucks operate at crawl speeds on a specific downgrade.

# APPENDIX C Design Criteria

# **25 MPH DESIGN CRITERIA**

6

$\begin{array}{c} \begin{array}{c} \begin{array}{c} \begin{array}{c} \begin{array}{c} \begin{array}{c} \begin{array}{c} \begin{array}{c} $										
NHS? (Y/N) <u>N</u> STRAHNET? (Y/N) <u>N</u>										
BESIGN DESIGNATION RT 28 DESIGN CRITERIA Reconstruction AREA SYSTEM (Urban/Rural) Rural FUNCTIONAL CLASSIFICATION Regional Arterial ROADWAY TYPOLOGY Suburban Center TOPOGRAPHY Rolling REMARKS New Bethlehem			- - - - -	4	TRAFFIC DATA OPENING DESIGN DI	i YEAR ADT ( I YEAR ADT ( ESIGN YEAR DHV (D D (Dii	Average Daily Traffic)8896 (2011)(Average Daily Traffic)10229(for Design Year ADT)2045esign Hourly Volume)818rectional Distribution)55T (Truck Percentage)5	7)		
	5 Criteria*		Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE	REQUIRED VALUE	PROPOSED VALUE	CRITERIA MET?	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference)	REMARKS (NOTE ANY DESIGN EXCEPTIONS)	
	Design Speed			25 MPH	30-35 MPH	25 MPH	No	DM-2, Table 1.3		
Γ	Lane Width			11'	10' to 12'	11'	Yes	DM-2, Table 1.3		
Γ	Shoulder Width			8'	4'-6'	8'	Yes	DM-2, Table 1.3		
	Minimum Bridge Widt	h		44'	28'-36'	44'	Yes	DM-2, Sec. 1.2C		
	Minimum Horizontal Rac	lius		600'	231' to 340'	600'	No	AASHTO, Table 3-9	* 25 mph, minimum radius is 144'	
	Maximum Superelevation	Rate		Varies	6.0%	6.0%	Yes	DM-2, Table 1.3		
	Vertical Grade	Minimum		0.10%	0.50%	0.50%	Yes	DM-2, Table 1.3	line segment 103	
		Maximum		2.90%	6.00%	6.00%	Yes	AASHTO, Table 7-2	line segment 90	
	Minimum Stopping Sight Distance	(SSD/HLSD)								

(vertical and horizontal) Varies 200'-250' 200' Yes AASHTO, Table 7-1 Minimum Intersection Sight Distance (ISD) 335' to 390' AASHTO, Table 9-6 \* 25 mph, minimum ISD is 280' Varies 280' No Minimum Cross Slope 2.0% 2.0% Yes DM-2. Table 1.3 Varies Minimum Vertical Clearance N/A 16'-6" N/A N/A DM-2, Table 2.2

\*Refer to Publication 10X, Design Manual 1X, Appendix P for more information on controlling criteria and design exceptions.

Any pedestrian and bicycle concerns/needs? Explain. Sidewalks, multimodal

Any ADA compliance issues? Explain.	ADA ramps on corners through town
Any transit issues? Explain.	
Any additional design issues? Explain.	

		DESIRED AVERAGE			NEDDERCEION	
ROADWAY CLASS	ROADWAY TYPE	OPERATING SPEED	TRIP LENGTH	VOLUME	INTERSECTION SPACING	COMMENTS
Arterial	Regional	50-90 km/h (30-55 mph)	24-56 km (15-35 mi)	10,000- 40,000 veh/day	200-400 m (660-1,320 ft)	Roadways in this category would be considered "Principal Arterial" in traditional functional classification.
Arterial	Community	40-90 km/h (25-55 mph)	11-40 km (7-25 mi)	5,000- 25,000 veh/day	90-400 m (300-1,320 ft)	Often classified as "Minor Arterial" in traditional classification but may include road segments classified as "Principal Arterial".
Collector	Community	40-90 km/h (25-55 mph)	8-16 km (5-10 mi)	5,000- 15,000 veh/day	90-200 m (300-660 ft)	Often similar in appearance to a community arterial. Typically classified as "Major Collector".
Collector	Neighborhood	40-60 km/h (25-35 mph)	< 11 km (< 7 mi)	< 6,000 veh/day	90-200 m (300-660 ft)	Similar in appearance to local roadways. Typically classified as "Minor Collector".
Local	Local	30-50 km/h (20-30 mph)	< 8 km (< 5 mi)	< 3,000 veh/day	60-200 m (200-660 ft)	

TABLE 1.2 ROADWAY TYPOLOGIES

## INTENTIONALLY BLANK

## FIGURE 1.2 ILLUSTRATED ROADWAY TYPOLOGIES



# FIGURE 1.2 (CONTINUED) ILLUSTRATED ROADWAY TYPOLOGIES



# TABLE 1.3 (ENGLISH) MATRIX OF DESIGN VALUE<mark>S – REGIONA</mark>L ARTERIAL

	-							
	Kegional Arterial	Rural	Suburban Neighborhood	Suburban Corridor	Suburban Center	Town/Village Neighborhood	Town/Village Center	Urban Core
	Lane Width <sup>1</sup>	11' to 12'	11' to 12'	11' to 12'	11' to 12'	10' to 12'	10' to 12'	10' to 12'
	Shoulder Width <sup>2, 3</sup>	8' to 10'	8' to 10'	8' to 12'	4' to 6' (if No Parking or Bike Lane)			
	Parking Lane	AN	AN	NA	8' Parallel	8' Parallel	8' Parallel	8' Parallel
	Bike Lane <sup>4</sup>	ΝA	5' to 6' (if No Shoulder)	6' (if No Shoulder)	5' to 6'	5' to 6'	5' to 6'	5' to 6'
	Median (if needed)	4' to 6'	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only
	Curb Return <sup>5</sup>	30' to 50'	25' to 35'	30' to 50'	25' to 50'	15' to 40'	15' to 40'	15' to 40'
	Travel Lanes	2 to 6	2 to 6	4 to 6	4 to 6	2 to 4	2 to 4	2 to 6
yew	Cross Slopes (Minimum) <sup>6, 7</sup>	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%
Road	Cross Slopes (Maximum) <sup>8</sup>	8.0%	6.0%	6.0%	6.0%	6.0%	6.0%	6.0%
	Bridge Widths (Two-Lane Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	_ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side
	Bridge Widths (Four-Lane or More Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	_ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side
	Vertical Grades (Minimum) <sup>11</sup>	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%
	Vertical Clearance (Minimum)	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2
	Clear Sidewalk Width	AN	مت	5' to 6'	5' to 6'	6' to 8'	6' to 10'	6' to 12'
z	Buffer <sup>13</sup>	AN	6'+	6' to 10'	4' to 6'	4' to 6'	4' to 6'	4' to 6'
, ə	Shy Distance	AN	AN	NA	0' to 2'	0' to 2'	2'	2'
bisba	Total Sidewalk Width	NA	5'	5' to 6'	9' to 14'	10' to 16'	12' to 18'	12' to 20'
SoA	Clear Zone Widths <sup>14</sup>	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12
	Right-of-Way Widths <sup>15</sup>	Varies	Varies	Varies	Varies	Varies	Varies	Varies
	Desired Operating Speed (Design Speed)	45-55 mph	35-40 mph	35-55 mph	40-35 mph	30-35 mph	30-35 mph	30-35 mph
beedS	Stopping and Passing Sight Distances (Minimum)	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1
	Vertical Grades (Maximum)	2004 AASHTO Green Book, Exhibit 7-2	2004 AASHTO Green Book, Exhibit 7-10					

S\$503						Met	rle					
	V <sub>a</sub> = 20	V <sub>d</sub> = 30	V <sub>a</sub> ≈ 40	V <sub>d</sub> = 50	V <sub>d</sub> = 60	V <sub>d</sub> ≈ 70	V <sub>d</sub> = 80	V <sub>d</sub> ≈ 90	V <sub>d</sub> = 100	V <sub>d</sub> = 110	V <sub>d</sub> ≈ 120	V <sub>d</sub> = 130
	km/h	km/h	km/h	km/h	km/h	km/h	km/b	km/h	km/h	km/h	km/h	km/h
e (%)	R (m)	<i>R</i> (m)	R (m)	R (m)								
NC	194	421	738	1050	1440	1910	2360	2880	3510	4060	4770	5240
RC	138	299	525	750	1030	1380	1710	2090	2560	2970	3510	3880
2.2	122	265	465	668	919	1230	1530	1880	2300	2670	3160	3500
2.4	109	236	415	599	825	1110	1380	1700	2080	2420	2870	3190
2.6	97	212	372	S40	746	1000	1260	1540	1890	2210	2630	2930
2.8	87	190	334	488	676	910	1150	1410	1730	2020	2420	2700
3.0	78	170	300	443	615	831	1050	1290	1590	1870	2240	2510
3.2	70	152	269	402	561	761	959	1190	1470	1730	2080	2330
3.4	61	133	239	364	511	697	882	1100	1360	1600	1940	2180
3.6	51	113	206	329	465	640	813	1020	1260	1490	1810	2050
3.8	42	96	177	294	422	586	749	939	1170	1390	1700	1930
4.0	36	87.	155	261	380	535	690	870	1090	1300	1590	1820
4.2	31	72	136	234	343	488	635	806	1010	1220	1500	1720
4.4	27	63	121	210	311	446	584	746	938	1140	1410	1630
4.6	24	56	108	190	283	408	538	692	873	1070	1330	1540
4.8	21	50	97	172	258	374	496	641	812	997	1260	1470
5.0	19	45	88	155	235	343	457	594	755	933	1190	1400
5.2	17	40	79	142	214	315	421	549	701	871	1120	1330
5.4	15	36	71	128	195	287	386	506	648	810	1060	1260
5.6	13	32	63	115	176	260	351	463	594	747	980	1190
5.8	11	28	56	102	156	232	315	416	537	679	900	1110
6.0	8	21	43	79	123	184	252	336	437	560	756	951

Table 3-9. Minimum Radii for Design Superelevation Rates, Design Speeds, and  $e_{\max}$  = 6%

	S(8333)		U.S. Customary														
	V <sub>d</sub> = 15	V <sub>0</sub> = 20	¥ <sub>tf</sub> ≠ 25	V <sub>d</sub> = 30	V <sub>ci</sub> = 35	V <sub>d</sub> ≈ 40	V <sub>d</sub> ≈ 45	V <sub>d</sub> = 50	V <sub>d</sub> = 55	V <sub>d</sub> ≈ 60	V <sub>d</sub> = 65	V <sub>d</sub> = 70	V <sub>d</sub> = 75	V <sub>d</sub> = 80			
	mph	mph	mph	mph	mph	mph	mph	raph	mph	mph	mph	mph	mph	mph			
e (%)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	<i>R</i> (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)			
NC	868	1580	2290	3130	4100	5230	6480	7870	9410	11100	12600	14100	15700	17400			
RC	614	1120	1630	2240	2950	3770	4680	\$700	6820	8060	9130	10300	11500	12900			
2.2	543	991	1450	2000	2630	3370	4190	5100	6110	7230	8200	9240	10400	11600			
2.4	482	884	1300	1790	2360	3030	3770	4600	5520	6540	7430	8380	9420	10600			
2.6	430	791	1170	1610	2130	2740	3420	4170	5020	5950	6770	7660	8620	9670			
2.8	384	709	1050	1460	1930	2490	3110	3800	4580	\$440	6200	7030	7930	8910			
3.0	341	635	944	1320	1760	2270	2840	3480	4200	4990	\$710	6490	7330	8260			
3.2	300	566	850	1200	1600	2080	2600	3200	3860	4600	5280	6010	6810	7680			
3.4	256	498	761	1080	1460	1900	2390	2940	3560	4250	4890	5580	6340	7180			
3.6	209	422	673	972	1320	1740	2190	2710	3290	3940	4540	5210	\$930	6720			
3.8	176	358	583	854	1190	1590	2010	2490	3040	3650	4230	4860	5560	6320			
4.0	151	309	511	766	1070	1440	1840	2300	2810	3390	3950	4550	5220	5950			
4.2	131	270	452	584	960	1310	1680	2110	2590	3140	3680	4270	4910	5620			
4.4	116	238	40Z	615	868	1190	1540	1940	2400	2920	3440	4010	4630	5320			
4.6	102	212	360	555	788	1090	1410	1780	2210	2710	3220	3770	4380	5040			
4.8	91	189	324	502	718	<del>9</del> 95	1300	1640	2050	2510	3000	3550	4140	4790			
5.0	82	169	292	456	654	911	1190	1510	1890	2330	2800	3330	3910	4550			
5.2	73	152	264	413	595	833	1090	1390	1750	2160	2610	3120	3690	4320			
S.4	65	136	237	373	540	759	995	1280	1610	1990	2420	2910	3460	4090			
5.6	58	121	212	335	487	687	903	1160	1470	1830	2230	2700	3230	3840			
5.8	51	106	186	296	431	611	806	1040	1320	1650	2020	2460	2970	3560			
6.0	39	81	144	231	340	485	643	833	1060	1330	1660	2040	2500	3050			

# A Policy on Geometric Design of Highways and Streets

tance are considered, there are seldom advantages to using the maximum grade values except when grades are long.

				M	etric							J.S. (	Custo	man	<u> </u>		
	Maximum Grade (%) for Specified Design Speed (km/h)								Maximum Grade (%) for Specified Design Speed (mph)								
Type of Terrain	60	70	80	90	100	110	120	130	40	45	50	55	60	65	70	75	80
Level	5	5	4	4	3	3	3	3	5	5	4	4	3	3	3	3	3
Rolling	6	6	5	5	4	4	4	4	6	6	5	5	4	4	4	4	4
Mountainous	8	7	7	6	6	5	5	5	8	7	7	6	6	5	5	5	5

#### Table 7-2. Maximum Grades for Rural Arterials

#### **Cross Slope**

Cross slope is provided to enhance roadway drainage. Two-lane rural roadways are normally designed with a centerline crown and traveled-way cross slopes ranging from 1.5 to 2 percent with the higher values being most prevalent.

#### Superelevation

Where curves are used on a rural arterial alignment, a superelevation rate based on the design speed should be used. Superelevation rates should not exceed 12 percent; however, where ice and snow conditions are a factor, the maximum superelevation rate should not exceed 8 percent. Superelevation runoff denotes the length of roadway needed to accomplish the change in cross slope from a section with adverse crown removed to a fully superelevated section and vice versa. Adjustments in design runoff lengths may be needed for smooth riding, drainage, and appearance. Section 3.3 provides a detailed discussion of superelevation and tables of appropriate superelevation rates and runoff lengths for various design speeds.

#### 7.2.3 Cross-Sectional Elements

#### Widths of Roadway

The logical approach to determining appropriate lane and shoulder widths is to provide a width related to the traffic demands. Table 7-3 provides values for the width of traveled way and usable shoulder that should be considered for the volumes indicated. Regardless of weather conditions, shoulders should be usable at all times. On high-volume highways, shoulders should preferably be paved, but paved shoulders may not always be practical. As a minimum, 0.6 m [2 ft] of the shoulder width should be paved to provide for pavement support, wide vehicles, and collision avoidance. Where bicycles are to be accommodated on the shoulder, a minimum paved width of 1.2 m [4 ft] should be used. The shoulder should be constructed to a uniform width for relatively long stretches of roadway. For additional information concerning shoulders, refer to Section 4.4.
### **Sight Distance**

Sight distance is directly related to and varies appreciably with design speed. Stopping sight distance should be provided throughout the length of the roadway. Passing and decision sight distances influence roadway operations and should be provided wherever practical. Providing decision sight distance at locations where complex decisions are made greatly enhances the capability for drivers to safely accomplish maneuvers. Examples of locations where complex decisions are needed include interchanges, high-volume intersections, transitions in roadway width, and transitions in the number of lanes. Providing adequate sight distance on rural arterials, which may combine both high speeds and high traffic volumes, can be complex. Table 7-1 presents the recommended minimum values of stopping and passing sight distance. Refer to Section 3.2 for a comprehensive discussion of sight distance and for tabulated values for decision sight distance.

	Metric			U.S. Customary	
Design Speed (km/h)	Minimum Stopping Sight Distance (m)	Minimum Passing Sight Distance (m)	Design Speed (mph)	Minimum Stopping Sight Distance (ft)	Minimum Passing Sight Distance (ft)
50	65	160	30	200	500
60	85	180	35	250	550
70	105	210	40	305	600
80	130	245	45	360	700
90	160	280	50	425	800
100	185	320	55	495	900
110	220	355	60	570	1000
120	250	395	65	645	1100
130	285	440	70	730	1200
			75	820	1300
			80	910	1400

### Table 7-1. Minimum Sight Distances for Arterials

Ideally, intersections and railroad crossings should be grade separated or provided with adequate sight distance. Intersections should be placed in sag or tangent locations, or both, where practical, to provide maximum visibility of the roadway and pavement markings.

### Alignment

A smooth flowing alignment is desirable on a rural arterial. Changes in alignment, both horizontal and vertical, should be sufficiently gradual to avoid surprising the driver. Minimum radii should be used sparingly; short horizontal curves—particularly at the end of long tangents—should be avoided. Roads with well-designed and consistent alignment usually function more efficiently and with lower crash rates than roads with poor alignment, even where enhanced signing and pavement marking are provided.

### Grades

The length and steepness of grades directly affect the operational characteristics of an arterial. Table 7-2 presents recommended maximum grades for rural arterials. When vertical curves for stopping sight dis-

## 9-38 A Policy on Geometric Design of Highways and Streets

intersection is located on a 4 percent upgrade, then the time gap selected for intersection sight distance design for left turns should be increased from 8.0 to 8.8 s, equivalent to an increase of 0.2 s for each percent grade.

The design values for intersection sight distance for passenger cars are shown in Table 9-6. Figure 9-17 includes design values, based on the time gaps for the design vehicles included in Table 9-5.

No adjustment of the recommended sight distance values for the major-road grade is generally needed because both the major- and minor-road vehicle will be on the same grade when departing from the intersection. However, if the minor-road design vehicle is a heavy truck and the intersection is located near a sag vertical curve with grades over 3 percent, then an adjustment to extend the recommended sight distance based on the major-road grade should be considered.

	Met	ric			U.S. Cus	U.S. Customary			
Design		Intersecti Distan Passeng	ion Sight ce for er Cars	Design	Stopping	Intersecti Distan Passeng	on Sight ce for er Cars		
Speed (km/h)	Stopping Sight Distance (m)	Calculated (m)	Design (m)	Speed (mph)	Sight Distance (ft)	Calculated (ft)	Design (ft)		
20	20	41.7	45	15	80	165.4	170		
30	35	62.6	65	20	115	220.5	225		
40	50	83.4	85	25	155	275.6	280		
50	65	104.3	105	30	200	330,8	335		
60	85	125.1	130	35	250	385.9	390		
70	105	146.0	150	40	305	441.0	445		
80	130	166.8	170	45	360	496.1	500		
90	160	187.7	190	50	425	551.3	555		
100	185	208.5	210	55	495	606.4	610		
110	220	229.4	230	60	570	661.5	665		
120	250	250.2	255	65	645	716.6	720		
130	285	271.1	275	70	730	771.8	775		
<u> </u>	_		—	75	820	826.9	830		
	_	_		80	910	882.0	885		

Table 9-6. Design Intersection Sight Distance—Case B1, Left Turn from Stop

Note: Intersection sight distance shown is for a stopped passenger car to turn left onto a two-lane highway with no median and grades 3 percent or less. For other conditions, the time gap should be adjusted and the sight distance recalculated.

Sight distance design for left turns at divided-highway intersections should consider multiple design vehicles and median width. If the design vehicle used to determine sight distance for a divided-highway intersection is larger than a passenger car, then sight distance for left turns will need to be checked for that selected design vehicle and for smaller design vehicles as well. If the divided-highway median is wide enough to store the design vehicle with a clearance to the through lanes of approximately 1 m [3 ft] at both ends of the vehicle, no separate analysis for the departure sight triangle for left turns is needed on the minor-road approach for the near roadway to the left. In most cases, the departure sight triangle for right

# 35 MPH DESIGN CRITERIA

OJECT DESCRIPTION: <u>RT 28 C</u> a	orridor Study from K	(1)	DESIGN CRI MPMS NO. SR 28	ITERIA MATRIX N/A SEC N/A	Armstrong , <u>Clarion</u> Jefferson ure planning and	COUNTY COUNTY COUNTY programmin	ng of potential transportation pro	ojects with in the study area.
NHS? (Y/N) <u>N</u>			STRAHNET?	(Y/N) N				
<u>ESIGN DESIGNATION</u> DESIGN CRIT AREA SYSTEM (Urban/R FUNCTIONAL CLASSIFICAT ROADWAY TYPOL TOPOGRA	RT 28 ERIA Reconstruction ural) Rural TION Regional Arter OGY Suburban Cent APHY Rolling	n ial ter		4	TRAFFIC DATA OPENING DESIGN D	S YEAR ADT ( I YEAR ADT ( ESIGN YEAR DHV (D D (Dir	Average Daily Traffic) 8996 (201   Average Daily Traffic) 10344   (for Design Year ADT) 2045   esign Hourly Volume) 828   rectional Distribution) 55   T (Truck Descention) 55	7)
REM	ARKS South Bethleh Summerville	em, Hawthorn,	_				T (Truck Percentage) 5	
REM/	ARKS South Bethleh Summerville	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE	REQUIRED VALUE	PROPOSED VALUE	CRITERIA MET?	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference)	REMARKS (NOTE ANY DESIGN EXCEPTION
REM/	ARKS South Bethleh Summerville	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH	REQUIRED VALUE 30-35 MPH	PROPOSED VALUE 35 MPH	CRITERIA MET? Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTION
REM/ 5 Criteria* Design Speed Lane Width	ARKS South Bethleh Summerville	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11'	REQUIRED VALUE 30-35 MPH 10'-12'	PROPOSED VALUE 35 MPH 11'	CRITERIA MET? Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTION
Criteria* <u>Design Speed</u> Lane Width Shoulder Wid	ARKS South Bethleh Summerville	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8'	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6'	PROPOSED VALUE 35 MPH 11' 6'	CRITERIA MET? Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTIO
Criteria* <u>Design Speed</u> Lane Width Shoulder Wid Minimum Bridge	ARKS South Bethleh Summerville d th Width	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44'	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36'	PROPOSED VALUE 35 MPH 11' 6' 44'	CRITERIA MET? Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTIO
Criteria* <u>Design Speer</u> Lane Width Shoulder Wid Minimum Bridge V	ARKS South Bethleh Summerville d th Width al Radius	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44' 75'	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36' 231' to 340'	PROPOSED VALUE 35 MPH 11' 6' 44' 340'	CRITERIA MET? Yes Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.2G AASHTO, Table 3-9	REMARKS (NOTE ANY DESIGN EXCEPTIO
Criteria* <u>Design Speer</u> Lane Width Shoulder Wid Minimum Bridge 1 Minimum Horizonta Maximum Supereleva	ARKS South Bethleh Summerville d th Width al Radius ation Rate	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44' 75' Varies	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36' 28'-36' 231' to 340' 6.0%	PROPOSED VALUE 35 MPH 11' 6' 44' 340' 6.0%	CRITERIA MET? Yes Yes Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.2G AASHTO, Table 3-9 DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTIO
REM/	ARKS South Bethleh Summerville d th Width al Radius ation Rate Minimum	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44' 75' Varies 0.40%	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36' 231' to 340' 6.0% 0.50%	PROPOSED VALUE 35 MPH 11' 6' 44' 340' 6.0% 0.50%	CRITERIA MET? Yes Yes Yes Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTIC
REM/ 5 Criteria* Design Speer Lane Width Shoulder Wid Minimum Bridge Minimum Horizonta Maximum Supereleva Vertical Grade	ARKS South Bethleh Summerville d th Width al Radius ation Rate Minimum Maximum	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44' 75' Varies 0.40% 1.90%	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36' 231' to 340' 6.0% 0.50% 6.00%	PROPOSED VALUE 35 MPH 11' 6' 44' 340' 6.0% 0.50% 6.00%	CRITERIA MET? Yes Yes Yes Yes Yes Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTIC
REM/ 5 Criteria* Design Speed Lane Width Shoulder Wid Minimum Bridge Minimum Horizonta Maximum Supereleva Vertical Grade Minimum Stopping Sight Dist (vertical and horiz	ARKS South Bethleh Summerville d th Width al Radius ation Rate Minimum Maximum tance (SSD/HLSD) contal)	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44' 75' Varies 0.40% 1.90% Varies	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36' 231' to 340' 6.0% 0.50% 6.00% 200' to 250'	PROPOSED VALUE 35 MPH 11' 6' 44' 340' 6.0% 0.50% 6.00% 250'	CRITERIA MET? Yes Yes Yes Yes Yes Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-2 AASHTO, Table 7-1	REMARKS (NOTE ANY DESIGN EXCEPTIC
REM/ 5 Criteria* Design Speed Lane Width Shoulder Wid Minimum Bridge Minimum Horizonta Maximum Supereleva Vertical Grade Minimum Stopping Sight Dist (vertical and horiz Minimum Intersection Sigh	ARKS South Bethleh Summerville	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44' 75' Varies 0.40% 1.90% Varies Varies	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36' 231' to 340' 6.0% 0.50% 6.00% 200' to 250' 335' to 390'	PROPOSED VALUE 35 MPH 11' 6' 44' 340' 6.0% 0.50% 6.00% 250' 390'	CRITERIA MET? Yes Yes Yes Yes Yes Yes Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.2G AASHTO, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-2 AASHTO, Table 7-1 AASHTO, Table 9-6	REMARKS (NOTE ANY DESIGN EXCEPTIO
REM/ 5 Criteria* Design Speed Lane Width Shoulder Wid Minimum Bridge Minimum Horizonta Maximum Supereleva Vertical Grade Minimum Stopping Sight Dist (vertical and horiz Minimum Intersection Sigh Minimum Cross 5	ARKS South Bethleh Summerville d th Width al Radius ation Rate Minimum Maximum tance (SSD/HLSD) contal) t Distance (ISD) Slope	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44' 75' Varies 0.40% 1.90% Varies Varies Varies Varies Varies	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36' 231' to 340' 6.0% 0.50% 6.00% 200' to 250' 335' to 390' 2.0%	PROPOSED VALUE 35 MPH 11' 6' 44' 340' 6.0% 0.50% 6.00% 250' 390' 2.0%	CRITERIA MET? Yes Yes Yes Yes Yes Yes Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-1 AASHTO, Table 7-1 AASHTO, Table 9-6 DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTIC

6

Any pedestrian and bicycle concerns/needs? Explain. Sidewalks, multimodal

pedestrian and bicycle concerns/needs? Explain.	Sidewarks, mutimodal
Any ADA compliance issues? Explain.	ADA ramps on corners through town
Any transit issues? Explain.	
Any additional design issues? Explain.	15 mph curve entering New Bethleham

		DESIRED	AVERAGE		NEDDERCEION	
ROADWAY CLASS	ROADWAY TYPE	OPERATING SPEED	TRIP LENGTH	VOLUME	INTERSECTION SPACING	COMMENTS
Arterial	Regional	50-90 km/h (30-55 mph)	24-56 km (15-35 mi)	10,000- 40,000 veh/day	200-400 m (660-1,320 ft)	Roadways in this category would be considered "Principal Arterial" in traditional functional classification.
Arterial	Community	40-90 km/h (25-55 mph)	11-40 km (7-25 mi)	5,000- 25,000 veh/day	90-400 m (300-1,320 ft)	Often classified as "Minor Arterial" in traditional classification but may include road segments classified as "Principal Arterial".
Collector	Community	40-90 km/h (25-55 mph)	8-16 km (5-10 mi)	5,000- 15,000 veh/day	90-200 m (300-660 ft)	Often similar in appearance to a community arterial. Typically classified as "Major Collector".
Collector	Neighborhood	40-60 km/h (25-35 mph)	< 11 km (< 7 mi)	< 6,000 veh/day	90-200 m (300-660 ft)	Similar in appearance to local roadways. Typically classified as "Minor Collector".
Local	Local	30-50 km/h (20-30 mph)	< 8 km (< 5 mi)	< 3,000 veh/day	60-200 m (200-660 ft)	

TABLE 1.2 ROADWAY TYPOLOGIES

# INTENTIONALLY BLANK

# FIGURE 1.2 ILLUSTRATED ROADWAY TYPOLOGIES



# FIGURE 1.2 (CONTINUED) ILLUSTRATED ROADWAY TYPOLOGIES



# TABLE 1.3 (ENGLISH) MATRIX OF DESIGN VALUE<mark>S – REGIONA</mark>L ARTERIAL

	-							
	Kegional Arterial	Rural	Suburban Neighborhood	Suburban Corridor	Suburban Center	Town/Village Neighborhood	Town/Village Center	Urban Core
	Lane Width <sup>1</sup>	11' to 12'	11' to 12'	11' to 12'	11' to 12'	10' to 12'	10' to 12'	10' to 12'
	Shoulder Width <sup>2, 3</sup>	8' to 10'	8' to 10'	8' to 12'	4' to 6' (if No Parking or Bike Lane)			
	Parking Lane	AN	AN	NA	8' Parallel	8' Parallel	8' Parallel	8' Parallel
	Bike Lane <sup>4</sup>	ΝA	5' to 6' (if No Shoulder)	6' (if No Shoulder)	5' to 6'	5' to 6'	5' to 6'	5' to 6'
	Median (if needed)	4' to 6'	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only
	Curb Return <sup>5</sup>	30' to 50'	25' to 35'	30' to 50'	25' to 50'	15' to 40'	15' to 40'	15' to 40'
	Travel Lanes	2 to 6	2 to 6	4 to 6	4 to 6	2 to 4	2 to 4	2 to 6
yew	Cross Slopes (Minimum) <sup>6, 7</sup>	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%
Road	Cross Slopes (Maximum) <sup>8</sup>	8.0%	6.0%	6.0%	6.0%	6.0%	6.0%	6.0%
	Bridge Widths (Two-Lane Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	_ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side
	Bridge Widths (Four-Lane or More Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	_ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side
	Vertical Grades (Minimum) <sup>11</sup>	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%
	Vertical Clearance (Minimum)	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2
	Clear Sidewalk Width	AN	مت	5' to 6'	5' to 6'	6' to 8'	6' to 10'	6' to 12'
z	Buffer <sup>13</sup>	AN	6'+	6' to 10'	4' to 6'	4' to 6'	4' to 6'	4' to 6'
, ə	Shy Distance	AN	AA	NA	0' to 2'	0' to 2'	2'	2'
bisba	Total Sidewalk Width	NA	5'	5' to 6'	9' to 14'	10' to 16'	12' to 18'	12' to 20'
SoA	Clear Zone Widths <sup>14</sup>	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12
	Right-of-Way Widths <sup>15</sup>	Varies	Varies	Varies	Varies	Varies	Varies	Varies
	Desired Operating Speed (Design Speed)	45-55 mph	35-40 mph	35-55 mph	40-35 mph	30-35 mph	30-35 mph	30-35 mph
beedS	Stopping and Passing Sight Distances (Minimum)	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1
	Vertical Grades (Maximum)	2004 AASHTO Green Book, Exhibit 7-2	2004 AASHTO Green Book, Exhibit 7-10					

S\$503						Met	rle					
	V <sub>a</sub> = 20	V <sub>d</sub> = 30	V <sub>a</sub> ≈ 40	V <sub>d</sub> = 50	V <sub>d</sub> = 60	V <sub>d</sub> ≈ 70	V <sub>d</sub> = 80	V <sub>d</sub> ≈ 90	V <sub>d</sub> = 100	V <sub>d</sub> = 110	V <sub>d</sub> ≈ 120	V <sub>d</sub> = 130
	km/h	km/h	km/h	km/h	km/h	km/h	km/b	km/h	km/h	km/h	km/h	km/h
e (%)	R (m)	<i>R</i> (m)	R (m)	R (m)								
NC	194	421	738	1050	1440	1910	2360	2880	3510	4060	4770	5240
RC	138	299	525	750	1030	1380	1710	2090	2560	2970	3510	3880
2.2	122	265	465	668	919	1230	1530	1880	2300	2670	3160	3500
2.4	109	236	415	599	825	1110	1380	1700	2080	2420	2870	3190
2.6	97	212	372	S40	746	1000	1260	1540	1890	2210	2630	2930
2.8	87	190	334	488	676	910	1150	1410	1730	2020	2420	2700
3.0	78	170	300	443	615	831	1050	1290	1590	1870	2240	2510
3.2	70	152	269	402	561	761	959	1190	1470	1730	2080	2330
3.4	61	133	239	364	511	697	882	1100	1360	1600	1940	2180
3.6	51	113	206	329	465	640	813	1020	1260	1490	1810	2050
3.8	42	96	177	294	422	586	749	939	1170	1390	1700	1930
4.0	36	87.	155	261	380	535	690	870	1090	1300	1590	1820
4.2	31	72	136	234	343	488	635	806	1010	1220	1500	1720
4.4	27	63	121	210	311	446	584	746	938	1140	1410	1630
4.6	24	56	108	190	283	408	538	692	873	1070	1330	1540
4.8	21	50	97	172	258	374	496	641	812	997	1260	1470
5.0	19	45	88	155	235	343	457	594	755	933	1190	1400
5.2	17	40	79	142	214	315	421	549	701	871	1120	1330
5.4	15	36	71	128	195	287	386	506	648	810	1060	1260
5.6	13	32	63	115	176	260	351	463	594	747	980	1190
5.8	11	28	56	102	156	232	315	416	537	679	900	1110
6.0	8	21	43	79	123	184	252	336	437	560	756	951

Table 3-9. Minimum Radii for Design Superelevation Rates, Design Speeds, and  $e_{\max}$  = 6%

	NY SALA		0505265			્રિટેટ વ	J.S. Custo	umary						
	V <sub>d</sub> = 15	V <sub>1</sub> = 20	V <sub>d</sub> ≠ 25	V <sub>d</sub> = 30	V <sub>c</sub> = 35	V <sub>d</sub> ≈ 40	V <sub>d</sub> = 45	V <sub>d</sub> = 50	V <sub>d</sub> = 55	V <sub>d</sub> ≈ 60	V <sub>d</sub> = 65	V <sub>d</sub> = 70	V <sub>d</sub> = 75	V <sub>d</sub> = 80
	mph	maph	mph	mph	mph	mph	mph	mph						
e (%)	R (ft)													
NC	868	1580	2290	3130	4100	5230	6480	7870	9410	11100	12600	14100	15700	17400
RC	614	1120	1630	2240	2950	3770	4680	\$700	6820	8060	9130	10300	11500	12900
2.2	543	991	1450	2000	2630	3370	4190	5100	6110	7230	8200	9240	10400	11600
2.4	482	884	1300	1790	2360	3030	3770	4600	5520	6540	7430	8380	9420	10600
2.6	430	791	1170	1610	21.30	2740	3420	4170	5020	5950	6770	7660	8620	9670
2.8	384	709	1050	1460	1930	2490	3110	3800	4580	5440	6200	7030	7930	8910
3.0	341	635	944	1320	1760	2270	2840	3480	4200	4990	\$710	6490	7330	8260
3.2	300	566	850	1200	1600	2080	2600	3200	3860	4600	5280	6010	6810	7680
3.4	256	498	761	1080	1460	1900	2390	2940	3560	4250	4890	5580	6340	7180
3.6	209	422	673	972	1320	1740	2190	2710	3290	3940	4540	5210	\$930	6720
3.8	176	358	583	864	1190	1590	2010	2490	3040	3650	4230	4860	5560	6320
4.0	151	309	511	766	1070	1440	1840	2300	2810	3390	3950	4550	5220	5950
4.2	131	270	452	684	960	1310	1680	2110	2590	3140	3680	4270	4910	5620
4.4	116	238	40Z	615	868	1190	1540	1940	2400	2920	3440	4010	4630	5320
4.6	102	212	360	555	788	1090	1410	1780	2210	2710	3220	3770	4380	5040
4.8	91	189	324	502	718	<del>9</del> 95	1300	1640	2050	2510	3000	3550	4140	4790
5.0	82	169	292	456	654	911	1190	1510	1890	2330	2800	3330	3910	4550
5.2	73	152	264	413	595	833	1090	1390	1750	2160	2610	3120	3690	4320
S.4	65	136	237	373	540	759	995	1280	1610	1990	2420	2910	3460	4090
5.6	58	121	212	335	487	687	903	1160	1470	1830	2230	2700	3230	3840
5.8	51	106	186	296	431	611	806	1040	1320	1650	2020	2460	2970	3560
6.0	39	81	144	231	340	485	643	833	1060	1330	1660	2040	2500	3050

# A Policy on Geometric Design of Highways and Streets

tance are considered, there are seldom advantages to using the maximum grade values except when grades are long.

				M	etric							J.S. (	Custo	man	<u> </u>		
		N Spec	laxin ified	num Desi	Grado gn Sp	e (%) eed (	for km/h	}		Spe	Maxi ecifie	mun d De	n Gra sign	de (% Spee	6) for d (m	ph)	
Type of Terrain	60	70	80	90	100	110	120	130	40	45	50	55	60	65	70	75	80
Level	5	5	4	4	3	3	3	3	5	5	4	4	3	3	3	3	3
Rolling	6	6	5	5	4	4	4	4	6	6	5	5	4	4	4	4	4
Mountainous	8	7	7	6	6	5	5	5	8	7	7	6	6	5	5	5	5

### Table 7-2. Maximum Grades for Rural Arterials

### **Cross Slope**

Cross slope is provided to enhance roadway drainage. Two-lane rural roadways are normally designed with a centerline crown and traveled-way cross slopes ranging from 1.5 to 2 percent with the higher values being most prevalent.

### Superelevation

Where curves are used on a rural arterial alignment, a superelevation rate based on the design speed should be used. Superelevation rates should not exceed 12 percent; however, where ice and snow conditions are a factor, the maximum superelevation rate should not exceed 8 percent. Superelevation runoff denotes the length of roadway needed to accomplish the change in cross slope from a section with adverse crown removed to a fully superelevated section and vice versa. Adjustments in design runoff lengths may be needed for smooth riding, drainage, and appearance. Section 3.3 provides a detailed discussion of superelevation and tables of appropriate superelevation rates and runoff lengths for various design speeds.

### 7.2.3 Cross-Sectional Elements

### Widths of Roadway

The logical approach to determining appropriate lane and shoulder widths is to provide a width related to the traffic demands. Table 7-3 provides values for the width of traveled way and usable shoulder that should be considered for the volumes indicated. Regardless of weather conditions, shoulders should be usable at all times. On high-volume highways, shoulders should preferably be paved, but paved shoulders may not always be practical. As a minimum, 0.6 m [2 ft] of the shoulder width should be paved to provide for pavement support, wide vehicles, and collision avoidance. Where bicycles are to be accommodated on the shoulder, a minimum paved width of 1.2 m [4 ft] should be used. The shoulder should be constructed to a uniform width for relatively long stretches of roadway. For additional information concerning shoulders, refer to Section 4.4.

### **Sight Distance**

Sight distance is directly related to and varies appreciably with design speed. Stopping sight distance should be provided throughout the length of the roadway. Passing and decision sight distances influence roadway operations and should be provided wherever practical. Providing decision sight distance at locations where complex decisions are made greatly enhances the capability for drivers to safely accomplish maneuvers. Examples of locations where complex decisions are needed include interchanges, high-volume intersections, transitions in roadway width, and transitions in the number of lanes. Providing adequate sight distance on rural arterials, which may combine both high speeds and high traffic volumes, can be complex. Table 7-1 presents the recommended minimum values of stopping and passing sight distance. Refer to Section 3.2 for a comprehensive discussion of sight distance and for tabulated values for decision sight distance.

	Metric			U.S. Customary	
Design Speed (km/h)	Minimum Stopping Sight Distance (m)	Minimum Passing Sight Distance (m)	Design Speed (mph)	Minimum Stopping Sight Distance (ft)	Minimum Passing Sight Distance (ft)
50	65	160	30	200	500
60	85	180	35	250	550
70	105	210	40	305	600
80	130	245	45	360	700
90	160	280	50	425	800
100	185	320	55	495	900
110	220	355	60	570	1000
120	250	395	65	645	1100
130	285	440	70	730	1200
			75	820	1300
			80	910	1400

### Table 7-1. Minimum Sight Distances for Arterials

Ideally, intersections and railroad crossings should be grade separated or provided with adequate sight distance. Intersections should be placed in sag or tangent locations, or both, where practical, to provide maximum visibility of the roadway and pavement markings.

### Alignment

A smooth flowing alignment is desirable on a rural arterial. Changes in alignment, both horizontal and vertical, should be sufficiently gradual to avoid surprising the driver. Minimum radii should be used sparingly; short horizontal curves—particularly at the end of long tangents—should be avoided. Roads with well-designed and consistent alignment usually function more efficiently and with lower crash rates than roads with poor alignment, even where enhanced signing and pavement marking are provided.

### Grades

The length and steepness of grades directly affect the operational characteristics of an arterial. Table 7-2 presents recommended maximum grades for rural arterials. When vertical curves for stopping sight dis-

## 9-38 A Policy on Geometric Design of Highways and Streets

intersection is located on a 4 percent upgrade, then the time gap selected for intersection sight distance design for left turns should be increased from 8.0 to 8.8 s, equivalent to an increase of 0.2 s for each percent grade.

The design values for intersection sight distance for passenger cars are shown in Table 9-6. Figure 9-17 includes design values, based on the time gaps for the design vehicles included in Table 9-5.

No adjustment of the recommended sight distance values for the major-road grade is generally needed because both the major- and minor-road vehicle will be on the same grade when departing from the intersection. However, if the minor-road design vehicle is a heavy truck and the intersection is located near a sag vertical curve with grades over 3 percent, then an adjustment to extend the recommended sight distance based on the major-road grade should be considered.

	Met	ric			U.S. Cus	U.S. Customary		
Design		Intersecti Distan Passeng	on Sight ce for er Cars	Design	Stopping	Intersecti Distan Passeng	on Sight ce for er Cars	
Speed (km/h)	Stopping Sight Distance (m)	Calculated (m)	Design (m)	Speed (mph)	Sight Distance (ft)	Calculated (ft)	Design (ft)	
20	20	41.7	45	15	80	165.4	170	
30	35	62.6	65	20	115	220.5	225	
40	50	83.4	85	25	155	275.6	280	
50	65	104.3	105	30	200	330,8	335	
60	85	125.1	130	35	250	385.9	390	
70	105	146.0	150	40	305	441.0	445	
80	130	166.8	170	45	360	496.1	500	
90	160	187.7	190	50	425	551.3	555	
100	185	208.5	210	55	495	606.4	610	
110	220	229.4	230	60	570	661.5	665	
120	250	250.2	255	65	645	716.6	720	
130	285	271.1	275	70	730	771.8	775	
	_		_	75	820	826.9	830	
	_	_		80	910	882.0	885	

Table 9-6. Design Intersection Sight Distance—Case B1, Left Turn from Stop

Note: Intersection sight distance shown is for a stopped passenger car to turn left onto a two-lane highway with no median and grades 3 percent or less. For other conditions, the time gap should be adjusted and the sight distance recalculated.

Sight distance design for left turns at divided-highway intersections should consider multiple design vehicles and median width. If the design vehicle used to determine sight distance for a divided-highway intersection is larger than a passenger car, then sight distance for left turns will need to be checked for that selected design vehicle and for smaller design vehicles as well. If the divided-highway median is wide enough to store the design vehicle with a clearance to the through lanes of approximately 1 m [3 ft] at both ends of the vehicle, no separate analysis for the departure sight triangle for left turns is needed on the minor-road approach for the near roadway to the left. In most cases, the departure sight triangle for right

# 40 MPH DESIGN CRITERIA

CHK'D BY: JDW	DATE: 4/:	1/2020	DESIGN CRI MPMS NO. SR 28	FERIA MATRIX N/A SEC N/A	Jefferson , <u>Clarion</u> ure planning and	COUNTY COUNTY	ng of potential transportation pro	piects with in the study area.
NHS? (Y/N) N			STRAHNET?	<b>(Y/N)</b> N			<u> </u>	· · · ·
DESIGN DESIGNATION DESIGN C AREA SYSTEM (Urbar FUNCTIONAL CLASSIFIC ROADWAY TYP TOPOC RE	RT 28 RITERIA Recons /Rural) Rural CATION Regior OLOGY Suburl SRAPHY Rolling MARKS Distan North	al Arterial an Neighborhood t, PA from New Bethlehem		4	- TRAFFIC DATA OPENING DESIGN D	YEAR ADT ( YEAR ADT ( ESIGN YEAR DHV (D D (Dir	Average Daily Traffic)7196 (201Average Daily Traffic)8274(for Design Year ADT)2045esign Hourly Volume)745rectional Distribution)52T (Truck Percentage)8	9)
5 Criteria	*	Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE	REQUIRED VALUE	PROPOSED VALUE	CRITERIA MET?	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference)	REMARKS (NOTE ANY DESIGN EXCEPTIONS)
Design Sp	eed		40 MPH	35-40 MPH	40 MPH	Yes	DM-2, Table 1.3	
Lane Wid	lth		11'	11'-12'	11'	Yes	DM-2, Table 1.3	
Shoulder W	/idth		3'-8'	8'-10'	8'	Yes	DM-2, Table 1.3	
	To Width		N/A	38'-44'	N/A	N/A	DM-2, Sec 1.2C	
Minimum Bridg	se wiutii		6001	340'-485'	600'	Yes	AASHTO, Table 3-9	Entering Distant, PA
Minimum Bridg Minimum Horizo	ntal Radius		600.	340 403				
Minimum Bridg Minimum Horizo Maximum Superel	ntal Radius		Varies	6.0%	6.0%	Yes	DM-2, Table 1.3	
Minimum Bridg Minimum Horizo Maximum Superel	ntal Radius evation Rate Mini	num	600 <sup>°</sup> Varies 1.50%	6.0% 0.50%	6.0% 0.50%	Yes Yes	DM-2, Table 1.3 DM-2, Table 1.3	line segment 83
Minimum Bridg Minimum Horizo Maximum Superel Vertical Grade	ntal Radius evation Rate Mini Maxi	mum	600 <sup>°</sup> Varies 1.50% 6.90%	6.0% 0.50% 6.00%	6.0% 0.50% 6.00%	Yes Yes Yes	DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-2	line segment 83 line segment 81
Minimum Bridg Minimum Horizo Maximum Superel Vertical Grade Minimum Stopping Sight D	evation Rate Mini Maxi istance (SSD/H	num mum LSD)	600 <sup>.</sup> Varies 1.50% 6.90%	6.0% 0.50% 6.00%	6.0% 0.50% 6.00%	Yes Yes Yes	DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-2	line segment 83 line segment 81
Minimum Bridg Minimum Horizo Maximum Superel Vertical Grade Minimum Stopping Sight E (vertical and ho	evation Rate evation Rate Mini Maxi listance (SSD/H rizontal)	mum mum LSD)	600 <sup>°</sup> Varies 1.50% 6.90% Varies	6.0% 0.50% 6.00% 250'-305'	6.0% 0.50% 6.00% 305'	Yes Yes Yes Yes	DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-2 AASHTO, Table 7-1	line segment 83 line segment 81
Minimum Bridg Minimum Horizo Maximum Superel Vertical Grade Minimum Stopping Sight I (vertical and ho Minimum Intersection S	ntal Radius evation Rate Mini Maxi vistance (SSD/H rizontal) ght Distance (I	mum mum LSD)	Varies 1.50% 6.90% Varies Varies	6.0% 0.50% 6.00% 250'-305' 390'-445'	6.0% 0.50% 6.00% 305' 445'	Yes Yes Yes Yes Yes	DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-2 AASHTO, Table 7-1 AASHTO, Table 9-6	line segment 83 line segment 81
Minimum Bridg Minimum Horizo Maximum Superel Vertical Grade Minimum Stopping Sight D (vertical and ho Minimum Intersection S Minimum Cro	ntal Radius evation Rate Mini Maxi listance (SSD/H rizontal) ght Distance (I is Slope	mum mum LSD) SD)	600'   Varies   1.50%   6.90%   Varies   Varies   Varies   Varies	6.0% 0.50% 6.00% 250'-305' 390'-445' 2.0%	6.0% 0.50% 6.00% 305' 445' 2.0%	Yes Yes Yes Yes Yes Yes	DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-2 AASHTO, Table 7-1 AASHTO, Table 9-6 DM-2, Table 1.3	line segment 83 line segment 81

\_\_\_\_\_

(6)

Any pedestrian and bicycle concerns/needs? Explain.

Any ADA compliance issues? Explain.

Any transit issues? Explain. Any additional design issues? Explain.

DOADWAN		DESIRED	AVERAGE		NEDDERCEION	
ROADWAY CLASS	ROADWAY TYPE	OPERATING SPEED	TRIP LENGTH	VOLUME	INTERSECTION SPACING	COMMENTS
Arterial	Regional	50-90 km/h (30-55 mph)	24-56 km (15-35 mi)	10,000- 40,000 veh/day	200-400 m (660-1,320 ft)	Roadways in this category would be considered "Principal Arterial" in traditional functional classification.
Arterial	Community	40-90 km/h (25-55 mph)	11-40 km (7-25 mi)	5,000- 25,000 veh/day	90-400 m (300-1,320 ft)	Often classified as "Minor Arterial" in traditional classification but may include road segments classified as "Principal Arterial".
Collector	Community	40-90 km/h (25-55 mph)	8-16 km (5-10 mi)	5,000- 15,000 veh/day	90-200 m (300-660 ft)	Often similar in appearance to a community arterial. Typically classified as "Major Collector".
Collector	Neighborhood	40-60 km/h (25-35 mph)	< 11 km (< 7 mi)	< 6,000 veh/day	90-200 m (300-660 ft)	Similar in appearance to local roadways. Typically classified as "Minor Collector".
Local	Local	30-50 km/h (20-30 mph)	< 8 km (< 5 mi)	< 3,000 veh/day	60-200 m (200-660 ft)	

TABLE 1.2 ROADWAY TYPOLOGIES

# INTENTIONALLY BLANK

# FIGURE 1.2 ILLUSTRATED ROADWAY TYPOLOGIES



# FIGURE 1.2 (CONTINUED) ILLUSTRATED ROADWAY TYPOLOGIES



# TABLE 1.3 (ENGLISH) MATRIX OF DESIGN VALUES – REGIONAL ARTERIAL

							1	
	кеgional Arterial	Rural	Suburban Neighborhood	Suburban Corridor	Suburban Center	Town/Village Neighborhood	Town/Village Center	Urban Core
	Lane Width <sup>1</sup>	11' to 12'	11' to 12'	11' to 12'	11' to 12'	10' to 12'	10' to 12'	10' to 12'
	Shoulder Width <sup>2, 3</sup>	8' to 10'	8' to 10'	8' to 12'	4' to 6' (if No Parking or Bike Lane)			
	Parking Lane	NA	NA	AN	8' Parallel	8' Parallel	8' Parallel	8' Parallel
	Bike Lane <sup>4</sup>	NA	5' to 6' (if No Shoulder)	6' (if No Shoulder)	5' to 6'	5' to 6'	5' to 6'	5' to 6'
	Median (if needed)	4' to 6'	16' to 18' for Left Turn; 6' to 8' for Pedestrians Onlv	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only
	Curb Return <sup>5</sup>	30' to 50'	25' to 35'	30' to 50'	25' to 50'	15' to 40'	15' to 40'	15' to 40'
	Travel Lanes	2 to 6	2 to 6	4 to 6	4 to 6	2 to 4	2 to 4	2 to 6
Yew	Cross Slopes (Minimum) <sup>6, 7</sup>	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%
Воаd	Cross Slopes (Maximum) <sup>8</sup>	8.0%	6.0%	6.0%	6.0%	6.0%	6.0%	6.0%
	Bridge Widths (Two-Lane Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side
	Bridge Widths (Four-Lane or More Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side
	Vertical Grades (Minimum) <sup>11</sup>	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%
	Vertical Clearance (Minimum)	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2
	Clear Sidewalk Width	NA	5.	5' to 6'	5' to 6'	6' to 8'	6' to 10'	6' to 12'
2	Buffer <sup>13</sup>	NA	+,9	6' to 10'	4' to 6'	4' to 6'	4' to 6'	4' to 6'
, ə	Shy Distance	NA	AA	AA	0' to 2'	0' to 2'	2'	2'
pispe	Total Sidewalk Width	NA	5.	5' to 6'	9' to 14'	10' to 16'	12' to 18'	12' to 20'
SoA	Clear Zone Widths <sup>14</sup>	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12
	Right-of-Way Widths <sup>15</sup>	Varies	Varies	Varies	Varies	Varies	Varies	Varies
	Desired Operating Speed (Design Speed)	45-55 mph	35-40 mph	35-55 mph	30-35 mph	30-35 mph	30-35 mph	30-35 mph
beed	Stopping and Passing Sight Distances (Minimum)	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1
	Vertical Grades (Maximum)	2004 AASHTO Green Book, Exhibit 7-2	2004 AASHTO Green Book, Exhibit 7-10					

						Met	ric					
	V <sub>a</sub> = 20	V <sub>a</sub> = 30	V <sub>d</sub> ≈ 40	V <sub>d</sub> ≈ 50	V <sub>d</sub> ≈ 60	V <sub>d</sub> ≈ 70	V <sub>d</sub> = 80	V <sub>d</sub> ≈ 90	V <sub>d</sub> = 100	V <sub>d</sub> = 110	V <sub>d</sub> ≈ 120	V <sub>d</sub> = 130
	km/h	km/h	km/h	km/h	km/h	km/h	km/b	km/h	km/h	km/h	km/h	km/h
e (%)	R (m)	R (m)	R (m)	R (m)								
NC	194	421	738	1050	1440	1910	2360	2880	3510	4060	4770	5240
RC	138	299	525	750	1030	1380	1710	2090	2560	2970	3510	3880
2.2	122	265	465	668	919	1230	1530	1880	2300	2670	3160	3500
2.4	109	236	415	599	825	1110	1380	1700	2080	2420	2870	3190
2.6	97	212	372	S40	746	1000	1260	1540	1890	2210	2630	2930
2.8	87	190	334	488	676	910	1150	1410	1730	2020	2420	2700
3.0	78	170	300	443	615	831	1050	1290	1590	1870	2240	2510
3.2	70	152	269	402	561	761	959	1190	1470	1730	2080	2330
3.4	61	133	239	364	511	697	882	1100	1360	1600	1940	2180
3.6	51	113	206	329	465	640	813	1020	1260	1490	1810	2050
3.8	42	96	177	294	422	586	749	939	1170	1390	1700	1930
4.0	36	82	155	261	380	535	690	870	1090	1300	1590	1820
4.2	31	72	136	234	343	488	635	806	1010	1220	1500	1720
4.4	27	63	121	210	311	446	584	746	938	1140	1410	1630
4.6	24	56	108	190	283	408	538	692	873	1070	1330	1540
4.8	21	50	97	172	258	374	496	641	81Z	997	1260	1470
5.0	19	45	88	156	235	343	457	594	755	933	1190	1400
5.2	17	40	7 <del>9</del>	142	214	315	421	549	701	871	1120	1330
5.4	15	36	71	128	195	287	386	506	648	810	1060	1260
5.6	13	32	63	115	176	260	351	463	594	747	980	1190
5.8	11	28	56	102	156	232	315	416	537	679	900	1110
6.0	8	21	43	79	123	184	252	336	437	560	756	951

Table 3-9. Minimum Radii for Design Superelevation Rates, Design Speeds, and  $e_{\max}$  = 6%

	NISSAN					્રા	J.S. Custo	ımary						S. (1) (2)
	V <sub>d</sub> = 15	V <sub>11</sub> = 20	V <sub>d</sub> ≠ 25	V <sub>d</sub> = 30	V <sub>c</sub> = 35	V <sub>d</sub> ≈ 40	V <sub>d</sub> = 45	V <sub>d</sub> = 50	V <sub>d</sub> = 55	V <sub>d</sub> ≈ 60	V <sub>d</sub> = 65	V <sub>d</sub> = 70	V <sub>d</sub> = 75	V <sub>d</sub> = 80
	nışh	mph	mph	mph	mph	mph	mph	raph	mph	mph	mph	mph	mph	mph
e (%)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)
NC	868	1580	2290	3130	4100	5230	6480	7870	9410	11100	12600	14100	15700	17400
RC	614	1120	1630	2240	2950	3770	4680	\$700	6820	8060	9130	10300	11500	12900
2.2	543	991	1450	2000	2630	3370	4190	5100	6110	7230	8200	9240	10400	11600
2.4	482	884	1300	1790	2360	3030	3770	4600	5520	6540	7430	8380	9420	10600
2.6	430	791	1170	1610	21.30	2740	3420	4170	5020	5950	6770	7660	8620	9670
2.8	384	709	1050	1460	1930	2490	3110	3800	4580	\$440	6200	7030	7930	8910
3.0	341	635	944	1320	1760	2270	2840	3480	4200	4990	\$710	6490	7330	8260
3.2	300	566	850	1200	1600	2080	2600	3260	3860	4600	5280	6010	6810	7680
3.4	256	498	761	1080	1460	1900	2390	2940	3560	4250	4890	5580	6340	7180
3.6	209	422	673	972	1320	1740	2190	2710	3290	3940	4540	5210	\$930	6720
3.8	176	358	583	864	1190	1590	2010	2490	3040	3650	4230	4860	5560	6320
4.0	151	309	511	766	1070	1440	1840	2300	2810	3390	3950	4550	5220	5950
4.2	131	270	452	584	960	1310	1680	2110	2590	3140	3680	4270	4910	5620
4.4	116	238	40Z	615	868	1190	1540	1940	2400	2920	3440	4010	4630	5320
4.6	102	212	360	555	788	1090	1410	1780	2210	2710	3220	3770	4380	5040
4.8	91	189	324	502	718	<del>9</del> 95	1300	1640	2050	2510	3000	3550	4140	4790
5.0	82	169	292	456	654	911	1190	1510	1890	2330	2800	3330	3910	4550
5.2	73	152	264	413	595	833	1090	1390	1750	2160	2610	3120	3690	4320
S.4	65	136	237	373	540	759	995	1280	1610	1990	2420	2910	3460	4090
5.6	58	121	212	335	487	687	903	1160	1470	1830	2230	2700	3230	3840
5.8	51	106	186	296	431	611	806	1040	1320	1650	2020	2460	2970	3560
6.0	39	81	144	231	340	485	643	833	1060	1330	1660	2040	2500	3050

# A Policy on Geometric Design of Highways and Streets

tance are considered, there are seldom advantages to using the maximum grade values except when grades are long.

				M	etric							J.S. (	Custo	man	<u> </u>		
		N Spec	laxin ified	num Desi	Grado gn Sp	e (%) eed (	for km/h	}		Spe	Maxi ecifie	mun d De	n Gra sign	de (% Spee	6) for d (m	ph)	
Type of Terrain	60	70	80	90	100	110	120	130	40	45	50	55	60	65	70	75	80
Level	5	5	4	4	3	3	3	3	5	5	4	4	3	3	3	3	3
Rolling	6	6	5	5	4	4	4	4	6	6	5	5	4	4	4	4	4
Mountainous	8	7	7	6	6	5	5	5	8	7	7	6	6	5	5	5	5

### Table 7-2. Maximum Grades for Rural Arterials

### **Cross Slope**

Cross slope is provided to enhance roadway drainage. Two-lane rural roadways are normally designed with a centerline crown and traveled-way cross slopes ranging from 1.5 to 2 percent with the higher values being most prevalent.

### Superelevation

Where curves are used on a rural arterial alignment, a superelevation rate based on the design speed should be used. Superelevation rates should not exceed 12 percent; however, where ice and snow conditions are a factor, the maximum superelevation rate should not exceed 8 percent. Superelevation runoff denotes the length of roadway needed to accomplish the change in cross slope from a section with adverse crown removed to a fully superelevated section and vice versa. Adjustments in design runoff lengths may be needed for smooth riding, drainage, and appearance. Section 3.3 provides a detailed discussion of superelevation and tables of appropriate superelevation rates and runoff lengths for various design speeds.

### 7.2.3 Cross-Sectional Elements

### Widths of Roadway

The logical approach to determining appropriate lane and shoulder widths is to provide a width related to the traffic demands. Table 7-3 provides values for the width of traveled way and usable shoulder that should be considered for the volumes indicated. Regardless of weather conditions, shoulders should be usable at all times. On high-volume highways, shoulders should preferably be paved, but paved shoulders may not always be practical. As a minimum, 0.6 m [2 ft] of the shoulder width should be paved to provide for pavement support, wide vehicles, and collision avoidance. Where bicycles are to be accommodated on the shoulder, a minimum paved width of 1.2 m [4 ft] should be used. The shoulder should be constructed to a uniform width for relatively long stretches of roadway. For additional information concerning shoulders, refer to Section 4.4.

### **Sight Distance**

Sight distance is directly related to and varies appreciably with design speed. Stopping sight distance should be provided throughout the length of the roadway. Passing and decision sight distances influence roadway operations and should be provided wherever practical. Providing decision sight distance at locations where complex decisions are made greatly enhances the capability for drivers to safely accomplish maneuvers. Examples of locations where complex decisions are needed include interchanges, high-volume intersections, transitions in roadway width, and transitions in the number of lanes. Providing adequate sight distance on rural arterials, which may combine both high speeds and high traffic volumes, can be complex. Table 7-1 presents the recommended minimum values of stopping and passing sight distance. Refer to Section 3.2 for a comprehensive discussion of sight distance and for tabulated values for decision sight distance.

	Metric			U.S. Customary	
Design Speed (km/h)	Minimum Stopping Sight Distance (m)	Minimum Passing Sight Distance (m)	Design Speed (mph)	Minimum Stopping Sight Distance (ft)	Minimum Passing Sight Distance (ft)
50	65	160	30	200	500
60	85	180	35	250	550
70	105	210	40	305	600
80	130	245	45	360	700
90	160	280	50	425	800
100	185	320	55	495	900
110	220	355	60	570	1000
120	250	395	65	645	1100
130	285	440	70	730	1200
			75	820	1300
			80	910	1400

### Table 7-1. Minimum Sight Distances for Arterials

Ideally, intersections and railroad crossings should be grade separated or provided with adequate sight distance. Intersections should be placed in sag or tangent locations, or both, where practical, to provide maximum visibility of the roadway and pavement markings.

### Alignment

A smooth flowing alignment is desirable on a rural arterial. Changes in alignment, both horizontal and vertical, should be sufficiently gradual to avoid surprising the driver. Minimum radii should be used sparingly; short horizontal curves—particularly at the end of long tangents—should be avoided. Roads with well-designed and consistent alignment usually function more efficiently and with lower crash rates than roads with poor alignment, even where enhanced signing and pavement marking are provided.

### Grades

The length and steepness of grades directly affect the operational characteristics of an arterial. Table 7-2 presents recommended maximum grades for rural arterials. When vertical curves for stopping sight dis-

## 9-38 A Policy on Geometric Design of Highways and Streets

intersection is located on a 4 percent upgrade, then the time gap selected for intersection sight distance design for left turns should be increased from 8.0 to 8.8 s, equivalent to an increase of 0.2 s for each percent grade.

The design values for intersection sight distance for passenger cars are shown in Table 9-6. Figure 9-17 includes design values, based on the time gaps for the design vehicles included in Table 9-5.

No adjustment of the recommended sight distance values for the major-road grade is generally needed because both the major- and minor-road vehicle will be on the same grade when departing from the intersection. However, if the minor-road design vehicle is a heavy truck and the intersection is located near a sag vertical curve with grades over 3 percent, then an adjustment to extend the recommended sight distance based on the major-road grade should be considered.

	Met	ric			U.S. Cus	itomary	
Design		Intersecti Distan Passeng	ion Sight ce for jer Cars	Design	Stopping	Intersecti Distan Passeng	on Sight ce for er Cars
Speed (km/h)	Stopping Sight Distance (m)	Calculated (m)	Design (m)	Speed (mph)	Sight Distance (ft)	Calculated (ft)	Design (ft)
20	20	41.7	45	15	80	165.4	170
30	35	62.6	65	20	115	220.5	225
40	50	83.4	85	25	155	275.6	280
50	65	104.3	105	30	200	330,8	335
60	85	125.1	130	35	250	385.9	390
70	105	146.0	150	40	305	441.0	445
80	130	166.8	170	45	360	496.1	500
90	160	187.7	190	50	425	551.3	555
100	185	208.5	210	55	495	606.4	610
110	220	229.4	230	60	570	661.5	665
120	250	250.2	255	65	645	716.6	720
130	285	271.1	275	70	730	771.8	775
	_		_	75	820	826.9	830
		_		80	910	882.0	885

Table 9-6. Design Intersection Sight Distance—Case B1, Left Turn from Stop

Note: Intersection sight distance shown is for a stopped passenger car to turn left onto a two-lane highway with no median and grades 3 percent or less. For other conditions, the time gap should be adjusted and the sight distance recalculated.

Sight distance design for left turns at divided-highway intersections should consider multiple design vehicles and median width. If the design vehicle used to determine sight distance for a divided-highway intersection is larger than a passenger car, then sight distance for left turns will need to be checked for that selected design vehicle and for smaller design vehicles as well. If the divided-highway median is wide enough to store the design vehicle with a clearance to the through lanes of approximately 1 m [3 ft] at both ends of the vehicle, no separate analysis for the departure sight triangle for left turns is needed on the minor-road approach for the near roadway to the left. In most cases, the departure sight triangle for right

# **45 MPH DESIGN CRITERIA**

ROJECT DESCRIPTION: <u>RT 28 Corri</u>	e: <u>4/1/2020</u>	(ittanning to I-80. This co	DESIGN CRI MPMS NO. SR 28	TERIA MATRIX N/A SEC N/A	Armstrong , Clarion Jefferson ure planning and	COUNTY programmin	ng of potential transportation pro	ojects with in the study area.
NHS? (Y/N) <u>N</u>			STRAHNET?	(Y/N) <u>N</u>				
DESIGN DESIGNATION F DESIGN CRITERI AREA SYSTEM (Urban/Rura	T 28 A <u>Reconstructio</u> I) Rural	n	-	4	<u>TRAFFIC DATA</u> OPENING DESIGN D	S YEAR ADT ( NYEAR ADT ( ESIGN YEAR	(Average Daily Traffic) 7349 (201 (Average Daily Traffic) 8450 (for Design Year ADT) 2045	9)
FUNCTIONAL CLASSIFICATIO ROADWAY TYPOLOG TOPOGRAPH DEMADR	N Regional Arter Y Rural Y Rolling	hatween New	- - -			DHV (D D (Dii	rectional Distribution) 761 T (Truck Percentage) 13	
	Bethlehem an Summerville	d Hawthrone, North of	- - -					
5 Criteria*		Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE	REQUIRED VALUE	PROPOSED VALUE	CRITERIA MET?	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference)	REMARKS (NOTE ANY DESIGN EXCEPTIO
Design Speed		,	45 MPH	45 -55 MPH	45 MPH	Yes	DM-2, Table 1.3	
Lane Width			11'	11' to 12'	11'	Yes	DM-2, Table 1.3	
Shoulder Width			4'	8' to 10'	8'	Yes	DM-2, Table 1.3	
Minimum Bridge Wid	lth		N/A	38' to 44'	N/A	N/A	DM-2, Sec 1.2C	
Minimum Horizontal R	adius		470'	587' to 960'	587'	Yes	AASHTO, Table 3-10b	
Maximum Superelevatio	n Rate		varies	8.0%	8.0%	Yes	DM-2, Table 1.3	
Vortige Crede	Minimum		0.10%	0.50%	0.50%	Yes	DM-2, Table 1.3	line segment 103
vertical Grade	Maximum		7.10%	6.00%	6.00%	Yes	AASHTO, Table 7-2	line segment 182
Minimum Stopping Sight Distand (vertical and horizont	e (SSD/HLSD) al)		varies	360' to 495'	360'	Yes	AASHTO, Table 7-1	
Minimum Intersection Sight D	stance (ISD)		varies	500' to 610'	500'	Yes	AASHTO, Table 9-6	
Minimum Cross Slop	)e		varies	2.0%	2.0%	Yes	DM-2, Table 1.3	
Minimum Vertical Clear	ance		N/A	16'-6"	16'-6"	Yes	DM-2, Table 2.2	
*Refer to Publication 10X, Design	Manual 1X, Appe	endix P for more informa	tion on contro	olling criteria and	design exception	ıs.		

Any transit issues? Explain.

Any additional design issues? Explain.

DOADWAN		DESIRED	AVERAGE		NEDDELETION	
ROADWAY CLASS	ROADWAY TYPE	OPERATING SPEED	TRIP LENGTH	VOLUME	INTERSECTION SPACING	COMMENTS
Arterial	Regional	50-90 km/h (30-55 mph)	24-56 km (15-35 mi)	10,000- 40,000 veh/day	200-400 m (660-1,320 ft)	Roadways in this category would be considered "Principal Arterial" in traditional functional classification.
Arterial	Community	40-90 km/h (25-55 mph)	11-40 km (7-25 mi)	5,000- 25,000 veh/day	90-400 m (300-1,320 ft)	Often classified as "Minor Arterial" in traditional classification but may include road segments classified as "Principal Arterial".
Collector	Community	40-90 km/h (25-55 mph)	8-16 km (5-10 mi)	5,000- 15,000 veh/day	90-200 m (300-660 ft)	Often similar in appearance to a community arterial. Typically classified as "Major Collector".
Collector	Neighborhood	40-60 km/h (25-35 mph)	< 11 km (< 7 mi)	< 6,000 veh/day	90-200 m (300-660 ft)	Similar in appearance to local roadways. Typically classified as "Minor Collector".
Local	Local	30-50 km/h (20-30 mph)	< 8 km (< 5 mi)	< 3,000 veh/day	60-200 m (200-660 ft)	

TABLE 1.2 ROADWAY TYPOLOGIES

# INTENTIONALLY BLANK

# FIGURE 1.2 ILLUSTRATED ROADWAY TYPOLOGIES



# FIGURE 1.2 (CONTINUED) ILLUSTRATED ROADWAY TYPOLOGIES



# TABLE 1.3 (ENGLISH) MATRIX OF DESIGN VALUES – REGIONAL ARTERIAL

							!	
	Regional Arterial	Rural	Suburban Neighborhood	Suburban Corridor	Suburban Center	Town/Village Neighborhood	Town/Village Center	Urban Core
	Lane Width <sup>1</sup>	11' to 12'	11' to 12'	11' to 12'	11' to 12'	10' to 12'	10' to 12'	10' to 12'
	Shoulder Width <sup>2, 3</sup>	8' to 10'	8' to 10'	8' to 12'	4' to 6' (if No Parking or Bike Lane)			
	Parking Lane	AN	AN	AN	8' Parallel	8' Parallel	8' Parallel	8' Parallel
	Bike Lane <sup>4</sup>	NA	5' to 6' (if No Shoulder)	6' (if No Shoulder)	5' to 6'	5' to 6'	5' to 6'	5' to 6'
	Median (if needed)	4' to 6'	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only
	Curb Return <sup>5</sup>	30' to 50'	25' to 35'	30' to 50'	25' to 50'	15' to 40'	15' to 40'	15' to 40'
	Travel Lanes	2 to 6	2 to 6	4 to 6	4 to 6	2 to 4	2 to 4	2 to 6
Yewb	Cross Slopes (Minimum) <sup>6, 7</sup>	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%
Road	Cross Slopes (Maximum) <sup>8</sup>	8.0%	6.0%	6.0%	6.0%	6.0%	6.0%	6.0%
	Bridge Widths (Two-Lane Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	_ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side				
	Bridge Widths (Four-Lane or More Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	_ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side				
	Vertical Grades (Minimum) <sup>11</sup>	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%
	Vertical Clearance (Minimum)	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2
	Clear Sidewalk Width	NA	5.	5' to 6'	5' to 6'	6' to 8'	6' to 10'	6' to 12'
z	Buffer <sup>13</sup>	AN	+,9	6' to 10'	4' to 6'	4' to 6'	4' to 6'	4' to 6'
۱ ə	Shy Distance	AA	AA	NA	0' to 2'	0' to 2'	2	2
pispe	Total Sidewalk Width	NA	٦	5' to 6'	9' to 14'	10' to 16'	12' to 18'	12' to 20'
SoA	Clear Zone Widths <sup>14</sup>	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12
	Right-of-Way Widths <sup>15</sup>	Varies	Varies	Varies	Varies	Varies	Varies	Varies
	Desired Operating Speed (Design Speed)	45-55 mph	35-40 mph	35-55 mph	30-35 mph	30-35 mph	30-35 mph	30-35 mph
pəədS	Stopping and Passing Sight Distances (Minimum)	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1
	Vertical Grades (Maximum)	2004 AASHTO Green Book, Exhibit 7-2	2004 AASHTO Green Book, Exhibit 7-10					

				5 ( <u>)</u> ( )				J.S. Custa	mary	<u> 988-976</u>					12653
		V <sub>d</sub> = 15	V <sub>d</sub> = 20	V <sub>d</sub> = 25	V <sub>d</sub> ≈ 30	V <sub>d</sub> = 35	V <sub>d</sub> = 40	V <sub>d</sub> ≈45	V <sub>d</sub> = 50	V <sub>d</sub> = 55	V <sub>d</sub> = 60	V <sub>d</sub> = 65	V <sub>d</sub> = 70	V <sub>d</sub> = 75	V <sub>d</sub> = 80
		mph	mph	mph	mph	mph	mph	mph	ութի	mph	mph	mph	mph	mph	mph
	e {%}	R (ft)	8 (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)					
	NC	932	1640	2370	3240	4260	5410	6710	8150	9720	11500	12900	14500	16100	17800
	RC	676	1190	1720	2370	3120	3970	4930	5990	7150	8440	9510	10700	12900	13300
	2.2	605	1070	1550	2130	2800	3570	4440	5400	6450	7620	8600	9660	10800	12000
	2.4	546	959	1400	1930	2540	3240	4030	4910	5870	6930	7830	8810	9850	11000
· · ·	2.6	496	872	1280	1760	2320	2960	3690	4490	5370	6350	7180	8090	9050	10100
· .	2.8	453	796	1170	1610	2130	2720	3390	4130	4950	5850	6630	7470	8370	9340
	3.0	415	730	1070	1480	1960	2510	3130	3820	4580	5420	6140	6930	7780	8700
	3.2	382	672	985	1370	1820	2330	2900	3550	4250	5040	5720	6460	7260	8130
· ·	3.4	352	620	911	1270	1690	2170	2700	3300	3970	4700	5350	6050	6800	7620
. 1	3.6	324	572	845	1180	1570	2020	2520	3090	3710	4400	5010	5680	6400	7180
· ·	3.8	300	530	784	1100	1470	1890	2360	2890	3480	4140	4710	5350	6030	6780
•	4.0	277	490	729	1030	1370	1770	2220	2720	3270	3890	4450	5050	5710	6420
	4.2	255	453	678	955	1280	1660	2080	2560	3080	3670	4200	4780	5410	6090
	4.4	235	418	630	893	1200	1560	1960	2410	2910	3470	3980	4540	5140	5800
•	4.6	215	384	585	834	1130	1470	1850	2280	2750	3290	3770	4310	4890	5530
	4.8	193	349	542	779	1060	1390	1750	2160	2610	3120	3590	4100	4670	5280
	5.0	172	314	499	727	991	1310	1650	2040	2470	2950	3410	3910	4460	5050
	5.2	154	284	457	676	929	1230	1560	1930	2350	2820	3250	3740	4260	4840
	5.4	139	258	420	627	870	1160	1480	1830	2230	2680	3110	3570	4090	4640
	5.6	126	236	387	582	813	1090	1390	1740	2120	2550	2970	3420	3920	4460
	5,8	115	216	358	542	761	1030	1320	1650	2010	2430	2840	3280	3760	4290
	6.0	105	199	332	506	713	965	1250	1560	1920	2320	2710	3150	3620	4140
	6.2	97	184	308	472	669	909	1180	1480	1820	2210	2600	3020	3480	3990
1.1	6.4	89	170	287	442	628	857	1110	1400	1730	2110	2490	2910	3360	3850
· .	6.6	82	157	267	413	590	808	1050	1330	1650	2010	2380	2790	3240	3720
•	6.8	76	145	248	386	553	761	990	1260	1560	1910	2280	2690	3120	3600
	7.0	70	135	231	360	518	716	933	1190	1480	1820	2180	2580	3010	3480
· *	7.2	64	125	214	336	485	672	878	1120	1400	1720	2070	2470	2900	3370
. 1	7.4	59	115	198	312	451	628	822	1060	1320	1630	1970	2350	2780	3250
. ·	7.6	54	105	182	287	417	583	765	980	1230	1530	1850	2230	2650	3120
·	7.8	48	94	164	261	380	533	701	901	1140	1410	1720	2090	2500	2970
:	8.0	38	76	134	214	314	444	587	758	960	1200	1480	1810	2210	2670

Chapter 3—Elem Table 3-10b. Minimum Radii for Design Superelevation Rates, Design Speeds, and e<sub>max</sub> = 8%

© 2011 by the American Association of State Highway and Transportation Officials. All rights reserved. Duplication is a violation of applicable law.

# A Policy on Geometric Design of Highways and Streets

tance are considered, there are seldom advantages to using the maximum grade values except when grades are long.

				M	etric							J.S. (	Custo	man	<u> </u>		
		N Spec	laxin ified	num Desi	Grado gn Sp	e (%) eed (	for km/h	}		Sp	Maxi ecifie	mun d De	n Gra sign	de (% Spee	6) for d (m	ph)	
Type of Terrain	60	70	80	90	100	110	120	130	40	45	50	55	60	65	70	75	80
Level	5	5	4	4	3	3	3	3	5	5	4	4	3	3	3	3	3
Rolling	6	6	5	5	4	4	4	4	6	6	5	5	4	4	4	4	4
Mountainous	8	7	7	6	6	5	5	5	8	7	7	6	6	5	5	5	5

### Table 7-2. Maximum Grades for Rural Arterials

### **Cross Slope**

Cross slope is provided to enhance roadway drainage. Two-lane rural roadways are normally designed with a centerline crown and traveled-way cross slopes ranging from 1.5 to 2 percent with the higher values being most prevalent.

### Superelevation

Where curves are used on a rural arterial alignment, a superelevation rate based on the design speed should be used. Superelevation rates should not exceed 12 percent; however, where ice and snow conditions are a factor, the maximum superelevation rate should not exceed 8 percent. Superelevation runoff denotes the length of roadway needed to accomplish the change in cross slope from a section with adverse crown removed to a fully superelevated section and vice versa. Adjustments in design runoff lengths may be needed for smooth riding, drainage, and appearance. Section 3.3 provides a detailed discussion of superelevation and tables of appropriate superelevation rates and runoff lengths for various design speeds.

### 7.2.3 Cross-Sectional Elements

### Widths of Roadway

The logical approach to determining appropriate lane and shoulder widths is to provide a width related to the traffic demands. Table 7-3 provides values for the width of traveled way and usable shoulder that should be considered for the volumes indicated. Regardless of weather conditions, shoulders should be usable at all times. On high-volume highways, shoulders should preferably be paved, but paved shoulders may not always be practical. As a minimum, 0.6 m [2 ft] of the shoulder width should be paved to provide for pavement support, wide vehicles, and collision avoidance. Where bicycles are to be accommodated on the shoulder, a minimum paved width of 1.2 m [4 ft] should be used. The shoulder should be constructed to a uniform width for relatively long stretches of roadway. For additional information concerning shoulders, refer to Section 4.4.

### **Sight Distance**

Sight distance is directly related to and varies appreciably with design speed. Stopping sight distance should be provided throughout the length of the roadway. Passing and decision sight distances influence roadway operations and should be provided wherever practical. Providing decision sight distance at locations where complex decisions are made greatly enhances the capability for drivers to safely accomplish maneuvers. Examples of locations where complex decisions are needed include interchanges, high-volume intersections, transitions in roadway width, and transitions in the number of lanes. Providing adequate sight distance on rural arterials, which may combine both high speeds and high traffic volumes, can be complex. Table 7-1 presents the recommended minimum values of stopping and passing sight distance. Refer to Section 3.2 for a comprehensive discussion of sight distance and for tabulated values for decision sight distance.

	Metric			U.S. Customary	
Design Speed (km/h)	Minimum Stopping Sight Distance (m)	Minimum Passing Sight Distance (m)	Design Speed (mph)	Minimum Stopping Sight Distance (ft)	Minimum Passing Sight Distance (ft)
50	65	160	30	200	500
60	85	180	35	250	550
70	105	210	40	305	600
80	130	245	45	360	700
90	160	280	50	425	800
100	185	320	55	495	900
110	220	355	60	570	1000
120	250	395	65	645	1100
130	285	440	70	730	1200
			75	820	1300
			80	910	1400

### Table 7-1. Minimum Sight Distances for Arterials

Ideally, intersections and railroad crossings should be grade separated or provided with adequate sight distance. Intersections should be placed in sag or tangent locations, or both, where practical, to provide maximum visibility of the roadway and pavement markings.

### Alignment

A smooth flowing alignment is desirable on a rural arterial. Changes in alignment, both horizontal and vertical, should be sufficiently gradual to avoid surprising the driver. Minimum radii should be used sparingly; short horizontal curves—particularly at the end of long tangents—should be avoided. Roads with well-designed and consistent alignment usually function more efficiently and with lower crash rates than roads with poor alignment, even where enhanced signing and pavement marking are provided.

### Grades

The length and steepness of grades directly affect the operational characteristics of an arterial. Table 7-2 presents recommended maximum grades for rural arterials. When vertical curves for stopping sight dis-

## 9-38 A Policy on Geometric Design of Highways and Streets

intersection is located on a 4 percent upgrade, then the time gap selected for intersection sight distance design for left turns should be increased from 8.0 to 8.8 s, equivalent to an increase of 0.2 s for each percent grade.

The design values for intersection sight distance for passenger cars are shown in Table 9-6. Figure 9-17 includes design values, based on the time gaps for the design vehicles included in Table 9-5.

No adjustment of the recommended sight distance values for the major-road grade is generally needed because both the major- and minor-road vehicle will be on the same grade when departing from the intersection. However, if the minor-road design vehicle is a heavy truck and the intersection is located near a sag vertical curve with grades over 3 percent, then an adjustment to extend the recommended sight distance based on the major-road grade should be considered.

	Met	ric			U.S. Customary					
Design		Intersecti Distan Passeng	ion Sight ce for er Cars	Design	Stopping	Intersecti Distan Passeng	ion Sight ce for er Cars			
Speed (km/h)	Stopping Sight Distance (m)	Calculated (m)	Design (m)	Speed (mph)	Sight Distance (ft)	Calculated (ft)	Design (ft)			
20	20	41.7	45	15	80	165.4	170			
30	35	62.6	65	20	115	220.5	225			
40	50	83.4	85	25	155	275.6	280			
50	65	104.3	105	30	200	330,8	335			
60	85	125.1	130	35	250	385.9	390			
70	105	146.0	150	40	305	441.0	445			
80	130	166.8	170	45	360	496.1	500			
90	160	187.7	190	50	425	551.3	555			
100	185	208.5	210	55	495	606,4	610			
110	220	229.4	230	60	570	661.5	665			
120	250	250.2	255	65	645	716.6	720			
130	285	271.1	275	70	730	771.8	775			
	_		_	75	820	826.9	830			
		_		80	910	882.0	885			

Table 9-6. Design Intersection Sight Distance—Case B1, Left Turn from Stop

Note: Intersection sight distance shown is for a stopped passenger car to turn left onto a two-lane highway with no median and grades 3 percent or less. For other conditions, the time gap should be adjusted and the sight distance recalculated.

Sight distance design for left turns at divided-highway intersections should consider multiple design vehicles and median width. If the design vehicle used to determine sight distance for a divided-highway intersection is larger than a passenger car, then sight distance for left turns will need to be checked for that selected design vehicle and for smaller design vehicles as well. If the divided-highway median is wide enough to store the design vehicle with a clearance to the through lanes of approximately 1 m [3 ft] at both ends of the vehicle, no separate analysis for the departure sight triangle for left turns is needed on the minor-road approach for the near roadway to the left. In most cases, the departure sight triangle for right

# **55 MPH DESIGN CRITERIA**

NHS? (Y/N) N   STRAHNET? (Y/N) N     3   DESIGN DESIGNATION     SR 28     DESIGN CRITERIA Reconstruction     AREA SYSTEM (Urban/Rural)     FUNCTIONAL CLASSIFICATION     ROADWAY TYPOLOGY     REMARKS     Most locations along corridor     except where other criteria is used
3   DESIGN DESIGNATION     SR 28     DESIGN CRITERIA   Reconstruction     AREA SYSTEM (Urban/Rural)   Rural     FUNCTIONAL CLASSIFICATION   Regional Arterial     ROADWAY TYPOLOGY   Rural     TOPOGRAPHY   Rolling     REMARKS   Most locations along corridor     except where other criteria is used
SR 28   OPENING YEAR ADT (Average Daily Traffic)   7349 (2019)     DESIGN CRITERIA   Reconstruction   8450     AREA SYSTEM (Urban/Rural)   Rural   DESIGN YEAR ADT (Average Daily Traffic)   8450     FUNCTIONAL CLASSIFICATION   Regional Arterial   DESIGN YEAR (for Design Year ADT)   2045     ROADWAY TYPOLOGY   Rural   DHV (Design Hourly Volume)   761     TOPOGRAPHY   Rolling   T (Truck Percentage)   13     REMARKS   Most locations along corridor   13
DESIGN CRITERIA   Reconstruction   DESIGN YEAR ADT (Average Daily Traffic) 8450     AREA SYSTEM (Urban/Rural)   Rural   DESIGN YEAR (for Design Year ADT)   2045     FUNCTIONAL CLASSIFICATION   Regional Arterial   DHV (Design Hourly Volume)   761     ROADWAY TYPOLOGY   Rural   D (Directional Distribution)   59     TOPOGRAPHY   Most locations along corridor   T (Truck Percentage)   13
AREA SYSTEM (Urban/Rural)   Rural   DESIGN YEAR (for Design Year ADT)   2045     FUNCTIONAL CLASSIFICATION   Regional Arterial   DHV (Design Hourly Volume)   761     ROADWAY TYPOLOGY   Rural   D (Directional Distribution)   59     TOPOGRAPHY   Rolling   T (Truck Percentage)   13     REMARKS   Most locations along corridor   except where other criteria is used   13
FUNCTIONAL CLASSIFICATION   Regional Arterial   DHV (Design Houry Volume)   761     ROADWAY TYPOLOGY   Rural   D (Directional Distribution)   59     TOPOGRAPHY   Rolling   T (Truck Percentage)   13     REMARKS   Most locations along corridor   except where other criteria is used   13
TOPOGRAPHY Rolling T (Truck Percentage) 13 REMARKS Most locations along corridor except where other criteria is used
REMARKS Most locations along corridor except where other criteria is used
except where other criteria is used
(5) Criteria* (ENTIRE PROJECT VALUE VALUE VALUE MALTS (AASHTO OR DM-2 Reference) (NOTE ANY DESIGN EXCEPTIONS)
OR BY STATION) VALUE VALUE VALUE (ASTITUTION DIVISION DIVISION EACH HONS)
Design Speed     55 MPH     45-55 MPH     55 MPH     Yes     DM-2, Table 1.3
Lane Width     11'     11' to 12'     11'     Yes     DM-2, Table 1.3
Shoulder Width     6'     8' to 10'     8'     Yes     DM-2, Table 1.3
Minimum Bridge Width     N/A     38' to 44'     N/A     N/A     DM-2, Sec 1.2C
Minimum Horizontal Radius     850'     587' to 960'     960'     Yes     AASHTO, Table 3-10b     North of Summerville
Maximum Superelevation Rate     Varies     8.0%     8.0%     Yes     DM-2, Table 1.3
Vertical Grade Minimum 0.20% 0.50% 0.50% Yes DM-2, Table 1.3 line segment 132
Maximum     7.10%     5.00%     5.00%     Yes     AASHTO, Table 7-2     line segment 157
Minimum Stopping Sight Distance (SSD/HLSD)
(vertical and horizontal) Varies 360' to 495' 495' Yes AASHTO, Table 7-1
Minimum Intersection Sight Distance (ISD)     Varies     500' to 610'     610'     Yes     AASHTO, Table 9-6
Minimum Cross Slope     Varies     2.0%     2.0%     Yes     DM-2, Table 1.3
Minimum Vertical Clearance N/A 16'-6" 16'-6" Yes DM-2, Table 2.2

6

Any pedestrian and bicycle concerns/needs? Explain.

Any ADA compliance issues? Explain.

Any transit issues? Explain.

Any additional design issues? Explain.

DOADWAN		DESIRED	AVERAGE		NEDDOLOTION	
ROADWAY CLASS	ROADWAY TYPE	OPERATING SPEED	TRIP LENGTH	VOLUME	INTERSECTION SPACING	COMMENTS
Arterial	Regional	50-90 km/h (30-55 mph)	24-56 km (15-35 mi)	10,000- 40,000 veh/day	200-400 m (660-1,320 ft)	Roadways in this category would be considered "Principal Arterial" in traditional functional classification.
Arterial	Community	40-90 km/h (25-55 mph)	11-40 km (7-25 mi)	5,000- 25,000 veh/day	90-400 m (300-1,320 ft)	Often classified as "Minor Arterial" in traditional classification but may include road segments classified as "Principal Arterial".
Collector	Community	40-90 km/h (25-55 mph)	8-16 km (5-10 mi)	5,000- 15,000 veh/day	90-200 m (300-660 ft)	Often similar in appearance to a community arterial. Typically classified as "Major Collector".
Collector	Neighborhood	40-60 km/h (25-35 mph)	< 11 km (< 7 mi)	< 6,000 veh/day	90-200 m (300-660 ft)	Similar in appearance to local roadways. Typically classified as "Minor Collector".
Local	Local	30-50 km/h (20-30 mph)	< 8 km (< 5 mi)	< 3,000 veh/day	60-200 m (200-660 ft)	

TABLE 1.2 ROADWAY TYPOLOGIES

# INTENTIONALLY BLANK

# FIGURE 1.2 ILLUSTRATED ROADWAY TYPOLOGIES



# FIGURE 1.2 (CONTINUED) ILLUSTRATED ROADWAY TYPOLOGIES



# TABLE 1.3 (ENGLISH) MATRIX OF DESIGN VALUES – REGIONAL ARTERIAL

							1	
	Regional Arterial	Rura	Suburban Neighborhood	Suburban Corridor	Suburban Center	Town/Village Neighborhood	Town/Village Center	Urban Core
	Lane Width <sup>1</sup>	11' to 12'	11' to 12'	11' to 12'	11' to 12'	10' to 12'	10' to 12'	10' to 12'
	Shoulder Width <sup>2, 3</sup>	8' to 10'	8' to 10'	8' to 12'	4' to 6' (if No Parking or Bike Lane)			
	Parking Lane	NA	NA	AA	8' Parallel	8' Parallel	8' Parallel	8' Parallel
	Bike Lane <sup>4</sup>	NA	5' to 6' (if No Shoulder)	6' (if No Shoulder)	5' to 6'	5' to 6'	5' to 6'	5' to 6'
	Median (if needed)	4' to 6'	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only
	Curb Return <sup>5</sup>	30' to 50'	25' to 35'	30' to 50'	25' to 50'	15' to 40'	15' to 40'	15' to 40'
	Travel Lanes	2 to 6	2 to 6	4 to 6	4 to 6	2 to 4	2 to 4	2 to 6
Yewb	Cross Slopes (Minimum) <sup>6, 7</sup>	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%
Гоас	Cross Slopes (Maximum) <sup>8</sup>	8.0%	6.0%	6.0%	6.0%	6.0%	6.0%	6.0%
	Bridge Widths (Two-Lane Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	_ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side				
	Bridge Widths (Four-Lane or More Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	_ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side				
	Vertical Grades (Minimum) <sup>11</sup>	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%
	Vertical Clearance (Minimum)	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2
	Clear Sidewalk Width	NA	5'	5' to 6'	5' to 6'	6' to 8'	6' to 10'	6' to 12'
7.	Buffer <sup>13</sup>	AA	6'+	6' to 10'	4' to 6'	4' to 6'	4' to 6'	4' to 6'
l 9	Shy Distance	AA	NA	NA	0' to 2'	0' to 2'	2'	2'
pispe	Total Sidewalk Width	NA	Ω	5' to 6'	9' to 14'	10' to 16'	12' to 18'	12' to 20'
SoA	Clear Zone Widths <sup>14</sup>	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12
	Right-of-Way Widths <sup>15</sup>	Varies	Varies	Varies	Varies	Varies	Varies	Varies
	Desired Operating Speed (Design Speed)	45-55 mph	35-40 mph	35-55 mph	30-35 mph	30-35 mph	30-35 mph	30-35 mph
pəədS	Stopping and Passing Sight Distances (Minimum)	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1
	Vertical Grades (Maximum)	2004 AASHTO Green Book, Exhibit 7-2	2004 AASHTO Green Book, Exhibit 7-10					
L								

				5 ( <u>)</u> ( )				J.S. Custa	mary	<u> 988-976</u>					
		V <sub>d</sub> = 15	V <sub>d</sub> = 20	V <sub>d</sub> = 25	V <sub>d</sub> ≈ 30	V <sub>d</sub> = 35	V <sub>d</sub> = 40	V <sub>d</sub> ≈45	V <sub>d</sub> = 50	V <sub>d</sub> = 55	V <sub>d</sub> = 60	V <sub>d</sub> = 65	V <sub>d</sub> = 70	V <sub>d</sub> = 75	V <sub>d</sub> = 80
		mph	mph	mph	mph	mph	mph	mph	ութի	mph	mph	mph	mph	mph	mph
	e {%}	R (ft)	8 (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)					
	NC	932	1640	2370	3240	4260	5410	6710	8150	9720	11500	12900	14500	16100	17800
	RC	676	1190	1720	2370	3120	3970	4930	5990	7150	8440	9510	10700	12900	13300
	2.2	605	1070	1550	2130	2800	3570	4440	5400	6450	7620	8600	9660	10800	12000
	2.4	546	959	1400	1930	2540	3240	4030	4910	5870	6930	7830	8810	9850	11000
· · ·	2.6	496	872	1280	1760	2320	2960	3690	4490	5370	6350	7180	8090	9050	10100
· .	2.8	453	796	1170	1610	2130	2720	3390	4130	4950	5850	6630	7470	8370	9340
	3.0	415	730	1070	1480	1960	2510	3130	3820	4580	5420	6140	6930	7780	8700
	3.2	382	672	985	1370	1820	2330	2900	3550	4250	5040	5720	6460	7260	8130
· ·	3.4	352	620	911	1270	1690	2170	2700	3300	3970	4700	5350	6050	6800	7620
. 1	3.6	324	572	845	1180	1570	2020	2520	3090	3710	4400	5010	5680	6400	7180
· ·	3.8	300	530	784	1100	1470	1890	2360	2890	3480	4140	4710	5350	6030	6780
•	4.0	277	490	729	1030	1370	1770	2220	2720	3270	3890	4450	5050	5710	6420
	4.2	255	453	678	955	1280	1660	2080	2560	3080	3670	4200	4780	5410	6090
	4.4	235	418	630	893	1200	1560	1960	2410	2910	3470	3980	4540	5140	5800
•	4.6	215	384	585	834	1130	1470	1850	2280	2750	3290	3770	4310	4890	5530
	4.8	193	349	542	779	1060	1390	1750	2160	2610	3120	3590	4100	4670	5280
	5.0	172	314	499	727	991	1310	1650	2040	2470	2950	3410	3910	4460	5050
	5.2	154	284	457	676	929	1230	1560	1930	2350	2820	3250	3740	4260	4840
	5.4	139	258	420	627	870	1160	1480	1830	2230	2680	3110	3570	4090	4640
	5.6	126	236	387	582	813	1090	1390	1740	2120	2550	2970	3420	3920	4460
	5,8	115	216	358	542	761	1030	1320	1650	2010	2430	2840	3280	3760	4290
	6.0	105	199	332	506	713	965	1250	1560	1920	2320	2710	3150	3620	4140
	6.2	97	184	308	472	669	909	1180	1480	1820	2210	2600	3020	3480	3990
1.1	6.4	89	170	287	442	628	857	1110	1400	1730	2110	2490	2910	3360	3850
· .	6.6	82	157	267	413	590	808	1050	1330	1650	2010	2380	2790	3240	3720
•	6.8	76	145	248	386	553	761	990	1260	1560	1910	2280	2690	3120	3600
	7.0	70	135	231	360	518	716	933	1190	1480	1820	2180	2580	3010	3480
· *	7.2	64	125	214	336	485	672	878	1120	1400	1720	2070	2470	2900	3370
. 1	7.4	59	115	198	312	451	628	822	1060	1320	1630	1970	2350	2780	3250
. ·	7.6	54	105	182	287	417	583	765	980	1230	1530	1850	2230	2650	3120
·	7.8	48	94	164	261	380	533	701	901	1140	1410	1720	2090	2500	2970
:	8.0	38	76	134	214	314	444	587	758	960	1200	1480	1810	2210	2670

Chapter 3—Elem Table 3-10b. Minimum Radii for Design Superelevation Rates, Design Speeds, and e<sub>max</sub> = 8%

© 2011 by the American Association of State Highway and Transportation Officials. All rights reserved. Duplication is a violation of applicable law.

# A Policy on Geometric Design of Highways and Streets

tance are considered, there are seldom advantages to using the maximum grade values except when grades are long.

		Metric								U.S. Customary								
	Maximum Grade (%) for Specified Design Speed (km/h)									Maximum Grade (%) for Specified Design Speed (mph)								
Type of Terrain	60	70	80	90	100	110	120	130	40	45	50	55	60	65	70	75	80	
Level	5	5	4	4	3	3	3	3	5	5	4	4	3	3	3	3	3	
Rolling	6	6	5	5	4	4	4	4	6	6	5	5	4	4	4	4	4	
Mountainous	8	7	7	6	6	5	5	5	8	7	7	6	6	5	5	5	5	

### Table 7-2. Maximum Grades for Rural Arterials

### **Cross Slope**

Cross slope is provided to enhance roadway drainage. Two-lane rural roadways are normally designed with a centerline crown and traveled-way cross slopes ranging from 1.5 to 2 percent with the higher values being most prevalent.

### Superelevation

Where curves are used on a rural arterial alignment, a superelevation rate based on the design speed should be used. Superelevation rates should not exceed 12 percent; however, where ice and snow conditions are a factor, the maximum superelevation rate should not exceed 8 percent. Superelevation runoff denotes the length of roadway needed to accomplish the change in cross slope from a section with adverse crown removed to a fully superelevated section and vice versa. Adjustments in design runoff lengths may be needed for smooth riding, drainage, and appearance. Section 3.3 provides a detailed discussion of superelevation and tables of appropriate superelevation rates and runoff lengths for various design speeds.

### 7.2.3 Cross-Sectional Elements

### Widths of Roadway

The logical approach to determining appropriate lane and shoulder widths is to provide a width related to the traffic demands. Table 7-3 provides values for the width of traveled way and usable shoulder that should be considered for the volumes indicated. Regardless of weather conditions, shoulders should be usable at all times. On high-volume highways, shoulders should preferably be paved, but paved shoulders may not always be practical. As a minimum, 0.6 m [2 ft] of the shoulder width should be paved to provide for pavement support, wide vehicles, and collision avoidance. Where bicycles are to be accommodated on the shoulder, a minimum paved width of 1.2 m [4 ft] should be used. The shoulder should be constructed to a uniform width for relatively long stretches of roadway. For additional information concerning shoulders, refer to Section 4.4.
### **Sight Distance**

Sight distance is directly related to and varies appreciably with design speed. Stopping sight distance should be provided throughout the length of the roadway. Passing and decision sight distances influence roadway operations and should be provided wherever practical. Providing decision sight distance at locations where complex decisions are made greatly enhances the capability for drivers to safely accomplish maneuvers. Examples of locations where complex decisions are needed include interchanges, high-volume intersections, transitions in roadway width, and transitions in the number of lanes. Providing adequate sight distance on rural arterials, which may combine both high speeds and high traffic volumes, can be complex. Table 7-1 presents the recommended minimum values of stopping and passing sight distance. Refer to Section 3.2 for a comprehensive discussion of sight distance and for tabulated values for decision sight distance.

	Metric			U.S. Customary	
Design Speed (km/h)	Minimum Stopping Sight Distance (m)	Minimum Passing Sight Distance (m)	Design Speed (mph)	Minimum Stopping Sight Distance (ft)	Minimum Passing Sight Distance (ft)
50	65	160	30	200	500
60	85	180	35	250	550
70	105	210	40	305	600
80	130	245	45	360	700
90	160	280	50	425	800
100	185	320	55	495	900
110	220	355	60	570	1000
120	250	395	65	645	1100
130	285	440	70	730	1200
			75	820	1300
			80	910	1400

#### Table 7-1. Minimum Sight Distances for Arterials

Ideally, intersections and railroad crossings should be grade separated or provided with adequate sight distance. Intersections should be placed in sag or tangent locations, or both, where practical, to provide maximum visibility of the roadway and pavement markings.

#### Alignment

A smooth flowing alignment is desirable on a rural arterial. Changes in alignment, both horizontal and vertical, should be sufficiently gradual to avoid surprising the driver. Minimum radii should be used sparingly; short horizontal curves—particularly at the end of long tangents—should be avoided. Roads with well-designed and consistent alignment usually function more efficiently and with lower crash rates than roads with poor alignment, even where enhanced signing and pavement marking are provided.

#### Grades

The length and steepness of grades directly affect the operational characteristics of an arterial. Table 7-2 presents recommended maximum grades for rural arterials. When vertical curves for stopping sight dis-

### 9-38 A Policy on Geometric Design of Highways and Streets

intersection is located on a 4 percent upgrade, then the time gap selected for intersection sight distance design for left turns should be increased from 8.0 to 8.8 s, equivalent to an increase of 0.2 s for each percent grade.

The design values for intersection sight distance for passenger cars are shown in Table 9-6. Figure 9-17 includes design values, based on the time gaps for the design vehicles included in Table 9-5.

No adjustment of the recommended sight distance values for the major-road grade is generally needed because both the major- and minor-road vehicle will be on the same grade when departing from the intersection. However, if the minor-road design vehicle is a heavy truck and the intersection is located near a sag vertical curve with grades over 3 percent, then an adjustment to extend the recommended sight distance based on the major-road grade should be considered.

	Met	ric			U.S. Customary				
Design		Intersection Sight Distance for Passenger Cars Calculated Design (m) (m)		Design	Stopping	Intersection Sight Distance for Passenger Cars			
Speed (km/h)	Stopping Sight Distance (m)			Speed (mph)	Sight Distance (ft)	Calculated (ft)	Design (ft)		
20	20	41.7	45	15	80	165.4	170		
30	35	62.6	65	20	115	220.5	225		
40	50	83.4	85	25	155	275.6	280		
50	65	104.3	105	30	200	330,8	335		
60	85	125.1	130	35	250	385.9	390		
70	105	146.0	150	40	305	441.0	445		
80	130	166.8	170	45	360	496.1	500		
90	160	187.7	190	50	425	551.3	555		
100	185	208.5	210	55	495	606,4	610		
110	220	229.4	230	60	570	661.5	665		
120	250	250.2	255	65	645	716.6	720		
130	285	271.1	275	70	730	771.8	775		
	_		_	75	820	826.9	830		
		_		80	910	882.0	885		

Table 9-6. Design Intersection Sight Distance—Case B1, Left Turn from Stop

Note: Intersection sight distance shown is for a stopped passenger car to turn left onto a two-lane highway with no median and grades 3 percent or less. For other conditions, the time gap should be adjusted and the sight distance recalculated.

Sight distance design for left turns at divided-highway intersections should consider multiple design vehicles and median width. If the design vehicle used to determine sight distance for a divided-highway intersection is larger than a passenger car, then sight distance for left turns will need to be checked for that selected design vehicle and for smaller design vehicles as well. If the divided-highway median is wide enough to store the design vehicle with a clearance to the through lanes of approximately 1 m [3 ft] at both ends of the vehicle, no separate analysis for the departure sight triangle for left turns is needed on the minor-road approach for the near roadway to the left. In most cases, the departure sight triangle for right

# APPENDIX D Stakeholder Meeting Minutes

Pagel of 2

Stakeholder Outreach INTERVIEW INVITATION SIGN IN SHEET BROOKVILLE February 26, 2020

STUDY STUDY	G TO 1-80
E B	TRNMING
CORRI	FROM HIT

NAME	ORGANIZATION	EMAIL	PHONE
Josh Spano	SPC	) spande spiregurning	
Ashley Tracy	We Corruice Tag le	and racy anon with tay be	
Kari Shedlock	French Encinerias	Kshedlocke frenchenar com	
Mary Eberhardt	French Engineering	Weberhard Chenchencr. c	Ma
Evan Schoss	SPC 0	pschosse spercyion.	610
Deb Wilson	SCOD	Jord @ windstram. met	
Any Kirster	NC 2.7.0	Any Oncertal. ch	814-773.3142
PAUE TONIASMICK	PENNUDON DISTRICT 10	DOMASUACK @ PA . 40 V	724 357 2845
Aurie Ledacie	K K		
Steve MC Nevsen	Willestabrichtion Solu	smepherson Omiller Fabrication solutions cond	8/4-715-0691
Joe Barber	Barber Toucking	jor @barbutrucking. con	814-913-1526
AARON EMHOEF	PENNDOT	demholfepagou	814-939-9167
-back Madson	Jeffer on Ount,	Undry Leftersneart M. C.	P14-P49-1653
AFRIS BUILTER SNAL	20 Ac Prese Co.	h bolles A Recourty Pa.	Car 849 -1652
Juff fisan K	Tipperson, chy	the server a pettoserienty	PHE. / WED

Page Zef Z

Stakeholder Outreach INTERVIEW INVITATION SIGN IN SHEET BROOKVILLE February 26, 2020

	5 📕
SNE	- F
	N N
	ξĒ
-	
	2
20	00
	) 😤

	849.5052	849-4009							
PHONE	may Br. Com	, por to way							
EMAIL	+2ersta Chercon	cclor ko Jefterbrow							
ORGANIZATION	JEFFERSON GUISTY	Selferantin 1 1 911							
NAME	TRACY ZENTS	Chreis Clerk							

Ø



Meeting:	Stakeholder Interview Meeting - Brookville	Date:
Location:	Jefferson County Conservation District	Time:

 Date:
 February 26, 2020

 Time:
 10:00am to 11:30am

Attendees: See attached sign-in sheet

*Purpose:* The purpose of the meeting was to interview a variety of stakeholders for the Route 28 Corridor Study Project to obtain input from their local knowledge for consideration of proposed improvement within the study.

*Discussion:* The format of the meeting followed an initial list of questioned provided to the stakeholders to guide the discussion. This list provided a general outline of project specific question regarding the use, operation and safety within the Route 28 Corridor. The following information provided a summary of the stakeholders input at the meeting and discussion:

- Traffic signals are not synchronized, and during an emergency detour situation, can cause traffic congestion. Presently, municipalities control them, but it would be good if a centralized authority made up of various stakeholders had operational control during emergencies.
- When traffic is detoured on I-80, some vehicles don't use the posted detour, and a lot of traffic is converging in Brookville at the intersection of SR 28 and US 322 near Sheetz. When I-80 is detoured, need coordination in Brookville due to traffic gridlock at that intersection.
- There is no parallel route for I-80 closures, people don't realize the detours and cell phones will just bring them right back into the detour. It was suggested to install message boards on parallel routes to control traffic on SR 28.
- Recently, a tanker had an accident on I-80, and traffic was detoured to SR 28. Traffic was at a standstill for hours and hazardous material freight was coming off the interstate onto SR 28 which creates potential for accident or contamination that close to the Red Bank Creek. There is a need for a spill response team or plan along the corridor. During detour traffic, it is also extremely difficult for local emergency vehicles to get through the detour congestion since the shoulders on the corridor are so narrow. They cannot bypass the traffic.
- I-80 has no signage to show that SR 28 leads to Pittsburgh, and the Pittsburgh Airport.
- Many accidents occur from the Brookville Borough line to Snyder Road.
- Coder Road experiences accidents with commercial vehicles turning into Coder Road.
- There are landslides that occur north of Summerville.
- There are issues on Anderson Creek Road with commercial vehicles in the wintertime getting stuck on the top of the hill due to the steep grade.
- The Redbank Creek runs parallel to SR 28. The main concerns are with its proximity to the roadway, including potential for hazardous materials spills, flooding, ice jams, and narrow shoulders around the Summerville area.
- I-80/SR 322/SR 28 is a potential economic hub/area for development that would benefit from improved alignment and traffic conditions.
- Mendenhall Road is a safety concern due to sight distance/blind curve.
- Mayport Road is a safety concern as trucks have difficulty turning here due to the skew of the intersection, which is compounded by poor sight distance caused by the hill and the curvature of the roadway.
- Amy Kessler asked the question if there would be an increase in freight traffic due to the Shell Pennsylvania Petrochemicals Complex in Beaver County (cracker plant). The consensus was there would not be significant changes, though some minor manufacturing trips to process the plastic pellets could use the corridor.
- Since the turnpike tolls are high, and some trucks use 28 as a connector. This increases commuter and truck traffic on SR 28. Fuel tax is also too high. Many trucks will drop down to take 68 and pay the lower gas tax in Maryland.
- The issue with possible tolling of major highways and its implication on SR 28 was discussed.
- The Potters Mills project further east on US 322 was discussed. It was the consensus that when this project is complete more traffic that would use the Turnpike will instead be using SR 28 as an alternate route since it's a better connection.
- Jefferson County PennDOT maintenance stated that there are several crash clusters along SR 28 due to hills and curves. They also reiterated that congestion becomes an issue when traffic is detoured from I-80, but vehicles are following GPS instead of the posted detour. Noted a need for coordinated overhead messaging signs. Transporting a sign out from the

District office to tell people to stay on the detour route takes too long to be efficient at moving people before it becomes gridlock.

- There is inconsistency in speed limit and prevailing speed on SR 28 for the length of the corridor.
- The Redbank Valley Trail does not have good connections to Route 28. There is a lack of signage denoting where the trail can be accessed. The current trail crossing north New Bethlehem is perceived as particularly challenging.
- The Mayport curve was discussed as having sight distance concerns.
- The Baxter curve was discussed as having issues due to geometry and sight distance. Trucks also speed through Baxter. A possible improvement would be Baxter and Summerville widening and flattening the existing curves.
- It was mentioned that cell phone coverage along SR 28 is inconsistent, which could cause concerns for vehicle breakdowns and for those following GPS.
- Miller Transportation indicated they have daily deliveries on the corridor and speed is an issue for them. They would like to see a 4-lane roadway from Brookville to Kittanning as they are expecting deliveries to grow.
- The Conservation District indicated that water quality and spills were a major concern with the potential for increased traffic and the frequent use of Route 28 as a I-80 detour route.
- Amy Kessler asked about truck parking on the corridor. Generally the consensus was that truck parking presents little concern
  along the corridor. No one noted designated or unofficial locations of truck parking overnight on the corridor. The
  representative of the local freight community said that more shippers are providing overnight amenities at their facilities due to
  the new regulations. Haulers are also considering changes to their hours of operation to take shipments to more effectively
  meet the regulations.
- Hazen interchange was discussed as a possible future development project that could impact the traffic on SR 28.
- ATV crossings were noted along SR 28. ATV signs in the area around Dewey Road.
- In general, school bus stops along the corridor are hazardous, particularly where there is a 3-lane section with a passing lane. Cars will pass school buses even when they are supposed to stop. For example, south of Coder Hollow, a bus stop is located where the 3-lane road begins. Not an ideal place for a bus stop as people are speeding to get to the 3-lane road and pass slower moving vehicles.
- The guide rail is thought to be insufficient in Summerville and Baxter because you are so close to the water. It was noted that in recent years, a vehicle ran off the road and a woman drowned in the creek.
- In the summer, farming equipment using the road south of Summerville and throughout the corridor often slows traffic.
- The following tourism draws were discussed:
  - o Cooks Forest draws a lot of traffic from Pittsburgh
  - o Trout season
  - o Deer Season
  - o Poker Runs
  - o Peanut Butter Festival
  - o Historic Brookville
  - o Laurel Festival
  - o Several festivals in the summer
  - o Hazen Flea Market
  - o Autumn Leaf Festival
- Companies located along the corridor are doing their own shipping which increases the number of trucks on the road. Logging company employs independent drivers.

A list of action items was developed to summarize the stakeholders input and potential improvement areas within the study. The study team will further evaluate these stakeholder concern locations with our existing conditions, crash history, geometric conditions, public input, and operational conditions. The stakeholder action items to be considered are listed below:

### Action Item List:

- Determine existing Variable Messaging Signing (VMS) that exists on I-80 and its proximity to the Route 28 Corridor.
- Further discuss areas where VMS placement along the corridor at strategic locations may provide helpful information during an I-80 emergency detour for travelers to consider prior to entering into congested areas to reduce gridlock. Also, this could serve as advanced warning for winter weather events or incidents along Route 28.
- Evaluate potential directional signing updates along I-80 to indicate that Route 28 connects to Pittsburgh and the Pittsburgh International Airport.
- Potential areas where emergency responders may have difficulty getting through congested areas during the use of Rt 28 as an I-80 detour route.
- Further investigate specific concerns noted by stakeholders at the following locations:
  - Brookville Borough line to Snyder Road
  - Route 28 near the Redbank Creek near Summerville
  - Mendenhall Road sight distance
  - Route 28 and Mayport Road sight distance/truck turning concerns with entrance skew
  - Summerville and Baxter potential for deficient guide rail

The meeting was adjourned at approximately 11:15 a.m. by thanking the stakeholders for their feedback and time.

Prepared by:

MCCORMICK TAYLOR, INC.

<u>Copies:</u> Attendees

MT Project File

Attachments:

Meeting Sign-in Sheet

Stakeholder Outreach INTERVIEW INVITATION SIGN IN SHEET

> ROUTE28 CORRIDOR STUDY

NEW BETHLEHEM February 26, 2020

PHONE			814-319-5200		814-221-9819	814-319-3401	734-543-3011	724 357 2645	814-226-4000,×2800	(14-329-544)	60 GH-275-2003	814 226 -8200	8121-522-218	H (Project Team)	
EMAIL			tomseidlelyaha	2			ESINKOCA. GOV	DOMASMICICO P. GON	a Lamato & Co. Clanon.		moyor ON entsethlehmille	Jelizer@ pa.gov	schateer (By mail. rom	edlock Wary Eberhand	
ORGANIZATION	XX	8PC	mahan 1 Two	Hauthon	MAHONING TWP	Hawthorn Boro.	PSP KITAWNING	PENNIDOT DISTRICT 10	Clarier Co. Planning	Mahoning Teep ARWS	New Bethlehen Maxis	Cloren Court, PenDUT	New Berly Berly Weils Aron	we. Evian Schoss, kani sh	
NAME	guer e adarel	Ryan Gordon	Tom Seidle	TERRY BEDMU	HEN BIAKE	Mallinda Little	ERIC SIMKU	PAUE TOMAINICK	Krish' Amoto	Re-14 Schoeckenest	Gerton Berrows	Jush Climps	Saudy meter	Ashley Tracy, Josh Sod	



Meeting:Stakeholder Interview Meeting – New BethlehemLocation:New Bethlehem Public Library Community Room

 Date:
 February 26, 2020

 Time:
 1:00pm to 2:30pm

Attendees: See attached sign-in sheet

*Purpose:* The purpose of the meeting was to interview a variety of stakeholders for the Route 28 Corridor Study to obtain input from their local knowledge for consideration of proposed improvement within the study.

*Discussion:* The format of the meeting followed an initial list of questioned provided to the stakeholders to guide the discussion. This list provided a general outline of project specific question regarding the use, operation and safety within the Route 28 Corridor. The following information provided a summary of the stakeholders input at the meeting and discussion:

- The pedestrian crossing at Redbank Valley School is challenging with fast-moving vehicles nearby and many pedestrians. Vehicles typically park across SR 28 from the school and children cross SR 28 to get to their parents. They would like to evaluate a sign and/or traffic signal.
- The trail crossing is under PUC authority because it's a railbanked corridor. The crossing is particularly difficult and would benefit from signing in advance of and at the crossing, flashing lights, as well as a realignment of the trail so that it is perpendicular to the road and shortened, instead of crossing at a diagonal. The painted crosswalk across SR 28 was removed due to driver complaints, but the location has anecdotally had numerous accidents with folks driving off the road.
- The question was also posed if the restrictions on Tourist Oriented Directional Signing (TODS) could be lessened. The town would benefit from markers for economic development of businesses on trail, including B&B's, as well as for parking areas.
- There may be trail counts done by the Redbank Valley Trail Association, though most counters have been damaged or stolen. Study team will look into obtaining previous counts taken of the trail users.
- The Mahoning Township supervisors mentioned a study that was done to look at locations for the trail or roadway in front of Nolf Chrysler, that would side cut the hill, flatten the trail past Chrysler but there was a wetland issue that stopped the study moving forward. Wetland mitigation was mentioned as a potential solution for the project. Study team will look into obtaining this information.
- Redbank Valley High School has issues with pedestrians crossing the street during the school dismissal hour at 3:10pm. Parents park in the Subway and Chiropractor parking lots and then jump onto Route 28. They said there is plenty of parking in the back of the school, but that parents and students don't want to use it. They have crossing guards but are curious if a traffic signal could help. It's primarily drivers, with some walking students crossing to walk down the trail to get back to their homes. Dr. Mastillo, superintendent of the Redbank Valley School District, was supposed to attend but could not at the last minute, study team will follow up with him.
- It was discussed that congestion becomes an issue when traffic is detoured from I-80 but vehicles are following GPS instead of the posted detour.
- There is a operational concern at the SR 28/SR 66 intersection when trying to detour trucks due to geometric constraints. Trucks frequently hit the building and traffic signals at this location. The pole has been hit 8 times since the pedestrian ramp was installed. One day there was a bollard, but it kept getting hit and never came back. Cars also regularly pull beyond the stop bar and this creates congestion because trucks cannot navigate the turn with them there.
- Generally, the PSP has issues along SR 28 due to hills, climbing lanes (or lack of) needed at Hogback Hill and Orchardville Hill toward Exxon Station to Baum Pump Station. Other issues include snow, trucks that get diverted from I-80, and speeding along the corridor.
- PSP said speed along Route 28 is a safety concern, but there is not a high rate of crashes in this area of Route 28 if you compare it to the lower portion of Route 28.

- There is a choke point at the bridge in New Bethlehem over Redbank Creek which causes congestion. Any major crash, spill, or slide would wreak havoc on the transportation system because there is no way around it. The transportation system is very limited in this area.
- It was indicated that there should be improvements to the crosswalks throughout New Bethlehem and Hawthorn.
- Speed is an issue at the mini mall. The speed limit is 35 mph in one direction and 25 mph in the other. PennDOT mentioned that it should not be signed differently in opposing directions, and that the roadway needs to meet certain requirements to be posted at 25mph, including 85<sup>th</sup> percentile speed and residential density.
- There was another speed limit difference noted in Hawthorn, where it is 45 mph in one direction and 35 mph in the other. PennDOT again stated that it should not be signed as such.
- Along SR 28 from Kittanning, there are issues with erosion which is causing the guiderail to shift.
- Generally, the Redbank Creek runs along SR 28 too close to the road (horizontally and vertically) and during the winter months, ice jams cause issues over the roadway, including flooding. It was suggested that the stream needs to be dredged in some areas to remove debris. The Leisure Run flood is still being cleaned up.
- The 3-lane roadway ends at the Mahoning Creek Bridge.
- There is a 55/40/55 speed differential through difficult geometry which makes traveling through Distant difficult.
- A northbound turning lane begins where a passing lane ends at the crest of a hill at Calhoun School Road. This poses a safety concern for potential rear end and head on collisions. People think this is an extension of the passing lane and use it for passing.
- There is an ice cream shop directly adjacent to SR 28 that is very popular near Distant. Distant Dairy and Dollar General have a lot of traffic and generate pedestrians close to the roadway. Dollar General is noted as a difficultarea to pull out of due to blind curves. Some places in Distant lack sidewalks.
- There are rockslide and hill side erosion issues along the corridor which occur frequently and in many places.
- The intersection of SR 28 and SR 536 Mayport Road has deficient sight distance.
- Smucker's currently has access issues to their plant that could be addressed with a future project. In particular, the intersection of Wood and Penn poses an issue for trucks driving to Smucker's having to use local roads. Trucks get trapped and end up driving into people's yards and break the curb and sidewalk. They would like to see Smucker's have their own access road, but a study was done in the past and there was possibly a problem with sight distance that could not be overcome. Ms. Amato was involved with the Economic Development Commission with this study. The study team will obtain a copy.
- New Bethlehem Borough provided a list of issues that are included as an attachment to this summary.
- The passing lane at Distant is not long enough coming up the hill, then you hit 40mph, and SR 1004 is a quick turn with poor deceleration length.
- Upper/Lower Hayes at 28, and South Main Street could use a turn lane to separate turning vehicles from the general through traffic.
- Parking near the Sunoco/Key Beverage on Broad Street causes issues for traffic traveling WB turning into Sunoco. It could use a turn lane or restrict some parking closer to the area to provide room to turn into these businesses.
- There is acid mine drainage from Summerville to Moore Road in Corsica.
- On the 3 lane sections of SR 28, it has been noticed by PSP that vehicles in the opposing outermost lane do not stop for school buses when they legally are required to.
- There are sight distance issues at the PennDOT maintenance/school bus turnaround location at the Jefferson County line.
- The sidewalks in Distant and South Bethlehem are in poor condition.
- It was suggested that turning lanesare needed at Sloan Hill Road and Calhoun Crest.
- There are little to no issues with freight loading in the downtown New Bethlehem area. There aren't many places that freight has to stop.
- The following tourism draws were discussed:
  - o Redbank Valley Trail

- o Redbank Creek during trout season
- o Bed and Breakfast locations
- o Local campgrounds
- o The County Fair at the end of July is a large traffic generator
- o Poker Runs (ATV event)
- o Peanut Butter Festival
- Friday night football games
- o Deer season
- o I-80/SR 28 in Brookville is a route to the Pittsburgh International Airport

The meeting was adjourned at approximately 1:15 p.m. by thanking the stakeholders for their feedback and time. A list of action items was developed to summarize the stakeholders input and potential improvement areas within the study. The study team will further evaluate these stakeholder concern locations with our existing conditions, crash history, geometric conditions, public input, and operational conditions. The stakeholder action items to be considered are listed below:

### Action Item List:

- Consider potential for climbing lanes at Hogback Hill and Orchardville Hill toward Exxon Station to Baum Pump Station.
- Consider potential/need for alternate route to bypass bridge in New Bethlehem over Redbank Creek during an incident.
- Consider designated crosswalk improvements for consistent and safe pedestrian access across Route 28.
- Obtain trail counts and previous studies on crossing locations performed by the Redbank Valley Trail Assocation.
- Obtain Smucker's access study for consideration.
- Connect with school superintendent separately to note New Bethlehem School District's concerns along the corridor.
- Document areas of inconsistent speed limits along Route 28 and in certain area in NB and SB directions.
- Investigate potential narrow shoulders or flooding issues where Redbank Creek is close to Route 28.
- Consider potential turning lanes at Upper/Lower Hayes Road and at South Main Street.
- Consider pedestrian access and sidewalks in Distant and South Bethlehem.
- Consider improvements at Sloan Hill Road and Calhoun School Road to improve sight distance and safety.
- Further investigate specific concerns noted by stakeholders at the following locations:
  - o Pedestrian crossing at Redbank Valley High School.
  - o Redbank Trail crossing at Route 28.
  - o SR 28/SR 66 intersection geometric improvements for trucks to navigate the intersection.
  - Calhoun School Road where the northbound passing lane ends at the crest of a hill and stops in a turning lane.
  - o Pedestrian connections and sight distance at Distant Dairy and Dollar General.
  - o SR 28 and SR 536 Mayport Road and potential improvements to address deficient sight distance.
  - Hogback Hill potential lengthening of passing lane coming up into Distant.
  - o Jefferson County line PennDOT maintenance/school bus turnaround location sight distance issues.

Prepared by: McCORMICK TAYLOR, INC. Copies:

## Attendees

MT Project File

<u>Attachments:</u> Meeting Sign-in Sheet Borough of New Bethlehem Identified Areas of Concern Photos of Meeting Rt 28 improvements/Corridor Study Comments - Sandy Mateer, 814-275-1718, VP of New Bethlehem Borough Council and President of Redbank Valley Trails Association

## Starting at SR 28/66 at intersection with Rt 85 and Clearfield Pike. (Mile 0)

1. **From Mile 0 north** – replace guardrails, reduce litter and inspect erosion of northbound side lanes. Some areas are very narrow and don't allow much room for snow removal. The creek alongside some areas is plugged with debris which may cause road to flood in low areas. Consider dredging and deepening water channel.

2. 3 miles up at Pine Creek Church - needs intersection improvements

3. 4 miles up – guard rail appears to be collapsing from hillside erosion.

4. 5 miles up – from Ridge Road to Exxon station and beyond to church. Deer fences might prevent some accidents and plantings might cut some windblown snow from impacting the road. Same comment at around 9 and 10 miles up to old New Bethlehem Wesleyan school area.

5. Dayton Road intersection needs improvement.

6. 11 miles up - the truck stop needs more signage for truckers to let them know about Hogback hill and speed limits.

7. 14 miles up – There needs to be more notice for the lane reduction on the hill and placement of the reduction needs to be reviewed in connection with oncoming (southbound) traffic. Southbound there or previous area where lane reduces the reduction ends at the top of a hill on a curve.

8. Dollar General in Distant – Sight distance is horrible and a bad accident waiting to happen. A different access point should be considered or more warning signage or speed restrictions should be considered.

9. Distant – sidewalks should be considered to improve pedestrian access.

10. Sidewalks in South Bethlehem Borough are in terrible condition and deter pedestrian use.

11. Signage for trail access should be less restrictive and less costly so that more directional signs can be added for tourism attraction.

Within New Bethlehem Borough - Improve all cross walk signals in Borough and add stop for pedestrian signage.

12. Corner of Broad (28/66) and Wood (66).

a. Move the stop line and treadles for both through and left turn north to Wood back to allow trucks turning west on Broad Street from Wood St to make the turn with out having to worry about running into vehicles stopped to turn north on Wood St. from Broad St.

b. Remove two existing traffic light poles at NW and SE corners and install one double armed traffic light pole on southwest corner of Broad and Wood to handle all traffic so that damage to

current light poles and building is eliminated. NW corner traffic pole and it or the protective post have been hit numerous times by trucks and continue to be hit almost once a month. This has occurred more frequently since August 2018 when Penn Dot removed the old curbs and put in flat handicapped accessible curbs. The Borough has installed signage and delimitators in an attempt to keep trucks from cutting the corner too tightly. The pole has been replaced once since then in 2019 and has been hit at least twice again since replacement. We were informed that we can't replace the pole again because of new regulations and that the new pole will cost at least \$300,000. The existing NW pole foundation is near utility lines for the Bish Chiropractic/Laurel

Eye building on the corner which has also been hit by trucks.

July 2, 2007 – building support pole on NE corner was taken out. Building on west side is the Bish Chiropractic building and pole is at middle top of photo.

2018-2020 damage:





Jan 2020 damage after signage added.













**13. Broad Street in 100 block**. Consider putting in a turn lane from Liberty St. east to at most Maple Street so that traffic can turn into the beer distributor or gas station whether going east or west on Broad St. This might entail eliminating parking on south side of Broad St. from Liberty to Maple or maybe on the north side for part of the distance.

14. Broad/Rt. 28 from Wood (66) to eastern Borough limit. Make the speed limit 25 on both sides of the street for safety of pedestrians, customers of businesses and speed monitoring, as 25 mph is the speed limit on Broad from Wood west to Liberty Street.

**15. Lincoln and Broad Street.** Consider recommending that Lincoln be made one way Northbound at Post Office because of sight distance issues with car parking along north side of Broad.

### 16. 500 Block of Broad Street.

a. Work with Smuckers and Redbank Valley Trails Association to create a truck access to plant parking area directly from SR 28 to limit need for trucks to use only current access via Broad and Wood intersection, Wood and Penn (SR 861) intersection, 1920s bridge over Leasure Run on Penn Street and Penn Street residential area. Keep in mind that the corridor is railbanked so that nothing can be done to corridor to prevent rail from returning.



Corner of Wood/66 and Penn St. 861

b. Improve drainage under SR28 at Vine Street bridge for Leasure Run.

## 17. SR 28 east of Borough Line through Redbank Township to Fishbasket curve

a. Improve drainage facilities under 28.

b. Mitigate flood and ice jam damage by dredging creek to deepen channel and perhaps armoring the channel. This might prevent closure of SR 28 in high water and ice jam situations.

c. Invasive species remediation – Bank is lined with Japanese Knotweed which causes erosion and prevents other native plants from growing.

### 18. Fishbasket Curve

a. Work with Redbank Valley Trails Association and PUC to improve crossing. Keep in mind that the corridor is railbanked so that nothing can be done to corridor to prevent rail from returning such as major changes to grade without PUC and Buffalo & Pittsburgh Rail Road approval. Suggested improvements include a flashing light triggered by trail users from either direction toward crossing. Move the crossing slightly to the west to shorten the crossing distance instead of being on a diagonal. Add additional signage in both directions at further distance than existing signage to indicate trail crossing ahead. Consider crosswalk markings.

19. Hawthorn - allow directional signage to trail before and/or at Walker Flat Road.

20. Shannondale Flats – Speed and intersections are a concern.

Rt 28 Corridor Improvements – Suggestions by Sandy Mateer 2-26-20 Page 4

21. **Summerville – Carrier Street** - allow directional signage to trail before and at Carrier Street in both directions.

22. **Summerville to Moore Road** – There appears to be a lot of acid mine drainage coming from hillside that drains along the road and then works it way into the Red Bank Creek.

23. **Moore Road** - allow directional signage to trail before and/or at Moore Road in Corsica in both directions.

24. South Main Street, Brookville – Consider adding a turn lane on sharp town to S. Main Street leading to hospital.

25. **Main Street/322 intersection** - Allow directional signage to trail before and at intersection from both directions.

ROUTE28 CORRIDOR STUDY

Stakeholder Outreach INTERVIEW INVITATION SIGN IN SHEET

KITTANNING February 26, 2020

NAME	ORGANIZATION	EMAIL	PHONE
NUMED S, KAMMERDIEVER	L BEECS TWP .		724 - 545 - 7142
Allie PANCA	HMNIStrena Co Planning	arpence a corrisorance.	a. US 724-5418-3734
Carmen Juhnsen	Phone Co. Perelopment	Let chusaule to armstrange have	124.548.3121
Tavis TongravicII	PENNUO DATAIRE IC	DTOMASHICK @ PA HO	724 357 2845
Bu Class	Freqs Two March	WCST 87 Ochitaca	724954679
Lynde Pozzato	AKSTming chambe	L lynde cakstans c	01, 724 224-3400
MILE COONT Len	ARM. G. ECONNING DET	Moevers but E currants	ON 194241 12 40. NO.
Steven Dalla	Kittemaine Then VFI	) stelibation years.	724 - 664 -3995
Keith Buseic	Bagligars IN	K cithe bearigned	1734-55-3562
Audy Breddigan	Bradiband Inc	and to be radiance	758-525-756
Jase Orter	Acmy	forser. Orter@AHN. eg	à 412 491-9256
Justin Nolder	Arm. Co. Econ. Dev.	ir nolde (C) co. armstrong. De	w 734-548-1500
Ruan Gordon, Ashley Tr	acu kar Shedlock, W	any Ebarhart Project Tea	(m)



Meeting:	Stakeholder Interview Meeting - Kittanning	Date:	February 26, 2020
Location:	The Belmont Complex	Time:	4:00pm to 5:30pm
Attendees:	See attached sign-in sheet		
Purpose:	The purpose of the meeting was to interview a variety of stakeholders for	or the Ro	ute 28 Corridor Study Project.

*Discussion:* The following outlines the highlights of the discussion:

- The concerns expressed by the EMS/Ambulance representative were that the hills and geometry of SR 28 present a challenge in getting patients to the most appropriate local hospital. The Armstrong Hospital has advanced cardiac technologies that other local hospitals do not, and many times flights are needed to get patients to the Armstrong Hospital.
- Truck traffic presents an operational and safety concern due to speed differentials between cars and trucks. Many times, vehicles pass slow moving trucks in a no passing zone. Suggested a need for additional truck climbing lanes near Orchardville.
- Spacious Corners / Sloan Hill Road has poor sight distance due to the hill and curve.
- At the top of Hogback Hill at the truck weigh station, sight distance is poor, and trucks are slowing down, stopping, pulling over in this location. Trucks also sometimes don't stop as directed and roll through the brake check area and pull out in front of cars.
- Goheenville speeding issues are noted. An improved project in this area is currently being designed by PennDOT.
- The concerns expressed by the local trucking company, who delivers heating oil and other seasonal products, were that
  houses are too close to the road in many locations. Other areas of concern were brake check stops, the Baum Pump
  Station, and the "tickle turn" by Horse Trader just north of SR 85 that has a sharp turn that is difficult for trucks to
  maneuver at high speeds. There was a recent project that fixed some geometric issues but the project limits did not
  address that turn. They would like to see the improvements continued to address the sharp turn.
- The crosswalk at Fish Basket needs to be straight across the road. (This is the New Bethlehem crossing of the Redbank Valley Trail).
- Speeding is a concern at the 15 mph curve in South Bethlehem. Trucks frequently overtrack and sometimes roll over.
- The discussion regarding the traffic models incorporating drawing additional freight traffic from other major adjacent highways such as I-79, I-80, Route 8, and US 119 was discussed. It was determined that the tools to address this quantitatively are limited, so this would be considered qualitatively..
- There are sight distance and access concerns coming out of Oscar Road.
- There is significant congestion in the afternoon in New Bethlehem. Better coordination of the two signals in New Bethlehem was suggested.
- There is a crash history in Distant due to the narrow roadway/shoulders and the stream located so close to the road, north of Wadding Road to Redding Road.
- There is an active slide at the Pine Creek Bridge.
- Other general concerns included narrow shoulders, lack of truck lanes, trout and deer season congestion, Sloan Hill Road blind curve with buses pulling out, sight distance at Lower Hays to Upper Hays Run, and SR 28 near SR 1035 Oscar Rd needs truck lanes and wider shoulders.
- The following tourism draws were discussed:
  - o Port Armstrong Folk Fest
  - o Armstrong Festival
  - o Arts on Allegheny
  - o ATV events
  - o Cooks Forest

- o Autumn Leaf Festival
- o Peanut Butter Festival
- o Proposed ATV Facilities large scale improvements, Poker Runs, Scrubgrass Run, a big draw

The meeting was adjourned at approximately 5:15 p.m. by thanking the stakeholders for their feedback and time. A list of action items was developed to summarize the stakeholders input and potential improvement areas within the study. The study team will further evaluate these stakeholder concern locations with our existing conditions, crash history, geometric conditions, public input, and operational conditions. The stakeholder action items to be considered are listed below:

### Action Item List:

- Consider EMS provider concerns with Route 28 geometry and access to Armstrong Hospital.
- Consider local freight provider concerns with Route 28.
- Consider a need for additional truck climbing lanes near Orchardville.
- Consider better coordination of the two signals through New Bethlehem.
- Further investigate specific concerns noted by stakeholders at the following locations:
  - o Sloan Hill Road sight distance.
  - o Hogback Hill in general at the truck weigh station.
  - o Route 28 at the Redbank Trail concerns for pedestrians crossing.
  - o 15mph curve south of New Bethlehem where trucks frequently overtrack and sometimes roll over.
  - o Oscar Road sight distance and truck access concerns.
  - o Lower Hayes Run turning vehicle provisions.
  - Discuss with School District separately their concerns along the corridor.
  - o Coordinate with Armstrong County on planned and potential future developments.

Prepared by: McCORMICK TAYLOR, INC. Copies:

Attendees

MT Project File

<u>Attachments:</u> Meeting Sign-in Sheet Photos of Meeting

# APPENDIX E Survey Questions

## Route 28 Corridor Study Wiki-map Survey Questions 01.17.20

### ADD PROBLEM OR OPPORTUNITY

- Select a point type and then place on map.
   [Each point type receives a different list of concerns Q4-7]
  - Traveling via a car
  - Traveling via bike
  - Traveling via walking
  - Traveling via truck/freight vehicle
- 2. I use this area for: (Select all that apply)
  - Local commuting (Less than 10 miles each way)
  - Regional commuting (More than 10 miles each way)
  - Business travel (Deliveries, moving freight, etc.)
  - Accessing government services
  - Accessing Redbank Valley Trail
  - Accessing local schools
  - Accessing stores, services, goods, healthcare
  - Accessing recreational opportunities
- 3. How frequently do you use this facility?
  - Daily
  - Weekly
  - Monthly
- 4. What about this location causes you concerns? [CARS]
  - Pedestrian Safety
  - Cyclist Safety
  - Vehicle speeds
  - Slow moving vehicles
  - Congestion
  - Stopping or turning vehicles
  - Lack of connectivity
  - Interstate access
  - Roadway safety
  - Drainage
  - Parking
  - Signal timing
  - Roadway or bridge maintenance
  - Sight Distance
- 5. What about this location causes you concerns? [BIKES]
  - No shoulder

## Route 28 Corridor Study Wiki-map Survey Questions 01.17.20

- Shoulder is too narrow
- Poor shoulder condition
- Debris
- Lack of bike lane
- Lack of protected bike lane
- Travel lanes are too narrow
- Drainage
- Vehicle speeds
- Roadway safety
- Proximity to large trucks/vehicles
- Connectivity to regional trail system
- Aesthetics
- 6. What about this location causes you concerns? [FREIGHT]
  - Pedestrian Safety
  - Cyclist Safety
  - Vehicle speeds
  - Roadway incline/grade
  - No climbing lane on steep grade
  - Travel lanes are too narrow
  - Intersection too narrow to safely turn
  - General congestion
  - Stopping or turning vehicles
  - Lack of connectivity
  - Shoulder width/condition
- 7. What about this location causes you concerns? [WALKING]
  - Sidewalk ends/no sidewalk
  - Sidewalk condition
  - Pedestrian safety/visibility
  - Roadway safety
  - No shoulder
  - Shoulder condition
  - Drainage
  - Vehicle speeds
  - Proximity to large trucks/vehicles
  - Crosswalk
  - Sidewalk not Americans with Disabilities Act (ADA) compliant
  - Connectivity
  - Aesthetics
- 8. Please explain your concern. (open-ended)

## Route 28 Corridor Study Wiki-map Survey Questions 01.17.20

- 9. Do you have a photo of this area of concern for us to consider? Please upload it here.
- 10. Is there any other information you would like us to know about the Route 28 corridor? (openended)

Click submit to return to the map to add any additional problems or concerns.

# APPENDIX F Field Notes

# **REDBANK VALLEY TRAIL**

The trail is well-supported, has free parking, and even had a few folks using it during the field work day which was approximately a 50-degree day in January. It was awarded "Trail of the Year 2014". The field work included 3 locations along the trail:

- South Bethlehem trailhead bridge
- New Bethlehem
- Brookeville Depot St Spur

The trail is advertised in Brookeville and New Bethlehem. There is free parking in the north at the Depot Street Spur near Brookville, free parking in downtown New Bethlehem, and a small gravel area in South Bethlehem where a bridge takes you to the trail just west of the 15mph curve sign (see image). The parking area is limited (see image).



View from the bridge over Redbank Creek



Parking near the trail head is limited

The houses along the trail in New Bethlehem don't appear to have any other access (roadway or sidewalk). There is significant public art and continuous access to the trail throughout New Bethlehem.



Public art invites trail users to stop and explore



Bicycles parked along the trail in New Bethlehem



Some residences along the trail have no offstreet parking



Some residences only access is via the trail



The New Bethlehem trailhead offers bike racks, free parking, a portapotty, and wayfinding signage



View from Above and Below Trail Overpass in New Bethlehem, which also leads to JM Smucker's Facility



Redbank Valley Trail Sign from Brookville

## SIGNAGE

Many signs on the corridor have been struck – particularly at SR 0536, SR 85, and US 322. Trucks were observed overtracking due to the tight geometry of the roadway and intersection approaches. A few areas of damaged guiderail were noted. A relatively flat, straight segment of roadway exists between New Bethlehem and Brookville where most of the passing zones are.



Sign damage at SR 536 Mayport Road



Sign damage at SR 85 and at US 322

## **DOWNTOWN NEW BETHLEHEM**

In downtown New Bethlehem, Route 28 is Broad Street. There are two signals in close proximity, at Lafayette Street and at Wood Street. They appear to operate well. No significant queueing was observed. Both signals had pedestrian signal heads. At Wood Street, some pedestrian heads are outdated and burnt out. Trucks were observed overtracking turning EBL to Route 66 at Wood Street (see image). There are delineators to keep them from coming up on the curb, but not bollards. I had to jump back from the corner as this truck nearly overtracked onto the sidewalk. Lafayette Street crossing is short and easier to cross.



New Bethlehem approach to Wood Street Signal



Truck Overtracking at Wood Street in New Bethlehem



Sidewalks and DWS Present, Pedestrian Head Burnt Out



Traffic Signal at Lafayette Street

## **TRUCKS AND FREIGHT**

The Route 28 corridor is home to industry and trucking facilities. Some noticeable include McCauley trucking and warehousing, Glen Gary. There is a noticeable amount of timber hauling in the area. JM Smucker's is in downtown New Bethlehem. At the northern end of the corridor, the Brookville Travel Center provides facilities for trucks using the I-80 and SR 28/SR 36 corridors.

On the field view, steep grades were found in excess of 9%. There is an area for heavy trucks to pull off and stop before beginning their descent. Truck speed limits on the downgrade are posted at 35 mph. The smell of brakes and sound of engine braking was ubiquitous through the mountainous and rolling parts of the corridor. A few hills were noted as good candidates for truck climbing lanes, including the hill near Baum Pump Station/Orchardville, and Hogback Hill.



9% Grade Next 2 MI



Pull off for trucks going NB on SR 28 before the 9% grade



Northbound downhill following



Northbound climbing lane begins



Trucks at the Brookville Travel Center



Glen-Gary is located at Carrier Street



Timber hauling is a noticeable industry along the corridor



Smucker's Facility in New Bethlehem

## SAFETY COUNTERMEASURES

Generally the corridor has centerline rumblestrips, but shoulder rumblestrips were not observed. In most places, the rumblestrips have worn and are not effective.

Curve warning signs often have no advisory speeds and no chevrons.

## RETROREFLECTIVITY

The corridor was driven in the evening and the paint and signs varied in retroreflectivity, poor. Most night time reflection comes from bridge and curve delineators. A southbound corridor video is available in nighttime conditions.



Traveling SB on Route 28 north of New Bethlehem



Traveling SB at the New Bethlehem / Hawthorn sign



Traveling SB south of New Bethlehem



A typical night-time scene traveling SB on Route 28

## **S**PEEDS

Significant speed differentials were observed along the corridor. Some passenger vehicles were observed speeding, traveling between 65 and 70 mph on 55 mph segments. Improper passing of slow-moving vehicles in non-passing zones was also observed.

Other vehicles, both cars and trucks, were observed driving 5-10 mph below the speed limit. Speed limits change frequently throughout the corridor, from 55 mph on most sections, to 35 mph through most villages, and 25 mph through New Bethlehem.



15mph Curve Advisory Sign



Speed limit is 35 mph in South Bethlehem



Speed limit drops to 25mph through New Bethlehem


Speed limit rises again to 55mph

#### SIGHT DISTANCE

Sight distance turning onto Route 28 is limited for many intersections due to horizontal and vertical curvature. Other sight distance obstructions noted include hillsides, guide rail and bridge barriers, trees and brush, signs, and houses. There are many minor intersections along the approximately 40-mile corridor with sight distance concerns; however, the major intersections that were identified observed during this round of field observations were:

- Sloan Hill Road
- SR 1035 (Oscar Road)
- SR 1004 (Kohlersburg/Madison Rd)
- SR 1025 (Putneyville Road)
- SR 0536 (Mayport Road)
- South Main Street near Brookville

# SLOAN HILL ROAD



Sloan Hill Road looking north on Route 28



Sight distance limited from crest and guide rail looking north at the stop on SR 1035



Sight distance looking south at the stop sign on SR 1035



Looking northbound on Madison Road



Looking south from the stop

# SR 1004 (KOHLERSBURG/MADISON RD)



Looking southbound on Route 28



Looking north from the stop



Sight distance looking north from stop at Mayport Rd



Sight distance looking south from stop at Mayport Rd



Main Street Sight distance looking south



Main Street Sight distance looking north

### POVERTY HILL ROAD

The intersection of Poverty Hill Road, McGregor Road and SR 28 is a skewed intersection north of the end of the freeway. At this intersection, geometric and roadway conditions were observed. In general, the intersection and surrounding area to the south is relatively flat with some residential buildings, commercial buildings, and billboards. To the north, SR 28 begins a steep climb while Poverty Hill Road has a short, steep grade.

Looking at the roadway conditions, the guide rail in the area was in good condition. The edge of the shoulder is beginning to deteriorate and there is a pothole located on the southwest corner along McGregor Road (see image). Several traffic and roadway signs were located at the intersection including stop signs and weight limit signs on the minor legs.



Roadside deterioration at McGregor Road

Heavy truck traffic was observed and there is evidence of overtracking on the corner of SR 28 and McGregor Road. The sight distance to and from McGregor Road appears to be sufficient. The sight distance from Poverty Hill Road was insufficient due to the hills along the road and several residential buildings to the south (see image). Being so close to the end of the freeway, there were no speed limit signs observed northbound on SR 28 but there was a 45 mph speed limit sign on the downhill grade going southbound on SR 28.



Sight line at stop sign from Poverty Hill Road facing south on SR 28

# SR 28 AND JARALY LANE GUIDE RAIL

While traveling north from Poverty Hill Road to Jaraly Lane, roadway conditions were observed. The guide rail along the road was in good condition but some locations had evidence of minor erosion under the guide rail. The shoulders varied in width down to about two feet.

Just south of Jaraly Lane, there is heavy erosion under the guide rail. Along the northbound lanes, the shoulder is beginning to crumble and larger pieces of pavement have broken off from the roadway. There is heavy erosion under the guide rail and around the posts. There is a path under the guide rail of erosion from water. Some of the guide rail is beginning to lean into the slope (see image).



*Erosion and deteriorating shoulder on northbound lanes of SR 28 (looking south)* 

Along the southbound lanes, the guide rail is in better condition. While some of the posts appear to be leaning into the slope, a section about fifty feet long was reinforced with bituminous material. Minor erosion is evident along the shoulder. The impact attenuator appears to have been replaced recently.

#### SR 1028 AND SR 28

While travelling north from Jaraly Lane to SR 1028, roadway conditions were observed. Minor erosion along the shoulders were evident along with minor deterioration of the edge of pavement.

At SR 1028, insufficient sight distance was observed. When turning from SR 1028, there

is a stop sign for SR 1028 only. Facing south, SR 28 curves away from SR 1028 and has a steep grade of 8.7% (field measured). The combination of the horizontal curve, downhill grade, and trees limits the sight distance (see image). Facing north, the roadway is relatively flat but there is a small hill and a large tree, which are located at the edge of the pavement. Behind the tree, there is a residential building, which limits sight distance as a vehicle approaches the intersection (see image).



Large tree and Residence at the stop sign on SR1035, facing north on SR 28



Sight line facing south on SR 28

The roadway along SR 28 is in good condition but the pavement along SR 1028 is beginning to deteriorate, especially along the edge of shoulder.

# NEAR THE ADDRESS OF 742 SR 28 AND 66

Traveling a short distance north from SR 1028, heavy erosion and a large skid mark were observed on SR 28. The erosion along the guide rail on the northbound side is about 125 feet in length and several inches deep. The erosion travels under the guide rail and washes out on the hillside to a creek at the bottom of the hill (see image). The skid mark is along the northbound lanes and is about 75 feet long. It is a single tire width suggesting a car or pickup caused it.



Heavy erosion on Section 742 of Route 28 from edge of pavement down to stream

#### **CRISSMAN LANE AND SR 28**

Traveling north from 742 SR 28, guide rail damage and poor sight distance was observed. The guide rail had evidence of damage from a vehicle brushing the guide rail and from large branches falling on top of the guide rail. The sight distance was limited due to horizontal curves and skewed intersections with local roads. The large cut slopes along the roadway looked to be in good condition with minimal erosion. The area was mostly farm or residential with some community centers such as a church and a school.

Just north of Crissman Lane, there is a large section of damaged guide rail. The slope was reinforced with bituminous material and large rocks. The guide rail posts are beginning to slide down the slopes and are out of line. Washouts and erosion are present under the guiderail and along the shoulder (see image).



Damaged guide rail and slope repair

## SR 1035 AND SR 28

Traveling north from Crissman Lane, poor sight distance at intersections with local roads and driveways and reinforced rock slopes behind the guide rail were observed. The shoulders along SR 28 vary in width and at times are about two feet wide.

At the intersection of SR 1035, SR 28 is curving away from SR 1035 with a cresting vertical curve just north of the intersection. Looking right from SR 1035 approach, there is poor sight distance due to guide rail along the northbound lanes of SR 28, which is higher than the driver's eyes on SR 1035. There is also a cresting vertical curve making it difficult to see any vehicles traveling south on SR 28 (see image). Looking left from SR 1035 approach, there are several trees in the sight line, which limits the sight distance. Along SR 1035, there is broken pavement and recently repaired patches on the shoulders. The guiderail on the northbound side of SR 28, along the curve radius from SR 1035, appears to have damage on the top by a vehicle that did not turn wide enough form SR 1035 to travel north.



Facing north on SR 28 from SR 1035

# SR 1004 AND SR 28

Travelling north from SR 1035, the roadway is in good condition. There are some sharp curves and steep grades with truck climbing lanes, but the guide rail is in good condition and there is only minor erosion along the guide rail.

The intersection of SR 1004 and SR 28 is a five-way intersection with a channelized right turn lane from southbound SR 28. The three minor roads converge to one intersection with the channelized right turn lane and a bidirectional lane to SR 28 (see image). The sight distance to and from SR 28 is good from the bidirectional lane and the channelized lane. Approaching the five-way intersection with SR 1004, there is a sharp curve along one of the three minor roads. There is a short distance from this intersection and the travel lanes on SR 28. Approaching the intersection from the south along SR 28, there is a steep grade, which flattens out at the intersection and enters a residential area.



Approaching intersection from SR 1004, facing north. Vehicle is located on bidirectional lane.

# 15 MPH CURVE IN SOUTH BETHLEHEM

Leaving SR 1004 and traveling north along SR 28, there is a section of damaged guide rail from falling branches. The speed limit also changed several times from 45 mph to 55 mph to 35 mph as SR 28 approaches New Bethlehem.

Entering South Bethlehem, there is a sharp curve with a 15 mph advisory speed at the T intersection of Broad Street (see image). At the intersection, there is damaged guide rail along Broad Street, which is a minor road leading to residences and a Redbank Valley Trailhead. At the two corners of the intersection, there is a gas station with several pumps. Large trucks from single unit trucks to WB-67s were observed to overtrack when heading both north and south along SR 28. When travelling south, trucks generally tracked into the northbound lanes. When traveling north, trucks either oversteered into the southbound lanes or ran over the curb.



Facing east on SR 28 from gas station

# ADA RAMPS IN NEW BETHLEHAM

Along SR 28 (Broad Street) though New Bethleham, the ADA ramps were check to verify that they meet the standards for grade and width. All ramps at the following cross streets were checked:

- Liberty Street
- Maple Street
- LaFayette Street
- Wood Street
- Vine Street

The ADA ramps for two crossing were also checked near the following businesses:

- Klingensmith's Drug Store
- United States Post Office

All ramps met standards and were in good condition.



ADA Ramp crossing the entrance from Klingensmith's Drug Store

## REDBANK VALLEY TRAIL CROSSING

After travelling through New Bethlehem and its commercial district, the Redbank Valley Trail crosses SR 28. The trail crossing is skewed to SR 28, which is an S-bend on either side of the crossing. The sight distance is minimal from both the roadway and the trail. Approaching the trail crossing along SR 28, there are several signs warning of the crossing and an advisory speed reduction sign for 25 mph through the curves. To the north of the crossing, there is an uphill grade (see image).. South of the crossing, the roadway is relatively flat but is lower in elevation than the trail (see image). Brush and trees separate the trail and roadway along the slopes. Visibility is poor from the trail and from the roadway. To cross SR 28, a trail user must travel about 30 feet. There are no warning lights for the trail crossing. The sight distance for pedestrians and vehicles approaching the crossing is only a few hundred feet. Vehicles were difficult to see from the detectable warning surface on the trail due to the slopes along the roadway. Vehicles were observed to be speeding through the S-bend even though it is a 25 mph advisory speed curve.



Redbank Valley Trail Crossing, facing south on SR 28



Redbank Valley Trail Crossing, facing north on SR 28



Approaching Redbank Valley Trail Crossing, southbound on SR 28 (Image from Google Street View)

#### **ADA RAMPS IN HAWTHRON**

In Hawthron, there are three ADA ramps along SR 28 at the cross roads of Center Street and Arch Street. They were measured for grade and width and found to be within standards. At Arch Street, there is only one ADA ramp. There is no ADA at the corner where Alcorn Funeral Home is located.



ADA Ramp across from Alcorn Funeral Home at Arch Street

SR 0536, TR 0506, AND SR 28

Traveling north from the trail crossing to SR 0536, guide rail, is in good condition or appears to have recently been replaced. The speed limit increases from 45 mph to 55 mph north of Hawthorn.

At the intersection of SR 0536, there is deteriorating pavement in several locations. Most of this pavement is on SR 0536 and on the curve returns of the intersection. The intersection with SR 0536 is skewed and northbound traffic from SR 28 has to make a sharp turn to travel east on SR 0536. There is evidence of overtracking at this corner. In addition, at this corner, the slope is beginning to deteriorate. This could be due to natural erosion but there were tracks on the grass, which suggest a trailer was brought up on the hill and taken off the hill at the corner.



From SR 0536, facing south on SR 28

Across from SR 0536 is TR 0506, a gravel road leading to several residential properties. Near the intersection, there is a weight limit sign for the bridge, which is farther down the road.

## NEAR THE ADDRESS OF 5934 SR 28

Just north of the intersection of SR 0536 and SR 28, there is an impact attenuator on the southbound side, which was recently damaged. The impact attenuator was crushed and debris remains from the accident. About 25 feet of guide rail was curled over itself and snapped from the wooden posts due to the impact attenuator (see image). There is a 55 mph speed limit along this stretch of road. Sight distance for vehicles traveling southbound is good due to the open fields and relatively flat terrain.



Used impact attenuator on southbound side of SR 28

## TOADTOWN ROAD, ANDERSON ROAD, CREEK STREET, AND SR 28

Traveling from 5934 SR 28 to Toadtown Road, the roadway was in good condition. The guide rail was in fair condition with some erosion evident along the shoulder. There were several locations where the slope was reinforced with gabions along the southbound lanes.

At the intersection of Toadtown Road, two other minor roads that create a 5-way intersection. Anderson Road and Creek Street intersect SR 28 and are parallel with each other. Toadtown Road and Creek Street lead to residential areas immediately while Anderson Road turns away from Creek Street to a residential area along the Redbank Creek.

The speed limit along the minor roads are 15 to 25 mph while SR 28 has a speed limit of 55 mph. The pavement on the minor roads are deteriorating and have potholes. The guide rail along SR 28 is in good condition but the radius to Toadtown road is in poor condition (see image).

Sight distance at this location is fair. The terrain is mostly flat to the north, east, and west. To the south, there is downhill approaching the intersection. While the stop signs are a short distance from the intersection on the minor roads, vehicles were observed to move closer to SR 28 to see better around the brush and utility poles if traveling north or crossing SR 28 (see image). To travel south or cross the road, there are no obstructions in the sight line.



Facing east at SR 28 on Toadtown Road



Facing south on Toadtown Road

#### **SR 322 AND SR 28**

Traveling north from Summerville, the roadway varies in condition. Most of the roadway is in good condition but there is evidence of a small slide and cliff overhangs on the southbound side of SR 28. Several smaller intersections are skewed along SR 28. These could potentially have insufficient sight distance. The speed limit changes several times from 55 mph to 45 mph to 35 mph as vehicles approach Brookville. Several S-bends have a 40 mph advisory speed.

The intersection of SR 322 and SR 28 is a signalized intersection with channelized right turn lanes on all four corners. The pavement at the intersection is in good condition as is the concrete used for the islands in the intersection. The last 135 feet of guide rail on

the southeast corner is heavily damaged on the radius (see image). The 100 feet of the guide rail appears to have been pulled from the posts and dragged into the parking lot just past the corner. There is 25 feet of guide rail that is damaged, but still connected to the posts.

Along the guide rail radius, there is heavy erosion which has damaged the edge of pavement and leads down the slope behind the guide rail (see image).



Damaged guide rail on SR 322/SR 28



Heavy erosion under guide rail on northbound channelized right turn

# APPENDIX G Intersection Level of Service 2019 AM/PM and 2045 AM/PM

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
		SR 85	FB	EBL	67.3	E	51 7	D		
		517 00	LD	EBT/R	40.9	D	01.7	D		
		SR 85	WB	WBL	47.8	D	41 4	D		
	SR 28 at SR 85	517 00	WB	WBT/R	26.3	С		U		
1	(Signalized)			NBL	319.2	F			38.3	D
		SR 28	NB	NBT	18.8	В	29.7	С		
				SBI	129.6	F				
		SR 28	SB	SBT/R	28.7	С	37.5	D		
		SR 1004	EB	EBL/R	12.6	В	12.6	В		
2	SR 28 at SR 1004	SR 28	NB	NBL/T	9.3(L)	А	0.5	А	3	А
	IVIAUISUIT RU	SR 28	SB	SBT/R	0	А	0	А		
		SR 1004	EB	EBL/T/R	6.8	А	6.8	А		
	Kohlersburg Rd at SR 1004	Slip Ramp	WB	WBL/T/R	7.4	А	7.4	А		
21	Madison Rd	SR 1004	NB	NBL/T/R	7.9	А	7.9	А	7.1	A
		Kburg Rd	SB	SBL/T/R	7.3	А	7.3	А		
		Kburg Rd	EB	EBL/R	13.4	В	13.4	В		
3	SR 28 at Kohlersburg Rd	SR 28	NB	NBL/T	8.7(L)	А	0	А	0.2	А
	je na se	SR 28	SB	SBT/R	0	А	0	А	0.2	
		SR 28	EB	EBL/T/R	8.9(L)	А	0.1	А		
		SR 28 at SR 839 SR 28 W		WBL	9.4	A	٨			
4 SR 28 at SR 839	SR 28 at SR 839		WB	WBT/R	0	А	1.2	A	2.1	A
		SR 839	NB	NBL/T/R	11	В	11	В		
	Short St	SB	SBL/T/R	24.9	С	24.9	С			

Exhibit 1 - Intersection Level of Service (2019 AM)

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
		SR 28	EB	EBL	9	А	8.1	А		
				EBT/R	7.7	А				
5	(Signalized)	SR 28	WB	WBL/T/R	19.1	В	19.1	В	14.6	В
		Wood St	NB	NBL/T/R	13.5	В	13.5	В		
		SR 66	SB	SBL/T/R	19.1	В	19.1	В		
		SR 28	EB	EBL/T/R	9.5 (L)	А	0.3	А		
7	SD 28 at Contor St	SR 28	WB	WBL/T/R	9.6(L)	А	0.2	А	1 0	٨
1		Walker Flat Rd	NB	NBL/T/R	13.3	В	13.3	В	1.2	~
		Center St	SB	SBL/T/R	12.1	В	12.1	В		
		SR 28	EB	EBL/T/R	9(L)	А	0.2	А		
0	SR 28 at Mayport Rd	SR 28	WB	WBL/T/R	9.3(L)	А	0.6	А	2.4	
8	SR 536	Mayport Rd	NB	NBL/T/R	11.1	В	11.1	В	2.6	A
		Driveway	SB	SBL/T/R	12	В	12	В		
		SR 28	EB	EBL/T/R	8.8(L)	А	0.3	А		
		SR 28	WB	WBL/T/R	9.1(L)	А	1.3	А		
9	SR 28 at Carrier St	Carrier St	NB	NBL/T/R	9.8	А	9.8	А	2.3	A
		Carrier St	SB	SBL/T/R	10.5	В	10.5	В		
		Driveway	EB	EBL/T/R	10.8	В	10.8	В		
10	CD 20 at C Main Ct	S. Main St	WB	WBL/T/R	10	В	10	В	2.2	٨
10	SR 28 at 5 Main St	SR 28	NB	NBL/T/R	8.2(L)	А	0	А	2.3	A
		SR 28	SB	SBL/T/R	8.7(L)	А	2.7	А		
		SR 322	EB	EBL/T/R	16.6	В	16.6	В		
		SR 322	WB	WBL/T/R	14.9	В	14.9	В		
11	SR 28 at SR 322	SR 28	NB	NBL	10.7	В	13.6	В	12.9	В
	(Signalized)			NBT/R	14	В		В		
		SR 36	SB	SBL	9.4	A	9.7	А		
				SRI	10.2	В				

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
				SBR	0	А				
			FD	EBL/T	31.1	С	22	C		
		1-00 Rainps	ED	EBR	34.5	С	33	C		
12	SR 36 at I-80 EB Ramps (Signalized)	SR 36	NB	NBT/R	7	А	6.8	А	11.1	В
	(Orghanzou)	SR 36	SB	SBL	4	А	71	Δ		
		517 50	50	SBT	8.4	А	7.1	Λ		
		L 80 Pamps	WR	WBL/T	30.2	С	30.0	C		
		1-00 Kamps	VVD	WBR	34.4	С	JZ.Z	C		
13	SR 36 at I-80 WB Ramps (Signalized)	SR 36	NB	NBL	3.7	А	0.9	Δ	10.5	В
	( ) <i>/</i>	517 50	ND	NBT	0.1	А	0.7	Λ		
		SR 36	SB	SBT/R	7.6	А	7.5	А		
		SR 28	EB	EBL/T	9(L)	А	0.1	А		
14	SR 28 at Waterford Pike	SR 28	WB	WBT/R	0	А	0	А	0.1	А
		Waterford Pike	SB	SBL/R	9.8	А	9.8	А		
		I-80 Ramps	EB	EBL/T/R	10.1	В	10.1	В		
15	SR 28 at I-80 EB Ramps	SR 28	NB	NBT/R	0	А	0	А	3.6	А
		SR 28	SB	SBL/T	8.3(L)	А	0.2	А		
		I-80 Ramps	WB	WBL/T/R	9.8	А	9.8	А		
16	SR 28 at I-80 WB Ramps	SR 28	NB	NBL/T	8.3(L)	А	1.7	А	0.2	А
		SR 28	SB	SBT/R	0	А	0	А		
		SR 28	EB	EBT/R	0	А	0	А		
81	SR 28 at Dairy Rd	SR 28	WB	WBL/T	9.2(L)	А	0.1	А		А
		Dairy Rd	NB	NBL/R	10.6	В	10.6	В		

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS	
		SR 85	FR	EBL	51.7	D	47 7	П			
		517 05	LD	EBT/R	44.3	D	77.7	U			
		SR 85	WR	WBL	50.5	D	45	D	34.9		
		51(05	WD	WBT/R	29.2	С	-10	D			
1	SR 28 at SR 85 (Signalized)			NBL	108.3	F				С	
	(Signalized)	SR 28	NB	NBT	24.1	С	26.8	С			
				NBR	0	А					
			0.5	SBL	117.2	F	00.0	0			
		SR 28	SB	SBT/R	23.3	С	29.2	С			
		SR 1004	EB	EBL/R	13.3	В	13.3	В			
2	SR 28 at SR 1004	SR 28	NB	NBL/T	9.2(L)	А	0.7	А	2	А	
	Madison Ru	SR 28	SB	SBT/R	0	A 0 A					
		SR 1004	EB	EBL/T/R	7.3	А	7.3	А			
	Kohlersburg Rd at SR 1004	Slip Ramp	WB	WBL/T/R	7.6	А	7.6	А			
21	Madison Rd	SR 1004	NB	NBL/T/R	7.8	А	7.8	А	7.5	A	
		Kburg Rd	SB	SBL/T/R	7.3	А	7.3	А			
		Kburg Rd	EB	EBL/R	14.6	В	14.6	В			
3	SR 28 at Kohlersburg Rd	SR 28	NB	NBL/T	8.9(L)	А	0	А	0.2	А	
		SR 28	SB	SBT/R	0	А	0	А	4 U.2 A		
		SR 28	EB	EBL/T/R	9.1(L)	А	0	А			
		SR 28 at SR 839 SR 28 WB Plan Max Plan	W/R	WBL	9.5	А	10	٨			
4	SR 28 at SR 839		A	1.8	А						
		SR 839	NB	NBL/T/R	10.6	В	10.6	В	1.8	~	
			Short St	SB	SBL/T/R	24.8	С	24.8	С		

#### Exhibit 2 - Intersection Level of Service (2019 PM)

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
		SR 28	EB	EBL EBT/R	9.4 8.3	A A	8.6	А		
5	SR 28 at SR 66	SR 28	WB	WBL/T/R	19.3	В	19.3	В	15.6	В
	(Siyiidiizeu)	Wood St	NB	NBL/T/R	13.5	В	13.5	В		
		SR 66	SB	SBL/T/R	19.7	В	19.7	В		
		SR 28	EB	EBL/T/R	9.7(L)	А	0.5	А		
7	SD 20 at Contor St	SR 28	WB	WBL/T/R	9.5(L)	А	0.4	А	1 /	٨
/	SK ZO di Ceriler Si	Walker Flat Rd	NB	NBL/T/R	15.3	С	15.3	С	1.4	A
		Center St	SB	SBL/T/R	12.5	В	12.5	В		
		SR 28	EB	EBL/T/R	9.2(L)	А	0.1	А		
0	SR 28 at Mayport Rd SR	SR 28	WB	WBL/T/R	9.4(L)	А	1.4	А	<b>)</b> )	٨
ð	536	Mayport Rd	NB	NBL/T/R	13.1	В	13.1	В	5.5	A
		Driveway	SB	SBL/T/R	14	В	14	В		
		SR 28	EB	EBL/T/R	9.3(L)	А	0.1	А		
_		SR 28	WB	WBL/T/R	9.1(L)	А	1.4	А	2.4	
9	SR 28 at Carrier St	Carrier St	NB	NBL/T/R	11.4	В	11.4	В		А
		Carrier St	SB	SBL/T/R	12.1	В	12.1	В		
		Driveway	EB	EBL/T/R	11.2	В	11.2	В		
		S. Main St	WB	WBL/T/R	12.4	В	12.4	В		
10	SR 28 at S Main St	SR 28	NB	NBL/T/R	8.6(L)	А	0.1	А	4	A
		SR 28	SB	SBL/T/R	8.6(L)	А	0.8	А		
		SR 322	EB	EBL/T/R	18.5	В	18.5	В	B B	
		SR 322	WB	WBL/T/R	16.4	В	16.4	В		
11		SR 28	NR	NBL	12.4	В	15 <i>I</i>	R		
	SR 28 at SR 322 (Signalized)	517 20		NBT/R	16	В	13.4	U	14.1	В
				SBL	9.3	A				
		SR 36	SB	SBT	11.1	В	10 A			
				SBR	0	A				

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
		LOO Domos	FD	EBL/T	29.5	С	22.0	C		
		1-80 Ramps	ED	EBR	36.8	D	33.9	C		
12	SR 36 at I-80 EB Ramps (Signalized)	SR 36	NB	NBT/R	8.7	А	8.5	А	13.2	В
	(orginalized)	SD 26	CD	SBL	5.1	А	0 1	٨		
		SK 30	30	SBT	9.4	А	0.2	A		
		1.90 Damas	\//D	WBL/T	174	F	07 1	Г		
		1-00 Rainps	VVD	WBR	32.7	С	97.1	Г		
13	SR 36 at I-80 WB Ramps (Signalized)	SD 24	ND	NBL	5.7	А	1 5	٨	29.7	С
	(Orginalized)	SK 30	IND	NBT	0.2	А	1.0	A		
		SR 36	SB	SBT/R	10.9	В	10.8	В		
		SR 28	EB	EBL/T	9.6(L)	А	0.2	А		
14	SR 28 at Waterford Pike	SR 28	WB	WBT/R	0	А	0	А	0.2	А
		Waterford Pike	SB	SBL/R	13.4	В	13.4	В		
		I-80 Ramps	EB	EBL/T/R	10.1	В	10.1	В		
15	SR 28 at I-80 EB Ramps	SR 28	NB	NBT/R	0	А	0	А	2.4	А
		SR 28	SB	SBL/T	8.7(L)	А	0.5	А		
		I-80 Ramps	WB	WBL/T/R	12.6	В	12.6	В		
16	SR 28 at I-80 WB Ramps	SR 28	NB	NBL/T	8.6(L)	А	3.1	А	3.3	А
		SR 28	SB	SBT/R	0	А	0	А	0.0	
		SR 28	EB	EBT/R	0	А	0	А		
81	SR 28 at Dairy Rd	SR 28	WB	WBL/T	9.2(L)	А	0	А	0.1	А
		Dairy Rd	NB	NBL/R	11.1	В	11.1	В	0.1	

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
			50	EBL	75.2	E	(0.0	-		
		SR 85	EB	EBT/R	49.7	D	60.0	E		
				WBL	60.2	E	50.0	5		
		SR 85	WB	WBT/R	28.6	С	50.8	D		
1	(Signalized)			NBL	158.7	F			43.3	D
		SR 28	NB	NBT	20.0	С	25.6	С		
				NBR	0.0	А				
		SD 20	CD	SBL	149.1	F	12 0	D		
		JK 20	30	SBT/R	33.0	С	43.0	U		
		SR 1004	EB	EBL/R	13.8	В	13.8	В		
2	SR 28 at SR 1004 Madison Rd	SR 28	NB	NBL/T	9.5(L)	А	0.5	А	3.2	А
	Madison Na	SR 28	SB	SBT/R	0.0	А	0.0	А	3.2	
		SR 1004	EB	EBL/T/R	6.9	А	6.9	А		
21	Kohlersburg Rd at SR 1004	Slip Ramp	WB	WBL/T/R	7.5	А	7.5	А	7.0	٨
21	Madison Rd	SR 1004	NB	NBL/T/R	7.9	А	7.9	А	1.2	A
		Kburg Rd	SB	SBL/T/R	7.4	А	7.4	А		
		Kburg Rd	EB	EBL/R	14.7	В	14.7	В		
3	SR 28 at Kohlersburg Rd	SR 28	NB	NBL/T	8.8(L)	А	0.0	А	0.2	А
		SR 28	SB	SBT/R	0.0	А	0.0	А	0.2	
		SR 28	EB	EBL/T/R	9.0(L)	А	0.1	А		
		SR 28 W	WB	WBL	9.6	A	1.2	А		
4	SR 28 at SR 839	2B 830	NR		0.0	A	11 7	R	2.2	A
		Short St	SR		31.5	D	31.5	D		

#### Exhibit 3 - Intersection Level of Service (2045 AM)

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
		SR 28	EB	EBL EBT/R	10.4 9.0	B A	9.5	А		
5	SR 28 at SR 66	SR 28	WB	WBL/T/R	22.8	С	22.8	С	17.2	В
	(Siynalizeu)	Wood St	NB	NBL/T/R	15.1	В	15.1	В		
		SR 66	SB	SBL/T/R	22.5	С	22.5	С		
		SR 28	EB	EBL/T/R	9.7(L)	А	0.3	А		
7	SD 20 at Contor St	SR 28	WB	WBL/T/R	9.8(L)	А	0.2	А	1 0	٨
/		Walker Flat Rd	NB	NBL/T/R	14.6	В	14.6	В	1.J	A
		Center St	SB	SBL/T/R	12.9	В	12.9	В		
		SR 28	EB	EBL/T/R	9.1(L)	А	0.2	А		
0	SR 28 at Mayport Rd SR	SR 28	WB	WBL/T/R	9.4(L)	А	0.6	А	27	٨
ð	536	Mayport Rd	NB	NBL/T/R	11.8	В	11.8	В	2.1	A
		Driveway	SB	SBL/T/R	12.7	В	12.7	В		
		SR 28	EB	EBL/T/R	8.8(L)	А	0.3	А		
0	SD 20 at Carrier St	SR 28	WB	WBL/T/R	9.2(L)	А	1.4	А	2.4	٨
9	SR 20 dl Callel Sl	Carrier St	NB	NBL/T/R	10.1	В	10.1	В		A
		Carrier St	SB	SBL/T/R	10.7	В	10.7	В		
		Driveway	EB	EBL/T/R	11.2	В	11.2	В		
10	SR 28 at S Main St	S. Main St	WB	WBL/T/R	10.4	В	10.4	В	24	Δ
10	Sit 20 at 5 Main St	SR 28	NB	NBL/T/R	8.3(L)	А	0.0	А	2.7	
		SR 28	SB	SBL/T/R	8.8(L)	А	2.8	А		
		SR 322	EB	EBL/T/R	17.5	В	17.5	В		
		SR 322	WB	WBL/T/R	15.4	В	15.4	В	B B 12.4	
	SD 28 at SD 222	SR 28	NB	NBL	10.9	В	14 4	B		
11	(Signalized)	517 20	ND	NBT/R	14.8	В	14.4	U	13.4	В
	,			SBL	9.4	А				
		SR 36 SB	SBT	10.4	В	B 9.7	А	13.4		
				SBR	0.0	А				

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
		LOO Domos	FD	EBL/T	30.7	С	22 E	C		
		1-80 Rainps	ED	EBR	35.7	D	33.3	C		
12	SR 36 at I-80 EB Ramps (Signalized)	SR 36	NB	NBT/R	7.8	А	7.7	А	11.8	В
	(orgnalized)	SD 26	SB	SBL	4.5	А	7.6	٨		
		SK 30	30	SBT	8.9	А	7.0	A		
		1.90 Damps	\//R	WBL/T	29.7	С	22.0	C		
			VVD	WBR	34.6	С	32.0	C		
13	SR 36 at I-80 WB Ramps (Signalized)	SD 26	NR	NBL	4.1	А	1.0	٨	10.9	В
	(orgnail2ou)	SK 30	ND	NBT	0.2	А	1.0	A		
		SR 36	SB	SBT/R	8.4	А	8.3	А		
		SR 28	EB	EBL/T	9.2(L)	А	0.1	А		
14	SR 28 at Waterford Pike	SR 28	WB	WBT/R	0.0	А	0.0	А	0.1	А
		Waterford Pike	SB	SBL/R	10.1	В	10.1	В		
		I-80 Ramps	EB	EBL/T/R	10.5	В	10.5	В		
15	SR 28 at I-80 EB Ramps	SR 28	NB	NBT/R	0.0	А	0.0	А	3.7	А
		SR 28	SB	SBL/T	8.3(L)	А	0.2	А		
		I-80 Ramps	WB	WBL/T/R	10.2	В	10.2	В		
16	SR 28 at I-80 WB Ramps	SR 28	NB	NBL/T	8.4(L)	А	1.7	А	2.8	А
		SR 28	SB	SBT/R	0.0	А	0.0	А		
		SR 28	EB	EBT/R	0.0	А	0.0	А		
81	SR 28 at Dairy Rd	SR 28	WB	WBL/T	9.3(L)	А	0.1	А	0.2	А
		Dairy Rd	NB	NBL/R	11.1	В	11.1	В		

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
		SR 85	FR	EBL	54	D	51.8	D		
		51(05	LD	EBT/R	49.8	D	51.0	U		
		SR 85	WB	WBL	64.3	E	56	F		
4	SR 28 at SR 85	01100	110	WBT/R	32.1	С		-	00.0	P
I	(Signalized)		ND	NBL	97.5	F	00.4	0	39.8	D
		SR 28	NB	NBL	27.9	C	30.1	С		
					U 112 Q	A F				
		SR 28	SB	SBT/R	26	C	31.5	С		
		SR 1004	EB	EBL/R	14.7	В	14.7	В		
2	SR 28 at SR 1004	SR 28	NB	NBL/T	9.3(L)	А	0.7	А	2.2	А
	IVIAUISUIT KU	SR 28	SB	SBT/R	0	А	0	А		
		SR 1004	EB	EBL/T/R	7.4	А	7.4	А		
01	Kohlersburg Rd at SR 1004	Slip Ramp	WB	WBL/T/R	7.8	А	7.8	А	7.7	А
21	Madison Rd	SR 1004	NB	NBL/T/R	7.9	А	7.9	А		
		Kburg Rd	SB	SBL/T/R	7.4	А	7.4	А		
		Kburg Rd	EB	EBL/R	16.4	С	16.4	С		
3	SR 28 at Kohlersburg Rd	SR 28	NB	NBL/T	9.1(L)	А	0	А	0.2	А
		SR 28	SB	SBT/R	0	А	0	А		
		SR 28	EB	EBL/T/R	9.2(L)	А	0	А		
		SR 28	WB	WBL	9.8	А	1.9	А	4.0	
4	SR 28 at SR 839	020		WBT/R	0	A			1.9	A
		SR 839 NB NBL/T/R	11.1	В	11.1	В				
		Short St	SB	SBL/1/R	30.9	D	30.9	D	3	
		SR 28	EB	EBL FRT/R	10.7 0.7	Δ	10	В		
5	SR 28 at SR 66	SR 28	WB	WBL/T/R	24.7	C	24.7	С	19.2	В
5	(Signalized)	Wood St	NB	NBL/T/R	15	В	15	В		
		SR 66	SB	SBL/T/R	23.7	С	23.7	С		

#### Exhibit 4 - Intersection Level of Service (2045 PM)

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
		SR 28	EB	EBL/T/R	9.9(L)	А	0.5	А		
7	SD 30 at Contar St	SR 28	WB	WBL/T/R	9.7(L)	А	0.4	А	1 5	Λ
1	SK 20 di Ceriler Si	Walker Flat Rd	NB	NBL/T/R	17.5	С	17.5	С	1.0	A
		Center St	SB	SBL/T/R	13.6	В	13.6	В		
		SR 28	EB	EBL/T/R	9.3(L)	А	0.1	А		
0	SR 28 at Mayport Rd SR	SR 28	WB	WBL/T/R	9.6(L)	А	1.4	А	2 5	Λ
0	536	Mayport Rd	NB	NBL/T/R	14.5	В	14.5	В	5.0	A
		Driveway	SB	SBL/T/R	15.5	С	15.5	С		
		SR 28	EB	EBL/T/R	9.5(L)	А	0.2	А		
0	SD 20 at Carrier St	SR 28	WB	WBL/T/R	9.2(L)	А	1.4	А	2.6	٨
9		Carrier St	NB	NBL/T/R	12	В	12	В	2.0	A
		Carrier St	SB	SBL/T/R	12.9	В	12.9	В		
		Driveway	EB	EBL/T/R	11.8	В	11.8	В		
10	SD 28 at S Main St	S. Main St	WB	WBL/T/R	13.7	В	13.7	В	4.3	٨
10		SR 28	NB	NBL/T/R	8.6(L)	А	0.1	А		A
		SR 28	SB	SBL/T/R	8.6(L)	А	0.8	А		
		SR 322	EB	EBL/T/R	19.3	В	19.3	В		
		SR 322	WB	WBL/T/R	16.8	В	16.8	В		
		SR 28	NR	NBL	13.6	В	17 0	B		
11	SR 28 at SR 322 (Signalized)	517 20	ND	NBT/R	17.9	В	17.2	U	15.0	В
				SBL	10.2	В			15.0	
		SR 36	SB	SBT	11.9	В	10.9	В		
				SBR	0	А				
		I-80 Ramps	FB	EBL/T	29	С	35.2	D	D A 14.2	
	SR 36 at L80 FR Ramos	e contampo		EBR	39.3	D	0012			
12	(Signalized)	SR 36	NB	NBT/R	9.9	A	9.8	A		В
12		(Signalized) SR 36 SF	SB	SBL	5.9	A	8.9	А		
				SBT	10.1	В				

ID	Intersection	Roadway	Approach	Lane Config	Movement Delay (s)	Movement LOS	Approach Delay (s)	Approach LOS	Intersection Delay (s)	Intersection LOS
				WBL/T	232.9	F	107 4	F		
		I-80 Ramps	WB	WBR	38.9	D	127.4	F		
13	SR 36 at I-80 WB Ramps (Signalized)	SD 24	ND	NBL	5.9	А	1 /	٨	37.7	D
	(Olynalized)	SK 30	ND	NBT	0.2	А	1.0	А		
		SR 36	SB	SBT/R	11.5	В	11.3	В		
		SR 28	EB	EBL/T	9.9(L)	А	0.3	А		
14	SR 28 at Waterford Pike	SR 28	WB	WBT/R	0	А	0	А	0.2	А
		Waterford Pike	SB	SBL/R	14.8	В	14.8	В	0.2	
		I-80 Ramps	EB	EBL/T/R	10.6	В	10.6	В		
15	SR 28 at I-80 EB Ramps	SR 28	NB	NBT/R	0	А	0	А	2.5	А
		SR 28	SB	SBL/T	8.8(L)	А	0.6	А		
		I-80 Ramps	WB	WBL/T/R	13.8	В	13.8	В		
16	SR 28 at I-80 WB Ramps	SR 28	NB	NBL/T	8.7(L)	А	3.2	А	3.5	А
		SR 28	SB	SBT/R	0	А	0	А		
		SR 28	EB	EBT/R	0	А	0	А		
81	SR 28 at Dairy Rd	SR 28	WB	WBL/T	9.3(L)	А	0	А	0.1	А
		Dairy Rd	NB	NBL/R	11.7	В	11.7	В		

# APPENDIX H Design Criteria

## **25 MPH DESIGN CRITERIA**

6

(2) PR	BY: <u>NVA</u> DATE: CHK'D BY: <u>JDW</u> DATE: OJECT DESCRIPTION: <u>RT 28 Corrid</u>	3/18/2020 4/1/2020	(ittanning to I-80. This con	DESIGN CRIT MPMS NO. SR 28 rridor plan wil	FERIA MATRIX N/A SEC N/A , I assist in the fut	<u>Clarion</u> ure planning and	_COUNTY programmi	ng of potential transportation pro	jects with in the study area.
$\sim$	NHS? (Y/N) <u>N</u>	-		STRAHNET?	(Y/N) N	_			
(3) ₽	RT 28 DESIGN CRITERIA Reconstruction AREA SYSTEM (Urban/Rural) Rural FUNCTIONAL CLASSIFICATION Regional Arterial ROADWAY TYPOLOGY Suburban Center TOPOGRAPHY Rolling REMARKS New Bethlehem				4	TRAFFIC DATA OPENING DESIGN DI	i YEAR ADT ( I YEAR ADT ( ESIGN YEAR DHV (D D (Dii	Average Daily Traffic)8896 (2011)(Average Daily Traffic)10229(for Design Year ADT)2045esign Hourly Volume)818rectional Distribution)55T (Truck Percentage)5	7)
	5 Criteria*		Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE	REQUIRED VALUE	PROPOSED VALUE	CRITERIA MET?	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference)	REMARKS (NOTE ANY DESIGN EXCEPTIONS)
	Design Speed			25 MPH	30-35 MPH	25 MPH	No	DM-2, Table 1.3	
Γ	Lane Width			11'	10' to 12'	11'	Yes	DM-2, Table 1.3	
Γ	Shoulder Width			8'	4'-6'	8'	Yes	DM-2, Table 1.3	
	Minimum Bridge Widt	h		44'	28'-36'	44'	Yes	DM-2, Sec. 1.2C	
	Minimum Horizontal Rac	lius		600'	231' to 340'	600'	No	AASHTO, Table 3-9	* 25 mph, minimum radius is 144'
	Maximum Superelevation	Rate		Varies	6.0%	6.0%	Yes	DM-2, Table 1.3	
	Vertical Grade	Minimum		0.10%	0.50%	0.50%	Yes	DM-2, Table 1.3	line segment 103
	Vertical Grade	Maximum		2.90%	6.00%	6.00%	Yes	AASHTO, Table 7-2	line segment 90
	Minimum Stopping Sight Distance	(SSD/HLSD)							

(vertical and horizontal) Varies 200'-250' 200' Yes AASHTO, Table 7-1 Minimum Intersection Sight Distance (ISD) 335' to 390' AASHTO, Table 9-6 \* 25 mph, minimum ISD is 280' Varies 280' No Minimum Cross Slope 2.0% 2.0% Yes DM-2. Table 1.3 Varies Minimum Vertical Clearance N/A 16'-6" N/A N/A DM-2, Table 2.2

\*Refer to Publication 10X, Design Manual 1X, Appendix P for more information on controlling criteria and design exceptions.

Any pedestrian and bicycle concerns/needs? Explain. Sidewalks, multimodal

Any ADA compliance issues? Explain.	ADA ramps on corners through town
Any transit issues? Explain.	
Any additional design issues? Explain.	

		DESIRED	AVERAGE		NEDDELETION	
ROADWAY CLASS	ROADWAY TYPE	OPERATING SPEED	TRIP LENGTH	VOLUME	INTERSECTION SPACING	COMMENTS
Arterial	Regional	50-90 km/h (30-55 mph)	24-56 km (15-35 mi)	10,000- 40,000 veh/day	200-400 m (660-1,320 ft)	Roadways in this category would be considered "Principal Arterial" in traditional functional classification.
Arterial	Community	40-90 km/h (25-55 mph)	11-40 km (7-25 mi)	5,000- 25,000 veh/day	90-400 m (300-1,320 ft)	Often classified as "Minor Arterial" in traditional classification but may include road segments classified as "Principal Arterial".
Collector	Community	40-90 km/h (25-55 mph)	8-16 km (5-10 mi)	5,000- 15,000 veh/day	90-200 m (300-660 ft)	Often similar in appearance to a community arterial. Typically classified as "Major Collector".
Collector	Neighborhood	40-60 km/h (25-35 mph)	< 11 km (< 7 mi)	< 6,000 veh/day	90-200 m (300-660 ft)	Similar in appearance to local roadways. Typically classified as "Minor Collector".
Local	Local	30-50 km/h (20-30 mph)	< 8 km (< 5 mi)	< 3,000 veh/day	60-200 m (200-660 ft)	

TABLE 1.2 ROADWAY TYPOLOGIES

#### INTENTIONALLY BLANK

#### FIGURE 1.2 ILLUSTRATED ROADWAY TYPOLOGIES



#### FIGURE 1.2 (CONTINUED) ILLUSTRATED ROADWAY TYPOLOGIES



# TABLE 1.3 (ENGLISH) MATRIX OF DESIGN VALUE<mark>S – REGIONA</mark>L ARTERIAL

1	-						I	
	Kegional Arterial	Rural	Suburban Neighborhood	Suburban Corridor	Suburban Center	Town/Village Neighborhood	Town/Village Center	Urban Core
	Lane Width <sup>1</sup>	11' to 12'	11' to 12'	11' to 12'	11' to 12'	10' to 12'	10' to 12'	10' to 12'
	Shoulder Width <sup>2, 3</sup>	8' to 10'	8' to 10'	8' to 12'	4' to 6' (if No Parking or Bike Lane)			
	Parking Lane	NA	AN	NA	8' Parallel	8' Parallel	8' Parallel	8' Parallel
	Bike Lane <sup>4</sup>	ΝA	5' to 6' (if No Shoulder)	6' (if No Shoulder)	5' to 6'	5' to 6'	5' to 6'	5' to 6'
	Median (if needed)	4' to 6'	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only
	Curb Return <sup>5</sup>	30' to 50'	25' to 35'	30' to 50'	25' to 50'	15' to 40'	15' to 40'	15' to 40'
	Travel Lanes	2 to 6	2 to 6	4 to 6	4 to 6	2 to 4	2 to 4	2 to 6
Yew	Cross Slopes (Minimum) <sup>6, 7</sup>	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%
Road	Cross Slopes (Maximum) <sup>8</sup>	8.0%	6.0%	6.0%	6.0%	6.0%	6.0%	6.0%
	Bridge Widths (Two-Lane Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	_ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side
	Bridge Widths (Four-Lane or More Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side
	Vertical Grades (Minimum) <sup>11</sup>	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%
	Vertical Clearance (Minimum)	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2
	Clear Sidewalk Width	NA	5'	5' to 6'	5' to 6'	6' to 8'	6' to 10'	6' to 12'
z	Buffer <sup>13</sup>	AA	6'+	6' to 10'	4' to 6'	4' to 6'	4' to 6'	4' to 6'
, ə	Shy Distance	NA	NA	NA	0' to 2'	0' to 2'	2'	2'
bisbe	Total Sidewalk Width	NA	5'	5' to 6'	9' to 14'	10' to 16'	12' to 18'	12' to 20'
Ros	Clear Zone Widths <sup>14</sup>	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12
	Right-of-Way Widths <sup>15</sup>	Varies	Varies	Varies	Varies	Varies	Varies	Varies
	Desired Operating Speed (Design Speed)	45-55 mph	35-40 mph	35-55 mph	30-35 mph	30-35 mph	30-35 mph	30-35 mph
beed	Stopping and Passing Sight Distances (Minimum)	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1
	Vertical Grades (Maximum)	2004 AASHTO Green Book, Exhibit 7-2	2004 AASHTO Green Book, Exhibit 7-10					

S\$503						Met	rle					
	V <sub>a</sub> = 20	V <sub>d</sub> = 30	V <sub>a</sub> ≈ 40	V <sub>d</sub> = 50	V <sub>d</sub> = 60	V <sub>d</sub> ≈ 70	V <sub>d</sub> = 80	V <sub>d</sub> ≈ 90	V <sub>d</sub> = 100	V <sub>d</sub> = 110	V <sub>d</sub> ≈ 120	V <sub>d</sub> = 130
	km/h	km/h	km/h	km/h	km/h	km/h	km/b	km/h	km/h	km/h	km/h	km/h
e (%)	R (m)	8 (m)	R (m)	R (m)								
NC	194	421	738	1050	1440	1910	2360	2880	3510	4060	4770	5240
RC	138	299	525	750	1030	1380	1710	2090	2560	2970	3510	3880
2.2	122	265	465	668	919	1230	1530	1880	2300	2670	3160	3500
2.4	109	236	415	599	825	1110	1380	1700	2080	2420	2870	3190
2.6	97	212	372	S40	746	1000	1260	1540	1890	2210	2630	2930
2.8	87	190	334	488	676	910	1150	1410	1730	2020	2420	2700
3.0	78	170	300	443	615	831	1050	1290	1590	1870	2240	2510
3.2	70	152	269	402	561	761	959	1190	1470	1730	2080	2330
3.4	61	133	239	364	511	697	882	1100	1360	1600	1940	2180
3.6	51	113	206	329	465	640	813	1020	1260	1490	1810	2050
3.8	42	96	177	294	422	586	749	939	1170	1390	1700	1930
4.0	36	87.	155	261	380	535	690	870	1090	1300	1590	1820
4.2	31	72	136	234	343	488	635	806	1010	1220	1500	1720
4.4	27	63	121	210	311	446	584	746	938	1140	1410	1630
4.6	24	56	108	190	283	408	538	692	873	1070	1330	1540
4.8	21	50	97	172	258	374	496	641	812	997	1260	1470
5.0	19	45	88	156	235	343	457	594	755	933	1190	1400
5.2	17	40	79	142	214	315	421	549	701	871	1120	1330
5.4	15	36	71	128	195	287	386	506	648	810	1060	1260
5.6	13	32	63	115	176	260	351	463	594	747	980	1190
5.8	11	28	56	102	156	232	315	416	537	679	900	1110
6.0	8	21	43	79	123	184	252	336	437	560	756	951

Table 3-9. Minimum Radii for Design Superelevation Rates, Design Speeds, and  $e_{\max}$  = 6%

	S(8333)					્રા	J.S. Custo	ımary						S. (1) (2)
	V <sub>d</sub> = 15	V <sub>0</sub> = 20	¥ <sub>tf</sub> ≠ 25	V <sub>d</sub> = 30	V <sub>ci</sub> = 35	V <sub>d</sub> ≈ 40	V <sub>d</sub> = 45	V <sub>d</sub> = 50	V <sub>d</sub> = 55	V <sub>d</sub> ≈ 60	V <sub>d</sub> = 65	V <sub>d</sub> = 70	V <sub>d</sub> = 75	V <sub>d</sub> = 80
	mph	mph	mph	mph	mph	mph	mph	raph	mph	mph	mph	mph	mph	mph
e (%)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	<i>R</i> (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)
NC	868	1580	2290	3130	4100	5230	6480	7870	9410	11100	12600	14100	15700	17400
RC	614	1120	1630	2240	2950	3770	4680	\$700	6820	8060	9130	10300	11500	12900
2.2	543	991	1450	2000	2630	3370	4190	5100	6110	7230	8200	9240	10400	11600
2.4	482	884	1300	1790	2360	3030	3770	4600	5520	6540	7430	8380	9420	10600
2.6	430	791	1170	1610	21.30	2740	3420	4170	5020	5950	6770	7660	8620	9670
2.8	384	709	1050	1460	1930	2490	3110	3800	4580	\$440	6200	7030	7930	8910
3.0	341	635	944	1320	1760	2270	2840	3480	4200	4990	\$710	6490	7330	8260
3.2	300	566	850	1200	1600	2080	2600	3260	3860	4600	5280	6010	6810	7680
3.4	256	498	761	1080	1460	1900	2390	2940	3560	4250	4890	5580	6340	7180
3.6	209	422	673	972	1320	1740	2190	2710	3290	3940	4540	5210	\$930	6720
3.8	176	358	583	854	1190	1590	2010	2490	3040	3650	4230	4860	5560	6320
4.0	151	309	511	766	1070	1440	1840	2300	2810	3390	3950	4550	5220	5950
4.2	131	270	452	584	960	1310	1680	2110	2590	3140	3680	4270	4910	5620
4.4	116	238	40Z	615	868	1190	1540	1940	2400	2920	3440	4010	4630	5320
4.6	102	212	360	555	788	1090	1410	1780	2210	2710	3220	3770	4380	5040
4.8	91	189	324	502	718	<del>9</del> 95	1300	1640	2050	2510	3000	3550	4140	4790
5.0	82	169	292	456	654	911	1190	1510	1890	2330	2800	3330	3910	4550
5.2	73	152	264	413	595	833	1090	1390	1750	2160	2610	3120	3690	4320
S.4	65	136	237	373	540	759	995	1280	1610	1990	2420	2910	3460	4090
5.6	58	121	212	335	487	687	903	1160	1470	1830	2230	2700	3230	3840
5.8	51	106	186	296	431	611	806	1040	1320	1650	2020	2460	2970	3560
6.0	39	81	144	231	340	485	643	833	1060	1330	1660	2040	2500	3050

#### A Policy on Geometric Design of Highways and Streets

tance are considered, there are seldom advantages to using the maximum grade values except when grades are long.

				M	etric							J.S. (	Custo	man	<u> </u>		
		N Spec	laxin ified	num Desi	Grado gn Sp	e (%) eed (	for km/h	}		Spe	Maxi ecifie	mun d De	n Gra sign	de (% Spee	6) for d (m	ph)	
Type of Terrain	60	70	80	90	100	110	120	130	40	45	50	55	60	65	70	75	80
Level	5	5	4	4	3	3	3	3	5	5	4	4	3	3	3	3	3
Rolling	6	6	5	5	4	4	4	4	6	6	5	5	4	4	4	4	4
Mountainous	8	7	7	6	6	5	5	5	8	7	7	6	6	5	5	5	5

#### Table 7-2. Maximum Grades for Rural Arterials

#### **Cross Slope**

Cross slope is provided to enhance roadway drainage. Two-lane rural roadways are normally designed with a centerline crown and traveled-way cross slopes ranging from 1.5 to 2 percent with the higher values being most prevalent.

#### Superelevation

Where curves are used on a rural arterial alignment, a superelevation rate based on the design speed should be used. Superelevation rates should not exceed 12 percent; however, where ice and snow conditions are a factor, the maximum superelevation rate should not exceed 8 percent. Superelevation runoff denotes the length of roadway needed to accomplish the change in cross slope from a section with adverse crown removed to a fully superelevated section and vice versa. Adjustments in design runoff lengths may be needed for smooth riding, drainage, and appearance. Section 3.3 provides a detailed discussion of superelevation and tables of appropriate superelevation rates and runoff lengths for various design speeds.

#### 7.2.3 Cross-Sectional Elements

#### Widths of Roadway

The logical approach to determining appropriate lane and shoulder widths is to provide a width related to the traffic demands. Table 7-3 provides values for the width of traveled way and usable shoulder that should be considered for the volumes indicated. Regardless of weather conditions, shoulders should be usable at all times. On high-volume highways, shoulders should preferably be paved, but paved shoulders may not always be practical. As a minimum, 0.6 m [2 ft] of the shoulder width should be paved to provide for pavement support, wide vehicles, and collision avoidance. Where bicycles are to be accommodated on the shoulder, a minimum paved width of 1.2 m [4 ft] should be used. The shoulder should be constructed to a uniform width for relatively long stretches of roadway. For additional information concerning shoulders, refer to Section 4.4.

#### **Sight Distance**

Sight distance is directly related to and varies appreciably with design speed. Stopping sight distance should be provided throughout the length of the roadway. Passing and decision sight distances influence roadway operations and should be provided wherever practical. Providing decision sight distance at locations where complex decisions are made greatly enhances the capability for drivers to safely accomplish maneuvers. Examples of locations where complex decisions are needed include interchanges, high-volume intersections, transitions in roadway width, and transitions in the number of lanes. Providing adequate sight distance on rural arterials, which may combine both high speeds and high traffic volumes, can be complex. Table 7-1 presents the recommended minimum values of stopping and passing sight distance. Refer to Section 3.2 for a comprehensive discussion of sight distance and for tabulated values for decision sight distance.

	Metric			U.S. Customary	
Design Speed (km/h)	Minimum Stopping Sight Distance (m)	Minimum Passing Sight Distance (m)	Design Speed (mph)	Minimum Stopping Sight Distance (ft)	Minimum Passing Sight Distance (ft)
50	65	160	30	200	500
60	85	180	35	250	550
70	105	210	40	305	600
80	130	245	45	360	700
90	160	280	50	425	800
100	185	320	55	495	900
110	220	355	60	570	1000
120	250	395	65	645	1100
130	285	440	70	730	1200
			75	820	1300
			80	910	1400

#### Table 7-1. Minimum Sight Distances for Arterials

Ideally, intersections and railroad crossings should be grade separated or provided with adequate sight distance. Intersections should be placed in sag or tangent locations, or both, where practical, to provide maximum visibility of the roadway and pavement markings.

#### Alignment

A smooth flowing alignment is desirable on a rural arterial. Changes in alignment, both horizontal and vertical, should be sufficiently gradual to avoid surprising the driver. Minimum radii should be used sparingly; short horizontal curves—particularly at the end of long tangents—should be avoided. Roads with well-designed and consistent alignment usually function more efficiently and with lower crash rates than roads with poor alignment, even where enhanced signing and pavement marking are provided.

#### Grades

The length and steepness of grades directly affect the operational characteristics of an arterial. Table 7-2 presents recommended maximum grades for rural arterials. When vertical curves for stopping sight dis-

#### 9-38 A Policy on Geometric Design of Highways and Streets

intersection is located on a 4 percent upgrade, then the time gap selected for intersection sight distance design for left turns should be increased from 8.0 to 8.8 s, equivalent to an increase of 0.2 s for each percent grade.

The design values for intersection sight distance for passenger cars are shown in Table 9-6. Figure 9-17 includes design values, based on the time gaps for the design vehicles included in Table 9-5.

No adjustment of the recommended sight distance values for the major-road grade is generally needed because both the major- and minor-road vehicle will be on the same grade when departing from the intersection. However, if the minor-road design vehicle is a heavy truck and the intersection is located near a sag vertical curve with grades over 3 percent, then an adjustment to extend the recommended sight distance based on the major-road grade should be considered.

	Met	ric			U.S. Cus	tomary	
Design		Intersecti Distan Passeng	on Sight ce for er Cars	Design	Stopping	Intersecti Distan Passeng	on Sight ce for er Cars
Speed (km/h)	Stopping Sight Distance (m)	Calculated (m)	Design (m)	Speed (mph)	Sight Distance (ft)	Calculated (ft)	Design (ft)
20	20	41.7	45	15	80	165.4	170
30	35	62.6	65	20	115	220.5	225
40	50	83.4	85	25	155	275.6	280
50	65	104.3	105	30	200	330,8	335
60	85	125.1	130	35	250	385.9	390
70	105	146.0	150	40	305	441.0	445
80	130	166.8	170	45	360	496.1	500
90	160	187.7	190	50	425	551.3	555
100	185	208.5	210	55	495	606.4	610
110	220	229.4	230	60	570	661.5	665
120	250	250.2	255	65	645	716.6	720
130	285	271.1	275	70	730	771.8	775
-	_		_	75	820	826.9	830
	_	_		80	910	882.0	885

Table 9-6. Design Intersection Sight Distance—Case B1, Left Turn from Stop

Note: Intersection sight distance shown is for a stopped passenger car to turn left onto a two-lane highway with no median and grades 3 percent or less. For other conditions, the time gap should be adjusted and the sight distance recalculated.

Sight distance design for left turns at divided-highway intersections should consider multiple design vehicles and median width. If the design vehicle used to determine sight distance for a divided-highway intersection is larger than a passenger car, then sight distance for left turns will need to be checked for that selected design vehicle and for smaller design vehicles as well. If the divided-highway median is wide enough to store the design vehicle with a clearance to the through lanes of approximately 1 m [3 ft] at both ends of the vehicle, no separate analysis for the departure sight triangle for left turns is needed on the minor-road approach for the near roadway to the left. In most cases, the departure sight triangle for right
# 35 MPH DESIGN CRITERIA

OJECT DESCRIPTION: <u>RT 28 C</u> a	orridor Study from K	(1)	DESIGN CRI MPMS NO. SR 28	ITERIA MATRIX N/A SEC N/A	Armstrong , <u>Clarion</u> Jefferson ure planning and	COUNTY COUNTY COUNTY programmin	ng of potential transportation pro	ojects with in the study area.
NHS? (Y/N) <u>N</u>			STRAHNET?	(Y/N) N				
<u>ESIGN DESIGNATION</u> DESIGN CRIT AREA SYSTEM (Urban/R FUNCTIONAL CLASSIFICAT ROADWAY TYPOL TOPOGRA	RT 28 ERIA Reconstruction ural) Rural TION Regional Arter OGY Suburban Cent APHY Rolling	n ial ter		4	TRAFFIC DATA OPENING DESIGN D	S YEAR ADT ( I YEAR ADT ( ESIGN YEAR DHV (D D (Dir	Average Daily Traffic)   8996 (201     Average Daily Traffic)   10344     (for Design Year ADT)   2045     esign Hourly Volume)   828     rectional Distribution)   55     T (Truck Descentor)   10	7)
REM	ARKS South Bethleh Summerville	em, Hawthorn,	_				T (Truck Percentage) 5	
REM/	ARKS South Bethleh Summerville	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE	REQUIRED VALUE	PROPOSED VALUE	CRITERIA MET?	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference)	REMARKS (NOTE ANY DESIGN EXCEPTION
REM/	ARKS South Bethleh Summerville	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH	REQUIRED VALUE 30-35 MPH	PROPOSED VALUE 35 MPH	CRITERIA MET? Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTION
REM/ 5 Criteria* Design Speed Lane Width	ARKS South Bethleh Summerville	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11'	REQUIRED VALUE 30-35 MPH 10'-12'	PROPOSED VALUE 35 MPH 11'	CRITERIA MET? Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTION
Criteria* <u>Design Speed</u> Lane Width Shoulder Wid	ARKS South Bethleh Summerville	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8'	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6'	PROPOSED VALUE 35 MPH 11' 6'	CRITERIA MET? Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTIO
Criteria* <u>Design Speed</u> Lane Width Shoulder Wid Minimum Bridge	ARKS South Bethleh Summerville d th Width	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44'	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36'	PROPOSED VALUE 35 MPH 11' 6' 44'	CRITERIA MET? Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTIO
Criteria* <u>Design Speer</u> Lane Width Shoulder Wid Minimum Bridge V	ARKS South Bethleh Summerville d th Width al Radius	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44' 75'	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36' 231' to 340'	PROPOSED VALUE 35 MPH 11' 6' 44' 340'	CRITERIA MET? Yes Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.2G AASHTO, Table 3-9	REMARKS (NOTE ANY DESIGN EXCEPTIO
Criteria* <u>Design Speer</u> Lane Width Shoulder Wid Minimum Bridge 1 Minimum Horizonta Maximum Supereleva	ARKS South Bethleh Summerville d th Width al Radius ation Rate	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44' 75' Varies	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36' 28'-36' 231' to 340' 6.0%	PROPOSED VALUE 35 MPH 11' 6' 44' 340' 6.0%	CRITERIA MET? Yes Yes Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.2G AASHTO, Table 3-9 DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTIO
REM/	ARKS South Bethleh Summerville d th Width al Radius ation Rate Minimum	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44' 75' Varies 0.40%	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36' 231' to 340' 6.0% 0.50%	PROPOSED VALUE 35 MPH 11' 6' 44' 340' 6.0% 0.50%	CRITERIA MET? Yes Yes Yes Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTIC
REM/ 5 Criteria* Design Speer Lane Width Shoulder Wid Minimum Bridge Minimum Horizonta Maximum Supereleva Vertical Grade	ARKS South Bethleh Summerville d th Width al Radius ation Rate Minimum Maximum	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44' 75' Varies 0.40% 1.90%	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36' 231' to 340' 6.0% 0.50% 6.00%	PROPOSED VALUE 35 MPH 11' 6' 44' 340' 6.0% 0.50% 6.00%	CRITERIA MET? Yes Yes Yes Yes Yes Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTIC
REM/ 5 Criteria* Design Speed Lane Width Shoulder Wid Minimum Bridge Minimum Horizonta Maximum Supereleva Vertical Grade Minimum Stopping Sight Dist (vertical and horiz	ARKS South Bethleh Summerville d th Width al Radius ation Rate Minimum Maximum tance (SSD/HLSD) contal)	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44' 75' Varies 0.40% 1.90% Varies	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36' 231' to 340' 6.0% 0.50% 6.00% 200' to 250'	PROPOSED VALUE 35 MPH 11' 6' 44' 340' 6.0% 0.50% 6.00% 250'	CRITERIA MET? Yes Yes Yes Yes Yes Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-2 AASHTO, Table 7-1	REMARKS (NOTE ANY DESIGN EXCEPTIC
REM/ 5 Criteria* Design Speed Lane Width Shoulder Wid Minimum Bridge Minimum Horizonta Maximum Supereleva Vertical Grade Minimum Stopping Sight Dist (vertical and horiz Minimum Intersection Sigh	ARKS South Bethleh Summerville	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44' 75' Varies 0.40% 1.90% Varies Varies	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36' 231' to 340' 6.0% 0.50% 6.00% 200' to 250' 335' to 390'	PROPOSED VALUE 35 MPH 11' 6' 44' 340' 6.0% 0.50% 6.00% 250' 390'	CRITERIA MET? Yes Yes Yes Yes Yes Yes Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.2G AASHTO, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-2 AASHTO, Table 7-1 AASHTO, Table 9-6	REMARKS (NOTE ANY DESIGN EXCEPTIO
REM/ 5 Criteria* Design Speed Lane Width Shoulder Wid Minimum Bridge Minimum Horizonta Maximum Supereleva Vertical Grade Minimum Stopping Sight Dist (vertical and horiz Minimum Intersection Sigh Minimum Cross 5	ARKS South Bethleh Summerville d th Width al Radius ation Rate Minimum Maximum tance (SSD/HLSD) contal) t Distance (ISD) Slope	em, Hawthorn, Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE 35 MPH 11' 2'-8' 44' 75' Varies 0.40% 1.90% Varies Varies Varies Varies Varies	REQUIRED VALUE 30-35 MPH 10'-12' 4'-6' 28'-36' 231' to 340' 6.0% 0.50% 6.00% 200' to 250' 335' to 390' 2.0%	PROPOSED VALUE 35 MPH 11' 6' 44' 340' 6.0% 0.50% 6.00% 250' 390' 2.0%	CRITERIA MET? Yes Yes Yes Yes Yes Yes Yes Yes Yes Yes	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference) DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-1 AASHTO, Table 7-1 AASHTO, Table 9-6 DM-2, Table 1.3	REMARKS (NOTE ANY DESIGN EXCEPTIC

6

Any pedestrian and bicycle concerns/needs? Explain. Sidewalks, multimodal

pedestrian and bicycle concerns/needs? Explain.	Sidewarks, mutimodal
Any ADA compliance issues? Explain.	ADA ramps on corners through town
Any transit issues? Explain.	
Any additional design issues? Explain.	15 mph curve entering New Bethleham

		DESIRED	AVERAGE		NEDDELETION	
ROADWAY CLASS	ROADWAY TYPE	OPERATING SPEED	TRIP LENGTH	VOLUME	INTERSECTION SPACING	COMMENTS
Arterial	Regional	50-90 km/h (30-55 mph)	24-56 km (15-35 mi)	10,000- 40,000 veh/day	200-400 m (660-1,320 ft)	Roadways in this category would be considered "Principal Arterial" in traditional functional classification.
Arterial	Community	40-90 km/h (25-55 mph)	11-40 km (7-25 mi)	5,000- 25,000 veh/day	90-400 m (300-1,320 ft)	Often classified as "Minor Arterial" in traditional classification but may include road segments classified as "Principal Arterial".
Collector	Community	40-90 km/h (25-55 mph)	8-16 km (5-10 mi)	5,000- 15,000 veh/day	90-200 m (300-660 ft)	Often similar in appearance to a community arterial. Typically classified as "Major Collector".
Collector	Neighborhood	40-60 km/h (25-35 mph)	< 11 km (< 7 mi)	< 6,000 veh/day	90-200 m (300-660 ft)	Similar in appearance to local roadways. Typically classified as "Minor Collector".
Local	Local	30-50 km/h (20-30 mph)	< 8 km (< 5 mi)	< 3,000 veh/day	60-200 m (200-660 ft)	

TABLE 1.2 ROADWAY TYPOLOGIES

# INTENTIONALLY BLANK

# FIGURE 1.2 ILLUSTRATED ROADWAY TYPOLOGIES



# FIGURE 1.2 (CONTINUED) ILLUSTRATED ROADWAY TYPOLOGIES



# TABLE 1.3 (ENGLISH) MATRIX OF DESIGN VALUE<mark>S – REGIONA</mark>L ARTERIAL

	-							
	Kegional Arterial	Rural	Suburban Neighborhood	Suburban Corridor	Suburban Center	Town/Village Neighborhood	Town/Village Center	Urban Core
	Lane Width <sup>1</sup>	11' to 12'	11' to 12'	11' to 12'	11' to 12'	10' to 12'	10' to 12'	10' to 12'
	Shoulder Width <sup>2, 3</sup>	8' to 10'	8' to 10'	8' to 12'	4' to 6' (if No Parking or Bike Lane)			
	Parking Lane	AN	AN	NA	8' Parallel	8' Parallel	8' Parallel	8' Parallel
	Bike Lane <sup>4</sup>	ΝA	5' to 6' (if No Shoulder)	6' (if No Shoulder)	5' to 6'	5' to 6'	5' to 6'	5' to 6'
	Median (if needed)	4' to 6'	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only
	Curb Return <sup>5</sup>	30' to 50'	25' to 35'	30' to 50'	25' to 50'	15' to 40'	15' to 40'	15' to 40'
	Travel Lanes	2 to 6	2 to 6	4 to 6	4 to 6	2 to 4	2 to 4	2 to 6
yew	Cross Slopes (Minimum) <sup>6, 7</sup>	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%
Road	Cross Slopes (Maximum) <sup>8</sup>	8.0%	6.0%	6.0%	6.0%	6.0%	6.0%	6.0%
	Bridge Widths (Two-Lane Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	_ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side
	Bridge Widths (Four-Lane or More Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	_ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side
	Vertical Grades (Minimum) <sup>11</sup>	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%
	Vertical Clearance (Minimum)	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2
	Clear Sidewalk Width	AN	مت	5' to 6'	5' to 6'	6' to 8'	6' to 10'	6' to 12'
z	Buffer <sup>13</sup>	AN	6'+	6' to 10'	4' to 6'	4' to 6'	4' to 6'	4' to 6'
, ə	Shy Distance	AN	AN	NA	0' to 2'	0' to 2'	2'	2'
bisba	Total Sidewalk Width	NA	5'	5' to 6'	9' to 14'	10' to 16'	12' to 18'	12' to 20'
SoA	Clear Zone Widths <sup>14</sup>	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12
	Right-of-Way Widths <sup>15</sup>	Varies	Varies	Varies	Varies	Varies	Varies	Varies
	Desired Operating Speed (Design Speed)	45-55 mph	35-40 mph	35-55 mph	40-35 mph	30-35 mph	30-35 mph	30-35 mph
beedS	Stopping and Passing Sight Distances (Minimum)	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1
	Vertical Grades (Maximum)	2004 AASHTO Green Book, Exhibit 7-2	2004 AASHTO Green Book, Exhibit 7-10					

S\$503						Met	rle					
	V <sub>a</sub> = 20	V <sub>d</sub> = 30	V <sub>a</sub> ≈ 40	V <sub>d</sub> = 50	V <sub>d</sub> = 60	V <sub>d</sub> ≈ 70	V <sub>d</sub> = 80	V <sub>d</sub> ≈ 90	V <sub>d</sub> = 100	V <sub>d</sub> = 110	V <sub>d</sub> ≈ 120	V <sub>d</sub> = 130
	km/h	km/h	km/h	km/h	km/h	km/h	km/b	km/h	km/h	km/h	km/h	km/h
e (%)	R (m)	<i>R</i> (m)	R (m)	R (m)								
NC	194	421	738	1050	1440	1910	2360	2880	3510	4060	4770	5240
RC	138	299	525	750	1030	1380	1710	2090	2560	2970	3510	3880
2.2	122	265	465	668	919	1230	1530	1880	2300	2670	3160	3500
2.4	109	236	415	599	825	1110	1380	1700	2080	2420	2870	3190
2.6	97	212	372	S40	746	1000	1260	1540	1890	2210	2630	2930
2.8	87	190	334	488	676	910	1150	1410	1730	2020	2420	2700
3.0	78	170	300	443	615	831	1050	1290	1590	1870	2240	2510
3.2	70	152	269	402	561	761	959	1190	1470	1730	2080	2330
3.4	61	133	239	364	511	697	882	1100	1360	1600	1940	2180
3.6	51	113	206	329	465	640	813	1020	1260	1490	1810	2050
3.8	42	96	177	294	422	586	749	939	1170	1390	1700	1930
4.0	36	87.	155	261	380	535	690	870	1090	1300	1590	1820
4.2	31	72	136	234	343	488	635	806	1010	1220	1500	1720
4.4	27	63	121	210	311	446	584	746	938	1140	1410	1630
4.6	24	56	108	190	283	408	538	692	873	1070	1330	1540
4.8	21	50	97	172	258	374	496	641	812	997	1260	1470
5.0	19	45	88	155	235	343	457	594	755	933	1190	1400
5.2	17	40	79	142	214	315	421	549	701	871	1120	1330
5.4	15	36	71	128	195	287	386	506	648	810	1060	1260
5.6	13	32	63	115	176	260	351	463	594	747	980	1190
5.8	11	28	56	102	156	232	315	416	537	679	900	1110
6.0	8	21	43	79	123	184	252	336	437	560	756	951

Table 3-9. Minimum Radii for Design Superelevation Rates, Design Speeds, and  $e_{\max}$  = 6%

	NY SALA		0505265			્રિટેટ વ	J.S. Custo	umary						
	V <sub>d</sub> = 15	V <sub>1</sub> = 20	V <sub>d</sub> ≠ 25	V <sub>d</sub> = 30	V <sub>c</sub> = 35	V <sub>d</sub> ≈ 40	V <sub>d</sub> = 45	V <sub>d</sub> = 50	V <sub>d</sub> = 55	V <sub>d</sub> ≈ 60	V <sub>d</sub> = 65	V <sub>d</sub> = 70	V <sub>d</sub> = 75	V <sub>d</sub> = 80
	mph	maph	mph	mph	mph	mph	mph	mph						
e (%)	R (ft)													
NC	868	1580	2290	3130	4100	5230	6480	7870	9410	11100	12600	14100	15700	17400
RC	614	1120	1630	2240	2950	3770	4680	\$700	6820	8060	9130	10300	11500	12900
2.2	543	991	1450	2000	2630	3370	4190	5100	6110	7230	8200	9240	10400	11600
2.4	482	884	1300	1790	2360	3030	3770	4600	5520	6540	7430	8380	9420	10600
2.6	430	791	1170	1610	21.30	2740	3420	4170	5020	5950	6770	7660	8620	9670
2.8	384	709	1050	1460	1930	2490	3110	3800	4580	5440	6200	7030	7930	8910
3.0	341	635	944	1320	1760	2270	2840	3480	4200	4990	\$710	6490	7330	8260
3.2	300	566	850	1200	1600	2080	2600	3200	3860	4600	5280	6010	6810	7680
3.4	256	498	761	1080	1460	1900	2390	2940	3560	4250	4890	5580	6340	7180
3.6	209	422	673	972	1320	1740	2190	2710	3290	3940	4540	5210	\$930	6720
3.8	176	358	583	864	1190	1590	2010	2490	3040	3650	4230	4860	5560	6320
4.0	151	309	511	766	1070	1440	1840	2300	2810	3390	3950	4550	5220	5950
4.2	131	270	452	684	960	1310	1680	2110	2590	3140	3680	4270	4910	5620
4.4	116	238	40Z	615	868	1190	1540	1940	2400	2920	3440	4010	4630	5320
4.6	102	212	360	555	788	1090	1410	1780	2210	2710	3220	3770	4380	5040
4.8	91	189	324	502	718	<del>9</del> 95	1300	1640	2050	2510	3000	3550	4140	4790
5.0	82	169	292	456	654	911	1190	1510	1890	2330	2800	3330	3910	4550
5.2	73	152	264	413	595	833	1090	1390	1750	2160	2610	3120	3690	4320
S.4	65	136	237	373	540	759	995	1280	1610	1990	2420	2910	3460	4090
5.6	58	121	212	335	487	687	903	1160	1470	1830	2230	2700	3230	3840
5.8	51	106	186	296	431	611	806	1040	1320	1650	2020	2460	2970	3560
6.0	39	81	144	231	340	485	643	833	1060	1330	1660	2040	2500	3050

# A Policy on Geometric Design of Highways and Streets

tance are considered, there are seldom advantages to using the maximum grade values except when grades are long.

				M	etric							J.S. (	Custo	man	<u> </u>		
		N Spec	laxin ified	num Desi	Grado gn Sp	e (%) eed (	for km/h	}		Spe	Maxi ecifie	mun d De	n Gra sign	de (% Spee	6) for d (m	ph)	
Type of Terrain	60	70	80	90	100	110	120	130	40	45	50	55	60	65	70	75	80
Level	5	5	4	4	3	3	3	3	5	5	4	4	3	3	3	3	3
Rolling	6	6	5	5	4	4	4	4	6	6	5	5	4	4	4	4	4
Mountainous	8	7	7	6	6	5	5	5	8	7	7	6	6	5	5	5	5

# Table 7-2. Maximum Grades for Rural Arterials

### **Cross Slope**

Cross slope is provided to enhance roadway drainage. Two-lane rural roadways are normally designed with a centerline crown and traveled-way cross slopes ranging from 1.5 to 2 percent with the higher values being most prevalent.

### Superelevation

Where curves are used on a rural arterial alignment, a superelevation rate based on the design speed should be used. Superelevation rates should not exceed 12 percent; however, where ice and snow conditions are a factor, the maximum superelevation rate should not exceed 8 percent. Superelevation runoff denotes the length of roadway needed to accomplish the change in cross slope from a section with adverse crown removed to a fully superelevated section and vice versa. Adjustments in design runoff lengths may be needed for smooth riding, drainage, and appearance. Section 3.3 provides a detailed discussion of superelevation and tables of appropriate superelevation rates and runoff lengths for various design speeds.

# 7.2.3 Cross-Sectional Elements

### Widths of Roadway

The logical approach to determining appropriate lane and shoulder widths is to provide a width related to the traffic demands. Table 7-3 provides values for the width of traveled way and usable shoulder that should be considered for the volumes indicated. Regardless of weather conditions, shoulders should be usable at all times. On high-volume highways, shoulders should preferably be paved, but paved shoulders may not always be practical. As a minimum, 0.6 m [2 ft] of the shoulder width should be paved to provide for pavement support, wide vehicles, and collision avoidance. Where bicycles are to be accommodated on the shoulder, a minimum paved width of 1.2 m [4 ft] should be used. The shoulder should be constructed to a uniform width for relatively long stretches of roadway. For additional information concerning shoulders, refer to Section 4.4.

# **Sight Distance**

Sight distance is directly related to and varies appreciably with design speed. Stopping sight distance should be provided throughout the length of the roadway. Passing and decision sight distances influence roadway operations and should be provided wherever practical. Providing decision sight distance at locations where complex decisions are made greatly enhances the capability for drivers to safely accomplish maneuvers. Examples of locations where complex decisions are needed include interchanges, high-volume intersections, transitions in roadway width, and transitions in the number of lanes. Providing adequate sight distance on rural arterials, which may combine both high speeds and high traffic volumes, can be complex. Table 7-1 presents the recommended minimum values of stopping and passing sight distance. Refer to Section 3.2 for a comprehensive discussion of sight distance and for tabulated values for decision sight distance.

	Metric			U.S. Customary	
Design Speed (km/h)	Minimum Stopping Sight Distance (m)	Minimum Passing Sight Distance (m)	Design Speed (mph)	Minimum Stopping Sight Distance (ft)	Minimum Passing Sight Distance (ft)
50	65	160	30	200	500
60	85	180	35	250	550
70	105	210	40	305	600
80	130	245	45	360	700
90	160	280	50	425	800
100	185	320	55	495	900
110	220	355	60	570	1000
120	250	395	65	645	1100
130	285	440	70	730	1200
			75	820	1300
			80	910	1400

## Table 7-1. Minimum Sight Distances for Arterials

Ideally, intersections and railroad crossings should be grade separated or provided with adequate sight distance. Intersections should be placed in sag or tangent locations, or both, where practical, to provide maximum visibility of the roadway and pavement markings.

### Alignment

A smooth flowing alignment is desirable on a rural arterial. Changes in alignment, both horizontal and vertical, should be sufficiently gradual to avoid surprising the driver. Minimum radii should be used sparingly; short horizontal curves—particularly at the end of long tangents—should be avoided. Roads with well-designed and consistent alignment usually function more efficiently and with lower crash rates than roads with poor alignment, even where enhanced signing and pavement marking are provided.

### Grades

The length and steepness of grades directly affect the operational characteristics of an arterial. Table 7-2 presents recommended maximum grades for rural arterials. When vertical curves for stopping sight dis-

# 9-38 A Policy on Geometric Design of Highways and Streets

intersection is located on a 4 percent upgrade, then the time gap selected for intersection sight distance design for left turns should be increased from 8.0 to 8.8 s, equivalent to an increase of 0.2 s for each percent grade.

The design values for intersection sight distance for passenger cars are shown in Table 9-6. Figure 9-17 includes design values, based on the time gaps for the design vehicles included in Table 9-5.

No adjustment of the recommended sight distance values for the major-road grade is generally needed because both the major- and minor-road vehicle will be on the same grade when departing from the intersection. However, if the minor-road design vehicle is a heavy truck and the intersection is located near a sag vertical curve with grades over 3 percent, then an adjustment to extend the recommended sight distance based on the major-road grade should be considered.

	Met	ric			U.S. Cus	tomary	
Design		Intersecti Distan Passeng	on Sight ce for er Cars	Design	Stopping	Intersecti Distan Passeng	on Sight ce for er Cars
Speed (km/h)	Stopping Sight Distance (m)	Calculated (m)	Design (m)	Speed (mph)	Sight Distance (ft)	Calculated (ft)	Design (ft)
20	20	41.7	45	15	80	165.4	170
30	35	62.6	65	20	115	220.5	225
40	50	83.4	85	25	155	275.6	280
50	65	104.3	105	30	200	330,8	335
60	85	125.1	130	35	250	385.9	390
70	105	146.0	150	40	305	441.0	445
80	130	166.8	170	45	360	496.1	500
90	160	187.7	190	50	425	551.3	555
100	185	208.5	210	55	495	606.4	610
110	220	229.4	230	60	570	661.5	665
120	250	250.2	255	65	645	716.6	720
130	285	271.1	275	70	730	771.8	775
	_		_	75	820	826.9	830
	_	_		80	910	882.0	885

Table 9-6. Design Intersection Sight Distance—Case B1, Left Turn from Stop

Note: Intersection sight distance shown is for a stopped passenger car to turn left onto a two-lane highway with no median and grades 3 percent or less. For other conditions, the time gap should be adjusted and the sight distance recalculated.

Sight distance design for left turns at divided-highway intersections should consider multiple design vehicles and median width. If the design vehicle used to determine sight distance for a divided-highway intersection is larger than a passenger car, then sight distance for left turns will need to be checked for that selected design vehicle and for smaller design vehicles as well. If the divided-highway median is wide enough to store the design vehicle with a clearance to the through lanes of approximately 1 m [3 ft] at both ends of the vehicle, no separate analysis for the departure sight triangle for left turns is needed on the minor-road approach for the near roadway to the left. In most cases, the departure sight triangle for right

# 40 MPH DESIGN CRITERIA

CHK'D BY: JDW	DATE: 4/:	1/2020 (1)	DESIGN CRI MPMS NO. SR 28	FERIA MATRIX N/A SEC N/A	Jefferson , <u>Clarion</u> ure planning and	COUNTY COUNTY	ng of potential transportation pro	piects with in the study area.
NHS? (Y/N) N			STRAHNET?	<b>(Y/N)</b> N			<u> </u>	· · · ·
DESIGN DESIGNATION DESIGN C AREA SYSTEM (Urbar FUNCTIONAL CLASSIFIC ROADWAY TYP TOPOC RE	RT 28 RITERIA Recons /Rural) Rural CATION Regior OLOGY Suburl SRAPHY Rolling MARKS Distan North	al Arterial an Neighborhood t, PA from New Bethlehem		4	- TRAFFIC DATA OPENING DESIGN D	YEAR ADT ( YEAR ADT ( ESIGN YEAR DHV (D D (Dir	Average Daily Traffic)7196 (201Average Daily Traffic)8274(for Design Year ADT)2045esign Hourly Volume)745rectional Distribution)52T (Truck Percentage)8	9)
5 Criteria	*	Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE	REQUIRED VALUE	PROPOSED VALUE	CRITERIA MET?	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference)	REMARKS (NOTE ANY DESIGN EXCEPTIONS)
Design Sp	eed		40 MPH	35-40 MPH	40 MPH	Yes	DM-2, Table 1.3	
Lane Wid	lth		11'	11'-12'	11'	Yes	DM-2, Table 1.3	
Shoulder W	/idth		3'-8'	8'-10'	8'	Yes	DM-2, Table 1.3	
	To Width		N/A	38'-44'	N/A	N/A	DM-2, Sec 1.2C	
Minimum Bridg	se wiutii		6001	340'-485'	600'	Yes	AASHTO, Table 3-9	Entering Distant, PA
Minimum Bridg Minimum Horizo	ntal Radius		600.	340 403				
Minimum Bridg Minimum Horizo Maximum Superel	ntal Radius		Varies	6.0%	6.0%	Yes	DM-2, Table 1.3	
Minimum Bridg Minimum Horizo Maximum Superel	ntal Radius evation Rate Mini	num	600 <sup>°</sup> Varies 1.50%	6.0% 0.50%	6.0% 0.50%	Yes Yes	DM-2, Table 1.3 DM-2, Table 1.3	line segment 83
Minimum Bridg Minimum Horizo Maximum Superel Vertical Grade	ntal Radius evation Rate Mini Maxi	mum	600 <sup>°</sup> Varies 1.50% 6.90%	6.0% 0.50% 6.00%	6.0% 0.50% 6.00%	Yes Yes Yes	DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-2	line segment 83 line segment 81
Minimum Bridg Minimum Horizo Maximum Superel Vertical Grade Minimum Stopping Sight D	evation Rate Mini Maxi istance (SSD/H	num mum LSD)	600 <sup>.</sup> Varies 1.50% 6.90%	6.0% 0.50% 6.00%	6.0% 0.50% 6.00%	Yes Yes Yes	DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-2	line segment 83 line segment 81
Minimum Bridg Minimum Horizo Maximum Superel Vertical Grade Minimum Stopping Sight E (vertical and ho	evation Rate evation Rate Mini Maxi listance (SSD/H rizontal)	mum mum LSD)	600 <sup>°</sup> Varies 1.50% 6.90% Varies	6.0% 0.50% 6.00% 250'-305'	6.0% 0.50% 6.00% 305'	Yes Yes Yes Yes	DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-2 AASHTO, Table 7-1	line segment 83 line segment 81
Minimum Bridg Minimum Horizo Maximum Superel Vertical Grade Minimum Stopping Sight I (vertical and ho Minimum Intersection S	ntal Radius evation Rate Mini Maxi vistance (SSD/H rizontal) ght Distance (I	mum mum LSD)	Varies 1.50% 6.90% Varies Varies	6.0% 0.50% 6.00% 250'-305' 390'-445'	6.0% 0.50% 6.00% 305' 445'	Yes Yes Yes Yes Yes	DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-2 AASHTO, Table 7-1 AASHTO, Table 9-6	line segment 83 line segment 81
Minimum Bridg Minimum Horizo Maximum Superel Vertical Grade Minimum Stopping Sight D (vertical and ho Minimum Intersection S Minimum Cro	ntal Radius evation Rate Mini Maxi listance (SSD/H rizontal) ght Distance (I is Slope	mum mum LSD) SD)	600'   Varies   1.50%   6.90%   Varies   Varies   Varies   Varies	6.0% 0.50% 6.00% 250'-305' 390'-445' 2.0%	6.0% 0.50% 6.00% 305' 445' 2.0%	Yes Yes Yes Yes Yes Yes	DM-2, Table 1.3 DM-2, Table 1.3 AASHTO, Table 7-2 AASHTO, Table 7-1 AASHTO, Table 9-6 DM-2, Table 1.3	line segment 83 line segment 81

\_\_\_\_\_

(6)

Any pedestrian and bicycle concerns/needs? Explain.

Any ADA compliance issues? Explain.

Any transit issues? Explain. Any additional design issues? Explain.

		DESIRED	AVERAGE		NEDDOLOTION	
ROADWAY CLASS	ROADWAY TYPE	OPERATING SPEED	TRIP LENGTH	VOLUME	INTERSECTION SPACING	COMMENTS
Arterial	Regional	50-90 km/h (30-55 mph)	24-56 km (15-35 mi)	10,000- 40,000 veh/day	200-400 m (660-1,320 ft)	Roadways in this category would be considered "Principal Arterial" in traditional functional classification.
Arterial	Community	40-90 km/h (25-55 mph)	11-40 km (7-25 mi)	5,000- 25,000 veh/day	90-400 m (300-1,320 ft)	Often classified as "Minor Arterial" in traditional classification but may include road segments classified as "Principal Arterial".
Collector	Community	40-90 km/h (25-55 mph)	8-16 km (5-10 mi)	5,000- 15,000 veh/day	90-200 m (300-660 ft)	Often similar in appearance to a community arterial. Typically classified as "Major Collector".
Collector	Neighborhood	40-60 km/h (25-35 mph)	< 11 km (< 7 mi)	< 6,000 veh/day	90-200 m (300-660 ft)	Similar in appearance to local roadways. Typically classified as "Minor Collector".
Local	Local	30-50 km/h (20-30 mph)	< 8 km (< 5 mi)	< 3,000 veh/day	60-200 m (200-660 ft)	

TABLE 1.2 ROADWAY TYPOLOGIES

# INTENTIONALLY BLANK

# FIGURE 1.2 ILLUSTRATED ROADWAY TYPOLOGIES



# FIGURE 1.2 (CONTINUED) ILLUSTRATED ROADWAY TYPOLOGIES



# TABLE 1.3 (ENGLISH) MATRIX OF DESIGN VALUES – REGIONAL ARTERIAL

							1	
	кеgional Arterial	Rural	Suburban Neighborhood	Suburban Corridor	Suburban Center	Town/Village Neighborhood	Town/Village Center	Urban Core
	Lane Width <sup>1</sup>	11' to 12'	11' to 12'	11' to 12'	11' to 12'	10' to 12'	10' to 12'	10' to 12'
	Shoulder Width <sup>2, 3</sup>	8' to 10'	8' to 10'	8' to 12'	4' to 6' (if No Parking or Bike Lane)			
	Parking Lane	NA	NA	AN	8' Parallel	8' Parallel	8' Parallel	8' Parallel
	Bike Lane <sup>4</sup>	NA	5' to 6' (if No Shoulder)	6' (if No Shoulder)	5' to 6'	5' to 6'	5' to 6'	5' to 6'
	Median (if needed)	4' to 6'	16' to 18' for Left Turn; 6' to 8' for Pedestrians Onlv	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only
	Curb Return <sup>5</sup>	30' to 50'	25' to 35'	30' to 50'	25' to 50'	15' to 40'	15' to 40'	15' to 40'
	Travel Lanes	2 to 6	2 to 6	4 to 6	4 to 6	2 to 4	2 to 4	2 to 6
Yew	Cross Slopes (Minimum) <sup>6, 7</sup>	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%
Воаd	Cross Slopes (Maximum) <sup>8</sup>	8.0%	6.0%	6.0%	6.0%	6.0%	6.0%	6.0%
	Bridge Widths (Two-Lane Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side
	Bridge Widths (Four-Lane or More Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side
	Vertical Grades (Minimum) <sup>11</sup>	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%
	Vertical Clearance (Minimum)	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2
	Clear Sidewalk Width	NA	5.	5' to 6'	5' to 6'	6' to 8'	6' to 10'	6' to 12'
2	Buffer <sup>13</sup>	AN	+,9	6' to 10'	4' to 6'	4' to 6'	4' to 6'	4' to 6'
, ə	Shy Distance	NA	AA	AA	0' to 2'	0' to 2'	2'	2'
pispe	Total Sidewalk Width	NA	5.	5' to 6'	9' to 14'	10' to 16'	12' to 18'	12' to 20'
SoA	Clear Zone Widths <sup>14</sup>	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12
	Right-of-Way Widths <sup>15</sup>	Varies	Varies	Varies	Varies	Varies	Varies	Varies
	Desired Operating Speed (Design Speed)	45-55 mph	35-40 mph	35-55 mph	30-35 mph	30-35 mph	30-35 mph	30-35 mph
beed	Stopping and Passing Sight Distances (Minimum)	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1
	Vertical Grades (Maximum)	2004 AASHTO Green Book, Exhibit 7-2	2004 AASHTO Green Book, Exhibit 7-10					

						Met	ric					
	V <sub>a</sub> = 20	V <sub>a</sub> = 30	V <sub>d</sub> ≈ 40	V <sub>d</sub> ≈ 50	V <sub>d</sub> ≈ 60	V <sub>d</sub> ≈ 70	V <sub>d</sub> = 80	V <sub>d</sub> ≈ 90	V <sub>d</sub> = 100	V <sub>d</sub> = 110	V <sub>d</sub> ≈ 120	V <sub>d</sub> = 130
	km/h	km/h	km/h	km/h	km/h	km/h	km/b	km/h	km/h	km/h	km/h	km/h
e (%)	R (m)	R (m)	R (m)	R (m)								
NC	194	421	738	1050	1440	1910	2360	2880	3510	4060	4770	5240
RC	138	299	525	750	1030	1380	1710	2090	2560	2970	3510	3880
2.2	122	265	465	668	919	1230	1530	1880	2300	2670	3160	3500
2.4	109	236	415	599	825	1110	1380	1700	2080	2420	2870	3190
2.6	97	212	372	S40	746	1000	1260	1540	1890	2210	2630	2930
2.8	87	190	334	488	676	910	1150	1410	1730	2020	2420	2700
3.0	78	170	300	443	615	831	1050	1290	1590	1870	2240	2510
3.2	70	152	269	402	561	761	959	1190	1470	1730	2080	2330
3.4	61	133	239	364	511	697	882	1100	1360	1600	1940	2180
3.6	51	113	206	329	465	640	813	1020	1260	1490	1810	2050
3.8	42	96	177	294	422	586	749	939	1170	1390	1700	1930
4.0	36	82	155	261	380	535	690	870	1090	1300	1590	1820
4.2	31	72	136	234	343	488	635	806	1010	1220	1500	1720
4.4	27	63	121	210	311	446	584	746	938	1140	1410	1630
4.6	24	56	108	190	283	408	538	692	873	1070	1330	1540
4.8	21	50	97	172	258	374	496	641	81Z	9.97	1260	1470
5.0	19	45	88	156	235	343	457	594	755	933	1190	1400
5.2	17	40	7 <del>9</del>	142	214	315	421	549	701	871	1120	1330
5.4	15	36	71	128	195	287	386	506	648	810	1060	1260
5.6	13	32	63	115	176	260	351	463	594	747	980	1190
5.8	11	28	56	102	156	232	315	416	537	679	900	1110
6.0	8	21	43	79	123	184	252	336	437	560	756	951

Table 3-9. Minimum Radii for Design Superelevation Rates, Design Speeds, and  $e_{\max}$  = 6%

	NISSAN					્રા	J.S. Custo	ımary						S. (1) (2)
	V <sub>d</sub> = 15	V <sub>11</sub> = 20	V <sub>d</sub> ≠ 25	V <sub>d</sub> = 30	V <sub>c</sub> = 35	V <sub>d</sub> ≈ 40	V <sub>d</sub> = 45	V <sub>d</sub> = 50	V <sub>d</sub> = 55	V <sub>d</sub> ≈ 60	V <sub>d</sub> = 65	V <sub>d</sub> = 70	V <sub>d</sub> = 75	V <sub>d</sub> = 80
	nışh	mph	mph	mph	mph	mph	mph	raph	mph	mph	mph	mph	mph	mph
e (%)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)
NC	868	1580	2290	3130	4100	5230	6480	7870	9410	11100	12600	14100	15700	17400
RC	614	1120	1630	2240	2950	3770	4680	\$700	6820	8060	9130	10300	11500	12900
2.2	543	991	1450	2000	2630	3370	4190	5100	6110	7230	8200	9240	10400	11600
2.4	482	884	1300	1790	2360	3030	3770	4600	5520	6540	7430	8380	9420	10600
2.6	430	791	1170	1610	21.30	2740	3420	4170	5020	5950	6770	7660	8620	9670
2.8	384	709	1050	1460	1930	2490	3110	3800	4580	\$440	6200	7030	7930	8910
3.0	341	635	944	1320	1760	2270	2840	3480	4200	4990	\$710	6490	7330	8260
3.2	300	566	850	1200	1600	2080	2600	3260	3860	4600	5280	6010	6810	7680
3.4	256	498	761	1080	1460	1900	2390	2940	3560	4250	4890	5580	6340	7180
3.6	209	422	673	972	1320	1740	2190	2710	3290	3940	4540	5210	\$930	6720
3.8	176	358	583	864	1190	1590	2010	2490	3040	3650	4230	4860	5560	6320
4.0	151	309	511	766	1070	1440	1840	2300	2810	3390	3950	4550	5220	5950
4.2	131	270	452	584	960	1310	1680	2110	2590	3140	3680	4270	4910	5620
4.4	116	238	40Z	615	868	1190	1540	1940	2400	2920	3440	4010	4630	5320
4.6	102	212	360	555	788	1090	1410	1780	2210	2710	3220	3770	4380	5040
4.8	91	189	324	502	718	<del>9</del> 95	1300	1640	2050	2510	3000	3550	4140	4790
5.0	82	169	292	456	654	911	1190	1510	1890	2330	2800	3330	3910	4550
5.2	73	152	264	413	595	833	1090	1390	1750	2160	2610	3120	3690	4320
S.4	65	136	237	373	540	759	995	1280	1610	1990	2420	2910	3460	4090
5.6	58	121	212	335	487	687	903	1160	1470	1830	2230	2700	3230	3840
5.8	51	106	186	296	431	611	806	1040	1320	1650	2020	2460	2970	3560
6.0	39	81	144	231	340	485	643	833	1060	1330	1660	2040	2500	3050

# A Policy on Geometric Design of Highways and Streets

tance are considered, there are seldom advantages to using the maximum grade values except when grades are long.

				M	etric							J.S. (	Custo	man	<u> </u>		
		N Spec	laxin ified	num Desi	Grado gn Sp	e (%) eed (	for km/h	}		Spe	Maxi ecifie	mun d De	n Gra sign	de (% Spee	6) for d (m	ph)	
Type of Terrain	60	70	80	90	100	110	120	130	40	45	50	55	60	65	70	75	80
Level	5	5	4	4	3	3	3	3	5	5	4	4	3	3	3	3	3
Rolling	6	6	5	5	4	4	4	4	6	6	5	5	4	4	4	4	4
Mountainous	8	7	7	6	6	5	5	5	8	7	7	6	6	5	5	5	5

# Table 7-2. Maximum Grades for Rural Arterials

### **Cross Slope**

Cross slope is provided to enhance roadway drainage. Two-lane rural roadways are normally designed with a centerline crown and traveled-way cross slopes ranging from 1.5 to 2 percent with the higher values being most prevalent.

### Superelevation

Where curves are used on a rural arterial alignment, a superelevation rate based on the design speed should be used. Superelevation rates should not exceed 12 percent; however, where ice and snow conditions are a factor, the maximum superelevation rate should not exceed 8 percent. Superelevation runoff denotes the length of roadway needed to accomplish the change in cross slope from a section with adverse crown removed to a fully superelevated section and vice versa. Adjustments in design runoff lengths may be needed for smooth riding, drainage, and appearance. Section 3.3 provides a detailed discussion of superelevation and tables of appropriate superelevation rates and runoff lengths for various design speeds.

# 7.2.3 Cross-Sectional Elements

### Widths of Roadway

The logical approach to determining appropriate lane and shoulder widths is to provide a width related to the traffic demands. Table 7-3 provides values for the width of traveled way and usable shoulder that should be considered for the volumes indicated. Regardless of weather conditions, shoulders should be usable at all times. On high-volume highways, shoulders should preferably be paved, but paved shoulders may not always be practical. As a minimum, 0.6 m [2 ft] of the shoulder width should be paved to provide for pavement support, wide vehicles, and collision avoidance. Where bicycles are to be accommodated on the shoulder, a minimum paved width of 1.2 m [4 ft] should be used. The shoulder should be constructed to a uniform width for relatively long stretches of roadway. For additional information concerning shoulders, refer to Section 4.4.

# **Sight Distance**

Sight distance is directly related to and varies appreciably with design speed. Stopping sight distance should be provided throughout the length of the roadway. Passing and decision sight distances influence roadway operations and should be provided wherever practical. Providing decision sight distance at locations where complex decisions are made greatly enhances the capability for drivers to safely accomplish maneuvers. Examples of locations where complex decisions are needed include interchanges, high-volume intersections, transitions in roadway width, and transitions in the number of lanes. Providing adequate sight distance on rural arterials, which may combine both high speeds and high traffic volumes, can be complex. Table 7-1 presents the recommended minimum values of stopping and passing sight distance. Refer to Section 3.2 for a comprehensive discussion of sight distance and for tabulated values for decision sight distance.

	Metric			U.S. Customary	
Design Speed (km/h)	Minimum Stopping Sight Distance (m)	Minimum Passing Sight Distance (m)	Design Speed (mph)	Minimum Stopping Sight Distance (ft)	Minimum Passing Sight Distance (ft)
50	65	160	30	200	500
60	85	180	35	250	550
70	105	210	40	305	600
80	130	245	45	360	700
90	160	280	50	425	800
100	185	320	55	495	900
110	220	355	60	570	1000
120	250	395	65	645	1100
130	285	440	70	730	1200
			75	820	1300
			80	910	1400

## Table 7-1. Minimum Sight Distances for Arterials

Ideally, intersections and railroad crossings should be grade separated or provided with adequate sight distance. Intersections should be placed in sag or tangent locations, or both, where practical, to provide maximum visibility of the roadway and pavement markings.

### Alignment

A smooth flowing alignment is desirable on a rural arterial. Changes in alignment, both horizontal and vertical, should be sufficiently gradual to avoid surprising the driver. Minimum radii should be used sparingly; short horizontal curves—particularly at the end of long tangents—should be avoided. Roads with well-designed and consistent alignment usually function more efficiently and with lower crash rates than roads with poor alignment, even where enhanced signing and pavement marking are provided.

### Grades

The length and steepness of grades directly affect the operational characteristics of an arterial. Table 7-2 presents recommended maximum grades for rural arterials. When vertical curves for stopping sight dis-

# 9-38 A Policy on Geometric Design of Highways and Streets

intersection is located on a 4 percent upgrade, then the time gap selected for intersection sight distance design for left turns should be increased from 8.0 to 8.8 s, equivalent to an increase of 0.2 s for each percent grade.

The design values for intersection sight distance for passenger cars are shown in Table 9-6. Figure 9-17 includes design values, based on the time gaps for the design vehicles included in Table 9-5.

No adjustment of the recommended sight distance values for the major-road grade is generally needed because both the major- and minor-road vehicle will be on the same grade when departing from the intersection. However, if the minor-road design vehicle is a heavy truck and the intersection is located near a sag vertical curve with grades over 3 percent, then an adjustment to extend the recommended sight distance based on the major-road grade should be considered.

	Met	ric			U.S. Cus	itomary	
Design		Intersecti Distan Passeng	ion Sight ce for jer Cars	Design	Stopping	Intersecti Distan Passeng	on Sight ce for er Cars
Speed (km/h)	Stopping Sight Distance (m)	Calculated (m)	Design (m)	Speed (mph)	Sight Distance (ft)	Calculated (ft)	Design (ft)
20	20	41.7	45	15	80	165.4	170
30	35	62.6	65	20	115	220.5	225
40	50	83.4	85	25	155	275.6	280
50	65	104.3	105	30	200	330,8	335
60	85	125.1	130	35	250	385.9	390
70	105	146.0	150	40	305	441.0	445
80	130	166.8	170	45	360	496.1	500
90	160	187.7	190	50	425	551.3	555
100	185	208.5	210	55	495	606.4	610
110	220	229.4	230	60	570	661.5	665
120	250	250.2	255	65	645	716.6	720
130	285	271.1	275	70	730	771.8	775
	_		_	75	820	826.9	830
		_		80	910	882.0	885

Table 9-6. Design Intersection Sight Distance—Case B1, Left Turn from Stop

Note: Intersection sight distance shown is for a stopped passenger car to turn left onto a two-lane highway with no median and grades 3 percent or less. For other conditions, the time gap should be adjusted and the sight distance recalculated.

Sight distance design for left turns at divided-highway intersections should consider multiple design vehicles and median width. If the design vehicle used to determine sight distance for a divided-highway intersection is larger than a passenger car, then sight distance for left turns will need to be checked for that selected design vehicle and for smaller design vehicles as well. If the divided-highway median is wide enough to store the design vehicle with a clearance to the through lanes of approximately 1 m [3 ft] at both ends of the vehicle, no separate analysis for the departure sight triangle for left turns is needed on the minor-road approach for the near roadway to the left. In most cases, the departure sight triangle for right

# **45 MPH DESIGN CRITERIA**

ROJECT DESCRIPTION: <u>RT 28 Corri</u>	e: <u>4/1/2020</u>	(ittanning to I-80. This co	DESIGN CRI MPMS NO. SR 28	TERIA MATRIX N/A SEC N/A	Armstrong , Clarion Jefferson ure planning and	COUNTY programmin	ng of potential transportation pro	ojects with in the study area.
NHS? (Y/N) <u>N</u>			STRAHNET?	(Y/N) <u>N</u>				
DESIGN DESIGNATION F DESIGN CRITERI AREA SYSTEM (Urban/Rura	T 28 A <u>Reconstructio</u> I) Rural	n	-	4	<u>TRAFFIC DATA</u> OPENING DESIGN D	S YEAR ADT ( NYEAR ADT ( ESIGN YEAR	(Average Daily Traffic) 7349 (201 (Average Daily Traffic) 8450 (for Design Year ADT) 2045	9)
FUNCTIONAL CLASSIFICATIO ROADWAY TYPOLOG TOPOGRAPH DEMADR	N Regional Arter Y Rural Y Rolling	hatween New	- - -			DHV (D D (Dii	rectional Distribution) 761 T (Truck Percentage) 13	
	Bethlehem an Summerville	d Hawthrone, North of	- - -					
5 Criteria*		Location (ENTIRE PROJECT OR BY STATION)	EXISTING VALUE	REQUIRED VALUE	PROPOSED VALUE	CRITERIA MET?	SOURCE OF DESIGN CRITERIA (AASHTO OR DM-2 Reference)	REMARKS (NOTE ANY DESIGN EXCEPTIO
Design Speed		,	45 MPH	45 -55 MPH	45 MPH	Yes	DM-2, Table 1.3	
Lane Width			11'	11' to 12'	11'	Yes	DM-2, Table 1.3	
Shoulder Width			4'	8' to 10'	8'	Yes	DM-2, Table 1.3	
Minimum Bridge Wid	lth		N/A	38' to 44'	N/A	N/A	DM-2, Sec 1.2C	
Minimum Horizontal R	adius		470'	587' to 960'	587'	Yes	AASHTO, Table 3-10b	
Maximum Superelevatio	n Rate		varies	8.0%	8.0%	Yes	DM-2, Table 1.3	
Vortige Crede	Minimum		0.10%	0.50%	0.50%	Yes	DM-2, Table 1.3	line segment 103
vertical Grade	Maximum		7.10%	6.00%	6.00%	Yes	AASHTO, Table 7-2	line segment 182
Minimum Stopping Sight Distand (vertical and horizont	e (SSD/HLSD) al)		varies	360' to 495'	360'	Yes	AASHTO, Table 7-1	
Minimum Intersection Sight D	stance (ISD)		varies	500' to 610'	500'	Yes	AASHTO, Table 9-6	
Minimum Cross Slop	)e		varies	2.0%	2.0%	Yes	DM-2, Table 1.3	
Minimum Vertical Clear	ance		N/A	16'-6"	16'-6"	Yes	DM-2, Table 2.2	
*Refer to Publication 10X, Design	Manual 1X, Appe	endix P for more informa	tion on contro	olling criteria and	design exception	ıs.		

Any transit issues? Explain.

Any additional design issues? Explain.

		DESIRED	AVERAGE		NEDDOLOTION	
ROADWAY CLASS	ROADWAY TYPE	OPERATING SPEED	TRIP LENGTH	VOLUME	INTERSECTION SPACING	COMMENTS
Arterial	Regional	50-90 km/h (30-55 mph)	24-56 km (15-35 mi)	10,000- 40,000 veh/day	200-400 m (660-1,320 ft)	Roadways in this category would be considered "Principal Arterial" in traditional functional classification.
Arterial	Community	40-90 km/h (25-55 mph)	11-40 km (7-25 mi)	5,000- 25,000 veh/day	90-400 m (300-1,320 ft)	Often classified as "Minor Arterial" in traditional classification but may include road segments classified as "Principal Arterial".
Collector	Community	40-90 km/h (25-55 mph)	8-16 km (5-10 mi)	5,000- 15,000 veh/day	90-200 m (300-660 ft)	Often similar in appearance to a community arterial. Typically classified as "Major Collector".
Collector	Neighborhood	40-60 km/h (25-35 mph)	< 11 km (< 7 mi)	< 6,000 veh/day	90-200 m (300-660 ft)	Similar in appearance to local roadways. Typically classified as "Minor Collector".
Local	Local	30-50 km/h (20-30 mph)	< 8 km (< 5 mi)	< 3,000 veh/day	60-200 m (200-660 ft)	

TABLE 1.2 ROADWAY TYPOLOGIES

# INTENTIONALLY BLANK

# FIGURE 1.2 ILLUSTRATED ROADWAY TYPOLOGIES



# FIGURE 1.2 (CONTINUED) ILLUSTRATED ROADWAY TYPOLOGIES



# TABLE 1.3 (ENGLISH) MATRIX OF DESIGN VALUES – REGIONAL ARTERIAL

							!	
	Regional Arterial	Rural	Suburban Neighborhood	Suburban Corridor	Suburban Center	Town/Village Neighborhood	Town/Village Center	Urban Core
	Lane Width <sup>1</sup>	11' to 12'	11' to 12'	11' to 12'	11' to 12'	10' to 12'	10' to 12'	10' to 12'
	Shoulder Width <sup>2, 3</sup>	8' to 10'	8' to 10'	8' to 12'	4' to 6' (if No Parking or Bike Lane)			
	Parking Lane	AN	AN	AN	8' Parallel	8' Parallel	8' Parallel	8' Parallel
	Bike Lane <sup>4</sup>	NA	5' to 6' (if No Shoulder)	6' (if No Shoulder)	5' to 6'	5' to 6'	5' to 6'	5' to 6'
	Median (if needed)	4' to 6'	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only
	Curb Return <sup>5</sup>	30' to 50'	25' to 35'	30' to 50'	25' to 50'	15' to 40'	15' to 40'	15' to 40'
	Travel Lanes	2 to 6	2 to 6	4 to 6	4 to 6	2 to 4	2 to 4	2 to 6
Yewb	Cross Slopes (Minimum) <sup>6, 7</sup>	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%
Road	Cross Slopes (Maximum) <sup>8</sup>	8.0%	6.0%	6.0%	6.0%	6.0%	6.0%	6.0%
	Bridge Widths (Two-Lane Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	_ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side				
	Bridge Widths (Four-Lane or More Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	_ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side				
	Vertical Grades (Minimum) <sup>11</sup>	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%
	Vertical Clearance (Minimum)	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2
	Clear Sidewalk Width	NA	5.	5' to 6'	5' to 6'	6' to 8'	6' to 10'	6' to 12'
z	Buffer <sup>13</sup>	AN	+,9	6' to 10'	4' to 6'	4' to 6'	4' to 6'	4' to 6'
ا ع	Shy Distance	AA	AA	NA	0' to 2'	0' to 2'	2	2
pispe	Total Sidewalk Width	NA	٦	5' to 6'	9' to 14'	10' to 16'	12' to 18'	12' to 20'
SoA	Clear Zone Widths <sup>14</sup>	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12
	Right-of-Way Widths <sup>15</sup>	Varies	Varies	Varies	Varies	Varies	Varies	Varies
	Desired Operating Speed (Design Speed)	45-55 mph	35-40 mph	35-55 mph	30-35 mph	30-35 mph	30-35 mph	30-35 mph
pəədS	Stopping and Passing Sight Distances (Minimum)	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1
	Vertical Grades (Maximum)	2004 AASHTO Green Book, Exhibit 7-2	2004 AASHTO Green Book, Exhibit 7-10					

				5 ( <u>)</u> ( )				J.S. Custa	mary	<u> 988-976</u>					12653
		V <sub>d</sub> = 15	V <sub>d</sub> = 20	V <sub>d</sub> = 25	V <sub>d</sub> ≈ 30	V <sub>d</sub> = 35	V <sub>d</sub> = 40	V <sub>d</sub> ≈45	V <sub>d</sub> = 50	V <sub>d</sub> = 55	V <sub>d</sub> = 60	V <sub>d</sub> = 65	V <sub>d</sub> = 70	V <sub>d</sub> = 75	V <sub>d</sub> = 80
		mph	mph	mph	mph	mph	mph	mph	ութի	mph	mph	mph	mph	mph	mph
	e {%}	R (ft)	8 (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)					
	NC	932	1640	2370	3240	4260	5410	6710	8150	9720	11500	12900	14500	16100	17800
	RC	676	1190	1720	2370	3120	3970	4930	5990	7150	8440	9510	10700	12900	13300
	2.2	605	1070	1550	2130	2800	3570	4440	5400	6450	7620	8600	9660	10800	12000
	2.4	546	959	1400	1930	2540	3240	4030	4910	5870	6930	7830	8810	9850	11000
· · ·	2.6	496	872	1280	1760	2320	2960	3690	4490	5370	6350	7180	8090	9050	10100
· .	2.8	453	796	1170	1610	2130	2720	3390	4130	4950	5850	6630	7470	8370	9340
	3.0	415	730	1070	1480	1960	2510	3130	3820	4580	5420	6140	6930	7780	8700
	3.2	382	672	985	1370	1820	2330	2900	3550	4250	5040	5720	6460	7260	8130
· ·	3.4	352	620	911	1270	1690	2170	2700	3300	3970	4700	5350	6050	6800	7620
. 1	3.6	324	572	845	1180	1570	2020	2520	3090	3710	4400	5010	5680	6400	7180
· ·	3.8	300	530	784	1100	1470	1890	2360	2890	3480	4140	4710	5350	6030	6780
•	4.0	277	490	729	1030	1370	1770	2220	2720	3270	3890	4450	5050	5710	6420
	4.2	255	453	678	955	1280	1660	2080	2560	3080	3670	4200	4780	5410	6090
	4.4	235	418	630	893	1200	1560	1960	2410	2910	3470	3980	4540	5140	5800
•	4.6	215	384	585	834	1130	1470	1850	2280	2750	3290	3770	4310	4890	5530
	4.8	193	349	542	779	1060	1390	1750	2160	2610	3120	3590	4100	4670	5280
	5.0	172	314	499	727	991	1310	1650	2040	2470	2950	3410	3910	4460	5050
	5.2	154	284	457	676	929	1230	1560	1930	2350	2820	3250	3740	4260	4840
	5.4	139	258	420	627	870	1160	1480	1830	2230	2680	3110	3570	4090	4640
	5.6	126	236	387	582	813	1090	1390	1740	2120	2550	2970	3420	3920	4460
	5,8	115	216	358	542	761	1030	1320	1650	2010	2430	2840	3280	3760	4290
	6.0	105	199	332	506	713	965	1250	1560	1920	2320	2710	3150	3620	4140
	6.2	97	184	308	472	669	909	1180	1480	1820	2210	2600	3020	3480	3990
1.1	6.4	89	170	287	442	628	857	1110	1400	1730	2110	2490	2910	3360	3850
· .	6.6	82	157	267	413	590	808	1050	1330	1650	2010	2380	2790	3240	3720
•	6.8	76	145	248	386	553	761	990	1260	1560	1910	2280	2690	3120	3600
	7.0	70	135	231	360	518	716	933	1190	1480	1820	2180	2580	3010	3480
· *	7.2	64	125	214	336	485	672	878	1120	1400	1720	2070	2470	2900	3370
. 1	7.4	59	115	198	312	451	628	822	1060	1320	1630	1970	2350	2780	3250
. ·	7.6	54	105	182	287	417	583	765	980	1230	1530	1850	2230	2650	3120
·	7.8	48	94	164	261	380	533	701	901	1140	1410	1720	2090	2500	2970
:	8.0	38	76	134	214	314	444	587	758	960	1200	1480	1810	2210	2670

Chapter 3—Elem Table 3-10b. Minimum Radii for Design Superelevation Rates, Design Speeds, and e<sub>max</sub> = 8%

© 2011 by the American Association of State Highway and Transportation Officials. All rights reserved. Duplication is a violation of applicable law.

# A Policy on Geometric Design of Highways and Streets

tance are considered, there are seldom advantages to using the maximum grade values except when grades are long.

				M	etric							J.S. (	Custo	man	<u> </u>		
		N Spec	laxin ified	num Desi	Grado gn Sp	e (%) eed (	for km/h	}		Sp	Maxi ecifie	mun d De	n Gra sign	de (% Spee	6) for d (m	ph)	
Type of Terrain	60	70	80	90	100	110	120	130	40	45	50	55	60	65	70	75	80
Level	5	5	4	4	3	3	3	3	5	5	4	4	3	3	3	3	3
Rolling	6	6	5	5	4	4	4	4	6	6	5	5	4	4	4	4	4
Mountainous	8	7	7	6	6	5	5	5	8	7	7	6	6	5	5	5	5

# Table 7-2. Maximum Grades for Rural Arterials

### **Cross Slope**

Cross slope is provided to enhance roadway drainage. Two-lane rural roadways are normally designed with a centerline crown and traveled-way cross slopes ranging from 1.5 to 2 percent with the higher values being most prevalent.

### Superelevation

Where curves are used on a rural arterial alignment, a superelevation rate based on the design speed should be used. Superelevation rates should not exceed 12 percent; however, where ice and snow conditions are a factor, the maximum superelevation rate should not exceed 8 percent. Superelevation runoff denotes the length of roadway needed to accomplish the change in cross slope from a section with adverse crown removed to a fully superelevated section and vice versa. Adjustments in design runoff lengths may be needed for smooth riding, drainage, and appearance. Section 3.3 provides a detailed discussion of superelevation and tables of appropriate superelevation rates and runoff lengths for various design speeds.

# 7.2.3 Cross-Sectional Elements

### Widths of Roadway

The logical approach to determining appropriate lane and shoulder widths is to provide a width related to the traffic demands. Table 7-3 provides values for the width of traveled way and usable shoulder that should be considered for the volumes indicated. Regardless of weather conditions, shoulders should be usable at all times. On high-volume highways, shoulders should preferably be paved, but paved shoulders may not always be practical. As a minimum, 0.6 m [2 ft] of the shoulder width should be paved to provide for pavement support, wide vehicles, and collision avoidance. Where bicycles are to be accommodated on the shoulder, a minimum paved width of 1.2 m [4 ft] should be used. The shoulder should be constructed to a uniform width for relatively long stretches of roadway. For additional information concerning shoulders, refer to Section 4.4.

# **Sight Distance**

Sight distance is directly related to and varies appreciably with design speed. Stopping sight distance should be provided throughout the length of the roadway. Passing and decision sight distances influence roadway operations and should be provided wherever practical. Providing decision sight distance at locations where complex decisions are made greatly enhances the capability for drivers to safely accomplish maneuvers. Examples of locations where complex decisions are needed include interchanges, high-volume intersections, transitions in roadway width, and transitions in the number of lanes. Providing adequate sight distance on rural arterials, which may combine both high speeds and high traffic volumes, can be complex. Table 7-1 presents the recommended minimum values of stopping and passing sight distance. Refer to Section 3.2 for a comprehensive discussion of sight distance and for tabulated values for decision sight distance.

	Metric			U.S. Customary	
Design Speed (km/h)	Minimum Stopping Sight Distance (m)	Minimum Passing Sight Distance (m)	Design Speed (mph)	Minimum Stopping Sight Distance (ft)	Minimum Passing Sight Distance (ft)
50	65	160	30	200	500
60	85	180	35	250	550
70	105	210	40	305	600
80	130	245	45	360	700
90	160	280	50	425	800
100	185	320	55	495	900
110	220	355	60	570	1000
120	250	395	65	645	1100
130	285	440	70	730	1200
			75	820	1300
			80	910	1400

## Table 7-1. Minimum Sight Distances for Arterials

Ideally, intersections and railroad crossings should be grade separated or provided with adequate sight distance. Intersections should be placed in sag or tangent locations, or both, where practical, to provide maximum visibility of the roadway and pavement markings.

### Alignment

A smooth flowing alignment is desirable on a rural arterial. Changes in alignment, both horizontal and vertical, should be sufficiently gradual to avoid surprising the driver. Minimum radii should be used sparingly; short horizontal curves—particularly at the end of long tangents—should be avoided. Roads with well-designed and consistent alignment usually function more efficiently and with lower crash rates than roads with poor alignment, even where enhanced signing and pavement marking are provided.

### Grades

The length and steepness of grades directly affect the operational characteristics of an arterial. Table 7-2 presents recommended maximum grades for rural arterials. When vertical curves for stopping sight dis-

# 9-38 A Policy on Geometric Design of Highways and Streets

intersection is located on a 4 percent upgrade, then the time gap selected for intersection sight distance design for left turns should be increased from 8.0 to 8.8 s, equivalent to an increase of 0.2 s for each percent grade.

The design values for intersection sight distance for passenger cars are shown in Table 9-6. Figure 9-17 includes design values, based on the time gaps for the design vehicles included in Table 9-5.

No adjustment of the recommended sight distance values for the major-road grade is generally needed because both the major- and minor-road vehicle will be on the same grade when departing from the intersection. However, if the minor-road design vehicle is a heavy truck and the intersection is located near a sag vertical curve with grades over 3 percent, then an adjustment to extend the recommended sight distance based on the major-road grade should be considered.

	Met	ric			U.S. Cus	tomary	
Design		Intersecti Distan Passeng	ion Sight ce for er Cars	Design	Stopping	Intersecti Distan Passeng	ion Sight ce for er Cars
Speed (km/h)	Stopping Sight Distance (m)	Calculated (m)	Design (m)	Speed (mph)	Sight Distance (ft)	Calculated (ft)	Design (ft)
20	20	41.7	45	15	80	165.4	170
30	35	62.6	65	20	115	220.5	225
40	50	83.4	85	25	155	275.6	280
50	65	104.3	105	30	200	330,8	335
60	85	125.1	130	35	250	385.9	390
70	105	146.0	150	40	305	441.0	445
80	130	166.8	170	45	360	496.1	500
90	160	187.7	190	50	425	551.3	555
100	185	208.5	210	55	495	606,4	610
110	220	229.4	230	60	570	661.5	665
120	250	250.2	255	65	645	716.6	720
130	285	271.1	275	70	730	771.8	775
	_		_	75	820	826.9	830
		_		80	910	882.0	885

Table 9-6. Design Intersection Sight Distance—Case B1, Left Turn from Stop

Note: Intersection sight distance shown is for a stopped passenger car to turn left onto a two-lane highway with no median and grades 3 percent or less. For other conditions, the time gap should be adjusted and the sight distance recalculated.

Sight distance design for left turns at divided-highway intersections should consider multiple design vehicles and median width. If the design vehicle used to determine sight distance for a divided-highway intersection is larger than a passenger car, then sight distance for left turns will need to be checked for that selected design vehicle and for smaller design vehicles as well. If the divided-highway median is wide enough to store the design vehicle with a clearance to the through lanes of approximately 1 m [3 ft] at both ends of the vehicle, no separate analysis for the departure sight triangle for left turns is needed on the minor-road approach for the near roadway to the left. In most cases, the departure sight triangle for right

# **55 MPH DESIGN CRITERIA**

NHS? (Y/N) N   STRAHNET? (Y/N) N     3   DESIGN DESIGNATION     SR 28     DESIGN CRITERIA Reconstruction     AREA SYSTEM (Urban/Rural)     FUNCTIONAL CLASSIFICATION     ROADWAY TYPOLOGY     REMARKS     Most locations along corridor     except where other criteria is used
3   DESIGN DESIGNATION     SR 28     DESIGN CRITERIA   Reconstruction     AREA SYSTEM (Urban/Rural)   Rural     FUNCTIONAL CLASSIFICATION   Regional Arterial     ROADWAY TYPOLOGY   Rural     TOPOGRAPHY   Rolling     REMARKS   Most locations along corridor     except where other criteria is used
SR 28   OPENING YEAR ADT (Average Daily Traffic)   7349 (2019)     DESIGN CRITERIA   Reconstruction   8450     AREA SYSTEM (Urban/Rural)   Rural   DESIGN YEAR ADT (Average Daily Traffic)   8450     FUNCTIONAL CLASSIFICATION   Regional Arterial   DESIGN YEAR (for Design Year ADT)   2045     ROADWAY TYPOLOGY   Rural   DHV (Design Hourly Volume)   761     TOPOGRAPHY   Rolling   T (Truck Percentage)   13     REMARKS   Most locations along corridor   13
DESIGN CRITERIA   Reconstruction   DESIGN YEAR ADT (Average Daily Traffic) 8450     AREA SYSTEM (Urban/Rural)   Rural   DESIGN YEAR (for Design Year ADT)   2045     FUNCTIONAL CLASSIFICATION   Regional Arterial   DHV (Design Hourly Volume)   761     ROADWAY TYPOLOGY   Rural   D (Directional Distribution)   59     TOPOGRAPHY   Most locations along corridor   T (Truck Percentage)   13
AREA SYSTEM (Urban/Rural)   Rural   DESIGN YEAR (for Design Year ADT)   2045     FUNCTIONAL CLASSIFICATION   Regional Arterial   DHV (Design Hourly Volume)   761     ROADWAY TYPOLOGY   Rural   D (Directional Distribution)   59     TOPOGRAPHY   Rolling   T (Truck Percentage)   13     REMARKS   Most locations along corridor   except where other criteria is used   13
FUNCTIONAL CLASSIFICATION   Regional Arterial   DHV (Design Houry Volume)   761     ROADWAY TYPOLOGY   Rural   D (Directional Distribution)   59     TOPOGRAPHY   Rolling   T (Truck Percentage)   13     REMARKS   Most locations along corridor   except where other criteria is used   13
TOPOGRAPHY Rolling T (Truck Percentage) 13 REMARKS Most locations along corridor except where other criteria is used
REMARKS Most locations along corridor except where other criteria is used
except where other criteria is used
(5) Criteria* (ENTIRE PROJECT VALUE VALUE VALUE MALTS (AASHTO OR DM-2 Reference) (NOTE ANY DESIGN EXCEPTIONS)
OR BY STATION) VALUE VALUE VALUE (ASTITUTION DIVISION DIVISION EACH HONS)
Design Speed     55 MPH     45-55 MPH     55 MPH     Yes     DM-2, Table 1.3
Lane Width     11'     11' to 12'     11'     Yes     DM-2, Table 1.3
Shoulder Width     6'     8' to 10'     8'     Yes     DM-2, Table 1.3
Minimum Bridge Width     N/A     38' to 44'     N/A     N/A     DM-2, Sec 1.2C
Minimum Horizontal Radius     850'     587' to 960'     960'     Yes     AASHTO, Table 3-10b     North of Summerville
Maximum Superelevation Rate     Varies     8.0%     8.0%     Yes     DM-2, Table 1.3
Vertical Grade Minimum 0.20% 0.50% 0.50% Yes DM-2, Table 1.3 line segment 132
Maximum     7.10%     5.00%     5.00%     Yes     AASHTO, Table 7-2     line segment 157
Minimum Stopping Sight Distance (SSD/HLSD)
(vertical and horizontal) Varies 360' to 495' 495' Yes AASHTO, Table 7-1
Minimum Intersection Sight Distance (ISD)     Varies     500' to 610'     610'     Yes     AASHTO, Table 9-6
Minimum Cross Slope     Varies     2.0%     2.0%     Yes     DM-2, Table 1.3
Minimum Vertical Clearance N/A 16'-6" 16'-6" Yes DM-2, Table 2.2

6

Any pedestrian and bicycle concerns/needs? Explain.

Any ADA compliance issues? Explain.

Any transit issues? Explain.

Any additional design issues? Explain.

		DESIRED	AVERAGE		NEDDELETION	
ROADWAY CLASS	ROADWAY TYPE	OPERATING SPEED	TRIP LENGTH	VOLUME	INTERSECTION SPACING	COMMENTS
Arterial	Regional	50-90 km/h (30-55 mph)	24-56 km (15-35 mi)	10,000- 40,000 veh/day	200-400 m (660-1,320 ft)	Roadways in this category would be considered "Principal Arterial" in traditional functional classification.
Arterial	Community	40-90 km/h (25-55 mph)	11-40 km (7-25 mi)	5,000- 25,000 veh/day	90-400 m (300-1,320 ft)	Often classified as "Minor Arterial" in traditional classification but may include road segments classified as "Principal Arterial".
Collector	Community	40-90 km/h (25-55 mph)	8-16 km (5-10 mi)	5,000- 15,000 veh/day	90-200 m (300-660 ft)	Often similar in appearance to a community arterial. Typically classified as "Major Collector".
Collector	Neighborhood	40-60 km/h (25-35 mph)	< 11 km (< 7 mi)	< 6,000 veh/day	90-200 m (300-660 ft)	Similar in appearance to local roadways. Typically classified as "Minor Collector".
Local	Local	30-50 km/h (20-30 mph)	< 8 km (< 5 mi)	< 3,000 veh/day	60-200 m (200-660 ft)	

TABLE 1.2 ROADWAY TYPOLOGIES

# INTENTIONALLY BLANK

# FIGURE 1.2 ILLUSTRATED ROADWAY TYPOLOGIES



# FIGURE 1.2 (CONTINUED) ILLUSTRATED ROADWAY TYPOLOGIES



# TABLE 1.3 (ENGLISH) MATRIX OF DESIGN VALUES – REGIONAL ARTERIAL

							1	
	Regional Arterial	Rura	Suburban Neighborhood	Suburban Corridor	Suburban Center	Town/Village Neighborhood	Town/Village Center	Urban Core
	Lane Width <sup>1</sup>	11' to 12'	11' to 12'	11' to 12'	11' to 12'	10' to 12'	10' to 12'	10' to 12'
	Shoulder Width <sup>2, 3</sup>	8' to 10'	8' to 10'	8' to 12'	4' to 6' (if No Parking or Bike Lane)			
	Parking Lane	NA	NA	AA	8' Parallel	8' Parallel	8' Parallel	8' Parallel
	Bike Lane <sup>4</sup>	NA	5' to 6' (if No Shoulder)	6' (if No Shoulder)	5' to 6'	5' to 6'	5' to 6'	5' to 6'
	Median (if needed)	4' to 6'	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only	16' to 18' for Left Turn; 6' to 8' for Pedestrians Only
	Curb Return <sup>5</sup>	30' to 50'	25' to 35'	30' to 50'	25' to 50'	15' to 40'	15' to 40'	15' to 40'
	Travel Lanes	2 to 6	2 to 6	4 to 6	4 to 6	2 to 4	2 to 4	2 to 6
Yewb	Cross Slopes (Minimum) <sup>6, 7</sup>	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%	2.0%
Гоас	Cross Slopes (Maximum) <sup>8</sup>	8.0%	6.0%	6.0%	6.0%	6.0%	6.0%	6.0%
	Bridge Widths (Two-Lane Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	_ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side				
	Bridge Widths (Four-Lane or More Facilities) <sup>9, 10, 16</sup>	Lane Widths Plus Shoulders Each Side	_ane Widths Plus Shoulders Each Side	Lane Widths Plus Shoulders Each Side				
	Vertical Grades (Minimum) <sup>11</sup>	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%	0.5%
	Vertical Clearance (Minimum)	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2	16'-6", See Chapter 2
	Clear Sidewalk Width	NA	5'	5' to 6'	5' to 6'	6' to 8'	6' to 10'	6' to 12'
7.	Buffer <sup>13</sup>	AA	6'+	6' to 10'	4' to 6'	4' to 6'	4' to 6'	4' to 6'
l 9	Shy Distance	AA	NA	NA	0' to 2'	0' to 2'	2'	2'
pispe	Total Sidewalk Width	NA	Ω	5' to 6'	9' to 14'	10' to 16'	12' to 18'	12' to 20'
SoA	Clear Zone Widths <sup>14</sup>	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12	See Chapter 12
	Right-of-Way Widths <sup>15</sup>	Varies	Varies	Varies	Varies	Varies	Varies	Varies
	Desired Operating Speed (Design Speed)	45-55 mph	35-40 mph	35-55 mph	30-35 mph	30-35 mph	30-35 mph	30-35 mph
pəədS	Stopping and Passing Sight Distances (Minimum)	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1	2004 AASHTO Green Book, Exhibit 7-1
	Vertical Grades (Maximum)	2004 AASHTO Green Book, Exhibit 7-2	2004 AASHTO Green Book, Exhibit 7-10					
L								

				5 ( <u>)</u> ( )				J.S. Custa	mary	<u>988-04</u>					
		V <sub>d</sub> = 15	V <sub>d</sub> = 20	V <sub>d</sub> = 25	V <sub>d</sub> ≈ 30	V <sub>d</sub> = 35	V <sub>d</sub> = 40	V <sub>d</sub> ≈45	V <sub>d</sub> = 50	V <sub>d</sub> = 55	V <sub>d</sub> = 60	V <sub>d</sub> = 65	V <sub>d</sub> = 70	V <sub>d</sub> = 75	V <sub>d</sub> = 80
		mph	mph	mph	mph	mph	mph	mph	ութի	mph	mph	mph	mph	mph	mph
	e {%}	R (ft)	8 (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)	R (ft)					
	NC	932	1640	2370	3240	4260	5410	6710	8150	9720	11500	12900	14500	16100	17800
	RC	676	1190	1720	2370	3120	3970	4930	5990	7150	8440	9510	10700	12900	13300
	2.2	605	1070	1550	2130	2800	3570	4440	5400	6450	7620	8600	9660	10800	12000
	2.4	546	959	1400	1930	2540	3240	4030	4910	5870	6930	7830	8810	9850	11000
· · ·	2.6	496	872	1280	1760	2320	2960	3690	4490	5370	6350	7180	8090	9050	10100
· .	2.8	453	796	1170	1610	2130	2720	3390	4130	4950	5850	6630	7470	8370	9340
	3.0	415	730	1070	1480	1960	2510	3130	3820	4580	5420	6140	6930	7780	8700
	3.2	382	672	985	1370	1820	2330	2900	3550	4250	5040	5720	6460	7260	8130
· ·	3.4	352	620	911	1270	1690	2170	2700	3300	3970	4700	5350	6050	6800	7620
. 1	3.6	324	572	845	1180	1570	2020	2520	3090	3710	4400	5010	5680	6400	7180
· ·	3.8	300	530	784	1100	1470	1890	2360	2890	3480	4140	4710	5350	6030	6780
•	4.0	277	490	729	1030	1370	1770	2220	2720	3270	3890	4450	5050	5710	6420
	4.2	255	453	678	955	1280	1660	2080	2560	3080	3670	4200	4780	5410	6090
	4.4	235	418	630	893	1200	1560	1960	2410	2910	3470	3980	4540	5140	5800
•	4.6	215	384	585	834	1130	1470	1850	2280	2750	3290	3770	4310	4890	5530
	4.8	193	349	542	779	1060	1390	1750	2160	2610	3120	3590	4100	4670	5280
	5.0	172	314	499	727	991	1310	1650	2040	2470	2950	3410	3910	4460	5050
	5.2	154	284	457	676	929	1230	1560	1930	2350	2820	3250	3740	4260	4840
	5.4	139	258	420	627	870	1160	1480	1830	2230	2680	3110	3570	4090	4640
	5.6	126	236	387	582	813	1090	1390	1740	2120	2550	2970	3420	3920	4460
	5,8	115	216	358	542	761	1030	1320	1650	2010	2430	2840	3280	3760	4290
	6.0	105	199	332	506	713	965	1250	1560	1920	2320	2710	3150	3620	4140
	6.2	97	184	308	472	669	909	1180	1480	1820	2210	2600	3020	3480	3990
1.1	6.4	89	170	287	442	628	857	1110	1400	1730	2110	2490	2910	3360	3850
· .	6.6	82	157	267	413	590	808	1050	1330	1650	2010	2380	2790	3240	3720
•	6.8	76	145	248	386	553	761	990	1260	1560	1910	2280	2690	3120	3600
	7.0	70	135	231	360	518	716	933	1190	1480	1820	2180	2580	3010	3480
· *	7.2	64	125	214	336	485	672	878	1120	1400	1720	2070	2470	2900	3370
. 1	7.4	59	115	198	312	451	628	822	1060	1320	1630	1970	2350	2780	3250
. ·	7.6	54	105	182	287	417	583	765	980	1230	1530	1850	2230	2650	3120
·	7.8	48	94	164	261	380	533	701	901	1140	1410	1720	2090	2500	2970
:	8.0	38	76	134	214	314	444	587	758	960	1200	1480	1810	2210	2670

Chapter 3—Elem Table 3-10b. Minimum Radii for Design Superelevation Rates, Design Speeds, and e<sub>max</sub> = 8%

© 2011 by the American Association of State Highway and Transportation Officials. All rights reserved. Duplication is a violation of applicable law.

# A Policy on Geometric Design of Highways and Streets

tance are considered, there are seldom advantages to using the maximum grade values except when grades are long.

				M	etric							J.S. (	Custo	man	<u> </u>		
	Maximum Grade (%) for Specified Design Speed (km/h)								Maximum Grade (%) for Specified Design Speed (mph)								
Type of Terrain	60	70	80	90	100	110	120	130	40	45	50	55	60	65	70	75	80
Level	5	5	4	4	3	3	3	3	5	5	4	4	3	3	3	3	3
Rolling	6	6	5	5	4	4	4	4	6	6	5	5	4	4	4	4	4
Mountainous	8	7	7	6	6	5	5	5	8	7	7	6	6	5	5	5	5

# Table 7-2. Maximum Grades for Rural Arterials

### **Cross Slope**

Cross slope is provided to enhance roadway drainage. Two-lane rural roadways are normally designed with a centerline crown and traveled-way cross slopes ranging from 1.5 to 2 percent with the higher values being most prevalent.

### Superelevation

Where curves are used on a rural arterial alignment, a superelevation rate based on the design speed should be used. Superelevation rates should not exceed 12 percent; however, where ice and snow conditions are a factor, the maximum superelevation rate should not exceed 8 percent. Superelevation runoff denotes the length of roadway needed to accomplish the change in cross slope from a section with adverse crown removed to a fully superelevated section and vice versa. Adjustments in design runoff lengths may be needed for smooth riding, drainage, and appearance. Section 3.3 provides a detailed discussion of superelevation and tables of appropriate superelevation rates and runoff lengths for various design speeds.

# 7.2.3 Cross-Sectional Elements

### Widths of Roadway

The logical approach to determining appropriate lane and shoulder widths is to provide a width related to the traffic demands. Table 7-3 provides values for the width of traveled way and usable shoulder that should be considered for the volumes indicated. Regardless of weather conditions, shoulders should be usable at all times. On high-volume highways, shoulders should preferably be paved, but paved shoulders may not always be practical. As a minimum, 0.6 m [2 ft] of the shoulder width should be paved to provide for pavement support, wide vehicles, and collision avoidance. Where bicycles are to be accommodated on the shoulder, a minimum paved width of 1.2 m [4 ft] should be used. The shoulder should be constructed to a uniform width for relatively long stretches of roadway. For additional information concerning shoulders, refer to Section 4.4.

# **Sight Distance**

Sight distance is directly related to and varies appreciably with design speed. Stopping sight distance should be provided throughout the length of the roadway. Passing and decision sight distances influence roadway operations and should be provided wherever practical. Providing decision sight distance at locations where complex decisions are made greatly enhances the capability for drivers to safely accomplish maneuvers. Examples of locations where complex decisions are needed include interchanges, high-volume intersections, transitions in roadway width, and transitions in the number of lanes. Providing adequate sight distance on rural arterials, which may combine both high speeds and high traffic volumes, can be complex. Table 7-1 presents the recommended minimum values of stopping and passing sight distance. Refer to Section 3.2 for a comprehensive discussion of sight distance and for tabulated values for decision sight distance.

	Metric			U.S. Customary	
Design Speed (km/h)	Minimum Stopping Sight Distance (m)	Minimum Passing Sight Distance (m)	Design Speed (mph)	Minimum Stopping Sight Distance (ft)	Minimum Passing Sight Distance (ft)
50	65	160	30	200	500
60	85	180	35	250	550
70	105	210	40	305	600
80	130	245	45	360	700
90	160	280	50	425	800
100	185	320	55	495	900
110	220	355	60	570	1000
120	250	395	65	645	1100
130	285	440	70	730	1200
			75	820	1300
			80	910	1400

## Table 7-1. Minimum Sight Distances for Arterials

Ideally, intersections and railroad crossings should be grade separated or provided with adequate sight distance. Intersections should be placed in sag or tangent locations, or both, where practical, to provide maximum visibility of the roadway and pavement markings.

### Alignment

A smooth flowing alignment is desirable on a rural arterial. Changes in alignment, both horizontal and vertical, should be sufficiently gradual to avoid surprising the driver. Minimum radii should be used sparingly; short horizontal curves—particularly at the end of long tangents—should be avoided. Roads with well-designed and consistent alignment usually function more efficiently and with lower crash rates than roads with poor alignment, even where enhanced signing and pavement marking are provided.

### Grades

The length and steepness of grades directly affect the operational characteristics of an arterial. Table 7-2 presents recommended maximum grades for rural arterials. When vertical curves for stopping sight dis-

# 9-38 A Policy on Geometric Design of Highways and Streets

intersection is located on a 4 percent upgrade, then the time gap selected for intersection sight distance design for left turns should be increased from 8.0 to 8.8 s, equivalent to an increase of 0.2 s for each percent grade.

The design values for intersection sight distance for passenger cars are shown in Table 9-6. Figure 9-17 includes design values, based on the time gaps for the design vehicles included in Table 9-5.

No adjustment of the recommended sight distance values for the major-road grade is generally needed because both the major- and minor-road vehicle will be on the same grade when departing from the intersection. However, if the minor-road design vehicle is a heavy truck and the intersection is located near a sag vertical curve with grades over 3 percent, then an adjustment to extend the recommended sight distance based on the major-road grade should be considered.

	Met	ric			U.S. Customary					
Design		Intersecti Distan Passeng	ion Sight ce for er Cars	Design	Stopping	Intersection Sight Distance for Passenger Cars				
Speed (km/h)	Stopping Sight Distance (m)	Calculated (m)	Design (m)	Speed (mph)	Sight Distance (ft)	Calculated (ft)	Design (ft)			
20	20	41.7	45	15	80	165.4	170			
30	35	62.6	65	20	115	220.5	225			
40	50	83.4	85	25	155	275.6	280			
50	65	104.3	105	30	200	330,8	335			
60	85	125.1	130	35	250	385.9	390			
70	105	146.0	150	40	305	441.0	445			
80	130	166.8	170	45	360	496.1	500			
90	160	187.7	190	50	425	551.3	555			
100	185	208.5	210	55	495	606,4	610			
110	220	229.4	230	60	570	661.5	665			
120	250	250.2	255	65	645	716.6	720			
130	285	271.1	275	70	730	771.8	775			
	_		_	75	820	826.9	830			
		_		80	910	882.0	885			

Table 9-6. Design Intersection Sight Distance—Case B1, Left Turn from Stop

Note: Intersection sight distance shown is for a stopped passenger car to turn left onto a two-lane highway with no median and grades 3 percent or less. For other conditions, the time gap should be adjusted and the sight distance recalculated.

Sight distance design for left turns at divided-highway intersections should consider multiple design vehicles and median width. If the design vehicle used to determine sight distance for a divided-highway intersection is larger than a passenger car, then sight distance for left turns will need to be checked for that selected design vehicle and for smaller design vehicles as well. If the divided-highway median is wide enough to store the design vehicle with a clearance to the through lanes of approximately 1 m [3 ft] at both ends of the vehicle, no separate analysis for the departure sight triangle for left turns is needed on the minor-road approach for the near roadway to the left. In most cases, the departure sight triangle for right
# APPENDIX I SPC Funding Program

#### **WINTER 2020**

Two Chatham Center Suite 500, 112 Washington Place Pittsburgh, PA 15219 (412) 391-5590 (P) (412) 391-9160 (F) comments@spcregion.org www.spcregion.org

# TRANSPORTATION & COMMUNITY FUNDING PROGRAMS

# ⑧ ಈ ▲ 🚍 💂 ♠⊶♠ ॐ 🏌

### Grant and Reimbursement Programs to Advance and Guide Effective Investment of Public Funds

The Southwestern Pennsylvania Commission (SPC) serves the 10-county Pittsburgh region as the official Metropolitan Planning Organization, Local Development District, and Economic Development District. SPC's Transportation Department meets federal mandates with the publication of a long-range (20-year) transportation plan and the establishment of a short-range (4-year) Transportation Improvement Program (TIP). Planning activities range from data systems and modeling to special transportation studies and air quality analysis.

AUSTERN PENIL

COMMISSIO

SPC is committed to assisting our local governments and agencies in the preparation, planning, and execution of their community's priority projects and investments. The information within this document will provide local project sponsors a guide to available resources that can assist with the implementation of a community's shared goals.



## Act 13 Programs (Marcellus Legacy Fund)

The Marcellus Legacy Fund was created by Act 13 of 2012 to provide for the distribution of unconventional gas well impact fees to counties, municipalities, and commonwealth agencies. Pursuant to Section 2315 (a) (6) (i) of the Act, a portion of the fee revenue will be transferred to the Commonwealth Financing Authority for the statewide initiatives listed on pages 2 & 3:

#### Abandoned Mine Drainage (AMD) Abatement and Treatment Program

**Purpose:** Funding for projects that involve the reclamation of Abandoned Mine Well(s); construction of a new AMD site; remediation and repair of existing AMD project sites; operation and maintenance maintaining current AMD remediation sites; establishment of trust fund to ensure ongoing maintenance is achieved; and, monitoring of water quality to track or continue to trace non-point source load reductions resulting from AMD remediation projects.

**Eligibility:** Municipalities; Councils of Governments; Authorized Organizations; Institutions of Higher Education; Watershed Organizations; For-Profit Businesses

Deadline: Applications accepted between February 1, 2019 and May 31, 2019

Match/Funding: 15% match of the total project cost; grants do not exceed \$1,000,000

Website: <a href="https://dced.pa.gov/programs/abandoned-mine-drainage-abatement-treatment-program-amdatp/">https://dced.pa.gov/programs/abandoned-mine-drainage-abatement-treatment-program-amdatp/</a>

#### **Baseline Water Quality Data Program**

**Purpose:** Funding for projects that involve practices for water sample collection and analysis to document existing groundwater quality conditions on private water supplies.

**Eligibility:** Municipalities; Councils of Governments; Authorized Organizations; Institutions of Higher Education; Watershed Organizations; For-Profit Businesses

Deadline: Applications accepted between February 1, 2019 to May 31, 2019

Match/Funding: 15% match of the total project cost; grants do not exceed \$250,000

Website: https://dced.pa.gov/programs/baseline-water-quality-data-program/

#### **Flood Mitigation Program**

**Purpose:** Funding for flood mitigation projects authorized by a flood protection authority, the Department of Environmental Protection, the U.S. Army Corps of Engineers, the U.S. Department of Agriculture's Natural Resources Conservation Service, or identified by a local government. Grants are awarded to eligible applicants for projects with a total cost of \$50,000 or more.

**Eligibility:** Municipalities; Councils of Governments; Authorized Organizations; Institutions of Higher Education; Watershed Organizations; For-Profit Businesses

Deadline: Applications accepted between February 1, 2019 and May 31, 2019

Local Match Requirement: 15% match of the total project cost; grants do not exceed \$500,000

Website: https://dced.pa.gov/programs/flood-mitigation-program-fmp/

#### Greenways, Trails and Recreation Program

**Purpose:** Funding for planning, acquisition, development, rehabilitation and repair of greenways, recreational trails, open space, parks and beautification projects. Projects can involve development, rehabilitation and improvements to public parks, recreation areas, greenways, and trails, as well as river conservation.

**Eligibility:** Municipalities; Councils of Governments; Authorized Organizations; Institutions of Higher Education; Watershed Organizations; For-Profit Businesses

Deadline: Applications accepted between February 1, 2019 and May 31, 2019

Match/Funding: 15% match of the total project cost; grants do not exceed \$250,000

Website: https://dced.pa.gov/programs/greenways-trails-and-recreation-program-gtrp/

#### Orphan or Abandoned Well Plugging Program

**Purpose:** Funds for orphaned or abandoned well plugging projects, including the cleaning out and plugging of abandoned and orphan oil and gas wells; stray gas mitigation systems; and well venting projects.

**Eligibility:** Municipalities; Councils of Governments; Authorized Organizations; Institutions of Higher Education; Watershed Organizations; For-Profit Businesses

Deadline: Applications accepted between February 1, 2019 and May 31, 2019

Match/Funding: No match required; grants do not exceed \$250,000

Website: https://dced.pa.gov/programs/orphan-abandoned-well-plugging-program-oawp/

#### Sewage Facilities Program

**Purpose:** Funding for costs associated with the planning work required under the Pennsylvania Sewage Facilities Act (Act 537).

**Eligibility:** Municipalities; Councils of Governments; Authorized Organizations; Institutions of Higher Education; Watershed Organizations; For-Profit Businesses

Deadline: Applications accepted between February 1, 2019 and May 31, 2019

Match/Funding: 50% match of the total project cost; grants do not exceed \$100,000

Website: https://dced.pa.gov/programs/sewage-facilities-program-sfp/

#### Watershed Restoration and Protection Program

**Purpose:** Funding for watershed restoration and protection projects that involve the construction, improvement, expansion, repair, maintenance or rehabilitation of new or existing watershed protection BMPs. The overall goal of the program is to restore and maintain restored stream reaches impaired by the uncontrolled discharge of nonpoint source polluted runoff, and ultimately to remove these streams from the DEP's Impaired Waters list.

**Eligibility:** Municipalities; Councils of Governments; Authorized Organizations; Institutions of Higher Education; Watershed Organizations; For-Profit Businesses

Deadline: Applications accepted between February 1, 2019 and May 31, 2019

Match/Funding: 15% match of the total project cost; grants do not exceed \$300,000

Website: <a href="https://dced.pa.gov/programs/watershed-restoration-protection-program-wrpp/">https://dced.pa.gov/programs/watershed-restoration-protection-program-wrpp/</a>

## **Funding Programs**

#### SPC and PennDOT Transportation Alternatives Set-Aside Program

**Purpose:** The Transportation Alternatives Set-Aside (TASA) Program provides funding for programs and projects defined as transportation alternatives, including on- and off-road pedestrian and bicycle facilities; infrastructure projects for improving non-driver access to public transportation and enhanced mobility; environmental mitigation; recreational trail program projects; and, safe routes to school projects. Key criterion in the review of applications will be readiness for implementation and delivery, safety, consistency with local or regional plans; collaboration with stakeholders; and, statewide or regional significance.

#### **Eligibility**:

- Local governments
- Regional transportation authorities
- Transit agencies
- Natural resource or public land agencies, including federal agencies
- School districts, local education agencies, or schools
- Tribal governments
- A nonprofit entity responsible for the administration of local transportation safety programs
- Any other governmental entity with responsibility for oversight of transportation or recreational trails

Deadline: Applications accepted between August 26, 2019 and September 20, 2019

**Local Match Requirement:** There is no match requirement; however, local sponsors pay all costs for pre-construction activities (design, environmental clearance, right of way, utilities, etc.) and PennDOT provides 100% cost reimbursement for the construction phase (including construction inspection).

#### Website: <a href="https://spcregion.org/trans\_plan\_tap.asp">https://spcregion.org/trans\_plan\_tap.asp</a>

#### DCED Multimodal Transportation Fund (MTF)

**Purpose:** Provides grants to encourage economic development and ensure that a safe and reliable system of transportation is available to Pennsylvania residents. The program is intended to provide financial assistance to improve transportation assets that enhance communities, pedestrian safety, and transit revitalization. The program is under the direction of the Commonwealth Financing Authority.

**Eligibility:** Local Governments; Councils of Governments; Businesses & Non-Profits; Economic Development Organizations; Public Transportation Agencies (including but not limited to an airport authority, public airport, port authority, or similar public entity); and, Rail and Freight Ports

Deadline: Applications are accepted between March 1, 2019 and July 31, 2019

Local Match Requirement: 30% match of requested amount (state/federal grants do not count as match)

Website: http://community.newpa.com/programs/multimodal-transportation-fund/

#### PennDOT Pennsylvania Infrastructure Bank (PIB)

**Purpose:** A PennDOT program that provides low-interest loans to accelerate priority transportation projects. Loan emphasis is on construction projects, but other project phases such as design, right-of-way acquisition, and transportation equipment purchases will be considered. Projects financed by the PIB include: aviation, highway/bridge, rail freight, and transit.

**Eligibility:** Local Governments; Counties; Transportation Authorities; Economic Development Agencies; Non-Profit Organizations; and Private Corporations

Deadline: Always accepting applications

Website: <u>http://www.penndot.gov/ProjectAndPrograms/Planning/Pages/PA-Infrastructure-Bank.aspx</u>

#### PennDOT Automated Red Light Enforcement Program (ARLE)

**Purpose:** The program provides opportunities to improve safety and reduce congestion. ARLE intends to reduce violations and crashes, provide additional safety benefits to highway users, and improve pedestrian safety. The types of eligible projects are wide ranging when considering highway safety or mobility. It is the intent of the ARLE Program to fund worthwhile projects that can be completed at a relatively low cost, and award grants to projects that will be fully funded at the execution of the grant agreement date.

**Eligibility:** Local Governments; Counties; Councils of Governments; Authorized Organizations; Institutions of Higher Education; Watershed Organizations; For-Profit Businesses

**Deadline:** Applications accepted between June 1, 2019 and June 30, 2019

Local Match Requirement: No matching funds are required for eligibility in the ARLE program

Website: <u>http://www.dot.state.pa.us/Portal%20Information/Traffic%20Signal%20Portal/FUNDARLE.html</u>

#### SPC Congestion Mitigation Air Quality Improvement Program (CMAQ)

**Purpose:** The CMAQ Program provides funds for transportation projects and programs that will contribute to attainment or maintenance of the national ambient air quality standards for ozone, carbon monoxide, and particulate matter; and supports goals of the U.S. Department of Transportation: improving air quality, and relieving congestion. Project types include: traffic flow and signal improvements, transportation demand management, transit improvements and programs, commuter bicycle and pedestrian improvements, and diesel emission reductions.

**Eligibility:** Any qualified government entity, including local governments, regional transit agencies, port authorities, and state agencies, is eligible to apply for CMAQ funding. Non-profits and private sector entities may partner with an eligible applicant to apply for CMAQ funding.

Deadline: CMAQ application period closes September 9, 2019

Local Match Requirement: 20% match of total project cost (by phase) from local, state, or other non-federal sources

Website: https://www.spcregion.org/trans\_tip\_cmaq.asp

#### DCNR Community Conservation Partnerships Program (C2P2)

**Purpose:** DCNR's Bureau of Recreation and Conservation provides a single point of contact for communities and non-profit conservation agencies seeking state assistance through the C2P2 Program in support of local recreation and conservation initiatives and those that implement Pennsylvania's Comprehensive Outdoor Recreation Plan. This assistance can take the form of grants, technical assistance, information exchange, and training. All of DCNR's funding sources are combined into one annual application cycle and there is a single application format and process with one set of requirements and guidelines.

**Eligibility:** A wide range of grant and technical assistance programs are offered through C2P2 to help communities, land conservancies, and non-profit organizations plan, acquire, and develop:

- Recreation, park and conservation facilities
- Watersheds and rivers corridors
- Greenways and trails
- Heritage areas and facilities
- Critical habitat, natural areas & open space

Deadline: Applications accepted between January 15, 2020 and April 22, 2020

Local Match Requirement: Generally, a 50% match by either cash or non-cash value is required

Website: <a href="http://www.dcnr.state.pa.us/brc/grants/">http://www.dcnr.state.pa.us/brc/grants/</a>

#### Department of Environmental Protection (DEP): Loan, Grant, and Rebate Programs

The DEP has grants and loans, as well as rebates to assist individuals, groups, and businesses with a host of environmental issues. Due to the fact that many of DEP's programs are dependent on annual funding from the commonwealth's budget, program availability and application dates can vary widely and are historically inconsistent. Interested program applicants should use <u>DEP's Grant and Loan Programs Center website</u> to view available grants and loans. Some of the most utilized DEP Programs are:

- County and Municipal Recycling Financial Assistance Programs
- Alternative Fuels Incentive Grant Program
- Small Business Ombudsman's Grants and Loans
- Driving PA Forward
- Growing Greener Grants
- Environmental Education Grants

#### PennDOT Multimodal Transportation Fund

**Purpose:** Provides grants to ensure that a safe and reliable system of transportation is available to the residents of this commonwealth. The program is intended to provide financial assistance to municipalities, councils of governments, businesses, economic development organizations, public transportation agencies, rail freight, passenger rail, and ports in order to improve transportation assets that enhance communities, pedestrian safety, and transit revitalization.

**Eligibility:** Municipalities; Council of Governments; Business/Non-profit; Economic Development Organization; Public Transportation Agency; Ports or Rail / Freight Entity

Deadline: Applications accepted between September 9, 2019 and November 9, 2019

Local Match Requirement: 30% match of the amount awarded; grants normally do not exceed \$3,000,000

Website: https://www.penndot.gov/ProjectAndPrograms/MultimodalProgram/Pages/default.aspx

#### Green Light - Go

**Purpose:** The Green Light - Go: Pennsylvania's Municipal Signal Partnership Program is a competitive state grant program designed to improve the efficiency and operation of existing traffic signals located in the Commonwealth of Pennsylvania. Established by Act 89 of 2013 and revised by Act 101 of 2016, the program is administered by the Pennsylvania Department of Transportation and is purposed to improve mobility and safety at signalized intersections.

Eligibility: Municipalities and Planning Organizations

Deadline: Applications were accepted between October 15, 2018 through January 11, 2019

Local Match Requirement: Minimum 20% match/reimbursement

Website: http://www.dot.state.pa.us/portal%20information/traffic%20signal%20portal/fundglg.html



### 2020 Calendar of Programs Anticipated Application Opening & Closing Dates\*

Jan.	Feb.	March	April	May	June	July	Aug.	Sep.	Oct.	Nov.	Dec.
	Act 13 Programs	Act 13 Programs	Act 13 Programs	Act 13 Programs							
							SPC TASA	SPC TASA			
		DCED MTF	DCED MTF	DCED MTF	DCED MTF	DCED MTF					
PennPOT PIB	PennPOT PIB	PennPOT PIB	PennPOT PIB	PennPOT PIB	PennPOT PIB	PennPOT PIB	PennPOT PIB	PennPOT PIB	PennPOT PIB	PennPOT PIB	PennPOT PIB
					PennPOT ARLE						
							CMAQ	СМАQ			
DCNR C2P2	DCNR C2P2	DCNR C2P2	DCNR C2P2								
								PennPOT MTF	PennPOT MTF	PennPOT MTF	
					GreenLi (Deadlin	ght-Go e Varies)					

\*Funding programs and the agencies that administer them oftentimes will alter anticipated application periods. Contact these agencies or SPC for up-to-date application information.

### SPC Transportation Department Planning and Programming Contact Information:

#### **Ryan Gordon**

Transportation Program Development Manager 412-391-5590 x333 rgordon@spcregion.org